
Title List of Documents Made Publicly Available

November 1-30, 1980

Office of Administration
U.S. Nuclear Regulatory
Commission



Title List of Documents Made Publicly Available

November 1-30, 1980

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Items by Facility Name	xvi
Docketed Items	1
Low Level Radwaste Disposal Sites – Docket 27	1
Domestic Licensing of Source Material – Docket 40... ..	2
Domestic Licensing of Production and Utilization Facilities – Docket 50	9
Domestic Licensing of Special Nuclear Material – Docket 70	256
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions – Docket 71	265
Nondocketed Items	269
10CFR – Commission Meeting Records	269
ACRS – Advisory Committee on Reactor Safeguards	270
COMMISSION – NRC Commissioners	271
CONTRACT – NRC Contracts and Modifications	273
DISCLOSURE – Financial Disclosure Information	275
FOIA – Freedom of Information Act Requests and Releases	275
GEN TECH IS – Generic Technical Issues	278
I&E – Inspection and Enforcement	278
MISC – Public Document Room Miscellaneous	279
NUREG – NUREG Reports and Related Correspondence	279
ORG – Correspondence with Other Organizations	284
PR – Proposed Rule	285
PRM – Petition for Rulemaking	290
PROJ – Projects - Predocket Licensing	290
PT21 – Noncompliance Reports and Related Correspondence	291
QA999 – Quality Assurance Inspections	292
REGGD – Regulatory Guides	295
RES – Research and Technical Assistance Reports	296
REVIEW GRP – NRC Research Review Groups	297
RM – Rulemakings	297
SECY – Position Papers Before the Commission	297
STATE PROG – State Programs	299
TOPREP – Vendor Reports and Related Correspondence	300
WASTE MGT – Nuclear Waste Management	302
XPORTLIC – Export and Import Licenses	302
Personal Author Index	309
Corporate Source Index	335
Report Number Index	359
Cross Reference of Enclosures to Principal Documents	361
Appendix A – Definitions of Docket 50 Categories	375
Appendix B – Definitions of Nondocketed Categories	383

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS


The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters

- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are.



1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number
3. Description of information contained in the document
4. Personal author. An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source
6. Date of document described
7. Pages in document
8. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to video terminals.
9. This three-digit portion of this entry is the number of the frame on which this document starts.
10. If this space is blank, the document is available to the public only in the NRC Public Document Room. 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS


The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

- 10CFR — Commission Meeting Records
- ACRS — Advisory Committee on Reactor Safeguards
- COMMISSION — NRC Commissioners
- CONTRACT — NRC Contracts and Modifications
- DISCLOSURE — Financial Disclosure Information
- FOIA — Freedom of Information Act Requests and Releases

GEN TECH IS — Generic Technical Issues
 I&E — Inspection and Enforcement
 MISC — Public Document Room Miscellaneous
 NUREG — NUREG Reports and Related Correspondence
 ORG — Correspondence with other organizations
 PR — Proposed Rule
 PRM — Petition for Rulemaking
 PROJ — Projects-Predocket Licensing
 PT9 — Public Records
 PT21 — Noncompliance Reports and Related Correspondence
 QA999 — Quality Assurance Inspections
 REGGD — Regulatory Guides
 RES — Research and Technical Assistance Reports
 REVIEW GRP — NRC Research Review Groups
 RM — Rulemakings
 SECY — Position Papers Before the Commission
 STATE PROG — State Programs
 TOPREP — Vendor Reports and Related Correspondence
 WASTE MGT — Nuclear Waste Management
 XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocketed category
2. NRC Accession Number
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author
6. Corporate, agency or other nonindividual source
7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
8. Date of document described
9. Pages in document
10. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to video terminals.
11. This three-digit portion of this entry is the number of the frame on which this document starts.

the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on this page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-010	Beatty, NV	1	40-8452	Bear Creek Uranium Co.	5
27-039	Sheffield, IL, Nuclear Engineering Co.	1	40-8502	Irigaray Mine, Wyoming Mining Corp.	6
27-043	Peekskill, NY	2	40-8511	Cotter Corp.	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	2	40-8549	T.N. Nuclear Specialties	6
27-048	Richland, WA, Nuclear Engineering Co.	2	40-8579	TNS	6
40-0299	Union Carbide Corp.	2	40-8584	Union 76 Minerals Exploration Co.	7
40-0534	General Electric Co., Lamp Business Div.	3	40-8585	Wyoming Mineral Corp.	7
40-0672	Nuclear Metals, Inc.	3	40-8602	United Nuclear Corp.	7
40-1162	Western Nuclear, Inc.	3	40-8676	Energy Fuels Nuclear, Inc.	7
40-1341	Edgemont Uranium Mine, TVA and Mines Development, Inc.	3	40-8681	Energy Fuels Nuclear, Inc.	7
40-2053	Little Creek Mining and Milling Co.	3	40-8692	Cotter Corp.	7
40-2061	West Chicago Facility, Kerr-McGee Corp.	3	40-8693	Ogle Petroleum, Inc.	7
40-2259	Pathfinder Mines Corp.	4	40-8696	Thiokol Corp.	7
40-3453	Atlas Minerals	4	40-8697	Rocky Mountain Energy Co.	7
40-4492	Federal American Partners (Mining)	4	40-8698	Plateau Resources, Ltd.	7
40-6586	Virginia Polytechnic Institute	4	40-8702	Dept. of the Army, Armament Materials Readiness Command	7
40-7869	Plateau Resources, Ltd.	4	40-8711	Dept. of the Navy	7
40-8011	Dept. of the Air Force	5	40-8714	Cleveland Cliffs Iron Co.	8
40-8027	Kerr-McGee Corp.	5	40-8727	Kerr-McGee Nuclear Corp.	8
40-8064	Exxon Minerals Co. USA, Exxon Corp.	5	40-8728	Teton Exploration Drilling Co., Inc.	8
40-8084	Lisbon Mine, Rio Algom Corp.	5	40-8743	Conoco	8
40-8304	Wyoming Mineral Corp.	5	40-8745	Ogle Petroleum	8
40-8323	Dept. of the Navy	5	40-8781	Teton Exploration Drilling Co., Inc.	9
40-8364	Indiana Univ., Indianapolis, IN	5	50-2	Univ. of Michigan Research Reactor	9
40-8380	Rocky Mountain Energy Co.	5	50-3	Indian Point Station, Unit 1	9
40-8412	Dept. of the Navy, Naval Nuclear Power Unit	5	50-5	Pennsylvania State Univ. Research Reactor	9
			50-10	Dresden Nuclear Power Station, Unit 1	10

Docket	Name	Page	Docket	Name	Page
50-18	Vallecitos Boiling Water Reactor	12	50-206	San Onofre Nuclear Station, Unit 1	19
50-29	Yankee-Rowe Nuclear Power Station	12	50-213	Haddam Neck Plant	21
50-30	Plum Brook Research Reactor Facility	13	50-219	Oyster Creek Nuclear Power Plant	22
50-54	Union Carbide Research Reactor	13	50-220	Nine Mile Point Nuclear Station, Unit 1	25
50-70	General Electric Test Reactor	14	50-237	Dresden Nuclear Power Station, Unit 2	26
50-72	Univ. of Utah Research Reactor	14	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	30
50-73	General Electric Nuclear Test Reactor	14	50-245	Millstone Nuclear Power Station, Unit 1	32
50-89	General Atomic Co.	14	50-246	Advanced Critical Reactor Experiment	34
50-94	Rockwell International Research Reactor	14	50-247	Indian Point Station, Unit 2	34
50-97	Cornell Univ. Zero Power Reactor	15	50-249	Dresden Nuclear Power Station, Unit 3	37
50-112	Univ. of Oklahoma Research Reactor	15	50-250	Turkey Point Plant, Unit 3	41
50-116	Iowa State Univ. Research Reactor	15	50-251	Turkey Point Plant, Unit 4	42
50-124	Virginia Polytechnic Institute Training Reactor	15	50-254	Quad-Cities Station, Unit 1	44
50-128	Texas A&M Univ. Research Reactor	15	50-255	Palisades Nuclear Plant	46
50-133	Humboldt Bay Power Plant, Unit 3	15	50-258	Isochem, Inc. Fission Production Conversion Plant	48
50-134	Worcester Polytechnic Institute Research Reactor	16	50-259	Browns Ferry Nuclear Power Station, Unit 1	49
50-142	UCLA Training Reactor	16	50-260	Browns Ferry Nuclear Power Station, Unit 2	50
50-146	Saxton Nuclear Experimental Facility	16	50-261	H. B. Robinson Plant, Unit 2	52
50-147	Rockwell International Corp. Critical Facility	16	50-263	Monticello Nuclear Generating Plant	54
50-150	Ohio State Univ. Research Reactor	16	50-264	Dow Chemical Co.	55
50-155	Big Rock Point Nuclear Plant	16	50-265	Quad-Cities Station, Unit 2	55
50-157	Cornell Univ. Research Reactor	18	50-266	Point Beach Nuclear Plant, Unit 1	57
50-160	Georgia Institute of Technology Research Reactor	18	50-267	Fort St. Vrain Nuclear Generating Station	59
50-163	General Atomic Co.	18	50-269	Oconee Nuclear Station, Unit 1	61
50-183	Vallecitos Experimental Superheat Reactor	18	50-270	Oconee Nuclear Station, Unit 2	63
50-185	Plum Brook Reactor - Mock-up	18	50-271	Vermont Yankee Nuclear Power Station	65
50-186	Univ. of Missouri Research Reactor	18	50-272	Salem Nuclear Generating Station, Unit 1	67
50-187	Space Radiation Research Reactor	19	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	69
50-199	Manhattan College Research Reactor	19	50-277	Peach Bottom Atomic Power Station, Unit 2	71
50-201	West Valley Reprocessing Plant	19	50-278	Peach Bottom Atomic Power Station, Unit 3	73
50-202	Univ. of Nevada Research Reactor	19	50-280	Surry Power Station, Unit 1	75

Docket	Name	Page	Docket	Name	Page
50-281	Surry Power Station, Unit 2	77	50-329	Midland Plant, Unit 1	140
50-282	Prairie Island Nuclear Station, Unit 1	79	50-330	Midland Plant, Unit 2	142
50-285	Fort Calhoun Station, Unit 1	80	50-331	Duane Arnold Energy Center	144
50-286	Indian Point Station, Unit 3	81	50-332	Barnwell Reprocessing Plant	146
50-287	Oconee Nuclear Station, Unit 3	84	50-333	James A. Fitzpatrick Nuclear Power Plant	146
50-288	Reed College Research Reactor	86	50-334	Beaver Valley Power Station, Unit 1	148
50-289	Three Mile Island Nuclear Station, Unit 1	86	50-335	St. Lucie Plant, Unit 1	150
50-293	Pilgrim Nuclear Power Station, Unit 1	91	50-336	Millstone Nuclear Power Station, Unit 2	151
50-295	Zion Nuclear Power Station, Unit 1	93	50-338	North Anna Power Station, Unit 1	153
50-296	Browns Ferry Nuclear Power Station, Unit 3	96	50-339	North Anna Power Station, Unit 2	155
50-298	Cooper Nuclear Station	98	50-340	Seabrook Nuclear Station, Unit 1	158
50-301	Point Beach Nuclear Plant, Unit 2	99	50-341	Enrico Fermi Atomic Power Plant, Unit 2	158
50-302	Crystal River Nuclear Plant, Unit 3	100	50-344	Trojan Nuclear Plant	158
50-304	Zion Nuclear Power Station, Unit 2	102	50-346	Davis-Besse Nuclear Power Station, Unit 1	161
50-305	Kewaunee Nuclear Power Plant	104	50-348	Joseph M. Farley Nuclear Plant, Unit 1	162
50-306	Prairie Island Nuclear Station, Unit 2	106	50-352	Limerick Generating Station, Unit 1	165
50-309	Maine Yankee Atomic Power Plant	107	50-353	Limerick Generating Station, Unit 2	166
50-311	Salem Nuclear Generating Station, Unit 2	109	50-354	Hope Creek Nuclear Station, Unit 1	167
50-312	Rancho Seco Nuclear Generating Station	111	50-355	Hope Creek Nuclear Station, Unit 2	168
50-313	Arkansas Nuclear One, Unit 1	112	50-358	William H. Zimmer Nuclear Station, Unit 1	169
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	115	50-361	San Onofre Nuclear Station, Unit 2	170
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	116	50-362	San Onofre Nuclear Station, Unit 3	172
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	117	50-363	Forked River Nuclear Station, Unit 1	173
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	119	50-364	Joseph M. Farley Nuclear Plant, Unit 2	173
50-320	Three Mile Island Nuclear Station, Unit 2	120	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	176
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	127	50-367	Bailly Generating Station	178
50-322	Shoreham Nuclear Power Station	129	50-368	Arkansas Nuclear One, Unit 2	181
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	130	50-369	William B. McGuire Nuclear Station, Unit 1	184
50-324	Brunswick Steam Electric Plant, Unit 2	132	50-370	William B. McGuire Nuclear Station, Unit 2	185
50-325	Brunswick Steam Electric Plant, Unit 1	134	50-373	LaSalle County Station, Unit 1	187
50-326	Univ. of California at Irvine Research Reactor	136	50-374	LaSalle County Station, Unit 2	189
50-327	Sequoyah Nuclear Plant, Unit 1	136	50-375	Nuclear Examination Reactor	190
50-328	Sequoyah Nuclear Plant, Unit 2	139	50-376	North Coast Nuclear Plant, Puerto Rico	191

Docket	Name	Page	Docket	Name	Page
50-382	Waterford Generating Station, Unit 3	191	50-446	Comanche Peak Steam Electric Station, Unit 2	224
50-387	Susquehanna Steam Electric Station, Unit 1	191	50-452	Greenwood Energy Center, Unit 2	226
50-388	Susquehanna Steam Electric Station, Unit 2	194	50-453	Greenwood Energy Center, Unit 3	226
50-389	St. Lucie Plant, Unit 2	196	50-454	Byron Station, Unit 1	226
50-390	Watts Bar Nuclear Plant, Unit 1	197	50-455	Byron Station, Unit 2	227
50-391	Watts Bar Nuclear Plant, Unit 2	198	50-456	Braidwood Station, Unit 1	228
50-395	Virgil C. Summer Nuclear Station, Unit 1	200	50-457	Braidwood Station, Unit 2	229
50-397	WPPSS Nuclear Project, Unit 2	203	50-458	River Bend Station, Unit 1	230
50-400	Shearon Harris Nuclear Power Plant, Unit 1	203	50-459	River Bend Station, Unit 2	230
50-401	Shearon Harris Nuclear Power Plant, Unit 2	204	50-460	WPPSS Nuclear Project, Unit 1	231
50-402	Shearon Harris Nuclear Power Plant, Unit 3	205	50-461	Clinton Power Station, Unit 1	231
50-403	Shearon Harris Nuclear Power Plant, Unit 4	205	50-462	Clinton Power Station, Unit 2	232
50-404	North Anna Power Station, Unit 3	206	50-465	Ringhals Nuclear Power Station, Unit 3, Sweden	233
50-405	North Anna Power Station, Unit 4	206	50-466	Allens Creek Nuclear Station, Unit 1	233
50-407	Univ. of Utah Research Reactor	206	50-467	Allens Creek Nuclear Station, Unit 2	234
50-409	La Crosse Boiling Water Reactor	206	50-471	Pilgrim Nuclear Power Station, Unit 2	234
50-410	Nine Mile Point Nuclear Station, Unit 2	208	STN-50-482	Wolf Creek Generating Station	235
50-412	Beaver Valley Power Station, Unit 2	209	STN-50-483	Calloway Plant, Unit 1	235
50-413	Catawba Nuclear Station, Unit 1	209	STN-50-484	Tyrone Energy Park, Unit 1	236
50-414	Catawba Nuclear Station, Unit 2	210	STN-50-485	Sterling Power Project Nuclear, Unit 1	236
50-416	Grand Gulf Nuclear Station, Unit 1	211	STN-50-486	Calloway Plant, Unit 2	237
50-417	Grand Gulf Nuclear Station, Unit 2	213	STN-50-488	Perkins Nuclear Station, Unit 1	237
50-423	Millstone Nuclear Power Station, Unit 3	214	STN-50-489	Perkins Nuclear Station, Unit 2	238
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	215	STN-50-490	Perkins Nuclear Station, Unit 3	238
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	215	STN-50-491	Cherokee Nuclear Station, Unit 1	238
STN-50-437	Floating Nuclear Plant	215	STN-50-492	Cherokee Nuclear Station, Unit 2	238
50-438	Bellefonte Nuclear Plant, Unit 1	216	STN-50-493	Cherokee Nuclear Station, Unit 3	239
50-439	Bellefonte Nuclear Plant, Unit 2	216	STN-50-498	South Texas Project, Unit 1	239
50-440	Perry Nuclear Power Plant, Unit 1	217	STN-50-499	South Texas Project, Unit 2	241
50-441	Perry Nuclear Power Plant, Unit 2	219	50-500	Davis-Besse Nuclear Power Station, Unit 2	243
50-443	Seabrook Nuclear Station, Unit 1	220	50-501	Davis-Besse Nuclear Power Station, Unit 3	243
50-444	Seabrook Nuclear Station, Unit 2	221	STN-50-508	WPPSS Nuclear Project, Unit 3	243
50-445	Comanche Peak Steam Electric Station, Unit 1	222			

Docket	Name	Page	Docket	Name	Page
STN-50-509	WPPSS Nuclear Project, Unit 5	243	STN-50-597	New Haven, Unit 2	255
50-513	WPPSS Nuclear Project, Unit 4	244	50-599	Carroll Facility I	256
50-514	Pebble Springs Nuclear Plant, Unit 1	244	50-600	Carroll Facility II	256
50-515	Pebble Springs Nuclear Plant, Unit 2	245	70-0008	Battelle Columbus Laboratories	256
STN-50-516	Jamesport Nuclear Station, Unit 1	245	70-0025	Rockwell International Corp.	256
STN-50-517	Jamesport Nuclear Station, Unit 2	245	70-0027	Babcock & Wilcox Co.	256
STN-50-518	Hartsville Nuclear Plant, Unit 1	245	70-0033	Texas Instruments, Inc.	256
STN-50-519	Hartsville Nuclear Plant, Unit 2	246	70-0048	Westinghouse Electric Corp.	256
STN-50-520	Hartsville Nuclear Plant, Unit 3	246	70-0135	Babcock & Wilcox Co.	256
STN-50-521	Hartsville Nuclear Plant, Unit 4	246	70-0143	Nuclear Fuel Services, Inc.	257
STN-50-522	Skagit Nuclear Power Project, Unit 1	246	70-0162	Lucius Pitkin, Inc.	258
STN-50-523	Skagit Nuclear Power Project, Unit 2	247	70-0182	Dept. of the Navy	258
STN-50-528	Palo Verde Nuclear Station, Unit 1	247	70-0261	Schlumberger Technology Corp.	258
STN-50-529	Palo Verde Nuclear Station, Unit 2	248	70-0267	Nuclear Science & Technology Facility at Suny	258
STN-50-530	Palo Verde Nuclear Station, Unit 3	248	70-0364	Parks Township Site, Babcock & Wilcox Co.	259
STN-50-533	Ringhals Nuclear Power Station, Unit 4, Sweden	249	70-0371	United Nuclear Corp.	259
STN-50-535	GASSAR-6	249	70-0398	Dept. of Commerce	259
50-537	Clinch River Breeder Reactor	249	70-0572	Monsanto Research Corp.	260
STN-50-546	Marble Hill Nuclear Station, Unit 1	249	70-0687	Unlon Carbide Corp.	260
STN-50-547	Marble Hill Nuclear Station, Unit 2	251	70-0698	Waltz Mill Site, Westinghouse Electric Corp.	260
50-548	Fort Calhoun Station, Unit 2	253	70-0734	General Atomic Co.	260
STN-50-553	Phipps Bend Nuclear Plant, Unit 1	253	70-0754	Vallecitos Nuclear Center, General Electric Co.	260
STN-50-554	Phipps Bend Nuclear Plant, Unit 2	253	70-0820	United Nuclear Corp.	260
STN-50-556	Black Fox Station, Unit 1	253	70-0824	Babcock & Wilcox Co.	260
STN-50-557	Black Fox Station, Unit 2	254	70-0882	Columbia Univ.	260
50-564	Nuclear Fuels Recovery and Recycle Center	254	70-0925	Cimarron Facility, Kerr-McGee Corp.	261
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	254	70-0997	Westinghouse Electric Corp.	261
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	255	70-1027	Atomic Energy of Canada, Chalk River Nuclear Laboratory	261
STN-50-580	Erie Nuclear Plant, Unit 1	255	70-1092	United Nuclear Corp.	261
STN-50-581	Erie Nuclear Plant, Unit 2	255	70-1100	Combustion Engineering, Inc.	261
STN-50-592	Palo Verde Nuclear Station, Unit 4	255	70-1113	General Electric Co.	261
STN-50-593	Palo Verde Nuclear Station, Unit 5	255	70-1143	Westinghouse Electric Corp.	262
STN-50-596	New Haven, Unit 1	255			

Docket	Name	Page	Docket	Name	Page
70-1151	Westinghouse Electric Corp.	262	71-0121	Neutron Products, Inc.	265
70-1193	Cimarron Facility, Kerr-McGee Corp.	262	71-0164	Massachusetts Institute of Technology	265
70-1201	UF-6 Conversion Facility, Babcock & Wilcox Co.	262	71-0198	Nuclear Fuel Services, Inc.	265
70-1207	Dept. of the Navy	262	71-0248	Monsanto Research Corp.	265
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	263	71-0325	Consumers Power Co.	265
70-1308	Morris Operations, General Electric Co.	263	71-0371	Model: NNFD-10, Unified Nuclear Corp.	265
70-1327	UF-6 Conversion Facility, Allied-General Nuclear Services Corp.	263	71-0382	Dept. of Interior Geological Survey	266
70-1432	Recycle Fuels Plant, Westinghouse Electric Corp.	263	71-0395	Dept. of the Navy, Naval Facilities Engineering Command	266
70-1470	Veterans Administration Hospital, Los Angeles, CA	263	71-0397	Teledyne Energy Systems	266
70-1503	Westinghouse R&D Center, Westinghouse Electric Corp.	263	71-0398	Texas A&M Univ.	266
70-1810	Westinghouse Electric Corp.	263	71-0399	State of North Carolina	266
70-1821	Plutonium Production Facility, Allied- General Nuclear Services Corp.	263	71-0400	Dept. of the Navy	266
70-1840	General Electric Co.	263	71-5026	Model: BC-48-220, Atcor, Inc.	266
70-1966	Tennessee Valley Authority	263	71-5059	Model: URANY NIT-TNK, Nuclear Fuel Services, Inc.	266
70-2116	Lawrence General Hosp., Lawrence, MA	264	71-5086	Model: UNC-2600, General Atomic Co.	266
70-2172	Westinghouse Electric Corp.	264	71-5442	Model: LA-36, Babcock & Wilcox Co.	266
70-2304	Medical College of Pennsylvania	264	71-5768	Model BB-250-2, Combustion Engineering Co., Inc.	266
70-2313	Nuclear Fuel Services, Inc.	264	71-5939	Model GE-1500, General Electric Co.	266
70-2314	General Electric Co.	264	71-5980	Model GE-600, General Electric Co.	266
70-2623	McGuire Spent Fuel Pool, Duke Power Co.	264	71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	267
70-2860	South Carolina Electric & Gas Co.	264	71-6273	Model 48X, F, A, Y, Allied-General Nuclear Services Corp.	267
70-2909	Westinghouse Electric Corp. Power Systems	264	71-6294	Model: UNC-2901, Combustion Engineering Co., Inc.	267
70-2910	Tennessee Valley Authority	265	71-6386	Model: 235R001, Dept. of Energy	267
70-2913	Tennessee Valley Authority	265	71-6400	Model: Super Tiger, Westinghouse Electric Corp.	267
70-2936	Mississippi Power & Light Co.	265	71-6568	Model: LL-60-150, TVA	267
71-0003	Exxon Nuclear Co., Inc.	265	71-6581	Model: 51032-1 & 1A, Exxon Nuclear Co., Inc.	267
71-0018	Nuclear Assurance Corp.	265	71-6601	Model: LL-50-100, Chem-Nuclear Systems, Inc.	267
71-0024	Hittman Nuclear & Development Corp.	265	71-6679	Model: 1/2 Super Tiger, Nuclear Engineering Co.	267
71-0102	Source Products & Equipment Co., Inc.	265			
71-0112	Dept. of the Navy	265			

Docket	Name	Page	Docket	Name	Page
71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	267	71-9086	Model: HN-100 Series 1, Hittman Nuclear & Development Corp.	268
71-6722	Model: BS-33-180, Tennessee Valley Authority	267	71-9089	Model: NH-100 S, Hittman Nuclear & Development Corp.	268
71-9010	Model: NLI-1/2, NL Industries, Inc.	267	71-9091	Model: 30 A, General Electric Co.	268
71-9019	Model: BU-7, General Electric Co.	268	71-9094	Model: CNSI-14-195-H, Chem-Nuclear Systems, Inc.	268
71-9044	Model: GE-1600, General Electric Co.	268	71-9132	Model: T-3, Nuclear Packaging, Inc.	268
71-9057	Model: FPD-100, General Atomic Co.	268	71-9136	Model: GE-9136, General Electric Co.	268
71-9070	Model: N-55, Dept. of Energy	268	71-9141	Model: 900 Type B, Technical Operations, Inc.	268
71-9074	Model: AP-100, Anefco, Inc.	268			

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Advanced Critical Reactor Experiment	50-246	34	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	117
Allens Creek Nuclear Station, Unit 1	50-466	233	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	119
Allens Creek Nuclear Station, Unit 2	50-467	234	Carroll Facility I	50-599	256
Arkansas Nuclear One, Unit 1	50-313	112	Carroll Facility II	50-600	256
Arkansas Nuclear One, Unit 2	50-368	181	Catawba Nuclear Station, Unit 1	50-413	209
Duane Arnold Energy Center	50-331	144	Catawba Nuclear Station, Unit 2	50-414	210
Bailly Generating Station	50-367	178	Cherokee Nuclear Station, Unit 1	STN-50-491	238
Barnwell Reprocessing Plant	50-332	146	Cherokee Nuclear Station, Unit 2	STN-50-492	238
Beaver Valley Power Station, Unit 1	50-334	148	Cherokee Nuclear Station, Unit 3	STN-50-493	239
Beaver Valley Power Station, Unit 2	50-412	209	Clinch River Breeder Reactor	50-537	249
Bellefonte Nuclear Plant, Unit 1	50-438	216	Clinton Power Station, Unit 1	50-461	231
Bellefonte Nuclear Plant, Unit 2	50-439	216	Clinton Power Station, Unit 2	50-462	232
Big Rock Point Nuclear Power Plant	50-155	16	Comanche Peak Steam Electric Station, Unit 1	50-445	222
Black Fox Station, Unit 1	STN-50-556	253	Comanche Peak Steam Electric Station, Unit 2	50-446	224
Black Fox Station, Unit 2	STN-50-557	254	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	115
Braidwood Station, Unit 1	50-456	228	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	116
Braidwood Station, Unit 2	50-457	229	Cooper Nuclear Station	50-298	98
Browns Ferry Nuclear Power Station, Unit 1	50-259	49	Cornell Univ. Research Reactor	50-157	18
Browns Ferry Nuclear Power Station, Unit 2	50-260	50	Cornell Univ. Zero Power Reactor	50-97	15
Browns Ferry Nuclear Power Station, Unit 3	50-296	96	Crystal River Nuclear Plant, Unit 3	50-302	100
Brunswick Steam Electric Plant, Unit 1	50-325	134	Davis-Besse Nuclear Power Station, Unit 1	50-346	161
Brunswick Steam Electric Plant, Unit 2	50-324	132	Davis-Besse Nuclear Power Station, Unit 2	50-500	243
Byron Station, Unit 1	50-454	226	Davis-Besse Nuclear Power Station, Unit 3	50-501	243
Byron Station, Unit 2	50-455	227			
Calloway Plant, Unit 1	STN-50-483	235			
Calloway Plant, Unit 2	STN-50-486	237			

Name	Docket	Page	Name	Docket	Page
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	69	Shearon Harris Nuclear Power Plant, Unit 1	50-400	203
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	130	Shearon Harris Nuclear Power Plant, Unit 2	50-401	204
Dow Chemical Co.	50-264	55	Shearon Harris Nuclear Power Plant, Unit 3	50-402	205
Dresden Nuclear Power Station, Unit 1	50-10	10	Shearon Harris Nuclear Power Plant, Unit 4	50-403	205
Dresden Nuclear Power Station, Unit 2	50-237	26	Hartsville Nuclear Plant, Unit 1	STN-50-518	245
Dresden Nuclear Power Station, Unit 3	50-249	37	Hartsville Nuclear Plant, Unit 2	STN-50-519	246
Erle Nuclear Plant, Unit 1	STN-50-580	255	Hartsville Nuclear Plant, Unit 3	STN-50-520	246
Erle Nuclear Plant, Unit 2	STN-50-581	255	Hartsville Nuclear Plant, Unit 4	STN-50-521	246
Joseph M. Farley Nuclear Plant, Unit 1	50-348	162	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	127
Joseph M. Farley Nuclear Plant, Unit 2	50-364	173	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	176
Enrico Fermi Atomic Power Plant, Unit 2	50-341	158	Hope Creek Nuclear Station, Unit 1	50-354	167
James A. Fitzpatrick Nuclear Power Plant	50-333	146	Hope Creek Nuclear Station, Unit 2	50-355	168
Floating Nuclear Plant	STN-50-437	215	Humboldt Bay Power Plant, Unit 3	50-133	15
Forked River Nuclear Station, Unit 1	50-363	173	Indian Point Station, Unit 1	50-3	9
Fort Calhoun Station, Unit 1	50-285	80	Indian Point Station, Unit 2	50-247	34
Fort Calhoun Station, Unit 2	50-548	253	Indian Point Station, Unit 3	50-286	81
Fort St. Vrain Nuclear Generating Station	50-267	59	Iowa State Univ. Research Reactor	50-116	15
GASSAR-6	STN-50-535	249	Isochem, Inc. Fission Production Conversion Plant	50-258	48
General Atomic Co.	50-89	14	Jamesport Nuclear Station, Unit 1	STN-50-516	245
General Atomic Co.	50-163	18	Jamesport Nuclear Station, Unit 2	STN-50-517	245
General Electric Nuclear Test Reactor	50-73	14	Kewaunee Nuclear Power Plant	50-305	104
General Electric Test Reactor	50-70	14	La Crosse Boiling Water Reactor	50-409	206
Georgia Institute of Technology Research Reactor	50-160	18	LaSalle County Station, Unit 1	50-373	187
Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	30	LaSalle County Station, Unit 2	50-374	189
Grand Gulf Nuclear Station, Unit 1	50-416	211	Limerick Generating Station, Unit 1	50-352	165
Grand Gulf Nuclear Station, Unit 2	50-417	213	Limerick Generating Station, Unit 2	50-353	166
Greenwood Energy Center, Unit 2	50-452	226	Maine Yankee Atomic Power Plant	50-309	107
Greenwood Energy Center, Unit 3	50-453	226	Manhattan College Research Reactor	50-199	19
Haddam Neck Plant	50-213	21	Marble Hill Nuclear Station, Unit 1	STN-50-546	249
			Marble Hill Nuclear Station, Unit 2	STN-50-547	251

			NAME	Docket	Page
William B. McGuire Nuclear Station, Unit 1	50-369	184	Peach Bottom Atomic Power Station, Unit 3	50-278	73
William B. McGuire Nuclear Station, Unit 2	50-370	185	Pebble Springs Nuclear Plant, Unit 1	50-514	244
Midland Plant, Unit 1	50-329	140	Pebble Springs Nuclear Plant, Unit 2	50-515	245
Midland Plant, Unit 2	50-330	142	Pennsylvania State Univ. Research Reactor	50-5	9
Millstone Nuclear Power Station, Unit 1	50-245	32	Perkins Nuclear Station, Unit 1	STN-50-488	237
Millstone Nuclear Power Station, Unit 2	50-336	151	Perkins Nuclear Station, Unit 2	STN-50-489	238
Millstone Nuclear Power Station, Unit 3	50-423	214	Perkins Nuclear Station, Unit 3	STN-50-490	238
Monticello Nuclear Generating Plant	50-263	54	Perry Nuclear Power Plant, Unit 1	50-440	217
New Haven, Unit 1	50-596	255	Perry Nuclear Power Plant, Unit 2	50-441	219
New Haven, Unit 2	50-597	255	Phipps Bend Nuclear Plant, Unit 1	STN-50-553	253
Nine Mile Point Nuclear Station, Unit 1	50-220	25	Phipps Bend Nuclear Plant, Unit 2	STN-50-554	253
Nine Mile Point Nuclear Station, Unit 2	50-410	208	Pilgrim Nuclear Power Station, Unit 1	50-293	91
North Anna Power Station, Unit 1	50-338	153	Pilgrim Nuclear Power Station, Unit 2	50-471	234
North Anna Power Station, Unit 2	50-339	155	Plum Brook Reactor - Mock-up	50-185	18
North Anna Power Station, Unit 3	50-404	206	Plum Brook Research Reactor Facility	50-30	13
North Anna Power Station, Unit 4	50-405	206	Point Beach Nuclear Plant, Unit 1	50-266	57
North Coast Nuclear Plant, Puerto Rico	50-376	191	Point Beach Nuclear Plant, Unit 2	50-301	99
Nuclear Examination Reactor	50-375	190	Prairie Island Nuclear Station, Unit 1	50-282	79
Nuclear Fuels Recovery and Recycle Center	50-564	254	Prairie Island Nuclear Station, Unit 2	50-306	106
Oconee Nuclear Station, Unit 1	50-269	61	Quad-Cities Station, Unit 1	50-254	44
Oconee Nuclear Station, Unit 2	50-270	63	Quad-Cities Station, Unit 2	50-265	55
Oconee Nuclear Station, Unit 3	50-287	84	Rancho Seco Nuclear Generating Station	50-312	111
Ohio State Univ. Research Reactor	50-150	16	Reed College Research Reactor	50-288	86
Oyster Creek Nuclear Power Plant	50-219	22	Ringhals Nuclear Power Station, Unit 3, Sweden	50-465	233
Palisades Nuclear Plant	50-255	46	Ringhals Nuclear Power Station, Unit 4, Sweden	50-533	249
Palo Verde Nuclear Station, Unit 1	STN-50-528	247	River Bend Station, Unit 1	50-458	230
Palo Verde Nuclear Station, Unit 2	STN-50-529	248	River Bend Station, Unit 2	50-459	230
Palo Verde Nuclear Station, Unit 3	STN-50-530	248	H. B. Robinson Plant, Unit 2	50-261	52
Palo Verde Nuclear Station, Unit 4	STN-50-592	255	Rockwell International Corp. Critical Facility	50-147	16
Palo Verde Nuclear Station, Unit 5	STN-50-593	255	Rockwell International Research Reactor	50-94	14
Peach Bottom Atomic Power Station, Unit 2	50-277	71	Salem Nuclear Generating Station, Unit 1	50-272	67

Name	Docket	Page	Name	Docket	Page
Salem Nuclear Generating Station, Unit 2	50-311	109	UCLA Training Reactor	50-142	16
San Onofre Nuclear Station, Unit 1	50-206	19	Union Carbide Research Reactor	50-54	13
San Onofre Nuclear Station, Unit 2	50-361	170	Univ. of California at Irvine Research Reactor	50-326	136
San Onofre Nuclear Station, Unit 3	50-362	172	Univ. of Michigan Research Reactor	50-2	9
Saxton Nuclear Experimental Facility	50-146	16	Univ. of Missouri Research Reactor	50-186	18
Seabrook Nuclear Station, Unit 1	50-340	158	Univ. of Nevada Research Reactor	50-202	19
Seabrook Nuclear Station, Unit 1	50-443	220	Univ. of Oklahoma Research Reactor	50-112	15
Seabrook Nuclear Station, Unit 2	50-444	221	Univ. of Utah Research Reactor	50-72	14
Sequoyah Nuclear Plant, Unit 1	50-327	136	Univ. of Utah Research Reactor	50-407	206
Sequoyah Nuclear Plant, Unit 2	50-328	139	Vallecitos Boiling Water Reactor	50-18	12
Shoreham Nuclear Power Station	50-322	129	Vallecitos Experimental Superheat Reactor	50-183	18
Skagit Nuclear Power Project, Unit 1	STN-50-522	246	Vermont Yankee Nuclear Power Station	50-271	65
Skagit Nuclear Power Project, Unit 2	STN-50-523	247	Virginia Polytechnic Institute Training Reactor	50-124	15
South Texas Project, Unit 1	STN-50-498	239	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	215
South Texas Project, Unit 2	STN-50-499	241	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	215
Space Radiation Research Reactor	50-187	19	Waterford Generating Station, Unit 3	50-382	191
Sterling Power Project, Nuclear, Unit 1	STN-50-485	236	Watts Bar Nuclear Plant, Unit 1	50-390	197
St. Lucie Plant, Unit 1	50-335	150	Watts Bar Nuclear Plant, Unit 2	50-391	198
St. Lucie Plant, Unit 2	50-389	196	West Valley Reprocessing Plant	50-201	19
Virgil C. Summer Nuclear Station, Unit 1	50-395	200	Wolf Creek Generating Station	STN-50-482	235
Surry Power Station, Unit 1	50-280	75	Worcester Polytechnic Institute Research Reactor	50-134	16
Surry Power Station, Unit 2	50-281	77	WPPSS Nuclear Project, Unit 1	50-460	231
Susquehanna Steam Electric Station, Unit 1	50-387	191	WPPSS Nuclear Project, Unit 2	50-397	203
Susquehanna Steam Electric Station, Unit 2	50-388	194	WPPSS Nuclear Project, Unit 3	STN-50-508	243
Texas A&M Univ. Research Reactor	50-128	15	WPPSS Nuclear Project, Unit 4	50-513	244
Three Mile Island Nuclear Station, Unit 1	50-289	86	WPPSS Nuclear Project, Unit 5	STN-50-509	243
Three Mile Island Nuclear Station, Unit 2	50-320	120	Yankee-Rowe Nuclear Power Station	50-29	12
Trojan Nuclear Plant	50-344	158	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	254
Turkey Point Plant, Unit 3	50-250	41	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	255
Turkey Point Plant, Unit 4	50-251	42	William H. Zimmer Nuclear Station, Unit 1	50-358	169
Tyrone Energy Park, Unit 1	50-484	236	Zion Nuclear Power Station, Unit 1	50-295	93
			Zion Nuclear Power Station Unit 2	50-304	102

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-010 BEATTY, NV

8011170189 "Geology & Hydrology of Proposed Site for Burial of Solid Radwaste Southeast of Beatty, Nye County, NV," App A Attachment F to 800404 application for renewal of NV License 13-11-0043-02
CLEBSCH, A Nuclear Engineering Co, Inc, (subs of Teledyne, Inc)
80/04/04 35pp 06915 001

8011190053 PNO-V-80-75 on 801103, Nuclear Engineering Co, Beatty, NV, burial site received shipment of 40 wooden boxes from GE, Wilmington, NC, which were found to be leaking liquid State of NV has banned GE from use of burial site
THOMAS, R D Region 3, San Francisco, Office of the Director
80/11/05 1p 07001 293

DOCKET 27-039 SHEFFIELD, IL, NUCLEAR ENGINEERING CO

8011040646 Ack receipt of 800509 ltr informing NRC of steps taken to correct violations noted in Waste Packaging Insp Rept
15000039/79-08
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch
80/10/08 1p 06873 357

801110115 Advises that visit to disposal site is scheduled for 801028-29 to review maint of records & discuss operating experience
STEPHEN, D L Low Level Waste Licensing Branch
80/10/23 5pp 06943 319

8011120061 Forwards omitted Page 31 of NUREG/CR-1683, "Characterization of Existing Surface Conditions at Sheffield Low Level Waste Facility"
MARTIN, J B Division of Waste Management
80/10/29 1p, 06953 325.

--8011120065 Omitted Page 31 for "Characterization of Existing Surface Conditions at Sheffield Low Level Waste Disposal Facility"
HEIM, G E, MACHALINSKI, M Harding-Lawson Associates
NUREG/CR-1683 ERR
80/10/29 1p 06953 326

8011050050 Request to strike State of IL 801020 general objection to discovery requests Request is in disregard of Commission rules of practice & ABLB 800909 discovery order Objection waived due to untimely filing Certificate of Svc encl
CONNOR, T B, RADER, R M Nuclear Engineering Co, Inc, (subs of Teledyne, Inc)
CONNOR, T B Connor, Moore & Corber
80/10/30, 7pp 06897 260

8011040379 Forwards unexecuted stipulation re deferring taking of depositions until written discovery is completed & deferring State of IL responses to licensee discovery. Requests signature if client is agreeable Related correspondence
ANSBACH, K Illinois, State of
80/10/31 2pp 06873 349

8011050151 Response to ANS, Chicago Section interrogatories. Identifies persons intended to be called as witnesses & persons consulted by util Objects to remaining interrogatories Certificate of Svc encl
ANSBACH, K G, FAHNER, T C, WOLFF, Q W Illinois, State of
80/10/31 8pp 06897 291

801100218 Response to State of IL first set of interrogatories Identifies present & past executives, employees working in facility, contractors & consultants Related correspondence
BAER, T S Nuclear Engineering Co, Inc, (subs of Teledyne, Inc.)
80/10/31 12pp 06929 048

--801100225 Response to NRC first set of interrogatories & request for production of documents Explains current status of lease entered & terminated w/State of IL re low level radwaste disposal Certificate of Svc encl
BAER, T S Nuclear Engineering Co, Inc, (subs of Teledyne, Inc)
80/10/31 7pp 06929 038

8011060248 Response to util 801010 interrogatories & requests for admissions & production of documents Cites & documents instances of noncompliances noted in IE insp repts Insp correspondence, affidavits & Certificate of Svc encl
HAWKINS, E, SHAFFNER, J, TURI, O P Low Level Waste Licensing Branch
80/11/03 38pp 02319 196

8011060388 Response to ANS Chicago Section, Interrogatories 1-3, 5, 6, 8, 11-14 & 16-19 Identifies persons involved in preparation of NRC position & experts intended to be called as witnesses Affidavits & Certificate of Svc encl
TURI, O P, SHAFFNER, J, DRAGONETTE, K S Low Level Waste Licensing Branch
80/11/03 17pp 06911 002

801100233 Stipulation setting 801118 as date for State of IL to respond to interrogatories & requests for documents & admissions IL will continue scheduled depositions TD Connor
801103 ltr to State of IL encl
CONNOR, T B Nuclear Engineering Co, Inc, (subs of Teledyne, Inc)
ANSBACH, K, FAHNER, T C Illinois, State of
80/11/03, 3pp 06929 067

8011060192 Response stating no objection to Nuclear Engineering Co 801014 motion to reopen discovery Conditions position on mod of schedule to allow sufficient time for NRC to respond to discovery requests Certificate of Svc encl
MCGURREN, H J Hearing Branch 3
80/11/04 4pp 06912 094

801110393 Response in opposition to Nuclear Engineering motion to strike State of IL 801020 objection to discovery. Requests extension until 801118 to respond to requests w/affidavit, K Ansbach 801031 ltr, draft stipulation & Certificate of Svc
ANSBACH, K O, FAHNER, T C, WOLFF, Q W Illinois, State of.
80/11/07, 12pp 06946 255

8011180152 Summary of 800925 meeting w/NECO in Washington, DC re NRC site closure conditions for disposal facility. Several clarifications made but no formal agreements or commitments
HAWKINS, E F Low Level Waste Licensing Branch
80/11/12 4pp 06987 209

8011190171 Motion for order compelling Nuclear Engineering Co to respond to certain of NRC 801010 first set of interrogatories & request for production of documents Info may reveal background facts Certificate of Svc encl
MCGURREN, H J Hearing Branch 3
80/11/14 17pp 06998 208.

8011250045 Request for order to compel applicant, Nuclear Engineering Co, to answer 801010 request for designation of witnesses to be used at hearing Certificate of Svc encl.
ANSBACH, K O, FAHNER, T C Illinois, State of
80/11/14, 4pp 07055 208

8011250694 Motion to compel answers to certain of intervenor first set of interrogatories to Nuclear Engineering Co Legal relationship between parent & subsidiary corporations is relevant. Certificate of Svc encl
ANSBACH, K O, FAHNER, T C Illinois, State of
80/11/14 39pp 07068 210.

8011190135 Motion to compel intervenors Schieler et al & County of Bureau responses to interrogatories Intervenor failed to comply w/ASLB 800909 prehearing conference order requiring objections by 801020 or response by 801101
CONNOR, T B, RADER, R M Nuclear Engineering Co, Inc, (subs of Teledyne, Inc)
CONNOR, T B Connor, Moore & Corber
80/11/15, 3pp, 06998 308

DOCKETED ITEMS

--801190145 Motion to compel State of IL response to requests for admissions & interrogatories & request for production of documents IL neither filed objection nor answers per ASLB
BOU709 prehearing conference order
CONNER, T B , RADER, R M Nuclear Engineering Co , Inc , (subs of Teledyne, Inc) CONNER, T B Conner, Moore & Corber 80/11/15 7pp 0699B 311

--801190159 Motion to compel NRC response to requests for admissions & interrogatories & request for production of documents NRC
801023 objections & 801103 answers deprive util of opportunity to present theory of case w/Certificate of Svc
CONNER, T B , RADER, R M Nuclear Engineering Co , Inc , (subs of Teledyne, Inc) CONNER, T B Conner, Moore & Corber 80/11/15 24pp 0699B 318

8011240159 Motion to compel Nuclear Engineering Co to produce documents pursuant to 801010 request Certificate of Svc encl
ANSFACH, K O , FAHNER, T C Illinois, State of 80/11/17 18pp 07041 131

8011250038 Withdrawal of 801010 notice of deposition & request for production of documents until after completion of written or documentary discovery Certificate of Svc encl
ANSFACH, K O , FAHNER, T C Illinois, State of 80/11/18 4pp 07046 201

8011250633 Response to Nuclear Engineering Co request for admissions, interrogatories & request for production of documents
Includes list of witnesses to be called & areas of testimony w/Affidavit & Certificate of Svc
ANSFACH, K O , FAHNER, T C Illinois, State of 80/11/18 13pp 07058 187

DOCKET 27-043 PEEMSKILL, H

8011250633 Comments on proposed rule 10CFR20 re dumping of low level radwaste into sewer s/s & reopening of reprocessing plant in West Valley, NY Opposes rule & reopening of reprocessing plant
JONIENTI, R Affiliation Unknown 80/11/03 2pp 02227 001

8011180773 Summary of 801020 meeting w/DGE re technical aspects of plans to implement high level waste solidification project & DOE responsibilities
DAVIS, J G Office of Nuclear Material Safety & Safeguards 80/11/12 2pp 06989 107

DOCKET 27-047 BARNWELL, SC ,CHEM-NUCLEAR SYSTEMS

8011260123 Forwards IE Waste Packaging Insp Rept 15000039/80-13 & IE Insp Rept 40-0572/80-02 on 800618 & 0730-0801
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/02 2pp 07074 259

--8011260129 IE Waste Packaging Insp Rept 15000039/80-13 on 800618
Noncompliance noted elevated radiation level
MACARTHUR, T C , POTTER, J P Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/25 4pp 07074 286

8011060607 Ack receipt of Waste Packaging Insp Rept 15000039/80-15 on 800727-0801 No proprietary info
KAPLAN, A L General Electric Co , Nuclear Energy Products Div 80/10/07 1p 06909 259

--8011060613 Forwards Waste Packaging Insp Rept 15000039/80-15 on 800727-0801 No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 2pp 06909 269

--8011060620 Waste Packaging Insp Rept 15000039/80-15 on 800727-0801 No noncompliance noted Major areas inspected licensee-shipper vehicle for compliance w/shipping paper requirements, radiation levels & removable contamination
MACARTHUR, T C , POTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/16 8pp 06909 271

8011210403 Forwards IE Waste Packaging Insp Repts 50-327/80-33 & 50-328/80-18 on 800811 & 25 No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/15 2pp 07034 014

--8011210413 IE Waste Packaging Insp Repts 50-327/80-33 & 50-328/80-18 on 800811 & 25 No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels & removable contamination
MACARTHUR, T C , PUCKETT, J M , POTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/14 5pp 07034 016

8011210326 Ack receipt of 801009 ltr informing NRC of steps taken to correct violations noted in IE Waste Packaging Insp Rept 15000039/80-07
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/24 1p 07030 144

--8011210336 Responds to NRC 800917 ltr re violations noted in IE Waste Packaging Insp Rept 15000039/80-07 Corrective actions labels will be affixed to survive inclement weather & waste checklist will be modified
MOODY, D E Maine Yankee Atomic Power Co 80/10/09 2pp 07030 145

--8011210356 Forwards IE Waste Packaging Insp Rept 15000039/80-07 on 800516 & notice of violation
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/17 2pp 07030 147

--8011210363 Notice of violation from Insp on 800516
* Region 1, Philadelphia, Office of the Director NRC 80/08/18 1p 07030 149

--8011210373 IE Waste Packaging Insp Rept 15000039/80-07 on 800516
Noncompliance noted outside of package containing low specific activity radioactive matl not stencilled or otherwise marked to identify contents
MACARTHUR, T C , POTTER, J P Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/18 4pp 07030 131

8011210711 Ack receipt of 801010 ltr informing NRC of steps taken to correct violations noted in Waste Packaging Insp Rept 15000039/80-17
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/24 1p 07029 001

--8011210717 Responds to NRC 800922 ltr re violations noted in Waste Packaging Insp Rept 15000039/80-17 Corrective actions pictures taken of all vehicles leaving site w/radioactive matl for burial showing proper placards
COURISIL, W G , FEE, W F Connecticut Yankee Atomic Power Co 80/10/10 5pp 07029 002

--8011210724 Forwards Waste Packaging Insp Rept 15000039/80-17 on 800728 & notice of violation
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/22 2pp 07029 007

--8011210729 Notice of violation from Waste Packaging Insp Rept 15000039/80-17 on 800728
* Region 1, Philadelphia, Office of the Director 80/08/18 1p 07029 009

--8011210736 Waste Packaging Insp Rept 15000039/80-17 on 800728
Noncompliance noted failure to properly placard vehicle transporting waste radioactive matl
MACARTHUR, T C , POTTER, J P Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/18 4pp 07029 011

8011210229 Responds to NRC 801003 ltr transmitting questions re license renewal & std operating procedures Forwards "Environ Annual Rept 1979" & "Environ First Quarter Rept 1980"
CORBETT, J S Chem-Nuclear Systems, Inc 80/10/29 8pp 07032, 350

--8011210232 "Environ Annual Rept 1979"
* Chem-Nuclear Systems, Inc 80/10/29 75pp 07032 358

--8011210235 "Environ First Quarter Rept 1980"
* Chem-Nuclear Systems, Inc 80/10/29 49pp 07033 114,

DOCKET 27-048 RICHLAND, WA ,NUCLEAR ENGINEERING CO

8011100020 EIA for renewal of SNM disposal license at facility
* Commissioners 80/01/18 20pp 06929 165

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP

8011050255 Notifies of 800908 visual insp of evaporation pond const procedures at site No noncompliance noted Surveyed invert elevations for north & south ponds should be submitted to NRC in weekly repts
HANSBOM, H W Barr Engineering Co 80/09/19, 2pp 06896 282

DOCKETED ITEMS

3

8011040056 Advises that pumping tests in 800805 submittal, "A-9 Pit Leaky Aquifer Tests for Union Carbide Corp by Hydro-Engineering," are invalid. New tests must be performed. Requests response to encl comments by 801114.
LINEHAN, J J Uranium Recovery Licensing Branch 80/10/14 6pp 06911 155

8011190245 Trip repts of 800922-29 visits to AZ Public Svc Co, Kerr McGee in situ leach site, Teton, East Gas Hills, Federal-American Partners mill & lab, Moab, Dyle Petroleum & Uranium re amends to Reg Guide 4 14 W/o photos
VANDELL, T D Uranium Recovery Licensing Branch 80/10/28 7pp. 07000 089

8011070440 Forwards "Const Rept on Evaporation Ponds, East Gas Hills, WY Plant Site " Four oversize drawings available in Central Files only
PARIS, N C Union Carbide Corp 80/10/31 1p 06918 004

--8011070445 "Const Rept on Evaporation Ponds, East Gas Hills, WY Plant Site "
* Union Carbide Corp 80/10/31 92pp 06918 005

8011250319 Forwards analytical results of surface & core samples from area affected by releases of seepage from west tailings berm sump, per Condition 7 of Amend 15 to License SUA-648. Results constitute addendum to 800707 ltr
WONG, T Union Carbide Corp 80/11/19 3pp 07055 146

8011250324 Forwards insp & monitoring program re new tailings disposal sys, per Condition 7 of Amend 15 to License SUA-648
WONG, T Union Carbide Corp 80/11/19 5pp 07055 141

DOCKET 40-0504 GENERAL ELECTRIC CO , LAMP BUSINESS DIV

8010020739 Submits corporate info applicable to encl list of licenses Forwards Annual Financial Rept 1979
DIPIAZZA, R P Westinghouse Electric Corp. 80/09/04. 5pp 03616 198

--8010020745 Annual Financial Rept 1979
* Westinghouse Electric Corp 80/01/30 51pp. 03616 203

DOCKET 40-0672 NUCLEAR METALS, INC

8011260123 Forwards IE Waste Packaging Insp Rept 15000039/80-13 & IE Insp Rept 40-0672/80-02 on 800618 & 0730-0801
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/02. 2pp 07074 259

--8011260126 IE Insp Rept 40-0672/80-02 on 800730-0801 Noncompliance noted. Severity Level 1 radiation level elevated in cab of truck & inadequacies in mgt control & procedures re packaging & transportation of radwaste
ROTH, J Region 1, Philadelphia, Office of the Director
CROCKER, H W. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/26 25pp 07074 261

--8011260129 IE Waste Packaging Insp Rept 15000039/80-13 on 800618 Noncompliance noted elevated radiation level.
MACARTHUR, T C , POTTER, J P Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/25 4pp 07074 286

DOCKET 40-1162 WESTERN NUCLEAR, INC

8011170404 Forwards NUREQ-0639, FES on environ considerations re U mill & FR notice of availability
SCARAND, R A Uranium Recovery Licensing Branch 80/03/04 1p 06911.001

--8011170415 Notice of availability of NUREQ-0639, FES for Split Rock U mill.
SCARAND, R A. Uranium Recovery Licensing Branch 80/02/15 3pp 06911 001

--8011170424 FES for facility
* Office of Nuclear Material Safety & Safeguards NUREQ-0639 80/02/29. 350pp Available at NTIS 06911 001.

8011070431 Submits recommendations on proposed license conditions for facility in response to NRC 800828 ltr Viable groundwater monitoring program must be established
ACKERMAN, W C., GARLAND, W Wyoming, State of 80/09/04 2pp. 06921 039

8011070617 Confirms 800925 telcon re spacing for resistivity survey soundings & clarification of anticipated results.
BOGDEN, G Western Nuclear, Inc (subs of Phelps Dodge Corp) 80/10/06 3pp 06921 030

8011050024 Forwards tailings dam insp rept for 800929-1005
BOGDEN, G Western Nuclear, Inc (subs of Phelps Dodge Corp) 80/10/08 4pp 06896 286

8011090407 Petition to intervene in license renewal proceeding Certificate of Svc encl
BOOKE, B L Wyoming Outdoor Council 80/10/15 1p 06898 171

8011040400 Order granting WY Outdoor Council 801015 motion to withdraw petition to intervene Conditions of encl 801015 stipulation will be made part of renewed license if issued Proceeding dismissed
WOLFE, B J Atomic Safety and Licensing Board Panel 80/10/30 3pp 06873 255

--8011040403 Stipulation setting license conditions re performance of hydrology study, incorporation of groundwater well monitoring program, development of plan re seepage environ impacts & other related conditions.
BOOKE, B L Wyoming Outdoor Council WALPOLE, J R Western Nuclear, Inc. (subs of Phelps Dodge Corp) MCCOURREN, H J Hearing Branch 3 80/10/15 3pp 06873, 258

DOCKET 40-1341 EDGEHOMT URANIUM MINE, TVA & MINES DEVELOPMENT, INC

8011050175 Forwards affidavit of svc for correspondence re decommissioning plan environ rept
MILLS, L M Tennessee Valley Authority 80/10/07 5pp 06896 340

8011190260 Comments on Revision 3, environ rept, Edgemont U mill decommissioning plan, in response to NRC 801002 request. Rept provides adequate description of selected disposal site & proposed measures to protect surface waters
KEENLYNE, K D Interior, Dept of, Fish & Wildlife Service 80/10/27. 3pp 07000 096

8011190307 Advises that NRC determined at 800930 meeting w/EPA that 40CFR190 is no longer applicable to site. Util must ensure that all practicable control measures are taken to reduce exposures to as low as possible during decommissioning
SCARAND, R A. Uranium Recovery Licensing Branch 80/11/03. 1p. 06996 276

DOCKET 40-2053 LITTLE CREEK MINING & MILLING CO

8011210613 Forwards IE Insp Rept 40-2053/80-01 on 801024 & 27 No noncompliance noted
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/03. 1p 07029 260

--8011210618 IE Insp Rept 40-2053/80-01 on 801024 & 27 No noncompliance noted Major areas inspected status of expired license & review of license file
NICHOLSON, N A , PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/11/03 3pp 07029 261

DOCKET 40-2061 WEST CHICAGO FACILITY, KERR-MCQUEE CORP

8011190501 Informs that results of bioassay measurements taken by ANL indicate that levels of Ra-226 not elevated & levels of Th-232 within range of background for residents of West Chicago
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/28 1p. 06998 114

--8011190503 Discusses result of radiation measurements of employees at former plant in West Chicago No excessive amounts of Ra-226 or Th-232 detected for 8 Tennes
* Argonne National Laboratory 80/10/01 2pp. 06998.115

8011190510 Informs that results of bioassay measurements taken by ANL indicate that levels of Ra-226 not elevated & levels of Th-232 within range of background for residents of West Chicago.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28. 1p 06998 117

DOCKETED ITEMS

801190522 Informs that results of bioassay measurements taken by ANL indicate that levels of Ra-226 not elevated & levels of Th-232 uncertain & possibly higher than those of average resident of Chicago
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28
1p 06998 130

--801190528 Discusses results of radiation measurements of employees at former plant in West Chicago No excessive amounts of Ra-226 & possible excessive amounts of Th-232 found for R Johnson
Argonne National Laboratory 80/10/01 2pp 06998 131

801190540 Informs that results of bioassay measurements taken by ANL indicate that levels of Ra-226 not elevated & levels of Th-232 uncertain & possibly higher than those of average resident of Chicago
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28
1p 06998 158

801190597 Informs that results of bioassay measurements taken by ANL indicate that levels of Ra-226 not elevated & levels of Th-232 within range of background for residents of West Chicago
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28
1p 06916 001

8011200541 Discusses results of bioassay measurements by ANL for T Schwantes internal burden measurements. Individual does not contain elevated levels of Ra-226 or Th-232
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28
1p 01741 019

801190578 Informs that results of bioassay measurements taken by ANL indicate that levels of Ra-226 not elevated & levels of Th-232 within range of background for residents of West Chicago
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/29
1p 07001 198

8011240102 Discusses results of bioassay measurements by ANL for NE Rennels internal burden of radioactive matl Individual does not contain elevated levels of Ra-226 or Th-232
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/29
1p 07049 147

8011240121 Discusses results of bioassay measurements by ANL for F Rocca internal burden of radioactive matl Individual does not contain elevated levels of Ra-226 or Th-232
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/29
1p 07049 150

8011240126 Discusses results of bioassay measurements by ANL for A Nell internal burden of radioactive matl Individual does not contain elevated levels of Ra-226 or Th-232
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/29
1p 07049 153

8011240132 Discusses results of bioassay measurements by ANL for RA Hensel internal burden of radioactive matl Individual does not contain elevated levels of Ra-226 or Th-232
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/29
1p 07049 156

8011240141 Discusses results of bioassay measurements by ANL for RA Rennels internal burden of radioactive matl Individual does not contain elevated levels of Ra-226 or Th-232
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/29
1p 07049 160

DOCKET 40-2259 PATHFINDER MINES CORP

801190320 Summary of 800825 meeting w/vendor in Silver Spring, MD re current status of embankment const, tailing mgt plans & NRC review of 1978 & 1979 monitoring data
GILLEN, D H Uranium Recovery Licensing Branch 80/10/08 5pp.

801103378 Requests addl field work re up-to-date inventory of extraneous sources re NRC evaluation of compliance w/ 40CFR190 NRC would consider authorizing license amend for temporary relocation of air monitoring station, if requested
SCARANO, R A Uranium Recovery Licensing Branch 80/10/16 2pp
06857 306

8011230788 Forwards monitoring data from Lucky Mcmill per 801114 request info includes airborne radiation monitoring, radon daughter monitoring for Jan 1979-Oct 1980 & personnel monitoring including bioassays for 1978-1980 w/o encl
POYER, R W Pathfinder Mines Corp 80/11/19 1p 07056 082

DOCKET 40-3453 ATLAS MINERALS

8011060046 Forwards map of proposed location for background monitoring site in response to NRC 800910 ltr Requests NRC comments
SWANBY, O T Atlas Minerals 80/09/26 2pp 02319 196

8011050228 Confirms 800930 telcon re Fourth Quarter 1979 & First Quarter 1980 repts of radium assays No errors found in calculations. Trucking of ore from stockpile during Fourth Quarter 1979 may have caused high readings
SWANBY, O T Atlas Minerals 80/10/06 1p 06899 056

801190037 Forwards listing of needed info re 40CFR190 compliance Requests response by 801103
LINEHAN, J J Uranium Recovery Licensing Branch 80/10/23 2pp
06996 270

801120645 Forwards questions & comments addressing NRC concerns re current hydrogeologic conditions & ground water & surface water monitoring programs at site Schedule for compiling & evaluating info should be submitted by 801031
LINEHAN, J J Uranium Recovery Licensing Branch 80/10/24 7pp
06953 262.

801190022 Confirms 80114 meeting in Washington, DC to meet new president, RR Weaver & to discuss raising tailing structure, surety requirements, addl seepage studies, 40CFR190 & 801003 final regulations.
SWANBY, O T Atlas Minerals 80/10/24 1p 06996 272

801190245 Trip repts of 800922-29 visits to AZ Public Svc Co, Kerr McQue in situ leach site, Teton, East Gas Hills, Federal-American Partners mill & lab, Moab, Ogle Petroleum & Uranium re amends to Reg Guide 4 14 w/o photos
VANDELL, T D Uranium Recovery Licensing Branch 80/10/28 7pp
07000 089

DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MINING)

801180873 Informs of intention to add seventh stage to leaching circuit increasing retention time of slurry
ANDRUS, N J Federal American Partners 80/10/02 1p 06991 362

8011060069 Requests amend to Condition 30 of Amend 9 to source matl license, allowing water level in Pond 2 to raise to design elevation of 6,503 ft Dames & Moore rept re operating procedure of present tailings disposal sys encl
ANDRUS, N J Federal American Partners 80/10/14 5pp 06916 184

8010290379 Forwards responses to hydrologic questions from 800829 submittal, in response to NRC 801006 ltr Study re items requiring addl field work dealing w/solar evaporation pond is near completion Monitor well photographs encl
ANDRUS, N J Federal American Partners 80/10/17 10pp 06841 005.

--8010290381 "Area Water Well Locations"
Federal American Partners 77/08/18 1p 06841 010

801190245 Trip repts of 800922-29 visits to AZ Public Svc Co, Kerr McQue in situ leach site, Teton, East Gas Hills, Federal-American Partners mill & lab, Moab, Ogle Petroleum & Uranium re amends to Reg Guide 4 14 w/o photos
VANDELL, T D Uranium Recovery Licensing Branch 80/10/28 7pp
07000 089

8011210707 Advises that 801014 request to amend License BUA-667 to raise water in Pond 2 to level in accordance w/Dames & Moore 801008 rept requires minor safety & environ amend fee Payment should refer to Control Number 17676
WEISS, D. License Fee Management Branch 80/11/11 1p 07029 141

DOCKET 40-6586 VIRGINIA POLYTECHNIC INSTITUTE

8011030699 IE Insp Findings & Licensee Act dtd 800812 of License EUB-0750 Insp findings no noncompliance noted
PEERY, W W Region 2, Atlanta, Office of the Director. 80/08/12
1p 06860 120

DOCKET 40-7869 PLATEAU RESOURCES, LTD

8011030309 Requests onsite visit by R Person prior to developing decommissioning conditions
HEAD, W J. Plateau Resources, Ltd 80/10/10 2pp. 06861 204.

DOCKETED ITEMS

5

DOCKET 40-8011 AIR FORCE, DEPT OF

8011030696 IE Insp Findings & Licensee Ack dtd 800711 of Licensee
BUB-0792 Insp findings no noncompliance noted
WODDRUFF, R L Region 2, Atlanta, Office of the Director 80/07/11
1p 06860 119

DOCKET 40-8027 KERR-MCQUEE CORP

8011190025 Informs of plans to install raffinate sludge asphalt
solidification pilot plant to allow effective evaluation
of waste encapsulation method Forwards rept on vol reduction
& solidification sys Title page encl
SHELLEY, H T Kerr-McQuee Nuclear Corp 80/10/14 3pp 06996 277

--8011190035 Forwards NRC evaluation of Nov 1976 rept, "Radwaste Vol
Reduction & Solidification Sys " Rept considered acceptable
for ref in licensing applications Facility installing sys
would be subj to fire protection review
KNIEL, K Light Water Reactors Branch 2 78/04/14 7pp
06996 280

DOCKET 40-8064 EXXON MINERALS CO USA, EXXON CORP

8011190328 Informs that aquifer restoration of original Highland
solution mine wellfield has progressed satisfactorily Six
original production wells have been returned to water
quality consistent w/restoration target values
TRUBBELL, H H Exxon Minerals Co, USA 80/10/21, 1p. 06996 250.

DOCKET 40-8084 LISBON MINE, RIO ALGOM CORP

8011050178 Forwards corrected rept, "Review of Proposed 5-Ft Dam Raise,
Upper Tailings Pond Embankment Sys, Lisbon Valley Operations,
Rio Algom Corp " Rept sent on 801001 should be destroyed
NELSON, J D Colorado State Univ 80/10/03 1p 06896 349

--8011050184 Corrected rept, "Review of Proposed 5-Ft Dam Raise, Upper
Tailings Pond Embankment Sys, Lisbon Valley Operations, Rio
Algom Corp "
NELSON, J D, ABT, B R Colorado State Univ 80/10/01, 25pp.
06896 346

8011170245 Requests addl info re proposed 5-ft dam raise for upper
tailings pond embankment sys Response should be submitted as
soon as possible Requirements must be fully satisfied before
final determination can be made.
SCARANO, R A Uranium Recovery Licensing Branch 80/10/08 3pp.
06976 276

8011120030 Forwards responses to notice of violation cited in NRC
801008 ltr Corrective actions currently attempting to employ
radiation safety officer Adtl technician has been trained
to back up personal air sampling program. Memo encl
LAUJON, M D Rio Algom, Ltd 80/10/28 16pp. 06983 222

DOCKET 40-8304 WYOMING MINERAL CORP

801110188 Notifies of 780927 fire at facility which had no effect on
structural integrity of tank Part of emergency equipment
damaged No measurable U release occurred Radioactive matl
release minimal Investigation started
SCHENDEL, K R Wyoming Mineral Corp, 78/09/28 3pp 06944 013.

8010020739 Submits corporate info applicable to encl list of licensees.
Forwards Annual Financial Rept 1979
DIPIAZZA, R P Westinghouse Electric Corp 80/09/04, 5pp
03616 198

--8010020745 Annual Financial Rept 1979
* Westinghouse Electric Corp 80/01/30, 51pp 03616 203.

DOCKET 40-8323 NAVY, DEPT OF

8011070555 IE Insp Findings & Licensee Ack dtd 800917 of Licensee
BUB-1209 Insp findings no items of noncompliance found.
RIEDLINGER, B A Region 5, San Francisco, Office of the Director
80/09/17 1p. 06925 188.

DOCKET 40-8364 INDIANA UNIV INDIANAPOLIS

8011070545 Responds to FOIA request for all records re License
13-02752-03 Forwards documents listed in App A Document B
partially withheld name of individual exposed to radiation
(ref FOIA Exemption b)
FELTON, J H Division of Rules and Records 80/10/31 3pp
06925 054

--8011070561 Matl/Bqproduct License 13-02752-03 for IN Univ is amended
per 780925 application Amend 48 adds Subitems 6 O, 7 O, 8 O &
9 O authorizing 0 160 kg U in cadmium plated metal for use
as shielding in medical linear accelerator
COOPER, J W Licensing Management Branch 79/11/21 1p

--8011070590 Discusses IE Insp of Licensees 13-02752-03 & 13-02752-03 &
BUC-1217 on 800620-22 & forwards notice of violation
ALLAN, J H Region 3, Chicago, Office of the Director 77/07/26
2pp

--8011070579 IE Insp Repts 30-09792/77-01 & 40-8364/77-01 on 770620-22
Noncompliance noted no records of tests available on
electrical interlocks on entrance doors to Picker
teletherapy room prior to 760930
DICEY, B B Region 3, Chicago, Office of the Director 77/07/14
14pp

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO

801110825 Forwards results of 801007 sampling of Pattern III monitor
wells
NEUMANN, H R Rocky Mountain Energy Co 80/10/14, 5pp 06948 029

DOCKET 40-8412 NAVY, DEPT OF, NAVAL NUCLEAR POWER UNIT

8011140674 Ack receipt of 800903 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 40-8412/80-01.
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch, 80/09/19 1p. 06968 136

--8011140677 IE Insp Rept 40-8412/80-01 on 800826 Noncompliance noted
license expiration.
ROWE, C A Region 1, Philadelphia, Office of the Director
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch, 80/09/16 2pp 06968 157

--8011140682 Forwards application for renewal of Source Matl License
BUC-1239 W/o encl
PEACOCK, D O Navy, Dept of, 80/09/03, 1p. 06968 159

--8011140686 Supports application for renewal of Source Matl License
BUC-1239.
OROVES, K L Navy, Dept of, Naval Nuclear Power Unit, 80/03/27,
1p 06968 160

--8011140688 Forwards application for renewal of Source Matl License
BUC-1239.
BALLANCE, N B Navy, Dept of, 80/03/10, 1p 06968 161.

--8011140693 Application for renewal of Source Matl License BUC-1239,
authorizing WB Barbour & JC Wilbourne to use 2/or supervise
use of 100 lbs depleted U for 4 MEV Varian Associates linear
accelerator.
WILBOURNE, J C Navy, Dept of 80/03/10 9pp. 06968 162

DOCKET 40-8492 BEAR CREEK URANIUM CO

8011100418 Requests written approval of NRC 800926 agreement to abandon
plans for modifying tailings area runoff diversion sys by
rerouting culvert around key trench turning point Basin
capacity design is fail-safe in event of max flooding.
MEDLOCK, R L Bear Creek Uranium Co, 80/10/09 2pp. 06928 006

8011070149 Summary of 800826 meeting w/Bear Creek U Co in Silver
Spring, MO re proposed below grade tailings disposal plan
GARCIA, P J Uranium Recovery Licensing Branch 80/10/17, 5pp.
06911 001

DOCKETED ITEMS

DOCKET 40-8502 IRIGARAY MINE, WYOMING MINING CORP

8011070293 Forwards mine permit & license received from WY Dept of Environ Quality & final data package provided to WY Dept of Environ Quality for review of mine permit application
SCHEDEL, K.R Wyoming Mineral Corp 78/09/03 67pp 06919 202

8011170293 Forwards biweekly notification of excursion status of Shallow Monitor Wells 98M-1, 98M-6 & 98M-7
WICHERS, D.L Wyoming Mineral Corp 79/08/15 5pp 06978 299.

8011190264 Summarizes status of major excursion trends at site Requests data to perform adequate evaluation of excursion which seems to be centered about RS-25 & RS-23, within eastern portion of D-field.
PETERSON, R. Wyoming, State of 79/08/20 3pp 07000 099

8011190330 Supplia 790805 memo re 790329 vertical excursion discussed at 790817 meeting w/Dept of Environ Quality in Cheyenne, WY
HULBURT, H Wyoming Mineral Corp 79/08/20 2pp 07001 176

8011170292 Notifies that excursion status of Shallow Monitor Wells 98M-1 & 98M-7 ended on 790823 & 790821 respectively
Pertinent assay results from sample analyses encl
WICHERS, D.L Wyoming Mineral Corp 79/08/23 3pp 06978 296

8011190336 Informs that all addl monitor wells drilled & completed in shallow monitor zone have been considered as part of shallow monitor sys since 790622 meeting in Sheridan, WY Chloride should be only excursion parameter for wells
MORROW, D Wyoming, State of 79/08/27 1p 06996 249

8011170315 Discusses initial review of 0 Field baseline water quality & hydrology info & analysis Provides list of addl info needed for thorough review of pump test data
HULBURT, M Wyoming Mineral Corp 79/08/31 1p 06976 271

8011170329 Provides listing of subsj for discussion at 790905 meeting between WY minerals Permit 478 & WY Dept of Environ Quality, Land Quality Div
PETERSON, R Wyoming, State of 79/08/31 2pp 06975 357

8011170131 Requests addl info re pump test data for proposed Well Field Q.
MORROW, D Wyoming, State of 79/09/27 1p 06981:359

8011170319 Forwards results of chemical analysis of sampled wells SM1, SM6, 7, 8, RS13, 19, 21, 22, 23, 24, 25, 31 & 32 Discusses sampling procedures
PUTMAN, F. Wyoming Mineral Corp 79/09/28 2pp 06975 361

8011190340 Forwards Dept of Environ Quality set of full-length baseline electric logs for listed wells, in response to 790823 ltr request Gamma section has been cut off logs W/Y encl
WICHERS, D.L Wyoming Mineral Corp 79/09/28 1p 06996 248

8011190345 Responds to NRC 790824 ltr to WC Ackerman & to D Hichers 790928 submittal of eight electric logs WY Dept of Environ Quality will allow blocking-out of gamma log within production zone only for eight logs placed in public files
MORROW, D Wyoming, State of. 79/10/04 06996 247

801120641 Approves 791020 request to discontinue quarterly reporting Option retained for future quarterly reporting WY Mineral Corp 791020 & 29 ltrs encl
MORROW, D. Wyoming, State of 79/10/31 25pp 06953 056

801120635 Forwards weekly water quality analysis results from shallow monitor & research well samples taken on 791030 & 1102 Daily analytical values from SM-12 encl
WICHERS, D.L Wyoming Mineral Corp 79/11/07 5pp 06953 040

801120643 Forwards baseline variation analysis for Unit 5 Shallow Monitor Wells SM-14 & SM-17, in response to 791015 request
WICHERS, D.L Wyoming Mineral Corp 79/11/09 4pp 06952 358

801120649 Submits annual insp rept of in situ U leach project Fill upon which new plant addition was constructed has intruded into adjacent draw & is partially blocking drainage.
PUTMAN, F., MOONEY, O Wyoming, State of 79/11/15. 12pp 06953:010

8011190308 Discusses review of leakage & travel time calculations submitted as stipulation to 0 Field approval
HULBURT, M. Wyoming Mineral Corp 79/11/15 2pp 06976:274

801120638 Forwards results of weekly water quality analyses for shallow monitor & research wells from samples taken on 791006, 09, 12 & 16 SM-12 daily analytical values, arsenic & selenium analytical results & piezometric contour maps encl
WICHERS, D.L Wyoming Mineral Corp 79/11/16. 11pp 06953 045

8011170325 Discusses 791207 meeting re 0 Field leakage calculations & permit requirements for Units 6 & 7 Leakage rept will be rewritten & submitted to WY Dept of Environ Quality, Land Quality Div Lists info for inclusion in revised rept
HULBURT, H Wyoming Mineral Corp 79/12/07 2pp 06975 359

8011110131 Advises that twice per wk sampling schedule approved per 791210 request
MORROW, D Wyoming, State of 79/12/20 1p 06943 325

8011110125 Act receipt of NRC 791119 ltr re proposed amend to increase recovery plant flow rate capacity Amend requires application for permit revision due to significant change in mining operation
MORROW, D Wyoming, State of 79/12/28 1p 06943 324

8010230193 Submits status rept re shallow monitor zone Weekly water quality analysis results, piezometric contour maps, biweekly monitoring data from wells, arsenic & selenium analysis results & eight oversized, unnumbered drawings encl
WICHERS, D.L Wyoming Mineral Corp 80/09/29 61pp 06794 327

8011030378 Advises that reduction in number of wells being sampled is premature, per review of shallow monitor zone data through 800915 Frequency may be reduced to biweekly except for wells SM-4, SM-12 & RS-19 which should remain on weekly schedule
HULBURT, H Wyoming Mineral Corp 80/09/30 1p 01754 001

8011030336 Informs of shallow monitoring zone data review through 800915, indicating shallow zone has not recharged after shutdown of cleanup program Most well chemical levels not stabilized Several wells to continue weekly sampling
MOONEY, O Wyoming, State of 80/10/09 1p 06867 279

801110646 Forwards "Quarterly Rept for First, Second & Third Quarters Jul 1979-Mar 1980 "
WICHERS, D.L Wyoming Mineral Corp 80/10/16 1p 06948 034

--801110650 "Quarterly Rept for First, Second & Third Quarters, Jul 1979-Mar 1980 "
* Wyoming Mineral Corp 80/10/16 200pp 06948 035

8011170740 Submits info re status of Shallow Monitor Wells 98M-4 & RS-19 Well 98M-4 remains in excursion status Well RS-19 was incorrectly reported in excursion status, but 801013-14 samples indicate that well remains on normal status
WICHERS, D.L Wyoming Mineral Corp 80/10/16 2pp 06973 361

DOCKET 40-8511 COTTER CORP

8011170093 Confirms 801017 discussion re NRC review of CD Bureau of Investigation 800905 rept & CD Dept of Health actions on Cotter license Recommends revisions to administrative policies & civil penalty authority W/related documents
KERR, O.W Office of State Programs, Director 80/10/27 15pp 06915 001

DOCKET 40-8549 T N NUCLEAR SPECIALTIES

8011100089 Forwards 1E Insp Repts 40-8549/80-01 & 40-8579/80-01 on 800727-0801 No noncompliance noted
STOHR, J.P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 2pp 06929 350

--8011100098 1E Insp Repts 40-8549/80-01 & 40-8579/80-01 on 800727-0801 No noncompliance noted Major areas inspected licensee shipper compliance w/DOT & NRC re shipping paper, DOT placarding & radiation level requirements
MACARTHUR, T.C., POTTER, J.P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/16 8pp 06929 352

DOCKET 40-8579 TNS

8011100089 Forwards 1E Insp Repts 40-8549/80-01 & 40-8579/80-01 on 800727-0801 No noncompliance noted
STOHR, J.P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 2pp 06929 350

DOCKETED ITEMS

7

--801100098 IE Insp Repts 40-8549/80-01 & 40-8579/80-01 on 800727-0801 No noncompliance noted Major areas inspected licensee shipper compliance w/DOT & NRC re shipping paper, DOT placarding & radiation level requirements
MACARTHUR, T C , POTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/16 8pp 06929 352

DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO

8011240010 Confirms 801024 telcon re fire at const site Cause of fire is not known No leakage of source matl or damage to tanks found Formal rept will be transmitted following completion of investigation
MARSHALL, J A Minerals Exploration Co (subs of Union Oil Co of California) 80/10/24 1p 07039 253

DOCKET 40-8585 WYOMING MINERAL CORP

8011120047 Forwards License SUA-1315 in response to NMSS Questionnaire 80-1 re unsailed radioactive matls received, processed, handled, used or disposed of in 1979 Total activity estimated from total 1979 plant production W/o encl
BERG, R E Wyoming Mineral Corp 80/11/05 3pp 06932 033

DOCKET 40-8602 UNITED NUCLEAR CORP

8011120031 Forwards trip rept re 800624 site visit to Morton Ranch near Glen Rock, WY to view main embankment & impoundment area
Dames & Moore 800709 rept re suitability of drainage zone matl for proposed embankment encl
ABT, S R Colorado State Univ 80/08/07, 15pp 06951 109

8011101079 Advises of appointment of CE Wolff as project manager effective 801001.
WOLFF, C E United Nuclear Corp 80/10/15 1p 06943 348

8011180537 Forwards Dames & Moore 800930 "Rept of Insp & Testing of Compacted Fill, Proposed Evaporation Pond Embankment, Morton Ranch Project, Near Casper, WY for United Nuclear Corp Mining & Milling Svcs, Inc."
WOLFF, C E United Nuclear Corp 80/11/11 1p 06988 173

--8011180540 "Rept of Insp & Testing of Compacted Fill, Proposed Evaporation Pond Embankment, Morton Ranch Project Near Casper, WY, for United Nuclear Corp Mining & Milling Svcs, Inc."
* Dames & Moore 80/09/30 28pp 06988 174

--8011180543 "Rept on Suitability of Drainage Zone Matl Proposed Evaporation Pond Embankment, Morton Ranch Project Near Casper, WY, for United Nuclear Corp Mining & Milling Svcs, Inc."
* Dames & Moore 80/07/09 41pp 06988 202

DOCKET 40-8676 ENERGY FUELS NUCLEAR, INC

8011250150 Advises that Source Matl License SUA-1324 is terminated since NRC review & issuance of Source Matl license SUA-1358 included info on both facilities Separate license for ore buying station no longer necessary
SCARANO, R A Uranium Recovery Licensing Branch 80/09/26 1p, 07036, 150

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC

8011170352 Submits contract costs incurred & manhours used in reviewing 800908 application
OILLEN, D M ; LINEHAN, J Uranium Recovery Licensing Branch 80/10/07, 1p 06977 331

8011040250 Forwards rept, "Cultural Resource Investigations Haulway from EFN Mill Site to Plateau Resources Stockpile, San Juan County, UT," submitted for approval by archeological contractor
BAKER, G E Energy Fuels Nuclear, Inc 80/10/09 1p 06873 354

--8011040253 "Cultural Resource Investigations Haulway from EFN Mill Site Plateau Resources Stockpile, San Juan County, UT."
ADENBROOD, L D Plano Archaeological Consultants 80/10/09 17pp 06873 355.

8011180878 Notifies of fee requirement for 801017 application to amend License SUA-1358
WEISS, D License Fee Management Branch 80/11/05, 1p 06991 345

DOCKET 40-8692 COTTER CORP

8011060088 Advises that part of fee remitted for review & approval of Amend 1 issued on 800731 will be refunded by Ofc of Controller
MILLER, W D License Fee Management Branch 80/10/22 1p 02319 196

8011170093 Confirms 801017 discussion re NRC review of CO Bureau of Investigation 800903 rept & CO Dept of Health actions on Cotter license Recommends revisions to administrative policies & civil penalty authority W/related documents
KERR, G W Office of State Programs, Director 80/10/29 15pp 06915 001

DOCKET 40-8693 OOLE PETROLEUM, INC

8011190245 Trip repts of 800922-29 visits to AZ Public Svc Co, Kerr McOse in situ leach site, Teton-East Gas Hills, Federal-American Partners mill & lab, Moab, Ogla Petroleum & Uranium re amends to Reg Guide 4 14 W/o photos
VANDELL, T D Uranium Recovery Licensing Branch 80/10/28 7pp

DOCKET 40-8696 THIOKOL CORP

8011030682 IE Insp Findings & Licensee Ack dtd 800903 of License SUB-1334 Insp findings no noncompliance noted
WOODRUFF, R L Region 2, Atlanta, Office of the Director 80/09/03 1p, 06860 101

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO

8011050170 Forwards description of well integrity test & results re Pattern 2 injection wells to WY Dept of Environ Quality Confirms that authorization was received to begin injection in Pattern 2
NEUMANN, M R Rocky Mountain Energy Co 80/10/03 2pp 06896 334.

DOCKET 40-8698 PLATEAU RESOURCES, LTD

8011180480 Notifies that as of 801001, there are no significant differences in land use from those described in environ rept & supply
SCOTT, A D Plateau Resources, Ltd 80/10/24 1p, 06991 231

DOCKET 40-8702 ARMY, DEPT OF, ARMAMENT MAT READINESS COMMAND

8011210265 Forwards IE Insp Rept 40-8702/80-02 on 800814 No noncompliance noted
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/01 2pp 07030 125

--8011210275 IE Insp Rept 40-8702/80-02 on 800814 No noncompliance noted. Major areas inspected review of decontamination plans & schedules & independent measurements of bldg radiation levels
DAVIS, J B , RONE, C Region 1, Philadelphia, Office of the Director, KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/30 2pp 07030, 127

8011210689 Forwards IE Insp Rept 40-8702/80-03 on 800918 & 1002 No noncompliance noted
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/22 2pp 07029 299

--8011210699 IE Insp Rept 40-8702/80-03 on 800918 & 1002 No noncompliance noted. Major areas inspected review of decontamination plans & schedules & independent bldg surveys for radiation levels
DAVIS, J B , O'NEILL, B , RONE, C Region 1, Philadelphia, Office of the Director 80/10/22 2pp 07029 301.

DOCKET 40-8711 NAVY, DEPT OF

8011030689 IE Insp Findings & Licensee Ack dtd 800903 of License SMB-1345, Insp findings no noncompliance noted
BROWN, R A Region 2, Atlanta, Office of the Director 80/09/03, 1p, 06860 102

DOCKET 40-8714 CLEVELAND CLIFFS IRON CO

8011200197 Forwards 801024 request to WY Water Quality Div to increase max quantity of U & radium discharged to pilot process field.
LAHAN, J T Cleveland-Cliffs Iron Co 80/10/24 14pp 07021 249

DOCKET 40-8727 KERR-MCGEE NUCLEAR CORP

8010290375 Forwards discussion of evaporation pond contingency plan for SPRB U extraction/IX program Forwards drawing ATW-05-C-01 of pond design showing two cells, separating dam & leak detection sys
SHELLEY, W J Kerr-McGee Nuclear Corp 80/10/15 2pp 06841 003

--8010290377 "Bill Smith Mine - SPRB Evaporation Ponds, IX Pilot Plant "
Kerr-McGee Nuclear Corp 80/10/15. 1c/.

DOCKET 40-8728 TETON EXPLORATION DRILLING CO , INC

8011030372 Provides third quarterly rept re pilot in situ U mining operation in Powder River Basin area of WY Rept covers period from Jul-Sept 1980 Info indicates no leach solution excursions
RIEGER, S N , HERLIHY, D M Teton Exploration Drilling Co , Inc 80/10/09 4pp 06867-300

8011190245 Trip repts of 800922-29 visits to AZ Public Svc Co, Kerr McGee in situ leach site, Teton, East Oas Hills, Federal- American Partners mill & lab, Moab, Ogle Petroleum & Uranium re amends to Reg Guide 4 14 W/o photos
VAIDELL, T D Uranium Recovery Licensing Branch. 80/10/28 7pp

DOCKET 40-8743 CONOCO

801100240 Forwards transmittal ltrs which accompanied distribution of environ rept & supplementary distribution list Requests response to any problems w/ltrs distributed under old letterhead.
GUIOLEY, T W CONOCO, Inc (Continental Oil Co). 80/09/16 4pp 06931 123

8011030582 Advises that project does not affect any units of Natl Park Svc, per review of environ rept Urges NRC to continue close supervision of total operation, especially effects on air & water quality & proposed mitigating measures.
STRAIT, R A Interior, Dept. of, National Park Service 80/09/30 1p 01756. 001

8011030589 Advises that U mill should have no direct effect on Water & Power Resources Svc projects, in response to NRC request for review of environ rept Confusion as to location of project area should be resolved when EIS is drafted
RAHLINOS, J Interior, Dept of. 80/10/01 1p. 01756 001

8011030564 Advises that air quality application submitted to Air Quality Div of WY Dept of Environ Quality re project was also furnished to NRC in encl 800813 ltr
GUIOLEY, T W CONOCO, Inc (Continental Oil Co) 80/10/02 1p 01756 001

--8011030571 Forwards matls submitted to Air Quality Div of WY Dept of Environ Quality re project, in response to NRC 800812 telcon Matls should be helpful in evaluating radiological modeling aspects
GUIOLEY, T W CONOCO, Inc (Continental Oil Co) 80/08/13 1p 01756. 001.

8011030074 Forwards NE Fowler, Natrona County Commissioner, WY, 801001 ltr re scoping meeting on facility environ rept Correspondence re project will be continued
GUIOLEY, T W CONOCO, Inc (Continental Oil Co) 80/10/06 2pp 06937:119

8011000012 Forwards Advisory Council on Historic Preservation 801002 ltr advising that addl info re cultural resources should be included in environ rept Archaeological rept & clearance ltr from WY Recreation Commission was forwarded to council.
GUIOLEY, T W CONOCO, Inc (Continental Oil Co) 80/10/07 4pp 06928. 238.

8011040114 Forwards environ rept on facility, in response to state planning coordinator request W/o encl
GUIOLEY, T W CONOCO, Inc (Continental Oil Co). 80/10/08 1p 06974:072

8011030173 Forwards organizational chart giving names & positions of personnel involved in project Provides brief descriptions of personnel to be present at 801016 meeting
GUIOLEY, T W CONOCO, Inc (Continental Oil Co) 80/10/10 4pp 06976 336

8011060302 Responds to 800926 request for copy of vendor project application Application available for insp & copying at PDR
HAMILL, K J Uranium Recovery Licensing Branch 80/10/10 1p 06911 291

--8011060306 Requests copy of vendor application for source matl license
HUSS, J Powder River Basin Resource Council 80/09/26 1p 06911 292

801110160 Expresses gratitude for opening Casper meeting to public participation Disagrees w/J Huss comments supporting "no change - no growth" policy for WY & USA
SCHMILL, H Affiliation Unknown 80/10/17 1p 06943 341

8011200140 Offers comments to make EIS more complete & accurate re wildlife resources Applicant should not make value judgments re importance of wildlife species
DEXTER, W D Wyoming, State of 80/10/20 2pp 07021 064

8011170921 Requests transcript & attendance list from 801016 scoping meeting in Casper, WY re project
HUSS, J Wyoming, State of 80/10/22 1p 06971 007

8011210197 Requests application & environ rept for source matl license for const & operation of project
BEERS, R Beers, R 80/10/22 1p 07032 322

8011190179 Informs that Intermountain Field Operations personnel reviewed environ rept Suggests subsequent documents dealing w/environ impacts of project discuss oil & gas well drilling policy in mine & mill area No objection to rept as written
EMITH, J B Interior, Dept of, Bureau of Mines 80/10/23 1p 06996 261

8011170895 Responds to 800910 request for project environ rept & relevant info All publicly available documents may be inspected & copied at PDR DES not scheduled for release until early 1981
HAMILL, K J Uranium Recovery Licensing Branch 80/10/24 1p 06981 227

--8011170898 Requests applicant EIS, NRC DES & any relevant info re project
HAUO, F W Ecological Analysts, Inc 80/09/10 1p 06981 228

8011190217 Informs that review of environ rept & notice of intent to prepare environ statement has been completed Consequences of major floods should be discussed Discussion of results & evaluation of applicable method to site area is necessary
MEHARD, H W Interior, Dept of, Geological Survey 80/10/24 1p 06996 260

DOCKET 40-8745 OGLE PETROLEUM

8011070239 Requests source matl license authorizing commencement of drilling of injection & recovery wells in Unit 1 Expresses understanding that no injection of lixiviant may take place prior to approval of source matl license
CATCHPOLE, G J Ogle Petroleum, Inc 80/10/08 2pp 06925 024

8010220304 Info suppl to environ rept, "Evaporation Ponds " Two oversized maps encl
CATCHPOLE, G J Ogle Petroleum, Inc 80/10/13 22pp 06795 019

8011101140 Submits info re industrial water well in response to request for addl info re application for commercial source matl license
CATCHPOLE, G J, Ogle Petroleum, Inc 80/10/13 3pp 06949:336

8011101149 Forwards monitor well location map re change in identification number for second lower aquifer.
CATCHPOLE, G J Ogle Petroleum, Inc 80/10/13 2pp 06943 339.

8011190001 Forwards response to 791123 request for biological assessment re proposed in situ mining of U Neither bald eagle nor black-footed ferret is present in vicinity
MILLER, H J Uranium Fuel Licensing Branch 80/10/23 4pp 06978.358

DOCKETED ITEMS

9

801180784 Safety evaluation approving exemption from 10CFR40 32(e) for purpose of drilling & completing wells in Mining Unit 1
MARTIN, D E , MILLER, H J Uranium Recovery Licensing Branch
80/10/30 5pp 06989 142

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl.
EISENHUT, D O Division of Licensing 80/10/06 6pp 06940 347

DOCKET 40-8781 TETON EXPLORATION DRILLING CO

8011030658 Forwards application for source matl license for commercial scale in situ U extraction operation on Leuenberger Ranch property, Converse County, WY Fee encl
APPEL, R R Teton Exploration Drilling Co , Inc 80/10/14 1p 06865 221

--8011030666 Application for source matl license for commercial scale in situ U solution extraction operation on Leuenberger Ranch property in Converse County, WY Oversize drawings encl
* Teton Exploration Drilling Co , Inc 80/10/14 300pp 06865 222

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

P Operating license stage documents & correspondence

801180291 Memo to all nonpower reactor licensees advising that NRC has upgraded emergency preparedness regulations to ensure adequate protective measures will be taken in radiological emergency. W/o encl 800819 FR notice
TEDEBEC, R L Assistant Director for Licensing 80/11/06 3pp, 06989 147

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F Security, medical, emergency & fire protection plans

801180317 Forwards facility emergency planning info for placement in LPDR W/o encl
BOUDER, J L Division of Rules and Records. 80/11/04 1p 06991 158

8011280097 Ack receipt of 800307 ltr forwarding change in security plan. Change acceptable. Changes withheld (ref 10CFR2 790)
VARQA, S A Operating Reactors Branch 1 80/11/17 2pp 07081 333

H General correspondence

8011060193 Responses to encl 800823 ltr to President Carter requesting facilities be shutdown because of threat to life. Two reactors may continue to operate until completion of hearing process to re-examine safety considerations
INGRAM, F Office of Public Affairs 80/10/20 2pp 02319 196

8011040408 Requests FI Bialik name be added to wvc lists for all matters re facilities, BNL & transport of nuclear matls in NY
BIALIK, E I New York, State of 80/10/31 1p 02319 196

801190498 Petitions for denial of Con Ed & PASNY petition to resume operations pending full investigation of safety issues to be adjudicated at forthcoming hearings
SCHEIDER, D , MOTYCKA, M , BERNARD, T J Affiliation Unknown 80/11/18 4pp 07001 289

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of THF action plan requirements. Provides summary listing of all approved THF-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 207pp 02319 196

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp 06940 358

8011050205 Forwards table giving calculated peak values & associated probabilities & weather conditions for several risk measures at facilities. Values should be viewed as representative of general shape of curve
MURLEY, T E Office of Nuclear Regulatory Research, Director. 80/10/03 3pp 06896 279

G Inspection reports, IE Bulletins & correspondence

8011070072 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/09/30 1p 06920 041

8011060652 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/10/24 1p 06909 345

8011070343 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/10/24 1p 06925 064

801140066 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators " No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/10/31 1p 06968 247

801140605 Forwards IE Info Notice 80-39, "Malfunction of Bolenoid Valves Mfg by Valcor Engineering Corp." No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/10/31 1p 06963 243

R Periodic operating reports & related correspondence

8011060080 Partial response to FOIA request for info re radiation levels of plant environs & dump sites & radiation levels in nine listed places. Forwards documents listed in App A. Search is continuing for documents re second part of request.
FELTON, J H Division of Rules and Records 80/10/29 2pp 06914 355

--8011060122 Excerpts from environ monitoring annual repts. Includes Indian Point rept for 1978 & ME Yankee & JA Fitzpatrick Repts for 1979.
* Consolidated Edison Co. of New York * Maine Yankee Atomic Power Co * Power Authority of the State of New York. 80/10/29 13pp

8011170521 Forwards data specified in Section 401 certification for Oct 1980
MONTI, W A Consolidated Edison Co of New York. 80/11/10 18pp 06968 277

801180683 Forwards tabulation of daily record of fish collections for Oct 1980.
ZARAKAS, P Consolidated Edison Co of New York 80/11/14 1p 06991 267

--801180690 Tabulation of daily record of fish collections for Oct 1980.
* Consolidated Edison Co. of New York. 80/11/14 4pp. 06991 268

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

801180241 Forwards revised Page 24 of security plan Page withheld (ref 10CFR2 790)
CUNNINGHAM, R O Pennsylvania State Univ. 80/11/13 1p 06985 249

P Operating license stage documents & correspondence

8011030478 Application to amend License R-2, requesting exemption from 10CFR70.24 requirements of monitoring sys. due to remote possibility that flooding of fuel elements w/water in any configuration will not permit attaining criticality.
CUNNINGHAM, R O Pennsylvania State Univ. 80/10/14 3pp 06872 262

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

801170336 Forwards comments on revised emergency plan per requirements of NUREG-0654 Plan should be revised to address comments
EISENHUT, D O Division of Licensing 80/10/02 5pp. 06976 264

801190191 Informs of DOJ decision not to prosecute guard contractor for improprieties re firearms qualification & documentation of patrols Decision based on prompt identification, notification & resolution of matter H-related ltrs
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28 6pp 06999 228

8011050428 Forwards draft public info package re emergency preparedness for facilities Package has been distributed to States of IL, IA & WI for comment Requests NRC comment by 801121
DELOERD, E L O Commonwealth Edison Co 80/11/03 8pp. 06994 107

G Adjudicatory correspondence

8011040515 Withdraws 801014 request for hearing & petition
STEPH, P P Isham, Lincoln & Beale 80/10/28 1p 06873 135

H General correspondence

801180075 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06984 200

801180086 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 322

801180111 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 329

801180115 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 331

801180120 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 332

801180124 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 334

801180127 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 335

801180132 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 337

801180134 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 06987 336

801180137 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 338

801180141 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 339

801180143 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 340

801180146 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 341

801180175 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 295

801180187 Discusses water samples collected by NRC around facilities & analyzed by ANL No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 296

8011250937 Expresses concern re environ statement re proposed decontamination of facility Deficiencies should be removed prior to approval of primary coolant sys decontamination Util reserve capacity makes facility unnecessary
FREY, D O Sassafras Audubon Society 80/11/17 4pp 07058 355

J Insurance & indemnity information

801180717 Forwards Endorsements 124 & 123 to NELIA Policy NF-43
OSTER, J Commonwealth Edison Co 80/11/12 5pp 06991 313

8011250332 Forwards Endorsements 104 & 105 to MAELU Policy MF-22
OSTER, J Commonwealth Edison Co 80/11/19 5pp 07055 134

D Advisory Committee on Reactor Safeguards reports & correspondence

801130110 Notice of ACRS Subcommittee on Dresden Nuclear Power Plant 801008 meeting in Washington, DC
HOYLE, J C Office of the Secretary of the Commission 80/09/16 3pp 06957 314

P Operating license stage documents & correspondence

7809290027 Notice of meeting on 780927 w/util owners group of the systematic evaluation prog to discuss prog
DAVIS, D K Systematic Evaluation Programs Branch (Pre 790629) 78/09/25 2pp

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition
GRIMES, C I Assistant Director for Engineers & Projects (Pre 790629) 79/03/02 2pp 03145 305

801180557 Discusses chemical cleaning of facility using NS-1 solvent Recommends rinsing procedure for decomposition of residual solvent NRC should concur w/procedure
WEEKS, J R Brookhaven National Laboratory 80/05/05 3pp. 06992 127

801100083 "Solidification & Leaching of Dow Vinyl Ester-Styrene Waste Forms Containing NS-1 Decontamination Waste Concentrate"
WEISS, A J, MILLAN, L, NICOLOSI, S L Brookhaven National Laboratory 80/05/19 2pp 06915 001

--801100087 Vol 2 & apps of "FES for Waste Mgt Operations, Hanford Reservation, Richland WA"
LIVERMAN, J. L. Energy Research & Development Admin (Presently DOE)
ERDA-1538 75/12/31 150pp 06915 001

--801100091 "Natural Radiation Exposure in US"
DAKLEY, D. T. Environmental Protection Agency QRP/SID 72-1
72/06/30 72pp 06915 001

801180512 Responds to NRC 800505 ltr re progressive corrosion in residual acid crevices Corrosion has been greatly reduced as result of NRC 800827 telcon outlining proposed cleaning & rinsing procedures
WEEKS, J. R. Brookhaven National Laboratory 80/09/03 2pp 06988 315

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D. G. Division of Licensing 80/09/05 209pp

8009290143 Notification of 800926 meeting w/utills & Kerr-McGee Chemical Corp in Bethesda, MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment
ALLISON, D. P. Systematic Evaluation Program Branch 80/09/08 3pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D. G. Division of Licensing 80/10/01 3pp

801190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance Info should be submitted within 25 days
EISENHUT, D. G. Division of Licensing 80/10/01 2pp 07000 087

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports" w/o encl
EISENHUT, D. G. Division of Licensing 80/10/04 4pp

801130192 Concurs w/BEP Topic III-10 A, "Thermal Overload Protection for Motor Operated Valves." Util is in compliance w/current criteria No ref has been found for licensing requirement re use of limit switch w/valve position signal
JANECEK, R. F. Commonwealth Edison Co 80/10/06 2pp 06939 222

801105049 Forwards survey status rept re loss of offsite power in connection w/BEP Topics VI-7 C 1, VII-6, VIII-1, VIII-2 & VIII-3 for review & comment Response due in 60 days.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/10/10 42pp 02319 196

8011200378 Forwards proposed FES re primary cooling sys chemical decontamination marked up to include branch comments & changes Branch concurs w/FES subj to incorporation of changes noted in copy
MARTIN, J. B. Division of Waste Management 80/10/14 1p 07018 288

801130216 Forwards FES, NUREG-0686, re chemical decontamination of facility. Also forwards FR notice of availability W/o encl
CRUTCHFIELD, D. Operating Reactors Branch 5 80/10/17 1p 06938 289

801140394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201
ABEL, J. B. Commonwealth Edison Co 80/10/31 1p 06874 174

801100389 Forwards Page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments.
TRAMM, T. R. Commonwealth Edison Co 80/11/05 2pp 06930 357

8011250346 Forwards suppl info to effluent & waste disposal radioactive effluents in response to R Beebe request Info suggests changes to data
SCOTT, D. J. Commonwealth Edison Co 80/11/18 12pp 02227 001

Q Inspection reports, IE Bulletins & correspondence

801190513 Forwards IE Insp Repts 50-010/80-14, 50-237/80-17 & 50-249/80-21 on 800803-0906 & notice of violation
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/08 2pp 06998 120.

--801190518 Notice of violation from insp on 800803-0906
* Region 3, Chicago, Office of the Director 80/09/29 1p 06998 122

--801190526 IE Insp Repts 50-010/80-14, 50-237/80-17 & 50-249/80-21 on 800803-0906 Noncompliance noted personnel failed to follow radiation protection procedures
BARKER, J. L., TONGUE, T. H., REIMANN, F. W. Region 3, Chicago, Office of the Director 80/09/29 7pp 06998 123

801110027 Forwards IE Insp Repts 50-010/80-15, 50-237/80-18 & 50-249/80-22 on 800905-17 No noncompliance noted
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/17 2pp 06943 232

--801110034 IE Insp Repts 50-010/80-15, 50-237/80-18 & 50-249/80-22 on 800905-17 No noncompliance noted Major areas inspected circumstances re allegations that radioactive water released to environ over period of one to two months
REIMANN, F. W., TONGUE, T., JANUSKA, A. Region 3, Chicago, Office of the Director 80/10/14 9pp 06943 254

8011060172 Confirms 801031 meeting w/RL Spessard in Chicago, IL to discuss regulatory performance
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/21 3pp 06915 327

8011070285 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/24 1p 06921 300

801190040 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc
Badge examples encl
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/28 3pp 06999 180

8011200009 Forwards IE Insp Rept 50-010/80-17 on 801008-10 No noncompliance noted
HIND, J. A. Region 3, Chicago, Safeguards Branch 80/11/03 2pp 07015 351

--8011200012 IE Insp Rept 50-010/80-17 on 801008-10 No noncompliance noted Major areas inspected facility organization & operation, storage & internal controls Details withheld (ref 10CFR2.790)
FINLEY, A. G., PATTERSON, J. P. Region 3, Chicago, Office of the Director HIND, J. A. Region 3, Chicago, Safeguards Branch 80/10/30 1p 07015 353

8011200537 Forwards IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-263/80-27, 50-295/80-21 & 50-304/80-23 on 801031 No noncompliance noted
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/06 2pp 07020 167

--8011200544 IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-263/80-27, 50-295/80-21 & 50-304/80-23 on 801031 No noncompliance noted Major areas discussed performance of activities
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/06 26pp 07020 167

8011250496 Forwards response to IE Bulletin 80-11, "Masonry Wall Design." Operability assessment performed on walls classified as safety-related but failed to meet acceptance criteria Safe shutdown capability not jeopardized
ABEL, J. S. Commonwealth Edison Co 80/11/06 23pp 07056 050

R Periodic operating reports & related correspondence

801180447 Forwards monthly operating repts for Oct 1980
SCOTT, D. J. Commonwealth Edison Co 80/11/12 1p 06989 208

--801180453 Monthly operating repts for Oct 1980.
CIESZKIEWICZ, S. Commonwealth Edison Co 80/11/01 15pp 06989 209

V Operator Examinations

801100481 Forwards response to NRC 800731 ltr transmitting interim criteria for shift staffing & requesting util schedule for compliance Vacancies may create situations requiring overtime in excess of NRC guidelines
JANECEK, R. F. Commonwealth Edison Co 80/11/05 5pp 06928 010.

DOCKETED ITEMS

801120492 Forwards response to NRC 800731 request for schedule per interim shift staffing requirements
JANECEK, R. F. Commonwealth Edison Co 80/11/05 5pp 06932 097

DOCKET 50-18 VALLECITOS BUILDING WATER REACTOR

P Operating license stage documents & correspondence

7812190001 Forwards Summary of a 771202 meeting re postulated Verona fault, 771209 NRC ltr to US Geological Survey requesting info on surface faulting Requests course of action planned to resolve surface faulting issue
SCHWENGER, A. Operating Reactors Branch 1 (Pre 790623). 77/12/14 2pp.

--7812190020 Forwards NRC order to show cause which requires that QETR be placed & maintained safely in cold shutdown condition pending further order
CASE, E. O. Office of Nuclear Reactor Regulation, Director 77/10/21 1p 94214 234

--7812190026 Show cause order requiring that, upon completion of present operating cycle on 771027, QETR should be placed & maintained safely in cold shutdown condition Comments for QETR 771202 meeting encl
CASE, E. O. Office of Nuclear Reactor Regulation, Director 77/10/24 13pp 94214 235

DOCKET 50-29 YANKEE-ROHE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

8011040079 Forwards safety evaluation re fire protection Fire protection plan acceptable w/exception of implementation date for Item 3.2.3 & proposed use of shift supervisor as fire brigade leader
LAINAS, G. C. Assistant Director for Safety Assessment 80/10/01 4pp 06916 157.

--8011040081 Suppl 1 to fire protection safety evaluation rept
* Office of Nuclear Reactor Regulation, Director 80/10/01 7pp. 06916 161

Q Adjudicatory correspondence

8011240051 Forwards order for mod of License DPR-3 re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl
CRUTCHFIELD, D. Operating Reactors Branch 5 80/10/24 3pp 07039 049

--8011240059 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D. G. Division of Licensing 80/10/24 6pp 07039 052

--8011240063 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 07039 058

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of THM action plan requirements. Provides summary listing of all approved THM-2 related requirements
EISENHUT, D. G. Division of Licensing 80/09/03 209pp.

8009290143 Notification of 800926 meeting w/utills & Kerr-McGee Chemical Corp in Bethesda, MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class 1E equipment
ALLISON, D. P. Systematic Evaluation Program Branch, 80/09/08 3pp.

8011200008 Forwards evaluation of SEP Topic VI-4 re electrical, instrumentation & control aspects of containment purge valve isolation override constituting input to integrated safety assessment.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/09/15 8pp 07015 343

1011200020 Forwards evaluation of SEP Topic VI-7 F re accumulator isolation valves power & control sys design Evaluation will constitute input to integrated safety assessment
CRUTCHFIELD, D. Operating Reactors Branch 5 80/09/15 8pp 07020 198

8011200064 Forwards evaluation of SEP Topic VIII-2, diesel generators. Evaluation will constitute basic input to integrated safety assessment
CRUTCHFIELD, D. Operating Reactors Branch 5 80/09/15 13pp 01741 019

8011200068 Forwards evaluation of SEP Topic VI-7 C 1, independence of redundant onsite power sys Evaluation will constitute basic input to integrated safety assessment
CRUTCHFIELD, D. Operating Reactors Branch 5, 80/09/15 8pp 07020 289

8011200266 Forwards evaluation of SEP Topic V-11 A, electrical, instrumentation & control feature for isolation of high & low pressure sys Evaluation will constitute basic input for facility safety assessment
CRUTCHFIELD, D. Operating Reactors Branch 5 80/09/15 9pp 01741 019.

8011210154 Forwards evaluation of SEP Topic III-10 A, thermal overload protection for motors of motor operated valves Evaluation will be basic input to safety assessment
CRUTCHFIELD, D. Operating Reactors Branch 5 80/09/15 4pp 07037 171

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D. G. Division of Licensing 80/10/01 5pp

8011210015 Submits addl topics to be deleted from facility SEP review. Topic removal results from either related generic NRC activities or nonapplicability of topics to certain facilities. PWR DBE topic list encl
CRUTCHFIELD, D. Operating Reactors Branch 5 80/10/01 5pp 02227 001

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" w/o encl
EISENHUT, D. G. Division of Licensing 80/10/06 4pp

8011030543 Application for Amend 59 to License DPR-3 consisting of changes to Tech Specs
VANDENBUROH, D. Yankee Atomic Electric Co 80/10/22 3pp 06855 250

--8011030549 Tech Spec 3/4 2 for power distribution limits, 3/4 3 for instrumentation, 3/4 4 for main coolant sys, 3/4 8 for electrical power sys, 3/4 8 2 for onsite power distribution sys & 3/4 9 for refueling operations
* Yankee Atomic Electric Co 80/10/22 12pp 06855 253

8011030999 Application for amend to License DPR-3, consisting of Proposed Change 172 to App A Tech Specs to comply w/NRC & util commitments to minimize personnel radiation exposure Amend fee encl
VANDENBUROH, D. Yankee Atomic Electric Co 80/10/22 3pp 06861 186

--8011030610 Proposed Change 172 to App A Tech Specs 4 4 for surveillance requirements & limiting conditions for operation of main coolant sys, to minimize personnel radiation exposure
* Yankee Atomic Electric Co 80/10/22 4pp 06861 189

8011240051 Forwards order for mod of License DPR-3 re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl
CRUTCHFIELD, D. Operating Reactors Branch 5 80/10/24 3pp 07039 049

--8011240059 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201.
EISENHUT, D. G. Division of Licensing 80/10/24 6pp 07039 052

--8011240063 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24, 2pp 07039 058.

8011030320 Forwards "Environ Qualification of Safety-Related Electrical Equipment - SEP Topic III-12"
VANDENBUROH, D. Yankee Atomic Electric Co 80/10/31 2pp 06877 009.

DOCKETED ITEMS

13

--8011050325 "Environ Qualification of Safety-Related Electrical Equipment - SEP Topic III-12"
* Yankee Atomic Electric Co YAEC-1227 80/10/31 200pp
95084 040

801190486 Ack receipt of 800520 application re clarification of term "operable" for facility Application is not exempt from fee requirements Class III fee requested
DIOGS, R M License Fee Management Branch 80/10/31 1p
06998 107

8011210003 Advises of delay in completion of SEP Topic XVI, Tech Specs, until completion of all SEP topic reviews & integrated safety assessment Delay will allow evaluation of current Tech Specs w/proposed changes resulting from reviews
CRUTCHFIELD, D Operating Reactors Branch 5 80/11/05 2pp
07033 187

8011200329 Forwards addl info on SEP Topics VI-7 B, VI-7 C, VI-10, VII-3, VIII-2 & VIII-3 re instrument inverters & vital buses, per NRC 800916 ltr
KAY, J A Yankee Atomic Electric Co 80/11/06 4pp 07019 028

801170828 Notification of 801114 meeting in Bethesda, MD w/util to discuss topics re SEP seismic evaluation of facility
CARUSO, R Operating Reactors Branch 5 80/11/07 2pp 06978 359

8011200073 Responds to 800528 submittal re LUCA loads at facility Efforts should be continued to determine radiological impact of implementing conceptual physical mods required to stresses from postulated double-ended guillotine break
CRUTCHFIELD, D Operating Reactors Branch 5 80/11/07, 3pp, 07018 141

8011210555 Forwards summary of SEP efforts completed & committed to by owners for NRC SEP progress evaluation
SCHAFSTALL, R SEP Owners Group 80/11/17 5pp 07035 028

G Inspection reports, IE Bulletins & correspondence

801180455 Forwards IE Insp Rept 30-029/80-13 on 800804-06 No noncompliance noted
BRUNER, E J, Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/19 2pp 05989 224

--801180460 IE Insp Rept 30-029/80-13 on 800804-06 No noncompliance noted Major areas inspected containment integrated leak rate test procedure & activities, pumps & valves inservice testing program & actions on previous findings
REKTO, W A Region 1, Philadelphia, Office of the Director, CAPTION, D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/18 9pp 06989 226

801190609 Ack receipt of 800527 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-029/79-15
SMITH, G M Region 1, Philadelphia, Fuel Facility & Materials Safety Branch, 80/10/16 1p 07001 210

--801190619 Responds to NRC 800311 ltr re violations noted in IE Insp Rept 30-029/79-15 Corrective actions training program revised & records maintained Audit performed on transfer, packaging & transport of low level waste.
MOODY, D E Yankee Atomic Electric Co 80/05/27, 2pp 07001 211

--801190624 Forwards IE Insp Rept 30-029/79-15 on 791213-14, No noncompliance noted Addl info needed on training/retraining program & audit program for low level waste transfer, packaging & transport.
SMITH, G M Region 1, Philadelphia, Fuel Facility & Materials Safety Branch, 80/03/11 2pp 07001 213

--801190632 IE Insp Rept 30-029/79-15 on 791213-14 No noncompliance noted Major areas inspected licensee response to IE Bulletin 79-19, including review of DOT & NRC regulations maintained on site
PLUMLEE, K E Region 1, Philadelphia, Office of the Director
KNAPP, P J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/07 9pp, 07001 215.

8011070292 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director, 80/10/24, 1p, 06921 312.

801140070 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators." No written response required
GRIER, B H, Region 1, Philadelphia, Office of the Director 80/10/31, 1p, 06968 231

801170864 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06979 356

R Periodic operating reports & related correspondence

801140389 Forwards monthly operating rept for Oct 1980
MOODY, D E Yankee Atomic Electric Co 80/11/12 1p 06963 022

--801140390 Monthly operating rept for Oct 1980
BEERS, F C Yankee Atomic Electric Co 80/11/12 5pp 06963 023

S Reportable occurrences, LERs & related correspondence

801100475 Forwards LER 80-017/03L-0
AUTIO, H A Yankee Atomic Electric Co 80/11/05 1p 06931 101

--801100482 LER 80-017/03L-0 on 801005, during maint outage while performing calibr of steam generator 2, low steam generator water trip setpoint was found operating below Tech Spec limits. Caused by sensing line configuration deficiency
FRENCH, L D Yankee Atomic Electric Co 80/11/05 1p 06931 102.

801140046 Forwards LER 80-018/03L-0
AUTIO, H A Yankee Atomic Electric Co 80/11/11 1p 06961 352

--801140052 LER 80-018/03L-0, on 801012, both scram contact setpoints of steam generator 1 found below Tech Specs limit Caused by design deficiency in sensing line which did not allow adequate venting Setpoint adjusted
MAY, E L Yankee Atomic Electric Co 80/11/11 1p 06961 353

DOCKET 30-30 PLUM BROOK RESEARCH REACTOR FACILITY

801140121 Responds to NRC questions resulting from review of supporting dismantling plans & environ repts forwarded w/800317 ltr to WP Gannett requesting issuance of dismantling order & termination of licenses
BENEDICT, D E National Aeronautics & Space Admin 80/11/07 5pp 06911 001.

--801140128 NPDES Permit OH 0001392 issued to NASA Supporting documentation encl.
* Environmental Protection Agency, 80/08/25, 14pp, 06911 001

DOCKET 30-54 UNION CARBIDE RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

801130090 Ack receipt of 790504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-054/79-01.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/02, 1p 06958 211

--801130099 Responds to NRC 790410 ltr re violations noted in IE Insp Rept 30-054/79-01 Corrective actions clarification made re interpretation of term, at controls. Also discusses IE Bulletins 78-07 & 78-08 & Circular 77-14
VOTH, H H Union Carbide Corp, 79/03/04 4pp 06958 212

--801130105 Forwards IE Insp Rept 30-054/79-01 on 790227-28 & notice of violation
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/04/10, 3pp 06958 216

--801130109 Notice of violation from insp on 790227-28
* Region 1, Philadelphia, Office of the Director, 79/03/29 2pp, 06958 219.

--801130113 IE Insp Rept 30-054/79-01 on 790227-28, Noncompliance noted: reactor operator left controls, audits were not reviewed & bulletins could not be located.
ARCHITZEL, R Region 1, Philadelphia, Office of the Director, MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 79/03/29 8pp, 06958 221.

DOCKETED ITEMS

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

O Advisory Committee on Reactor Safeguards reports & correspondence

801110654 Transcript of Subcommittee on GETR 801104 meeting in Washington, DC, re show cause order requiring cold shutdown
Pp 1-154
* ACRS - Advisory Committee on Reactor Safeguards 80/11/04
190pp 06943 106

801110920 Summaries ACRS 801106-08 review of GE request for facility restart Licensee must show facility can sustain ground level accelerations of 0.75 gravity w/o surface offset & 0.6 gravity w/surface displacement
PLESSET, H S ACRS - Advisory Committee on Reactor Safeguards
80/11/12 3pp 07000 102

P Operating license stage documents & correspondence

7812190031 Forwards Summary of a 771202 meeting re postulated Verona fault, 771209 NRC ltr to US Geological Survey requesting info on surface faulting Requests course of action planned to resolve surface faulting issue
SCHMENCER, A Operating Reactors Branch 1 (Pre 790625) 77/12/14
2pp

7812190031 Forwards Summary of a 771202 meeting re postulated Verona fault, 771209 NRC ltr to US Geological Survey requesting info on surface faulting Requests course of action planned to resolve surface faulting issue
SCHMENCER, A Operating Reactors Branch 1 (Pre 790625) 77/12/14
2pp

--7812190004 Summary of 771202 meeting re geological & seismological matters relating to seismic re-evaluation of GETR Requests that facility provide info re surface faulting in support of 771024 show cause order w/list of attendees
BURGER, A Operating Reactors Branch 1 (Pre 790625) 77/12/14
4pp 94214 228

--7812190013 Requests advice & info on potential for surface faulting within immediate vicinity of GETR Forwards NRC show cause order & comments for evaluation before a meeting between NRC & UEGS can be held
CASE, E Q Office of Nuclear Reactor Regulation, Director
77/12/09 2pp 94214 232

--7812190020 Forwards NRC order to show cause which requires that GETR be placed & maintained safely in cold shutdown condition pending further order
CASE, E Q Office of Nuclear Reactor Regulation, Director
77/10/21 1p 94214 234

--7812190026 Show cause order requiring that, upon completion of present operating cycle on 771027, GETR should be placed & maintained safely in cold shutdown condition Comments for GETR 771202 meeting encl
CASE, E Q Office of Nuclear Reactor Regulation, Director
77/10/24 13pp 94214 235

801110686 Forwards draft safety evaluation re GETR landslide hazard & seismic design Addl info needed to determine soil property effects on seismic analysis
EISENHUT, D Q Assistant Director for Licensing 80/10/27 8pp
06943 005

8011050447 Forwards response to NRC request for addl info re bearing capacity values for soil beneath test reactor Recent evaluations of soil bearing capacity reflect conditions presented in previous findings Affirmation encl
DARMITZEL, R W General Electric Co 80/10/31 14pp 06894 091

G Inspection reports, IE Bulletins & correspondence

8011070205 Forwards IE Insp Rept 50-070/80-02 on 800918-19 No noncompliance noted
CRENS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/10/14 2pp 05924 193

--8011070211 IE Insp Rept 50-070/80-02 on 800918-19 No noncompliance noted Major areas inspected facility activities & staffing, surveillance, review & audit, facility mods & independent insp effort
ZHETZIO, Q B Region 5, San Francisco, Office of the Director
FAUXENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/10/14 5pp 06924 195

DOCKET 80-72 UNIV OF UTAH RESEARCH REACTOR

P Operating license stage documents & correspondence

8011100001 Forwards Amends 4 & 11 to Licenses R-126 & R-25, respectively, revising physical security plans
MILLER, J R Standardization & Special Projects Branch 80/10/17
3pp 06928 231

--8011100004 Amends 4 & 11 to Licenses R-126 & R-25, respectively, revising physical security plan
MILLER, J R Standardization & Special Projects Branch 80/10/17
4pp 06928 234

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

P Operating license stage documents & correspondence

7812190001 Forwards Summary of a 771202 meeting re postulated Verona fault, 771209 NRC ltr to US Geological Survey requesting info on surface faulting Requests course of action planned to resolve surface faulting issue
SCHMENCER, A Operating Reactors Branch 1 (Pre 790625) 77/12/14
2pp

--7812190020 Forwards NRC order to show cause which requires that GETR be placed & maintained safely in cold shutdown condition pending further order
CASE, E Q Office of Nuclear Reactor Regulation, Director
77/10/21 1p 94214 234

--7812190026 Show cause order requiring that, upon completion of present operating cycle on 771027, GETR should be placed & maintained safely in cold shutdown condition Comments for GETR 771202 meeting encl
CASE, E Q Office of Nuclear Reactor Regulation, Director
77/10/24 13pp 94214 235

8011120616 Forwards Amend 14 to License R-53 & safety evaluation
MILLER, J R Standardization & Special Projects Branch 80/11/05
4pp 06950 302

--8011120620 Amend 14 to License R-53, revising Tech Specs to include limits on excess reactivity on movement of manual poison sheets
MILLER, J R Standardization & Special Projects Branch 80/11/05
8pp 06950 304

--8011120624 Safety evaluation supporting Amend 14 to License R-53
* Office of Nuclear Reactor Regulation, Director 80/11/05 5pp
06950 314

8011210126 Forwards FR notice re renewal of amended facility OL Existing license will not expire until application finally determined
MILLER, J R Standardization & Special Projects Branch 80/11/05
2pp 07037 136

--8011210131 Notice of consideration of application for renewal of amended OL
MILLER, J R Standardization & Special Projects Branch 80/11/05
3pp 07037 138

DOCKET 50-69 GENERAL ATOMIC CO

J Insurance & indemnity information

8011030430 Forwards Endorsement 113 to NELIA Policy NF-34
CORREA, M A Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc
Div 80/10/28 2pp 06855 094

DOCKET 50-94 ROCKWELL INTERNATIONAL RESEARCH REACTOR

J Insurance & indemnity information

8011140015 Forwards Endorsements 91, 92 & 93 to NELIA Policy NF-12 & Endorsements 81 & 82 to NELIA Policy NF-93.
BRINDLEY, J H Rockwell International Corp, Energy Systems Div
80/10/27 8pp 06961 195

DOCKETED ITEMS

15

Q Inspection reports, IE Bulletins & correspondence

8011070587 Forwards IE Insp Rept 50-094/80-01 on 800924-25 No noncompliance noted
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/10/16 2pp 06925 220

--8011070591 IE Insp Rept 50-094/80-01 on 800924-25 No noncompliance noted Major areas inspected physical status of facility to determine licensee plans & timetable re reactor dismantling plant
CURTIS, J R, WENBLAWSKI, F Region 5, San Francisco, Office of the Director BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/10/15 2pp 06925 222

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

J Insurance & indemnity information

8011260012 Amend 10 to Indemnity Agreement E-4, changing financial info in article III, Paragraph 4(b)(2)
SALTZMAN, J Utility Finance Branch (formerly Antitrust & Indemnity) 80/11/13 1p 07075 295

8011260025 Amend 11 to Indemnity Agreement E-4 changing financial info in article III, Paragraph 4(b)(2)
SALTZMAN, J Utility Finance Branch (formerly Antitrust & Indemnity) 80/11/13 1p 07074 234

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

P Operating license stage documents & correspondence

8011030325 Provides listing & explanation of matl that should be included in license renewal Tech Specs, SAR financial statement, physical security plans & emergency planning
MILLER, J A Standardization & Special Projects Branch 80/10/16 2pp 06861 206

DOCKET 50-116 IOWA STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8011060694 Forwards IE Insp Rept 50-116/80-03 on 801015-16 No noncompliance noted
HIND, J A Region 3, Chicago, Safeguards Branch 80/10/27 1p 06914 335

--8011060699 IE Insp Rept 50-116/80-03 on 801015-16 No noncompliance noted Major areas inspected security plan implementation Details withheld (ref 10CFR2 790)
KNICELEY, J R Region 3, Chicago, Office of the Director HIND, J A Region 3, Chicago, Safeguards Branch 80/10/24 1p 06914 336

DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR

P Operating license stage documents & correspondence

801120569 Forwards safety evaluation of licensee 800917 request for amend to License R-62 re temporary waiver of Tech Specs to permit operation & tests of 13-plate fuel assembly Request is acceptable Proposed Tech Specs change encl
RUBENSTEIN, L B Assistant Director for Core & Containment Systems 80/10/23 1p 06953 295

--801120571 Safety evaluation supporting Amend 4 to License R-62 re temporary waiver of Tech Specs to permit operation & tests of 13-plate fuel assembly
* Assistant Director for Core & Containment Systems 80/10/23, 2pp 06953 256

--801120573 Amend 4 to License R-62, re temporary waiver of Tech Specs to permit operation & tests of 13-plate fuel assembly
* Assistant Director for Core & Containment Systems 80/10/23 2pp 06953 258

8011190252 Informs that safety evaluation of amend request, forwarded in 800917 ltr, to License R-62 for temporary waiver of Tech Specs to permit operation & tests of 13-plate fuel assembly is acceptable Forwards Tech Spec change w/o encl
RUBENSTEIN, L B Division of Systems Integration 80/10/23 1p 06956 259

DOCKET 90-128 TEXAS A&M UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

8011040483 Application to revise 790702 request for renewal of License R-83 Revisions to application, Tech Specs & safety evaluation are due to administrative changes
SAMSON, C H Texas A & M Univ 80/10/20 1p 06873 057

--8011040489 Application to change 790702 request for renewal of License R-83 Revisions are due to administrative changes Safety evaluation encl
* Texas A & M Univ 80/10/20 6pp 06873 038

--8011040494 Proposed Tech Specs & O re administrative organization for operation
* Texas A & M Univ 80/10/20 2pp 06873 064

DOCKET 90-133 HUMBOLDT BAY POWER PLANT, UNIT 3

Q Adjudicatory correspondence

8011250584 Order granting licensee motion to hold proceeding in abeyance until 801231 ASLB withdraws order to Joint Intervenor to file amended contentions within 45 days of receipt of Woodward-Clyde Consultants rept
LAZO, R M Atomic Safety and Licensing Board Panel 80/11/18 3pp 07069 001

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp

8011190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance Info should be submitted within 25 days
EISENHUT, D G Division of Licensing 80/10/01 2pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

8011040079 Forwards list of info needed for completing review of GE emergency procedure guidelines Guidelines have been approved for trial implementation at LaBalle, Zinner, Shoreham, Fermi 2 & Susquehanna facilities
EISENHUT, D G Division of Licensing, 80/10/21 8pp 02319 196

Q Inspection reports, IE Bulletins & correspondence

8011060779 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting" No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/10 1p 06909 094

8011130021 Forwards Suppl 3 to IE Bulletin 79-018, "Environment Qualification of Class IE Equipment," to aid in written response required by 801101
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/24 1p 06958 056

8011170631 Forwards IE Circular 80-23, "Potential Defects in Beldit Power Sys Emergency Generators" No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/31 1p 06977 274

R Periodic operating reports & related correspondence

8011180576 Forwards monthly operating rept for Oct 1980
WEEKS, E D Pacific Gas & Electric Co 80/11/05, 1p 06987 352

DOCKETED ITEMS

--801180579 Monthly operating rept for Oct 1980
BAUM, P W Pacific Gas & Electric Co 80/11/05 App 06987 353

DOCKET 50-134 WORCESTER POLYTECH INST RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8011230351 Forwards revised Pages 3 & 4 of physical security plan
Pages withheld (ref 10CFR2 790)
WILBUR, L C Worcester Polytechnic Inst 80/11/20 1p 07056 123

DOCKET 50-142 UCLA TRAINING REACTOR

G Adjudicatory correspondence

8011140053 Order granting extension until 801117 for Commission to
elect whether to review Director's decision
CHILK, B J Office of the Secretary of the Commission 80/11/07
1p 06961 357.

8011240167 Responses to intervenor first set of interrogatories
Includes info re percentage of operating & maint devoted to
sales, svcs & research Certificate of Svc encl
REIDHAAR, D L, WOODS, O R, HELWICK, C California, Univ of,
Berkeley 80/11/14 20pp 07041 084

8011240183 Order granting extension until 801124 for Commission to
determine whether to review Director's decision per 2 772
CHILK, B J Office of the Secretary of the Commission 80/11/17
1p 07042 362

8011280043 Order granting extension until 801217 for Commission to
determine whether to review Director's decision under
10CFR2 206
CHILK, B J Office of the Secretary of the Commission 80/11/24
1p 07084 089

J Insurance & indemnity information

8011140003 Informs that endorsements, indemnity agreements or most
current amends have not been received & requests provision
of all referenced agreements.
DENESS, S J California, Univ of, Berkeley 80/10/31 1p
06961 220

--8011140004 Requests signed copies of Amends 7 & 9 to Indemnity
Agreement E-16
DINITZ, I Utility Finance Branch (formerly Antitrust & Indemnity)
80/09/24 1p 06961 221

8011260017 Amend 7 to Indemnity Agreement E-16 changing financial info
in Article III, Paragraph 4(b)(2)
BALTZMAN, J Utility Finance Branch (formerly Antitrust & Indemnity)
80/11/13 1p 07074 156

8011260029 Amend 9 to Indemnity Agreement 16, changing transportation
info in Article I, Paragraph 4
BALTZMAN, J Utility Finance Branch (formerly Antitrust & Indemnity)
80/11/14 1p 07074 235

DOCKET 50-146 SAXTON NUCLEAR EXPERIMENTAL FACILITY

I Inspection reports, IE Bulletins & correspondence

1011190250 Ack receipt of 800929 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-146/79-01
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety
Branch 80/10/16 1p 07001 192

--8011190253 Responds to NRC 800905 ltr re violations noted in IE Insp
Rept 50-146/79-01 Corrective actions contaminated soil has
been removed to reduce radiation levels & repairs to roof
hatch cover complete
MONTGOMERY, C R Saxton Nuclear Experimental Corp 80/09/29 2pp
07001 193

8011190263 Informs that no personnel monitoring required during CY79
& CY80
MONTGOMERY, C R Saxton Nuclear Experimental Corp. 80/09/24 1p
07001 193

R Periodic operating reports & related correspondence

8011200304 Advises that 790929 ltr (ref SNEG/88), transmitting yearly
rept, should be dtd 800930
MONTGOMERY, C E Saxton Nuclear Experimental Corp 80/09/30 1p
07020 049

DOCKET 50-147 ROCKWELL INTL CORP CRITICAL FACILITY

J Insurance & indemnity information

8011140015 Forwards Endorsements 91, 92 & 93 to NELIA Policy NF-12 &
Endorsements 81 & 82 to NELIA Policy NF-93
BRINDLEY, J H Rockwell International Corp, Energy Systems Div
80/10/27 8pp 06961 195

DOCKET 50-150 OHIO STATE UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8011190490 Forwards IE Insp Rept 50-150/80-03 on 800930 No
noncompliance noted
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety
Branch 80/10/14 2pp 06998 108

--8011190496 IE Insp Rept 50-150/80-03 on 800930 No noncompliance noted
Major areas inspected emergency planning, including
examination of coordination w/support agencies, emergency
equipment & training & drills
GREER, R J, PAPERIELLO, C J Region 3, Chicago, Office of the
Director 80/10/12 4pp 06998 110

DOCKET 50-155 BIO ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8011100515 Responds to 800718 & 0811 ltrs re IE Health Physics
Rept 50-155/80-04 Off-shift radiation protection coverage
should be upgraded to ensure effective accident response
KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/24
2pp 06931 221

8011100533 Forwards response to items of noncompliance noted in IE
Health Physics Rept 50-155/80-04 Corrective action
supervisory position re radiation protection established,
per Item 1, although util does not agree w/infracton
HOFFMAN, D P Consumers Power Co 82/07/18 6pp 06931 223

--8011100539 Clarifies util position re Item 1 of IE Health Physics Rept
50-155/80-04 Tech Spec 10 & 2 2(d) requiring presence of
person qualified in radiation protection when fuel is in
reactor, has been consistently implemented
HOFFMAN, D P Consumers Power Co 80/08/11 1p 06931 231

8011200189 Submits info in response to NRC 800905 request & to meet
requirements of NUREG-0654, "Criteria for Preparation &
Evaluation of Radiological Emergency Plans & Preparedness in
Support of Nuclear Power Plants"
HOFFMAN, D P Consumers Power Co 80/11/14 3pp 07019 337

G Adjudicatory correspondence

801110661 Forwards order for mod of License DPR-6 re environ
qualification of safety-related electrical equipment Revised
Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp
06944 307

--801110669 Order for mod of license re environ qualification of safety-
related electrical equipment Compliance w/Div of Operating
Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06944 310

--801110676 Revised Tech Spec pages per 801024 order for mod of license
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 2pp 06944 316

8011040142 Forwards parties' briefs before ASLAW re NEPA issue, in
response to 801030 telcon w/o encl
MOORE, J E Hearing Branch 2 80/10/31 1p 06873 285

DOCKETED ITEMS

17

- 8011070043 Notice of reconstitution of ASLAB in spent fuel expansion proceeding, consisting of TS Moore, chairman; JH Buck & CH Kohl, members
TO: PKINS, B A Atomic Safety and Licensing Appeal Panel 80/11/03
ip 06924 311
- 8011060372 Forwards objections & responses to first set of interrogatories re spent fuel pool mod Certain info available in PDR
MOORE, J E Hearing Branch 2 80/11/05 2pp 06910 268
- 8011060378 Response in opposition to certain of J O'Neill first set of interrogatories re spent fuel pool mod Requested info needs research & compilation of data not required per regulations & case law
MOORE, J E Hearing Branch 2 80/11/05 12pp 06910 270
- 8011060384 Response to J O'Neill Interrogatories 1,2,3 & 4. Submits tabulation of spent fuel storage capacity & identifies facilities that have irradiated mixed oxide fuel assemblies Affidavit & proof qualifications encl
PAULSON, W A Division of Licensing 80/11/04 14pp 06910 282
- 801180795 Motion for extension until 801204 to file brief in support of memorandum & order re NEPA review & 801222 to receive NRC & CPC reply briefs Draft order & Certificate of Evc encl
SEKMELE, H Christa-Maria 80/11/13 5pp 06985 103
- 8011240180 Petition to intervene Contentions encl
BIER, J, BARNETT, P, JOHN, S J Affiliation Unknown 80/11/13
2pp 07049 243
- 8011250043 Request for 10-day extension for intervenors Christa Maria, J Bier & J Mills to file answering brief re ASLAB review of ASLB memorandum & order on NEPA review Draft order encl
Granted for ASLAB 801117
SEKMELE, H Christa-Maria SEKMELE, H Urban Law Institute 80/11/18
3pp 07056 205
- P. Operating license stage documents & correspondence
- 7903240271 Forwards topics deleted from systematic evaluation program review, due to parallel review as generic issue or inapplicability Requests review & comments within 30 days
ZIEHMAN, D L Operating Reactors Branch 2 (Pre 790628) 79/04/16
7pp
- 7906260194 Forwards comments re systematic evaluation program deletions proposed in NRC 790416 ltr
BIYEL, D A Consumers Power Co 79/06/22 3pp 02318 211
- 8004110308 Forwards info re RELAP input for LOCA analysis at units
KUENIN, J L Consumers Power Co 80/04/02 61pp 90148 308
- 8011050384 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp
- 8009290143 Notification of 800926 meeting w/utills & Kerr-McGee Chemical Corp in Bethesda, MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment
ALLISON, D P Systematic Evaluation Program Branch 80/09/08 3pp
- 8011230340 Forwards corrections to 800627 proposed change to Tech Specs resolving problems re operability requirements for recirculation pump sump area sprinkler sys Supersedes 800627 request
HOFFMAN, D P Consumers Power Co 80/09/22 2pp 07056 128
- 8011230344 Corrections to 800627 proposed changes to Tech Specs re fire protection sys
* Consumers Power Co 80/09/22 7pp 07056 130
- 801180019 Advises that SEP Topics II-2 B, II-2 D, III-B, B & VI-B should be added to 791116 list of topics removed from review due to related generic NRC activities & nonapplicability BWR DBE topic list encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/26 5pp
06986 118
- 8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp
- 8011190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance info should be submitted within 25 days
EISENHUT, D O Division of Licensing 80/10/01 2pp
- 801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800927 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp
- 801110097 Confirms util commitment to NRC 791023 interim position on containment purging & venting Commitments will remain in effect pending completion of NRC long-term review
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/08 3pp
06943 112
- 8011100496 Responds to util 800825 & 0902 addl info re deferment of plant mods pending completed risk assessment re feasibility of continued operation ATWS recirculation pump trip & alternate shutdown panel mods cannot be deferred
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/10/14 8pp 06931 202
- 801110661 Forwards order for mod of License DPR-6 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp
06944 307
- 801110668 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0988 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06944 310
- 801110676 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944 316
- 8011030545 Forwards application for amend of License DPR-6 Tech Specs, revising Sections II 4 1 4A & B to provide surveillance requirements for new valving associated w/ECCS redundant line Class III fee encl
HOFFMAN, D P Consumers Power Co 80/10/28 1p 06861 183
- 8011030550 Application for amend of License DPR-6 Tech Specs, revising Sections II 4 1 4A & B to provide surveillance requirements for new valving associated w/ECCS redundant line
DEWITT, R B Consumers Power Co 80/10/28 2pp 06861 184
- 8011030568 Application for amend to License DPR-6 consisting of change to Tech Specs
HOFFMAN, D P Consumers Power Co 80/10/29 1p 06855 083
- 8011030573 Tech Spec 3 4 3(b) for control rod drive sys isolation
YOUNGBLUE, R C Consumers Power Co 80/10/29 1p 06855 084
- 8011040196 Forwards "Environ Qualification of Safety-Related Electrical Equipment" in response to NRC 800305 & 28 environ qualification of electrical equipment issue & to satisfy 800919 order modifying OL requiring submittal of info
HOFFMAN, D P Consumers Power Co 80/10/31 2pp 06876 151
- 8011040199 "Environ Qualification of Safety-Related Electrical Equipment"
* Consumers Power Co * Bechtel Corp 80/10/31 244pp
06876 153
- 801100487 Submits errata to Tech Spec, Table II 4 3 4 setpoints re surveillance interval for containment spray sys, Setpoints inadvertently omitted from 800707 application
WITHROW, G C Consumers Power Co 80/11/05 3pp 06928 015
- 801170728 Requests assistance in finalizing structural, mechanical & matls engineering portion of spent fuel pool storage expansion safety evaluation Requests review of encl marked-up draft by 801215
LAINAS, G C Assistant Director for Safety Assessment 80/11/05, 7pp 06977 286
- 8011250721 Notifies of delay in completion of SEP Topic XVI, "Tech Specs," to allow for integrated evaluation of current Tech Specs w/anticipated Tech Spec changes resulting from individual SEP topic reviews
CRUTCHFIELD, D Operating Reactors Branch 5 80/11/05 2pp
07056 045

DOCKETED ITEMS

8011280130 Informs that as result of 801113 meeting w/licenses, add'l work re containment temp pressure profile not presently justified
 RUSSELL, H Y Technical Support Branch 80/11/17 1p 03748 338

Q Inspection reports, IE Bulletins & correspondence

8011040177 Responds to IE Bulletin 79-26, Revision 1, "Baron Loss from BWR Control Blades " Core interior blades will be replaced during 1980 refueling outage
 HOFFMAN, D P Consumers Power Co 80/10/10 1p 06885 041

8011070235 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required
 KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/24 1p 06924 243

801110661 Forwards order for mod of License DPR-6 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
 CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp 06944 307

--801110668 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
 Complete records must be available by 801201
 EISENHART, D G Division of Licensing 80/10/24 6pp 06944 310

--801110676 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
 * Division of Licensing 80/10/24 2pp 06944 316

8011190337 Updates NRC 800903 ltr re site access of Region 3 personnel
 New badges are currently being issued Interim questions re Inspector identification should be directed to Region 3 ofc
 Badge examples encl
 KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/28 3pp 06999 185

8011200143 Forwards response to IE Bulletin 80-11 re masonry wall design All masonry wall segments satisfy re-evaluation criteria using basic allowable stresses adjusted w/allowable stress increase factor
 WITTHORN, Q C Consumers Power Co 80/11/03 42pp 07019 280

8011180363 Forwards response to NRC 801021 ltr re notice of violation noted in IE Insp Rept 80-135/80-12 Response withheld
 (ref 10CFR2 7901)
 HOFFMAN, D P Consumers Power Co 80/11/12 1p 06992 126

8011240255 Requests relief from provisions of ASME Boiler & Pressure Vessel Code, Section 10CFR50 35(a)(1)(i) Description of unit 40-yr Inservice insp master plan encl
 HOFFMAN, D P Consumers Power Co 80/11/17 67pp 07041 017

S Reportable occurrences, LERs & related correspondence

8011250314 Forwards LER 80-034/017-0
 HOFFMAN, D P Consumers Power Co 80/11/19 1p 07068 321

--8011250389 LER 80-034/017-0 on 801101, during routine shutdown operations, main steam isolation valve M07050 failed to close on remote manual initiation Caused by hardened packing matl on valve stem Other packing techniques are being considered
 * Consumers Power Co 80/11/19 1p 07068 322

8011290400 Forwards LER 80-035/03L-0
 HOFFMAN, D P Consumers Power Co 80/11/19 1p 07068 111

--8011250408 LER 80-035/03L-0 on 801024, during resin transfer from anion tank, found water leakage from 4-inch crack in anion tank Caused by leakage at weld seam Repair of tank planned
 * Consumers Power Co 80/11/19 1p 07068 112

V Operator Examinations

8011040128 Responds to NRC 800731 ltr re interim criteria for shift staffing Response outlines plans & schedule for adhering to various criteria, w/discussion on special problems, including personnel shortage & legal union agreement
 HOFFMAN, D P Consumers Power Co 80/10/31 4pp 06874 067

DOCKET 80-157 CORNELL UNIV RESEARCH REACTOR

J Insurance & indemnity information

8011260012 Amend 10 to Indemnity Agreement E-4, changing financial info in Article III, Paragraph 4(b)(2)
 SALTZMAN, J Utility Finance Branch (formerly Antitrust & Indemnity), 80/11/13 1p 07075 293

8011260025 Amend 11 to Indemnity Agreement E-4 changing financial info in article III, Paragraph 4(b)(2)
 SALTZMAN, J Utility Finance Branch (formerly Antitrust & Indemnity), 80/11/13 1p 07074 234

DOCKET 80-160 GEORGIA INST OF TECH RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8011140313 Forwards IE Insp Rept 80-160/80-03 on 800826-28 No noncompliance noted
 LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/30 2pp 06960 334

--8011140316 IE Insp Rept 80-160/80-03 on 800826-28, No noncompliance noted Major areas inspected nuclear safeguards committee log & record review, surveillance & procedures
 JULIAN, C, SKINNER, P Region 2, Atlanta, Office of the Director, DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/23 4pp 06960 336

DOCKET 80-163 GENERAL ATOMIC COMPANY

J Insurance & indemnity information

8011030430 Forwards Endorsement 113 to NELIA Policy NF-34
 CORREA, M A Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 80/10/28 2pp 06855 094

8011140348 Forwards Endorsements 50 & 111 to MAELU & NELIA Policies NF-39 & NF-34, respectively
 CORREA, M A General Atomic Co (subs of Gulf Oil Co), 80/10/30, 3pp 06960 360

DOCKET 80-183 VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR

P Operating license stage documents & correspondence

801110741 Forwards Summary of a 771202 meeting re postulated Verona fault, 771209 NRC ltr to US Geological Survey requesting info on surface faulting Requests course of action planned to resolve surface faulting issue
 SCHMENCER, A Operating Reactors Branch 1 (Pre 790625) 77/12/14 2pp

--7812190026 Show Cause Order requiring that, upon completion of present operating cycle on 771027, the Gen Elec Test Reactor be placed & maintained safely in cold shutdown condition
 Comments for OETR 771202 meeting encl
 CASE, E O Office of Nuclear Reactor Regulation, Director 77/10/24 13pp

DOCKET 80-185 PLUM BROOK REACTOR - MOCK-UP

8011140121 Responds to NRC questions resulting from review of supporting dismantling plans & environ repts forwarded w/800317 ltr to WP Gammill requesting issuance of dismantling order & termination of licenses
 BENEDICT, D E National Aeronautics & Space Admin 80/11/07 5pp 06911 001

--8011140128 NPDES Permit OH 0001392 issued to NASA Supporting documentation encl
 * Environmental Protection Agency 80/08/25 14pp 06911, 001

DOCKET 80-186 UNIV OF MISSOURI RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8011280199 Ack receipt of 801105 ltr informing NRC of evaluation of exposure & stating policy re oversight of health physics operations
 KEPPLER, J O Region 3, Chicago, Office of the Director, 80/11/18 1p 07082 362

--B011280202 Ack receipt of B01013 ltr Informs of policy to provide for independent oversight of health physics operation Forwards assessment of noted overexposure Senior-level health physics technician will be added to staff
GEORGE, M D Missouri, Univ of, Columbia 80/11/05 14pp
07083 001

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

B011070215 Forwards IE Insp Rept 50-187/80-01 on B00922-24 & notice of violation
BOOK, H E Region 9, San Francisco, Fuel Facility & Materials Safety Branch 80/10/16 2pp 06924 200

--B011070218 Notice of violation from insp on B00922-24
* Region 9, San Francisco, Office of the Director 80/10/16 1p
06924 202

--B011070223 IE Insp Rept 50-187/80-01 on B00922-24 Noncompliance noted annual exposure summary repts not submitted
CURTIS, J R, WENSLAWSKI, F A Region 9, San Francisco, Office of the Director BOOK, H E Region 9, San Francisco, Fuel Facility & Materials Safety Branch 80/10/16 5pp 06924 203

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B011030202 Requests info be provided by B01020 in order to assess compliance w/10CFR73 67 requirements since no security plan has been received by NRC Info requested includes total amount & enrichment of SNM currently possessed at facility
MILLER, J R Standardization & Special Projects Branch 80/09/23 1p 06897 141.

Q Inspection reports, IE Bulletins & correspondence

B011100303 Forwards IE Insp Rept 50-199/80-01 on B00827-28 No noncompliance noted.
MARTIN, H G Region 1, Philadelphia, Safeguards Branch 80/09/17 2pp 06929 141

--B011100311 IE Insp Rept 50-199/80-01 on B00827-28 No noncompliance noted Major areas inspected security plan, protection of SNM, security organization, access controls & alarm sys Details withheld (ref 10CFR2 790)
HICKEDIN, L M Region 1, Philadelphia, Office of the Director.
DEVLIN, J W Region 1, Philadelphia, Safeguards Branch 80/09/15 1p 06929 143

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

G Adjudicatory correspondence

B011040382 Responds to B01013 ltr transmitting J Courtney request for resumption of QEBMD proceeding Comments will be taken into account in NRC review re proceeding
KAMMERER, C Office of Congressional Affairs 80/10/22 1p
06873 294

H General correspondence

B011030454 Forwards LLL rept "Structural Analysis of Fuel Receiving Station Pool at Nuclear Fuel Reprocessing Plant, West Valley, NY;" UGRL-52575 & 790514 ltr, w/o encls
CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 80/09/17 1p 06861, 209

B011030458 Discusses status of radwaste burial grounds at West Valley, NY in response to ltr to President Carter, w/o encl interim safety evaluation
HAUGHNEY, C J Advanced Fuel & Spent Fuel Licensing Branch 80/09/17 2pp 06861 210

P. Operating license stage documents & correspondence

B011260432 Notification of postponed B01022 meeting w/NFS & NY State R&D Authority in Silver Spring, MD to discuss progress of company efforts to process available technical info needed to provide basis for future decontamination
HAUGHNEY, C J Advanced Fuel & Spent Fuel Licensing Branch 80/10/10 2pp 07073 088

B011260437 Notification of B01023 meeting w/NFS & NY State R&D Authority & DOE in Silver Spring, MD to discuss facility indemnification & liability issues associated w/implementation of work by contractor
HAUGHNEY, C J Advanced Fuel & Spent Fuel Licensing Branch 80/10/10 2pp 07073 094

B011030653 "Geotechnical Analysis of Soil Samples & Study of Research Trench at Western NY Nuclear Svc Ctr, West Valley, NY" HOFFMAN, V C, FICKIES, R H, DANA, R H New York, State of FIN B-6008 NUREG/CR-1566 80/10/31 82pp 06863 044

B011030672 "General Investigation of Radionuclide Retention in Migration Pathways at West Valley, NY Low Level Burial Site," final rept, Oct 1978-Feb 1980
DANA, R H, RAQAN, V S, MOLELLO, S A New York, State of. FIN B-6008 NUREG/CR-1565 80/10/31 157pp 06862 113

B01180273 Summary of B01020 meeting w/DOE re technical aspects of plans to implement high level waste solidification project & DOE responsibilities
DAVIS, J O Office of Nuclear Material Safety & Safeguards 80/11/12 2pp 06989 107

DOCKET 50-202 UNIV OF NEVADA RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

B011140683 Forwards order for mod of Licenses DPR-42 & DPR-60 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B011040177 Forwards emergency planning info for housing in Mission Viejo, CA LPDR W/o encl
BOUDER, J L Division of Rules and Records 80/10/23 1p
06911 343

G Adjudicatory correspondence

B011240028 Forwards order for mod of License DPR-13 re environ qualification of safety-related electrical equipment (BEP Topic 111-12) Revised Tech Specs also encl
CRUTCHFIELD, D, Operating Reactors Branch 5 80/10/24 3pp, 07042, 339

--B011240032 Order for mod of license re environ qualification of safety-related electrical equipment, Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by B20630 Complete records must be available by B01201
EISENHUT, D G Division of Licensing 80/10/24, 6pp 07042, 342

--B011240034 Revised Tech Spec pages per B01024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 07042 348

H General correspondence

B011090037 Responds to B00929 ltr discussing B Feldman concerns re nuclear insurance & liability coverage Price-Anderson Act provides \$360 million to pay public liability claims for personal injury & property damage resulting from incidents
DIRCKS, W J Office of the Executive Director for Operations, 80/10/22 5pp 06894 117

J Insurance & indemnity information

B011210442 Forwards Endorsements 71-74 & 76 to ANI Policy NF 146 & Endorsements 62, 63, 65 & 68 to MAELU Policy MF-38
HUOHES, W B Southern California Edison Co 80/11/14 10pp, 07034; 064.

P Operating license stage documents & correspondence

7809270027 Notice of meeting on 780927 w/util owners group of the systematic evaluation prog to discuss prog
DAVIS, D K, Systematic Evaluation Programs Branch (Pre 790625), 78/09/25 2pp

DOCKETED ITEMS

8011170453 Submits review of Suppl 1I & 1II to "Simulation of 15 Earthquake Ground Motions for San Onofre Generating Station Unit 1 " Validity of modeling above 10 Hz may be in doubt due to sampling interval
HERRMANN, R B St Louis Univ 80/09/27 2pp 06975 140

8011050354 Ltr to all licensees of operating plants/applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/03 209pp

8011170473 Submits review of Suppl 3, "Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station, Unit 1 " Rept should be completed by indicating values for source parameters used in comparison w/Imperial Valley 1979 data
LUCO, J E Affiliation Unknown 80/09/29 11pp 06979 142

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

8011180205 Advises that SEP Topics II-2 B, II-2 D, III-B, VI-B, XV-11, XV-18, II-1 B & X should be added to 791116 list of topics removed from review due to related generic NRC activities & nonapplicability
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/01 5pp.
06987 307

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800927 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " H/O encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011240028 Forwards order for mod of License DPR-13 re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp.
07042 339.

--8011240032 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0389 required by 800630
Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 07042 342

--8011240034 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 07042 348

8011030606 Notification of 801030 meeting w/util in Bethesda, MD to discuss loss of saltwater cooling event & procedures in place for loss of saltwater cooling & desiccate in air sys
NOWICKI, S J Operating Reactors Branch 2 80/10/28 2pp
06860 095

8011070390 Forwards proprietary & nonproprietary revisions of 800318 info re low pressure turbine disc integrity Spring 1980 disc insp revealed no cracks in discs Proprietary info withheld (ref 10CFR2 790)
BASKIN, K P Southern California Edison Co 80/10/30 27pp
06911-001.

8011040820 Forwards "Environ Qualification of Electrical Equipment," updating 800618 submittal
BASKIN, K P Southern California Edison Co 80/10/31 2pp
06877 302

--8011040826 "Environ Qualification of Electrical Equipment "
* Southern California Edison Co 80/10/31 115pp 06877 304

8011210005 Advises of delay in completion of SEP Topic XVI, Tech Specs, until completion of all SEP topic reviews & integrated safety assessment Delay will allow evaluation of current Tech Specs w/proposed changes resulting from reviews
CRUTCHFIELD, D Operating Reactors Branch 5 80/11/05 2pp
07033 179

801120467 Informs that addl info requested in NRC 800916 ltr will not be provided until 801201 due to current workloads associated w/TMI mods & environ qualification
BASKIN, K P Southern California Edison Co 80/11/06, 1p
06993 393

8011180160 Notification of 801204 meeting w/util in Bethesda, MD for licensee to address consultant comments resulting from review of util Unit 1 seismic model
NOWICKI, S J Operating Reactors Branch 5, 80/11/07 2pp
06987 218

8011240297 Advises that submittal concerning proposed changes to Tech Specs re decay heat removal will be delayed until 801201
BASKIN, K P Southern California Edison Co 80/11/14, 1p
07039 262

8011210355 Forwards summary of SEP efforts completed & committed to by owners for NRC SEP progress evaluation
SCHAFFSTALL, R SEP Owners Group 80/11/17 5pp 07035 02B.

G Inspection reports, IE Bulletins & correspondence

8011060753 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director.
80/10/10 1p 06909 031

8011030541 Immediate action ltr re recent discovery of foreign matl in hot leg piping of steam generator A Work inside primary channel heads must be stopped immediately until listed actions are completed
ENGELKEN, R H Region 5, San Francisco, Office of the Director.
80/10/15 2pp 01756 001

8011200059 Forwards original response dtd 800828 to IE Bulletin 80-15, re emergency notification sys, signed in accordance w/ 10CFR50 54(f)
HAYNES, J O Southern California Edison Co 80/10/16 1p
07020 269

8011050350 Forwards IE Insp Rept 80-206/80-27 on 800915-19 No noncompliance noted
CRENS, J L, Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/10/17 2pp 06899 302

--8011050353 IE Insp Rept 80-206/80-27 on 800915-19 No noncompliance noted Major areas inspected included onsite organization, administration, maint & IE bulletin & circular followup
HORN, A J Region 5, San Francisco, Office of the Director
FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/10/17 3pp 06899 304

8011130019 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director.
80/10/24 1p 06958 032

8011170640 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
80/10/31 1p 06976 349

801120435 Ack receipt of 800930 ltr informing NRC of steps taken to correct violations noted in 800815 health physics appraisal
Commitments made in 801104 telcon responsive to NRC concerns
ENGELKEN, R H Region 5, San Francisco, Office of the Director
80/11/12 1p 07029 167

R Periodic operating reports & related correspondence

8011140027 Forwards monthly operating rept for Oct 1980
CURRAN, J K Southern California Edison Co 80/11/06, 1p.
06961-327

--8011140029 Monthly operating rept for Oct 1980.
JOY, J K Southern California Edison Co 80/11/06 5pp
06961 328

S Reportable occurrences, LERs & related correspondence

8011190295 Forwards addl info re time & temp limits, equipment design limitations, desiccant contamination & preventive maint programs in response to NRC 800927 ltr request concerning review of facility saltwater cooling sys failure
BASKIN, K P Southern California Edison Co 80/10/08 49pp.
06916; 001

8011040437 Forwards LER 80-037/04L-0
HAYNES, J O Southern California Edison Co. 80/10/27 2pp
06884, 231

DOCKETED ITEMS

21

--8011040447 LER 80-037/04L-0 during routine data processing, ocean thermal measurement data taken at Station C28 & C228 on 790313-1113 found irretrievable. Caused by failure of ENDECO sensor motor, jammed cartridge or overexposed film
STRACHAN, A R Southern California Edison Co 80/10/27 1p
06884.233

DOCKET 80-213 HADDAM NECK PLANT

F Security, medical, emergency & fire protection plans

8011260112 Forwards summary of NRC requirements to resolve open items re Facility fire protection program Proposed plans & schedules for alternate shutdown capability should be provided by 801101.
EISENHUT, D O Division of Licensing. 80/10/07. 5pp 01741.019

8011170465 Forwards proposed revisions to modified amended security plan in response NRC 800611 ltr request & IE Insp Rept 80-213/80-10 Plan withheld (ref 10CFR2 7901).
COUNSIL, W O Connecticut Yankee Atomic Power Co 80/10/30 2pp
06971.359.

G. Adjudicatory correspondence

8011060124 Forwards revised orders for mod of license re environ qualification of safety-related electrical equipment. Hearing date revised accordingly
EISENHUT, D O Division of Licensing 80/09/19. 2pp 06916 002

--8011060130 Revised orders for mod of license correcting refs in 800829 orders
EISENHUT, D O Division of Licensing 80/09/19 6pp 06916 004

--8011060109 Revised orders for mod of license correcting refs in 800829 orders.
EISENHUT, D. O. Division of Licensing 80/09/19 6pp 06916 010

801110625 Forwards order for mod of License DPR-61 re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp
06945 313

--801110631 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D. O. Division of Licensing 80/10/24. 5pp. 06945.316

--801110638 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06945.322

P Operating license stage documents & correspondence

8008110072 Requests submission of plans for seismic evaluation program & justification for continued operation in interim Requests program plans by 800913, analysis by 80101 & necessary mods by 830101 Recommendations for site spectra encl
EISENHUT, D O. Division of Licensing. 80/08/04 4pp. 03189.006.

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

8011060049 Forwards evaluation of SEP Topic III-10 B, "Reactor Coolant Pump Flywheel Integrity." Requests that any discrepancy between as-built facility & licensing basis assumed in assessment be reported within 60 days of receipt of ltr
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/09/26. 4pp.
06911.149

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D. O Division of Licensing. 80/10/01 5pp.

8011100837 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl.
EISENHUT, D. O. Division of Licensing. 80/10/06 6pp.

8011060091 Accepts commitments to 791023, "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability." Commitments are to remain in effect pending completion of long-term review
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/08 2pp
06915 322

801120007 Forwards loss of offsite power survey status rept re SEP topics for review Rept describes method for data analysis & results of survey of loss of power events at domestic nuclear power facilities
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/10 43pp.
06916 001

801110625 Forwards order for mod of License DPR-61 re environ qualification of safety related electrical equipment (SEP Topic III-12). Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5. 80/10/24 3pp.
06945 313

--801110631 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing. 80/10/24 5pp 06945 316

--801110638 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06945 322

8011040320 Forwards "Environ Qualification of Safety-Related Electrical Equipment," & App I, "Master Listing of Electrical Components by Sys."
COUNSIL, W. O Connecticut Yankee Atomic Power Co 80/10/31 8pp
06890 143

--8011040363 "Environ Qualification of Safety-Related Electrical Equipment."
* Connecticut Yankee Atomic Power Co 80/10/31 230pp.
06890 151

--8011040366 App I, "Master Listing of Electrical Components by Sys." to "Environ Qualification of Safety-Related Electrical Equipment"
* Connecticut Yankee Atomic Power Co 80/10/31 200pp
06891 133

801140007 Forwards implementation status of TMI action plan items which cannot be implemented by 810101 identified
COUNSIL, W. O Connecticut Yankee Atomic Power Co COUNSIL, W. O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/10/31 17pp 06761 203

8011100422 Forwards update of 800821 response to Crutchfield 800701 ltr re adequacy of electric distribution sys voltages Encl data sheets summarize voltage study cases including min & max expected grid voltages & mod of operation
COUNSIL, W O Connecticut Yankee Atomic Power Co 80/11/04 37pp.
06928.022

801110450 Application to amend License DPR-61, changing Tech Specs re monthly manual tests of ECCB components Class III fee encl
COUNSIL, W O. Connecticut Yankee Atomic Power Co 80/11/04 3pp
06945.101

--801110453 Proposed Tech Specs re monthly manual tests of ECCB components
* Connecticut Yankee Atomic Power Co. 80/11/04 2pp 06945.104

801180348 Forwards response to NRC request for info re SEP Topic VI-5, combustible gas control. Response re hydrogen monitoring reflects currently available Sys & procedures & will be improved per TMI Lessons Learned requirements.
COUNSIL, W. O. Connecticut Yankee Atomic Power Co 80/11/05. 9pp.
06991.167

8011210041 Discusses decision to delay completion of SEP Topic XVI, Tech Specs, until all other SEP topic reviews & integrated safety assessments are completed, allowing for integrated evaluation of current & proposed Tech Specs
CRUTCHFIELD, D Operating Reactors Branch 5 80/11/05 2pp.
07030.336

801140349 Forwards Drawing 16103-30055, Sheet 1, Revision 2, & inverter info in response to NRC 800916 request for details re SEP Topics VI-7, B, VI-7 C, VI-10, VII-3, VIII-2 & VIII-3
COUNSIL, W. O. Connecticut Yankee Atomic Power Co 80/11/07. 3pp.
06968.171

DOCKETED ITEMS

--B01140336 "One-Line Diagram Inverters 120 Volt AC Vital Distribution Panel." Sheet 1
* Northeast Utilities Service Co 79/10/25 1p 0696B 174

B011210555 Forwards summary of SEP efforts completed & committed to by owners for NRC SEP progress evaluation
SCHAFFSTALL, R SEP Owners Group, 80/11/17 5pp

G Inspection reports, IE Bulletins & correspondence

B011100375 Forwards IE Insp Rept 50-213/80-14 on 800806-08, 25-27 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/26 2pp 06929 281

--B011100379 IE Insp Rept 50-213/80-14 on 800806-08 & 25-27. No noncompliance noted. Major areas inspected inservice insp program & related examination documentation
JERUHOA, E P. Region 1, Philadelphia, Office of the Director
TRIPP, L E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/24 5pp 06929 283

B011200141 Forwards IE Mgt Meeting Rept 50-213/80-17 on 800911
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/16 2pp. 07019 324

--B011200151 IE Mgt Meeting Rept 50-213/80-17 of 800911 mgt meeting to discuss regulatory performance of facility as concluded in systematic assessment of licensee program Licensee performance evaluation encl
ALLAN, J M, SMITH, T H Region 1, Philadelphia, Office of the Director, CARUSO, R Operating Reactors Branch 5 80/10/09 7pp 07019 326

B011180113 Immediate Action Ltr 80-39 confirming B01016 telcon re actions to be taken in response to findings of B01006-10 insp of physical protection program Encl detailing actions withheld (ref 10CFR2 790)
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/17 1p 06987 330

B011060678 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p. 06914 324

B011070284 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06921 296

B01110625 Forwards order for mod of License DPR-61 re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp 06945 313

--B01110631 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D G. Division of Licensing 80/10/24 5pp 06945 316

--B01110638 Revised Tech Spec pages per B01024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06945 322

B011210711 Ack receipt of B01010 ltr informing NRC of steps taken to correct violations noted in Waste Packaging Insp Rept 15000039/80-17
SMITH, O H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/24 1p 07029 001

--B011210717 Responds to NRC 800922 ltr re violations noted in Waste Packaging Insp Rept 15000039/80-17 Corrective actions pictures taken of all vehicles leaving site w/radioactive matl for burial showing proper placards
COUNSEL, W O., FEE, W F Connecticut Yankee Atomic Power Co 80/10/10 5pp 07029 002

--B011210724 Forwards Waste Packaging Insp Rept 15000039/80-17 on B00728 & notice of violation
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/09/22 2pp 07029 007

--B011210729 Notice of violation from Waste Packaging Insp Rept 15000039/80-17 on B00728
* Region 1, Philadelphia, Office of the Director 80/08/18 1p 07029 009

--B011210736 Waste Packaging Insp Rept 15000039/80-17 on B00728 Noncompliance noted failure to properly placard vehicle transporting waste radioactive matl
MACARTHUR, T C, POTTER, J P Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/18 4pp 07029 011

B011140275 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 0696B 239

B011140599 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06963 241

B011200079 Responds to IE Bulletin 80-11, "Masonry Wall Design." Log sheets describing walls & equipment, safety-related sys in proximity to walls & acceptance criteria encl Re-evaluation & mods will be completed by B010401
COUNSEL, W O Connecticut Yankee Atomic Power Co 80/11/04 16pp. 07020 306

R Periodic operating reports & related correspondence

B011180465 Forwards monthly operating rept for Oct 1980
GRAVES, R H Connecticut Yankee Atomic Power Co 80/11/10 1p 06989 240

--B011180467 Monthly operating rept for Oct 1980
NECK, H Connecticut Yankee Atomic Power Co 80/11/10 7pp 06989 241

B011250433 Forwards revised pages to semiannual radioactive effluent & waste disposal rept for Jan-June 1980
GRAVES, R H Connecticut Yankee Atomic Power Co 80/11/15 1p 07068 184

--B011250444 Revised Pages 8 & 10 to semiannual radioactive effluent & waste disposal rept for Jan-June 1980
* Connecticut Yankee Atomic Power Co 80/11/15 2pp 07068 185

S Reportable occurrences, LERs & related correspondence

B011030619 Discusses required actions re review of LER 80-040/03L-0 concerning operation of pressurizer power operated relief valves Requests submittal of schedule which reflects installation by B01030
EISENHUT, D G Division of Licensing 80/09/30 4pp 06873 022

V Operator Examinations

B011040158 Responds to NRC 800731 ltr re interim criteria for shift staffing Util commits to having two licensed senior reactor operators, two licensed reactor operators & min of two auxiliary operators at each operating reactor by 820701
COUNSEL, W O Northeast Utilities 80/10/22 6pp 06884 277

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

Q Adjudicatory correspondence

B009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREG-0423, "Rept of Siting Policy Task Force " Documents 6-8 & 13 are available in PDR Forwards remaining documents
FELTON, J M. Division of Rules and Records 80/09/04. 1p 06586 288

--B009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features
MINOUE, R B Office of Standards Development, Director
SECY-79-362 79/06/04 7pp

--B009190630 Requests that encl, "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards
SCINIO, J F Hearings Division 79/04/04 16pp

8011240014 Forwards order for mod of License DPR-16 re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl
CRUTCHFIELD,D Operating Reactors Branch 5 80/10/24 3pp
07049 306

--8011240020 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT,D O Division of Licensing 80/10/24 6pp 07049 309

--8011240025 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 07049 315

8011070192 Order granting extension until 801117 for Commission to elect whether to review ALAB-612
CHILK,B J Office of the Secretary of the Commission 80/11/03 1pp. 06921 008

801100235 Memorandum disclosing prior involvement in conversion to full-term OL proceeding as ACRS member from 660801-720312
Ability to consider present issues unimpaired Objections must be submitted by 801112
HENDRIE,J M Commissioners 80/11/06 1p 06929 070

P Operating license stage documents & correspondence

7910160145 Notification of 790926 meeting w/Mark I owners in Bethesda, MD to discuss pool swelling compressibility effects & downcomer condensation loads
GRIMES,C I Plant Systems Branch (Pre 791030) 79/09/24 1p
01147 344.

7910170010 Discusses need for addl confirmatory full scale tests to establish uncertainty in load magnitudes re condensation oscillation load definition procedures Draft ltr to Mark I
utils re test program encl
GRIMES,B K Assistant Director for Systems Engineering (Pre 791030) 79/09/25 4pp. 01155 333

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT,D O. Division of Licensing 80/09/05 209pp

8011190073 Forwards NRC evaluation of SEP Topic VIII-2, onsite emergency power sys Assessment compares facility w/criteria currently used for NRC licensing of new facilities
CRUTCHFIELD,D. Operating Reactors Branch 5 80/09/15 14pp
06999.192

8011050480 Forwards Amend 51 to License DPR-16 & notice of issuance & availability
CRUTCHFIELD,D Operating Reactors Branch 5 80/09/25 3pp
06898 287.

--8011050485 Amend 51 to License DPR-16, adding license condition to include Commission approved safeguards contingency plan
CRUTCHFIELD,D Operating Reactors Branch 5 80/09/25 2pp
06898 290.

--8011050487 Notice of issuance & availability of Amend 51 to License DPR-16
CRUTCHFIELD,D Operating Reactors Branch 5 80/09/25 2pp
06898 292

8011180251 Advises that SEP Topics II-2 B, II-2 D, III-B B & VI-B should be added to 791116 list of topics removed from review due to related generic NRC activities & nonapplicability BWR DBE list encl.
CRUTCHFIELD,D Operating Reactors Branch 5 80/09/26 3pp
06985 244

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT,D O. Division of Licensing 80/10/01. 5pp

8011190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance. Info should be submitted within 25 days.
EISENHUT,D O Division of Licensing 80/10/01 2pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT,D O Division of Licensing 80/10/06 6pp

8011090199 Advises that HRC has completed review of commitments to "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability " Commitments are acceptable
CRUTCHFIELD,D Operating Reactors Branch 5 80/10/08 2pp
06899 016

8011060052 Notification of 801021 meeting w/util in Bethesda, MD to discuss proposed new ECCS to replace core spray spargers
PAULSEN,H Operating Reactors Branch 5 80/10/13 3pp 06912 356

8011240014 Forwards order for mod of License DPR-16 re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl
CRUTCHFIELD,D Operating Reactors Branch 5 80/10/24 3pp
07049 306

--8011240020 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT,D O Division of Licensing 80/10/24 6pp. 07049 309

--8011240025 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing. 80/10/24 2pp. 07049.315

8011260065 FOIA request for summaries of nuclear waste shipments from facility
SHAFFER,D.O. The Express Easton, PA 80/10/27 2pp 07070 356

8011050423 Forwards rept, "Environ Qualification of Safety-Related Electrical Equipment," in response to NRC 800829 order
FINFROCK,I R Jersey Central Power & Light Co 80/10/28 2pp
06913 026

--8011050425 "Environ Qualification of Safety-Related Electrical Equipment "
* Jersey Central Power & Light Co 80/10/31 500pp 06913 028.

8011030527 Responds to NRC 801001 ltr re BWR scram sys. Reassessment of sys indicates that util complies w/applicable General Design Criteria (App A to 10CFR30) Results of sys re-evaluation, mods & implementation schedule will be submitted by 801215.
FINFROCK,I R Jersey Central Power & Light Co 80/10/30 1p
06855.086

8011030562 Submits quantitative evaluation of effect of cracks in core spray sys piping on water level indication Water level in annulus was lower than core spray vessel nozzle
FINFROCK,I R Jersey Central Power & Light Co 80/10/30 1p
06861 169

8011260304 "Ecological Studies of Wood-Boring Bivalves in Vicinity of Oyster Creek Nuclear Generating Station "
HOAGLAND,K E, CROCKET,L, TURNER,R D Lehigh Univ FIN B-5744
NUREG/CR-1517 80/10/31 67pp Available at NTEB 07073 148.

8011210002 Advises of delay in completion of SEP Topic XVI, Tech Specs, until completion of all SEP topic reviews & integrated safety assessment Delay will allow evaluation of current Tech Specs w/proposed changes resulting from reviews
CRUTCHFIELD,D Operating Reactors Branch 5 80/11/05 2pp.
07033 191

8011210555 Forwards summary of SEP efforts completed & committed to by owners for NRC SEP progress evaluation
SCHAFFSTALL,R SEP Owners Group 80/11/17 5pp.

8011260063 Responds to FOIA request for summaries of nuclear waste shipments from facility Forwards document entitled:
"Shipment of Nuclear Matl from JCP&L, Oyster Creek, During 680101-801103 "
FELTON,J M Division of Rules and Records 80/11/20 1p
07070.355

--8011260067 "Shipment of Nuclear Matl from JCP&L, Oyster Creek, During 680101-801103 "
* Commissioners 80/11/03 5pp.

DOCKETED ITEMS

Q Inspection reports, IE Bulletins & correspondence

8011030067 Immediate Action Ltr 80-36 confirms until 800929 & 1001 telcon commitments re 800827 & 0929 spillage of radioactive water from temporary chemical waste mineralizer Evaluation will be made to determine continued need for mineralizer
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/02 1p 06855 124

8011200120 Forwards IE Mgt Meeting Rept 80-219/80-31 on 800925
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/08 1p 07022 182

--8011200131 IE Mgt Meeting Rept 80-219/80-31 of 800925 meeting to discuss appraisal board evaluation of facility performance Aug 1979-Jul 1980 Performance evaluation & action plan encl
BRIGGS, L E, THOMAS, J A Region 1, Philadelphia, Office of the Director
KEIMIG, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
80/10/06 5pp 07022 183

8011170763 Resubmits 800619 response to IE Bulletin 80-05, "Engineered Safety Feature (ESF) Reset Controls," which was originally submitted w/o notarization
FINFROCK, I R Jersey Central Power & Light Co 80/10/15 1p 06973 339

8011170932 Ack receipt of 800915 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-219/80-23
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch
80/10/21 1p 06978 162

--8011170937 Responds to NRC 800820 ltr re violation noted in IE Insp Rept 80-219/80-23 Violation was due to personnel error, not lack of adequate mechanism Present sys considered adequate No changes planned
FINFROCK, I R Jersey Central Power & Light Co 80/09/15 3pp 06978 163

--8011170939 Forwards IE Insp Rept 80-219/80-23 on 800528-0711 & notice of violation
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch
80/08/20 2pp 06978 166

--8011170941 Notice of violation from Insp on 800528-0711
+ Region 1, Philadelphia, Office of the Director 80/08/13 1p 06978 168

--8011170946 IE Insp Rept 80-219/80-23 on 800528-0711 Noncompliance noted lack of adequate mechanism for issuance of mgt instructions required by Tech Spec 3.12 E 2
FLUMLEE, K E, THOMAS, J A Region 1, Philadelphia, Office of the Director
KNAPP, P J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch
80/08/13 11pp 06978 169

8011060629 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06909 297

8011070289 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06921 308

8011140129 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06968 221

8011140591 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06963 149

R Periodic operating reports & related correspondence

8011040460 Forwards "Woodborer Study Associated w/Dyster Creek Station," for 800511-800810
FINFROCK, I R Jersey Central Power & Light Co 80/10/24 2pp 06884 199

--8011040468 "Woodborer Study Associated w/Dyster Creek Generating Station," for 800511-800810
MACIOLEK, N J, BELMORE, C I, HILLMAN, R E Battelle Memorial Institute, Columbus Laboratories. 80/09/15 23pp 06884 201

8011250210 Forwards monthly operating rept for Oct 1980
FINFROCK, I R Jersey Central Power & Light Co 80/11/18 1p 07056 282

--8011250214 Monthly operating rept for Oct 1980
SKLAR, J B Jersey Central Power & Light Co 80/11/19 7pp 07056 283

S Reportable occurrences, LERs & related correspondence

8009300132 Nonroutine Environ Operating Rept 80-219/80-08 on 800910, second dilution pump placed into operation w/bridge water temp below ETS requirements Caused by insufficient pump quota Damaged pump removed & repaired
FINFROCK, I R Jersey Central Power & Light Co 80/09/25 3pp 06831 008

8011040425 Forwards LER 80-044/03L-0
FINFROCK, I R Jersey Central Power & Light Co 80/10/29 3pp 06873 278

--8011040432 LER 80-044/03L-0 on 800930, motor leads in core spray booster pumps A & C became wet when fire protection sys initiated inadvertently Caused by personnel error Pumps dried, inspected & returned to svc
CROSBY, P J Jersey Central Power & Light Co 80/10/29 1p 06873 281

801110247 Forwards nonroutine environ operating rept 80-219/80-9
FINFROCK, I R Jersey Central Power & Light Co 80/11/03 1p 06943 128

--801110267 RO 80-219/80-9 on 801026 intake trash racks, ristroph traveling screens, turbine bldg closed cooling water heat exchangers & main condensers were fouled w/seaweed & approx 10,000 blue crabs due to intense 801025 Northeast storm
* Jersey Central Power & Light Co 80/11/03 2pp 06943 129

8011170559 Nonroutine Environ Operating Rept 80-219/80-9 on 801026, intake trash racks, ristroph traveling screens, turbine bldg closed cooling water heat exchangers & main condensers were fouled w/seaweed & blue crabs Caused by 801025 storm
FINFROCK, I R Jersey Central Power & Light Co 80/11/03 3pp 06981 233

801120516 RO 80-49/1P on 801105, while removing isolation condenser B from svc to repair steam leak on vent isolation valve V-14-15, isolation valves V-14-1 & V-14-19 for condenser failed to close Cause still under investigation
* Jersey Central Power & Light Co 80/11/05 2pp 06916 001

8011140100 RO 80-219/80-49/1P on 801105, while removing isolation condenser B from svc to repair leak on isolation valve V-14-19, valves V-14-1 & V-14-19 failed to close Cause undetermined
CARROLL, J T Jersey Central Power & Light Co 80/11/06 3pp 06965 002

8011180636 Forwards LER 80-046/03L-0
FINFROCK, I R Jersey Central Power & Light Co 80/11/11 4pp 06992 106

--8011180645 LER 80-046/03L-0 on 801017, during testing of SOTS 2 HEPA Filters, pressure drop across upstream filter exceeded Tech Spec limit Caused by incorrect replacement of HEPA filters
Filters replaced w/correct models
GASBARRO, D P Jersey Central Power & Light Co 80/11/11 1p 06992 110

8011250500 Forwards LER 80-048/03L-0
FINFROCK, I R Jersey Central Power & Light Co 80/11/18 3pp 07068 260

--8011250510 LER 80-048/03L-0 on 801029, during functional testing, snubber 23-7 failed to lock up in tension direction Cause unknown
Snubber replaced
FITZGERALD, M. Jersey Central Power & Light Co 80/11/18 1p 07068 263

8011250524 Forwards LER 80-049/01T-0
FINFROCK, I R Jersey Central Power & Light Co 80/11/19 3pp 07068 264

--8011250534 LER 80-049/01T-0 on 801103, when isolation condenser B was removed from svc to repair steam leak, vent isolation valves V-14-1 & V-14-19 apparently failed to close Cause undetermined Stem packing replaced & tested
CROSBY, P J Jersey Central Power & Light Co 80/11/20 1p 07068 267

DOCKETED ITEMS

25

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

BO11170021 Forwards facility emergency planning info for placement in LPDR w/o encl
SQUIDER, J L Division of Rules and Records 80/11/04 1p
06978 268

G Adjudicatory correspondence

BO11040346 Denies until 800630 petition to amend 800221 confirmatory order re plant operation w/o ATWS reactor pump trip
DENTON, H R Office of Nuclear Reactor Regulation, Director
80/10/06 5pp 06874 199

BO11070384 Forwards order for mod of License DPR-63 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp
06925 095

--BO11070385 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06925 097

--BO11070388 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06925 102

H General correspondence

BO11040408 Requests FI Bialik name be added to svc lists for all matters re facilities, BNL & transport of nuclear mats in NY.
BIALIK, E I New York, State of 80/10/31 1p 02319 196

BO11180150 Addl response to FOIA request for four categories of info re Crystal River 3 & info re six facilities NRC has no analyses subj to Paragraph 5 request
FELTON, J M Division of Rules and Records 80/11/07 1p
06987 291

J Insurance & indemnity information

BO11030438 Forwards until 790307 ltr forwarding Endorsements 32 & 33 to MAELU Policy MF-77 & Endorsements 38-40 to NCLIA Policy NF-208, in response to 800924 request.
DEEO, F H Power Authority of the State of New York 80/10/31 1p
06894 105

P Operating license stage documents & correspondence

7903120459 Summary of 790213 meeting in Bethesda, MD w/representatives of Mark I owner's group program committee to discuss generic Mark I program re safety relief valve loads w/encl attendees list & meeting handouts
SU, T H Containment Systems Branch (Pre 790101), 79/03/01 16pp
03319, 001

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition
GRIMES, C I Assistant Director for Engineers & Projects (Pre 790625) 79/03/02 2pp, 03143 305

BO11050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing, 80/09/05 209pp

BO11100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp

BO11190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance info should be submitted within 25 days
EISENHUT, D G Division of Licensing 80/10/01, 2pp

BO11040346 Denies until 800630 petition to amend 800221 confirmatory order re plant operation w/o ATWS reactor pump trip
DENTON, H R Office of Nuclear Reactor Regulation, Director
80/10/06 5pp 06874 199

BO11100937 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

BO10290008 Requests Commission approval of encl clarification & changes to 800905 ltr & encl setting forth complete listing of TMI-related requirements approved for implementation Ltr & encl will be published as NUREG-0737 upon approval
DENTON, H R Office of Nuclear Reactor Regulation, Director
80/10/22 10pp 06827 001

--BO10290010 Responds to 800905 request for outline of program to justify/revise until small break LOCA analysis methods Plant specific calculations will be reviewed & reanalysis performed if generic revisions to OE model are necessary
DISE, D P Niagara Mohawk Power Corp 80/10/01 1p 06827 326

BO11070384 Forwards order for mod of License DPR-63 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24, 2pp, 06925 095

--BO11070385 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06925 097

--BO11070388 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 2pp 06925 102

BO11030477 Forwards application for amend of License DPR-63, revising App A Tech Specs & Section 3 4 1 to allow work necessary to upgrade several safety-related sys Class III fee encl
THOMAS, E B LeBoeuf, Lamb, Leiby & MacRae, 80/10/29 2pp
06860 166

--BO11030481 Application for amend of License DPR-63, revising App A Tech Specs & Section 3 4 1 to allow work necessary to upgrade several safety-related sys
DISE, D P Niagara Mohawk Power Corp 80/10/29 2pp, 06860 168

--BO11030485 Proposed changes to App A Tech Specs & revisions to Section 3 4 1 re bases & limiting conditions for operation & leakage rate, respectively Supporting info & amend classification encl.
* Niagara Mohawk Power Corp 80/10/29, 5pp, 06860 170

BO11180459 Adds containment atmospheric dilution & monitoring sys to plant leakage reduction program per NUREG-0578.
Recommendation 2 1 6 a once every cycle Sys will undergo leak test using helium tracer
LEMPGES, T E Niagara Mohawk Power Corp 80/11/07 1p 06988 167

BO11180637 Responds to TMI Action Plan Item II K 3 29 Mod to emergency condenser vent sys will be performed during Spring 1981 refueling outage Mod will provide capability to vent emergency condensers under accident conditions
RHODE, G K Niagara Mohawk Power Corp 80/11/07 1p 06992 105.

G Inspection reports, IE Bulletins & correspondence

BO11130143 Forwards IE Insp Rept 50-220/80-07 on 800625-0815 No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 80/09/15 2pp 06958 241

--BO11130152 IE Insp Rept 50-220/80-07 on 800625-0815, No noncompliance noted Major areas inspected licensee action on previous insp findings, operational safety Verification & response to IE Bulletin 80-17.
BAUNACK, W, HUDSON, S, Region 1, Philadelphia, Office of the Director KISTER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/11 12pp, 06958 243

BO11070074 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/30, 1p 06920 043.

DOCKETED ITEMS

8011280171 Forwards IE Insp Rept 30-220/80-09 on 800908-11 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/01 2pp 07082 345

--8011280176 IE Insp Rept 30-220/80-09 on 800908-11 No noncompliance noted Major areas inspected torus mod activities including review of procedures, records & observations of work in progress.
MCBREARY, R A Region 1, Philadelphia, Office of the Director
TRIPP, L E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/01 5pp 07082 347

8011200103 Immediate Action Ltr 80-38 confirms 801009 discussion & 801010 telcon re findings of NRC health physics appraisal team indicating need for improvement of radiation protection program Lists actions to be initiated
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/10 2pp 07022 104

8011200097 Immediate Action Ltr 80-40 confirms 801017 telcon re util actions to complete requirements in NUREG-0578 as detailed in NRC 800102 show cause order Actions will be initiated to complete Category A, Item 2 1 B b by 801020
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/17 2pp 07022 102

8011060672 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06914 316

8011070335 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06922 037

8011140078 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06968 261

8011140580 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06963 141

R Periodic operating reports & related correspondence

8011140332 Forwards monthly operating rept for Oct 1980
LEMPGEB, T E Niagara Mohawk Power Corp 80/11/05 1p 06968 194

--8011140335 Monthly operating rept for Oct 1980
ROMAN, T W Niagara Mohawk Power Corp 80/11/04 4pp 06968 195

S. Reportable occurrences, LERs & related correspondence

8011070380 Forwards LER 80-024/03L-0
LEMPGEB, T E Niagara Mohawk Power Corp 80/10/30 1p 06925 089

--8011070381 LER 80-024/03L-0 on 800930, during audit, discovered that point valve was not recorded on 790721 instrument surveillance test for drywell high pressure trip sys Caused by personnel oversight Two-level review instituted
HARRISON, P Niagara Mohawk Power Corp 80/10/30 2pp 06925 090

V Operator Examinations

8011050448 Responds to NRC 800731 ltr requesting schedule & commitments for compliance w/interim criteria for shift staffing Upgrade training program for reactor operators will begin by Jan 1981. Tech Spec changes will be submitted by Jan 1982
LEMPGEB, T E Niagara Mohawk Power Corp 80/10/31 1p 06893 361

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8011190349 Supplements 791022 ltr re safe shutdown capability Staff has utilized BNL to review 780603 rept & supplement Requests submission of proposed plans & schedules by 801101
EISENHUT, D O Division of Licensing 80/10/01 3pp 06976 186

8011170336 Forwards comments on revised emergency plan per requirements of NUREG-0654 Plan should be revised to address comments
EISENHUT, D O Division of Licensing 80/10/02 5pp 06976 264

8011170573 Forwards position on mods required by licensee to comply w/proposed rule re min acceptable fire protection criteria Outstanding areas include smoke detection sys test & water suppression sys
IPPOLITO, T A Operating Reactors Branch 2 80/10/27 6pp 06979 202

8011190191 Informs of DOJ decision not to prosecute guard contractor for improprieties re firearms qualification & documentation of patrols Decision based on prompt identification, notification & resolution of matter w/related ltrs
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28 6pp 06979 228

8011110486 Responds to NRC 801001 ltr re fire protection safe shutdown analysis plans Util evaluation of BNL 800709 review has found current & ongoing fire protection installations sufficient to assure safe shutdown capability Review encl
JANECEK, R F Commonwealth Edison Co 80/10/31 5pp 06944 330

8011050428 Forwards draft public info package re emergency preparedness for facilities Package has been distributed to States of IL, IA & WI for comment Requests NRC comment by 801121
DELGRORE, L O Commonwealth Edison Co 80/11/03 8pp 06894:107.

G Adjudicatory correspondence

8011070283 Revised 800829 order for mod of license Corrects refs
EISENHUT, D O Division of Licensing 80/09/19 6pp 06925 018

8011240037 Forwards order for mod of License DPR-19 re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp 07049 317

--8011240042 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 07049 320

--8011240045 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 07049 326

8011050216 Forwards revised pages, Revision 3, to 780203 rept forming part of application Reduces number of storage spaces & accounts for unanticipated cumulative effect re rack pitch tolerance Util will discuss changes at evidentiary hearing
STEPTOE, P P Isham, Lincoln & Beale 80/10/29 17pp 06898 301

8011040417 Submits listing of addl documents produced per informal discovery agreement
FITZIBBONS, R Isham, Lincoln & Beale 80/10/30 2pp 06873:342.

8011050290 Notices of appearances in spent fuel pool mod proceeding. Svc list encl
FITZIBBONS, R, STAHL, D M Commonwealth Edison Co FITZIBBONS, R Isham, Lincoln & Beale 80/10/30 4pp 06899 070

8011040430 Response to ASLB 801014 order re intention to pursue application Safety evaluation & EIA or EIS will be published in May 1981 Certificate of Svc encl
GODDARD, R J Hearing Branch 2 80/10/31 2pp 06873 282

8011060381 Responds to ASLB 801014 order Util intends to pursue spent fuel transshipment application, although classified as second in priority to pending spent fuel rack replacement requests Urges that ASLB jurisdiction be retained
STEPTOE, P P Isham, Lincoln & Beale 80/10/31 3pp 06914 135.

8011060453 Withdraws util 801023 request for hearing in view of info presented in Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment "
STEPTOE, P P Isham, Lincoln & Beale 80/10/31 1p 06916 205

8011040419 Forwards IE repts in response to 801016 request for documents, Paragraph 4 w/o encls
GODDARD, R J Hearing Branch 2 80/11/03 1p 06873 272

BO11060201 Notice of appearance in proceeding re proposed amend to OLS increasing spent fuel storage capacity Certificate of Svc encl
VAN VRANKEN, J Illinois, State of 80/11/03 5pp 06912 087

BO11060472 Forwards Brooks & Perkins internal audits Signature denoting documents as proprietary requested W/o encl Related correspondence
FITZGIBBONS, R Isham, Lincoln & Beale 80/11/03 1p 06914 141

BO11170222 Forwards NFB Document D0001685 re fuel assembly clearances in high density spent fuel storage racks W/o encl Related correspondence
FITZGIBBONS, R Isham, Lincoln & Beale, 80/11/07 1p. 06981 357

BO11180129 Submits order of presentation of evidence per parties' agreement sub; to ASLB approval Safety evaluation, EIA & OA will be presented on 801119, contentions re corrosion & radiological protection on 801120 & re accidents on 801121
STEPTOE, P P, Isham, Lincoln & Beale 80/11/12 2pp 06987.194

BO11210513 Forwards Comm Ed OA dept surveillance repts re NRC & Lecklenby documents D0001694-D0001695 W/o encl
FITZGIBBONS, R, Isham, Lincoln & Beale, 80/11/18, 1p. 02227.001

H General correspondence

BO11180075 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J. O. Region 3, Chicago, Office of the Director, 80/11/04 1p. 06984 200

BO11180086 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/04, 1p 06987:322

BO11180111 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/04, 1p. 06987:329

BO11180115 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities. Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J. O. Region 3, Chicago, Office of the Director, 80/11/04 1p. 06987:331.

BO11180120 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/04 1p 06987:332

BO11180124 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/04, 1p. 06987:334

BO11180127 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J. O. Region 3, Chicago, Office of the Director, 80/11/04, 1p 06987:335.

BO11180132 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities. Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J. O. Region 3, Chicago, Office of the Director, 80/11/04, 1p 06987:337

BO11180134 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J. O. Region 3, Chicago, Office of the Director, 80/11/04 1p 06987:336

BO11180137 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J. O. Region 3, Chicago, Office of the Director, 80/11/04, 1p 06987:338

BO11180141 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/04 1p 06987:339

BO11180143 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/04 1p 06987:340.

BO11180146 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J. O. Region 3, Chicago, Office of the Director, 80/11/04 1p 06987:341

BO11180175 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J. O. Region 3, Chicago, Office of the Director, 80/11/04 1p 06987:295

BO11180187 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/04, 1p 06987:296

P Operating license stage documents & correspondence

8008270372 Advises that final part of NEDO-2188B, "Mark I Containment Program Load Definition Rept" was transmitted to NRC by LJ Bobon 790315 ltr Rept provides info re hydrodynamic loads produced on containment sys during LOCA
JANECEK, R F Commonwealth Edison Co, 80/08/18 1p. 06429 249.

8008270375 Advises that NEDO-2188B, "Mark I Containment Program Load Definition Rept" was transmitted to NRC by LJ Bobon 781228 ltr. Rept provides info re hydrodynamic loads on containment sys during postulated LOCA
JANECEK, R F Commonwealth Edison Co, 80/08/19 1p 06429 250.

8009180252 Forwards NUREG-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7" Rept discusses generic suppression pool hydrodynamic load definition W/o encl.
IPPOLITO, T A Operating Reactors Branch 2 80/08/20, 2pp 06572:312

BO11030354 Ltr to all licensees of operating plants, applicants for OLS & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

BO11100486 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by BO1101
EISENHUT, D O Division of Licensing, 80/10/01 5pp.

BO11190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin BO-17 required mods to assure adequate short-term performance Info should be submitted within 25 days.
EISENHUT, D O Division of Licensing, 80/10/01, 2pp.

BO11030437 Comments on SEP Topic III-10 A re thermal overload protection for motor operated valves. Elimination of overload protection could lead to long-term valve & motor damage during testing.
JANECEK, R F. Commonwealth Edison Co, 80/10/06 1p 06867:343

BO11030507 Discusses NRC evaluation of SEP Topic VIII-3.8 re dc power sys bus voltage monitoring & annunciation Facility complies w/intent of IEEE 308-1974 & Reg Guide 1.47. Design provides sufficient info to control room to alert operator
JANECEK, R F. Commonwealth Edison Co 80/10/06, 1p 01756:001.

DOCKETED ITEMS

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issues A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" H/O encl EISENHUT, D.O. Division of Licensing 80/10/06 4pp.

8011050045 Forwards survey status rept re loss of offsite power in connection w/SEP Topics VI-7 C 1, VII-6, VIII-1, VIII-2 & VIII-3 for review & comment Response due in 60 days. CRUTCHFIELD, D. Operating Reactors Branch 3 80/10/10. 42pp 02319:196

8011240037 Forwards order for mod of License DPR-19 re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl CRUTCHFIELD, D. Operating Reactors Branch 3 80/10/24. 3pp. 07049:317

--8011240042 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines on NUREG-0588 required by 802630. Complete records must be available by 801201. EISENHUT, D.O. Division of Licensing 80/10/24. 4pp 07049:320.

--8011240045 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment. * Division of Licensing. 80/10/24. 2pp 07049:326.

8011030577 Submits info re reassessment of scram sys in response to NRC 801001 ltr Results of re-evaluation & schedule of implementation will be provided by 801215 JANECEK, R.F. Commonwealth Edison Co 80/10/27 2pp 06855:081

801120552 Forwards Revision 3 to Nuclear Svcs Corp Oct 1980 "Licensing Rept, Dresden Nuclear Power Plant Units 2 & 3, Spent Fuel Rack Mod," re 780511 proposed amend to Licenses DPR-19 & DPR-23 JANECEK, R.F. Commonwealth Edison Co 80/10/29 2pp 06952:130

--801120560 "Licensing Rept, Dresden Nuclear Power Plant Units 2 & 3, Spent Fuel Rack Mod," Revision 3 HINES, D.P., MCCOY, J.J. Nuclear Services Corp QUAD-1-79-234 R3 80/10/29 16pp 06952:132.

8011040197 Forwards Revision 1, Vol 1 & Revision 2, Vols 2 & 3 of "Environ Qualification of Electrical Equipment," in response to NRC 800919 revised order for mod of license IE Bulletin 79-018, Suppl 2 info provided for evaluation of SEP response. ABEL, J.B. Commonwealth Edison Co 80/10/30 3pp 06885:091

--8011040203 Revision 1, Vol 1, "Environ Qualification of Electrical Equipment" * Bechtel Power Corp. (subs of Bechtel Corp.) 80/11/01. 77pp 06885:094

--8011040209 Revision 2, Vol 2, "Environ Qualification of Electrical Equipment." * Bechtel Power Corp. (subs of Bechtel Corp.) 80/11/01 200pp. 06885:170.

--8011040215 Revision 2, Vol 3, "Environ Qualification of Electrical Equipment" * Bechtel Power Corp. (subs of Bechtel Corp.). 80/11/01. 200pp 06885:044

8011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201. ABEL, J.B. Commonwealth Edison Co 80/10/31 1p 06874:174

8011060491 Provides addl info for review of new OE analysis of small steam line break inside containment, as discussed in 801030 ltr. ABEL, J.B. Commonwealth Edison Co 80/11/03 36pp 02319:196

8011090347 Forwards supplemental info re environ qualification of Class IE electrical equipment, in response to NRC 800919 revised order for mod of license ABEL, J.B. Commonwealth Edison Co 80/11/03 36pp 06916:001.

801100389 Forwards Page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments. TRAMM, T.R. Commonwealth Edison Co 80/11/03 2pp 06930:337.

801180419 Clarifies 800511 proposed fuel pool mode Rack replacement will be performed only w/125 ton redundant hook of reactor ydg crane. Fuel movements will be made w/existing fuel rapelle normally used during routine refueling outages. JANECEK, R.F. Commonwealth Edison Co 80/11/13 1p. 06989:091.

8011240374 Application to amend License DPR-29, changing Tech Specs for extended burnup fuel program Class III amend fee encl JANECEK, R.F. Commonwealth Edison Co 80/11/13. 2pp 07046:347

--8011240393 Revised Page 4-8 to "LOCA Analysis Rept" Supplemental discussion of NEDO-24855 encl * General Electric Co. NEDO-24146A 80/11/13 2pp. 07047:010.

8011210555 Forwards summary of SEP efforts completed & committed to by owners for NRC SEP progress evaluation SCHAFFSTALL, R. SEP Owners Group 80/11/17. 5pp. 07035:028

2. Inspection reports, IE Bulletins & correspondence

8011060575 Submits addl response to IE Insp Rept 80-249/80-09. Comparison of control rod designs at facilities scheduled for next outage if irreconcilable differences exist, seismic reanalysis of piping will be considered. ABEL, J.B. Commonwealth Edison Co 80/08/18. 1p. 06914:147.

8011190515 Forwards IE Insp Repts 80-010/80-14, 80-237/80-17 & 80-249/80-21 on 800803-0906 & notice of violation HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/10/08. 2pp 06978:120

--8011190518 Notice of violation from insp on 800803-0906. * Region 3, Chicago, Office of the Director 80/09/29 1p. 06978:122

--8011190526 IE Insp Repts 80-010/80-14, 80-237/80-17 & 80-249/80-21 on 800803-0906 Noncompliance noted personnel failed to follow radiation protection procedures BARKER, J.L., TONGUE, T.M., REIMANN, F.W. Region 3, Chicago, Office of the Director 80/09/29 7pp 06978:123

801110027 Forwards IE Insp Repts 80-010/80-15, 80-237/80-18 & 80-249/80-22 on 800905-17 No noncompliance noted HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/17 2pp 06943:232

--801110034 IE Insp Repts 80-010/80-15, 80-237/80-18 & 80-249/80-22 on 800905-17 No noncompliance noted Major areas inspected circumstances re allegations that radioactive water released to environ over period of one to two months REIMANN, F.W., TONGUE, T., JANUSKA, A. Region 3, Chicago, Office of the Director 80/10/14 9pp 06943:254

8011060793 Discusses IE insp on 800908-10 & forwards notice of violation & notice of proposed imposition of civil penalty STELLO, V. Office of Inspection & Enforcement, Office of the Director 80/10/20 3pp 06909:103

--8011060797 Notice of proposed imposition of civil penalty in amount of \$40,000 for item of noncompliance noted in IE insp on 800908-10 STELLO, V. Office of Inspection & Enforcement, Office of the Director 80/10/20 2pp 06909:106

8011060172 Confirms 801031 meeting w/RL Spessard in Chicago, IL to discuss regulatory performance KEPLER, J.O. Region 3, Chicago, Office of the Director 80/10/21 3pp 06915:327

801120415 Forwards monthly status rept re evaluations performed at facilities in response to IE Bulletin 79-14 H/O encl JANECEK, R.F. Commonwealth Edison Co 80/10/21 2pp 06933:361

8011070285 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required KEPLER, J.O. Region 3, Chicago, Office of the Director. 80/10/24 1p. 06921:300

8011190040 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc Badge examples encl. KEPLER, J.O. Region 3, Chicago, Office of the Director 80/10/28. 3pp. 06999:180

8011170249 Forwards four isometric drawings which were omitted from Oct 1980 status rept re IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" JANECEK, R.F. Commonwealth Edison Co 80/10/29. 5pp 06915:001

8011040197 Forwards Revision 1, Vol 1 & Revision 2, Vols 2 & 3 of "Environ Qualification of Electrical Equipment," in response to NRC 800919 revised order for mod of license IE Bulletin 79-018, Suppl 2 info provided for evaluation of SEP response ABEL, J.B. Commonwealth Edison Co 80/10/30 3pp 06885:091.

--8011040203 Revision 1, Vol 1: "Environ Qualification of Electrical Equipment,"
* Bechtel Power Corp. (subs. of Bechtel Corp.) 80/11/01 77pp.
06885:094

--8011040209 Revision 2, Vol 2: "Environ Qualification of Electrical Equipment"
* Bechtel Power Corp. (subs. of Bechtel Corp.) 80/11/01. 200pp
06885:170

--8011040215 Revision 2, Vol 3: "Environ Qualification of Electrical Equipment."
* Bechtel Power Corp. (subs. of Bechtel Corp.) 80/11/01 200pp.
06886:044.

8011200839 Forwards IE Mgt Meeting Repts 80-010/80-20, 80-237/80-22, 80-249/80-26, 80-254/80-26, 80-265/80-27, 80-295/80-21 & 80-304/80-23 on 801031 No noncompliance noted
KEPLER, J.O. Region 3, Chicago, Office of the Director 80/11/06. 2pp. 07020:167.

--8011200544 IE Mgt Meeting Repts 80-010/80-20, 80-237/80-22, 80-249/80-26, 80-254/80-26, 80-265/80-27, 80-295/80-21 & 80-304/80-23 on 801031 No noncompliance noted Major areas discussed: performance of activities
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/06 24pp 07020:169

8011250496 Forwards response to IE Bulletin 80-11, "Masonry Wall Design." Operability assessment performed on walls classified as safety-related but failed to meet acceptance criteria Safe shutdown capability not jeopardized
ABEL, J.B. Commonwealth Edison Co. 80/11/06 23pp 07056:050

8011200472 Grants extension until 801124 to respond to NRC 801020 ltr
BYELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/11/14 1p 07020:136

R Periodic operating reports & related correspondence

8011180447 Forwards monthly operating repts for Oct 1980
SCOTT, D J Commonwealth Edison Co. 80/11/12 1p 06989:208

--8011180453 Monthly operating repts for Oct 1980.
CIESZKIEWICZ, S. Commonwealth Edison Co 80/11/01 15pp
06989:209

8011250475 Forwards suggested changes to & verification of radioactive effluents from facility Encl available in Central Files only.
SCOTT, D J. Commonwealth Edison Co. 80/11/18 1p 07175:319.

B Reportable occurrences, LERs & related correspondence

8011030394 Forwards LER 80-038/03L-0
SCOTT, D J Commonwealth Edison Co 80/10/22 1p 06861:193

--8011030605 LER 80-038/03L-0 on 801011, during normal unit startup, while testing control rod driveline C-11 for overtravel, overtravel alarm came up & rod position indication was lost Probably caused by inner filter becoming detached
HOLLAND, P. Commonwealth Edison Co 80/10/21 1p. 06861:194.

8011030632 Forwards LER 80-040/03L-0
SCOTT, D J Commonwealth Edison Co 80/10/22 1p. 06861:195

--8011030640 LER 80-040/03L-0, on 801012, during normal unit startup, while control rod driveline C-8 was tested for overtravel, overtravel alarm came up & rod position indication was lost. Possibly caused by detachment of inner filter
HOLLAND, P Commonwealth Edison Co. 80/10/22 1p 06861:196

8011030629 Part 21 rept re failure of condition containment atmosphere monitoring sys, reported on 801023 Sensors fail to provide accurate hydrogen concentration measurements following LQCA. Analysis of defect re BWRs encl
SHERWOOD, G.O. General Electric Co 80/10/24 11pp 06860:148.

8011140005 Forwards LER 80-035/03L-0
SCOTT, D J Commonwealth Edison Co 80/11/03 1p. 06961:302

--8011140008 LER 80-035/03L-0 on 801009, standby gas treatment sys B tripped after auto start Caused by low sys flow. Flow control unit removed & checked for proper operation, then reinstalled & successfully operated
MAGROW, R Commonwealth Edison Co 80/10/29 1p. 06961:303

8011180600 Forwards LER 80-041/03L-0
SCOTT, D J Commonwealth Edison Co 80/11/12 1p 06988:266.

--8011180607 LER 80-041/03L-0 on 801016, during surveillance check, found refueling floor ARM CL A tripped at 109 mR Caused by instrument drift. Set point adjusted
RHEE, S J Commonwealth Edison Co 80/11/14 1p 06988:267.

8011250529 Forwards LER 80-042/03L-0
SCOTT, D J. Commonwealth Edison Co. 80/11/12 1p. 07058:353.

--8011250539 LER 80-042/03L-0: on 801102, during review of operator logs, ultrasonic testing of steam discharge val was not performed. Caused by personnel error. Memo issued to require contact w/individual if test not reported
ROMLEY, E.J. Commonwealth Edison Co 80/11/14. 1p. 07058:354

T Hearing transcripts on non-antitrust matters

8011070182 Forwards NRC supplemental testimony, safety evaluation & EIS. Changes in proposed spent fuel pool mod considered insignificant. Certificate of Bvc encl
GODDARD, R.J. Hearing Branch 2 80/11/04 2pp 06920:306

--8011070190 Supplemental testimony in response to ABLB Question 1: addressing current status of spent fuel unfilled storage capacity, normal refueling discharge & reactor shutdown alternatives per NUREG-0575. W/prof qualifications
O'CONNOR, P W Operating Reactors Branch 5. 80/11/04 7pp
06920:307

--8011070199 Supplemental testimony in response to Contention 1. Increase in radionuclide concentrations due to expansion would be relatively minor & can be adequately processed by present cleanup sys Prof qualifications encl
MALAFEEV, V. Effluent Treatment Systems Branch 80/11/04 4pp.
06920:314

--8011070204 Supplemental testimony on Contentions 2 & 3 Topical Rept CE-1-A commits util to QA program for activities affecting safety-related items during maint, mod & operation W/exhibits & prof qualifications
BELKE, W.L. Quality Assurance Branch. 80/11/04 24pp. 06920:318

--8011070209 Supplemental testimony on Contentions 4 & 5 Spent fuel pool radiation monitoring adequate to detect normal & abnormal radioactive releases from increased spent fuel bundles. Prof qualifications encl
BLOCK, S Division of Systems Integration 80/11/04 8pp
06920:342

--8011070214 Supplemental testimony on Contention 6. Use of improved 8x8 fuel will reduce noble gas release from stored spent fuel Thus far, no evidence of failures leading to leakage Prof qualifications encl
WUHL, M.L. Accident Evaluation Branch 80/11/04 3pp 06920:350.

--8011070219 Supplemental testimony on Contentions 7 & 8. Establishment of criteria for acceptable amount of corrosion on dimensional changes & strength tolerance is premature Design sufficiently conservative Prof qualifications encl.
WEERS, J R. Brookhaven National Laboratory 80/11/04. 6pp
06920:355

--8011070225 Affidavit re review of 801029 Revision 3 to licensing rept on spent fuel rack mod No revision to safety evaluation needed re criticality considerations Prof qualifications encl.
BROOKS, W.L. Core Performance Branch. 80/11/03 3pp. 06920:362.

8011100630 Forwards util testimony re spent fuel pool mod. Refs in TA Pickens testimony will be offered into evidence as exhibits
STEPHENS, P Isham, Lincoln & Seale 80/11/04 1p 06941:222

--8011100631 Testimony on Contention 1 re radwaste treatment sys for spent fuel pools & Contention 4 re radiation monitoring of spent fuel pool. Waste disposal & monitoring sys adequate for increased storage. Alarm sys satisfactory
ADAM, D. Commonwealth Edison Co. 80/11/04 16pp. 06941:223.

--8011100634 Fuel Procedure DFP 800-20, "Operation of Whiting Redundant Crans Sys," Revision 2
* Commonwealth Edison Co 76/05/31. 10pp. 06941:239

DOCKETED ITEMS

--801100635 Emergency Plan Implementation Procedure EPIP 200-12, "Area High Radiation"
* Commonwealth Edison Co 80/07/31 3pp 06941 249

--801100638 Emergency Plan Implementation Procedure EPIP 200-13, "High Airborne Activity"
* Commonwealth Edison Co 80/07/31 2pp 06941 252

--801100640 Testimony on Contention 7 re corrosion & related reactions of stainless steel boral storage rack tubes Replies to State of IL second amended contentions re ASLB 800909 memorandum & order. Prof qualifications encl
DRALEY, J E Commonwealth Edison Co 80/11/04 26pp 06941 254

--801100642 "Neutron Absorber Sampling Plan - in Pool" Ref A
* Commonwealth Edison Co 80/11/04 4pp 06941 283

--801100646 Testimony on Contention 8 re criteria to prohibit use of spent fuel storage racks Proposed surveillance program assures safe operation of racks. Prof qualifications encl
QILBERT, J D Commonwealth Edison Co 80/11/04 7pp 06941 287

--801100650 Testimony on Contention 2 re QA for spent fuel storage racks, Contention 3 re prevention & protection against damage in transportation & Contention 4 re impact of increased fuel storage capacity FSAR Sections 4 & 14 & PES Section 7 encl
PICKENS, T A Commonwealth Edison Co 80/11/04 60pp 06941 294

--801100652 Testimony on Contention 3 re prevention & protection against transportation damage & Contention 5 re workers' health & safety in spent fuel pool area Discusses receipt of new high density spent fuel racks
RAQAN, R Commonwealth Edison Co 80/11/04 13pp 06941 334

--801100656 Radiation Procedure DRP 37-1-B-1, "Control of Personnel External Exposures to Radiation" Util response to Question 1, Round 1 encl
* Commonwealth Edison Co 74/03/31 7pp 06942 005

--801100661 Deviation rept D-12-3-79-52 on 791025, fuel pool overflowed into vent ducts carrying contaminated water to all floors on Elevation 613-ft Caused by inadvertent opening of condensate fill valve Valve immediately closed
WRIGHT, M Commonwealth Edison Co, 79/10/29 5pp 06942 012

--801100667 Testimony on Contention 2 re QA assurance for spent fuel storage racks & Contention 3 re prevention & protection against transportation damage
SHEWSKI, W J Commonwealth Edison Co 80/11/04 14pp 06942 017

801180076 Forwards NRC supplemental testimony of ML Wahl reflecting changes to Pages 2 & 3 of testimony served on 801104 Basic conclusions not altered
QUDDARD, R J Hearing Branch 2 80/11/14 1p 06985 097

--801180083 Supplemental testimony on Contention 4 re control rod drop, refueling accident, main steam line break outside drywell & loss of coolant inside drywell Use of improved Bx8 fuel will reduce noble gas release from stored fuel Resume encl
WQHLM, M L Accident Evaluation Branch 80/11/14 5pp 06985 098

V Operator Examinations

801100481 Forwards response to NRC 800731 ltr transmitting interim criteria for shift staffing & requesting util schedule for compliance Vacancies may create situations requiring overtime in excess of NRC guidelines
JANFCEK, R F Commonwealth Edison Co 80/11/05 5pp 06928 010

801120492 Forwards response to NRC 800731 request for schedule per interim shift staffing requirements
JANECEK, R F Commonwealth Edison Co 80/11/05 5pp 06952 097

DOCKET 50-244 ROBERT EMMET OINNA NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

801140617 Concludes that fire mods are not fully identified based on BNL review of 791228 safe shutdown rept Requests proposed plans & schedules for dedicated shutdown capability by 801101
EISENHUT, D G Division of Licensing 80/09/18 3pp 06911 001.

--801140626 Discusses completed mini-review of util safe shutdown analysis Impossible to confirm safe shutdown during or after fire Suggests NRC require installation of more conservative shutdown sys
HALL, R E Brookhaven National Laboratory 80/06/16 4pp 06911 001

O Adjudicatory correspondence

8011240003 Forwards order for mod of License DPR-1B re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp 07049 295.

--8011240007 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 07049 298

--8011240011 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 07049 304

H General correspondence

8011040384 Informs of changes in organizational structure per FE Drake retirement as board chairman & chief executive officer Corporate organization chart, effective 801001, encl
HAJER, J E Rochester Gas & Electric Corp 80/10/29 2pp 06880 176

8011040408 Requests FI Bialik name be added to svc lists for all matters re facilities, BNL & transport of nuclear mats in NY
BIALIK, E I New York, State of 80/10/31 1p 02319 196

P Operating license stage documents & correspondence

8009030545 Discusses task action plan re asymmetric LOCA loads Specified repts support conclusion that under worst combination of loadings, including SSE effects, realistically postulated flaw will not cause guillotine break
WHITE, L D Rochester Gas & Electric Corp 80/08/27 2pp 06455 055

8009030485 Submits info describing current status & schedules re anchorage & support of safety-related electrical equipment
WHITE, L D Rochester Gas & Electric Corp 80/08/28 2pp 06456 349

8011030354 Ltr to all licensees of operating plants, applicants for OLS & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp

801180008 Advises that SEP Topics II-2 B, II-2 D, III-B, VI-B, XV-11, XV-18, II-1 B & X should be added to 791116 list of topics removed from review due to related generic NRC activities & nonapplicability
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/01 5pp 06986 089.

801100937 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

8011060087 Accepts commitment to 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability" Commitments are to remain in effect pending completion of long-term review
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/08 2pp 06916 155

DOCKETED ITEMS

31

- 8011050014 Forwards draft technical evaluation repts on SEP Topics III-1, VII-2 & VII-3 prepared for LLL by Energy Measurements Group. Requests licensee be informed that NRC will consider any comments received prior to 810123. RUSSELL, W T Systematic Evaluation Program Branch 80/10/10 46pp. 06894 315
- 8011240003 Forwards order for mod of License DPR-18 re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp 07049 295
- 8011240007 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820430 Complete records must be available by 801201 EISENHUT, D Q Division of Licensing 80/10/24 6pp 07049 298
- 8011240011 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment * Division of Licensing 80/10/24 2pp 07049 304
- 8011040237 Forwards "Environ Qualification of Electrical Equipment," Revision 3, in response to 800919 revised order for mod of license MAIER, J E Rochester Gas & Electric Corp 80/10/31 2pp 06878 142
- 8011040240 "Environ Qualification of Electrical Equipment," Revision 3 * Rochester Gas & Electric Corp 80/10/31 79pp 06878 144
- 8011040441 Forwards application for amend of License DPR-18, changing Tech Specs & 2-i Class II fee encl FARON, R B LeBoeuf, Lamb, Leiby & MacRae 80/11/04 2pp 06916 193.
- 8011040447 Application for amend of License DPR-18, changing Tech Specs, Figure & 2-i Certificate of Bvc encl MAIER, J E Rochester Gas & Electric Corp 80/11/04 4pp 06916 197
- 8011040449 Proposed change to Tech Specs Figure & 2-1, revising mgt organization chart * Rochester Gas & Electric Corp 80/11/04 4pp 06916 201
- 801120335 Forwards Revision 1 to design criteria for seismic upgrade program MAIER, J E Rochester Gas & Electric Corp 80/11/04 1p 06951 309
- 801120337 EWR-2512, Revision 1 to design criteria for seismic upgrade program LILLEY, M P, EASTERBROOK, K, HUTTON, J C Rochester Gas & Electric Corp. 80/09/01 39pp 06951 310
- 8011200483 Advises of delay in completion of SEP Topic XVI, Tech Specs, until completion of all SEP topic reviews & integrated safety assessment. Delay will allow evaluation of current Tech Specs w/proposed changes resulting from reviews CRUTCHFIELD, D Operating Reactors Branch 5 80/11/05 2pp. 07018 231
- 801120399 Forwards revised 790702 inservice insp program for 1980-89. Interval Changes permit sleeving, instead of plugging defective steam generator tubes. Change found not to involve unreviewed safety question or require Tech Specs mod MAIER, J E Rochester Gas & Electric Corp 80/11/06 1p 06952 102
- 801120401 Inservice insp program for 1980-89, Revision 4, App B to QA manual HECHREDY, R, ANDERSON, C R, CANTRELL, A Rochester Gas & Electric Corp 80/11/05 21pp 06952 103
- 801140103 Forwards proprietary version of: "Steam Generator Sleeves Development & Test Program" Rept describes test sleeves, verification program & safety analyses. Nonproprietary excerpt & affidavit encl Rept withheld (ref 10CFR2 790) MAIER, J E Rochester Gas & Electric Corp 80/11/06 7pp 06952 308
- 801170196 Forwards application to amend OL, changing App A Tech Specs to incorporate implementation of TMI-2 Lessons Learned Category A Items Certificate of Bvc & Class III fee encl FARON, R B LeBoeuf, Lamb, Leiby & MacRae 80/11/13 4pp. 06969 001
- 8011170200 Application to amend License DPR-18, changing App A Tech Specs Sections 2.0, 3.0, 4.0 & 6.0, to incorporate implementation of TMI-2 Lessons Learned Category A Items, in response to NRC 800702 ltr MAIER, J E Rochester Gas & Electric Corp 80/11/05 2pp 06969 005
- 8011170205 Proposed Tech Specs, Sections 2.0, 3.0, 4.0 & 6.0, to incorporate implementation of TMI-2 Lessons Learned Category A Items Safety evaluation encl * Rochester Gas & Electric Corp 80/11/05 48pp. 06969 007
- 8011180668 Responds to NRC 801031 ltr clarifying TMI-related items approved for implementation. Outline & schedule for model justification for Item II K 3.30 re revised small break LOCA methods was submitted to NRC in Westinghouse 800926 ltr MAIER, J E Rochester Gas & Electric Corp 80/11/13 1p 06991 256
- 8011260236 Reiterates 800425 request for addl info on SEP Topics VI-10 A & VI-7 A. Gre testing of reactor trip sys & engineered safety features & ECCS actuation, respectively. Info required to maintain integrated assessment schedule CRUTCHFIELD, D Operating Reactors Branch 5 80/11/14 2pp 07074 113
- 8011200268 Forwards application for amend to License DPR-18 Certificate of Bvc encl FARON, R B LeBoeuf, Lamb, Leiby & MacRae. 80/11/17 4pp 07021 287
- 8011200274 Application for amend to License DPR-18 consisting of changes to Tech Specs MAIER, J E Rochester Gas & Electric Corp 80/11/12 2pp 07021 291
- 8011200277 Tech Specs table of contents, Page iii.1.0, definitions & 3.0 for limiting conditions of operation * Rochester Gas & Electric Corp 80/11/12 23pp 07021 293
- 8011210555 Forwards summary of SEP efforts completed & committed to by owners for NRC SEP progress evaluation BCHAFFETALL, R SEP Owners Group 80/11/17 5pp.
- G Inspection reports, IE Bulletins & correspondence
- 801110390 Ack receipt of 800430 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-244/80-02. Corrective pages to 800409 ltr & App A clarifying language encl BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/19 3pp. 05944 204
- 801110399 Forwards IE Insp Rept 80-244/80-02 on 800219-22 & notice of violation BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/09 2pp 06944 207
- 801110404 Notice of violation from insp on 800219-22 * Region 1, Philadelphia, Office of the Director 80/03/26 1p 06944 209
- 801110412 IE Insp Rept 80-244/80-02 on 800219-22 Noncompliance noted failure to record required data & acceptance of out-of-tolerance setpoint & inadequate supervisory data review BLUMBERG, N Region 1, Philadelphia, Office of the Director, BAUNACK, W Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/03/26 16pp 06944 210
- 8011060559 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" IEB 79-018 & suppl dtd 800229, not previously transmitted, also encl No written response required GRIER, B H Region 1, Philadelphia, Office of the Director. 80/09/30 1p 06909 293
- 801100360 Ack receipt of 800825 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-244/80-10 MARTIN, W Q Region 1, Philadelphia, Safeguards Branch. 80/10/09 1p 06929 266
- 801100369 Forwards IE Insp Rept 80-244/80-10 on 800706-11 & notice of violation Rept & notice of violation withheld (ref 10CFR2 790) MARTIN, W Q Region 1, Philadelphia, Safeguards Branch 80/08/07 2pp. 06929 267

DOCKETED ITEMS

8011060459 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06914 301

8011070274 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06921 276

8011140119 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06965 361

8011170857 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Hfg by Valcor Engineering Corp " No written response is required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06979 393

8011120399 Forwards revised 790702 inservice insp program for 1980-89 interval changes permit sleeving instead of plugging defective steam generator tubes. Change found not to involve unrevised safety question or require Tech Specs mod.
HAIER, J E Rochester Gas & Electric Corp 80/11/06 1p 06992 102

--8011120401 Inservice insp program for 1980-89, Revision 4, App B to QA manual
MECREDY, R, ANDERSON, C R, CANTRELL, A Rochester Gas & Electric Corp 80/11/05 21pp 06992 103

R Periodic operating reports & related correspondence

8011180590 Forwards monthly operating rpt for Oct 1980
SNOW, B A Rochester Gas & Electric Corp. 80/11/10 1p 06987 357

--8011180596 Monthly operating rpt for Oct 1980.
MCNAMARA, A E Rochester Gas & Electric Corp 80/11/10 4pp 06987 358

S Reportable occurrences, LERs & related correspondence

8011040459 Forwards LER 80-009/03L-0
HAIER, J E Rochester Gas & Electric Corp 80/10/31 1p 06884 226

--8011040466 LER 80-009/03L-0 on 801003, during performance of PT-12 I to verify operability of 1A emergency generator, part from barring device seen to fly out Caused by bearings not designed to withstand operation w/generator running
SPECTOR, S M Rochester Gas & Electric Corp 80/10/31 1p 06884 227

DOCKET 80-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8011180067 Forwards summary of mods to be made at facility to resolve open fire protection items. Proposed plans & schedules for alternate shutdown capability should be provided by 801101
EISENHUT, D O Division of Licensing 80/09/29 6pp 06915 001

8011170007 Forwards facility emergency planning info for placement LPDR W/O encl
BOUDER, J L Division of Rules and Records 80/11/04 1p 06978 265

G Adjudicatory correspondence

8011060124 Forwards revised orders for mod of license re environ qualification of safety-related electrical equipment Hearing date revised accordingly
EISENHUT, D O, Division of Licensing 80/09/19 2pp 06916-002

--8011060139 Revised orders for mod of license correcting refs in 800829 orders.
EISENHUT, D O Division of Licensing 80/09/19 6pp 06916-010

801110669 Forwards order for mod of License DPR-21 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp 06944 318

--801110679 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06944 321

--801110687 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944 327

P Operating license stage documents & correspondence

7910150653 Forwards request for addl info re loss of offsite power & facility offsite grid Requests response within 90 days
ZIEHANN, D L Operating Reactors Branch 2 (Pre 791030) 79/09/29 3pp 01134 339

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

8011180034 Advises that SEP Topics 11-2 B, 11-2 D, 111-B B & VI-B should be added to 791116 list of topics removed from review due to related generic NRC activities & nonapplicability BWR DBE topic list encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/26 3pp 06984 187

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

8011190237 Ltr to all BWR licensees requesting info on plans to assure long-term steam sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance info should be submitted within 25 days
EISENHUT, D O Division of Licensing 80/10/01 2pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports " W/O encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011030692 Forwards Amend 69 to License DPR-21, safety evaluation & notice of issuance & availability
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/09 2pp 06860 103

--8011030700 Amend 69 to License DPR-21, revising Tech Specs to allow count rate on source range monitor channels to go below three counts per second under certain circumstances
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/09 9pp 06860 105

--8011030703 Safety evaluation supporting Amend 69 to License DPR-21
* Office of Nuclear Reactor Regulation, Director 80/10/09 3pp 06860 114

--8011030708 Notice of issuance & availability of Amend 69 to License DPR-21
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/09 2pp 06860 117

8011280020 Requests Region 1 documentation of acceptance criteria for containment integrated leak rate test Criteria has been accepted by Region 3 & is used by other BWRs Requests approval of proposed Tech Specs changes by 801128
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/10/19 2pp 07084 120

8011060524 Requests overdue Class 3 fee for requested relief from certain inservice insp & testing requirements Fee should be remitted within 15 days of ltr receipt
MILLER, W O, License Fee Management Branch 80/10/23 1p 06915 284

DOCKETED ITEMS

33

BO1110469 Forwards order for mod of License DPR-21 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp
06944 318

--BO1110679 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06944 321

--BO1110687 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944 327

BO11040439 Forwards "Environ Qualification of Safety-Related Electrical Equipment," & App I, "Master Listing of Electrical Components by Sys."
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/10/31 8pp 06903 135

--BO11040444 "Environ Qualification of Safety-Related Electrical Equipment"
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
80/10/31 300pp 06903 143

--BO11040450 App I, "Master Listing of Electrical Components by Sys," to "Environ Qualification of Safety-Related Electrical Equipment"
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
80/10/31 280pp

BO1110007 Forwards implementation status of TMI action plan items which cannot be implemented by 80101 identified
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
80/10/31 17pp 06961 203

BO11200495 Advises of delay in completion of SEP Topic XVI, Tech Specs, until completion of all SEP topic reviews & integrated safety assessment Delay will allow evaluation of current Tech Specs w/proposed changes resulting from reviews
CRUTCHFIELD, D Operating Reactors Branch 5 80/11/05 2pp
07018 227

BO11190108 Forwards 10CFR50, App J mod schedule for facility Mods for 1980 refueling outage include installation of feedwater check valves revised single isolation valve test procedures & reinstallation of valves for reverse direction testing
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/11/06 13pp 07000 040

BO11240361 Application for amend to License DPR-21, revising Tech Specs to require that standby liquid control sys produce concentration of 660 ppm boron in reactor core Changes
suppl Reload 7 licensing submittal
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/11/06 3pp 07046 339

--BO11240370 Proposed changes to Tech Specs 3.4 for bases of standby liquid control sys to require concentration of 660 ppm boron in reactor core
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
80/11/30 3pp 07046 342

BO11240138 Forwards Class III fee for NRC review of util 800409 & 0610 requests for relief from inservice insp & testing program for recirculation pump casing
COUNSIL, W G, FEE, W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/11/12 1p 07049 159

BO1110885 Forwards summary of SEP efforts completed & committed to by owners for NRC SEP progress evaluation
SCHAFFSTALL, R SEP Owners Group 80/11/17 5pp

Q Inspection reports, IE Bulletins & correspondence

BO11060591 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" IEB 79-01B & suppl dtd 800229, not previously transmitted, also encl. No written response required.
ORIER, B H, Region 1, Philadelphia, Office of the Director 80/09/30 1p 06909 285

BO11200110 Ack receipt of 800930 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-245/80-02
ORIER, B H, Region 1, Philadelphia, Office of the Director 80/10/10 1p 07021 032

--BO11200114 Responds to NRC 800910 ltr re violations noted in IE Insp Rept 50-245/80-02 Refutes NRC item that properly documented audits of job orders do not exist Administrative control procedure re incident reporting modified
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/30 2pp 07021 033

--BO11200116 Ack receipt of 800512 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-245/80-02 Requests addl info
ORIER, B H, Region 1, Philadelphia, Office of the Director 80/09/10 2pp 07021 035

--BO11200122 Responds to NRC 800417 ltr re violations noted in IE Insp Rept 50-245/80-02 Corrective actions documentation of repairs now satisfies job order packages Drywell wall cracking reinspected
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/12 2pp 07021 037

--BO11200126 Forwards IE Insp Rept 50-245/80-02 on 800102-04, 09-11, 29-31, 0213-15 & 20-22 & notice of violation
CARLBON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/04/17 2pp 07021 039

--BO11200130 Notice of violation from insp on 800102-04, 09-11, 29-31, 0213-15 & 20-22
* Region 1, Philadelphia, Office of the Director 80/04/16 1p 07021 041

--BO11200134 IE Insp Rept 50-245/80-02 on 800102-04, 09-11, 29-31, 0213-15 & 20-22 Noncompliance noted isolation condenser sys not capable of withstanding seismic, blowdown & water-hammer loads due to loose anchor bolts
CHAUDHARY, S K, SANDERS, F W, VARELA, A A Region 1, Philadelphia, Office of the Director 80/04/16 22pp 07021 042

BO11200259 Informs that info requested in IE Bulletin 79-26, Revision 1, re boron loss from control blades, remains same as in original response dtd 791120
COUNSIL, W G, FEE, W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/10/14 1p 07019 363

BO11190595 Forwards IE Mgt Meeting Repts 50-245/80-15 & 50-336/80-16 on 800911 No noncompliance noted
ORIER, B H, Region 1, Philadelphia, Office of the Director 80/10/21 2pp 07001 201

--BO11190602 IE Mgt Meeting Repts 50-245/80-15 & 50-336/80-16 on 800911 No noncompliance noted Major areas discussed results of appraisal board formed to evaluate performance of facility from Jul 1979-Jul 1980 re refueling & protection
SHEDLOSKEY, J T, SMITH, T H, CONNORS, E L Region 1, Philadelphia, Office of the Director 80/10/15 7pp 07001 203

BO11060746 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2" No written response required
ORIER, B H, Region 1, Philadelphia, Office of the Director 80/10/24 1p 06914 345.

BO11070300 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required
ORIER, B H, Region 1, Philadelphia, Office of the Director 80/10/24 1p 06921 328

BO1110669 Forwards order for mod of License DPR-21 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp
06944, 318

--BO1110679 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201.
EISENHUT, D G Division of Licensing 80/10/24 6pp 06944 321

--BO1110687 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 2pp 06944 327

BO11140063 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators" No written response required
ORIER, B H, Region 1, Philadelphia, Office of the Director 80/10/31 1p 06968 245.

DOCKETED ITEMS

801170887 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06981 220

8011200142 Provides addl info re IE Bulletin 80-11, "Masonry Wall Design " Revised log sheets describing walls, priority by which walls will be re-evaluated & acceptance criteria encl
Final rept will be sent by 810302
COUNSIL, W O Northeast Utilities 80/11/04 90pp 07021:046

8011240138 Forwards Class III fee for NRC review of util 800409 & 0610 requests for relief from inservice insp & testing program for recirculation pump casing
COUNSIL, W O, FEE, W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/11/12 1p 07049.159

R Periodic operating reports & related correspondence

801180629 Forwards monthly operating rept for Oct 1980
MROCKZKA, E J Northeast Utilities 80/11/12 1p 06992 089

--801180635 Monthly operating rept for Oct 1980
HARRAN, Q Northeast Utilities 80/11/01 4pp 06992 090

S Reportable occurrences, LERs & related correspondence

8011030441 Forwards LER 80-015/03L-0
MROCKZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/10/24 1p 06867.337

--8011030445 LER 80-015/03L-0 on 801007, during routine surveillance, reactor vessel low water level alarm & low-low level isolation functional & caliber test level switch L18-263-57B tripped slightly Caused by dust in switch mechanism
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
80/10/24 3pp 06867.358

801120375 RO-80-18/1P on 801105 main steam line support members MSR-32 & MSR-28 were found to have failed welds between support members & support structures. Cause unknown
Investigation in progress
MROCKZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/11/05 1p 06916 001

801120537 RO 80-19-1P, on 801106, during Class II inservice insp of isolation condenser sys, liquid penetrant examination of inside diameter steam supply piping nozzle-to-isolation condenser vessel weld revealed cracking Cause unknown
MROCKZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/11/06 1p 06916 001

8011200311 RO 80-18/1P on 801105 main steam line support members MSR-32 & MSR-28 were found to have failed welds between support members & support structures Cause of failure unknown Investigating problem Addl info to be filed
MROCKZKA, E J Northeast Utilities 80/11/06 1p

8011210507 Forwards LER 80-016/01T-0
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/11/06 1p 07034 293

--8011210515 LER 80-016/01T-0 on 801023, exam of jet pumps per IE Bulletin 80-07 revealed that one beam was rejectable & four in marginal condition Caused by intergranular stress corrosion cracking Beams will be replaced during refueling outage
BIOARELLI, M J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/11/06 95pp 07034 294

8011250398 Forwards LER 80-018/01T-0
MROCKZKA, E J Northeast Utilities 80/11/19 1p 07056 118

--8011250391 LER 80-018/01T-0 on 801105, two main steam line support members, MSR-32 & MSR-28, were found to have failed welds between support member & support structure Cause is under investigation Supports will be returned to original design
* Northeast Utilities 80/11/19 2pp 07055 119

8011250377 Forwards LER 80-019/01T-0
MROCKZKA, E J Northeast Utilities 80/11/20 1p 02227 001

--8011250385 LER 80-019/01T-0 on 801106, liquid penetrant examination of inside diameter of steam supply piping nozzle-to-isolation condenser vessel weld revealed circumferential cracking on both sides Cause is under investigation
* Northeast Utilities 80/11/20 2pp 02227 001

V Operator Examinations

8011040158 Responds to NRC 800731 ltr re interim criteria for shift staffing Util commits to having two licensed senior reactor operators, two licensed reactor operators & min of two auxiliary operators at each operating reactor by 820701
COUNSIL, W O Northeast Utilities 80/10/22 6pp 06884 277

DOCKET 80-246 ADVANCED CRITICAL REACTOR EXPERIMENT

S Reportable occurrences, LERs & related correspondence

8011200311 RO 80-18/1P on 801105, main steam line support members MSR-32 & MSR-28 found to have failed welds between support members & support structure Cause of failure unknown Investigating problem Addl info to be filed
MROCKZKA, E J Northeast Utilities 80/11/06 1p 01741 019

DOCKET 80-247 INDIAN POINT STATION, UNIT 2

F Security, medical, emergency & fire protection plans

801180317 Forwards facility emergency planning info for placement in LPDR W/o encl
SQUER, J L Division of Rules and Records 80/11/04 1p 06991 158

8011280097 Ack receipt of 800307 ltr forwarding change in security plan Change acceptable Changes withheld (ref 10CFR2 790)
VARGA, S A Operating Reactors Branch 1 80/11/17 2pp 07081 333.

G Adjudicatory correspondence

801110047 Forwards order for mod of License DPR-26 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARGA, S A Operating Reactors Branch 1 80/10/24 3pp 06943 263

--801110054 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0988 required by 820630
Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06943 266

--801110065 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06943 272

8011040335 Requests immediate action on request for hearings to reassess facility safety Interim operation should not be allowed until 801017 accident has been investigated
WEISS, E R, POLLARD, R D Union of Concerned Scientists 80/10/29 3pp 06884 241

801180102 Urges creation of stationed public sector safety person to rept facility problems Counties were not notified about 801017 leak until 801022 Four County Nuclear Safety Committee 801103 statement for NRC hearings encl
DELBELLO, A B Westchester County, NY 80/11/03 5pp 06985 118

H General correspondence

8011060195 Responds to encl 800823 ltr to President Carter requesting facilities be shutdown because of threat to life Two reactors may continue to operate until completion of hearing process to re-examine safety considerations
INGRAM, F Office of Public Affairs 80/10/20 2pp 02319 196

8011060474 Urges facility shutdown
CASSEL, R, CASSEL, F Affiliation Unknown 80/10/25 1p 02319 196

8011040408 Requests FI Bialik name be added to svc lists for all matters re facilities, BNL & transport of nuclear mats in NY
BIALIK, E I New York, State of 80/10/31 1p

801180128 Responds to 801027 ltr to JF Ahearne re request to keep facility shut down Facility will not restart until circumstances surrounding leakage are identified, fully evaluated & steps are taken to prevent recurrence
INGRAM, F L Office of Public Affairs 80/10/31 1p 06915 001

--B01180163 Requests that facility be kept shut down as 100,000 gallons of corrosive saltwater are already in reactor
BALL, L. H. Affiliation Unknown 80/10/27 1p 06915 001

B01180170 Responds to B01029 mailgram re util neglect & incompetence in operation of facility Facility will not restart until circumstances surrounding leakage are identified, fully evaluated & steps are taken to prevent recurrence
INGRAM, F. L. Office of Public Affairs 80/10/31 1p 06915 001

--B01180176 Expresses outrage at util neglect & incompetence re operation of facility Requests that facility be kept shut down Util has no evacuation plans & covers up truth
KIMERLING, N. Affiliation Unknown 80/10/29 1p 06915 001

B01190498 Petitions for denial of Con Ed & PASNY petition to resume operations pending full investigation of safety issues to be adjudicated at forthcoming hearings
SCHNEIDER, B., MOTYCKA, M., BERNARD, T. J. Affiliation Unknown 80/11/18 4pp 07001 289

B011260175 Urges expedited safety hearings on facility NRC should order interim shutdown immediately Expresses concern re facility being located in densely populated area
DELOPOULOS, S. J., STRAUSS, B. B., STRAUSS, R. R. Affiliation Unknown 80/11/18 1p 07071 337

B011210461 Demands immediate shutdown of facility Risks too great in populous area
LABLOM, M. W. Affiliation Unknown 80/11/20 1p 02227 001

P Operating license stage documents & correspondence

B011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D. O. Division of Licensing 80/09/05 209pp

B011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by B01101
EISENHUT, D. O. Division of Licensing 80/10/01 5pp

B011050205 Forwards table giving calculated peak values & associated probabilities & weather conditions for several risk measures at facilities Values should be viewed as representative of general shape of curve
MURLEY, T. E. Office of Nuclear Regulatory Research, Director 80/10/03 3pp 06896 279

B011100537 Ltr to all power reactor licensees & applicants forwarding summary of B00827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D. O. Division of Licensing 80/10/06 6pp

B011100500 Requests supporting info re B00811 auxiliary feedwater sys analyses Addl analyses must demonstrate that reduced flow rate can remove heat decay w/o operator action for at least 10 minutes
VARQA, B. A. Operating Reactors Branch 1 80/10/09 2pp 06931 211

B01110047 Forwards order for mod of License DPR-26 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, B. A. Operating Reactors Branch 1 80/10/24 3pp 06943 263

--B01110054 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by B20630 Complete records must be available by B01201
EISENHUT, D. O. Division of Licensing 80/10/24 6pp 06943 266

--B01110065 Revised Tech Spec pages per B01024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06943 272

B011060298 Notification of B01106 meeting w/utills in Bethesda, MD to discuss task action plan
OLSHAN, L., WIGGINTON, D. Operating Reactors Branch 1 80/10/27 1p 06911 289

B011070167 Notification of cancellation of B01106 meeting w/utills in Bethesda, MD to discuss status of task action plan
OLSHAN, L., WIGGINTON, D. Operating Reactors Branch 1. 80/10/27 2pp 06920 298

B011030517 Notifies that proposed Tech Spec revisions addressed in B00826, 0924 & 30 ltrs are now scheduled for submittal by B01231
ZARAKAS, P. Consolidated Edison Co of New York 80/10/29 1p 06955 071

B011070398 Forwards response to NRC B00919 revised order for mod of license Request satisfied by B00509 submittal, "Indian Point Unit 2 Electrical Equipment Environ Qualification Rept"
ZARAKAS, P. Consolidated Edison Co of New York 80/10/31 200pp 06911 001

B011100040 Forwards Amend 64 to License DPR-26, safety evaluation & notice of issuance & availability
VARQA, B. A. Operating Reactors Branch 1 80/10/31 4pp 06929 001

--B011100044 Amend 64 to License DPR-26, consisting of changes to Tech Specs to reflect addl sys required by 790131 fire protection safety evaluation
VARQA, B. A. Operating Reactors Branch 1. 80/10/31 26pp 06929 005

--B011100046 Safety evaluation supporting Amend 64 to License DPR-26
VARQA, B. A. Office of Nuclear Reactor Regulation, Director 80/10/31 1p 06929 031

--B011100051 Notice of issuance & availability of Amend 64 to License DPR-26
VARQA, B. A. Operating Reactors Branch 1 80/10/31 2pp 06929 032

B011170800 Informs that B00610 response to Item E 2 of B00211 confirmatory order lacks details & specificity Forwards summary of NRC independent review of control room design & related consultant rept & required corrective actions
VARQA, B. A. Operating Reactors Branch 1 80/10/31 6pp 06973 334

--B011170808 Discusses human engineering review of facility control room Control room showed number of design & procedure features contradictory to human engineering stds & practices Observations on potential design risks included
MALLORY, K. Essex Corp 80/03/12 7pp 06973 340

B011180729 "Hudson River White Perch," quarterly progress rept Apr-June, 1980
VAN WINKLE, W., BARNTHOUSE, L. W. Oak Ridge National Laboratory. FIN B-0423 B01180729, 80/11/13 85pp 06915 001.

B011190339 Advises that results of B01006 analysis indicate feasibility to discharge water into reactor cavity. Detailed evaluations re structural capability sys interactions seismic considerations & electrical power requirements to follow.
ZARAKAS, P. Consolidated Edison Co of New York 80/11/13 2pp 07000 001.

Q Inspection reports, IE Bulletins & correspondence

B011130159 Forwards IE Insp Rept 50-247/80-12 on B00B19-22. No noncompliance noted.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/16 2pp 06959 113.

--B011130165 IE Insp Rept 50-247/80-12 on B00B19-22 No noncompliance noted. Major areas inspected QA program including auditing, design changes & mods & previously identified items
NAPUDA, G. Region 1, Philadelphia, Office of the Director GREENMAN, E. Q. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/15 7pp 06959 113

B011070050 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/09/30 1p 06924 316

B011060632 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2" No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/10/24, 1p 06909 345.

B011070280 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/10/24 1p 06921 208

DOCKETED ITEMS

801110047 Forwards order for mod of License DPR-26 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARGAS A Operating Reactors Branch 1 80/10/24 3pp 06943 263

--801110054 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by B20630
Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 4pp 06943 266

--801110065 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06943 272

8011140066 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators " No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06968 247

8011140605 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06963 243

R Periodic operating reports & related correspondence

8011060080 Partial response to FOIA request for info re radiation levels of plant environs & dump sites & radiation levels in nine listed places Forwards documents listed in App A Search is continuing for documents re second part of request
FELTON, J M Division of Rules and Records 80/10/29 2pp 06914 333

--8011040122 Excerpts from environ monitoring annual repts Includes Indian Point repts for 1978 & ME Yankee & JA Fitzpatrick Repts for 1979
* Consolidated Edison Co of New York * Maine Yankee Atomic Power Co * Power Authority of the State of New York 80/10/29 13pp

8011170521 Forwards data specified in Section 401 certification for Oct 1980
MONTI, H A Consolidated Edison Co of New York 80/11/10 18pp 06968 277.

8011180457 Forwards monthly operating repts for Oct 1980
ZARAKAS, P Consolidated Edison Co of New York 80/11/14 1p 06989 233

--8011180462 Monthly operating repts for Oct 1980
EICHLE Consolidated Edison Co of New York 80/11/07 4pp 06989 236

8011180483 Forwards tabulation of daily record of fish collections for Oct 1980
ZARAKAS, P Consolidated Edison Co of New York 80/11/14 1p 06991 267.

--8011180690 Tabulation of daily record of fish collections for Oct 1980
* Consolidated Edison Co of New York 80/11/14 4pp 06991 268

S Reportable occurrences, LERs & related correspondence

8011060480 RD-80-012/01 on 801016, potential conflict identified re NRC requirements in procedural step to close manually operated valve LB41 during inservice testing of pneumatic valves
Test procedure revised & procedural review continuing
MONTI, H A Consolidated Edison Co of New York 80/10/16 2pp 02319 196

8011200545 Immediate Action Ltr 80-41 confirming until 801021 telcon commitments re accumulation of water on primary containment floor Licensee will determine cause of turbine runback which followed trip of nuclear instrument channel N42
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/22 2pp 07018 204

8011030685 Forwards LER 80-012/017-0
ZARAKAS, P Consolidated Edison Co. of New York 80/10/29 1p 06861 197

--8011030691 LER 80-012/017-0 on 801016, during procedure review program, determined that inservice valve test PT-Q13 required closure of valve LB41 during stroking of valves 876A & B Procedure has been revised to delete closing requirement
MAKEPEACE, J M Consolidated Edison Co of New York 80/10/29 2pp 06861 198

801110364 PNO-I-80-158 on 801029, during testing of new hose reel connection, hose reel isolation valve leaked approx 900 gallons of fresh water No damage found
KENNY, T. J., MCCABE, E C, BRUNNER, E J Region 1, Philadelphia, Office of the Director 80/10/30, 1p 06943 125

801110371 PNO-I-80-160 on 801103, approx 8,000 gallons of non-radioactive svc water spilled on containment floor Svc water leaking from isolation valve, SHN44-1, backed up through fan cooler 22 & flowed from open flange spool piece
GREENMAN, E., BRUNNER, E J Region 1, Philadelphia, Office of the Director 80/11/04, 1p 06943 124

8011180656 Forwards LER 80-014/03L-0
ZARAKAS, P Consolidated Edison Co of New York 80/11/14 1p 06991 251

--8011180664 LER 80-014/03L-D on 801017, while in hot shutdown condition, main steam isolation valve for Loop 23 failed to completely close during process of isolating secondary plant. Caused by binding within valve air operator Air operator replaced
MAKEPEACE, J M Consolidated Edison Co of New York 80/11/14 1p 06991 252

8011180672 Forwards LER 80-013/03L-0
ZARAKAS, P Consolidated Edison Co of New York 80/11/14 1p 06991 257

--8011180679 LER 80-013/03L-D on 801017, during full power operation, observed that power range nuclear instrumentation channel N42 indication was drifting Caused by defective power range detector resulting from moisture within connector
MAKEPEACE, J M Consolidated Edison Co of New York 80/11/14 1p 06991 258

T Hearing transcripts on non-antitrust matters

8011240516 FOIA request for transcripts of all Commission &/or staff meetings since 801017 re accident at facility
WEISS, E R Sheldon, Harmon & Weiss 80/10/30 1p 07049 082

8011240472 Transcript of 801114 public meeting in Washington, DC re investigation of containment flooding event at Indian Point 2 & restart of Indian Point 3 Pp 1-136
* Office of Inspection & Enforcement, Office of the Director 80/11/14, 136pp 07047 287

--8011240478 Forwards draft order re interim operation during adjudicatory hearing
BICKWIT, L Office of the General Counsel SECY-A-80-179A 80/11/13 33pp 07048 084

--8011240486 Discusses proposed footnote re procedural issues for ASLP to follow due to investigative nature of proceeding
BICKWIT, L Office of the General Counsel SECY-A-80-179 80/11/13 16pp 07048 114

8011240501 Responds to FOIA request for transcripts of all Commission &/or staff meetings since 801017 re accident at facility
Forwards transcripts of 801024 & 1105 Commission meetings
FELTON, J M Division of Rules and Records 80/11/20 1p 07049 081

--8011240524 Transcript of 801024 briefing in Washington, DC for PA Bradford re facility incident Pp 1-82
* Commissioners 80/10/24 84pp

--8011240532 Transcript of 801105 technical meeting in White Plains, NY re facility 801017 containment flood event Pp 1-180
* Commissioners 80/11/05 183pp

--8011240548 Transcript of 801105 technical meeting in White Plains, NY re comments on facility 801017 containment flood event.
Pp 180-370.
* Commissioners 80/11/05, 422pp

U Congressional/Executive Correspondence

8011170215 Urges decertification of Con Ed as facility operator due to poor operating record
OTTINGER, R L House of Rep 80/10/31 1p 06981 336

8011170440 Discusses NRC investigation of facts re water leakage into facility containment as important concern to author & other citizens Urges direct consideration re suspension or revocation of OLS NRC findings requested
MOFFETT, T House of Rep, Government Operations 80/11/05 2pp
06977 268

DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8011190349 Supplements 791022 ltr re safe shutdown capability Staff has utilized BNL to review 780605 rept & supplement Requests submission of proposed plans & schedules by 801101
EISENHUT, D O Division of Licensing 80/10/01 3pp. 06976 186

8011170336 Forwards comments on revised emergency plan per requirements of NUREG-0654 Plan should be revised to address comments
EISENHUT, D O Division of Licensing 80/10/02 5pp.

8011170573 Forwards position on mods required by licensee to comply w/proposed rule re min acceptable fire protection criteria Outstanding areas include smoke detection sys test & water suppression sys
IPPOLITO, T A Operating Reactors Branch 2 80/10/27. 6pp
06979 202

8011190191 Informs of DOJ decision not to prosecute guard contractor for improprieties re firearms qualification & documentation of patrols. Decision based on prompt identification, notification & resolution of matter w/related ltrs.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28 6pp. 06999 228

8011110486 Responds to NRC 801001 ltr re fire protection safe shutdown analysis plans Util evaluation of BNL 800709 review has found current & ongoing fire protection installations sufficient to assure safe shutdown capability Review encl
JANECEK, R F Commonwealth Edison Co 80/10/31. 5pp 06944 330

8011050428 Forwards draft public info package re emergency preparedness for facilities Package has been distributed to States of IL, IA & WI for comment Requests NRC comment by 801121.
DELOEOROE, L O Commonwealth Edison Co 80/11/03. 8pp 06894-107.

G Adjudicatory correspondence

8011100112 Forwards orders for mod of Licenses DPR-25, DPR-29 & DPR-30 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24. 2pp
06943-223

--801110022 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06943.225

--801110029 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24. 2pp 06943.231

--801110035 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201.
EISENHUT, D O Division of Licensing. 80/10/24. 6pp 06943 233.

--801110041 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 2pp. 06943 239

--801110050 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing. 80/10/24 6pp 06943.241.

--801110058 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp. 06943 247.

8011050716 Forwards revised pages. Revision 3, to 780203 rept forming part of application Reduces number of storage spaces & accounts for unanticipated cumulative effect re rack pitch tolerance Util will discuss changes at evidentiary hearing
STEPTOE, P P Isham, Lincoln & Beale 80/10/29 17pp. 06898-301

8011040417 Submits listing of addl documents produced per informal discovery agreement
FITZGERBONS, R Isham, Lincoln & Beale 80/10/30 2pp 06873 342

8011050200 Notices of appearances in spent fuel pool mod proceeding
Svc list encl
FITZGERBONS, R, STAHL, D M Commonwealth Edison Co FITZGERBONS, R Isham, Lincoln & Beale 80/10/30 4pp 06899 070

8011040430 Response to ABLB 801014 order re intention to pursue application Safety evaluation & EIA or EIS will be published in May 1981 Certificate of Svc encl
GODDARD, R J. Hearing Branch 2 80/10/31 2pp 06873-282

8011060381 Responds to ABLB 801014 order Util intends to pursue spent fuel transshipment application, although classified as second in priority to pending spent fuel rack replacement requests. Urges that ABLB jurisdiction be retained
STEPTOE, P P Isham, Lincoln & Beale 80/10/31 3pp. 06914 135

8011060453 Withdraws util 801023 request for hearing in view of info presented in Suppl 3 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment"
STEPTOE, P P Isham, Lincoln & Beale 80/10/31. 1p. 06916:205

8011040419 Forwards IE repts in response to 801016 request for documents. Paragraph 4.4/o encls
GODDARD, R J. Hearing Branch 2 80/11/03 1p 06873 272

8011060201 Notice of appearance in proceeding re proposed amend to OLS increasing spent fuel storage capacity Certificate of Svc encl
VAN VRANKEN, J Illinois, State of 80/11/03 5pp 06912:087

8011060472 Forwards Brooks & Perkins internal audits Signature denoting documents as proprietary requested w/o encl. Related correspondence
FITZGERBONS, R Isham, Lincoln & Beale. 80/11/03. 1p. 06914 141

8011170222 Forwards NFS Document D0001685 re fuel assembly clearances in high density spent fuel storage racks. W/o encl. Related correspondence
FITZGERBONS, R Isham, Lincoln & Beale. 80/11/07. 1p 06981:357

8011180129 Submits order of presentation of evidence per parties' agreement subj to ABLB approval Safety evaluation, EIA & GA will be presented on 801119; contentions re corrosion & radiological protection on 801120 & re accidents on 801121
STEPTOE, P P Isham, Lincoln & Beale. 80/11/12 2pp 06987:194.

8011210513 Forwards Comm Ed GA dept surveillance repts re NBC & Lickenby documents D0001694-D001695 w/o encl
FITZGERBONS, R Isham, Lincoln & Beale. 80/11/18 1p 02227-001

H General correspondence

8011180075 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities. Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/11/04 1p 06984 200.

8011180086 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities. Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/11/04 1p 06987:322

8011180111 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities. Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/11/04. 1p 06987:329

8011180113 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities. Util will analyze water from various aquifers in future & NRC will review results
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/11/04. 1p. 06987.331.

801180120 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 332

801180124 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 334.

801180127 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 335

801180132 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 337.

801180134 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 336

801180137 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 338

801180141 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 339

801180143 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 340

801180146 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987,341.

801180175 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 295

801180187 Discusses water samples collected by NRC around facilities & analyzed by ANL. No evidence found of radioactivity from facilities Util will analyze water from various aquifers in future & NRC will review results.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/04 1p 06987 296

P Operating license stage documents & correspondence

7903200701 Notification of meeting on 790314-15 w/representatives of Hart I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, hugging & lateral load definition.
RHEB, C E Assistant Director for Engineers & Projects (Pre 70625). 79/03/02 2pp 03145 305

050354 Ltr to all licensees of operating plants, applicants for DLS holders of CPs re preliminary clarification of TMI action in requirements Provides summary listing of all approved -2 related requirements
EISENHUT, D O. Division of Licensing 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for DLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801190237 Ltr to all DNR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance info should be submitted within 25 days
EISENHUT, D O. Division of Licensing 80/10/01 2pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/O encl
EISENHUT, D O. Division of Licensing 80/10/06 6pp

801110012 Forwards orders for mod of Licenses DPR-25, DPR-29 & DPR-30 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp

--801110022 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0388 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06943 225

--801110029 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06943 231

8011030577 Submits info re reassessment of scram sys in response to NRC 801001 ltr Results of re-evaluation & schedule of implementation will be provided by 801215
JANECEK, R F Commonwealth Edison Co 80/10/27 2pp 06855 081

801120552 Forwards Revision 3 to Nuclear Svcs Corp Oct 1980 "Licensing Rept, Dresden Nuclear Power Plant Units 2 & 3, Spent Fuel Rack Mod," re 780511 proposed amend to Licenses DPR-19 & DPR-23.
JANECEK, R F Commonwealth Edison Co 80/10/29 2pp 06952 130

--801120560 "Licensing Rept, Dresden Nuclear Power Plant Units 2 & 3, Spent Fuel Rack Mod," Revision 3
HINES, D P , MCCOY, J J Nuclear Services Corp QUAD-1-77-234 R3 80/10/29 16pp 06952 132

8011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201
ABEL, J B Commonwealth Edison Co 80/10/31 1p 06874 174

801100389 Forwards Page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments
TRAHM, T R Commonwealth Edison Co 80/11/05 2pp 06930 357

801180419 Clarifies 800511 proposed fuel pool mode Rack replacement will be performed only w/125 ton redundant hook of reactor bldg crane Fuel movements will be made w/existing fuel grapple normally used during routine refueling outages
JANECEK, R F Commonwealth Edison Co 80/11/13 1p 06989 091

8011240374 Application to amend License DPR-29, changing Tech Specs for extended burnup fuel program Class III amend fee encl
JANECEK, R F Commonwealth Edison Co 80/11/13 2pp 07046 347

--8011240393 Revised Page 4-B to "LOCA Analysis Rept " Supplemental discussion of NEDO-24855 encl
* General Electric Co NEDO-24146A 80/11/13 2pp, 07047 010

G Inspection reports, IE Bulletins & correspondence

8011060575 Submits addl response to IE Insp Rept 50-249/80-09 Comparison of control rod designs at facilities scheduled for next outage If irreconcilable differences exist, seismic reanalysis of piping will be considered
ABEL, J B Commonwealth Edison Co 80/08/18 1p 06914 147

801190315 Forwards IE Insp Repts 50-010/80-14, 50-237/80-17 & 50-249/80-21 on 800803-0906 & notice of violation
HEISMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/08 2pp 06998 120

DOCKETED ITEMS

39

--801100526 IE Insp Repts 50-010/80-14, 50-237/80-17 & 50-249/80-21 on 800803-0906 Noncompliance noted personnel failed to follow radiation protection procedures
BARKER, J. L., TONGUE, T. M., REIMANN, F. W. Region 3, Chicago, Office of the Director 80/09/27 7pp 06998 123

801110027 Forwards IE Insp Repts 50-010/80-15, 50-237/80-18 & 50-249/80-22 on 800905-17 No noncompliance noted
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/17 2pp 06943 252

--801110034 IE Insp Repts 50-010/80-15, 50-237/80-18 & 50-249/80-22 on 800905-17 No noncompliance noted Major areas inspected circumstances re allegations that radioactive water released to environ over period of one to two months
REIMANN, F. W., TONGUE, T., JANUSKA, A. Region 3, Chicago, Office of the Director 80/10/14 9pp 06943 254

8011060793 Discusses IE Insp on 800908-10 & forwards notice of violation & notice of proposed imposition of civil penalty
STELLO, V. Office of Inspection & Enforcement, Office of the Director 80/10/20 3pp 06909 103

--8011060797 Notice of proposed imposition of civil penalty in amount of \$40,000 for item of noncompliance noted in IE Insp on 800908-10
STELLO, V. Office of Inspection & Enforcement, Office of the Director 80/10/20 2pp 06909 106

8011060172 Confirms 801031 meeting w/RL Spessard in Chicago, IL to discuss regulatory performance
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/21 3pp 06915 327

801120415 Forwards monthly status rept re evaluations performed at facilities in response to IE Bulletin 79-14 H/a encl
JANECEK, R. F. Commonwealth Edison Co 80/10/21 2pp 06953 361.

8011070281 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/24 1p 06921 292

801110012 Forwards orders for mod of Licenses DPR-25, DPR-29 & DPR-30 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T. A. Operating Reactors Branch 2 80/10/24 2pp

--801110022 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D. O. Division of Licensing 80/10/24 4pp 06943 225

--801110029 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06943 231

801190040 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re Inspector Identification should be directed to Region 3 ofc
Badge examples encl
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/28 3pp 06999 180.

801170249 Forwards four isometric drawings which were omitted from Oct 1980 status rept re IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys "
JANECEK, R. F. Commonwealth Edison Co 80/10/29 5pp 06915-001.

801200062 Forwards final response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment," per NRC 800919 revised order for mod of license
ABEL, J. S. Commonwealth Edison Co 80/10/30 3pp 07011.001

--8011200064 Vol 1 of Revision 1 to "Response to IE Bulletin 79-01B for Dresden Nuclear Power Station, Unit 3 "
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 66pp 07011-004

--8011200071 Vol 2 of Revision 1 to "Response to IE Bulletin 79-01B for Dresden Nuclear Power Station, Unit 3 "
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 200pp. 07011 078

--8011200078 Vol 3 of Revision 1 to "Response to IE Bulletin 79-01B for Dresden Nuclear Power Station, Unit 3 "
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 200pp 07011 345

--8011200081 Vol 1, Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2 "
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 100pp. 07012 234

--8011200087 Vol 2 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2 "
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 230pp 07012 340

--8011200094 Vol 3 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2 "
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 230pp 07013 229

--8011200097 Vol 4 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2 "
* Bechtel Power Corp (subs of Bechtel Corp.) 80/11/01 160pp 07014 142

--8011200107 Vol 5 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2 "
* Bechtel Power Corp (subs of Bechtel Corp). 80/11/01 180pp 07014 345

8011200539 Forwards IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-265/80-27, 50-295/80-21 & 50-304/80-23 on 801031 No noncompliance noted
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/06 2pp. 07020 167

--8011200544 IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-265/80-27, 50-295/80-21 & 50-304/80-23 on 801031 No noncompliance noted Major areas discussed performance of activities
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/06 26pp 07020 169

8011250696 Forwards response to IE Bulletin 80-11, "Masonry Wall Design " Operability assessment performed on walls classified as safety-related but failed to meet acceptance criteria Safe shutdown capability not jeopardized
ABEL, J. S. Commonwealth Edison Co 80/11/06 23pp 07056-050

8011200472 Grants extension until 801124 to respond to NRC 801020 ltr
STELLO, V. Office of Inspection & Enforcement, Office of the Director 80/11/14 1p 07020 136

R Periodic operating reports & related correspondence

8011180447 Forwards monthly operating repts for Oct 1980,
SCOTT, D. J. Commonwealth Edison Co 80/11/12 1p 06989-208

--8011180453 Monthly operating repts for Oct 1980
CIESZKIEWICZ, B. Commonwealth Edison Co 80/11/01 15pp. 06909-209

8011250475 Forwards suggested changes to & verification of radioactive effluents from facility Encl available in Central Files only
SCOTT, D. J. Commonwealth Edison Co 80/11/18 1p. 07175 319.

S Reportable occurrences, LERs & related correspondence

8011040474 Forwards LER 80-036/03L-0
SCOTT, D. J. Commonwealth Edison Co 80/10/23 1p. 06874-133

--8011040512 LER 80-036/03L-0 on 801009, during normal operation w/red-block monitor in progress, Monitor seven found to have constant high & alarm ref set high alarms Caused by component failure on flow trip ref card, Card replaced
HOLLAND, P. Commonwealth Edison Co. 80/10/23. 2pp 06874.134.

8011030629 Part 21 rept re failure of condition containment atmosphere monitoring sys, reported on 801023. Sensors fail to provide accurate hydrogen concentration measurements following LOCA
Analysis of defect re BWRs encl
SHERWOOD, O. O. General Electric Co. 80/10/24 11pp. 06860.148

8011070382 Forwards LER 80-040/01T-0
SCOTT, D. J. Commonwealth Edison Co 80/10/31 1p 06925-092

--B011070383 LER 80-040/01T-0 on B01022, during normal operation, HPCI inboard steam supply valve failed to open. Caused by dirty auxiliary contact. Contact was cleaned & valve tested.
ZIRWAS, K Commonwealth Edison Co 80/10/28 2pp 06925 093

B011210543 Forwards LER 80-038/03L-0
SCOTT, D J Commonwealth Edison Co 80/11/13 1p 07029 253.

--B011210551 LER 80-038/03L-0 on B01021, crack was found on reactor water cleanup heat exchanger equalizing line (3-1292-2-A). Cause unknown. Leak was temporarily patched.
GIESZKIEWICZ, S Commonwealth Edison Co 80/11/12, 1p 07029 254

B011250558 Forwards LER 80-037/03L-0
SCOTT, D J Commonwealth Edison Co 80/11/17 1p 07056 101.

--B011250568 LER 80-037/03L-0 on B01020, during normal operation w/DIS 500-2 in progress, level switch LIS 263-578 was found to trip at differential pressure less than Tech Spec. Caused by instrument drift. Instrument readjusted.
HOLLAND, P Commonwealth Edison Co 80/11/17 1p 07056 102

B011250322 Forwards LER 80-042/03L-0.
SCOTT, D J Commonwealth Edison Co 80/11/18 1p 07068 330

--B011250368 LER 80-042/03L-0 on B01105, during normal operation, w/DIS 700-3 in progress, source range monitor channel 23 tripped at limit exceeding Tech Spec. Caused by drift of high alarm setpoint potentiometer on module 2-16B. Setpoint adjusted.
HOLLAND, P Commonwealth Edison Co 80/11/17 1p 07068 331

B011250325 Forwards LER 80-039/03L-0.
SCOTT, D J Commonwealth Edison Co 80/11/18 1p 07068 332

--B011250334 LER 80-039/03L-0 on B01022, during normal operation, while conducting isolation condenser valve operability tests, inboard isolation valve 3-1301-1 became inoperable when breaker tripped upon receiving open signal. Cause unknown.
MAQUON, R Commonwealth Edison Co 80/11/17 1p 07068 333

T Hearing transcripts on non-antitrust matters

B011070182 Forwards NRC supplemental testimony, safety evaluation & EIS Changes in proposed spent fuel pool mod considered insignificant. Certificate of Svc encl.
GODDARD, R J Hearing Branch 2 80/11/04 2pp 06920 306

--B011070190 Supplemental testimony in response to ASLB Question 1, addressing current status of spent fuel unfilled storage capacity, normal refueling discharge & reactor shutdown alternatives per NUREG-0575 w/prof qualifications.
O'CONNOR, P W Operating Reactors Branch 5, 80/11/04 7pp 06920 307

--B011070199 Supplemental testimony in response to Contention 1 Increase in radionuclide concentrations due to expansion would be relatively minor & can be adequately processed by present cleanup sys. Prof qualifications encl.
MALAFEEV, V Effluent Treatment Systems Branch 80/11/04 4pp 06920 314

--B011070204 Supplemental testimony on Contentions 2 & 3. Topical Rept CE-1-A commits util to QA program for activities affecting safety-related items during maint, mod & operation w/exhibits & prof qualifications.
BELKE, W L Quality Assurance Branch 80/11/04 24pp 06920 318

--B011070209 Supplemental testimony on Contentions 4 & 5. Spent fuel pool radiation monitoring adequate to detect normal & abnormal radioactive releases from increased spent fuel bundles. Prof qualifications encl.
BLUCK, S Division of Systems Integration 80/11/04 8pp 06920 342

--B011070214 Supplemental testimony on Contention 4 & Use of improved BxB fuel will reduce noble gas release from stored spent fuel. Thus far, no evidence of failures leading to leakage. Prof qualifications encl.
WOLHL, M L Accident Evaluation Branch 80/11/04 5pp 06920 350

--B011070219 Supplemental testimony on Contentions 7 & 8. Establishment of criteria for acceptable amount of corrosion on dimensional changes & strength tolerance is premature. Design sufficiently conservative. Prof qualifications encl.
HECKER, J R Brookhaven National Laboratory 80/11/04 6pp 06920 355

--B011070225 Affidavit re review of B01029 Revision 3 to licensing rept on spent fuel rack mod. No revision to safety evaluation needed re criticality considerations. Prof qualifications encl.
BROOKS, W L Core Performance Branch 80/11/03 3pp 06920 362

B01100630 Forwards util testimony re spent fuel pool mod. Refs in TA Pickens testimony will be offered into evidence as exhibits.
STEPTOE, P Isham, Lincoln & Beale 80/11/04 1p 06941 222

--B01100631 Testimony on Contention 1 re radwaste treatment sys for spent fuel pools & Contention 4 re radiation monitoring of spent fuel pool waste disposal & monitoring sys. Adequate for increased storage. Alarm sys satisfactory.
ADAM, D Commonwealth Edison Co 80/11/04 16pp 06941 223

--B01100634 Fuel Procedure DFP 800-20, "Operation of Whiting Redundant Crana Sys," Revision 2
* Commonwealth Edison Co 76/05/31 10pp 06941 239

--B01100635 Emergency Plan Implementation Procedure EPIP 200-12, "Area High Radiation"
* Commonwealth Edison Co 80/07/31 3pp 06941 249

--B01100638 Emergency Plan Implementation Procedure EPIP 200-13, "High Airborne Activity"
* Commonwealth Edison Co 80/07/31 2pp 06941 252

--B01100640 Testimony on Contention 7 re corrosion & related reactions of stainless steel boral storage rack tubes. Replies to State of IL second amended contentions re ASLB 800709 memorandum & order. Prof qualifications encl.
DRALEY, J E Commonwealth Edison Co 80/11/04 26pp 06941 254

--B01100642 "Neutron Absorber Sampling Plan - in Pool" Ref 6
* Commonwealth Edison Co 80/11/04 4pp 06941 283

--B01100646 Testimony on Contention 8 re criteria to prohibit use of spent fuel storage racks. Proposed surveillance program assures safe operation of racks. Prof qualifications encl.
OILEREST, J D Commonwealth Edison Co 80/11/04 7pp 06941 287

--B01100650 Testimony on Contention 2 re QA for spent fuel storage racks, Contention 3 re prevention & protection against damage in transportation & Contention 6 re impact of increased fuel storage capacity. FSAR Sections 4 & 14 & FES Section 7 encl.
PICKENS, T A Commonwealth Edison Co 80/11/04 60pp 06941 294

--B01100652 Testimony on Contention 3 re prevention & protection against transportation damage & Contention 5 re workers' health & safety in spent fuel pool area. Discusses receipt of new high density spent fuel racks.
RAGAN, R Commonwealth Edison Co 80/11/04 13pp 06941 354

--B01100656 Radiation Procedure DRP 37-1-B-1, "Control of Personnel External Exposures to Radiation" Util response to Question 1. Round 1 encl.
* Commonwealth Edison Co 74/03/31 7pp 06942 005

--B01100661 Deviation rept D-12-3-79-52 on 791023, fuel pool overflowed into vent ducts carrying contaminated water to all floors on Elevation 613-Ft. Caused by inadvertent opening of condensate fill valve. Valve immediately closed.
WRIGHT, M Commonwealth Edison Co 79/10/29 5pp 06942 012

--B01100667 Testimony on Contention 2 re QA assurance for spent fuel storage racks & Contention 3 re prevention & protection against transportation damage.
SHENSKI, W J Commonwealth Edison Co 80/11/04 14pp 06942 017.

B01180076 Forwards NRC supplemental testimony of ML Wohl reflecting changes to Pages 2 & 3 of testimony served on B01104. Basic conclusions not altered.
GODDARD, R J Hearing Branch 2 80/11/14 1p 06985 097

--B01180083 Supplemental testimony on Contention 4 re control rod drop, refueling accident, main steam line break outside drywell & loss of coolant inside drywell. Use of improved BxB fuel will reduce noble gas release from stored fuel. Resume encl.
WOLHL, M L Accident Evaluation Branch 80/11/14, 5pp 06985 098

V. Operator Examinations

B01100481 Forwards response to NRC B00731 ltr transmitting interim criteria for shift staffing & requesting util schedule for compliance. Vacancies may create situations requiring overtime in excess of NRC guidelines.
JANECEK, R F Commonwealth Edison Co 80/11/05 5pp 06928 010

DOCKETED ITEMS

41

801120492 Forwards response to NRC 800731 request for schedule per interim shift staffing requirements
JANECEK, R F Commonwealth Edison Co 80/11/05 3pp 06952 097

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8011130145 Forwards summary of mods for resolution of open items re NRC proposed rule on min fire protection requirements for facilities operating prior to 790101 Outstanding areas include fire water supply & auxiliary bldg corridor
VARQA, S A Operating Reactors Branch 1 80/10/09 6pp 02227 001

8011100504 Forwards request for addl info re security plan at facility Encl withheld (ref 10CFR2 790)
VARQA, S A Operating Reactors Branch 1 80/10/22 2pp

G Adjudicatory correspondence

8011140488 Responds to 800924 ltr requesting confirmation that answers to 800917 meeting questions will be addressed Suggests arrangements w/licenses for obtaining relevant documents
GRDTENHUIS, M Operating Reactors Branch 1 80/10/17 1p 06963 064

8011105522 Forwards orders for mod of Licenses DPR-31 & DPR-41 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, S A Operating Reactors Branch 1 80/10/24 2pp 06946 184

--8011105527 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06915 001

--8011105532 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Operating Reactors Branch 1, 80/10/24 5pp 06946 192

--8011105539 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 197

8011190062 Advises that, contrary to 800923 ltr, draft EIS is expected to be issued by 801219 Previous date could not be met.
GOLDRENO, B C Hearing Branch 2 80/11/18 1p 06999 334

P Operating license stage documents & correspondence

8011090354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 207pp

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" w/o encl
EISENHUT, D G, Division of Licensing 80/10/06 6pp

8011030698 Notification of 801023 visit to facilities to view steam generator & study reactor coolant pipe area & channel area
GRDTENHUIS, M Operating Reactors Branch 1, 80/10/17 1p 03692 194

8011100546 Forwards request for addl info re steam generator repair reft disposal alternatives Descriptions of hurricane resistant properties of storage bldg for steam generator lower assemblies & procedures to assure dryness needed
VARQA, S A Operating Reactors Branch 1 80/10/21 3pp 06931 249

801110105 Confirms 801023 site visit to view reactor coolant pipes & channel cut in steam generator cutting areas
VARQA, S A, Operating Reactors Branch 1 80/10/21 2pp 06943 115

801110117 Notifies of completed review re inadvertent safety injection during surveillance testing at facility. Util 791108 response is acceptable
VARQA, S A Operating Reactors Branch 1 80/10/21 2pp 06943 117

8011109522 Forwards orders for mod of Licenses DPR-31 & DPR-41 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, S A Operating Reactors Branch 1 80/10/24 2pp 06946 184

--8011105527 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06915 001

--8011105539 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 197

8011040391 Forwards addl info in response to NRC 800728 ltr re containment ventilation isolation Three oversize electrical drawings encl
UHRIG, R E Florida Power & Light Co 80/10/27 12pp 06913 013

8011050579 Summarizes 801023 site visit to obtain further understanding of decision by util re cuts made to separate steam generators from reactor sys
GRDTENHUIS, M Operating Reactors Branch 1 80/10/29 4pp 06902 074

8011210443 Forwards request for addl info generated from review of "Asymmetric LOCA Loading," WCAP-9628 & 9748, dtd Nov 1979 & June 1980, respectively
LAINAS, G C Assistant Director for Safety Assessment 80/10/29 27pp 07029 170

8011040401 Forwards description & basis for conflicting plans & schedules, in response to NRC 800905 ltr re preliminary clarification of TMI action plan requirements
UHRIG, R E Florida Power & Light Co 80/10/30 4pp 06874 175

8011050597 Forwards Amend 60 to License DPR-31, safety evaluation & notice of issuance & availability
VARQA, S A Operating Reactors Branch 1 80/10/30 3pp 06898 318

--8011050603 Amend 60 to License DPR-31, permitting continued operation of facility for six equivalent months of operation from 801024 at which time steam generators shall be inspected
VARQA, S A Operating Reactors Branch 1 80/10/30 4pp 06898 321

--8011050605 Safety evaluation supporting Amend 60 to License DPR-31
* Office of Nuclear Reactor Regulation, Director, 80/10/30 6pp 06898 325

--8011050609 Notice of issuance & availability of Amend 60 to License DPR-31
VARQA, S A Operating Reactors Branch 1 80/10/30 2pp 06898 331

8011050436 Forwards responses to Questions 2, 3 & 4 of NRC 801021 request for addl info re disposal alternatives Response to Question 1 will be submitted in near future
UHRIG, R E Florida Power & Light Co 80/10/31 12pp 06899 024

8011050474 Forwards supplementary info to assist in endangered species review American crocodile utilizes facility cooling canal sys & adjacent areas for feeding, loafing, mating & nesting Green & loggerhead turtles use cooling canal sys
UHRIG, R E Florida Power & Light Co, 80/10/31 7pp 06899 037

8011060260 Responds to NRC 800929 ltr requesting results of ultrasonic testing of low pressure rotor discs One keyway crack found on LP-1 rotor in Number 3 disc on governor end in Unit 3 Eight cracks found on LP-1 & LP-2 rotors in Unit 4
UHRIG, R E Florida Power & Light Co 80/10/31 1p 06909 160

8011210220 Forwards request for info re containment sumps & insulation for operating reactors Concerns are related to creation of debris air entrainment, formation of vortices & emergency procedures.
VARQA, S A Operating Reactors Branch 1, 80/10/31 4pp 07035 036

8011100352 Forwards response to Question 1 re disposal alternatives per 801021 request
UHRIG, R E Florida Power & Light Co 80/11/04 6pp 06930 334

DOCKETED ITEMS

801100370 Forwards responses to NRC 800929 request for addl info re industrial exposure, offsite doses & accident evaluation. Questions were discussed at public meeting between respective staffs on 800917.
UHR10,R E Florida Power & Light Co 80/11/04 4pp 06928 277

8011140134 Informs that Emergency Operating Procedure 20.000, immediate actions & diagnostics, has been revised to clarify compliance w/fourth paragraph of Section 2.1.4 to TMI Lessons Learned Category A items.
UHR10,R E Florida Power & Light Co 80/11/10 1p 06964.360

8011260992 Confirms 801114 telcon re strength of welds which seal steam generator sections & method of decontamination to be used. If info received by 801121, DES will be issued by 801219.
NOVAK, T M Assistant Director for Licensing 80/11/19 3pp 07081 330

G Inspection reports, IE Bulletins & correspondence

8010240648 Responds to IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture." Units do not have centrifugal charging pumps.
UHR10,R E Florida Power & Light Co 80/09/23 1p 06799 197

801130336 Forwards IE Insp Repts 50-250/80-28, 50-251/80-27, 50-335/80-28 & 50-389/80-11 on 800827-29 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/03 2pp 06960 292

--801130368 IE Insp Repts 50-250/80-28, 50-251/80-27, 50-335/80-28 & 50-389/80-11 on 800827-29 No noncompliance noted. Major areas inspected: followup of noncompliance re 10CFR21 procedures. BROWNLEE, V L Region 1, Philadelphia, Office of the Director. CHMLON, T E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/03 2pp 06960 294

8011260356 Forwards IE Insp Repts 50-250/80-27 & 50-251/80-26 on 800909-12 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/10 2pp 07072 291

--8011260362 IE Insp Repts 50-250/80-27 & 50-251/80-26 on 800909-12 No noncompliance noted. Major areas inspected: areas of IE Bulletin 77-14, containment & prestressing sys surveillance program.
CHAPTON, R M Region 2, Atlanta, Office of the Director. HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/07 3pp 07072 293

8011140655 Updates 800801 ltr responding to IE Bulletin 80-06 No mod planned for operation of Feedwater main & Bypass control valves. Scheduled completion date for circuit mods of containment cooling fans & sump pump is 810315.
UHR10,R E Florida Power & Light Co 80/10/21 1p 06965 358

801110522 Forwards orders for mod of Licenses DPR-31 & DPR-41 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl.
VARGA, S A Operating Reactors Branch 1 80/10/24 2pp

--801110527 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820430. Complete records must be available by 801201.
EISENHUT, D G Division of Licensing 80/10/24 4pp 06915 001

--801110537 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment.
" Division of Licensing 80/10/24 2pp

8011170666 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24 1p 06976 254

8011050467 Act receipt of 800923 ltr informing NRC of steps taken to correct violations noted in Health Physics Appraisal Repts 50-250/80-17 & 50-251/80-15.
STOHAR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/28 1p 06898 225

--8011050473 Responds to NRC 800828 ltr re violations noted in Health Physics Appraisal Repts 50-250/80-17 & 50-251/80-15. Corrective actions areas properly posted, ventilation sys modified & preventive maint program to be implemented.
UHR10,R E Florida Power & Light Co 80/09/23 5pp 06898 226

--8011050477 Forwards Health Physics Appraisal Repts 50-250/80-17 & 50-251/80-15 on 800505-16, notice of violation & significant appraisal findings.
O'REILLY, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/08/28 5pp 06898 231

--8011050481 Notice of violation from health physics appraisal on 800505-16.
" Region 2, Atlanta, Office of the Director 80/08/05 1p 06898 236

--8011050496 Health Physics Appraisal Repts 50-250/80-17 & 50-251/80-15 on 800505-16 Noncompliance noted: radiation level of readily accessible radwaste discharge piping in unrestricted area was at 3.5 millirem/h for at least 1-h.
ZAVADOSKI, R W, WRAY, J R Region 2, Atlanta, Office of the Director. GIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/08/05 48pp 06898 237

8011260147 Forwards response to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe." Hoop stress for all fusion welded stainless steel piping used in safety-related sys within 85% of code allowable stress.
UHR10,R E Florida Power & Light Co 80/10/31 5pp 07080 101

8011280114 Responds to IE Bulletin 80-11, "Masonry Wall Design." Re-evaluations of 99 safety-related walls in progress. Final rept scheduled for 810209.
UHR10,R E Florida Power & Light Co 80/11/04 2pp 07083 274

R Periodic operating reports & related correspondence

8011070319 Forwards marked-up draft effluent & waste disposal semiannual rept for 1978. Suggested changes & comments appear on draft.
UHR10,R E Florida Power & Light Co 80/10/23 8pp 06911 001

8011180599 Forwards monthly operating repts for Oct 1980.
SCHMIDT, A D Florida Power & Light Co 80/11/08 1p 06988:097

--8011180604 Monthly operating repts for Oct 1980.
CHILSON, V T Florida Power & Light Co 80/11/08 9pp 06988 098

V Operator Examinations

8011070299 Act receipt of NRC 800731 ltr providing interim criteria for shift staffing. Utili will be in compliance w/criteria by 810601.
UHR10,R E Florida Power & Light Co 80/11/03 1p 06919.309

DOCKET 50-231 TURKEY POINT PLANT, UNIT 4

F Security, medical, emergency & fire protection plans

8011130145 Forwards summary of mods for resolution of open items re NRC proposed rule on min fire protection requirements for facilities operating prior to 790101. Outstanding areas include fire water supply & auxiliary bldg corridor.
VARGA, S A Operating Reactors Branch 1 80/10/09 4pp 02227 001

8011100304 Forwards request for addl info re security plan at facility. Encl withheld (ref 10CFR2.790).
VARGA, S A Operating Reactors Branch 1 80/10/22 2pp

G Adjudicatory correspondence

8011140488 Responds to 800924 ltr requesting confirmation that answers to 800917 meeting questions will be addressed. Suggests arrangements w/licenses for obtaining relevant documents.
GROTEHUIS, M Operating Reactors Branch 1 80/10/17 1p 06963 064

801110922 Forwards orders for mod of Licenses DPR-31 & DPR-41 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl.
VARGA, S A Operating Reactors Branch 1 80/10/24 2pp 06946:184

--801110532 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201 EISENHUT,D G Operating Reactors Branch 1 80/10/24 5pp 06946 192

--801110539 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 197

8011190062 Advises that, contrary to 800923 ltr, draft EIS is expected to be issued by 801219 Previous date could not be met
QOLDBERG,B C Hearing Branch 2 80/11/18 1p 06999 334

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT,D G Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT,D G Division of Licensing 80/10/01 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports" w/o encl
EISENHUT,D G Division of Licensing 80/10/06 6pp

8011030698 Notification of 801023 visit to facilities to view steam generator & study reactor coolant pipe area & channel area
GROTEHUIS,M Operating Reactors Branch 1 80/10/17 1p 06992 194

8011100546 Forwards request for addl info re steam generator repair rept disposal alternatives Descriptions of hurricane resistant properties of storage bldg for steam generator lower assemblies & procedures to assure dryness needed
VARQA,B A Operating Reactors Branch 1 80/10/21 3pp 06931 249

801110105 Confirms 801023 site visit to view reactor coolant pipes & channel cut in steam generator cutting areas
VARQA,B A Operating Reactors Branch 1 80/10/21 2pp 06943 115

801110117 Notifies of completed review re inadvertent safety injection during surveillance testing at Facility Util 791108 response is acceptable
VARQA,B A Operating Reactors Branch 1 80/10/21 2pp 06943, 117.

801110522 Forwards orders for mod of Licenses DPR-31 & DPR-41 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA,B A Operating Reactors Branch 1 80/10/24 2pp

--801110532 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201 EISENHUT,D G Operating Reactors Branch 1 80/10/24 5pp 06946, 192.

--801110539 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp

8011040391 Forwards addl info in response to NRC 800728 ltr re containment ventilation isolation Three oversize electrical drawings encl
UHRIO,R E Florida Power & Light Co 80/10/27 12pp 06913, 013

8011050579 Summarizes 801023 site visit to obtain further understanding of decision by util re cuts made to separate steam generators from reactor sys
GROTEHUIS,M Operating Reactors Branch 1 80/10/29 4pp 06902, 074.

8011210443 Forwards request for addl info generated from review of "Asymmetric LOCA Loading," WCAP-9428 & 9748, dtd Nov 1977 & June 1980, respectively
LAINAB,O C Assistant Director for Safety Assessment 80/10/29 27pp 07029, 170

8011040401 Forwards description & basis for conflicting plans & schedules, in response to NRC 800905 ltr re preliminary clarification of TMI action plan requirements
UHRIO,R E Florida Power & Light Co 80/10/30 4pp 06874 175

8011050436 Forwards responses to Questions 2,3 & 4 of NRC 801021 request for addl info re disposal alternatives Response to Question 1 will be submitted in near future
UHRIO,R E Florida Power & Light Co 80/10/31 12pp 06999 024

8011050474 Forwards supplementary info to assist in endangered species review American crocodile utilizes facility cooling canal sys & adjacent areas for feeding, loafing, mating & nesting Green & loggerhead turtles use cooling canal sys
UHRIO,R E Florida Power & Light Co 80/10/31 7pp 06899 037

8011060260 Responds to NRC 800929 ltr requesting results of ultrasonic testing of low pressure rotor discs One keyway crack found on LP-1 rotor in Number 3 disc on governor end in Unit 3 Eight cracks found on LP-1 & LP-2 rotors in Unit 4
UHRIO,R E Florida Power & Light Co 80/10/31 1p 06909 160

8011210220 Forwards request for info re containment sumps & insulation for operating reactors Concerns are related to creation of debris air entrainment, formation of vortices & emergency procedures
VARQA,B A Operating Reactors Branch 1 80/10/31 4pp 07035, 036

8011100352 Forwards response to Question 1 re disposal alternatives per 801021 request
UHRIO,R E Florida Power & Light Co 80/11/04 6pp 06930 334

8011100390 Forwards responses to NRC 800929 request for addl info re industrial exposure, offsite doses & accident evaluation Questions were discussed at public meeting between respective staffs on 800917
UHRIO,R E Florida Power & Light Co 80/11/04 41pp 06928 277

8011140134 Informs that Emergency Operating Procedure 20,000, immediate actions & diagnostics, has been revised to clarify compliance w/fourth paragraph of Section 2.1.4 to TMI Lessons Learned Category A items
UHRIO,R E Florida Power & Light Co 80/11/10 1p 06964 360

8011280092 Confirms 801114 telcon re strength of welds which seal steam generator sections & method of decontamination to be used If info received by 801121, DES will be issued by 801219
NOVAK,T M Assistant Director for Licensing 80/11/19 3pp 07081, 330

Q Inspection reports, IE Bulletins & correspondence

8010240648 Responds to IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture" Units do not have centrifugal charging pumps.
UHRIO,R E Florida Power & Light Co 80/09/23 1p 06799 197

8011130356 Forwards IE Insp Repts 50-250/80-28, 50-251/80-27, 50-335/80-28 & 50-389/80-11 on 800827-29 No noncompliance noted.
MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/03 2pp 06960 292

--8011130358 IE Insp Repts 50-250/80-28, 50-251/80-27, 50-335/80-28 & 50-389/80-11 on 800827-29 No noncompliance noted Major areas inspected: followup of noncompliance re 10CFR21 procedures
BRONNLEE,V L Region 1, Philadelphia, Office of the Director COMCON,T E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/03 2pp 06960 294.

8011260356 Forwards IE Insp Repts 50-250/80-27 & 50-251/80-26 on 800909-12 No noncompliance noted
MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/10 2pp 07072 291

--8011260362 IE Insp Repts 50-250/80-27 & 50-251/80-26 on 800909-12 No noncompliance noted Major areas inspected: areas of IE Bulletin 79-14, containment & prestressing sys surveillance program
COMPTON,R M Region 2, Atlanta, Office of the Director HERDT,A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/07 3pp 07072 293

8011140655 Updates 800801 ltr responding to IE Bulletin 80-06 No mod planned for operation of feedwater main & bypass control valves. Scheduled completion date for circuit mods of containment cooling fans & sump pump is 801015
UHRIO,R E Florida Power & Light Co 80/10/21 1p 06965, 358.

DOCKETED ITEMS

801110522 Forwards orders for mod of Licenses DPR-31 & DPR-41 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VAROAB A Operating Reactors Branch 1 80/10/24 2pp

--801110532 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D G Operating Reactors Branch 1 80/10/24 5pp

--801110539 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp.

801110664 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/10/24 1p 06976 254

8011050467 Ack receipt of 800923 ltr informing NRC of steps taken to correct violations noted in Health Physics Appraisal Repts 50-250/80-17 & 50-251/80-15
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/10/28 1p 06898 225

--8011050473 Responds to NRC 800828 ltr re violations noted in Health Physics Appraisal Repts 50-250/80-17 & 50-251/80-15.
Corrective actions areas properly posted, ventilation sys modified & preventive maint program to be implemented.
WHRIO, R E Florida Power & Light Co 80/09/23, 5pp 06898:226

--8011050477 Forwards Health Physics Appraisal Repts 50-250/80-17 & 50-251/80-15 on 800505-16, notice of violation & significant appraisal findings
O'REILLY, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/08/28 5pp. 06898 231

--8011050481 Notice of violation from health physics appraisal on 800505-16
* Region 2, Atlanta, Office of the Director 80/08/05 1p 06898 236

--8011050496 Health Physics Appraisal Repts 50-250/80-17 & 50-251/80-15 on 800505-16 Noncompliance noted radiation level of readily accessible radwaste discharge piping in unrestricted area was at 3.5 millirem/h for at least 1-h
ZAVABOSKI, R W, WRAY, J R Region 2, Atlanta, Office of the Director GIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/08/05 48pp. 06898 237.

8011240147 Forwards response to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Hoop stress for all fusion welded stainless steel piping used in safety-related sys within 85% of code allowable stress
WHRIO, R E Florida Power & Light Co 80/10/31 5pp 07080 101

8011280114 Responds to IE Bulletin 80-11, "Masonry Wall Design" Re-evaluations of 99 safety-related walls in progress Final rept scheduled for 810209
WHRIO, R E Florida Power & Light Co 80/11/04 2pp 07083 274

R Periodic operating reports & related correspondence

8011070319 Forwards marked-up draft effluent & waste disposal semiannual rept for 1978 Suggested changes & comments appear on draft.
WHRIO, R E Florida Power & Light Co 80/10/23, 8pp 06911 001

8011180599 Forwards monthly operating repts for Oct 1980
SCHMIDT, A D Florida Power & Light Co 80/11/08, 1p. 06988 097

--8011180604 Monthly operating repts for Oct 1980
CHILBON, V T Florida Power & Light Co 80/11/08 9pp. 06988 098

V Operator Examinations

8011070299 Ack receipt of NRC 800731 ltr providing interim criteria for shift staffing. Util will be in compliance w/criteria by 810601
WHRIO, R E Florida Power & Light Co 80/11/03 1p 06919:309.

DOCKET 80-254 GUAD-CITIES STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8011170336 Forwards comments on revised emergency plan per requirements of NUREG-0654 Plan should be revised to address comments
EISENHUT, D G Division of Licensing 80/10/02 5pp 06976 264

8011170569 Forwards summary mods necessary to resolve open items indicated in NRC 790727 fire protection safety evaluation
NRC 800529 proposed rule on fire protection sets forth criteria for nuclear power plants operating prior to 790101
IPPOLITO, T A Operating Reactors Branch 2 80/10/27, 6pp 06911 001

8011050428 Forwards draft public info package re emergency preparedness for facilities Package has been distributed to States of IL, IA & WI for comment Requests NRC comment by 801121
DELGEOERGE, L D Commonwealth Edison Co 80/11/03 8pp

8011210239 Forwards suppl to safety evaluation re proposed fire protection mods Mods re 3.1 1(i), 3.1 5(f) & 3.1 5(j) are acceptable, Mods re 3.1 5(d), 3.1 5(k), 3.1 6(b) & 3.2 i are unacceptable & need addl mods
IPPOLITO, T A Operating Reactors Branch 2 80/11/05 1p 07032 308

--8011210245 Suppl to safety evaluation re proposed fire protection mod Review status encl
* Operating Reactors Branch 2 80/11/05 7pp. 07032 309

G Adjudicatory correspondence

801110012 Forwards orders for mod of Licenses DPR-25, DPR-29 & DPR-30 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp 06943 223

--8011110035 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp. 06943:233

--8011110041 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06943 239

8011040430 Response to ASLB 801014 order re intention to pursue application Safety evaluation & EIA or EIS will be published in May 1981 Certificate of Bvc encl
GODDARD, R J Hearing Branch 2 80/10/31 2pp 06873 282

8011060381 Responds to ASLB 801014 order Util intends to pursue spent fuel transshipment application, although classified as second in priority to pending spent fuel rack replacement requests
Urges that ASLB jurisdiction be retained
STEPTOE, P P Isham, Lincoln & Beale 80/10/31 3pp 06914 135

8011060493 Withdraws util 801023 request for hearing in view of info presented in Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment"
STEPTOE, P P Isham, Lincoln & Beale 80/10/31 1p 06916 205

P Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition
GRIMES, C I Assistant Director for Engineers & Projects (Prc 790625) 79/03/02 2pp 03149 303.

8011090354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D G Division of Licensing 80/09/05 209pp.

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp

DOCKETED ITEMS

45

801190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance Info should be submitted within 25 days
EISENHUT, D O Division of Licensing 80/10/01 2pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

801110012 Forwards orders for mod of Licenses DPR-25, DPR-29 & DPR-30 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp

--801110035 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O. Division of Licensing 80/10/24 6pp 06943 233.

--801110041 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06943 239

801103077 Submits info re reassessment of scram sys. in response to NRC 801001 ltr. Results of re-evaluation & schedule of implementation will be provided by 801215
JANECEK, R F Commonwealth Edison Co 80/10/27. 2pp 06855 081

8011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201
ABEL, J B Commonwealth Edison Co 80/10/31 1p

801100492 Forwards listing of changes, tests & experiments, w/safety evaluation summaries for each item. Two addl electrical penetrations into reactor bldg were installed Penetrations provide electrical feed from transformer outside bldg
KALIVIANAKIS, N Commonwealth Edison Co 80/11/03 3pp 06931.069

801100389 Forwards page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments
TRAMM, T. R. Commonwealth Edison Co 80/11/03. 2pp

8011240374 Application to amend License DPR-29, changing Tech Specs for extended burnup fuel program Class III amend fas encl
JANECEK, R F. Commonwealth Edison Co 80/11/13 2pp. 07046:347

--8011240381 "Quad Cities 1 Nuclear Generating Plant Extended Burnup Fuel Program "
* General Electric Co NEDO-24855 80/08/31 23pp 07046:349.

--8011240386 Proposed Tech Spec Figure 3 3-1 re max average planar linear heat generation rate
* Commonwealth Edison Co 80/11/13 1p 07047 009.

--8011240393 Revised Page 4-B to "LOCA Analysis Rept " Supplemental discussion of NEDO-24855 encl
* General Electric Co NEDO-24146A 80/11/13 2pp 07047 010

G Inspection reports, IE Bulletins & correspondence

8011040646 Ack receipt of 800509 ltr informing NRC of steps taken to correct violations noted in Waste Packaging Insp Rept 15000039/79-08.
DAVIS, A B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/10/08 1p 06879 357

8011240090 Forwards IE Insp Repts 50-254/80-19 & 50-265/80-21 on 800721-0829 & notice of violation
HEISHMAN, R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/10/15. 2pp 07047.026.

--8011240094 Notice of violation from insp on 800721-0829.
* Region 3, Chicago, Office of the Director. 80/10/08. 1p. 07047.028

--8011240098 IE Insp Repts 50-254/80-19 & 50-265/80-21 on 800721-0829 Noncompliance noted: operator failed to return reactor core isolation cooling sys to normal operating position & improper adjustments performed on exhaust restrictor.
CHRIBBOTT, N., DUPONT, B. O., SPESSARD, R L. Region 3, Chicago, Office of the Director. 80/10/08. 13pp 07047:029.

8011060172 Confirms 801031 meeting w/RL Spessard in Chicago, IL to discuss regulatory performance
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/21 3pp

801120415 Forwards monthly status rept re evaluations performed at facilities in response to IE Bulletin 79-14 W/o encl
JANECEK, R F Commonwealth Edison Co 80/10/21 2pp 06953 361

8011260771 Forwards IE Health Physics Appraisal Repts 50-254/80-20 & 50-265/80-22, notice of violation & significant appraisal findings.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/21 6pp 07072 131

--8011260275 Notice of violation from health physics appraisal on 800305-16.
* Region 3, Chicago, Office of the Director. 80/10/16. 1p 07072.157

--8011260283 IE Health Physics Appraisal Repts 50-254/80-20 & 50-265/80-22 Noncompliance noted uncontrolled access to unposted/unbarricaded & unobserved high radiation area & garments monitored from reissue bins exceeded limit
SCHUMACHER, M C, GRANT, W B, SELBY, J M Region 3, Chicago, Office of the Director 80/10/16 48pp 07072 158

8011280721 Forwards IE Insp Rept 50-254/80-24 on 800909-12 No noncompliance noted
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/10/23 2pp 07083 021.

--8011280224 IE Insp Rept 50-254/80-24 on 800909-12 No noncompliance noted Major areas inspected operational radiation protection program during refueling & maint.
HUETER, L J. Region 3, Chicago, Office of the Director
FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/10/21 13pp 07083 023.

8011070281 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/24 1p 06921 292

801110012 Forwards orders for mod of Licenses DPR-25, DPR-29 & DPR-30 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp

--801110035 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp

--801110041 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 2pp

8011210471 Submits preliminary technical evaluation rept for IE Bulletin 80-06, "Engineered Safety Feature Reset Controls." Util identified 11 sys which may change position upon manual reset at sys level for valves & equipment.
KOUNTANIS, B. EQ&O, Inc. 80/10/27. 3pp 07031.309.

--8011210474 "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Engineered Safety Features Reset Controls for Quad Cities 1 & 2 "
KOUNTANIS, B EQ&O, Inc. 80/10/27 10pp. 07031 312

801190040 Updates NRC 800903 ltr re site access of Region 3 personnel. New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc. Badge examples encl.
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/28 3pp.

801170249 Forwards four isometric drawings which were omitted from Oct 1980 status rept re IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys."
JANECEK, R F. Commonwealth Edison Co. 80/10/29 5pp. 06913:001.

8011200062 Forwards final response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment," per NRC 800919 revised order for mod of license.
ABEL, J B. Commonwealth Edison Co. 80/10/30 3pp 07011 001

DOCKETED ITEMS

--B011200091 Vol 1, Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2"
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 100pp
07012 234

--B011200097 Vol 2 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2"
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 230pp.
07012 340

--B011200094 Vol 3 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2"
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 230pp.
07013 229

--B011200099 Vol 4 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2"
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 160pp
07014 142

--B011200107 Vol 5 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2"
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 180pp
07014-343

B011200539 Forwards IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-265/80-27, 50-295/80-21 & 50-304/80-23 on 801031 No noncompliance noted
KEPPLER, J G Region 3, Chicago, Office of the Director 80/11/06 2pp

--B011200544 IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-265/80-27, 50-295/80-21 & 50-304/80-23 on 801031. No noncompliance noted Major areas discussed performance of activities
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/06 26pp

B011250696 Forwards response to IE Bulletin 80-11, "Masonry Wall Design" Operability assessment performed on walls classified as safety-related but failed to meet acceptance criteria Safe shutdown capability not jeopardized
ABEL, J S Commonwealth Edison Co 80/11/06 23pp

R Periodic operating reports & related correspondence

B011101085 Forwards monthly operating repts for Oct 1980
KALIVIANAKIS, N Commonwealth Edison Co 80/10/31 1p 06943 349

--B011101093 Monthly operating repts for Oct 1980
TUBBS, R C Commonwealth Edison Co 80/11/01 26pp. 06943 350

S Reportable occurrences, LERs & related correspondence

B011030629 Part 21 rept re failure of condition containment atmosphere monitoring sys. reported on 801023 Sensors fail to provide accurate hydrogen concentration measurements following LOCA Analysis of defect re BWRs encl
SHERWOOD, O O General Electric Co 80/10/24 11pp 06860 148

B011100400 Forwards LER 80-027/01T-0
KALIVIANAKIS, N Commonwealth Edison Co 80/10/29 1p 06928 064

--B011100406 LER 80-027/01T-0 on 801013, during IE Bulletin 79-14 reanalysis of safety related piping, ten pipes failed to meet operability criteria Caused by improper const Pipes will be modified to meet requirements prior to startup
KOPACZ, J J Commonwealth Edison Co 80/10/29 3pp 06928 063

B011140014 Forwards LER 80-026/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 80/10/29 1p 06961 312

--B011140019 LER 80-026/03L-0 on 801011, emergency diesel generator 1/2 tripped Caused by short in motor of diesel generator cooling water pumps. Motor replaced w/shop-tested, used motor Shorted motor will be repaired & reinstalled.
STEFFES, C Commonwealth Edison Co 80/10/29 2pp 06961 313

B011250354 Forwards LER 80-029/01T-0
KALIVIANAKIS, N Commonwealth Edison Co 80/11/12 1p 07056:088

B011250348 Forwards LER 80-025/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 80/11/13 1p. 07056:085

--B011250352 LER 80-025/03L-0 on 801007, while performing G08 1300-3, reactor core isolation cooling motor operated valve operability, valve MO-2-1301-49 could not be fully opened Caused by limit switches out of position Switches adjusted
TUBBS, R C Commonwealth Edison Co 80/11/13 2pp 07056 086

V Operator Examinations

B011100481 Forwards response to NRC 800731 ltr transmitting interim criteria for shift staffing & requesting util schedule for compliance Vacancies may create situations requiring overtime in excess of NRC guidelines
JANECEK, R F Commonwealth Edison Co 80/11/05 5pp

B01120492 Forwards response to NRC request for schedule per interim shift staffing requirements
JANECEK, R F Commonwealth Edison Co 80/11/05 5pp

DOCKET 50-255 PALISADES NUCLEAR PLANT

Q Adjudicatory correspondence

B01110500 Forwards order for mod of License DPR-20 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp 06946 173

--B01110506 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06946 176

--B01110513 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 182

B011140051 Notice of appearance in proceeding Certificate of Svc encl
DAUGHERTY, M L Consumers Power Co 80/11/05 3pp 06961 354

B011100627 Supplemental answers to CPC second round of interrogatories providing addl info to 800924 response to Interrogatories 1 & 2, in compliance w/801103 telcon re CPC motion to compel Addresses criteria of imposition of penalty Affidavit encl
BURNS, S O Rulemaking & Enforcement Division 80/11/07 3pp. 06941 001

--B011100629 Requests for admissions directed to CPC re two manual containment isolation valves found in locked open condition on 790911 Referenced documents & Certificate of Svc encl
BURNS, S O Rulemaking & Enforcement Division 80/11/07 69pp 06941 005

B011190013 Notice of 810106-08 depositions of BL Jorgensen, JO Keppler & V Swillo of NRC in Chicago, IL & Washington, DC re notice of violation & order proposing civil penalties Certificate of Svc encl
BIELANSKI, A P, MILLER, M I Consumers Power Co BIELANSKI, A P Isham, Lincoln & Beale 80/11/12 4pp 06999 234

B011250628 Third round of interrogatories propounded to NRC Requests info re items of noncompliance, imposition of civil penalties & regulatory authority. Certificate of Svc encl
BIELANSKI, A P Consumers Power Co 80/11/18 5pp 07069 007

P Operating license stage documents & correspondence

7905090029 Forwards topics deleted from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of ltr
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/04/16 7pp.

7910160306 Forwards request for addl info re loss of offsite power & facility offsite grid Requests response within 90 days.
ZIEMANN, D L Operating Reactors Branch 2 (Pre 791030) 79/09/25, 3pp 01153:070

7910300550 Responds to technical assistance request Plant facilities for mitigating consequences of flooding adequate & acceptable Safety evaluation encl
LAINAS, O Plant Systems Branch (Pre 791030) 79/10/17 1p 01237:072

DOCKETED ITEMS

47

- 7910300552 Safety evaluation supporting acceptability of plant facilities for mitigating consequences of flooding
* Plant Systems Branch (Pre 791030) 79/10/17 20pp 01237 073
- 7911140129 Forwards requests for addl info on structural topics for SEP review
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 791030) 79/10/29 3pp 01326 030
- 7912110020 Forwards updated lists of SEP topics not requiring site review due to ongoing generic licensing activities outside SEP or because of inapplicability to facility
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 800428) 79/11/16 8pp 01532 307
- 7912180081 Forwards draft evaluation of SEP Topic II-1 A, "Exclusion Area Authority & Control," SEP Topic II-1 B, "Population Distribution" & SEP Topic II-1 C, "Potential Hazards Due to Nearby Industrial, Transportation & Military Facilities"
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 800428) 79/11/27 19pp 01611 128
- 7912190466 Submits response to NRC 791029 request for addl info re SEP structural Topic III-2, Topic III-7 B 1, Topic III-7 B 2, Topic III-7 B 3, Topic III-7 B 4, Topic III-7 B 5, Topic III-7 C & Topic III-7 D
HOFFMAN, D P Consumers Power Co 79/12/14 4pp 01622 239
- 7912190487 "Containment Bldg Structural Integrity Test"
* Bechtel Corp 70/11/30 129pp 01622 263
- 7912190496 "Deformation Measurements During Containment Pressure Test"
* Wiss, Janney, Elstner & Association, Inc 70/10/03 35pp 01623 055
- 8002070263 Responds to NRC telcon requesting info re containment Describes fan cooler duty coefficient air cooler duty vs containment temp Submits data re shutdown heat exchanger & mass & energy release for double-ended LOCA
KUEMIN, J L Consumers Power Co 80/01/29 3pp 01938 025
- 8002140231 Notification of 800207 meeting w/util & Bechtel in Bethesda, MD to review acceptability of pipe supports under seismic loading
SILVER, R D Operating Reactors Branch 2 (Pre 800428) 80/02/04 2pp 04016 216
- 8003070274 Requests references to docketed info re SEP topics for NRC review in response to 800117 meeting info due within 90 days
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 800428) 80/02/14 2pp 04138 355
- 8003130577 Forwards drawings per NRC 791012 request re safety sys motor-operated valve control circuits Drawings available in Central Files only
HOFFMAN, D P Consumers Power Co 80/03/03 2pp 04190 003
- 8003130581 "Schematic Diagram Safety Injection Motor Operated Valves"
Sheet 2 of 2
* Bechtel Corp 79/04/03 1p 04190 005
- 8003130585 "Schematic Diagram Safety Injection Motor Operated Valves"
Sheet 3 of 4
* Bechtel Corp 78/09/05 1p 04190 006
- 8003130587 "Schematic Diagram Safety Injection Motor Operated Valves,"
Sheet 2 of 2
* Bechtel Corp 80/03/03 1p 04190 007
- 8003130590 "Schematic Diagram Safety Injection Motor Operated Valves"
Sheet 1 of 4
* Bechtel Corp 78/10/21 1p 04190 008
- 8003130592 "Schematic Diagram Safety Injection Tank Motor Operated Valves," Sheet 1 of 2
* Bechtel Corp 79/04/03 1p 04190 009
- 8004150627 Notifies that current main steam line break analysis requested in NRC 791221 ltr cannot be completed until containment spray problem identified in LER 80-002, is resolved
HOFFMAN, D P Consumers Power Co 80/04/11 1p 04394,363
- 8007180289 Requests comments on causes for & possible remedies for events re site identified in encl rept, "Loss of Offsite Power Survey Status Rept," within 120 days of receipt of ltr
CRUTCHFIELD, D Operating Reactors Branch 5 80/06/19 2pp 05892 177
- 8007250693 Forwards request for addl info re SEP design basis events Requests response within 45 days of ltr receipt
CRUTCHFIELD, D Operating Reactors Branch 5 80/07/01 4pp 05970 021
- 8011030394 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp
- 8011190002 Forwards evaluation of SEP Topics V-11 A, "Electrical Instrumentation & Control Features for Isolation of High & Low Pressure Sys," V-11 B, "RRR Interlock Requirements" & V-11-2, "Onsite Emergency Power Sys"
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/15 34pp 06994 287
- 8011100484 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 9pp
- 8011180050 Advises that SEP Topics II-2 B, II-2 D, II-8 B, VI-B, XV-11, XV-1B, II-1 B & X should be added to 791116 list of topics removed from review due to related generic NRC activities & nonapplicability
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/01 3pp 06984 195
- 8011100937 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp
- 8011110097 Confirms util commitment to NRC 791023 interim position on containment purging & venting Commitments will remain in effect pending completion of NRC long-term review
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/08 3pp 06943 112
- 8011170326 Forwards SEP status rept describing method for data analysis & survey results of loss of power events at facilities Requests comment within 60 days
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/10 42pp 06911:001.
- 8011110300 Forwards order for mod of License DPR-20 re environ qualification of safety-related electrical equipment, Revised Tech Specs also encl.
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp 06946 173
- 8011103006 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06946 176.
- 8011110513 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946:182.
- 8011030499 Forwards Revision 1 to util 801007 rept, "Environ Qualification of Safety-Related Electrical Equipment"
HOFFMAN, D P Consumers Power Co 80/10/30 2pp 06894:042
- 8011030503 Revision 1 to "Environ Qualification of Safety-Related Electrical Equipment"
* Consumers Power Co 80/10/30 50pp 06894:044
- 8011030533 Forwards mods to procedures assisting operators in identifying steam general dryout & operator action if water hammer were to occur, per 801002 ltr
HOFFMAN, D P Consumers Power Co 80/10/31 1p 06855,265.
- 8011030539 Emergency Operating Procedures 1-12.
* Consumers Power Co 80/10/31 5pp 06855:266.

DOCKETED ITEMS

8011040200 Requests exemption from testing frequency of air lock doors as stated in 10CFR50, App. J, Part II, Q 2 Exemption requested to eliminate add'l expense for testing & maint & possible reduction in containment integrity
HOFFMAN, D P Consumers Power Co 80/10/31 2pp 06884 265

8011210001 Advises of delay in completion of SEP Topic XVI, Tech Specs, until completion of all SEP topic reviews & integrated safety assessment Delay will allow evaluation of current Tech Specs w/proposed changes resulting from reviews
CRITCHFIELD, D Operating Reactors Branch 5 80/11/05 2pp 07033 193

8011230452 Submits long-term cooling equipment mods bimonthly status rept for Oct-Nov 1980 Final design details are being prepared Mods are scheduled for 1981 refueling outage
HOFFMAN, D P Consumers Power Co 80/11/20 1p 07068 253

G Inspection reports, IE Bulletins & correspondence

8011180849 Forwards IE Insp Rept 50-255/80-17 on 800826-29 & notice of violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/10/09 2pp 06992 010.

--8011180851 Notice of violation from insp on 800826-29
* Region 3, Chicago, Office of the Director 80/10/07 1p 06992 012

--8011180853 IE Insp Rept 50-255/80-17 on 800826-29, Noncompliance noted interviews w/workmen indicated general lack of knowledge re ignition control practices of fire plan such as hot work area preparation & fire watch
GRUBE, J A., BAKER, R R Region 3, Chicago, Office of the Director 80/10/07 8pp 06992 013

8011070257 Forwards Suppl 3 to IE Bulletin 79-010, "Environ Qualification of Class IE Equipment" No written response required
KEPPLER, J O. Region 3, Chicago, Office of the Director 80/10/24 1p 06924-247

801110300 Forwards order for mod of License DPR-20 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CRITCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp 06946 173

--801110306 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820430 Complete records must be available by 801201
EISENHUT, D G Division of Licensing. 80/10/24 6pp 06946 176

--801110513 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 182

8011190057 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc
BADGE examples encl.
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/28 3pp 06999 186

8011140673 Ack receipt of util 800926 ltr transmitting civil penalty fee & informing of steps taken to correct noncompliance noted in NRC 800916 ltr Item 5 is valid, since no immediate action was taken by licensee to rept item of noncompliance
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/11/04 1p 06963 316

8011260101 Forwards "Palisades 180-Day Response to IE Bulletin 80-11, 'Masonry Wall Design' " Updated rept will be issued upon completion of re-evaluation work re design adequacy
FROST, S R Consumers Power Co 80/11/06 1p 07075,324

--8011260102 "Palisades 180-Day Response to IE Bulletin 80-11, 'Masonry Wall Design' "
* Bechtel Power Corp (subs. of Bechtel Corp) 80/10/31 17pp 07075 335

8011180411 Forwards updated inservice insp program to 1977 edition of Section XI, ASME code w/addenda through Summer 1978 Includes info confirming adequacy of current Tech Specs & addenda to relief request statements re code applicability
HOFFMAN, D P Consumers Power Co 80/11/12 21pp 06991,201

8011190013 Notice of 80106-08 depositions of DL Jorgensen, JO Keppler & V Stello of NRC in Chicago, IL & Washington, DC re notice of violation & order proposing civil penalties Certificate of Svc encl
BIELANSKI, A P, MILLER, M I Consumers Power Co BIELANSKI, A P Isham, Lincoln & Seale 80/11/12 4pp 06999 234

R Periodic operating reports & related correspondence

8011120409 Forwards monthly operating rept for Oct 1980
KENNEDY, D M Consumers Power Co 80/11/07 1p 06950 297

--8011120419 Monthly operating rept for Oct 1980
BODYKE, P J Consumers Power Co 80/11/07 4pp 06950 298

S Reportable occurrences, LERs & related correspondence

8011140452 Forwards LER 80-038/03L-0
HOFFMAN, D P Consumers Power Co 80/11/10 1p 06963 058

--8011140457 LER 80-038/03L-0 on 801016, level in concentrated boric acid tank fell below limit Caused by increase in safety injection/refueling water tank level Proposed change in reporting requirement submitted to NRC
* Consumers Power Co 80/11/10 1p 06963 059

8011180685 Forwards LER 80-039/03L-0
HOFFMAN, D P Consumers Power Co 80/11/14 1p 06991 275

--8011180697 LER 80-039/03L-0 on 801023, during review of testing requirements for CV-3027 & CV-3056 it was determined that valves must be stroked quarterly Caused by testing requirements not addressing potential for degraded equipment
* Consumers Power Co 80/11/14 1p 06991 276

8011180715 Forwards LER 80-041/01T-0
HOFFMAN, D P Consumers Power Co 80/11/14 1p 06991 302

--8011180724 LER 80-041/01T-0 on 801030, during routine surveillance testing of diesel generator 1-2, emergency diesel generator charging was inoperable for tests while pump P-55C was inoperable for repairs Caused by deficient test procedure
* Consumers Power Co 80/11/14 1p 06991,303

8011180730 Forwards LER 80-042/01T-0
HOFFMAN, D P Consumers Power Co 80/11/14 1p 06991 309

--8011180735 LER 80-042/01T-0 on 801031, during plant cooldown, steam generator dp exceeded 1,380 psid limit for approx 85 minutes Caused by operator misplotting of power conversion sys vs pressure Operator counseled
* Consumers Power Co 80/11/14 1p 06991 310

8011180743 Forwards LER 80-040/01T-0
HOFFMAN, D P Consumers Power Co 80/11/14 1p 06991 311

--8011180748 LER 80-040/01T-0 on 801023, while sluicing resins from T-55 to T-67, waste gas monitor RIA-1113 alarmed, indicating airborne release. Caused by leakage in T-50 air supply Waste gas surge tank was pumped down
* Consumers Power Co 80/11/14 1p 06991 312

V Operator Examinations

8011040128 Responds to NRC 800731 ltr re interim criteria for shift staffing. Response outlines plans & schedule for adhering to various criteria, w/discussion on special problems, including personnel shortage & legal union agreement
HOFFMAN, D P Consumers Power Co 80/10/31 4pp 06874 067

DOCKET 50-258 ISOICHEM INC FISSION PROD CONVERSION PLANT

S Reportable occurrences, LERs & related correspondence

8011140055 Interim deficiency rept originally reported on 801014 re defective heating, ventilation & air conditioning isolation dampers Caused by electromechanically unqualified actuators. Supplier submitted proposed mod procedure to vendor
BOROMANN, E A Cincinnati Gas & Electric Co 80/11/04 2pp,

DOCKETED ITEMS

49

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8011060963 Notification of 801027 meeting w/util in Bethesda,MD to discuss emergency planning for facilities
STAHLER,C Licensing Branch 2 CLARK,R A Operating Reactors Branch 2 80/10/16 3pp 06914 222

8011030627 Forwards response to NRC 800822 comments on guard training & qualification plan Plan withheld (ref 10CFR2 790)
MILLS,L M Tennessee Valley Authority 80/10/24 1p 06855 085

8011250406 Forwards addl comments on draft test plan for replication test for fire protection sys Requests meeting w/NRC for resolution of comments & issues w/proposed test plan
MILLS,L M Tennessee Valley Authority 80/11/20 4pp 07056 114

G Adjudicatory correspondence

8011070916 Forwards order for mod of Licenses DPR-33,DPR-52 & DPR-68 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO,T A Operating Reactors Branch 2 80/10/24 2pp 06925 156

--8011070523 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT,D O Division of Licensing 80/10/24 6pp 06925 188

--8011070531 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06925 164

801120280 Requests reconsideration of NRC issuance of Amends 60.55 & 32 to Licenses DPR-33,DPR-52 & DPR-68 respectively Amends authorize temporary storage of low level radwaste in pavilions not designed to withstand winds over 80 mph
PAUL,T W , HORN,B , ELY,D Safe Energy Alliance 80/10/28 3pp 06952 087

P Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation,oscillation, chugging & lateral load definition
GRIMES,C I Assistant Director for Engineers & Projects (Pre 790629) 79/03/02 2pp 03145 305

8011050354 Ltr to all licensees of operating plants,applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT,D O Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT,D O Division of Licensing 80/10/01 3pp

8011190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance Info should be submitted within 25 days
EISENHUT,D O Division of Licensing 80/10/01 2pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " N/o encl
EISENHUT,D O Division of Licensing 80/10/06 6pp

8011060058 FOIA request for Ofc of Analysis & Evaluation of Operational Data 800930 rept, "Interim Equipment & Procedures at Browns Ferry to Detect Water in Scram Discharge Vol "
WEISS,E R Sheldon, Harmon & Weiss 80/10/14 1p 06914 143

8011070516 Forwards order for mod of Licenses DPR-33,DPR-52 & DPR-68 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO,T A Operating Reactors Branch 2 80/10/24 2pp

--8011070523 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT,D O Division of Licensing 80/10/24 6pp

--8011070531 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp

8011060051 Responds to FOIA request for Ofc of Analysis & Evaluation of Operational Data 800930 rept, "Interim Equipment & Procedures at Browns Ferry to Detect Water in Scram Discharge Vol " Forwards rept
FELTON,J M Division of Rules and Records 80/10/31 1p 06914 142

8011100317 Notification of 801107 meeting w/util in Bethesda,MD to discuss NRC position on util application for long-term onsite storage of low level waste
CLARK,R A Operating Reactors Branch 3 80/11/04 2pp 06929 144

8011140107 Ack receipt of EQ&O rept, "Summary Rept BWR Augmented Offgas Treatment Sys Operating Experience " No comment
MILLS,L M Tennessee Valley Authority 80/11/06 1p 06965 001

8011140118 Advises that detailed plan & schedule re environ qualification testing of equipment in safety-related sys will be submitted as soon as available, in response to NRC 801001 request
MILLS,L M Tennessee Valley Authority 80/11/06 1p 06964 362

8011170753 Notification of 801107 meeting between Div of Human Factors Safety,Div of Sys Integration & IE in Bethesda,MD to review interim equipment & procedures to detect water in scram discharge vol
GOODMAN,K J Procedures & Test Review Branch 80/11/06 2pp 06978 332

8011240164 Revises 800731 application to amend Licenses DPR-33,DPR-52 & DPR-68, to authorize onsite low level radwaste storage at facilities for 5 yrs
MILLS,L M Tennessee Valley Authority 80/11/17 2pp 07049 163

G Inspection reports, IE Bulletins & correspondence

8011170223 Ack receipt of 730810 ltr re nuclear engineering committee efforts to develop separation criteria for Class IE equipment & circuits Prefers to endorse satisfactory ANSI std, but AEC is also reactivating work on reg guide
ROGERS,L Atomic Energy Commission - Directorate of Regulatory Standards 73/09/07 2pp 06973 322

--8011170234 Forwards list of outstanding items at facility as of 730417 Util recently changed estimated core loading date from 730515 Loading date of 730615 is more realistic estimate W/o encl
THORNBURG,H D Atomic Energy Commission, Directorate of Regulatory Operations 73/04/26 1p 06973 327

--8011170238 Forwards listing of outstanding items whose status has changed significantly since 730312 memo Unresolved items will not delay licensing Licensee & Region 2 estimated core loading dates are 730515 & 0615, respectively
MOSELEY,N C Atomic Energy Commission, Directorate of Regulatory Operations 73/04/17 7pp 06973 328

8011100104 Forwards IE Insp Repts 80-259/80-31,50-260/80-24 & 80-296/80-29 on 800727-0801 No noncompliance noted
STOHR,J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 2pp 06930 302

--8011100111 IE Insp Repts 80-259/80-31,50-260/80-24 & 80-296/80-29 on 800727-0801 No noncompliance noted, Major areas inspected licensee shipper compliance w/DOE & NRC regulations for shipping paper & placarding requirements
MACARTHUR,T C , POTTER,J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 8pp 06930 304

8011060454 Forwards response to IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Ultrasonic exam of Unit 2 jet pump holddown beams & visual insps of jet pump assembly were made No indications detected
MILLS,L M Tennessee Valley Authority 80/10/03 2pp 06914 358

8011040090 Forwards monthly status rept for work as of 801001 re IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys "
MILLS,L M Tennessee Valley Authority 80/10/10 37pp 06874 073

DOCKETED ITEMS

8011040140 Forwards Progress Rept 5 re IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Rept reflects work progress since until 800910 ltr
MILLS,L.M. Tennessee Valley Authority 80/10/14 4pp 06874 063

8011130119 Forwards response to IE Bulletin 80-13, "Cracking in Core Spray Spargers " Visual insp of spargers conducted on 800911 No abnormalities found
MILLS,L.M. Tennessee Valley Authority 80/10/15 2pp 06956 334

8011170669 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required
O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 80/10/24 1p 06976 250

8011280983 Forwards final response to IE Bulletin 80-11, "Masonry Wall Design " Encl discusses results of re-evaluation program & info requested in Item 2b
CRSBS,J.L. Tennessee Valley Authority 80/11/07 42pp 06915 001.

R Periodic operating reports & related correspondence

8011040329 Forwards quarterly fish impingement rept for period ending 800930
MILLS,L.M. Tennessee Valley Authority 80/10/28 1p 06873 115

--8011040334 Fish impingement rept for quarter ending 800930
* Tennessee Valley Authority 80/10/28 13pp 06873 116

8011180588 Forwards monthly operating repts for Oct 1980
ABERCROMBIE,H. Tennessee Valley Authority 80/11/10 1p 06988 001

--8011180594 Monthly operating rept for Oct 1980
THOM,T., GREEN,D. Tennessee Valley Authority. 80/11/02 32pp 06988 002

8 Reportable occurrences, LERs & related correspondence

8011140033 RD-on 801006, faulty indication on outboard isolation valve of reactor coolant isolation sys would not allow operator to be aware of actual valve position Caused by open circuit in valve position indication Surveillance testing performed
ABERCROMBIE,H. Tennessee Valley Authority 80/10/06 1p 06911:001

8011030629 Part 21 rept re failure of condition containment atmosphere monitoring sys, reported on 801023 Sensors fail to provide accurate hydrogen concentration measurements following LOCA Analysis of defect re BHRs encl
SHERWOOD,O.G. General Electric Co 80/10/24 11pp

8011040424 Forwards LER 80-039/01T-1
CALHOUN,J.R. Tennessee Valley Authority 80/10/27 1p 06884 238

--8011040434 LER 80-039/01T-1 on 800507, during normal operation GE indicated that nuclear qualification of CAK sys hydrogen sensors did not meet purchase specs.Changes to applicable procedures & instructions have been incorporated
* Tennessee Valley Authority 80/10/27 2pp 06884 239.

8011140086 RD-on 801029,HPCI removed from svc due to ground occurring on gland seal condensor pump motor Cause attributed to moisture found in pump HPCI was returned to svc
ABERCROMBIE,H. Tennessee Valley Authority 80/10/29 1p 06911:001.

801120307 Forwards LER 80-075/03L-0
GREEN,H.J. Tennessee Valley Authority 80/11/04 1p 06932 217

--801120517 LER 80-075/03L-0 on 801006, valve position indication for steam supply valve,FCV-71-3, lost Caused by corrosion on terminal block inside junction box Corroded terminals bypassed temporarily & will later be replaced
* Tennessee Valley Authority 80/11/04 2pp 06932:218

801120572 Forwards LER 80-076/03L-0
GREEN,H.J. Tennessee Valley Authority 80/11/05 1p 06916 001

--801120576 LER 80-076/03L-0 on 801007, air differential temp recorders YDR-70-103 & -104 on channels A & B failed Caused by component failure in Model 3430 digital voltmeter Voltmeter repaired
* Tennessee Valley Authority 80/11/05 2pp 06916 001

8011210489 Forwards LER 80-078/03L-0
GREEN,H.J. Tennessee Valley Authority 80/11/10 1p 07029 227

--8011210485 LER 80-078/03L-0 on 801012, Tech Spec limit of 13.32 Kw/ft for linear heat generation rate exceeded in two nodes Caused by long-term xenon transient following preconditioning ramp Control rod insertion restored operation
* Tennessee Valley Authority 80/11/10 2pp 07029 228

8011210537 Forwards LER 80-082/01T-0
GREEN,H.J. Tennessee Valley Authority 80/11/12 1p 07035 023

--8011210548 LER 80-082/01T-0 on 801031, drywell pressure transmitters 1-PT-64-50 & 1-PT-64-67 were not qualified for radiation environ following LOCA, per IE Bulletin 79-018 requirements Cause not stated Models GENAC 552 & 556 replaced.
* Tennessee Valley Authority 80/11/12 2pp 07035 026

8011210601 Forwards LER 80-081/01T-0
GREEN,H.J. Tennessee Valley Authority 80/11/12 1p 07034:207

--8011210608 LER 80-081/01T-0 on 801031,FBV-84-19 (drywell or suppression chamber exhaust to standby gas treatment sys) solenoid coil found not qualified for environ existing after LOCA per IEB 79-018 Coil will be replaced w/qualified part
* Tennessee Valley Authority 80/11/12 2pp 07034 208

8011180694 Forwards LER 80-080/03L-0
GREEN,H.J. Tennessee Valley Authority 80/11/13 1p 06988,132

--8011180701 LER 80-080/03L-0 on 801015, valve O-FCV 39-11 on fire protection sys had actuating piston seal leak Caused by piston cup wearing out w/natural aging Part replaced
* Tennessee Valley Authority 80/11/13 2pp 06988 133

8011250345 Forwards LER 80-079/03L-0
GREEN,H.J. Tennessee Valley Authority 80/11/21 1p 07036 321

--8011250350 LER 80-079/03L-0 on 801025, electrical ground occurred at HPCI EGR actuator, causing failure of EGM output transistors Q9 & Q10 Caused by corrosion between EGR actuator connector & connector pins Actuator & box replaced
* Tennessee Valley Authority 80/11/21 2pp 07036 322

V Operator Examinations

801120298 Advises of plans to comply w/requirements for senior reactor operator by 800630 & for reactor operator by 800630, in response to NRC 800731 ltr transmitting interim criteria
MILLS,L.M. Tennessee Valley Authority 80/11/03 1p 06953:277

8011140325 Forwards info describing operator training & qualification programs which comply w/criteria addressed in 800328 ltr to all power reactor Applicants & licensees
MILLS,L.M. Tennessee Valley Authority 80/11/10 8pp 06960:347

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8011040563 Notification of 801027 meeting w/util in Bethesda,MD to discuss emergency planning for facilities
STAMLER,C. Licensing Branch 2 80/10/16 3pp

8011030627 Forwards response to NRC 800822 comments on guard training & qualification plan, Plan withheld (ref 10CFR2.790),
MILLS,L.M. Tennessee Valley Authority, 80/10/24 1p 06895 085

8011230406 Forwards addl comments on draft test plan for replication test for fire protection sys Requests meeting w/NRC for resolution of comments & issues w/proposed test plan
MILLS,L.M. Tennessee Valley Authority 80/11/20 4pp 07056:114

G Adjudicatory correspondence

8011070516 Forwards order for mod of Licenses DPR-33,DPR-52 & DPR-68 re environ qualification of safety-related electrical equipment, Revised Tech Specs also encl.
EISENHUT,D.O. Operating Reactors Branch 2, 80/10/24 2pp.

--8011070523 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 800630, Complete records must be available by 801201
EISENHUT,D.O. Division of Licensing 80/10/24 6pp 06925 158

--8011070531 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06925 164

801120280 Requests reconsideration of NRC issuance of Amends 60.55 & 32 to Licenses DPR-33, DPR-52 & DPR-68 respectively Amends authorize temporary storage of low level radwaste in pavilions not designed to withstand winds over 80 mph
PAULI, T. W., HORN, S., ELY, D. Safe Energy Alliance 80/10/28 3pp 06932 087

P Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition
GRIGES, C. I. Assistant Director for Engineers & Projects (Pre 790625) 79/03/02 2pp 03145 305

8011050394 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D. G. Division of Licensing 80/09/05 209pp

801100484 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101
EISENHUT, D. G. Division of Licensing 80/10/01 3pp

8011020237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance Info should be submitted within 25 days
EISENHUT, D. G. Division of Licensing 80/10/01 2pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " w/o encl.
EISENHUT, D. G. Division of Licensing 80/10/06 6pp

8011060698 FOIA request for Ofc of Analysis & Evaluation of Operational Data 800930 rept, "Interim Equipment & Procedures at Browns Ferry to Detect Water in Scram Discharge Vol "
WEISS, E. R. Sheldon, Harmon & Weiss 80/10/14 1p 06914 143

8011070514 Forwards order for mod of Licenses DPR-33, DPR-52 & DPR-68 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPCOLITO, T. A. Operating Reactors Branch 2 80/10/24 2pp 06925 156

--8011070523 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines w/UREO-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D. G. Division of Licensing 80/10/24 6pp

--8011070531 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp.

8011060091 Responds to FOIA request for Ofc of Analysis & Evaluation of Operational Data 800930 rept, "Interim Equipment & Procedures at Browns Ferry to Detect Water in Scram Discharge Vol " Forwards rept
FELTON, J. M. Division of Rules and Records, 80/10/31 1p 06914 142

801100317 Notification of 801107 meeting w/util in Bethesda, MD to discuss NRC position on util application for long-term onsite storage of low level waste
CLARK, R. A. Operating Reactors Branch 3 80/11/04 2pp. 06929 144

801100050 Confirms 801106 telcon & forwards proposed mods to facility fuel handling procedures, changes will resolve NRC concerns
MILLS, L. M. Tennessee Valley Authority 80/11/06 3pp. 06928 254

801140107 Ack receipt of EG&O rept, "Summary Rept-BWR Augmented Offgas Treatment Sys Operating Experience." No comment
MILLS, L. M. Tennessee Valley Authority. 80/11/06 1p. 06963 001

801140118 Advises that detailed plan & schedule re environ qualification testing of equipment in safety-related sys will be submitted as soon as available, in response to NRC 801001 request
MILLS, L. M. Tennessee Valley Authority 80/11/06 1p 06964 362

801170753 Notification of 801107 meeting between Div of Human Factors Safety, Div of Sys Integration & IE in Bethesda, MD to review interim equipment & procedures to detect water in scram discharge vol
GOODMAN, M. J. Procedures & Test Review Branch 80/11/06 2pp. 06978: 332

8011240164 Revises 800731 application to amend Licenses DPR-33, DPR-52 & DPR-68, to authorize onsite low level radwaste storage at facilities for 5 yrs
MILLS, L. M. Tennessee Valley Authority 80/11/17 2pp 07049 163.

G Inspection reports, IE Bulletins & correspondence

801100104 Forwards IE Insp Repts 50-259/80-31, 50-260/80-24 & 50-296/80-25 on 800727-0801 No noncompliance noted
STOHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 2pp 06930 302

--801100111 IE Insp Repts 50-259/80-31, 50-260/80-24 & 50-296/80-25 on 800727-0801 No noncompliance noted Major areas inspected licensee shipper compliance w/DOE & NRC regulations for shipping paper & placarding requirements
MACARTHUR, T. C., POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 8pp 06930 304

8011060454 Forwards response to IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Ultrasonic exam of Unit 2 jet pump holddown beams & visual insp of jet pump assembly were made No indications detected
MILLS, L. M. Tennessee Valley Authority 80/10/03 2pp 06914 358

8011040090 Forwards monthly status rept for work as of 801001 re IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys "
MILLS, L. M. Tennessee Valley Authority 80/10/10 37pp. 06874 073

8011040140 Forwards Progress Rept 5 re IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Rept reflects work progress since until 800910 ltr
MILLS, L. M. Tennessee Valley Authority 80/10/14 4pp 06874 063

801130119 Forwards response to IE Bulletin 80-13, "Cracking in Core Spray Spargers " Visual insp of spargers conducted on 800911 No abnormalities found
MILLS, L. M. Tennessee Valley Authority 80/10/15 2pp. 06956 354

801170569 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/24. 1p 06976 250.

8011280083 Forwards final response to IE Bulletin 80-11, "Masonry Wall Design " Encl discusses results of re-evaluation program & info requested in Item 2b
CROSS, J. L. Tennessee Valley Authority 80/11/07 42pp 06915 001.

R Periodic operating reports & related correspondence

8011040529 Forwards quarterly fish impingement rept for period ending 800930
MILLS, L. M. Tennessee Valley Authority 80/10/28 1p 06873 115

--8011040534 Fish impingement rept for quarter ending 800930.
* Tennessee Valley Authority 80/10/28 15pp. 06873 116

801180588 Forwards monthly operating repts for Oct 1980
ABERCROMBIE, H. Tennessee Valley Authority 80/11/10 1p 06988 001

--801180594 Monthly operating rept for Oct 1980
THOM, T., GREEN, D. Tennessee Valley Authority. 80/11/02 32pp 06988 002

S Reportable occurrences, LERs & related correspondence

8011030629 Part 21 rept re failure of condition containment atmosphere monitoring sys, reported on 801023 Sensors fail to provide accurate hydrogen concentration measurements following LOCA. Analysis of defect re BWRs encl
SHERROD, O. G. General Electric Co 80/10/24 11pp.

DOCKETED ITEMS

8011040471 Forwards LER 80-042/03L-0
CALHOUN, J R Tennessee Valley Authority 80/10/27 1p 06874 136

--8011040484 LER 80-042/03L-0 on 800929, during leak rate testing on main steam isolation valves, Valves 1-14, 1-15, 1-26 & 1-52 exceeded allowable leakage rate Caused by seating surface deterioration Valves repaired & retested
* Tennessee Valley Authority 80/10/27 2pp 06874 137

8011120448 Forwards LER 80-043/03L-0
GREEN, H J Tennessee Valley Authority 80/11/06 1p 06916 001

--8011120457 LER 80-043/03L-0 on 801039, during refueling operations, 17 level switches would not operate Caused by crud from sys accumulating on float, preventing operation of level switch
Switches cleaned, one replaced
* Tennessee Valley Authority 80/11/06 2pp 06916 001

8011140381 Forwards LER 80-044/03L-0
GREEN, H J Tennessee Valley Authority 80/11/10 1p 06968 181

--8011140382 LER 80-044/03L-0 on 801012, refueling zone inboard isolation time delay relay R3A found out of tolerance & nonrepetitive Caused by relay failure Relay, Agastat Model 7022 AB, replaced & calibr
* Tennessee Valley Authority 80/11/10 2pp 06968 182

8011210457 Forwards LER 80-045/01T-0
GREEN, H J Tennessee Valley Authority 80/11/14 1p 07029 206

--8011210458 LER 80-045/01T-0 on 801107, door latch mechanism failed on equipment access doors 237 & 238 between turbine bldg & reactor bldg Caused by misaligned latch pin Door adjusted
* Tennessee Valley Authority 80/11/14 2pp 07029 207

8011250428 RO 80-047 on 801107, max chlorination levels measured in raw cooling water exceeded total chlorine residual of 0.05 mg/l Cause not stated Corrective action not yet determined
MILLS, L M Tennessee Valley Authority 80/11/18 2pp 02227 001

8011250376 Forwards LER 80-047/04T-0
GREEN, H J Tennessee Valley Authority 80/11/20 1p 07056 332

--8011250384 LER 80-047/04T-0 on 801107, component cooling water pumps found not operating, thus not providing adequate dilution of water to environ Caused by component cooling water pumps being out of svc Plant instructions revised
* Tennessee Valley Authority 80/11/20 2pp 07056 333

8011250436 Forwards LER 80-046/01T-0
GREEN, H J Tennessee Valley Authority 80/11/24 1p 07056 346

--8011250442 LER 80-046/01T-0 on 801105, internals for excess flow check valve in instrument line to PD15-75-28, -56, PDT-85-17, PDT-85-18, PI-85-19 & PDT-68-52 found missing Caused by const installation error
* Tennessee Valley Authority 80/11/24 2pp 07056 347

V Operator Examinations

801120298 Advises of plans to comply w/requirements for senior reactor operator by 800530 & for reactor operator by 820530, in response to NRC 800731 ltr transmitting interim criteria
MILLS, L M Tennessee Valley Authority 80/11/03 1p 06953 277

8011140325 Forwards info describing operator training & qualification programs which comply w/criteria addressed in 800328 ltr to all power reactor applicants & licensees
MILLS, L M Tennessee Valley Authority 80/11/10 8pp 06960 347

DOCKET 80-261 H B ROBINSON PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8011100003 Requests participation in study of people-related security problems in licensed nuclear industry
VARQA, B A Operating Reactors Branch 1 80/08/14 1p 06943 206

801120404 Submits fire protection mode implementation status at facility Procedures, required Tech Specs & training for listed SER items completion expected by 801130
UTLEY, E E Carolina Power & Light Co 80/11/05 3pp 06990, 330.

G Adjudicatory correspondence

801110488 Forwards order for mod of License DPR-23 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, B A Operating Reactors Branch 1 80/10/24 2pp 06944, 277

--801110493 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06944 299

--801110498 Revised Tech Spec pages per 801024 order for mod at license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944 305

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements, Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 207pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01 3pp

8011030231 Forwards Amend 51 to License DPR-23 & notice of issuance & availability
VARQA, B A Operating Reactors Branch 1 80/10/06 3pp 06857 222

--8011030238 Amend 51 to License DPR-23, adding requirement to maintain safeguards contingency plan to be fully implemented within 30 days of approval
VARQA, B A Operating Reactors Branch 1 80/10/06 2pp 06857-225

--8011030240 Notice of issuance & availability of Amend 51 to License DPR-23
VARQA, B A Operating Reactors Branch 1 80/10/06 2pp 06857 227

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" w/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

801130022 Forwards Amend 52 to License DPR-23, safety evaluation & notice of issuance & availability
VARQA, B A Operating Reactors Branch 1 80/10/22 2pp, 06958 060

--801130028 Amend 52 to License DPR-23, changing Tech Specs re setpoints, calibr & surveillance requirements associated w/degraded voltage protection sys for Class IE equipment
VARQA, B A Operating Reactors Branch 1 80/10/22 6pp 06958 062

--801130030 Safety evaluation supporting Amend 52 to License DPR-23
* Office of Nuclear Reactor Regulation, Director 80/10/22 4pp 06958 068

--801130033 Notice of issuance & availability of Amend 52 to License DPR-23
VARQA, B A Operating Reactors Branch 1 80/10/22 2pp, 06958 072

801110488 Forwards order for mod of License DPR-23 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, B A Operating Reactors Branch 1 80/10/24 2pp 06944 297

--801110493 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630, Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06944, 279.

--801110498 Revised Tech Spec pages per 801024 order for mod at license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944 305.

DOCKETED ITEMS

53

8011070157 Summary of 801015 meeting w/util re recent & future insps of steam generators
MINER,S Operating Reactors Branch 1 80/10/29 3pp 06920 278

8011210443 Forwards request for addl info generated from review of "Asymmetric LOCA Loading," WCAP-9623 & 9748, dtd Nov 1979 & June 1980, respectively
LAINA,B Q C Assistant Director for Safety Assessment 80/10/29 27pp 07029 170

801120397 Requests balance of payment for 800509 application for clarification of term "operable"
DIQGS,R M License Fee Management Branch 80/10/30 1p 06953 081

801170651 Forwards request for info re containment sumps & insulation
Concerns have been identified re containment sump design & effect on long-term cooling following LOCA Info needed in developing appropriate range of test parameters
VARQA,S A Operating Reactors Branch 1 80/10/31 4pp 06972 351

801120393 Submits info re environ qualification testing of safety-related electrical equipment, in response to NRC 801001 request Complete schedule of tests to be performed within next 2 yrs not available
UTLEY,E E Carolina Power & Light Co 80/11/05 2pp 06953 093

801140090 Forwards request for license amend incorporating TMI Lessons Learned Category A items, Forwards proposed Tech Spec revisions & Class III amend fee Fee submitted under protest
UTLEY,E E Carolina Power & Light Co 80/11/05 2pp 06965 009

--801140094 Proposed Tech Spec revisions incorporating TMI Lessons Learned Category A items
* Carolina Power & Light Co 80/11/05, 30pp, 06965-011

801180356 Forwards proposed Tech Specs changes to radiological effluent & environ monitoring sys in response to NRC request Responses to NRC 800602 ltr transmitting comments on 790531 submittal encl
UTLEY,E E Carolina Power & Light Co 80/11/10 2pp 06992 178

--801180361 Proposed Tech Specs changes to radiological effluent & environ monitoring sys
* Carolina Power & Light Co 80/11/10 98pp 06992 180

--801180365 "Process Control Program for Solidification of Certain Wet Wastes"
* Carolina Power & Light Co 80/11/10 3pp 06992 278

8011260192 Forwards addl amend fee requested by NRC 801030 ltr re 800509 application for license amend Util supports original assessment of classification, but is remitting addl fee to facilitate review of request
UTLEY,E E Carolina Power & Light Co 80/11/19, 1p 07080 110.

G Inspection reports, IE Bulletins & correspondence

8011040352 Forwards IE Insp Rept 50-261/80-23 on 800903-05 No noncompliance noted
MURPHY,C E, Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/09/26 2pp 06873 236

--8011040357 IE Insp Rept 50-261/80-23 on 800903-05, No noncompliance noted, Major areas inspected inservice insp program, procedures, records & IE Bulletin 79-13
BLAKE,J Region 2, Atlanta, Office of the Director HERDT,A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/09/22, 4pp 06873 238

8011030297 Forwards IE Insp Rept 50-261/80-20 on 800825-29 No noncompliance noted
MURPHY,C E, Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/30 2pp, 06899 166

--8011030300 IE Insp Rept 50-261/80-20 on 800825-29 No noncompliance noted Major areas inspected installed electrical equipment per IE Bulletin 79-018 response
HARDWICK,R J, MERRIWEATHER,N Region 2, Atlanta, Office of the Director, CONLON,T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/26 5pp, 06899 168

8011210429 Forwards IE Insp Rept 50-261/80-28 on 800908-12 No noncompliance noted,
LEWIS,R C, Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/10/06 2pp, 07033 356

--8011210431 IE Insp Rept 50-261/80-28 on 800908-12 No noncompliance noted Major areas inspected procedure review, LERs & operations
HARDIN,A K Region 2, Atlanta, Office of the Director KELLCOO,P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/10/06 5pp 07033 358

801110488 Forwards order for mod of License DPR-23 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA,S A Operating Reactors Branch 1 80/10/24 2pp 06944 277

--801110493 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0988 required by 820630 Complete records must be available by 801201
EIBERHUT,D G Division of Licensing 80/10/24 6pp 06944 299

--801110498 Revised Tech Spec pages per 801024 order for mod at license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944 305

801170660 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required
O'REILLY,J P Region 2, Atlanta, Office of the Director 80/10/24 1p 06976 298

8011100461 Resubmits 800603 response to IE Bulletin 80-12 re decay heat removal sys operability Hardware, administrative controls & procedural safeguards have been reviewed & found to be adequate w/one exception
FURR,B J Carolina Power & Light Co 80/10/27 2pp 06940 343

8011050247 Ack receipt of 801007 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/80-21
LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/10/28 1p 06899 129

--8011050257 Responds to NRC 800916 ltr re violations noted in IE Insp Rept 50-261/80-21 Corrective actions valve opened Plant procedures modified to ensure both normal & backup cover gas regulators remain in svc
STARKEY,R D Carolina Power & Light Co 80/10/07 4pp, 06899 130

--8011050261 Forwards IE Insp Rept 50-261/80-21 on 800818-22 & notice of violation
LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/16 2pp 06899 134

--8011050264 Notice of violation from insp on 800818-22
* Region 2, Atlanta, Office of the Director 80/09/15 2pp 06899 136

--8011050268 IC Insp Rept 50-261/80-21 on 800818-22 Noncompliance noted failure to review procedure changes, to establish maint procedures & to complete required operator reading
MCDONALD,J A Region 2, Atlanta, Office of the Director KELLCOO,P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/15 5pp 06899 138

8011070157 Summary of 801015 meeting w/util re recent & future insps of steam generators
MINER,S Operating Reactors Branch 1 80/10/29 3pp 06920 278

8011280143 Requests extension for response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," to accommodate extensive revisions & expansion of scope
UTLEY,E E Carolina Power & Light Co 80/10/30 2pp 07083 282

8011070498 Discusses steam generator insp followup Corrective action re excessive primary-to-secondary leakage will include normal reactor shutdown, identification & repair of any leaking tubes & discussion w/NRC concerning situation
UTLEY,E E Carolina Power & Light Co 80/11/03 1p 06921 015

8011280031 Forwards final response to IE Bulletin 80-11, "Masonry Wall Design," Walls near safety-related sys or equipment have been reinforced w/structural steel supports
FURR,B J, Carolina Power & Light Co 80/11/03 15pp, 07082 206

R Periodic operating reports & related correspondence

801140391 Forwards monthly operating rept for Oct 1980,
STARKEY,R B, Carolina Power & Light Co 80/11/10, 1p, 06963 028.

DOCKETED ITEMS

--8011140392 Monthly operating rept for Oct 1980
WATFORD, M L Carolina Power & Light Co 80/11/04 3pp
06963 029

S Reportable occurrences, LERs & related correspondence

8011030417 Forwards LER 80-024/01T-0
STARKEY, R B Carolina Power & Light Co 80/10/28 1p 06857 201

--8011030423 LER 80-024/01T-0 on 801014, small fire was reported inside containment & airlock door interlocks failed to function Cause not stated Airlock door & interlock were repaired & placed in satisfactory sealed condition
STARKEY, R B Carolina Power & Light Co 80/10/28 2pp
06857 202.

801100386 Forwards LER 80-025/01T-0
STARKEY, R B Carolina Power & Light Co. 80/11/04 1p 06928 070

--801100391 LER 80-025/01T-0 on 801021, during test of reactor protection logic, reactor protection relay RT-7 in reactor protection train A failed On 801022, relays RT-1 & RT-3 in train B failed Caused by de-energized relay coils Relays replaced
STARKEY, R B Carolina Power & Light Co 80/11/04 2pp
06928 071

8011170432 Forwards LER 80-026/01T-0
STARKEY, R B Carolina Power & Light Co 80/11/13 1p 06977 269

--8011170444 LER 80-026/01T-0 on 801030, valve SI-892A found shut Caused by normally locked-open spray additive tank educator feed isolation valve mistaken for valve on operating work procedure & inadvertently closed. Procedure will be revised
STARKEY, R B Carolina Power & Light Co 80/11/13 2pp
06977 266

V Operator Examinations

8011120437 Submits info re shift staffing in response to NRC 800731 ltr transmitting interim criteria
UTLEY, E E Carolina Power & Light Co 80/11/05 1p 06953 092

DOCKET 30-263 MONTICELLO NUCLEAR GENERATING PLANT

F Security, medical, emergency & fire protection plans

8011190743 Forwards NRC evaluation of util 800528 & 0604 responses to fire protection safety evaluation open issues Proposed resolution is acceptable Safety evaluation will be issued upon completion of NRC evaluation
IPPOLITO, T A Operating Reactors Branch 2 80/10/29 8pp
06996 235

8011200015 Forwards revised 10CFR50.48, suspending fire mod completion dates Applicability to facility not yet determined.
EISENHUT, D O Division of Licensing 80/10/31 5pp 07015 356

J Adjudicatory correspondence

11070486 Forwards order for mod of License DPR-22 re environ qualification of safety-related electrical equipment
Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp
06925 136

8011070493 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06925 138

8011070497 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06925, 144

70027 Order granting extension until 801117 for Commission to ct whether to review ALAB-611
LK, B J Office of the Secretary of the Commission 80/11/03
06924 301

*76 Forwards errata sheet to 801015 submittal re Categories A & resolved generic safety issues per NUREG-0510 that ct safe operation of facility Contains corrections incorporated in suppl to 730203 safety evaluation
R O Hearing Branch 1 80/11/05 3pp 06920 303

801110235 Memorandum disclosing prior involvement in conversion to full-term QL proceeding as member of ACRS from 660801-720512 Conclusions on merits not formed impartiality
unimpaired Objections must be received by 801112
HENDRIE, J M Commissioners 80/11/06 2pp 06944 057

--801110240 Advises of remaining unresolved issue re concerns expressed in NRC 740404 ltr on prompt relief trip says Design changes per Reg Guide 1.22 required prior to installation
BASDEKAS, D L Atomic Energy Commission, Deputy Director for Technical Review (Pre-1975) 74/05/24 2pp 06944 059

--801110245 Reports results of 700507-09 & 0611-13 meetings w/util to review reactor vessel nozzle safe ends proposed changes Supports changes if properly executed to increase assurance of trouble-free operation
HENDRIE, J M ACRS - Advisory Committee on Reactor Safeguards 70/06/15 2pp 06944 061

--801110252 Reports results of 700108-10 review & 691129 ACRS subcommittee re application to operate BNR at 1670 MW power levels Supports application if due regard is given to certain items identified in ltr
HENDRIE, J M ACRS - Advisory Committee on Reactor Safeguards 70/01/10 3pp 06944 063

8011280016 Order affirming ASLB dismissal of proceeding re conversion of provisional to full term QL All intervenors withdrew Bua sponte review of issues raised by licensee & NRC 801015 response disclosed no basis to disagree w/dismissal
BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/11/24 6pp 07084 023

O Advisory Committee on Reactor Safeguards reports & correspondence

801110235 Memorandum disclosing prior involvement in conversion to full-term QL proceeding as member of ACRS from 660801-720512 Conclusions on merits not formed impartiality
unimpaired Objections must be received by 801112
HENDRIE, J M Commissioners 80/11/06 2pp 06944 057

--801110245 Reports results of 700507-09 & 0611-13 meetings w/util to review reactor vessel nozzle safe ends proposed changes Supports changes if properly executed to increase assurance of trouble-free operation
HENDRIE, J M ACRS - Advisory Committee on Reactor Safeguards 70/06/15 2pp 06944 061

--801110252 Reports results of 700108-10 review & 691129 ACRS subcommittee re application to operate BNR at 1670 MW power levels Supports application if due regard is given to certain items identified in ltr
HENDRIE, J M ACRS - Advisory Committee on Reactor Safeguards 70/01/10 3pp 06944 063

P Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition
GRIMES, C I Assistant Director for Engineers & Projects (Pre 790625) 79/03/02 2pp 03145 303

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

8011190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance Info should be submitted within 25 days
EISENHUT, D O Division of Licensing 80/10/01 2pp

8011009337 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl.
EISENHUT, D O Division of Licensing 80/10/06 6pp

DOCKETED ITEMS

55

8011030594 Responds to 801001 ltr re addl design & performance criteria developed by DHR owners subgroup Instrument discharge vols w/four hi level scram instruments & dedicated drain line will be installed Mods scheduled for completion by May 1981
MAYER, L Q Northern States Power Co 80/10/24 6pp 06861 177

8011070486 Forwards order for mod of License DPR-22 re environ qualification of safety-related electrical equipment
Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24, 2pp
06925 136

--8011070493 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0988 required by 800630
Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06925 138

--8011070497 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06925 144

8011070176 Forwards errata sheet to 801015 submittal re Categories A & B of unresolved generic safety issues per NUREG-0510 that may impact safe operation of facility Contains corrections to be incorporated in suppl to 730205 safety evaluation
BACHMANN, R O Hearing Branch 1 80/11/05 3pp 06920 303

8011130411 Responds to Eisenhut 801001 request to submit specific info re equipment environ qualification tests to be conducted within two yrs No specific plans to conduct unique tests exist at this time
MAYER, L O Northern States Power Co 80/11/06 1p 06958 263

8011180248 Informs NRC of schedule for completing installation & providing design info & Tech Spec changes for proposed mod to reactor protection sys power supply installation will be completed during 810515 refueling outage
MAYER, L O Northern States Power Co 80/11/12 1p 06987 333

8011170555 Responds to NRC 801031 ltr requesting implementation dates for revised post-TMI requirements Advises that NRC ltr was not received until 801110, reducing 45-day response time by 10 days Efforts will be undertaken to prepare response
MAYER, L O Northern States Power Co 80/11/14 2pp 06977 311

8011210482 Advises of delay in completion of NRC 790808 request re adequacy of electric distribution sys voltages Preliminary calculations have been completed on load flow computer Rept will be sent within 8 wks
MAYER, L O Northern States Power Co 80/11/17 1p 07035 113

G Inspection reports, IE Bulletins & correspondence

8011210183 Forwards IE Insp Rept 80-263/80-17 on 800918-19 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/15, 2pp 07029 328

--8011210190 IE Insp Rept 80-263/80-17 on 800918-19 No noncompliance noted, Major areas inspected: core power distribution limits, reactor shutdown margin determination & reactivity anomaly determination
HOPKINS, J B., CHOULES, N C Region 3, Chicago, Office of the Director
STREETER, J F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/14 4pp, 07029 330

8011070273 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required,
KEPPLER, J O, Region 3, Chicago, Office of the Director 80/10/24, 1p, 06921-272

8011190034 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc
Badge examples encl,
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28 3pp 06999, 162

8011180508 Forwards response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" W/o EDS Nuclear, Inc, Rept 01-0910-1087, Revision 2
GILBERTS, D E Northern States Power Co 80/10/31, 2pp, 06991 234

8011190341 Forwards response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" Rept describes method of responding to bulletin, summarizes equipment evaluation & presents method for resolution of outstanding items
GILBERTS, D E Northern States Power Co 80/10/31 300pp
07000 116

8011260104 Provides written notification of delay in response to IE Bulletin 80-11, "Masonry Wall Design," due to work load involved Required info will be submitted by 801114
GILBERTS, D E Northern States Power Co 80/11/04 2pp 07075 354

8011280101 Responds to IE Bulletin 80-11, "Masonry Wall Design" Investigation determined 117 accessible walls subj to bulletin requirements Forwards list of walls subj to re-evaluation & types of matl used in const
GILBERTS, D E Northern States Power Co 80/11/14 75pp
07081 335

R Periodic operating reports & related correspondence

8011205333 Forwards monthly operating rept for Oct 1980
MAYER, L O Northern States Power Co 80/11/06 1p 06950 283

--8011120538 Monthly operating rept for Oct 1980
MYRARD, A Northern States Power Co 80/11/05 4pp 06950 284

S Reportable occurrences, LERs & related correspondence

8011030597 Forwards LER 80-029/03L-0
MAYER, L O Northern States Power Co 80/10/30 1p, 06855-228

--8011030603 LER 80-029/03L-0 on 800930, operator insp revealed main steam leak in drain line to condenser Leak on tee due to erosion & impingement, caused by flow of steam & water from restricting orifice upstream of tee
OVERLID, T W Northern States Power Co 80/10/30 1p 06855 229

8011210449 Forwards LER 80-030/03L-0
MAYER, L O Northern States Power Co 80/11/14 1p 07032-230,

--8011210450 LER 80-030/03L-0 on 801013, during normal plant operations, attempt to close drywell floor drain sump outboard isolation valve AO-2541-B failed Caused by loss of resilience due to end of life of Buna-N diaphragm in solenoid, 5V-2541-B,
THURMAN, P Northern States Power Co 80/11/14 1p 07032 231

V Operator Examinations

8011030197 Concludes that Item 1, "A 1 a Experience" contained in 800611 submittal in response to D Eisenhut 800507 ltr identifying five new TMI-2 requirements, does not satisfy criteria for reactor operator training & licensing
COLLINS, P F Operator Licensing Branch 80/10/20 2pp 06857:139

8011030435 Responds to NRC 800731 ltr re interim criteria for shift staffing, Training program for addl entry level personnel scheduled for completion 820701 Other programs clarified & schedule delineated
MAYER, L O Northern States Power Co 80/10/29 2pp, 06855:092,

DOCKET 50-264 DDW CHEMICAL CO

G Inspection reports, IE Bulletins & correspondence

8011060271 Forwards IE Insp Rept 50-264/80-01 on 800828-29 No noncompliance noted
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch, 80/09/16 2pp 06911 232

--8011060274 IE Insp Rept 50-264/80-01 on 800828-29 No noncompliance noted, Major areas inspected: emergency planning, facilities, equipment, drills & training
GREER, R J, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/09/15 3pp 06911-234

DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8011170336 Forwards comments on revised emergency plan per requirements of NUREG-0654, Plan should be revised to address comments
EISENHUT, D O Division of Licensing 80/10/02 5pp,

DOCKETED ITEMS

B01170569 Forwards summary mods necessary to resolve open items indicated in NRC 790727 fire protection safety evaluation NRC 800529 proposed rule on fire protection sets forth criteria for nuclear power plants operating prior to 790101. IFFOLITO, T A Operating Reactors Branch 2 80/10/27 6pp 06911.001

B01105042B Forwards draft public info package re emergency preparedness for facilities Package has been distributed to States of IL, IA & WI for comment Requests NRC comment by B01121 BELGEORGE, L D Commonwealth Edison Co 80/11/03 8pp

B011210239 Forwards suppl to safety evaluation re proposed fire protection mods Mods re 3 1 1(i), 3 1 5(f) & 3 1 5(j) are acceptable Mods re 3 1 5(d), 3 1 5(i), 3 1 5(b) & 3 2 1 are unacceptable & need add'l mods IFFOLITO, T A Operating Reactors Branch 2 80/11/05 1p 07032 308

--B011210245 Suppl to safety evaluation re proposed fire protection mods Review status encl * Operating Reactors Branch 2 80/11/05 7pp 07032 309

Q Adjudicatory correspondence

B01110012 Forwards orders for mod of Licenses DPR-25, DPR-29 & DPR-30 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl IFFOLITO, T A Operating Reactors Branch 2 80/10/24 2pp 06943 223

--B01110050 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0988 required by 820630 Complete records must be available by 801201 EISENHUT, D G Division of Licensing 80/10/24 6pp 06943 241

B01110058 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment * Division of Licensing 80/10/24 2pp 06943 247

11040430 Response to ASLB 801014 order re intention to pursue application Safety evaluation & EIA or EIS will be published in May 1981 Certificate of Svc encl GDDARD, R J Hearing Branch 2 80/10/31 2pp

.D11060381 Responds to ASLB 801014 order Util intends to pursue spent fuel transshipment application, although classified as second in priority to pending spent fuel rack replacement requests Urges that ASLB jurisdiction be retained STEPTOE, P P Isham, Lincoln & Beale 80/10/31 3pp

B011060453 Withdraws until 801023 request for hearing in view of info presented in Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" STEPTOE, P P Isham, Lincoln & Beale 80/10/31 1p

Operating license stage documents & correspondence

703200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition GRIMES, C F Assistant Director for Engineers & Projects (Pw 790629) 79/03/02 2pp 03145 305

11050354 Ltr to all licensees of operating plants, applicants for OLS & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements EISENHUT, D G Division of Licensing 80/09/05 207pp

11100486 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101 EISENHUT, D G Division of Licensing 80/10/01 5pp

1190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required rds to assure adequate short-term performance Info should be submitted within 25 days EISENHUT, D G Division of Licensing 80/10/01 2pp

B011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issues A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl EISENHUT, D G Division of Licensing 80/10/06 6pp

B01110012 Forwards orders for mod of Licenses DPR-25, DPR-29 & DPR-30 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl IFFOLITO, T A Operating Reactors Branch 2 80/10/24 2pp

--B01110050 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0988 required by 820630 Complete records must be available by 801201 EISENHUT, D G Division of Licensing 80/10/24 6pp 06943 241

--B01110058 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment * Division of Licensing 80/10/24 2pp 06943 247

B011030577 Submits info re reassessment of scram sys. in response to NRC 801001 ltr Results of re-evaluation & schedule of implementation will be provided by 801215 JANECEK, R F Commonwealth Edison Co 80/10/27 2pp

B011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201 ABEL, J S Commonwealth Edison Co 80/10/31 1p

B01100492 Forwards listing of changes, tests & experiments, w/safety evaluation summaries for each item Two add'l electrical penetrations into reactor bldg were installed Penetrations provide electrical feed from transformer outside bldg KALIVIANAKIS, N Commonwealth Edison Co 80/11/03 3pp 06931 069

B011100389 Forwards page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments TRAMM, T R Commonwealth Edison Co 80/11/05 2pp

G Inspection reports, IE Bulletins & correspondence

B011240090 Forwards IE Insp Repts 50-254/80-19 & 50-265/80-21 on 800721-0829 & notice of violation HEIGHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/15 2pp 07047 026

--B011240098 IE Insp Repts 50-254/80-19 & 50-265/80-21 on 800721-0829 Noncompliance noted operator failed to return reactor core isolation cooling sys to normal operating position & improper adjustments performed on exhaust restrictor CHRISTOPHERS, N, DUPONT, S G, SPESSARD, R L Region 3, Chicago, Office of the Director 80/10/08 13pp 07047 029

B011060172 Confirms 801031 meeting w/RL Spessard in Chicago, IL to discuss regulatory performance KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/21 3pp

B01120415 Forwards monthly status rept re evaluations performed at facilities in response to IE Bulletin 79-14 W/o encl JANECEK, R F Commonwealth Edison Co 80/10/21 2pp

B011260271 Forwards IE Health Physics Appraisal Repts 50-254/80-20 & 50-265/80-22, notice of violation & significant appraisal findings KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/21, 6pp 07072 151

--B011260275 Notice of violation from health physics appraisal on 800505-16, * Region 3, Chicago, Office of the Director 80/10/16 1p 07072 157

--B011260283 IE Health Physics Appraisal Repts 50-254/80-20 & 50-265/80-22 Noncompliance noted uncontrolled access to unposted, unbarricaded & unobserved high radiation area & garments monitored from reissue bins exceeded limit SCHUMACHER, M G, GRANT, W B, SELBY, J M Region 3, Chicago, Office of the Director 80/10/16 48pp 07072 158

B011070281 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required, KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/24 1p 06921-292.

DOCKETED ITEMS

57

801110012 Forwards orders for mod of Licenses DPR-25, DPR-29 & DPR-30 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPD/LTD, T.A. Operating Reactors Branch 2 80/10/24 2pp

--801110050 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp

--801110058 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp

8011210471 Submits preliminary technical evaluation rept for IE Bulletin 80-06, "Engineered Safety Feature Reset Controls" Util identified 11 sys which may change position upon manual reset at sys level for valves & equipment
KOUNTANIS, B EQ&G, Inc 80/10/27 3pp 07031 309

--8011210474 "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Engineered Safety Features Reset Controls for Quad Cities 1 & 2"
KOUNTANIS, B EQ&G, Inc 80/10/27 10pp 07031 312

8011190040 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc
Badge examples encl
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28 3pp

8011170247 Forwards four isometric drawings which were omitted from Oct 1980 status rept re IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys"
JANECEK, R F Commonwealth Edison Co 80/10/29 5pp

8011200062 Forwards final response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment," per NRC 800919 revised order for mod of license
ABEL, J S Commonwealth Edison Co 80/10/30 3pp 07011 001

--8011200081 Vol 1, Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2"
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 100pp 07012 234

--8011200087 Vol 2 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2"
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 230pp 07012 340

--8011200094 Vol 3 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2"
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 230pp 07013 229

--8011200099 Vol 4 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2"
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 160pp 07014 142

--8011200107 Vol 5 of Revision 1 to "Response to IE Bulletin 79-01B for Quad Cities Nuclear Power Station, Units 1 & 2"
* Bechtel Power Corp (subs of Bechtel Corp) 80/11/01 180pp 07014 345

8011200539 Forwards IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-265/80-27, 50-295/80-21 & 50-304/80-23 on 801031 No noncompliance noted
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/06 2pp

--8011200544 IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-265/80-27, 50-295/80-21 & 50-304/80-23 on 801031, No noncompliance noted Major areas discussed performance of activities
HEISHKAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/06 26pp

8011250696 Forwards response to IE Bulletin 80-11, "Masonry Wall Design." Operability assessment performed on walls classified as safety-related but failed to meet acceptance criteria Safe shutdown capability not jeopardized
ABEL, J. B Commonwealth Edison Co. 80/11/06 23pp

R Periodic operating reports & related correspondence

80111010186 Forwards monthly operating repts for Oct 1980
KALIVIANAKIS, N Commonwealth Edison Co 80/10/31 1p 06943 349.

--80111010193 Monthly operating repts for Oct 1980
TUBBS, R C Commonwealth Edison Co 80/11/01 26pp 06943 350

S Reportable occurrences, LERs & related correspondence

8011100436 Forwards LER 80-024/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 80/10/23 1p 06929 302

--8011100439 LER 80-024/03L-0 on 801010, valve MD-2-1-1001-34A would only open far enough to give dual position indication Caused by limit switches on valve operator being out of adjustment
Limit switches adjusted & control switch cleaned
KEHRET, D Commonwealth Edison Co 80/10/23 2pp 06929 303

8011030629 Part 21 rept re failure of condition containment atmosphere monitoring sys, reported on 801023 Sensors fail to provide accurate hydrogen concentration measurements following LOCA Analysis of defect re BWRs encl
SHERWOOD, G Q General Electric Co 80/10/24 11pp

8011180595 Forwards LER 80-027/01T-0
KALIVIANAKIS, N Commonwealth Edison Co 80/11/03 1p 06988 268

--8011180613 LER 80-027/01T-0 on 801024, while performing surveillance check, RHR Pump 2C failed to start because trip interlock signal received from pump suction valve MD-2-1001-7C Caused by incorrectly adjusted limit switch Switch readjusted
MURRAY, R Commonwealth Edison Co 80/11/03 3pp 06988 269

8011180617 Forwards LER 80-023/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 80/11/06 1p 06988 263

--8011180628 LER 80-023/03L-0 on 801010, during LPCI motor operated valve operability test, MD-2-1001-29A valve initially failed to open fully Caused by tightly seated valve disc Torque switch limits adjusted to allow more time to unseat valve
HANNUM, D Commonwealth Edison Co 80/11/06 2pp 06988 264

8011250545 Forwards LER 80-026/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 80/11/12 1p 07058 359

--8011250553 LER 80-026/03L-0 on 801017, while performing procedure 008 201-1, relief valve 2-803-3C failed to open Caused by excessive leakage between main disc & guide. Valve replaced & tested satisfactorily
WYKOFF, D Commonwealth Edison Co 80/11/12 2pp 07058 360

8011250567 Forwards LER 80-029/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 80/11/17 1p 07056 093

--8011250571 LER 80-029/03L-0 on 801027, during surveillance procedure, pressure suppression chamber & reactor bldg vacuum breaker actuation calibr & functional test found to actuate at 0.52 psid Caused by instrument setpoint drift Switch recalibr
WYKOFF, D L Commonwealth Edison Co 80/11/17 2pp 07056 094

V Operator Examinations

8011100481 Forwards response to NRC 800731 ltr transmitting interim criteria for shift staffing & requesting util schedule for compliance Vacancies may create situations requiring overtime in excess of NRC guidelines
JANECEK, R F Commonwealth Edison Co 80/11/05 5pp

8011120492 Forwards response to NRC request for schedule per interim shift staffing requirements
JANECEK, R F Commonwealth Edison Co 80/11/05 5pp

DOCKET 90-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8011030595 Forwards comments on 800505 & 0725 emergency plan submittals Requests addl info to satisfy NUREG-0654 criteria.
CLARK, R.A. Licensing Branch 2 80/09/26 7pp 06860 084

DOCKETED ITEMS

8011060071 Forwards supplemental safety evaluation re fire protection mode identified as incomplete in 790802 safety evaluation. Summary of requirements to resolve open items & protection review status encl
CLARK, R. A. Operating Reactors Branch 3 80/10/21 3pp 06916 168

--8011060075 Safety evaluation suppl re resolution of open items concerning fire protection mode. Fourteen items in Sections 3.1 & 3.2 of 790802 safety evaluation remain unresolved
* Operating Reactors Branch 3 80/10/21 11pp 06916 171

8011060016 Forwards emergency planning info for housing in Two Rivers, WI LPDR W/o encl
BOUDER, J. L. Division of Rules and Records 80/10/22 1p 06914 146

8011060012 Forwards emergency planning info for housing in Two Rivers, WI LPDR W/o encl
BOUDER, J. L. Division of Rules and Records 80/10/23 1p 06914 144

8011170126 Forwards facility emergency planning info for placement in LPDR W/o encl
Division of Rules and Records 80/10/29 1p 06975 335

0 Adjudicatory correspondence

8011070362 Forwards order for mod of Licenses DPR-24 & DPR-27 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
CLARK, R. A. Operating Reactors Branch 3 80/10/24 2pp 06925 189

--8011070570 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D. O. Division of Licensing 80/10/24 6pp 06925 191

8011070576 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
Division of Licensing 80/10/24 4pp 06925 197

0490 Responds to 801003 ltr expressing concern re manner in which authorized resumption of operation & notified Wisconsin Electric Power Co of approval of Jul 1980 test results. Division of approval in 800404 order for convenience
WHIT, L. Office of the General Counsel 80/10/30 2pp 06977 164

070060 Order denying WI Environ Decade 791217 petition for hearing. 791130 confirmatory order. Intervenor request for certification to Commission or interlocutory appeal rejected
IOBMAN, H. Atomic Safety and Licensing Board Panel 80/11/04 1pp 06924 326

Operating license stage documents & correspondence

050354 Ltr to all licensees of operating plants, applicants for OLA holders of CPs re preliminary clarification of TMI action requirements. Provides summary listing of all approved IIR-2 related requirements
EISENHUT, D. O. Division of Licensing 80/09/05 209pp

1190039 Notifies that NRC review of licensee safety analysis for postulated uncontrolled boron dilution events indicates nonconservative plant conditions. Recalculation of boron dilution & Tech Spec mod recommended w/supporting info.
LARK, R. A. Operating Reactors Branch 1 80/09/30 4pp 06916 001

1100486 Ltr to all licensees of operating plants & applicants for LA & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D. O. Division of Licensing 80/10/01 5pp

11100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D. O. Division of Licensing 80/10/06 6pp

8011060930 Informs of approval of responses to concerns stated in NRC 790921 ltr re inadvertent safety injection actuations during surveillance testing.
CLARK, R. A. Operating Reactors Branch 2 80/10/21 2pp 06915 280.

8011100223 Notifies of duplicate fees required for util 800919 Tech Spec Change Request 64
DIQGS, R. H. License Fee Management Branch 80/10/23 1p 06928 267

8011070562 Forwards order for mod of Licenses DPR-24 & DPR-27 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
CLARK, R. A. Operating Reactors Branch 3 80/10/24 2pp 06925 189

--8011070570 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D. O. Division of Licensing 80/10/24 6pp 06925 191

--8011070576 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 4pp 06925 197

8011210443 Forwards request for addl info generated from review of "Asymmetric LOCA Loading," WCAP-9628 & 9749, dtd Nov 1979 & June 1980, respectively
LAING, G. C. Assistant Director for Safety Assessment 80/10/29 27pp

8011070322 Ack receipt of NRC 801006 ltr re licensee 790918 request for proprietary treatment of info describing technical & mgt resources. Public disclosure of experience & training of util personnel serves no purpose. Nonproprietary rpt encl
FAY, C. W. Wisconsin Electric Power Co 80/10/30 14pp 06924 239

8011040420 Submits environ qualification testing program equipment description, sys, location & cognizant licensee contact re safety-related pressure & differential pressure transmitters per NRC 801001 request
FAY, C. W. Wisconsin Electric Power Co 80/10/31 2pp 06880 184

801120338 Submits addl clarification of proposed instrument bus mods, in response to NRC request. Describes provisions for preventing parallel operation of new & old batteries
FAY, C. W. Wisconsin Electric Power Co 80/11/03 4pp 06932 023

8011170112 Confirms 801107 meeting w/util at facility to discuss evaluation of regulatory performance
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/04 1p 06978 261

8011180436 Discusses license amend approval fees. Only single Class 1 duplicate amend fee appropriate since all amend changes have been provided & should be processed & issued at same time
FAY, C. W. Wisconsin Electric Power Co 80/11/14 1p 06988 161

0 Inspection reports, IE Bulletins & correspondence

801120689 Forwards IE Insp Repts 50-266/80-14 & 50-301/80-14 on 800801-31 & notice of violation
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/09/29 2pp 03720 238

--801120688 Notice of violation from insp on 800801-31.
* Region 3, Chicago, Office of the Director 80/09/22 2pp 03720 260

--801120689 IE Insp Repts 50-266/80-14 & 50-301/80-14 on 800801-31. Noncompliance noted. Failure to comply w/ASME Section XI code requirements for valve inservice testing, exceeding Tech Specs due to improper valve testing on containment sys
GULDEMOND, W. O., HAGUE, R. L., CHOLEWICK, N. C. Region 3, Chicago, Office of the Director 80/09/22 9pp 03720 262

8011210142 Forwards IE Insp Repts 50-266/80-15 & 50-301/80-15 on 800902-30. No noncompliance noted
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/16 2pp 07037 154

--8011210149 IE Insp Repts 50-266/80-15 & 50-301/80-15 on 800902-30. No noncompliance noted. Major areas inspected: operational safety verification, monthly maint observation & IE bulletin & circular followup
GULDEMOND, W. O., HAGUE, R. L., HARNICK, R. F. Region 3, Chicago, Office of the Director 80/10/15 7pp 07037 156

8011070294 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/24 1p 06921 316

DOCKETED ITEMS

59

801190567 Updates NRC 800903 ltr re site access of Region 3 personnel
New badges are currently being issued. Interim questions re
inspector identification should be directed to Region 3 ofc
Badge examples encl
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/10/28
3pp 06999 189

801190577 Responds to IE Bulletin 79-01B, "Environ Qualification of
Class IE Equipment " Response includes final revision of
master list of electrical equipment, component evaluation
worksheets, svc profiles & equipment qualification plan
FAY, C W Wisconsin Electric Power Co 80/10/30 130pp 06997:281

8011060448 Submits seventh supplemental response to IE Bulletin 79-14,
"Seismic Analysis for As-Built Safety-Related Piping Sys "
Provides analysis & design effort progress rept Analytical
schedule for unreleased piping isometric drawings encl
FAY, C W Wisconsin Electric Power Co 80/10/31 4pp 06912 266

8011280192 Ack receipt of 800910 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-266/80-12 &
50-301/80-12 Downgrades Item 1 noncompliance to deficiency
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/11/10 2pp 07082 352

--8011280196 Responds to NRC 800822 ltr re violations noted in IE Insp
Repts 50-266/80-12 & 50-301/80-12 Corrective actions, refutes
NRC allegation of violation of procedure re normal entry &
exit from controlled zone
BURSTEIN, S Wisconsin Electric Power Co 80/09/10 3pp
07082 354

8011280081 Responds to IE Bulletin 80-11, "Masonry Wall Design "
Forwards rept on function & configuration of walls, const
practices & re-evaluation criteria Wall analysis survey
will be submitted within 30 days
FAY, C W Wisconsin Electric Power Co 80/11/14 41pp 07081 238.

R Periodic operating reports & related correspondence

8011170490 Forwards monthly operating repts for Oct 1980
BURSTEIN, S. Wisconsin Electric Power Co 80/11/10 1p 06975 062

--8011170492 Monthly operating repts for Oct 1980.
FAY, C W Wisconsin Electric Power Co 80/11/05 8pp 06975 063

8011230706 Forwards monthly operating repts for Oct 1980.
BURSTEIN, S. Wisconsin Electric Power Co 80/11/10, 1p 07056 280

S Reportable occurrences, LERs & related correspondence

8011100483 Forwards LER 80-012/03L-0
FAY, C W Wisconsin Electric Power Co, 80/10/31 1p 06931 098

--8011100487 LER 80-012/03L-0 on 801005, logs showed decrease in holdup
tank pressure during 801002-05 Evaluation showed leak on
compression fitting on inlet to valve IPCV-1022C Caused
by improper reinstallation of valve after cleaning
FAY, C W Wisconsin Electric Power Co 80/10/31 2pp 06931 099

V Operator Examinations

8011170076 Responds to util 800807 ltr relaying procedures for
selection & training of senior operators Conformance w/Item
A.2 of NRC 800328 ltr cannot be deferred
COLLINS, P F Operator Licensing Branch 80/10/28 1p 06978 272

801120325 Responds to NRC 800731 ltr re interim criteria for shift
staffing Util commits to six shifts of eight personnel plus
nine others for relief by 820701
FAY, C W Wisconsin Electric Power Co 80/11/03 6pp 06952 072

801120068 Advises that technical advisor training cannot be completed
by 810101 as committed to in 791231 ltr Extension to 810301
requested, at which time training program & evidence of
conformance w/800905 recommendations will be provided
FAY, C W Wisconsin Electric Power Co 80/11/03 2pp 06952 051

DOCKET 80-267 FORT ST VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8011290298 Requests meeting w/NRC to discuss status of emergency
response plan List of subjs for discussion encl
WAREMBOURG, D W. Public Service Co of Colorado, 80/11/14 2pp.
07068 319

O Adjudicatory correspondence

801110402 Forwards order for mod of License DPR-34 re environ
qualification of safety-related electrical equipment Revised
Tech Specs also encl
MILLER, J R Standardization & Special Projects Branch 80/10/27
2pp. 06944 226

--801110409 Order for mod of license re environ qualification of safety-
related electrical equipment Compliance w/Div of Operating
Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D Q Division of Licensing 80/10/27 6pp 06944.228

--801110424 Revised Tech Spec pages per 801024 order for mod of license
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/27 2pp 06944 235

8011250310 Requests opportunity per 10CFR2 206 to file response to
Northern IN Public Svc Co 801120 opposition to issuance of
show cause order Refs ASLAD 801120 order ruling that 2 206
proceeding exclusive forum for evacuation question
COHN, D B Gary, IN 80/11/21 1p 07055 243

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TMI action
plan requirements. Provides summary listing of all approved
TMI-2 related requirements
EISENHUT, D Q Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs info needed by 801101
EISENHUT, D Q Division of Licensing 80/10/01 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D Q Division of Licensing 80/10/06 6pp.

801110402 Forwards order for mod of License DPR-34 re environ
qualification of safety-related electrical equipment Revised
Tech Specs also encl
MILLER, J R Standardization & Special Projects Branch, 80/10/27
2pp. 06944 226

--801110409 Order for mod of license re environ qualification of safety-
related electrical equipment Compliance w/Div of Operating
Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D Q Division of Licensing 80/10/27 6pp 06944 228

--801110424 Revised Tech Spec pages per 801024 order for mod of license
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/27 2pp 06944 235.

8011100687 Notification of 801107 meeting w/util, LASL & ORNL in
Bethesda, MD to discuss core support block thermal stresses
KUZMYCZ, Q Standardization & Special Projects Branch 80/10/31
2pp 06963 009.

801120312 Responds to NRC 801001 ltr requesting info re environ
qualification testing scheduled within next 2 yrs Scheduling
equipment environ qualification testing for steam line
rupture, in progress
SWART, F E Public Service Co of Colorado 80/11/04, 1p
06956 265

8011100412 Notifies of payment due for applications for license amendments
& approvals for specific facilities List of applications &
fees encl.
MILLER, W D License Fee Management Branch 80/11/07, 2pp
06931, 266

801180620 Withdraws request for temporary relief from Limiting
Condition of Operation 4.3.10, in response to NRC 801106
telecon. Assumes fees are no longer required
WAREMBOURG, D W Public Service Co of Colorado 80/11/07, 1p
06988 262

801180440 Advises that util does not interpret requirements of
NUREG-0577 to be applicable to facility
SWART, F E Public Service Co of Colorado 80/11/10 1p
06992 134

DOCKETED ITEMS

8011290275 Requests change to Tech Spec SR 5.4.1 to delete Item C re pulse testing one ultrasonic channel w/one ultrasonic & two pressure channels tripped Item is redundant w/Item B in determining logic circuit operability
WAREMBOURG, D W Public Service Co. of Colorado 80/11/12 2pp
07032 347

G Inspection reports, IE Bulletins & correspondence

8011140126 Forwards IE Circular 80-22 "Confirmation of Employee Qualifications." No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/02.
1p. 06963 206

8011210714 Forwards Health Physics Appraisal Rept 80-267/80-13, notice of violation & significant appraisal findings.
SEYFRIT, K V, Region 4, Dallas, Office of the Director, 80/10/08
3pp 07029:014

--8011210718 Health Physics Appraisal Rept 80-267/80-13 Noncompliance noted, qualification of radiation protection manager not in accordance w/Tech Specs & inadequate portable instrumentation for beta dose rates.
BAIRD, J B., EVERETT, R J, SELBY, J M Region 4, Dallas, Office of the Director 80/10/06 44pp 07029 017

--8011210725 Notice of violation from health physics appraisal on 800616-27.
* Region 4, Dallas, Office of the Director 80/10/06 1p
07029 061

8011060751 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting." No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director, 80/10/10.
1p. 06909,047.

8011280032 Ack receipt of 800916 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 80-267/80-13
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/10/17 1p 07082 221.

--8011280035 Responds to NRC 800818 ltr re violation noted in IE Insp Rept 80-267/80-13 Corrective actions, info added to Radiation Work Permit 2365 Spent fuel shipping crew admonished for failure to follow permit
LEE, O R. Public Service Co of Colorado 80/09/16. 3pp
07082 222

8011260073 Forwards Page 2 to IE Insp Rept 80-267/80-19, omitted from original transmittal
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/10/22 1p 07074:230.

0011260076 Page 2 to IE Insp Rept 80-267/80-19, omitted from original transmittal
* Region 4, Dallas, Office of the Director 80/10/22 1p
07074:231

11260079 Forwards IE Insp Rept 80-267/80-19 on 800901-30. No noncompliance noted.
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch, 80/10/14. 2pp. 07074 252

011260081 IE Insp Rept 80-267/80-19 on 800901-30 No noncompliance noted. Major areas inspected unresolved items, surveillance, maint & operational safety verification.
DICKERSON, M W, COLLINS, R E, WESTERMAN, T F Region 4, Dallas, Office of the Director 80/10/10. 5pp. 07074 254.

801110402 Forwards order for mod of License DPR-34 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
MILLER, J R. Standardization & Special Projects Branch. 80/10/27
2pp. 06944 226

01110409 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/DIV of Operating Reactors guidelines or NUREG-0588 required by 80630. Complete records must be available by 801201.
EISENHUT, D O. Division of Licensing. 80/10/27. 6pp 06944:228.

01110424 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
1 Division of Licensing 80/10/27. 2pp. 06944:235.

R. Periodic operating reports & related correspondence

8011140340 Forwards monthly operating rept for Oct 1980
WAREMBOURG, D Public Service Co of Colorado 80/11/10 1p
06965,341

--8011140343 Monthly operating rept for Oct 1980
GAHM, J W Public Service Co of Colorado 80/11/01 5pp
06965 342

S Reportable occurrences, LERs & related correspondence

8011210477 Forwards LER 80-061/03L-0
WAREMBOURG, D Public Service Co of Colorado. 80/10/31 5pp.
07029 221

--8011210478 LER 80-061/03L-0 between 801003 & 13 on three occasions, plant operated w/individual snubbers out of svc Caused by need for maint One snubber filled w/oil & two snubbers adjusted
GAHM, J W. Public Service Co of Colorado 80/10/31 1p.
07029, 226

8011210541 Forwards LER 80-057/03L-0
WAREMBOURG, D. Public Service Co of Colorado 80/10/31. 5pp.
07029:247.

--8011210552 LER 80-057/03L-0 on 801004, PCRV pressure exceeded penetration interspace pressure Caused by malfunction of pressure switch PCRV pump-up terminated & switch linkage retightened & calibr
GAHM, J W Public Service Co of Colorado 80/10/31 1p.
07029:252

8011210575 Forwards LER 80-058/03L-0
WAREMBOURG, D Public Service Co of Colorado 80/10/31. 6pp.
07032 222

--8011210581 LER 80-058/03L-0 on 801009, plant was operated at power w/ emergency feedwater supply to Loop 1 helium circulator water turbine driver isolated to repair PV-21243-1 line leak Caused by erosion inside line at 90 degree elbow
GAHM, J W Public Service Co of Colorado. 80/10/31 1p
07032, 228

801120523 Forwards LER 80-062/01L-0
WAREMBOURG, D W Public Service Co of Colorado. 80/11/05. 8pp.
06952 220

--801120529 LER 80-062/01L-0 on 801021, isolation valve for A purification train would not close either electrically or by handjack Cause unknown Valve will be tested & evaluated when plant conditions permit
GAHM, J W Public Service Co of Colorado. 80/11/05. 1p
06952 228

8011140399 Forwards LER 80-059/03L-0
WAREMBOURG, D. Public Service Co of Colorado. 80/11/10 7pp
06963:039.

--8011140401 LER 80-059/03L-0, from 801012-21, plant operated w/total primary coolant oxidants greater than 4 ppm & average core outlet temp greater than 1,200 C on four occasions Caused by offgassing of oxidants due to moisture ingress.
GAHM, J W Public Service Co of Colorado. 80/11/10 1p
06963:046

8011140406 Forwards LER 80-060/03L-0
WAREMBOURG, D Public Service Co of Colorado 80/11/10 4pp
06963,047

--8011140411 LER 80-060/03L-0; on 801010, plant protective sys battery charger/inverter tripped Caused by noise spike exceeding inverter high voltage trip level Trip level is too sensitive to noise. Modified trip circuit will be installed
GAHM, J W Public Service Co of Colorado 80/11/10 1p.
06963:051

8011180659 Forwards LER 80-063/03L-0
WAREMBOURG, D Public Service Co. of Colorado 80/11/14. 4pp.
06992,099.

--8011180667 LER 80-063/03L-0 on 801017, gas waste release routed through unsampled tank Caused by nonlicensed operator inadvertently leaving valve open.
GAHM, J W. Public Service Co of Colorado 80/11/14 1p.
06992:103.

V Operator Examinations

801100383 Responds to NRC 800731 interim shift staffing criteria
Summits administrative procedures re overtime policy Sixteen
consecutive workdays used instead of 14 due to shift
rotation Special policy re technical advisor unnecessary
WARENBURG, D. Public Service Co of Colorado 80/10/30 2pp
06930-355

DOCKET 90-269 OCONEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8011250172 Forwards Revision 5 to security plan, Revision withheld (ref
10CFR2.790)
PARKER, W D Duke Power Co 80/11/17, 1p 07068 306

Q Adjudicatory correspondence

801110139 Forwards order for mod of Licenses DPR-38, DPR-47 & DPR-55 re
environ qualification of safety-related electrical
equipment Revised Tech Specs also encl.
REID, R W Operating Reactors Branch 4 80/10/24 2pp 06943-326

--801110195 Order for mod of licenses re environ qualification of
safety-related electrical equipment Compliance w/Div of
Operating Reactors guidelines or NUREG-0588 required by
820630 Complete records must be available by 801201.
EISENHUT, D O Division of Licensing 80/10/24, 6pp 06943-328

--801110171 Revised Tech Spec pages per 801024 order for mod of licenses
re environ qualification of safety-related electrical
equipment.
* Division of Licensing 80/10/24 2pp 06943-334

8011050143 Order denying Carolina Environ Study Group 801006 motion to
reopen record & rejecting NRC 801027 motion for extension re
spent fuel transshipments
MILLER, M E. Atomic Safety and Licensing Board Panel 80/10/31
2pp 02319-196.

8011060395 Initial decision denying util 780309 application for amend
of SNM license authorizing transshipment of spent nuclear
fuel from Oconee for storage in McGuire Initial decision
shall constitute final action 45 days from issuance.
HARD, C. H., LUEBKE, E. A., MILLER, M E Atomic Safety and Licensing
Board Panel 80/10/31, 103pp 06911-019

8011060465 Withdraws 801027 request for hearing re 801006 FR notice
PORTER, W L. Duke Power Co 80/11/03 1p. 06912-263

8011070020 Notice of reconstitution of ASLAB in license amend
proceeding, consisting of AS Rosenthal, Chairman & JH Buck &
RS Baltman members.
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 80/11/03
1p. 06924 284.

801140504 Exceptions to ASLB 801031 initial decision which denied
trans-shipment of spent nuclear fuel from Oconee to McGuire
for storage purposes. Cites 6B ASLB errors Certificate of
Svc encl.
MCQARRY, J M., PORTER, W L Duke Power Co MCQARRY, J M Debovoise &
Liberman 80/11/10, 16pp 06963 089

8011200741 Suggests obtaining B Spitalny assistance in preparing appeal
brief of initial decision re McGuire/Oconee spent fuel
transportation
CHRISTENBURY, E. Hearings Division 80/11/18 1p 07018-110.

J. Insurance & indemnity information

8011210559 Forwards Endorsement 59 to NELIA Policy NF-182 & Endorsement
44 to MAELU Policy NF-61
SANDERS, F. D Duke Power Co. 80/11/17 3pp. 07034-077

P Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of
Mark I owners group to discuss pool swell load definition
techniques & methodology for condensation, oscillation,
chugging & lateral load definition
CRIMES, C I Assistant Director for Engineers & Projects (Pre
790625), 79/03/02 2pp 03145-305

8011080354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TMI action
plan requirements. Provides summary listing of all approved
TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs Info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D O. Division of Licensing 80/10/06, 6pp

8011050208 Requests submittal of updated Tech Specs for facilities fire
protection program by 80115 Surveillance requirements for
new equipment should be implemented by administrative
control as soon as possible Forwards model Tech Specs.
REID, R W Operating Reactors Branch 4 80/10/07 2pp 02319 196

--8011050212 Model Tech Specs for fire protection program
* Operating Reactors Branch 4 80/01/15 17pp 02319 196

8011030057 Forwards request for addl info to complete review of util
800520 reload design methodology technical rept Outstanding
areas include reactivity coefficients & deficits, shutdown
margin calculation & kinetics parameters
REID, R W. Operating Reactors Branch 4 80/10/16 5pp 06855.117

8011060096 Requests addl info to complete review of structural &
seismic portions of common spent fuel pool submitted on
800701. Requests info by 801030
REID, R. W. Operating Reactors Branch 4 80/10/24 3pp 06916.152.

801110139 Forwards order for mod of Licenses DPR-38, DPR-47 & DPR-55 re
environ qualification of safety-related electrical
equipment. Revised Tech Specs also encl
REID, R. W. Operating Reactors Branch 4, 80/10/24, 2pp

--801110155 Order for mod of licenses re environ qualification of
safety-related electrical equipment Compliance w/Div of
Operating Reactors guidelines or NUREG-0588 required by
820630. Complete records must be available by 801201.
EISENHUT, D O Division of Licensing 80/10/24, 6pp

--801110171 Revised Tech Spec pages per 801024 order for mod of licenses
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 2pp

8011040609 Forwards request for addl info in order to complete review
of standby shutdown facility Response due in 30 days.
REID, R. W. Operating Reactors Branch 4, 80/10/27 3pp, 06875 163

801140168 Requests addl info re completion of spent fuel pool mod
review within 30 days of receipt of ltr.
REID, R. W. Operating Reactors Branch 4 80/10/29 3pp 06963.360

8011040146 Forwards proposed Tech Specs revision for radiological
effluent control per 800602 request
PARKER, W. D Duke Power Co 80/10/30 2pp. 06876 016

--8011040149 Proposed Tech Specs revision for radiological effluent
control
* Duke Power Co 80/10/30 133pp 06876 018

8011060499 Informs that util position re instrumentation sys to detect
inadequate core cooling is consistent w/info contained in
JH Taylor 801007 ltr to D Ross
PARKER, W D Duke Power Co 80/10/30 1p 06915 299

8011060502 Forwards proposed revision to Tech Spec 3.1.12, adding
explicit requirements for determining reportability of
inoperable monitors Proposal suppls 801002 proposed Tech
Spec revisions to reflect NUREG-0578, Category A items
PARKER, W. D Duke Power Co 80/10/30 1p. 06915 296

--8011060504 Proposed revision to Tech Spec 3.1.12, adding explicit
requirements for determining reportability of inoperable
monitors
* Duke Power Co. 80/10/30 1p 06915 297

DOCKETED ITEMS

8011040481 Forwards list re equipment which will undergo environ qualification tests, to be conducted within next two yrs, in response to NRC 801001 request
PARKER, H. D. Duke Power Co. 80/10/31 3pp 06874 126

8011070439 Forwards proposed revision to Tech Specs to incorporate NUREG-0578 Category A items, including shift technical advisor in response to NRC 800731 ltr requesting response to shift staffing criteria Operator staffing table encl
PARKER, H. D. Duke Power Co. 80/11/03 3pp 06919 194

--8011070446 Proposed Tech Specs, incorporating NUREG-0578 Category A items re min staffing requirements & shift technical advisor
* Duke Power Co. 80/11/03 5pp 06919 197

801110496 Forwards responses to NRC health physics-related questions re proposed retracting of spent fuel pool Supple info provided by 800701 & 25 ltrs
PARKER, H. D. Duke Power Co. 80/11/03 4pp 06950 119

801120374 Maintains position that license fees not required w/proposed Tech Spec changes provided in 801014 & 0624 ltrs, since neither changed operation of facility
PARKER, H. D. Duke Power Co. 80/11/04 1p 06952 053

801190671 Confirms commitments to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability." Commitments acceptable & should remain in effect pending completion of review
REID, R. W. Operating Reactors Branch 4. 80/11/05 2pp 07001.250

801130179 Application to amend OL changing Tech Spec 4.5.1, ECCB, by revising surveillance requirements for valves LP-17 & 18
PARKER, H. D. Duke Power Co. 80/11/07 2pp 06958:273

--801130203 Proposed revision to Tech Spec 4.5.1, ECCB, pages 4.5-2 & 4.5-3, to revise surveillance requirements for valves LP-17 & 18
* Duke Power Co. 80/11/07 3pp 06958 275.

801140098 Updates 800818 response to request for addl info re preliminary design approval of safety-grade anticipatory reactor sys Pressure switches are located in turbine bldg in areas w/environmentally safe conditions
PARKER, H. D. Duke Power Co. 80/11/07 1p 06962:346

215 Informs that charge for review of 801029 request for val of primary route to cover shipments of spent fuel 4 will be based on prof manpower required plus any net costs Route survey is excluded from computation
D. License Fee Management Branch 80/11/11 1p 07032 318

392 Forwards corrected Page 3, 11-1 to 801030 submittal of sed radiological effluent Tech Specs
R. W. D. Duke Power Co. 80/11/12 1p. 06992 160.

180296 Corrected Page 3 11-1 to proposed radiological effluent Tech Specs submitted 801030
Duke Power Co. 80/11/12 1p 06992:161.

1200178 Forwards addl info re facility reload design methodology technical rept. in response to NRC 801016 ltr request
PARKER, H. D. Duke Power Co. 80/11/13 25pp 07018:111

30548 Responds to TMI Action Plan Item II K 3.30. Existing small LOCA model fully meets requirements of 10CFR50 App K. Currently reviewing several aspects of model for possible overment &/or addl justification.
ER, H. D. Duke Power Co. 80/11/14 2pp 06992 132

0291 Responds to NRC 801112 request for addl info re environ fications of pressure switches Util provided info re concerns on 801107.
R. W. D. Duke Power Co. 80/11/20 1p. 07054 081

ection reports; IE Bulletins & correspondence

068 Forwards response to IE Circular 80-21, "Regulation of ling Crews." Senior reactor operator can supervise ties more effectively from refueling operations ctr in ol room than from reactor bldg refueling deck
R. W. D. Duke Power Co. 80/10/20 2pp 06956:348

1139 Forwards order for mod of Licenses DPR-38, DPR-47 & DPR-55 re on qualification of safety-related electrical ment Revised Tech Specs also encl.
R. W. Operating Reactors Branch 4. 80/10/24 2pp

--801110159 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0388 required by E20630 Complete records must be available by 801201
EISENHUT, D. O. Division of Licensing 80/10/24 6pp

--801110171 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp

8011060117 Ack receipt of 801003 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/80-28, 50-270/80-24 & 50-287/80-21
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/10/28 1p 06912 177

--8011060128 Responds to NRC 800911 ltr re violations noted in IE Insp Repts 50-269/80-28, 50-270/80-24 & 50-287/80-21 Corrective actions: stud matl verified to be correct matl & matl control instructions reviewed w/all appropriate personnel
PARKER, H. D. Duke Power Co. 80/10/03 3pp 06912 178

--8011060136 Forwards IE Insp Repts 50-269/80-28, 50-270/80-24 & 50-287/80-21 on 800701-31 & notice of violation
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/11 2pp 06912 181

--8011060141 Notice of violation from insp on 800701-31.
* Region 2, Atlanta, Office of the Director 80/09/04 1p 06912:183

--8011060149 IE Insp Repts 50-269/80-28, 50-270/80-24 & 50-287/80-21 on 800701-31 Noncompliance noted: failure to maintain traceability & accountability of QA matl used on safety-related sys
ORDERS, W. J. MYERS, D. Region 2, Atlanta, Office of the Director
MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/04 17pp 06912 184

801100429 Requests extension of IE Bulletin 80-11 re masonry wall design schedule to accommodate new submittal dates. Response to bulletin will be submitted 801108 & Dec 1981
PARKER, H. D. Duke Power Co. 80/10/28 1p. 06929:295

8011210440 Forwards 801101 Revision 5 to util 90-day response to IE Bulletin 79-01B, replacing Revision 4 in entirety w/o encl
THIES, A. C. Duke Power Co. 80/10/31 2pp 07029 148

8011260330 Forwards addl response to IE Bulletin 80-11, "Masonry Wall Design." Re-evaluation of design adequacy of walls identified in 800707 response is underway
PARKER, H. D. Duke Power Co. 80/11/04 16pp 07075 105

R. Periodic operating reports & related correspondence

8011250188 Forwards description of facility changes, in form of station mods, completed between Oct-Dec 1979 Mods listed by month
PARKER, H. D. Duke Power Co. 80/10/27 13pp 07068 293

8011180582 Forwards monthly operating repts for Oct 1980
PARKER, H. D. Duke Power Co. 80/11/13 1p 06988 041

--8011180592 Monthly operating repts for Oct 1980.
REAVIS, J. A. Duke Power Co. 80/11/13 16pp. 06988 042.

B. Reportable occurrences, LERs & related correspondence

8011030704 Requests addl info re 80 269/80-23 Reactivity anomaly raises questions re accuracy of core physics data used to calculate reactivity balances for facility
REID, R. W. Operating Reactors Branch 4 80/10/16 3pp 06860 162

8011030487 Forwards LER 80-029/03L-0
PARKER, H. D. Duke Power Co. 80/10/24 2pp. 06872:322

--8011030491 LER 80-029/03L-0 on 800925, Unit 2 failed to come up to synchronous speed on normal start & was shut down by operation of volts-to-Hertz relay Caused by bent clamp on governor distributing valve Mod approved to replace clamp.
JONES, J. L. Duke Power Co. 80/10/24 1p 06872:324

8011040478 Forwards LER 80-030/03L-0
PARKER, H. D. Duke Power Co. 80/10/31 3pp. 06874 129.

DOCKETED ITEMS

63

--BO11040503 LER 80-030/03L-0 on 801002, valve LPSW-365 failed to close completely during testing causing reactor bldg cooler unit to be out of line in ES mode Caused by torque switch setting being out of adjustment Torque switches reset
JONES, J L Duke Power Co 80/10/31 1p 06874 132

BO11120339 Forwards LER 80-032/03L-0
PARKER, W O Duke Power Co 80/11/07 2pp 06952 069

--BO11120344 LER 80-032/03L-0 on 801008, transformer lockout relay 86T initiated by 94T/K When cover to 94T/K was removed to obtain part number, total overhead transmission was declared inoperable Caused by possible instrument vibration
JONES, J L Duke Power Co 80/11/07 1p 06952 071

BO11140372 Forwards LER 80-033/03L-0
PARKER, W O Duke Power Co 80/11/10 2pp 06968 175

--BO11140374 LER 80-033/03L-0 on 801011, smoke detector alarmed & detector string removed from svc Caused by wind blowing dust into detectors when rollup doors opened Dust blown out of detector & string returned to svc
JONES, J L Duke Power Co 80/11/10 1p 06968 177

BO11180585 Forwards LER 80-031/01T-0
PARKER, W O Duke Power Co 80/11/13 5pp 06988 272

--BO11180593 LER 80-031/01T-0 on 800902, as result of dropped control rod & power tilt, reactor protection sys flux/flow/imbalance trip set points were set contrary to Tech Specs Caused by personnel & station misinterpretation of required specs.
JONES, J T Duke Power Co 80/11/13 1p 06988 277

BO11250365 Forwards addl info re reactivity anomaly that occurred at 97 A effective full power days of operation during Cycle A;
per 801016 ltr Ref RO 249/80-23
PARKER, W O Duke Power Co 80/11/20 8pp 07068 120.

V Operator Examinations

BO11070439 Forwards proposed revision to Tech Specs to incorporate NUREG-0578 Category A items, including shift technical advisor in response to NRC 800731 ltr requesting response to shift staffing criteria Operator staffing table encl
PARKER, W O Duke Power Co 80/11/03 3pp

DOCKET 80-270 OCONEE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

BO11290172 Forwards Revision 5 to security plan Revision withheld (ref 100FR2 790)
PARKER, W O Duke Power Co 80/11/17 1p 07068 306

Q Adjudicatory correspondence

BO1110139 Forwards order for mod of Licenses DPR-38, DPR-47 & DPR-55 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp 06943, 326.

--BO1110135 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06943 328

--BO1110171 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06943 334

BO11090143 Order denying Carolina Environ Study Group 801006 motion to reopen record & rejecting NRC 801027 motion for extension re spent fuel transshipments
MILLER, M E Atomic Safety and Licensing Board Panel. 80/10/31 2pp 02319 196

BO11040395 Initial decision denying util 780309 application for amend of SNM license authorizing transshipment of spent nuclear fuel from Oconee for storage in McGuire Initial decision shall constitute final action 45 days from issuance.
HAW, D C H, LUEBKE, E A, MILLER, M E. Atomic Safety and Licensing Board Panel 80/10/31 103pp 06911 019

BO11060465 Withdraws 801027 request for hearing re 801006 FR notice.
PORTER, W L Duke Power Co 80/11/03 1p. 06912, 263

BO11070020 Notice of reconstitution of ASLAB in license amend proceeding, consisting of AS Rosenthal, Chairman & JH Buck & RB Salzman, members
TOMPKINS, J A Atomic Safety and Licensing Appeal Panel 80/11/03 1p 06924 284

BO11140504 Exceptions to ASLB 801031 initial decision which denied trans-shipment of spent nuclear fuel from Oconee to McGuire for storage purposes Cites 68 ASLB errors Certificate of Bvc encl
MCQARRV, J M, PORTER, W L Duke Power Co MCQARRV, J M Debevoise & Liberman 80/11/10 16pp 06963 089

BO11200241 Suggests obtaining B Spitalny assistance in preparing appeal brief of initial decision re McGuire/Oconee spent fuel transportation
CHRISTENBURY, E Hearings Division 80/11/18 1p 07018 110

J Insurance & indemnity information

BO11210559 Forwards Endorsement 99 to NELIA Policy NF-182 & Endorsement 44 to MAELU Policy MF-61
SANDERS, F D Duke Power Co 80/11/17 3pp 07034-077.

P Operating license stage documents & correspondence

BO11050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D O Division of Licensing 80/09/05 207pp

BO1100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp.

BO1100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp.

BO11050208 Requests submittal of updated Tech Specs for facilities fire protection program by 801115 Surveillance requirements for new equipment should be implemented by administrative control as soon as possible Forwards model Tech Specs
REID, R W Operating Reactors Branch 4 80/10/07 2pp 02319, 196

--BO11050212 Model Tech Specs for fire protection program
* Operating Reactors Branch 4. 80/01/15 17pp. 02319 196

BO11030057 Forwards request for addl info to complete review of util 800520 reload design methodology technical rept Outstanding areas include reactivity coefficients & deficits, shutdown margin calculation & kinetics parameters
REID, R W Operating Reactors Branch 4 80/10/16 5pp 06855, 117

BO11040096 Requests addl info to complete review of structural & seismic portions of common spent fuel pool submitted on 800701 Requests info by 801030
REID, R W Operating Reactors Branch 4 80/10/24 3pp 06916, 152

BO1110139 Forwards order for mod of Licenses DPR-38, DPR-47 & DPR-55 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24. 2pp

--BO1110155 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630, Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp

--BO1110171 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24. 2pp

BO11040609 Forwards request for addl info in order to complete review of standby shutdown facility Response due in 30 days.
REID, R W, Operating Reactors Branch 4 80/10/27 3pp. 06875, 163

BO11140168 Requests addl info re completion of spent fuel pool mod review within 30 days of receipt of ltr
REID, R W, Operating Reactors Branch 4. 80/10/29. 3pp. 06943, 360.

DOCKETED ITEMS

8011040146 Forwards proposed Tech Specs revision for radiological effluent control per 800602 request
PARKER, W D Duke Power Co 80/10/30 2pp 06876 016

--8011040149 Proposed Tech Specs revision for radiological effluent control
* Duke Power Co 80/10/30 133pp 06876 018

8011060499 Informs that util position re instrumentation sys to detect inadequate core cooling is consistent w/info contained in JH Taylor 801007 ltr to D Ross
PARKER, W D Duke Power Co 80/10/30 1p 06915 299

8011060502 Forwards proposed revision to Tech Spec 3.1.12, adding explicit requirements for determining reportability of inoperable monitors Proposal suppl 801002 proposed Tech Spec revisions to reflect NUREG-0578 Category A items
PARKER, W D Duke Power Co 80/10/30 1p 06915 296

--8011060504 Proposed revision to Tech Spec 3.1.12, adding explicit requirements for determining reportability of inoperable monitors
* Duke Power Co 80/10/30 1p 06915 297

8011040481 Forwards list re equipment which will undergo environ qualification tests, to be conducted within next two yrs, in response to NRC 801001 request
PARKER, W D Duke Power Co 80/10/31 3pp 06874 126

8011070439 Forwards proposed revision to Tech Specs to incorporate NUREG-0578 Category A items, including shift technical advisor in response to NRC 800731 ltr requesting response to shift staffing criteria Operator staffing table encl
PARKER, W D Duke Power Co 80/11/03 3pp 06919 194

--8011070446 Proposed Tech Specs, incorporating NUREG-0578 Category A items re min staffing requirements & shift technical advisor
* Duke Power Co 80/11/03 5pp 06919 197

801110496 Forwards responses to NRC health physics-related questions re proposed reworking of spent fuel pool Suppl info provided by 800701 & 25 ltrs
PARKER, W D Duke Power Co 80/11/03 4pp 06950 119

801120334 Maintains position that license fees not required w/proposed Tech Spec changes provided in 801014 & 0624 ltrs, since neither changed operation of facility
PARKER, W D Duke Power Co 80/11/04 1p 06952 033

1190671 Confirms commitments to NRC 791023 "Interim Position on Retention Purgin & Venting Pending Resolution of Isolation Valve Operability." Commitments acceptable & will remain in effect pending completion of review
R W Operating Reactors Branch 4 80/11/05 2pp 07001 250

10199 Application to amend OL changing Tech Spec 4.5.1, ECCB, by using surveillance requirements for valves LP-17 & 18
KER, W D Duke Power Co 80/11/07, 2pp 06958 273

11130203 Proposed revision to Tech Spec 4.5.1, ECCB, pages 4.5-2 & 4.5-3, to revise surveillance requirements for valves LP-17 & 18
* Duke Power Co 80/11/07 3pp 06958 275

8011140398 Updates 800818 response to request for addl info re preliminary design approval of safety-grade anticipatory reactor sys Pressure switches are located in turbine bldg in areas w/environmentally safe conditions
PARKER, W D Duke Power Co 80/11/07 1p 06962 346

1180392 Forwards corrected Page 3.11-1 to 801030 submittal of proposed radiological effluent Tech Specs
PARKER, W D Duke Power Co 80/11/12 1p 06992 160

11180396 Corrected Page 3.11-1 to proposed radiological effluent Tech Spec submittal 801030
* Duke Power Co. 80/11/12 1p 06992 161

1200178 Forwards addl info re facility reload design methodology technical rept, in response to NRC 801016 ltr request.
PARKER, W D Duke Power Co 80/11/13, 23pp 07018 111

1180548 Responds to TMI Action Plan Item II K 3.30 Existing small break LOCA model fully meets requirements of 10CFR50 App K. Currently reviewing several aspects of model for possible improvement &/or addl justification
PARKER, W D Duke Power Co. 80/11/14 2pp 06992 132

8011290271 Responds to NRC 801112 request for addl info re environ qualifications of pressure switches Util provided info re NRC concerns on 801107
PARKER, W D Duke Power Co 80/11/20 1p 07056 081

G Inspection reports, IE Bulletins & correspondence

8011130068 Forwards response to IE Circular 80-21, "Regulation of Refueling Crews." Senior reactor operator can supervise activities more effectively from refueling operations ctr in control room than from reactor bldg refueling deck
PARKER, W D Duke Power Co 80/10/20 2pp 06956 348

801110139 Forwards order for mod of Licenses DPR-38, DPR-47 & DPR-55 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp

--801110155 Order for mod of licenses re environ qualification of safety-related electrical equipment, Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 800630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp

--801110171 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp

8011060117 Ack receipt of 801003 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/80-28, 50-270/80-24 & 50-287/80-21
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/10/28 1p 06912 177

--8011060128 Responds to NRC 800911 ltr re violations noted in IE Insp Repts 50-269/80-28, 50-270/80-24 & 50-287/80-21 Corrective actions stud matl verified to be correct matl & matl control instructions reviewed w/all appropriate personnel
PARKER, W D Duke Power Co 80/10/03 3pp 06912 178

--8011060136 Forwards IE Insp Repts 50-269/80-28, 50-270/80-24 & 50-287/80-21 on 800701-31 & notice of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/11 2pp 06912 181

--8011060149 IE Insp Repts 50-269/80-28, 50-270/80-24 & 50-287/80-21 on 800701-31 Noncompliance noted failure to maintain traceability & accountability of QA matl used on safety-related sys
ORDERS, W. J. Region 2, Atlanta, Office of the Director
MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/09/04 17pp 06912 184

8011100429 Requests extension of IE Bulletin 80-11 re masonry wall design schedule to accommodate new submittal dates Responses to bulletin will be submitted 801108 & Dec 1981
PARKER, W D Duke Power Co 80/10/28 1p 06929 295

8011210440 Forwards 801101 Revision 5 to util 90-day response to IE Bulletin 79-018, replacing Revision 4 in entirety w/e encl
THIES, A C Duke Power Co 80/10/31 2pp 07029 168

8011260330 Forwards addl response to IE Bulletin 80-11, "Masonry Wall Design." Re-evaluation of design adequacy of walls identified in 800707 response is underway
PARKER, W D Duke Power Co 80/11/04 16pp 07075 105

R Periodic operating reports & related correspondence

8011250188 Forwards description of facility changes, in form of station mods, completed between Oct-Dec 1979 Mods listed by month
PARKER, W D Duke Power Co 80/10/27 13pp 07068 293

8011180582 Forwards monthly operating repts for Oct 1980
PARKER, W D Duke Power Co 80/11/13 1p 06988 041

--8011180592 Monthly operating repts for Oct 1980
REAVIS, J A Duke Power Co 80/11/13 16pp 06988 042

S Reportable occurrences, LERs & related correspondence

8011030460 Forwards LER 80-017/03L-0
PARKER, W D Duke Power Co. 80/10/28 3pp 06872 314

--8011030465 LER 80-017/03L-0 on 800928, w/unit at 85% full power, concentrated boric acid storage tank pump declared inoperable when pump failed to pump from concentrated to letdown storage tank Caused by low oil level Pump primed JONES, J L Duke Power Co 80/10/28 1p 06872 317

801120504 Forwards LER 80-022/01T-0 PARKER, W O Duke Power Co 80/11/04 3pp 06952 046

--801120608 LER 80-022/01T-0 on 801011, four holes were knocked in fire barrier between cable spread room & turbine bldg w/o establishment of hourly fire watch Caused by failure to provide proper notification Hourly fire watch established JONES, J L Duke Power Co 80/11/06 1p 06952 049

801180446 RQ on 801013, unplanned 13 Ci gaseous release occurred from reactor bldg Caused by simultaneous opening of six purge sys valves during test Spent fuel pool evacuated Precautions taken to prevent recurrence PARKER, W O Duke Power Co 80/11/12 3pp 06988 162

801180704 Forwards LER 80-020/03L-0 PARKER, W O Duke Power Co 80/11/12 3pp 06991 275

--801180712 LER 80-020/03L-0 on 801013, during performance of EB on-line test, valve 2FDW-103 failed to close during cycling Caused by failure of torque switch Valve manually closed Bad torque switch replaced JONES, J L Duke Power Co 80/11/12 1p 06991 298

801210473 Forwards LER 80-019/01T-0 PARKER, W O Duke Power Co 80/11/17 3pp 07029 217

--801210475 LER 80-019/01T-0 on 801103, radiation monitor sounded high activity alarm in component cooling sys Cause unknown Cooler 2A will be replaced during current Unit 2 outage JONES, J L Duke Power Co 80/11/17 1p 07029 220

801250480 Forwards LER 80-023/03L-0 PARKER, W O Duke Power Co 80/11/21 3pp 07055 103

--801250806 LER 80-023/03L-0 on 801022, inoperable snubber & changer were found on B main steam atmospheric dump line Caused by piston rod coming unscrewed from piston rod eye, possibly due to vibration Snubber & hanger repaired & returned to svc JONES, J L Duke Power Co 80/11/21 1p 07055 106

V Operator Examinations

801070439 Forwards proposed revision to Tech Specs to incorporate NUREG-0578 Category A items, including shift technical advisor in response to NRC 800731 ltr requesting response to shift staffing criteria Operator staffing table encl PARKER, W O Duke Power Co 80/11/03 3pp

DOCKET 80-271 VERMONT YANKEE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

8011040599 Immediate Action Ltr 80-34 confirms 800930 telcon re emergency preparedness capabilities at facility Util will implement action levels for declaring site & general emergencies & initiate training program GRIER, B H, Region 1, Philadelphia, Office of the Director 80/10/03 2pp 06914 162

8011040688 Forwards safety evaluation re outstanding fire protection items in Amend 43 to License DPR-28 Fire protection mods acceptable IPPOLITO, T A Operating Reactors Branch 3 80/10/24 3pp 06876 010

--8011040691 Safety evaluation re outstanding fire protection items in Amend 43 to License DPR-28 * Office of Nuclear Reactor Regulation, Director 80/10/24 3pp 06876.013

G Adjudicatory correspondence

8011070569 Forwards order for mod of License DPR-28 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl IPPOLITO, T A, Operating Reactors Branch 2 80/10/24 2pp. 06925:199

--8011070573 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201 EISENHUT, D O Division of Licensing 80/10/24 6pp 06925 202

--8011070578 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment * Division of Licensing 80/10/24 2pp 06925 208

P Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition GRINES, C I Assistant Director for Engineers & Projects (Pre 790625) 79/03/02 2pp 03145 305

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101 EISENHUT, D O Division of Licensing 80/10/01 5pp

801190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance Info should be submitted within 25 days EISENHUT, D O Division of Licensing 80/10/01 2pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl. EISENHUT, D O Division of Licensing 80/10/06 6pp

801030172 Responds to util 800619 request for postponement of Commission decision re containment inerting pending completion of risk assessment & BWR survey Util should submit new info to proposed interim rule Chronology encl DIRCKS, W J Office of the Executive Director for Operations 80/10/15 3pp. 06855 199

--801030177 Requests postponement of Commission decision re containment inerting pending completion of probabilistic risk assessments for facility & BWR survey TRIBBLE, J E Vermont Yankee Nuclear Power Corp 80/06/19 2pp 06855:202

8011050569 Forwards order for mod of License DPR-28 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp 06925:199

--8011070573 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201 EISENHUT, D O, Division of Licensing, 80/10/24 6pp 06925:202

--8011070578 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment * Division of Licensing 80/10/24 2pp 06925 208

8011140491 Provides info on design, procurement & installation of inerting sys. EISENHUT, D O Division of Licensing 80/10/24 2pp. 06911 001.

801030613 Notification of 801031 meeting w/util in Bethesda, MD to discuss resumed operation of facility ROONEY, V L Operating Reactors Branch 3, 80/10/27 2pp 06860:096.

801190701 Denies util 800508 request for exemption from code requirements re integrated leak rate tests of containment vessel Type A tests provide assurance of containment vessel leak tightness IPPOLITO, T A Operating Reactors Branch 2, 80/10/29 3pp 06996:229.

DOCKETED ITEMS

8011040398 Submits comments on EQ&O internal technical rept on BWR augmented offgas treatment sys operating experience
SMITH,R L Vermont Yankee Nuclear Power Corp 80/10/30 2pp
06830 181

8011200041 Forwards request for addl info re NRC evaluation of util
800819 submittal re Reload 7
IPPOLITO,T A Operating Reactors Branch 2 80/10/30 5pp
07018 215

8011210722 Forwards Amend 58 to License DPR-28,safety evaluation &
notice of issuance & availability.
IPPOLITO,T A Operating Reactors Branch 2 80/11/03 3pp
07029 062

--8011210739 Amend 58 to License DPR-28, revising Tech Specs to authorize
replacement of existing pressure switches that sense reactor
pressure & water level w/analog loops
IPPOLITO,T A Operating Reactors Branch 2 80/11/03 29pp
07029 065

--8011210749 Safety evaluation supporting Amend 58 to License DPR-28
* Office of Nuclear Reactor Regulation, Director 80/11/03 5pp.
07029 092

--8011210756 Notice of issuance & availability of Amend 58 to
License DPR-28
IPPOLITO,T A Operating Reactors Branch 2 80/11/03 2pp
07029 097

801170064 Summary of 801031 meeting w/util & OE in Bethesda,MD re core
spray sparger cracking
ROONEY,V Operating Reactors Branch 2 80/11/03 4pp 06981 333

8011100774 Forwards check in payment of fee associated w/proposed
Change 94
CONWAY,H F Vermont Yankee Nuclear Power Corp 80/11/06 1p.
06943 127

801120532 Submits proposed change to Tech Specs,modifying Pages 183,
185 & 185a & adding Page 185b to incorporate definition of
requirements for spirally unloading & reloading reactor
core
HEIDER,L H Vermont Yankee Nuclear Power Corp 80/11/06 3pp
06950-346

--801120539 Tech Specs 3 12 & 4 12 re requirements for spirally
unloading & reloading reactor core
* Vermont Yankee Nuclear Power Corp 80/11/06, 7pp 06950,349

801180362 Application for Proposed Change 85 to License DPR-28,
changing existing & revised App A Tech Specs 4 5 & 4 7 to
implement NRC guidelines excluding cycling valves during
plant operation Class III fee encl
HEIDER,L H Vermont Yankee Nuclear Power Corp 80/11/12 3pp
06991 178

--801180371 Proposed Change 85 to App A Tech Specs 4 5 & 4 7 & to
implement NRC guidelines excluding cycling valves during
plant operation
* Vermont Yankee Nuclear Power Corp. 80/11/12 5pp 06991 181.

8011240083 Informs that OE will resolve NRC concerns w/small break
LOCA models for BWRs & respond to Requirement II K.3 30,
revised small break LOCA methods to show compliance
w/10CFR50, App K.
SMITH,R L Vermont Yankee Nuclear Power Corp 80/11/17, 1p
07049 137.

G Inspection reports, IE Bulletins & correspondence

801100324 Forwards IE Insp Rept 50-271/80-08 on 800602-0704 No
noncompliance noted
BRUNNER,E J. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/09/14 2pp 06929,197

--801100334 IE Insp Rept 50-271/80-08 on 800602-0704, No noncompliance
noted. Major areas inspected: plant operations, safety sys
operability verification, response to IE Bulletin 80-17 &
training staff qualifications.
RAYMOND,W J, COLLINS,S J Region 1, Philadelphia, Office of the
Director, MARTIN,T T Region 1, Philadelphia, Reactor Operations
Nuclear Support Branch. 80/09/09, 14pp 06929,199

801100340 Forwards IE Insp Rept 50-271/80-13 on 800811-0912 No
noncompliance noted.
BRUNNER,E J. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/09/29 2pp. 06929,216

--801100350 IE Insp Rept 50-271/80-13 on 800811-0912 No noncompliance
noted. Major areas inspected actions taken on previous insp
findings & review of operations
RAYMOND,W J, COLLINS,S J Region 1, Philadelphia, Office of the
Director, MARTIN,T T Region 1, Philadelphia, Reactor Operations
Nuclear Support Branch 80/09/25 20pp 06929 218

8011070030 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment." No written response
required
GRIER,B H Region 1, Philadelphia, Office of the Director
80/09/30 1p 06924 304

8011060441 Forwards IE Info Notice 80-37, "Containment Cooler Leaks &
Reactor Cavity Flooding At Indian Point Unit 2 " No written
response required
GRIER,B H Region 1, Philadelphia, Office of the Director
80/10/24, 1p 06909 321

8011070334 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " No written response
required
GRIER,B H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06922 033

801140069 Forwards IE Circular 80-23, "Potential Defects in Beloit
Power Sys Emergency Generators " No written response
required
GRIER,B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06968 249

801140622 Forwards IE Info Notice 80-39, "Malfunction of Solenoid
Valves Hfg by Valcor Engineering Corp " No written response
required
GRIER,B H Region 1, Philadelphia, Office of the Director,
80/10/31 1p 06963 291

801170783 Forwards response to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " Rept supersedes
previous submittals on equipment qualification
HEIDER,L H Vermont Yankee Nuclear Power Corp 80/11/01 400pp
06974 001.

R Periodic operating reports & related correspondence

8011803578 Forwards monthly operating rept for Oct 1980
CONWAY,H F Vermont Yankee Nuclear Power Corp 80/11/11, 1p.
06988 085

--801180584 Monthly operating rept for Oct 1980
BEER,B F C, BURGER,F J Vermont Yankee Nuclear Power Corp,
80/11/11 10pp 06988 086

B Reportable occurrences, LERs & related correspondence

8011040378 Forwards LER 80-033/01T-0
MURPHY,W P Vermont Yankee Nuclear Power Corp 80/10/28 2pp
06873 242

--8011040381 LER 80-033/01T-0 on 801014, ultrasonic insp per IE Bulletin
80-7 revealed crack in jet pump B holddown beam at mean
diameter of bolt thread. Caused by intergranular stress
corrosion. Beam replaced w/one of higher strength
MURPHY,W P Vermont Yankee Nuclear Power Corp 80/10/28 1p
06873,243

8011040385 Forwards LER 80-032/01T-0
MURPHY,W P Vermont Yankee Nuclear Power Corp 80/10/28 1p
06873:244

--8011040387 LER 80-032/01T-0 on 801014, core spray sparger visual insp
per IE Bulletin 80-13 revealed semicircular indication on
end cap of C sparger junction box Caused by intergranular
stress corrosion cracking Clamp type cover being designed
MURPHY,W P Vermont Yankee Nuclear Power Corp. 80/10/28 2pp
06873 245.

8011030560 Forwards LER 80-030/03L-0
MURPHY,W P Vermont Yankee Nuclear Power Corp 80/10/29 1p
06855 236

--8011030567 LER 80-030/03L-0 on 800929, during two rod lock functional
test on rod 38-35, position switch & rod block found
inoperable. Caused by stuck position indicating switch Switch
replaced by changing control rod position info probe.
MURPHY,W P Vermont Yankee Nuclear Power Corp 80/10/29, 1p
06855:237

8011030497 Forwards LER 80-031/03L-0

MURPHY, W P Vermont Yankee Nuclear Power Corp 80/10/31 1p.
06855 090

--8011030509 LER 80-031/03L-0 on 801001, while refueling, shock suppressor
MS-24 on main steam C piping found no visible fluid in
sight glass Caused by fluid leakage in one cylinder inlet
fitting Seals in cylinder & valve replaced
MURPHY, W P Vermont Yankee Nuclear Power Corp 80/10/31 1p
06855 091

801110306 Forwards LER 80-035/03L-0

MURPHY, W P Vermont Yankee Nuclear Power Corp 80/11/06 1p
06944 168

--801110313 LER 80-035/03L-0 on 801007, main steam relief valves had
as-found setpoint of 1.093 psig, exceeding max setpoint
Deviation caused by setpoint drift Valve disassembled &
rebuilt & setpoint readjusted
MURPHY, W P Vermont Yankee Nuclear Power Corp 80/11/06 1p
06944 169

8011170496 Forwards LER 80-037/01T-1

MURPHY, W P Vermont Yankee Nuclear Power Corp 80/11/10 1p
06975-072

--8011170500 LER 80-037/01T-1 on 801027, cracks discovered in 4-inch
reactor water cleanup suction line Cause undetermined
Samples of cracked pipes sent to lab for analysis
MURPHY, W P Vermont Yankee Nuclear Power Corp. 80/11/08 2pp.
06975 073

8011200155 PNO-I-80-163 as of 801107, seven defects have been identified
following ultrasonic, radiographic &/or visual exam of 17
welded pipe junctions in reactor water cleanup sys Affected
pipe is 4-inch, Type 304, Schedule 80 & 120 stainless steel.
RAYMOND, H J, COLLINS, S J, MARTIN, T T Region 1, Philadelphia,
Office of the Director 80/11/10 2pp 07021 275.

8011240406 Forwards LER 80-034/03L-0

MURPHY, W P Vermont Yankee Nuclear Power Corp. 80/11/12 1p.
07049 117

--8011240412 LER 80-034/03L-0 on 801013, discovered monthly interval was
exceeded by four days for operability test of plant fire
pumps Caused by misinterpretation of test interval by
personnel Test performed & personnel retrained
MURPHY, W P Vermont Yankee Nuclear Power Corp 80/11/12 1p
07049 118

8011180453 Forwards LER 80-036/03L-0

MURPHY, W P Vermont Yankee Nuclear Power Corp. 80/11/14. 1p
06988:143

--8011180463 LER 80-036/03L-0 on 801017, standby liquid control relief
valve setpoints found to be above Tech Spec 4.4 A
requirement of 1400 to 1490 psig Caused by setpoint drift.
Relief valves adjusted, bench tested & reinstalled
MURPHY, W P Vermont Yankee Nuclear Power Corp. 80/11/14. 1p
06988, 144

U Congressional/Executive Correspondence

8011060477 Forwards copy of 800725 ltr to Senator Kennedy expressing
concern re inaccurate contents of Kennedy 800428 ltr to NRC
endorsing meeting w/members of Vermont Yankee
Decommissioning Alliance
CDNHAY, W F Vermont Yankee Nuclear Power Corp 80/10/29 2pp
06911 344.

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F Security, medical, emergency & fire protection plans

801130208 Clarifies 800808 ltr re upgrading of emergency support
facilities Requirements for technical support ctr &
emergency operations facility will be implemented in
accordance w/NRC schedules
MITTL, R L Public Service Electric & Gas Co of New Jersey
80/11/06 2pp 06959 241

O Adjudicatory correspondence

8011140159 Forwards order for mod of License DPR-70 re environ
qualification of safety-related electrical equipment Revised
Tech Specs also encl
VARONA, B A Operating Reactors Branch 1 80/10/24. 2pp. 06961.228.

--8011140171 Order for mod of license re environ qualification of safety-
related electrical equipment Compliance w/DIV of Operating
Reactors guidelines or NUREG-0588 required by B20630
Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06961 230.

--8011140178 Revised Tech Spec pages per 801024 order for mod of license
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 2pp 06961 236

8011050465 Discusses LBP-80-27 in spent fuel pool mod proceeding,
authorizing Ofc of Nuclear Reactor Regulation to make
appropriate findings & issue requested amend Decision
should not be appealed
SHAPAR, H K Office of the Executive Legal Director 80/11/03 1p.
06893, 362

8011070031 Notice of reconstitution of ASLAB in spent fuel proceeding,
consisting of CN Kohl, chairman & WR Johnson & TS Moore,
members
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 80/11/03.
1p 06924:306

801120422 Responds to 801008 ltr requesting that WT Russell provide
testimony before NJ Board of Public Utils re investigation
into causes of 1979 outage extension Russell will testify
on IE Bulletins 79-07 & 79-14 implementation
DENTON, H R. Office of Nuclear Reactor Regulation, Director
80/11/03 1p 06916 001.

--801120426 Requests WT Russell testimony on work required & performed
by facility under IE Bulletins 79-07 & 79-14 affecting
outage duration Info necessary for Board of Public Utils
investigation into causes of 1979 outage extension
FORLENZA, F G New Jersey, State of 80/10/08 2pp. 06916 001

8011140101 Exceptions & appeal from ASLB 801027 initial decision
Exclusion of AS Benjamin of Sandia Labs testimony is
arbitrary due to relevant evidence re oxidation that could
propagate to older fuel Certificate of Bvc encl
VALORE, C J Lower Alloways Creek, NJ 80/11/04 6pp 06963:191.

8011190178 Appeal from ASLB 801027 initial decision Alleges erroneous
finding of facts re Contentions 2 & 4, evaluation of EIA,
acceptance of Pasadag testimony & rejection of Benjamin
testimony Counsel withdrawal & Certificate of Bvc encl.
COLEMAN, A C, COLEMAN, E O Affiliation Unknown 80/11/11 10pp.
06998 232.

8011290577 Notice of withdrawal of appearance as counsel for
Intervenors Coleman Intervenors Coleman to remain parties to
proceeding Certificate of Bvc encl
AYRES, S T, MAKUL, R E New Jersey, State of. 80/11/20. 2pp
07048 347.

H General correspondence

8011180150 Addl response to FOIA request for four categories of info re
Crystal River 3 & info re six facilities. NRC has no analyses
subj to Paragraph 3 request
FELTON, J M Division of Rules and Records 80/11/07 1p
06987 291

J Insurance & indemnity information

8011180586 Forwards Endorsement 33 to MAELU Policy MF-90
CORREA, M A Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc
Div 80/11/11 2pp 06992.122

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs
& holders of CPs re preliminary clarification of TMI action
plan requirements Provides summary listing of all approved
TMI-2 related requirements.
EISENHUT, D O Division of Licensing 80/09/03 209pp

8011100486 Ltr to all licensees of operating plants & applicants for
DLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs Info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01 5pp.

8011100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

DOCKETED ITEMS

- 8011200136 Confirms notification of 801023 mgt meeting w/NRC at facility to discuss util regulatory performance Agenda
encl
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/09 2pp 07019 322
- 8011140159 Forwards order for mod of License DPR-70 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
VAROBA, S A Operating Reactors Branch 1 80/10/24 2pp 06961.228
- 8011140171 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0388 required by 820630
Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06961.230
- 8011140178 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 2pp 06961.236
- 8011130018 "SER, Inservice Testing Program, Salem Nuclear Generating Station Unit 1," May 1979-Nov 1980
FEHRINGER, J M, ROCKHOLD, H C Energy Dept of, Idaho Operations Office, FIN A-6238. 8011130018 80/10/31 48pp. 06958.005.
- 8011250296 Forwards application for amend of Licenses DPR-70 & DPR-75, changing Apps A & B Tech Specs re administrative controls.
Class II & Class I fees encl
LIBRIZZI, F P Public Service Electric & Gas Co. of New Jersey.
80/11/20 1p 07032 286.
- 8011250300 Application for amend of Licenses DPR-70 & DPR-75, changing Apps A & B Tech Specs re administrative controls.
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey.
80/11/20 3pp 07032 287
- 8011250302 Proposed changes to Tech Specs, Section 6 re administrative controls
* Public Service Electric & Gas Co. of New Jersey. 80/11/20 7pp 07032 290.
- 8011250306 Proposed changes to ETS, Section 5 re administrative controls.
* Public Service Electric & Gas Co. of New Jersey 80/11/20. 3pp. 07032 299.
- 8011250698 Proposed changes to Tech Specs, Section 6 re administrative controls
* Public Service Electric & Gas Co. of New Jersey 80/11/20. 4pp. 07032:362
- 8011250697 Proposed changes to ETS, Section 5 re administrative controls
* Public Service Electric & Gas Co. of New Jersey 80/11/20. 1p. 07032 311.
- Inspection reports, IE Bulletins & correspondence
- 801070045 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/09/30 1p. 06924 314.
- 801180439 Ack receipt of 800915 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-272/80-17 & 80-311/80-13 Util ltr to be withheld (ref 10CFR2 790)
MARTIN, M O Region 1, Philadelphia, Safeguards Branch 80/10/09 1p 06989 204.
- 801180443 Forwards IE Insp Repts 80-272/80-17 & 80-311/80-13 on 800714-1B & notice of violation Notice of violation withheld (ref 10CFR2 790)
MARTIN, M O Region 1, Philadelphia, Safeguards Branch. 80/08/22 2pp. 06989.205.
- 801180430 IE Insp Repts 80-272/80-17 & 80-311/80-13 on 800714-1B. Noncompliance noted: failure to keep isolation zone clear of structures & failure to secure opening in auxiliary relay room wall. Details withheld (ref 10CFR2 790).
BAILEY, R J Region 1, Philadelphia, Office of the Director.
DEVLIN, J W Region 1, Philadelphia, Safeguards Branch. 80/08/20. 1p. 06989 207.
- 8011200282 Suppl response to IE Bulletin 80-06 re engineered safety feature reset controls Addl containment isolation valve identified which could reopen upon reset of isolation signal Circuitry will be revised
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey
80/10/20 1p 07020:018
- 801180800 Ack receipt of 801010 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-272/80-20 & 80-311/80-16
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/21. 1p 06992 038
- 801180805 Responds to NRC 800917 ltr re violations noted in IE Insp Repts 80-272/80-20 & 80-311/80-16 Corrective actions emphasized to operators importance of constant surveillance & proper procedures Affixed new tags on active matl.
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey
80/10/10 3pp 06992 039
- 801180808 Forwards IE Insp Repts 80-272/80-20 & 80-311/80-16 on 800801-31 & notice of violation.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/09/17 2pp 06992 042
- 801180811 Notice of violation from insp on 800801-31
* Region 1, Philadelphia, Office of the Director 80/09/16. 1p. 06992:044.
- 801180814 IE Insp Repts 80-272/80-20 & 80-311/80-16 on 800801-31. Noncompliance noted control console reading sheets not initiated; refueling water storage tank level less than Tech Spec min & valves not tagged
NORRHOOL, L J, HILL, W M Region 1, Philadelphia, Office of the Director
KEIMIG, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/16 14pp 06992 045
- 801060656 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director
80/10/24 1p 06909 349
- 801070320 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p. 06922 013.
- 8011200547 Immediate Action Ltr 80-42 confirming 801017 & 24 commitments re organizational interactions during activities having potential for substantial personnel exposure. Actions include instruction of supervisory personnel.
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 2pp 07018 202
- 801120316 Forwards environ qualification review repts for facility which supersede all previous info submitted in response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." Proprietary info withheld (ref 10CFR2 790).
SCHNEIDER, F.W. Public Service Electric & Gas Co. of New Jersey
80/10/31 500pp 07027 001
- 801140076 Forwards IE Circular 80-23, "Potential Defects in Boleit Power Sys Emergency Generators " No written response required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director.
80/10/31 1p. 06968.297
- 801170869 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
GRIER, B.H. Region 1, Philadelphia, Office of the Director
80/10/31. 1p 06979.360
- 801120422 Responds to 801008 ltr requesting that WT Russell provide testimony before NJ Board of Public Utils re investigation into causes of 1979 outage extension. Russell will testify on IE Bulletins 79-07 & 79-14 implementation
DENTON, H.R. Office of Nuclear Reactor Regulation, Director.
80/11/03 1p 06916:001
- 801120426 Requests WT Russell testimony on work required & performed by facility under IE Bulletins 79-07 & 79-14 affecting outage duration Info necessary for Board of Public Utils investigation into causes of 1979 outage extension
FORLENZA, F O, New Jersey, State of. 80/10/08 2pp. 06916:001.

DOCKETED ITEMS

69

8011260013 Submits updated response to IE Bulletin 80-11, "Masonry Wall Design," to correct error identified in Item 1 of util 800702 ltr. Requests extension for submittal of final rept & evaluation until 801203
SCHNEIDER, F.W. Public Service Electric & Gas Co. of New Jersey
80/11/04, 2pp 07070 328

R Periodic operating reports & related correspondence

801180621 Forwards NPDES discharge monitoring rept, Jul 1980 Util 800821 ltr to EPA transmitting repts encl
MIDURA, H.J. Public Service Electric & Gas Co. of New Jersey.
80/11/05 2pp 06915 001

--801180627 NPDES discharge monitoring rept, Jul 1980
* Public Service Electric & Gas Co. of New Jersey 80/10/07
12pp, 06915 001

801170446 Forwards monthly operating rept for Oct 1980
MIDURA, H.J. Public Service Electric & Gas Co. of New Jersey.
80/11/10, 1p 06975 001.

--801170451 Monthly operating rept for Oct 1980
MILLER, L.K. Public Service Electric & Gas Co. of New Jersey.
80/11/10 26pp, 06975.002

B Reportable occurrences, LERs & related correspondence

801060419 RO 80-54/01P on 801016, one available fire pump failed to start on receipt of automatic initiation signal & was inoperable per Tech Spec requirements. Cause unknown. Pump will be manually started until cause is determined
MIDURA, H.J. Public Service Electric & Gas Co. of New Jersey
80/10/17, 1p 02319-196

8011030558 Forwards LER 80-033/03L-0
LIBRIZZI, F.P. Public Service Electric & Gas Co. of New Jersey
80/10/28 1p 06835.093

--8011030575 LER 80-033/03L-0 on 801020, boron concentration found below Tech Specs min. Caused by personnel failure to anticipate effects of water entering RCB RCB borated & returned to within specs Hydrolyzing procedure to be developed
RANDOLPH, J.M. Public Service Electric & Gas Co. of New Jersey
80/10/28 3pp 06835:036

801040433 Forwards LER 80-054/01T-0
LIBRIZZI, F.P. Public Service Electric & Gas Co. of New Jersey
80/10/30, 3pp, 06884 234

--8011040431 LER 80-054/01T-0 on 801012, during refueling, fire pump diesel one failed, destroying engine block On 801016 fire pump diesel two failed to start, causing both sys to be inoperable. Caused by faulty lubrication & voltage regulator
RANDOLPH, J.M. Public Service Electric & Gas Co. of New Jersey.
80/10/30, 1p, 06884:237.

801200291 Forwards LER 80-055/01T-0.
LIBRIZZI, F.P. Public Service Electric & Gas Co. of New Jersey.
80/11/14, 3pp 07020 028

--8011200296 LER 80-055/01T-0 on 801029, unfused area found in root portion of butt weld on steam generator 13. Caused by weld defect in 1979 repair. Nondestructive testing base line data will be completed before unit returned to svc.
RANDOLPH, J.M. Public Service Electric & Gas Co. of New Jersey.
80/11/14 1p 07020-031

8011280035 Forwards LER 80-058/03L-0.
LIBRIZZI, F.P. Public Service Electric & Gas Co. of New Jersey.
80/11/21 2pp, 07084-098

--8011280058 LER 80-058/03L-0 on 801022, control valve for 1CV6B charging header motor found failed in closed position Caused by motor & operator failure Operator replaced from stock & motor sent out for repairs
GBUCH, J.C. Public Service Electric & Gas Co. of New Jersey.
80/11/21 1p, 07084:100.

V Operator Examinations

8011060416 Notifies that shift technical advisors will report directly to operating engineer to effect greater involvement in shift operation & improved awareness of plant conditions.
LIBRIZZI, F.P. Public Service Electric & Gas Co. of New Jersey.
80/10/29, 1p, 06909:039.

8011260086 Discusses telcon re shift experience requirements for licensee candidates Min of 3 months experience is necessary, but should be separated into multiple wk segments on specific topics Course schedules encl
SCHNEIDER, F.W. Public Service Electric & Gas Co. of New Jersey.
80/11/17 9pp 07071 313

DOCKET 80-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D.O. Division of Licensing. 80/09/05. 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D.O. Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D.O. Division of Licensing 80/10/06, 6pp.

8011040079 Forwards list of info needed for completing review of GE emergency procedure guidelines Guidelines have been approved for trial implementation at LaSalle, Zimmer, Shoreham, Fermi 2 & Busquahanna facilities.
EISENHUT, D.O. Division of Licensing 80/10/21, 8pp, 02319-196.

8011210308 Forwards response to NRC 800801 ltr containing Hydrologic Engineering Branch generic questions re Executive Order 11989 concerning floodplain mgt for plants near completion
CRANE, P.A. Pacific Gas & Electric Co 80/11/13 22pp, 07035:083

8011210318 Responds to NRC 800303 request for info re environ qualification program using NUREG-0588. Forwards environ qualification program for safety-related electrical equipment evaluation & tabulation of Class IE equipment.
CRANE, P.A. Pacific Gas & Electric Co 80/11/13 45pp, 02227-001.

8011260125 Forwards info re evaluation of environ qualification program for safety-related electrical & Class IE equipment, in response to 791102 ltr
CRANE, P.A. Pacific Gas & Electric Co 80/11/13, 45pp, 01741:019.

G. Adjudicatory correspondence

801170574 Notification of contract execution, Mod 2 to "Technical Assistance in Preparation of NRC Appeal Brief on Diablo Canyon Nuclear Power Plant Hearing " Contractor: NM Newmark.
HAIRSTON, C.A., GLAGOLA, A.F. Technical Assistance Contracts Branch
FIN B-6874, 80/09/30, 1p 06981:273.

--801170578 Mod 2, modifying scope of work & authorized representative & extending period of performance, to "Technical Assistance in Preparation of NRC Appeal Brief on Diablo Canyon Nuclear Power Plant Hearing "
NEWMARK, N.M. N.M. Newmark Consulting Engineering Services
HALMAN, E.L. Division of Contracts, FIN B-6874, 80/09/30, 2pp 06981, 274.

8011050406 Request for reconsideration of ASLB 801024 order granting extension until 801203 for Joint intervenors to file contentions. Previously granted extensions sufficient. Filing date of 801110 more realistic. W/Certificate of Bvc.
CRANE, P.A., GEHR, A.C., NORTON, B. Pacific Gas & Electric Co.
80/10/27, 3pp, 06898:166.

8011050165 Amended notice of appearance, replacing JA Kline Certificate of Bvc encl.
GEORGIU, B.S. California, State of. 80/10/30, 4pp 06897:311

8011040422 Response in opposition to San Luis Obispo Mothers for Peace 801013 motion for reconsideration of ASLB 801010 order re rejected Contention 12. Intervenor failed to show why access to security plan was not sufficient. Certificate of Bvc encl.
OLMSTEAD, W.J. Hearing Branch 4. 80/10/31, 3pp, 06873, 273.

8011040455 Response in opposition to P&E 801027 motion for reconsideration of ASLB 801024 order granting extension for fuel loading & low power testing contentions Certificate of Bvc encl.
BROWN, M.H., LANPHER, L.C. California, State of. BROWN, M.H. Hill Christopher & Phillips 80/10/31, 4pp, 06873:288.

DOCKETED ITEMS

- 8011100241 Motion for reconsideration of ASLB order scheduling 801110 hearing in security proceeding Urges deferral until 801111 to accommodate flight schedule Certificate of Svc encl BROWN, H. H. Illinois, State of BROWN, H. H. Hill Christopher & Phillips. 80/10/31. 3pp 06929.071
- 8011100227 Petition for directed certification of ASLB 801017 order re Part 3 deciding that hearings on security adequacy will be held in San Francisco, CA Choice of applicant premises compromises impartiality Certificate of Svc encl WILLIS, H. M., BALDWIN, W. A. San Luis Obispo Mothers for Peace BALDWIN, W. A. Baldwin, W. A. 80/11/01 5pp 06912.015
- 8011070198 Order affirming present schedule re holding of an camera hearing in San Francisco, CA from 801110 until full completion BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 80/11/03 2pp. 06921.009.
- 8011070234 Statement in support of San Luis Obispo Mothers for Peace petition for certification of ASLB 801017 order re site of hearing Use of P&E facilities should be preceded by statements of necessity & cost Certificate of Svc encl BROWN, H. H., GEORGIU, B. B. California, State of BROWN, H. H. Hill Christopher & Phillips 80/11/03 3pp 06924.216
- 8011100427 Forwards subpoena form directing until to bring to hearing all records re selection, qualifications & discharge of KK Weaver & LW Houle. Signature requested Newspaper article & Certificate of Svc encl. BROWN, L. H. Hill Christopher & Phillips 80/11/03 5pp 06928.017.
- 8011050451 Lists objections agreed to by parties re Joint Intervenor Exhibits R-6 through R-9 & R-17 Ref should not be made to exhibits as evidence in proceeding OLMSTEAD, W. J. Hearing Branch 4. 80/11/04 3pp 06898.218
- 8011070057 Submits parties' proposal re order of 801110 hearing presentation in San Francisco, CA about security issues. Suggests commencement w/applicant presentation; then Intervenor & State of CA & closing w/applicant rebuttal OLMSTEAD, W. J. Hearing Branch 2 80/11/05 1p 06924.323
- 8011070230 Response to San Luis Obispo Mothers for Peace 801101 petition for review of ASLB 801017 order re site of security hearings. NRC, rests on 801014 response to ASLB 801006 order Certificate of Svc encl OLMSTEAD, W. J. Hearing Branch 2 80/11/05 4pp. 06924.208
- 8011100210 Response in opposition to applicant 801027 motion for reconsideration of ASLB 801024 order which set 801203 for filing contentions re fuel loading & low power testing Plans already made by parties Certificate of Svc encl FLEISCHAKER, D., REYNOLDS, J. San Luis Obispo Mothers for Peace, FLEISCHAKER, D. Fleischaker, D. B. 80/11/05 5pp 06929.043
- 8011100246 Order advising that P&E 801027 motion for reconsideration of ASLB 801024 order is not persuasive Confirms 801203 filing date & urges parties to meet re fuel loading & low power testing contentions BOWERS, E. B. Atomic Safety and Licensing Board Panel 80/11/05 3pp. 06929.074
- 8011100243 Order accepting parties' agreement evidenced per encl WJ Olmstead 801104 ltr re portions of Joint Intervenor Exhibits R6-R9 & R-17 that are not relevant to proceeding. BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 80/11/05. 1p. 06929.082.
- 8011100273 Submits stipulation reached among parties identifying portions of Joint Intervenor Exhibits R7-R9 & R-17 that will not be introduced into evidence due to irrelevancy to seismic proceedings OLMSTEAD, W. J. Hearing Branch 2 80/11/04 3pp 06929.083
- 8011120095 Subpoena directed to PA Crane of P&E to produce refs described in P&E 801017 supplemental response to San Luis Obispo Mothers for Peace interrogatories. Answer A-6 Production must take place at 801110 security plan hearing BALZMAN, R. B. Atomic Safety and Licensing Appeal Panel. 80/11/05. 1p. 06952.182
- 8011120100 Subpoena directed to PA Crane of P&E to produce contracts & documents evidencing agreements w/security force at 801110 security plan hearing. Certificate of Svc encl. BALZMAN, R. B. Atomic Safety and Licensing Appeal Panel. 80/11/05. 4pp 06952.183.
- 8011070025 Notice of withdrawal from proceeding upon departure from NRC. DAVIS, L. D. Hearing Branch 4 80/11/06 1p. 06924.300
- 8011260002 Proposed findings of fact & conclusions of law addressing questions propounded in app to 800624 ALAB-598 Areas addressed include 791015 Imperial Valley earthquake & related soil info Certificate of Svc encl CRANE, P. A. Pacific Gas & Electric Co 80/11/21 59pp 07075.187
- 8011280057 Notice of availability of procedural assistance in adjudicatory licensing proceedings published in 800725 FR in order to qualify for aid. Intervenor must submit statement showing need to ASLB BOWERS, E. B. Atomic Safety and Licensing Board Panel 80/11/24 1p 07084.101
- H General correspondence

- 8011180344 Responds to 800710 ltr urging immediate licensing of facility. Favorable partial initial decision issued but was appealed by Joint Intervenor & hearing reopened by ASLB NRC presently working on timely resolution of safety issues DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/10/08 4p 06915.001
- 8011030086 Responds to 800307 postcard requesting reconsideration of lifting moratorium for licensing facilities All new applications for OLs are required to modify plant design to conform to TMI-related requirement MIRAOLIA, F. J. Resource & Scheduling Branch 80/10/14 2pp 01756.001.
- 8011030192 Requests reconsideration of lifting moratorium on licensing facilities. JOYNER, J. Affiliation Unknown 80/03/07. 1p 01786.001
- 8011050362 Forwards response to 800618 ltr directed to President Carter re proximity of Hsgri fault to plant location. License application is subj of contested adjudicatory proceeding during which concern will be addressed MIRAOLIA, F. J. Licensing Branch 3 80/10/20 3pp 06902.104
- 8011060097 Forwards response to 800610 ltr directed to President Carter re proximity of Hsgri fault to plant location License application is subj of contested adjudicatory proceeding during which concern will be addressed MIRAOLIA, F. J. Licensing Branch 3 80/10/20 4pp 06912.215.
- 8011190643 Responds to 800601 ltr to President Carter re potential for const deficiencies at plant & concern over recent earthquake activity in area MIRAOLIA, F. J. Resource & Scheduling Branch 80/10/20 2pp 07001.243
- 8011190648 Requests response to J & S Baumgartner ltr to President Carter re potential for const deficiency. SEAL, M. H. President of US & Executive Offices 80/06/20 1p 07001.246
- 8011060037 Responds to 800624 ltr to HR Denton re emergency planning, radiation monitoring & safety issues based on TMI accident Subj documents can be found in LPDR at CA Polytechnic State Univ Library Response re alternative fuel source encl MIRAOLIA, F. J. Licensing Branch 3 80/10/24. 4pp 02319.196
- 8011060039 Responds to 800610 ltr to President Carter re effects of low level radiation & emergency preparedness & evacuation of area surrounding plant in view of TMI accident Hearings re security plan scheduled on or about 801110. MIRAOLIA, F. J. Licensing Branch 3 80/10/24 5pp 02319.196
- 8011170514 Responds to 790329 ltr expressing concern re licensing of facilities NRC has reacted positively to improve safety of all nuclear power plants based on TMI lessons learned MIRAOLIA, F. J. Licensing Branch 3 80/10/31 3pp 06911.001.
- 8011170524 Expresses concern re licensing of facilities in light of TMI accident BHIDA, O. Affiliation Unknown 79/03/29 1p 06911.001
- 8011130407 Forwards Norwood 801029 ltr expressing concerns re security hearings Response requested LAQUARSHINO, R. House of Rep., Foreign Affairs 80/11/03 2pp. 06959.145.
- 8011210721 Responds to 800616 ltr to HR Denton re licensing of facility Major delays to completion of const have been due to plant mods resulting from seismic re-evaluation of facility & TMI-2 lessons learned requirements MIRAOLIA, F. J. Licensing Branch 3 80/11/12 2pp. 07029.134

DOCKETED ITEMS

71

--8011210726 Urges NRC to license facility for full power operation
Consumers of P&E want plant opened to reduce high util
bills Amount of oil wasted due to delay is drain on energy
reserves Supporting publications encl
WRINKLE, H H Affiliation Unknown 80/06/16 5pp 07029 136

8011210731 Responds to 800430 postcard to JF Ahearne re licensing of
facility Major delays to completion of const have been due
to plant mods resulting from seismic re-evaluation of
facility & TH1-2 lessons learned requirements
MIRAOLIA, F J Licensing Branch 3 80/11/12 2pp 07174 228

--8011210735 Urges NRC to move ahead w/licensing of facility at earliest
possible date No safer or cleaner large-scale source of
electricity currently available
CURTIS, D J Affiliation Unknown 80/04/30 3pp 02227 001

G. Advisory Committee on Reactor Safeguards reports & correspondence

8011180772 Transcript of ACRS 247th general meeting on 801107 in
Washington, DC. Pp 145-391 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 80/11/07
238pp. 06984-201.

8011190385 Discusses P&E study of possible adverse interactions of
nonsafety sys on plant safety as result of earthquake Util
examination of interactions is suitable & provides addl
assurance re plant ability to withstand earthquake
PLESBET, M. B. ACRS - Advisory Committee on Reactor Safeguards
80/11/12 2pp 06996 192

G. Inspection reports, IE Bulletins & correspondence

8011040779 Forwards IE Info Notice 80-36, "Failure of Steam Generator
Support Bolting." No written response required
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
80/10/10. 1p 06909, 094

8011100014 Responds to IE Bulletin 80-18 re flow through centrifugal
charging pumps Util will review any permanent vendor
recommended design mods when available
CRANE, P. A. Pacific Gas & Electric Co 80/10/16 2pp. 06928 340

8011100061 Ack receipt of 800617 ltr informing NRC of steps taken to
correct violations noted in IE insp rept
BENCER, Q. S. Region 5, San Francisco, Reactor Construction &
Engineering Support Branch 80/10/16 1p 06929 332

--8011100067 Responds to NRC 800519 ltr re violations noted in IE insp
rept. Corrective actions minor variation E-222 initiated to
document problem. Vital roadway supports inspected per QC
Procedure GCP-9
CRANE, P. A. Pacific Gas & Electric Co 80/06/17 2pp 06929-333.

8011100014 Forwards Suppl 3 to IE Bulletin 79-018, "Environ
Qualification of Class IE Equipment" No written response
required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
80/10/24. 1p. 06957, 259

8011170631 Forwards IE Circular 80-23, "Potential Defects in Beloit
Power Sys Emergency Generators" No written response
required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
80/10/31. 1p. 06977 274.

G. Reportable occurrences, LERs & related correspondence

8011200162 PNB-V-80-09: on 801114, NRC resident inspector discovered bomb
threat on automatic telephone recorder Male caller of
unknown identity stated, "there was a bomb set to go off."
Time given was unintelligible.
POWER, E. J., SCHUBERT, M. D. Region 5, San Francisco, Office of the
Director 80/11/14. 1p. 07021, 274.

T: Hearing transcripts on non-antitrust matters

8011030649 Transcript of 801022 hearing re geologic issues in San Luis
Obispo, CA. Pp 462-664. Related documentation encl.
* Atomic Safety and Licensing Board Panel 80/10/22. 300pp
06864:009.

8011120891 Transcript of 801106 Affirmation Session 80-80 in
Washington, DC re BECY-A-80-173 on facility physical security
proceeding motion to move hearing site. Pp 1-3.
* Commissioners. 80/11/06 6pp 06953-334.

U Congressional/Executive Correspondence

8011100384 Forwards ASLAP 801017 order in facility security plan
proceeding Order details why Board decided to hold hearing
at applicant San Francisco, CA facility W/o encl
CHO, J. Atomic Safety and Licensing Appeal Panel 80/11/04 1p
06928 272

DOCKET 30-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8011060342 Notification of cancellation of 801022 meeting w/util to
discuss open items associated w/fire protection review
VERRELLI, D. M. Operating Reactors Branch 4 80/10/06 2pp
06912 307

8011040561 Submits addl info & commitments re fire protection program
in response to 801025 telcon Exterior hose shall be
hydrostatically tested or replaced w/appropriately tested
hose annually
DALYROFF, B. L. Philadelphia Electric Co 80/10/31 2pp 06873 295

O Adjudicatory correspondence

801110565 Forwards orders for mod of Licenses DPR-44 & DPR-86 re
environ qualification of safety-related electrical
equipment Revised Tech Specs also encl
REID, R. W. Operating Reactors Branch 4 80/10/24 2pp 06946 217

--801110570 Order for mod of license re environ qualification of safety-
related electrical equipment Compliance w/Div of Operating
Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D. G. Division of Licensing 80/10/24 6pp 06946-219

--801110576 Revised Tech Spec pages per 801024 order for mod of license
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 2pp 06946 225

--801110579 Order for mod of license re environ qualification of safety-
related electrical equipment Compliance w/Div of Operating
Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D. G. Division of Licensing 80/10/24 6pp 06946 227

--801110582 Revised Tech Spec pages per 801024 order for mod of license
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 2pp 06946 233

8011250009 Informs that final regulations discussed in HJ Miller
800226-27 testimony published in 801003 FR & that Kerr-
McGee filed petition for review on 801003 to have
regulations declared invalid
BORDENICK, B. M. Hearing Branch 4 80/11/19 3pp 07056 183.

P Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of
Mark I owners group to discuss pool swell load definition
techniques & methodology for condensation, oscillation,
chugging & lateral load definition
GRINES, C. I. Assistant Director for Engineers & Projects (Pre
790628) 79/03/02. 2pp 03145 305

8011050354 Ltr to all licensees of operating plants, applicants for OLS
& holders of CPs re preliminary clarification of TH1 action
plan requirements Provides summary listing of all approved
TH1-2 related requirements
EISENHUT, D. G. Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for
OLS & holders of CPs re requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs. Info needed by 801101
EISENHUT, D. G. Division of Licensing 80/10/01 5pp

8011190237 Ltr to all BWR licensees requesting info on plans to assure
long-term scram sys reliability IE Bulletin 80-17 required
mods to assure adequate short-term performance. Info should
be submitted within 25 days
EISENHUT, D. G. Division of Licensing 80/10/01 2pp

DOCKETED ITEMS

- 8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Lou Fracture Toughness & Lameilar Tearing on Component Supports " W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp
- 8010290005 Requests Commission approval of encl clarification & changes to 800905 ltr & encl setting forth complete listing of TMI-related requirements approved for implementation Ltr & encl will be published as NUREG-0737 upon approval
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/10/22 10pp
- 8010290025 Submits assessment of util capabilities to implement near-term TMI action plan requirements & proposed schedule for implementation Duration of outages to accommodate mods estimated to be 2 & 3 wks for Units 2 & 3, respectively
DALTROFF, S L Philadelphia Electric Co 80/10/10 18pp 06928 025
- 801110556 Forwards orders for mod of Licenses DPR-44 & DPR-56 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp 06946 217
- 801110570 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06946 219
- 801110576 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 225
- 8011070125 Forwards Amends 74 & 73 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availability
REID, R W Operating Reactors Branch 4 80/10/28 2pp 06920 242.
- 8011070130 Amends 74 & 73 to Licenses DPR-44 & DPR-56, respectively, revising Tech Specs to incorporate certain TMI-2 Lessons Learned Category A requirements
REID, R W Operating Reactors Branch 4 80/10/28 23pp 06920 244
- 8011070136 Safety evaluation supporting Amends 74 & 73 to Licenses DPR-44 & DPR-56, respectively
* Office of Nuclear Reactor Regulation, Director 80/10/28 4pp 06920 267
- 8011070143 Notice of issuance & availability of Amends 74 & 73 to Licenses DPR-44 & DPR-56, respectively.
REID, R W Operating Reactors Branch 4 80/10/28 2pp 06920 271
- 801110821 Forwards safety evaluation of Amends 72 & 73 to DLs which incorporated mods in response to Item 2.1.5 a of NUREG-0578, "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations " Mods found acceptable
REID, R W Operating Reactors Branch 4 80/10/29 2pp 06972 357
- 801110826 Safety evaluation supporting Amends 73 & 72 to Licenses DPR-44 & DPR-56, respectively Util action to meet NUREG-0578 acceptance criteria is adequate
* Office of Nuclear Reactor Regulation, Director 80/10/29 2pp 06972 359
- 81060566 Submits addl info re implementation of Category A short-term lessons learned requirements of NUREG-0578, per 800102 ltr
DALTROFF, S L Philadelphia Electric Co 80/10/31 2pp 06912 253
- 81110042 Requests addl Class III fee & addl duplicate fee re 800930 proposed changes to Tech Specs Changes would expand max average planar linear heat generation rate & revise reactor protection sys response time
DIGGS, R M License Fee Management Branch, 80/11/03 1p 06943 107
- 8011200061 Confirms that commitments to 791023 "Interim Position of Containment Purging & Venting Pending Resolution of Isolation Valve Operability" are acceptable.
REID, R W Operating Reactors Branch 4 80/11/05 2pp 07018 153.
- 1250308 Forwards "Rept of Plant Startup Following Fourth Refueling Outage, Mar 1980 "
DEN, W M Philadelphia Electric Co 80/11/10 2pp 07055 109.
- 8011250299 "Rept of Plant Startup Following Fourth Refueling Outage, Mar 1980 "
* Philadelphia Electric Co 80/03/31 9pp 07055 110
- 8011180497 Submits info re environ qualification of safety-related equipment in response to NRC 801001 ltr One environ qualification test planned for Peach Bottom, w/pertinent info encl info for Limerick will be provided 801128
KEMPER, J S Philadelphia Electric Co 80/11/12 2pp 06988 254
- 8011180695 Responds to NRC 800922 request for addl info re adequacy of station electric distribution sys Voltages Voltages on several typical distribution panels verified to be on same per unit basis as corresponding motor control ctrs
DALTROFF, S L Philadelphia Electric Co 80/11/13 5pp 06991 201
- 8011250370 Responds to 801031 ltr requesting detailed outline of scope & schedule for meeting NUREG-0660 Requirement II K 3.30 Requests that NRC communicate directly w/OE re LOCA analysis models OE will discuss schedule by 801215
DALTROFF, S L Philadelphia Electric Co 80/11/19 2pp 07068 118
- G Inspection reports, IE Bulletins & correspondence
- 8011070067 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required.
ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/30 1p 06920 037
- 8011190195 Ack receipt of 801006 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-16 & 50-278/80-14
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/17 1p 06998 247
- 8011190203 Responds to NRC 800915 ltr re violations noted in IE Insp Repts 50-277/80-16 & 50-278/80-14 Corrective actions operator was counseled & importance of surveillance re-emphasized
DALTROFF, S L Philadelphia Electric Co 80/10/06 2pp 06998 248
- 8011190240 Forwards IE Insp Repts 50-277/80-16 & 50-278/80-14 on 800601-30 & notice of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/15 2pp 06998 250
- 8011190244 Notice of violation from insp on 800601-30
* Region 1, Philadelphia, Office of the Director 80/09/15 1p 06998 252
- 8011190254 IE Insp Repts 50-277/80-16 & 50-278/80-14 on 800601-30 Noncompliance noted: failure to properly log valve positions as required when isolation valve is inoperable
COWGILL, C J, BLOUGH, A R Region 1, Philadelphia, Office of the Director, GREENMAN, E G Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/15 7pp 06998 253
- 8011060639 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required.
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06909 317
- 8011070312 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required.
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06921 356
- 801110965 Forwards orders for mod of Licenses DPR-44 & DPR-56 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp
- 801110570 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06946 217
- 801110576 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 225

8011260431 Ack receipt of 801017 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-277/80-14 & 80-278/80-12
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/27 1p 07073 070

--8011260433 Responds to NRC 800926 ltr re violations noted in IE Insp Repts 80-277/80-14 & 80-278/80-12 Corrective actions obstructions impeding access to fire stations removed & red borders painted around critical areas
DALTROFF, S L Philadelphia Electric Co 80/10/17 2pp 07073 071

--8011260437 Forwards IE Insp Repts 80-277/80-14 & 80-278/80-12 on 800501-31 & notice of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/26 2pp 07073 073

--8011260441 Notice of violation from insp on 800501-31
* Region 1, Philadelphia, Office of the Director 80/09/23 1p 07073 075

--8011260446 IE Insp Repts 80-277/80-14 & 80-278/80-12 on 800501-31 Noncompliance noted operational safety verification, control room insps, nonroutine event review & IE bulletin & circular followup.
COWGILL, C J, BLOUGH, A R Region 1, Philadelphia, Office of the Director GREENMAN, E G Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/23 1p 07073 076

8011140240 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06968 235

8011140383 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp" No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06963 143

8011190124 Responds to 800829 order for mod of license requiring submittal of info re environ qualification of safety-related electrical equipment Vols 1 & 2 to util response to IE Bulletin 79-010 encl
DALTROFF, S L Philadelphia Electric Co 80/10/31 600pp 07008 350

8011260331 Submits interim response to IE Bulletin 80-11 re masonry wall evaluation Describes function of masonry walls, matls used in const, requirements for proper const & evaluation of load & load combinations
DALTROFF, S L Philadelphia Electric Co 80/11/03 37pp 07072 227

R Periodic operating reports & related correspondence

8011180665 Forwards monthly operating repts for Oct 1980
COONEY, M J Philadelphia Electric Co 80/11/12 1p 06915 001

--8011180673 Monthly operating repts for Oct 1980
ALDEN, W M Philadelphia Electric Co 80/11/12 9pp 06915 001

S Reportable occurrences, LERs & related correspondence

8011060354 RD 2-80-24/1P on 801020, standby gas treatment sys design reviewed for comparison to Limerick Station. Instrument air piping to moisture controller not seismically qualified Spec for sys did not specify qualification requirements.
ULLRICH, W T Philadelphia Electric Co 80/10/21 2pp 02319 176

8011040486 LER 80-021/03L-0 on 800924, BT revealed that indication for SW-2671A ~ Q control switches was lost Caused by short in coil of dymo type solenoid valve which blew common fuse in control circuit for all seven valves Common fuse replaced
COONEY, M J Philadelphia Electric Co 80/10/24 1p 06877 291

801120500 RD on 801106, during increase of reactor power from hot standby condition, main steam bypass valve 3 exhibited erratic operation. Caused by defective circuitry board Board removed Stable pressure control sys re-established
ULLRICH, W T Philadelphia Electric Co 80/11/06 2pp 06916 001.

801120501 RD on 801105, while performing routine surveillance test on HPCI sys, HPCI observed to start, trip & restart in succession several times Caused by open resistor which provides input power to emergency generator motor Component replaced
ULLRICH, W T Philadelphia Electric Co 80/11/06 2pp 06916 001.

8011170493 LER 80-023/03L-0 on 801019, standby gas treatment sys B filter assembly inlet isolation valve AD-00476-01 failed to open Caused by ruptured diaphragm Valve replaced & proper solenoid & isolation valve operation verified
COONEY, M J Philadelphia Electric Co 80/11/07 1p 06975 071

8011180652 LER 80-022/03L-0 on 801015, surveillance testing of DPIS 2-14-43B, core spray sparger to reactor pressure vessel delta-pressure switch, revealed setpoint was below Tech Spec FBI limit Caused by setpoint drift Instrument recalibr
COONEY, M J Philadelphia Electric Co 80/11/08 1p 06992 104

8011240499 PND-I-80-165 on 801116, during Startup, O 5 CI release occurred Increases in recombiner room & roof vent radioactivity monitors noted w/ slight increase in air ejector exhaust pressure Caused by blown loop seal
COWGILL, C, MCCABE, E C, WHITE, J R Region 1, Philadelphia, Office of the Director 80/11/17 1p 07039 259

8011250396 Forwards LER 80-026/01T-0
COONEY, M J Philadelphia Electric Co 80/11/19 2pp 07056 340

--8011250404 LER 80-026/01T-0 on 801105, HPCI turbine observed to trip & restart several times Caused by open resistor in power supply to HPCI turbine electronic governor motor (EGM), preventing EGM controls from receiving correct speed signal
COONEY, M J Philadelphia Electric Co 80/11/19 1p 07056:342

DOCKET 80-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8011060342 Notification of cancellation of 801022 meeting w/ util to discuss open items associated w/ fire protection review
VERRELLI, D M Operating Reactors Branch 4 80/10/06 2pp 06912 307

8011040561 Submits addl info & commitments re fire protection program in response to 801025 telcon Exterior hose shall be hydrostatically tested or replaced w/ appropriately tested hose annually
DALTROFF, S L Philadelphia Electric Co 80/10/31 2pp 06873 295

G Adjudicatory correspondence

801110565 Forwards orders for mod of Licenses DPR-44 & DPR-56 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp 06946 217

--801110579 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/ Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06946:227

--801110582 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 233

8011250209 Informs that final regulations discussed in HJ Miller 800226-27 testimony published in 801003 FR & that Kerr-McCree filed petition for review on 801003 to have regulations declared invalid.
BORDENICK, B M Hearing Branch 4 80/11/19 3pp 07056 183

P. Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/ representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation oscillation, chugging & lateral load definition
GRIMES, C. I Assistant Director for Engineers & Projects (Pre 790623) 79/03/02 2pp 03143 305

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of THM action plan requirements Provides summary listing of all approved THM-2 related requirements
EISENHUT, D O Division of Licensing. 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp.

DOCKETED ITEMS

- 8011190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance info should be submitted within 25 days
EISENHUT, D G Division of Licensing 80/10/01 2pp
- 8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800927 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " N/o encl
EISENHUT, D G Division of Licensing 80/10/06 4pp
- 8010290005 Requests Commission approval of encl clarification & changes to 800705 ltr & encl setting forth complete listing of TMI-related requirements approved for implementation Ltr & encl will be published as NUREG-0737 upon approval
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/10/22 10pp
- 8010290025 Submits assessment of util capabilities to implement near-term TMI action plan requirements & proposed schedule for implementation Duration of outages to accommodate mods estimated to be 2 & 3 wks for Units 2 & 3, respectively
DALTROFF, S L Philadelphia Electric Co 80/10/10 18pp 06828 025
- 8011110965 Forwards orders for mod of Licenses DPR-44 & DPR-56 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp
- 011110579 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201.
EISENHUT, D G Division of Licensing 80/10/24 6pp, 06946 227
- 8011110582 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 233
- 8011070125 Forwards Amends 74 & 73 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availability.
REID, R W Operating Reactors Branch 4 80/10/28 2pp 06920 242
- 8011070130 Amends 74 & 73 to Licenses DPR-44 & DPR-56, respectively, revising Tech Specs to incorporate certain TMI-2 Lessons Learned Category A requirements
REID, R W Operating Reactors Branch 4 80/10/28 23pp 06920 244
- 8011070136 Safety evaluation supporting Amends 74 & 73 to Licenses DPR-44 & DPR-56, respectively
* Office of Nuclear Reactor Regulation, Director 80/10/28 4pp 06920 267
- 8011070143 Notice of issuance & availability of Amends 74 & 73 to Licenses DPR-44 & DPR-56, respectively
REID, R W Operating Reactors Branch 4 80/10/28 2pp 06920 271
- 11170821 Forwards safety evaluation of Amends 72 & 73 to OLs which incorporated mods in response to Item 2.1.3 a of NUREG-0578, "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations " Mods found acceptable
REID, R W Operating Reactors Branch 4 80/10/29 2pp 06972 357
- 8011170826 Safety evaluation supporting Amends 73 & 72 to Licenses DPR-44 & DPR-56, respectively Util action to meet NUREG-0578 acceptance criteria is adequate
* Office of Nuclear Reactor Regulation, Director, 80/10/29 2pp, 06972 359
- 8011060566 Submits addl info re implementation of Category A short-term lessons learned requirements of NUREG-0578, per 800102 ltr
DALTROFF, S L Philadelphia Electric Co 80/10/31 2pp 06912 253
- 8011100942 Requests addl Class III fee & addl duplicate fee re 800930 proposed changes to Tech Specs. Changes would expand max average planar linear heat generation rate & revise reactor protection sys response time
DIGNON, R M License Fee Management Branch 80/11/03 1p 06943 107
- 8011200061 Confirms that commitments to 791023 "Interim Position of Containment Purging & Venting Pending Resolution of Isolation Valve Operability" are acceptable
REID, R W Operating Reactors Branch 4 80/11/05 2pp 07018 133
- 8011180497 Submits info re environ qualification of safety-related equipment, in response to NRC 801001 ltr One environ qualification test planned for Peach Bottom, w/pertinent info encl info for Limerick will be provided 801128
KEMPFER, J S Philadelphia Electric Co 80/11/12 2pp 06988 254
- 8011180695 Responds to NRC 800922 request for addl info re adequacy of station electric distribution sys voltages Voltages on several typical distribution panels verified to be on same per unit basis as corresponding motor control ctrs
DALTROFF, S L Philadelphia Electric Co 80/11/13 5pp 06991 283
- 8011250370 Responds to 801031 ltr requesting detailed outline of scope & schedule for meeting NUREG-0660 Requirement II K 3.30 Requests that NRC communicate directly w/GE re LOCA analysis models GE will discuss schedule by 801215
DALTROFF, S L Philadelphia Electric Co 80/11/19 2pp 07068 118
- G Inspection reports, IE Bulletins & correspondence
- 8011070067 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/30 1p 06920 037
- 8011190195 Ack receipt of 801006 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-16 & 50-278/80-14
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/17 1p 06998 247
- 8011190203 Responds to NRC 800915 ltr re violations noted in IE Insp Repts 50-277/80-16 & 50-278/80-14 Corrective actions operator was counseled & importance of surveillance re-emphasized.
DALTROFF, S L Philadelphia Electric Co 80/10/06 2pp 06998 248
- 8011190240 Forwards IE Insp Repts 50-277/80-16 & 50-278/80-14 on 800601-30 & notice of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/15 2pp 06998 250
- 8011190244 Notice of violation from insp on 800601-30
* Region 1, Philadelphia, Office of the Director 80/09/15 1p 06978 252
- 8011190254 IE Insp Repts 50-277/80-16 & 50-278/80-14 on 800601-30 Noncompliance noted failure to properly log valve positions as required when isolation valve is inoperable
CONGILL, C J, BLOUGH, A R Region 1, Philadelphia, Office of the Director GREENMAN, E O Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/15 7pp 06998 253
- 8011060639 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director, 80/10/24 1p 06909 317
- 8011070312 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06921 356
- 8011110565 Forwards orders for mod of Licenses DPR-44 & DPR-56 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp
- 8011110579 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp
- 8011110582 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing, 80/10/24 2pp
- 8011260431 Ack receipt of 801017 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-14 & 50-278/80-12.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/27 1p 07073 070.

DOCKETED ITEMS

75

--8011260433 Responds to NRC 800926 ltr re violations noted in IE Insp Repts 50-277/80-14 & 50-278/80-12 Corrective actions obstructions impeding access to fire stations removed & red borders painted around critical areas
DALTROFF, S L Philadelphia Electric Co 80/10/17 2pp 07073 071

--8011260439 Forwards IE Insp Repts 50-277/80-14 & 50-278/80-12 on 800501-31 & notice of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/26 2pp 07073 073

--8011260441 Notice of violation from insp on 800501-31
* Region 1, Philadelphia, Office of the Director 80/09/23 1p 07073 075

--8011260446 IE Insp Repts 50-277/80-14 & 50-278/80-12 on 800501-31 Noncompliance noted operational safety verification, control room insps, nonroutine event review & IE bulletin & circular followup.
COHOILL, C J, BLOUGH, A R Region 1, Philadelphia, Office of the Director GREENMAN, E Q Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/23 1p 07073 076

801140240 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
GRIER, S H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06968 235

801140583 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required
GRIER, S H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06963 143

801190124 Responds to 800829 order for mod of license requiring submittal of info re environ qualification of safety-related electrical equipment Vols 1 & 2 to util response to IE Bulletin 79-018 encl
DALTROFF, S L Philadelphia Electric Co 80/10/31 600pp 07008.350

8011260331 Submits interim response to IE Bulletin 80-11 re masonry wall evaluation Describes function of masonry walls, mats used in const. requirements for proper const & evaluation of load & load combinations
DALTROFF, S L Philadelphia Electric Co 80/11/03 37pp 07072:227

R Periodic operating reports & related correspondence

801180665 Forwards monthly operating repts for Oct 1980
COONEY, M J Philadelphia Electric Co 80/11/12 1p 06915 001

--801180673 Monthly operating repts for Oct 1980
ALDEN, W M Philadelphia Electric Co 80/11/12 9pp 06915.001.

S Reportable occurrences, LERs & related correspondence

8011060354 RD 2-80-24/1P on 801020, standby gas treatment sys design reviewed for comparison to Limerick Station Instrument air piping to moisture controller not seismically qualified Spec for sys did not specify qualification requirements
ULLRICH, W T Philadelphia Electric Co 80/10/21 2pp. 02319.196.

DOCKET 50-280 BERRY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

801130154 Forwards summary of mods for resolution of open items re NRC proposed rule on min fire protection requirements Evaluation of fire doors & hose stations & review status encl
VARQA, S A Operating Reactors Branch 1 80/10/09 1ipp. 06957:325.

8011040506 Forwards "Fire Hazard Safe Shutdown Evaluation," resolving SER open items per 801009 discussion, & updated project status summary of fire protection mods
BYLVIA, B R Virginia Electric & Power Co. 80/10/31 2pp 06877:205.

--8011040519 Forwards updated project status rept of all fire protection mods,
BYLVIA, B R. Virginia Electric & Power Co. 80/10/31, 1ipp. 06877:207.

--8011040527 "Fire Hazard/Safe Shutdown Evaluation," resolving SER open items
* Virginia Electric & Power Co 80/10/31 59pp 06877 216

8011070174 Notification of 801107 meeting w/util in Bethesda, MD to discuss emergency plan Matters may also pertain to North Anna
NEIGHBOR, J D Licensing Branch 1 80/11/03 2pp 06920 300

8011170683 Summary of 801027 meeting w/util in Bethesda, MD re emergency response facilities
DROHERICK, A W Licensing Branch 1 80/11/05 5pp 06977 353

G Adjudicatory correspondence

801110497 Forwards orders for mod of Licenses DPR-32 & DPR-37 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, S A Operating Reactors Branch 1 80/10/24 2pp 06946.157.

--801110501 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D Q Division of Licensing 80/10/24 6pp 06946.159.

--801110507 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D Q Division of Licensing 80/10/24 6pp 06946.165

--801110515 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 171

P. Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D O. Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O. Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " H/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

801110497 Forwards orders for mod of Licenses DPR-32 & DPR-37 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, S A Operating Reactors Branch 1 80/10/24 2pp 06946 157

--801110501 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O. Division of Licensing 80/10/24 6pp. 06946.159

--801110515 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 2pp. 06946 171

801190561 Forwards request for addl info re auxiliary feedwater automatic initiation & flow indication Response requested by 801201 Items relate to NUREG-0660, Action Plan Item II.E.1.2.
VARQA, S A Operating Reactors Branch 1 80/10/29 4pp 07001.277

8011210443 Forwards request for addl info generated from review of "Asymmetric LOCA Loading," WCAP-7428 & 7748, dtd Nov 1979 & June 1980, respectively
LAINAS, G C Assistant Director for Safety Assessment 80/10/29 27pp.

801120599 Requests balance of payment for 800516 application for Proposed Change 86 re clarification of term "operable"
DIOSB, R M. License Fee Management Branch. 80/10/30 1p 06953.176.

DOCKETED ITEMS

- 8011200397 Notification of 801203 meeting w/utill in Bethesda, MD to discuss util plans in area of core reload licensing in upcoming yr
BERGQREH, J S Standardization & Special Projects Branch. 80/11/06 2pp 07020 068
- 801110320 Submits info re environ qualification tests to be conducted on safety-related equipment per 801001 request. Describes test programs to assist in planning & scheduling of NRC audits of test programs
BYLVIA, B R Virginia Electric & Power Co 80/11/07 3pp. 06943.212
- 8011190782 Forwards proposed amend to DLs changing Tech Specs to incorporate addl limiting conditions of operation, surveillance requirements & bases for areas of instrumentation, in response to NRC 800702 ltr request.
FERGUSON, J H Virginia Electric & Power Co. 80/11/14. 3pp 06996.320
- 8011190287 Proposed Tech Spec changes to amend DLs incorporating addl limiting conditions of operation, surveillance requirements & bases for areas of instrumentation, reactor coolant sys, auxiliary feedwater sys & administrative controls
* Virginia Electric & Power Co 80/11/14 50pp 06996.323
- 8011240300 Requests that NRC re-evaluate determination of required amend fee re 800316 license amend application. Amend should be evaluated as administrative, changes requested in NRC 800410 ltr do not involve new & unreviewed safety issues.
BYLVIA, B R Virginia Electric & Power Co. 80/11/17 1p. 07049 099
- 8011280085 Forwards interim safety evaluation of auxiliary feedwater sys Requests addl info re auxiliary feedwater flow control valves
VARQA, B A Operating Reactors Branch 1 80/11/17 19pp 07081.311
- 11210216 Informs that installation of redundant safety-grade RCB pressure input to core subcooling monitors will not be installed on Unit 2 until spring maint outage currently scheduled for May 1981
BYLVIA, B R Virginia Electric & Power Co 80/11/18 1p 07032.317
- 8011250395 Responds to NUREG-0737 re TMI Action Plan Items II K 3 9 & II K 3 12. Rate time constants on proportional integral derivatives set equal to zero. Anticipatory reactor trip upon turbine trip confirmed
BYLVIA, B R Virginia Electric & Power Co 80/11/21 1p. 07056 122
- Q Inspection reports, IE Bulletins & correspondence
- 8011040325 Ack receipt of 801010 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-32 & 50-281/80-35
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/22 1p 06874:185
- 8011040330 Responds to NRC 800917 ltr re violations noted in IE Insp Repts 50-280/80-32 & 50-281/80-35. Corrective actions: new procedure for specifically processing hanger mods issued
BYLVIA, B R Virginia Electric & Power Co 80/10/10 2pp. 06874 186
- 8011040337 Forwards IE Insp Repts 50-280/80-32 & 50-281/80-35 on 800820-22 & notice of violation.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/17 2pp. 06874:188
- 8011040340 Notice of violation from insp on 800820-22
* Region 2, Atlanta, Office of the Director. 80/09/16 1p 06874:190
- 8011040345 IE Insp Repts 50-280/80-32 & 50-281/80-35 on 800820-22 Noncompliance noted: improper installation & insp of pipe support
COMPTON, R M Region 2, Atlanta, Office of the Director, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/16 5pp 06874:191.
- 8011100431 Requests extension of IE Bulletin 80-11 deadline for completion of masonry wall re-evaluation program. Based on current schedule & available manpower, reanalysis is scheduled for completion by Jul 1981.
BYLVIA, B R Virginia Electric & Power Co. 80/10/24. 2pp. 06929:216
- 801110497 Forwards orders for mod of Licenses DPR-32 & DPR-37 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
VARQA, B A Operating Reactors Branch 1 80/10/24 2pp
- 801110591 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 800630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24. 6pp 06946.189
- 801110515 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp
- 8011170672 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24. 1p. 06976 246
- 8011040327 Forwards response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." & 800829 order for mod of license re environ qualification of electrical equipment, submitted as 90-day rept Master list encl
BYLVIA, B R Virginia Electric & Power Co 80/10/31. 500pp 06878 354.
- 8011070479 Forwards updated response to IE Bulletin 80-11, submitting re-evaluation criteria used to evaluate masonry walls & informing of progress & schedule for completing re-evaluation program
BYLVIA, B R Virginia Electric & Power Co 80/11/03. 49pp. 06918.218.
- 8011200376 Ack receipt of 801002 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-280/80-31
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/03 1p 07020 056
- 8011200379 Responds to NRC 800910 ltr re violations noted in IE Insp Rept 50-280/80-31 Corrective actions: S&W instructed to respond to IE Bulletin 79-14.
BYLVIA, B R Virginia Electric & Power Co 80/10/02 4pp. 07020 057
- 8011200382 Forwards IE Insp Rept 50-280/80-31 on 800805-06 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/10 2pp 07020 061
- 8011200386 Notice of violation from insp on 800805-06.
* Region 2, Atlanta, Office of the Director 80/09/08 1p 07020.063
- 8011200390 IE Insp Rept 50-280/80-31 on 800805-06 Noncompliance noted: improper pipe support installation & insp.
COMPTON, R M Region 2, Atlanta, Office of the Director, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/08 4pp 07020.064
- 8011260338 Updates 800707 response to IE Bulletin 80-11, "Masonry Wall Design." Walls not meeting initial conservative acceptance criteria are being analyzed using more refined analytical techniques. Final results will be submitted upon completion
BYLVIA, B R Tennessee Valley Authority 80/11/03 47pp 07075:121.
- 801120281 Notifies that required inservice insps are complete & available for review at site
BYLVIA, B R Virginia Electric & Power Co. 80/11/07. 1p 06953 278
- 8011210352 Suppl 800424 response to IE Bulletin 79-13, Revision 2, re cracking in feedwater sys piping. No reportable indications found during listed insps
BYLVIA, B R Virginia Electric & Power Co 80/11/07. 2pp. 02227:001.
- 8011240349 Advises that 80111 ltr incorrectly indicated that inservice insp was completed on Unit 1. Required ASME B&PV Code Section XI, IAW-6220, Paragraph B insp has been completed for Unit 2. Insp rept available at site.
BYLVIA, B R Virginia Electric & Power Co 80/11/20. 1p. 07049:093.

DOCKETED ITEMS

77

R Periodic operating reports & related correspondence

8011140387 Forwards monthly operating repts for Oct 1980
BYLVIA, B. R. Virginia Electric & Power Co 80/11/12 1p
06911:001

--8011140388 Monthly operating repts for Oct 1980
BUNN, B. D. Virginia Electric & Power Co 80/11/05 48pp
06911:001.

B Reportable occurrences, LERs & related correspondence

8011030492 Forwards updated LER 79-012/03X-1
WILSON, J. L. Virginia Electric & Power Co 80/10/27 1p
06855:096

--8011030493 Updated LER 79-012/03X-1 on 790402, during shutdown
functional test of 74 snubbers revealed 21 not meeting
design criteria. Caused by snubbers not being readjusted to
design conditions. Units reset.
WILSON, J. L. Virginia Electric & Power Co 80/10/27 3pp.
06855:097.

8011040394 Forwards LER 80-059/01T-0
WILSON, J. L. Virginia Electric & Power Co 80/10/30 1p
06973:101.

--8011040402 LER 80-059/01T-0 on 801016, util confirmed Westinghouse input
re potential for loss of auxiliary feedwater flow following
small steamline rupture. Caused by original auxiliary
feedwater sys design. Emergency procedures changed.
WILSON, J. L. Virginia Electric & Power Co 80/10/30 3pp.
06873:102.

8011140006 Forwards LER 80-067/01T-0
WILSON, J. L. Virginia Electric & Power Co. 80/11/10 1p
06961:304.

--8011140009 LER 80-067/01T-0 on 801028, indications found on all three
steam generators. Caused by original const Weld areas will be
completely machined out & replaced.
WILSON, J. L. Virginia Electric & Power Co. 80/11/10 2pp
06961:305.

8011210310 Forwards LERs 80-033/03L-0, 80-032/03L-0 & 80-062/03L-0
WILSON, J. L. Virginia Electric & Power Co 80/11/17 1p
07034:035.

--8011210322 LER 80-033/03L-0 on 801024, w/unit at 100% power, positive
pressure of greater than 0.05 inches of water could not be
maintained in control room. Caused by deterioration of door
seals. Defective doors repaired.
WILSON, J. L. Virginia Electric & Power Co. 80/11/17 2pp.
07034:037.

--8011210335 LER 80-032/03L-0 on 801020, during check of low heat tracing
alarm, circuit 2A panel 11 found to have low amps. Caused by
damage to heat tracing tape. Operation of redundant heat
tracing circuit verified & tape replaced.
* Virginia Electric & Power Co 80/11/17, 2pp 07034:039

--8011210350 LER 80-062/03L-0 on 801019, w/unit at cold shutdown &
defueled, PT 26.1 showed RM-CC-105/106 alarm setpoint to be
greater than twice background radiation levels. Caused by
decrease in background radiation levels. Setpoints reduced.
* Virginia Electric & Power Co 80/11/17 2pp 07034:041.

8011250366 Forwards LER 80-069/03L-0
WILSON, J. L. Virginia Electric & Power Co 80/11/20 1p
07056:329.

--8011250372 LER 80-069/03L-0 on 801022, PT-27D revealed low amp reading
for panel B, circuit 13A (boron injection recirculation to
boric acid tanks). Caused by excessive heat. Failed heat tape
replaced.
WILSON, J. L. Virginia Electric & Power Co. 80/11/20 2pp.
07056:330.

V. Operator Examinations

8011260089 Informs NRC that corporate ofc personnel will be utilized as
certifiers re startup certification program in order to
regain independence from power station staffs & in light of
basis for NRC approval of certification program.
FERGUSON, J. M. Virginia Electric & Power Co 80/11/20 1p.
07071:322.

DOCKET 80-281 BARRY POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8011130154 Forwards summary of mods for resolution of open items re NRC
proposed rule on min fire protection requirements. Evaluation
of fire doors & hose stations & review status encl
VAROA, B. A. Operating Reactors Branch 1 80/10/09 11pp
06957:325

8011040906 Forwards "Fire Hazard Safe Shutdown Evaluation," resolving
SER open items per 801009 discussion, & updated project
status summary of fire protection mods
BYLVIA, B. R. Virginia Electric & Power Co 80/10/31 2pp
06877:205

--8011040519 Forwards Updated project status rept of all fire protection
mods.
BYLVIA, B. R. Virginia Electric & Power Co 80/10/31 11pp
06877:207

--8011040527 "Fire Hazard/Safe Shutdown Evaluation," resolving SER open
items
* Virginia Electric & Power Co 80/10/31 59pp 06877:216

8011070174 Notification of 801107 meeting w/util in Bethesda, MD to
discuss emergency plan matters may also pertain to North
Anne.
NEIGHBOR, J. D. Licensing Branch 1 80/11/03 2pp. 06920:300

8011170683 Summary of 801027 meeting w/util in Bethesda, MD re emergency
response facilities.
DRONERICK, A. W. Licensing Branch 1 80/11/05 3pp 06977:353

G Adjudicatory correspondence

8011110497 Forwards orders for mod of Licenses DPR-32 & DPR-37 re
environ qualification of safety-related electrical
equipment. Revised Tech Specs also encl.
VAROA, B. A. Operating Reactors Branch 1 80/10/24 2pp 06946:157.

--8011110507 Order for mod of license re environ qualification of safety-
related electrical equipment. Compliance w/Div of Operating
Reactors guidelines or NUREG-0588 required by 820630.
Complete records must be available by 801201.
EISENHUT, D. O. Division of Licensing 80/10/24 6pp 06946:165

--8011110515 Revised Tech Spec pages per 801024 order for mod of licenses
re environ qualification of safety-related electrical
equipment.
* Division of Licensing 80/10/24 2pp 06946:171

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs
& holders of CPs re preliminary clarification of TMI action
plan requirements. Provides summary listing of all approved
TMI-2 related requirements.
EISENHUT, D. O. Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for
DLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs. Info needed by 801101.
EISENHUT, D. O. Division of Licensing 80/10/01 5pp.

8011100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports" w/o encl.
EISENHUT, D. O. Division of Licensing 80/10/06 6pp

8011140639 Submits responses to 800731 comments on draft EIS re steam
generator repair program. Comments received after 800731
issuance of FEB
VAROA, B. A. Operating Reactors Branch 1. 80/10/22 5pp 06963:260

8011110497 Forwards orders for mod of Licenses DPR-32 & DPR-37 re
environ qualification of safety-related electrical
equipment. Revised Tech Specs also encl.
VAROA, B. A. Operating Reactors Branch 1. 80/10/24 2pp.

--8011110507 Order for mod of license re environ qualification of safety-
related electrical equipment. Compliance w/Div of Operating
Reactors guidelines or NUREG-0588 required by 820630.
Complete records must be available by 801201.
EISENHUT, D. O. Division of Licensing. 80/10/24 6pp. 06946:165.

DOCKETED ITEMS

- 801110513 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp
- 8011040012 Forwards VEP-FRD-37, "Surry Unit 2, Cycle 5 Startup Physics Test Rept"
THOMAS, W H Virginia Electric & Power Co 80/10/29 1p
02319 196
- 8011040014 "Surry Unit 2, Cycle 5 Startup Physics Test Rept"
LEDERSTEIN, J H, ROSS, T K Virginia Electric & Power Co
VEP-FRD-37 80/10/31 72pp 02319 196
- 801190951 Forwards request for addl info re auxiliary feedwater automatic initiation & flow indication Response requested by 801201 items relate to NUREG-0460, Action Plan Item II E 1.2
VARQA, B A Operating Reactors Branch 1 80/10/29 4pp 07001 277
- 8011210443 Forwards request for addl info generated from review of "Asymmetric LDOA Loading," WCAP-9628 & 9748, dtd Nov 1979 & June 1980, respectively
LAINAS, Q C Assistant Director for Safety Assessment 80/10/29 27pp
- 801120599 Requests balance of payment for 800516 application for Proposed Change 85 re clarification of term "operable"
DIOG9, R M License Fee Management Branch 80/10/30 1p
06933 178
- 8011200377 Notification of 801203 meeting w/util in Bethesda, MD to discuss util plans in area of core reload licensing in upcoming yr
BERGOREN, J B Standardisation & Special Projects Branch 80/11/06 2pp 07020 068
- 801110320 Submits info re environ qualification tests to be conducted on safety-related equipment per 801001 request Describes test programs to assist in planning & scheduling of NRC audits of test programs
SYLVIA, B R Virginia Electric & Power Co 80/11/07 3pp
06943 212
- 801190282 Forwards proposed amend to DLs changing Tech Specs to incorporate addl limiting conditions of operation, surveillance requirements & bases for areas of instrumentation, in response to NRC 800702 ltr request
FERGUSON, J H Virginia Electric & Power Co 80/11/14 3pp
06996 320
- 801190287 Proposed Tech Spec changes to amend DLs incorporating addl limiting conditions of operation, surveillance requirements & bases for areas of instrumentation, reactor coolant sys, auxiliary feedwater sys & administrative controls
* Virginia Electric & Power Co 80/11/14 50pp 06996 323
- 8011240300 Requests that NRC re-evaluate determination of required amend fee re 800516 license amend application Amend should be evaluated as administrative changes requested in NRC 800410 ltr do not involve new & unreviewed safety issues
SYLVIA, B R Virginia Electric & Power Co 80/11/17 1p
07049 099
- 8011280085 Forwards interim safety evaluation of auxiliary feedwater sys Requests addl info re auxiliary feedwater flow control valves
VARQA, B A Operating Reactors Branch 1 80/11/17 19pp
07081 311
- 8011210216 Informs that installation of redundant safety-grade RCB pressure input to core subcooling monitors will not be installed on Unit 2 until spring maint outage currently scheduled for May 1981
SYLVIA, B R Virginia Electric & Power Co, 80/11/18 1p
07032 317.
- 8011250355 Responds to NUREG-0737 re TMI Action Plan Items II K 3 9 & II K 3 12 Rate time constants on proportional integral derivatives set equal to zero Anticipatory reactor trip upon turbine trip confirmed
SYLVIA, B R Virginia Electric & Power Co 80/11/21 1p,
07056 122
- 8011040330 Responds to NRC 800917 ltr re violations noted in IE Insp Repts 50-280/80-32 & 50-281/80-35 Corrective actions: new procedure for specifically processing hanger mods issued
SYLVIA, B R Virginia Electric & Power Co 80/10/10 2pp
06874 186
- 8011040337 Forwards IE Insp Repts 50-280/80-32 & 50-281/80-35 on 800820-22 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/17 2pp 06874 188
- 8011040340 Notice of violation from insp on 800820-22
* Region 2, Atlanta, Office of the Director 80/09/16 1p
06874 190
- 8011040345 IE Insp Repts 50-280/80-32 & 50-281/80-35 on 800820-22 Noncompliance noted improper installation & insp of pipe support
COMPTON, R M Region 2, Atlanta, Office of the Director,
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/16 3pp 06874 191
- 8011040431 Requests extension of IE Bulletin 80-11 deadline for completion of masonry wall re-evaluation program Based on current schedule & available manpower, reanalysis is scheduled for completion by Jul 1981
SYLVIA, B R Virginia Electric & Power Co 80/10/24 2pp
06929 296
- 801110497 Forwards orders for mod of licenses DPR-32 & DPR-37 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, B A Operating Reactors Branch 1 80/10/24 2pp
- 801110507 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines on NUREG-0388 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 4pp
- 801110515 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp
- 801170672 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24 1p 06976 246
- 8011040327 Forwards response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment," & 800829 order for mod of license re environ qualification of electrical equipment, submitted as 90-day rept Master list encl
SYLVIA, B R Virginia Electric & Power Co 80/10/31 500pp
06878 334
- 8011070479 Forwards updated response to IE Bulletin 80-11, submitting re-evaluation criteria used to evaluate masonry walls & informing of progress & schedule for completing re-evaluation program
SYLVIA, B R Virginia Electric & Power Co 80/11/03 49pp
06918 218
- 8011260338 Updates 800707 response to IE Bulletin 80-11, "Masonry Wall Design," Walls not meeting initial conservative acceptance criteria are being analyzed using more refined analytical techniques Final results will be submitted upon completion
SYLVIA, B R Tennessee Valley Authority 80/11/03 47pp
07075 121
- 8011240349 Advises that 80111 ltr incorrectly indicated that inservice insp was completed on Unit 1 Required ASME B&PV Code Section XI, IAW-4220, Paragraph B insp has been completed for Unit 2 Insp rept available at site
SYLVIA, B R Virginia Electric & Power Co 80/11/20 1p
07049 093
- R Periodic operating reports & related correspondence
- 8011140387 Forwards monthly operating repts for Oct 1980,
SYLVIA, B R Virginia Electric & Power Co, 80/11/12, 1p
06911-001
- 8011140388 Monthly operating repts for Oct 1980,
DUNN, S D, Virginia Electric & Power Co 80/11/05 48pp
06911 001,
- Q Inspection reports, IE Bulletins & correspondence
- 8011040325 Ack receipt of 801010 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-32 & 50-281/80-35,
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/22 1p 06874:185

DOCKETED ITEMS

79

S Reportable occurrences, LERs & related correspondence

8011040371 Forwards LERs 80-023/03L-0, 80-026/03L-0 & 80-027/03L-0
WILSON, J L Virginia Electric & Power Co 80/10/31 1p
06873 082

--8011040576 LER 80-023/03L-0 on 801003, while operating at 100% power,
during periodic test 27D, low amp readings found on circuit
18, panels 10 & 11, causing valve MOV-2867D to be considered
inoperable. Caused by damaged heat tracing tapes
WILSON, J L Virginia Electric & Power Co 80/10/31 2pp
06873 083

--8011040586 LER 80-026/03L-0 on 801005, w/reactor at 100% power &
redundant low head safety injection pump out of svc for
maint, operator failed to retest operable pump 2-SI-P-1a
within specified time. Caused by operator oversight
WILSON, J L Virginia Electric & Power Co 80/10/31 2pp
06873 085

--8011040592 LER 80-027/03L-0 on 801005, w/unit at 100% power, PT-27B
revealed that amp reading for circuit 6A, boric acid to
blender, panel 11 was below acceptance criteria. Caused by
failure of heat tracing tape due to excessive heat
WILSON, J L Virginia Electric & Power Co 80/10/31 2pp
06873 087

801100501 Forwards LER 80-030/03L-0
WILSON, J L Virginia Electric & Power Co 80/11/04 1p
06931 086

--801100505 LER 80-030/03L-0 on 801013, at 100% power, PT-27B indicated
low amp reading on circuit 6A, boric acid to blender panel
10. Caused by heat tracing failure due to mechanical damage
sustained from erecting scaffolding
WILSON, J L Virginia Electric & Power Co 80/10/04 2pp
06931:057

801100012 Forwards LER 80-029/03L-0
WILSON, J L Virginia Electric & Power Co 80/11/07 1p
06961:309

--801100017 LER 80-029/03L-0 on 801012, svc water pump 2-SW-P-10A
developed low discharge pressure. Caused by seal lodged in
impeller. Seal removed, pump returned to svc
WILSON, J L Virginia Electric & Power Co 80/11/07 2pp
06961:310

801180601 Forwards LERs 80-031/03L-0 & 80-035/01T-0
WILSON, J L Virginia Electric & Power Co 80/11/13 1p
06988 111

--801180609 LER 80-031/03L-0 on 801015, pipe support in alternate
charging header found in overstressed condition per IE
Bulletin 79-14, Suppl 2. Caused by faulty installation
Modified support & returned subsys to svc
* Virginia Electric & Power Co 80/11/13 2pp 06988:112

--801180618 LER 80-035/01T-0 on 801101, electrical transient tripped
breaker & two emergency generators started & loaded. Caused
by contact of jackhammer with power cable. Emergency diesel
generators verified operating & supplying emergency buses.
WILSON, J L Virginia Electric & Power Co 80/11/13 2pp
06988:114

801120510 Forwards LERs 80-033/03L-0, 80-032/03L-0 & 80-062/03L-0
WILSON, J L Virginia Electric & Power Co 80/11/17 1p
07034:036

--801120535 LER 80-032/03L-0 on 801020, during check of low heat tracing
alarms, circuit 2A panel 11 found to have low amps. Caused by
damage to heat tracing tape. Operation of redundant heat
tracing circuit verified & tape replaced
* Virginia Electric & Power Co 80/11/17 2pp 07034:039

8011240091 RO on 801102, during cold shutdown, condenser cooling water
outlet temp exceeded max rate of change of 3 F/hr. Caused by
lack of svc water flow through Unit 1. No detrimental
evidence found re river environ.
BYLVIA, B R Virginia Electric & Power Co 80/11/19 1p
07049 148.

V. Operator Examinations

8011260089 Informs NRC that corporate o/c personnel will be utilized as
certifiers re startup certification program in order to
regain independence from power station staffs & in light of
basis for NRC approval of certification program
FERGUSON, J H Virginia Electric & Power Co 80/11/20 1p
07071:322

DOCKET 30-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

801190398 Notices of interim rule suspending completion dates for
fire protection mods previously approved by NRC FR notice
encl
EISENHUT, D O Division of Licensing 80/10/31 5pp 06996 214

801180156 Notification of 801112 meeting w/util in Minneapolis, MN to
provide further clarification of emergency planning
requirements
MARTIN, R E Operating Reactors Branch 3 80/11/10 2pp
06987 217

8011260222 Requests addl info & commitments for review of onsite
emergency plan against NUREG-0694 criteria. Revised plan
should address encl comments
CLARK, R A Operating Reactors Branch 3 80/11/14 17pp
07074 093

G Adjudicatory correspondence

801140683 Forwards order for mod of Licenses DPR-42 & DPR-60 re
environ qualification of safety-related electrical
equipment. Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06968 199

--801140692 Order for mod of licenses re environ qualification of
safety-related electrical equipment. Compliance w/Div of
Operating Reactors guidelines or NUREG-0588 required by
820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06968 201

--801140695 Revised Tech Spec pages per 801024 order for mod of licenses
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 4pp 06968 207

P Operating license stage documents & correspondence

8011050394 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TMI action
plan requirements. Provides summary listing of all approved
TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100215 "LWR In-Plant Measurement Program," informal monthly
progress rept for Aug 1980
MANDLER, J W EG&G Idaho, Inc FIN A-6075 801100215 80/09/19
4pp 06931:129.

801100486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs. Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports." W/o encl.
EISENHUT, D O Division of Licensing 80/10/06 6pp.

801140683 Forwards order for mod of Licenses DPR-42 & DPR-60 re
environ qualification of safety-related electrical
equipment. Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06968:199

--801140692 Order for mod of licenses re environ qualification of
safety-related electrical equipment. Compliance w/Div of
Operating Reactors guidelines or NUREG-0588 required by
820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06968:201

--801140695 Revised Tech Spec pages per 801024 order for mod of licenses
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 4pp 06968 207.

801190224 Forwards request for addl info necessary to continue review
of 800131 license amend request re spent fuel storage mod.
CLARK, R A Operating Reactors Branch 3 80/11/05 13pp
06999:338

DOCKETED ITEMS

8011170217 Responds to NRC 801001 request for info re environ qualification tests to be conducted within 2 yrs Provides schedule for valve monitoring sys re pressurizer power operated relief safety valves
MAYER, L D Northern States Power Co 80/11/06 2pp 06968 358

8011140263 Documents util commitment to perform mods to satisfy NRC interim position re containment purge & vent valve operation prior to resuming purging Purge & vent valve circuitry being reviewed Results will be transmitted in approx 6 wks
MAYER, L D Northern States Power Co 80/11/07 2pp 06961 286

8011170555 Responds to NRC 801031 ltr requesting implementation dates for revised post-TMI requirements Advises that NRC ltr was not received until 801110, reducing 45-day response time by 10 days Efforts will be undertaken to prepare response
MAYER, L D Northern States Power Co 80/11/14 2pp 06977 311

8011210484 Informs NRC that work on distribution sys voltage evaluation was deferred due to heavy work load Some progress has been made in completing evaluation Remaining work should be completed within 8 wks
MAYER, L D Northern States Power Co 80/11/17 1p 07035 114

8011230410 Requests relief from TMI action plan implementation schedule of NUREG-0737, Item 11.F.2, re final instrumentation for detection of inadequate core cooling Affidavit encl
MAYER, L D Northern States Power Co 80/11/20 3pp 07056 108

8011280022 Requests amend to Licenses DPR-42 & DPR-60 re decay heat removal capability Water depth over irradiated fuel Tech Spec changes also proposed
* Northern States Power Co 80/11/24 1p 07084 127

8011280063 Forwards application for amend of Licenses DPR-42 & DPR-60, changing Tech Specs re decay heat removal & water depth over irradiated fuel Class III fee encl
MAYER, L D Northern States Power Co 80/11/24 1p 07082 234

--8011280066 Application for amend of Licenses DPR-42 & DPR-60, changing Tech Specs Section 3 & Table 4 1-2A re decay heat removal & water depth over irradiated fuel
MAYER, L D Northern States Power Co 80/11/24 3pp 07082 255

--8011280068 Proposed changes to Tech Specs Section 3 & Table 4 1-2A re decay heat removal & water depth over irradiated fuel
* Northern States Power Co 80/11/24 6pp 07082 258

Inspection reports, IE Bulletins & correspondence

11070035 Forwards IE Insp Repts 50-282/80-14 & 50-306/80-15 on 800801-31 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/09/19 2pp 06921 041

8011070040 IE Insp Repts 50-282/80-14 & 50-306/80-15 on 800801-31 No noncompliance noted Major areas inspected: plant operation maint, surveillance, security, radiation protection, organization, training & followup on IE bulletins
FEIERABEND, C D, BURGESS, B L, LITTLE, W S Region 3, Chicago, Office of the Director 80/09/19 3pp 06921 043

8011070263 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/24 1p 06924:255

11140692 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp

8011140695 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 4pp

11050147 Forwards IE Insp Repts 50-282/80-15 & 50-306/80-16 on 800901-30 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/28 2pp 06977:263

8011050153 IE Insp Repts 50-282/80-15 & 50-306/80-16 on 800901-30 No noncompliance noted Major areas inspected: operation, maint, surveillance, security, radiation protection & refueling activities
FEIERABEND, C D, BURGESS, B L, LITTLE, W S Region 3, Chicago, Office of the Director 80/10/08 6pp 06897:285

8011190304 Updates NRC 800903 ltr re site access of Region 3 personnel. New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc
Badge examples encl
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28 3pp 06999 162

8011030467 Forwards "Inservice Insp Examination Summary," 800818-1013
MAYER, L D Northern States Power Co 80/10/30 1p 06860 024

--8011030471 "Inservice Insp Examination Summary," 800818-1013
HASSEN, D B, DAHLMAN, L C, ANDERSON, R W Northern States Power Co 80/10/21 58pp 06860 025

8011190019 Forwards final response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Replacement of solenoid valves, limit switches & other instruments is being accomplished as matl is received
OILBERTS, D E Northern States Power Co 80/10/31 130pp 06999 131

8011190079 Submits addl response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Two outstanding Unit 1 welds examined ultrasonically & found acceptable
OILBERTS, D E Northern States Power Co 80/10/31 1p 06999 204

8011240471 Forwards final response to IE Bulletin 80-11, "Masonry Wall Design," containing schedule for field mods & updated response to Items 1.2a & 3 W/o encl
OILBERTS, D E Northern States Power Co 80/11/04 2pp 07049:073

R Periodic operating reports & related correspondence

8011170308 Forwards monthly operating repts for Oct 1980
MAYER, L D Northern States Power Co 80/11/11 1p 06975:086

--8011170510 Monthly operating repts for Oct 1980
HUNSTAD, A A Northern States Power Co 80/11/01 8pp 06975 087

S Reportable occurrences, LERs & related correspondence

8011040615 Informs that matter of inadvertent safety injection during surveillance testing resolved per util 791107 response to NRC 790921 & 0626 ltrs.
CLARK, R A Operating Reactors Branch 3 80/10/23 2pp 06875:166

8011170802 Describes status of environ qualification deficiency re NAIHCD EA-180 limit switch installation discovered during IE Bulletin 79-018 investigations Matl necessary to upgrade switch installation has been ordered
MAYER, L D Northern States Power Co 80/11/13 2pp 06968:273

8011210628 Forwards LER 80-031/03L-0
MAYER, L D Northern States Power Co 80/11/14 1p 07029 148

--8011210632 LER 80-031/03L-0 on 801017, during surveillance program review, discovery was made that steam exclusion test SP1112 was not done for Sept 1980 Caused by personnel oversight
No changes considered Involved personnel will review rept
HUNSTAD, A A Northern States Power Co 80/11/14 1p 07029 149

V Operator Examinations

8011040122 Responds to NRC 800731 ltr re interim criteria for shift staffing Requirements outlined have been implemented re administrative procedures, movement of key individuals about the plant & overtime work.
MAYER, L D Northern States Power Co 80/10/29 1p 06874 071

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

8011030586 Advises that Feedwater line cracks issue considered closed per review of 790618, 0808, 1025, 1111 & 800229 submittals. All examinations performed per IE Bulletins 79-13, 79-02 & 79-14
CLARK, R A Licensing Branch 3 80/09/26 2pp 06860 082

8011030586 Advises that feedwater line cracks issue considered closed per review of 790618,0808,1023,1111 & 800229 submittals All examinations performed per IE Bulletins 79-13,79-02 & 79-14
CLARK,R A Licensing Branch 3 80/09/26 2pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101
EISENHUT,D G Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laxellar Tearing on Component Supports " W/o encl
EISENHUT,D G Division of Licensing 80/10/06 6pp

8011030932 Notifies that util 760611 application to amend Tech Specs re core barrel motion monitoring sys will be considered withdrawn Sys does not present significant safety concern
CLARK,R A Operating Reactors Branch 3 80/10/09 2pp 06855 115

8011060367 Forwards Amend 52 to License DPR-40,safety evaluation & notice of issuance & availability
CLARK,R A Operating Reactors Branch 3 80/10/14 2pp 06912 270

--8011060375 Amend 52 to License DPR-40,changing Tech Specs to revise charcoal filter flow rates & clarify term operable
CLARK,R A Operating Reactors Branch 3 80/10/14 11pp 06912 272

--8011060379 Safety evaluation supporting Amend 52 to License DPR-40
* Operating Reactors Branch 3 80/10/14 12pp 06912 283

--8011060383 Notice of issuance & availability of Amend 52 to License DPR-40
CLARK,R A Operating Reactors Branch 3 80/10/14 2pp 06912 295

8011040495 Forwards plant electrical drawings,per 800815 ltr Drawings withheld (ref 10CFR2 790)
JONES,W C Omaha Public Power District 80/10/21 3pp 06873 142

8011040507 Forwards info re environ qualification tests to be conducted within 2 yrs on equipment to be used at facility in response to NRC 801001 request Schedules are set by vendors & util contact
JONES,W C Omaha Public Power District 80/10/31 2pp 06873.067

8011140127 Submits info clarifying QA requirements for diesel generator fuel oil requested in NRC 800717 ltr Tests to be performed onsite prior to adding new fuel include specific or API gravity,water & sediment & viscosity Oil added to Q-list
JONES,W C Omaha Public Power District 80/11/07 1p 06964 361

8011190491 Responds to TMI Action Plan Item II K 3 30 Util involved in C-E owners group preparation of prediction for LOFT Test L3-6 for small-break LOCA Model changes would be inappropriate prior to NRC review of owners group model
JONES,W C Omaha Public Power District 80/11/12 1p 06996 243

8011180435 Forwards application for amend to License DPR-40 Certificate of Evc encl
LEBDEUF,R J, LAMB,H R, LEIBY,A C LeBdeuf, Lamb, Leiby & MacRae
80/11/17 2pp 06988 281

--8011180452 Application for amend to License DPR-40 consisting of changes to Tech Specs.
JONES,W C Omaha Public Power District 80/11/14 2pp 06988 283

--8011180461 Tech Specs table of contents,definitions for azimuthal power tilt,unrodded planar radial peaking factor,unrodded integrated radial peaking factor,fire suppression water sys & dose equivalent I-131 & 2 O for limiting conditions
* Omaha Public Power District 80/11/14 16pp 06988 285.

Q Inspection reports, IE Bulletins & correspondence

8011050337 Forwards IE Insp Rept 50-285/80-15 on 800730-0831 & notice of violation Notice of violation withheld (ref 10CFR2 790)
MADSEN,G L Region 4, Dallas, Reactor Operations Nuclear Support Branch. 80/09/16. 2pp 06899 288.

--8011050340 IE Insp Rept 50-285/80-15 on 800730-0831 Noncompliance noted in area of physical security Details withheld (ref 10CFR2 790).
KELLEY,B L, HUNNICUTT,D M Region 4, Dallas, Office of the Director. 80/09/11 4pp 06899 290

8011030586 Advises that feedwater line cracks issue considered closed per review of 790618,0808,1023,1111 & 800229 submittals All examinations performed per IE Bulletins 79-13,79-02 & 79-14
CLARK,R A Licensing Branch 3 80/09/26 2pp 06860 082

8011140130 Forwards IE Circular 80-22 "Confirmation of Employee Qualifications " No written response required
SEYFRIT,K V Region 4, Dallas, Office of the Director 80/10/02 1p 06963 209

8011060749 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No written response required
SEYFRIT,K V Region 4, Dallas, Office of the Director 80/10/10 1p 06909 043

8011190651 Ack receipt of 801002 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/80-15
MADSEN,G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/10/21 1p 07001 229

8011190131 Forwards update to 800417 ltr,containing responses to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" & NRC 800919 order for license mod Significant changes to response includes new Encls 14-17
JONES,W C Omaha Public Power District 80/10/31 400pp. 07001 296

R Periodic operating reports & related correspondence

8011180443 Forwards monthly operating rept for Oct 1980
JONES,W C Omaha Public Power District 80/11/12 1p 06915 001

--8011180447 Monthly operating rept for Oct 1980
PATTERSON,T L Omaha Public Power District 80/11/12 8pp 06915 001

S Reportable occurrences, LERs & related correspondence

8010230559 Discusses apparent deficiency in insp techniques used for studs which secure flanged surfaces Program should be established to ensure that studs & bolts on pumps,valves & piping connections are inspected to detect wastage
NOVAK,T M Assistant Director for Operating Reactors 80/09/26. 1p 03560-001

8011120469 Forwards LER 80-026/03L-0
STEVENB,B C Omaha Public Power District 80/11/04 1p 06952.199

--8011120476 LER 80-026/03L-0 on 801030,AB-1 matrix relay failed to trip clutch power supplies Caused by failure of matrix circuit to break contact Relay replaced & applicable surveillance test performed to demonstrate operability
CORE,M Omaha Public Power District 80/10/30 4pp 06952 200

8011250465 Forwards LER 80-027/03L-0
STEVENB,B C Omaha Public Power District 80/11/07 1p 07036 103

--8011250474 LER 80-027/03L-0 on 801027,during monthly ac sequencer timer test,timer FW-6 on sequencer Si-2 failed to time out within prescribed limit Caused by sticky operating mechanism Timer replaced w/spare.
MUELLER,R Omaha Public Power District 80/11/03 4pp 07036:104

V. Operator Examinations

8011040395 Responds to NRC 800731 interim criteria for shift manning Supports NRC position on importance of maintaining adequate operating personnel Program for upgrading shift manning encl
JONES,W C Omaha Public Power District 80/10/30 3pp 06880 178.

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8011070503 Forwards revised security force training & qualification plan Plan withheld (ref 10CFR2 790).
BAYNE,J P. Power Authority of the State of New York 80/10/28 2pp 06921-016

DOCKETED ITEMS

801170814 Forwards results of NRC sponsored vital area analysis for facility Security plan may be required as result of vital area analysis Requests review of security plan & results of review forwarded to NRC Encl withheld (ref 10CFR2 790)
VARQA,B A Operating Reactors Branch 1 80/10/30 2pp 06972 335

801180317 Forwards facility emergency planning info for placement in LPDR w/o encl
SOUJER,J L Division of Rules and Records 80/11/04 1p
06991 158

801170572 Confirms 800930 telcon re fixed battery pack emergency lighting Util will be unable to provide tested fire barrier ac & dc feedlines inside containment
DAYNE,J P Power Authority of the State of New York 80/11/07 2pp 06979 200.

801180475 Forwards revised listing of fire damper installations per fire protection review plan
DAYNE,J P Power Authority of the State of New York 80/11/12 8pp 06991 259

O Adjudicatory correspondence

801110100 Forwards order for mod of License DPR-64 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA,B A Operating Reactors Branch 1 80/10/24 3pp 06943 308

--801110112 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT,D O Division of Licensing 80/10/24 6pp 06943 311

--801110120 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06943 317

801190738 Informs that 800611 response to item E 2 of 800211 confirmatory order re assessment of facility control rooms lacks details & specificity needed to conduct thorough review Forwards NRC 801031 ltr to Con Ed re control room
VARQA,B A Operating Reactors Branch 1 80/10/31 3pp 07001 171

H General correspondence

8011060195 Responds to encl 800823 ltr to President Carter requesting facilities be shutdown because of threat to life. Two reactors may continue to operate until completion of hearing process to re-examine safety considerations.
INGRAM,F Office of Public Affairs 80/10/20 2pp 02319.196

011060474 Urges facility shutdown
CASSEL,R , CASSEL,F Affiliation Unknown 80/10/25 1p
02319 196

011040408 Requests FI Blalik name be added to svc lists for all matters re facilities,BNL & transport of nuclear matls in NY
BIALIK,E I New York State of 80/10/31 1p

801190498 Petitions for denial of Con Ed & PASNY petition to resume operations pending full investigation of safety issues to be adjudicated at forthcoming hearings
SCHNEIDER,B , MOTYCKA,M , BERNARD,T J Affiliation Unknown
80/11/18 4pp 07001 289

8011260175 Urges expedited safety hearings on facility NRC should order interim shutdown immediately Expresses concern re facility being located in densely populated area
DELOFOLLO,B J , STRAUSS,B B , STRAUSS,R R Affiliation Unknown
80/11/18, 1p 07071 337

8011210461 Demands immediate shutdown of facility.Risks too great in populous area
LASLO,M.W. Affiliation Unknown 80/11/20 1p 02227 001

J Insurance & indemnity information

8011050438 Forwards util 790307 ltr forwarding Endorsements 32 & 33 to MAELU Policy NF-77 & Endorsements 38-40 to NELIA Policy NF-208.In response to 800924 request.
DEEG,F H Power Authority of the State of New York. 80/10/31. 1p
06894:105.

P Operating license stage documents & correspondence

8011050384 Ltr to all licensees of operating plants,applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT,D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT,D O Division of Licensing 80/10/01 5pp

8011030205 Forwards table giving calculated peak values & associated probabilities & weather conditions for several risk measures at facilities Values should be viewed as representative of general shape of curve.
MURLEY,T E Office of Nuclear Regulatory Research, Director
80/10/03 3pp 06896 279.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " N/o encl
EISENHUT,D.O Division of Licensing 80/10/06 6pp

801110128 Requests supporting info re util 800811 auxiliary feedwater sys analyses Addl analyses must demonstrate that reduced flow rate can adequately remove heat decay w/o operator action for at least 10 minutes
VARQA,B.A Operating Reactors Branch 1 80/10/09 2pp. 06943 119

8011050370 Act receipt of 800523 application (IPN-80-50) re clarification of term "operable" Class II amend fee on 800905 Addl review indicates applicability of Class III fee Addl sum should be promptly submitted
MILLER,W.O License Fee Management Branch. 80/10/16 1p.
06899-021

801110100 Forwards order for mod of License DPR-64 re environ qualification of safety-related electrical equipment.Revised Tech Specs also encl
VARQA,B A Operating Reactors Branch 1 80/10/24 3pp 06943 308

--801110112 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT,D.O Division of Licensing 80/10/24 6pp. 06943:311

--801110120 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06943.317

8011030452 Forwards check to cover cost of processing Tech Spec change re definition of "operable" in response to NRC 801016 ltr
DAYNE,J P Power Authority of the State of New York 80/10/27 2pp 06872 310.

8011060298 Notification of 801106 meeting w/utills in Bethesda,MD to discuss task action plan.
OLSHAN,L , WIGGINTON,D Operating Reactors Branch 1 80/10/27 1p.
06911-289.

8011070167 Notification of cancellation of 801106 meeting w/utills in Bethesda,MD to discuss status of task action plan
OLSHAN,L , WIGGINTON,D Operating Reactors Branch 1 80/10/27 2pp. 06920 298

8011060569 Forwards response to NRC 800919 order for mod of license re environ qualification of electrical equipment.Responds to concerns noted in 800919 draft interim technical evaluation rept.Splice analysis encl
ZULLA,B B Power Authority of the State of New York. 80/10/30. 10pp 06914 164.

--8011060572 "Design Approval Tests on Mtls Used in Westinghouse Penetrations for Brunswick Station of Carolina Power & Light Co."
CARPENTER,P.E , KORNER,R.L , SHAFFER,R. Westinghouse Electric Corp 72/08/11 43pp. 06914:174.

--8011060577 Revision I, "Qualification of NAMCO Controls Limit Switch Model EA-180 to IEEE Std 344 ('75),323 ('74) & 382 ('72)."
PATHEY,J.J , SOLEM,E L , SKINOLE,T.J Acme-Cleveland Co., Namco Controls Div 78/09/05 18pp 06914:217.

--B011060582 "Seismic Qualification Test of Limit Control Switches " W/
supporting documentation
* Acme-Cleveland Co , Namco Controls Div 77/06/30 60pp
06914 234

B011030529 Forwards application for amend of License DPR-64, App A Tech
Specs, revising Section 1 12 to reflect max & cumulative
surveillance intervals in STS for Westinghouse plants Class
III fee encl
BAYNE, J P Power Authority of the State of New York 80/10/31
2pp 06861 123

--B011030536 Application for amend of License DPR-64, App A Tech Specs,
revising Section 1 12 to reflect max & cumulative
surveillance intervals in STS for Westinghouse plants Safety
evaluation & revised Tech Spec encl
BAYNE, J P Power Authority of the State of New York 80/10/31
3pp. 06861 125

B011040182 Forwards application for amend to OL & proposed Tech Spec
changes assuring min of 23 ft of water over top reactor
pressure vessel flange during fuel assembly movement
BAYNE, J P Power Authority of the State of New York 80/10/31
2pp 06874 047

--B011040186 Application for amend to OL, changing App A Tech Specs to
assure min water level over fuel assemblies is sufficient
to prevent inadvertent exposure of fuel assembly during
movement
BAYNE, J P. Power Authority of the State of New York 80/10/31
1p. 06874 049

--B011040210 Proposed changes to Tech Spec Pages 3 B-2 & 3.8-4 re min
water level during fuel movement
* Power Authority of the State of New York 80/10/31 3pp
06874 050

--B011040216 Safety evaluation re min water level during fuel movement
* Power Authority of the State of New York 80/10/31 2pp
06874 053

B011190738 Informs that B00611 response to Item E 2 of B00211
confirmatory order re assessment of facility control rooms
lacks details & specificity needed to conduct thorough
review Forwards NRC B01031 ltr to Con Ed re control room
VARQA, S A. Operating Reactors Branch 1 80/10/31 3pp 07001:171

B011180433 Forwards application to amend License DPR-64, changing App A
Tech Spec 3 3 to preclude spurious closing of RHR sys
miniflow line valves, per NRC B00922 request, Class III fee
encl
BAYNE, J P Power Authority of the State of New York 80/11/07.
2pp. 06991:223

--B011180442 Application for amend to License DPR-64, changing App A Tech
Spec 3 3 to avert possible RHR pump damage by precluding
spurious closing of Miniflow Valves 1870 & 743, per B00922
request
BAYNE, J.P. Power Authority of the State of New York 80/11/07.
1p. 06991 225

--B011180449 Proposed Tech Spec 3 3 re RHR sys miniflow line valves.
Safety evaluation encl
* Power Authority of the State of New York. 80/11/07. 4pp
06991 226

B011180532 Advises of initiation of actions to request Tech Spec
change, deleting chlorine concentration requirements
Compliance w/site discharge limits on chlorine will be
maintained
ZULLA, B. S. Power Authority of the State of New York 80/11/12
2pp. 06992:130

B011180729 "Hudson River White Perch," quarterly progress rept
Apr-June, 1980
VAN NINKLE, W , BARNHOUSE, L W Oak Ridge National Laboratory FIN
B-0423. B011180729 80/11/13 85pp 06913 001

B011250280 Responds to NRC B00902 request for revised offsite dose
calculation manual based on Commission review comments
Revised manual will be provided by B0101, Proposed schedule
is acceptable
BAYNE, J P. Power Authority of the State of New York 80/11/18 1p
07032:349.

B011250327 Provides info re evaluation of feasibility of bringing
coolant pipe into reactor cavity. Discharging water in
reactor cavity is feasible. Detailed evaluations of design
features will await probabilistic risk assessment analysis.
BAYNE, J.P. Power Authority of the State of New York 80/11/18 1p.
07038.352.

G Inspection reports, IE Bulletins & correspondence

B011130061 Forwards IE Insp Rept 50-286/80-12 on B00813-19 No
noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/09/24 2pp 06958 191

--B011130066 IE Insp Rept 50-286/80-12 on B00813-19 No noncompliance
noted Major areas inspected util mgt & technical competence
in areas of shift technical advisors & training &
qualifications of personnel
KISTER, H B Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch REBELOWSKI, T Region 1, Philadelphia, Office of
the Director WILLIAMS, F J Assistant Director for Licensing
80/09/22 10pp 06958 193

B011070034 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " No written response
required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/09/30 1p 06924 307

B011210708 Forwards IE Insp Rept 50-286/80-08 on B00608-0802 No
noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/10/02 2pp 07029 303

--B011210715 IE Insp Rept 50-286/80-08 on B00608-0802 No noncompliance
noted Major areas inspected plant operations, licensee action
on previous insp findings & observation of physical
security
REBELOWSKI, T , KENNY, T , PADLINO, R Region 1, Philadelphia, Office
of the Director 80/09/26 23pp 07029 305

B011070271 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " No written response
required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06921 268

B011110100 Forwards order for mod of License DPR-64 re environ
qualification of safety-related electrical equipment Revised
Tech Specs also encl
VARQA, S A Operating Reactors Branch 1 80/10/24 3pp 06943 308

--B011110112 Order for mod of license re environ qualification of safety-
related electrical equipment Compliance w/Div of Operating
Reactors guidelines or NUREG-0588 required by B00630
Complete records must be available by B01201
EISENHUT, D.G Division of Licensing 80/10/24. 4pp 06943 311

--B011110120 Revised Tech Spec pages per B01024 order for mod of license
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 2pp 06943 317

B011050453 Forwards "Mid-Cycle Steam Generator Insp."
BAYNE, J P Power Authority of the State of New York 80/10/31
2pp 06894 015

--B011050455 "Mid-Cycle Steam Generator Insp "
* Power Authority of the State of New York. 80/10/29 20pp.
06894 017

B011140077 Forwards IE Circular 80-23, "Potential Defects in Beloit
Power Sys Emergency Generators " No written response
required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06968 259

B011170676 Forwards IE Info Notice 80-39, "Malfunction of Solenoid
Valves Hfg by Valcor Engineering Corp " No written response
is required
GRIER, B.H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06979 211

B011250342 Submits results of facility turbine disc insp performed
during Oct 1980. Results correct data previously submitted in
B00201 ltr
BAYNE, J P Power Authority of the State of New York 80/11/18
2pp 07035.132.

R Periodic operating reports & related correspondence

B011060080 Partial response to FOIA request for info re radiation
levels of plant environs & dump sites & radiation levels in
nine listed places Forwards documents listed in App A. Search
is continuing for documents re second part of request
FELTON, J H. Division of Rules and Records 80/10/29 2pp

DOCKETED ITEMS

--8011060122 Excerpts from environ monitoring annual repts Includes Indian Point rept for 1978 & ME Yankee & JA Fitzpatrick Repts for 1979
* Consolidated Edison Co of New York 80/10/29 15pp

8011170521 Forwards data specified in Section 401 certification for Oct 1980
KONIL, W A Consolidated Edison Co of New York 80/11/10 18pp
06968 277

8011180651 Forwards monthly operating rept for Oct 1980
ZULLA, S S Power Authority of the State of New York 80/11/14 1p.
06915 001

--8011180650 Monthly operating rept for Oct 1980
CONNELL, C. Power Authority of the State of New York 80/11/01 8pp 06915 001

8011180683 Forwards tabulation of daily record of fish collections for Oct 1980
ZARAKAS, P Consolidated Edison Co of New York 80/11/14 1p
06991 267

--8011180690 Tabulation of daily record of fish collections for Oct 1980
* Consolidated Edison Co of New York 80/11/14 4pp
06991 268

S Reportable occurrences, LERs & related correspondence

8011190437 Forwards LER 80-013/03L-0
ZULLA, S S Power Authority of the State of New York 80/11/15.
2pp 06916 001.

--8011190439 LER 80-013/03L-0 on 801017, safety valve PCV-466 leaked excess pressure through throat & valve PCV-464 found w/setpoint below min Caused by grooves on valve seat of PCV-466 Valve seat lapped on PCV-466 & PCV-464 reset
QUAKES, E.F.W Power Authority of the State of New York 80/11/15 1p 06916 001

T Hearing transcripts on non-antitrust matters

8011240472 Transcript of 801114 public meeting in Washington, DC re investigation of containment flooding event at Indian Point 2 & restart of Indian Point 3 Pp 1-156
* Office of Inspection & Enforcement, Office of the Director.
80/11/14 156pp. 07047 287

--8011240478 Forwards draft order re interim operation during adjudicatory hearing
BICKHIT, L. Office of the General Counsel SECY-A-80-179A
80/11/13 33pp 07048 084

--8011240486 Discusses proposed footnote re procedural issues for ASLP to follow, due to investigative nature of proceeding
BICKHIT, L. Office of the General Counsel. SECY-A-80-179
80/11/13 16pp 07048 114

U Congressional/Executive Correspondence

8011170215 Urges decertification of Con Ed as facility operator due to poor operating record
OTTINGER, R L House of Rep. 80/10/31 1p 06981 356.

8011170440 Discusses NRC investigation of facts re water leakage into facility containment as important concern to author & other citizens Urges direct consideration re suspension or revocation of QLS.NRC findings requested
MOFFETT, T. House of Rep., Government Operations. 80/11/05 2pp
06977.268

V Operator Examinations

8011040464 Responds to NRC 800731 interim criteria for shift staffing Administrative procedure revised to meet criteria & new overtime restrictions Addl operator on loan from Con Ed per util response to 800211 confirmatory order
BAYNE, J.P. Power Authority of the State of New York 80/10/29 2pp. 06877 161

DOCKET 80-287 OCONEE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8011250172 Forwards Revision 5 to security plan Revision withheld (ref 10CFR2 790)
PARKER, W.D Duke Power Co 80/11/17 1p 07068 306.

0 Adjudicatory correspondence

8011101039 Forwards order for mod of Licenses DPR-38, DPR-47 & DPR-55 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4. 80/10/24 2pp 06943 326

--8011101055 Order for mod of licenses re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0888 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06943 328

--8011101071 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing. 80/10/24 2pp 06943.334.

8011050143 Order denying Carolina Environ Study Group 801006 motion to reopen record & rejecting NRC 801027 motion for extension re spent fuel transshipments
MILLER, M E. Atomic Safety and Licensing Board Panel 80/10/31 2pp 02319 196

8011060393 Initial decision denying util 780309 application for amend of BHM license authorizing transshipment of spent nuclear fuel from Oconee for storage in McGuire Initial decision shall constitute final action 45 days from issuance
HAND, C.H., LUEBKE, E.A., MILLER, M.E. Atomic Safety and Licensing Board Panel 80/10/31 103pp 06911-019

8011060465 Withdraws 801027 request for hearing re 801006 FR notice
PORTER, W.L Duke Power Co 80/11/03. 1p. 06912.263.

8011070020 Notice of reconstitution of ASLAB in license amend proceeding, consisting of AB Rosenthal, Chairman & JH Buck & RS Balzman, members,
TOKPKINS, B A Atomic Safety and Licensing Appeal Panel. 80/11/03 1p 06924.284

8011140504 Exceptions to ASLB 801031 initial decision which denied trans-shipment of spent nuclear fuel from Oconee to McGuire for storage purposes Cites 68 ASLB errors Certificate of Svc encl
MCQARRY, J.M., PORTER, W.L Duke Power Co MCQARRY, J.M. Debevoise & Liberman 80/11/10 16pp 06963 089.

8011200241 Suggests obtaining B Spitalny assistance in preparing appeal brief of initial decision re McGuire/Oconee spent fuel transportation.
CHRISTENBURY, E Hearings Division 80/11/18. 1p 07018:110

J Insurance & indemnity information

8011210559 Forwards Endorsement 59 to NELIA Policy NF-182 & Endorsement 44 to MAELU Policy MF-61,
SANDERS, F.D. Duke Power Co 80/11/17. 3pp. 07034 077.

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of THI action plan requirements. Provides summary listing of all approved THI-2 related requirements
EISENHUT, D.O Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D.O. Division of Licensing 80/10/01 5pp.

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/a encl.
EISENHUT, D.O. Division of Licensing. 80/10/06 6pp.

DOCKETED ITEMS

85

BO11050208 Requests submittal of updated Tech Specs for facilities fire protection program by 810115 Surveillance requirements for new equipment should be implemented by administrative control as soon as possible Forwards model Tech Specs
REID,R.W Operating Reactors Branch 4 80/10/07 2pp 02319 196

--BO11050212 Model Tech Specs for fire protection program,
* Operating Reactors Branch 4 80/01/15 17pp 02319 196

BO11030057 Forwards request for addl info to complete review of util BO0520 reload design methodology technical rept Outstanding areas include reactivity coefficients & deficits, shutdown margin calculation & kinetics parameters
REID,R.W Operating Reactors Branch 4 80/10/16 5pp 06855 117

BO11060096 Requests addl info to complete review of structural & seismic portions of common spent fuel pool submittal on BO0701,Requests info by 801030
REID,R.W Operating Reactors Branch 4 80/10/24 3pp 06916 152.

BO11110139 Forwards order for mod of Licenses DPR-38,DPR-47 & DPR-55 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID,R.W Operating Reactors Branch 4 80/10/24 2pp

--BO11110155 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0589 required by B20630,Complete records must be available by 801201
EISENHUT,D O. Division of Licensing 80/10/24 6pp

--BO11110171 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp

BO11040609 Forwards request for addl info in order to complete review of standby shutdown facility Response due in 30 days
REID,R.W Operating Reactors Branch 4 80/10/27 3pp 06875 163

BO11040146 Forwards proposed Tech Specs revision for radiological effluent control per BO0602 request
PARKER,W O. Duke Power Co 80/10/30 2pp 06876 016

--BO11040149 Proposed Tech Specs revision for radiological effluent control,
* Duke Power Co. 80/10/30, 133pp 06876.018

BO11060499 Informs that util position re instrumentation sys to detect inadequate core cooling is consistent w/info contained in JH Taylor 801007 ltr to D Rest
PARKER,W.O. Duke Power Co 80/10/30 1p. 06915-299

BO11060502 Forwards proposed revision to Tech Spec 3.1.12,adding explicit requirements for determining reportability of inoperable monitors,Proposal supls BO1002 proposed Tech Spec revisions to reflect NUREG-0578,Category A items,
PARKER,W O. Duke Power Co. 80/10/30 1p. 06915 296

--BO11060504 Proposed revision to Tech Spec 3.1.12,adding explicit requirements for determining reportability of inoperable monitors,
* Duke Power Co. 80/10/30, 1p 06915.297.

BO11040481 Forwards list re equipment which will undergo environ qualification tests,to be conducted within next two yrs,in response to NRC 801001 request.
PARKER,W O. Duke Power Co 80/10/31 3pp 06874 126

BO11070439 Forwards proposed revision to Tech Specs to incorporate NUREG-0578 Category A items,including shift technical advisor in response to NRC BO0731 ltr requesting response to shift staffing criteria,Operator staffing table encl,
PARKER,W O. Duke Power Co. 80/11/03 3pp 06919,194

--BO11070446 Proposed Tech Specs,incorporating NUREG-0578 Category A items re min staffing requirements & shift technical advisor,
* Duke Power Co. 80/11/03 5pp. 06919:197.

BO11120334 Maintains position that license fees not required w/proposed Tech Spec changes provided in 801014 & 0624 ltrs,since neither changed operation of facility
PARKER,W.O. Duke Power Co. 80/11/04 1p 06932:033.

BO11190671 Confirms commitments to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability " Commitments acceptable & should remain in effect pending completion of review
REID,R W Operating Reactors Branch 4 80/11/05 2pp 07001 250

BO11130199 Application to amend OL changing Tech Spec 4.5.1,ECCS,by revising surveillance requirements for valves LP-17 & 18.
PARKER,W O Duke Power Co 80/11/07 2pp 06958 273

--BO11130203 Proposed revision to Tech Spec 4.5.1,ECCS,pages 4.5-2 & 4.5-3, to revise surveillance requirements for valves LP-17 & 18
* Duke Power Co 80/11/07 3pp 06958 275

BO11140398 Updates BO0818 response to request for addl info re preliminary design approval of safety-grade anticipatory reactor sys Pressure switches are located in turbine bldg in areas w/environmentally safe conditions
PARKER,W O. Duke Power Co 80/11/07 1p 06962:346

BO11180392 Forwards corrected Page 3.11-1 to BO1030 submittal of proposed radiological effluent Tech Specs
PARKER,W O Duke Power Co 80/11/12 1p 06992 160

--BO11180396 Corrected Page 3.11-1 to proposed radiological effluent Tech Specs submitted BO1030
* Duke Power Co 80/11/12 1p 06992 161

BO11200178 Forwards addl info re facility reload design methodology technical rept,in response to NRC 801016 ltr request
PARKER,W O. Duke Power Co 80/11/13 25pp 07018 111

BO11180548 Responds to TMI Action Plan Item II K.3.30,Existing small break LOCA model fully meets requirements of 10CFR50 App K Currently reviewing several aspects of model for possible improvement &/or addl justification
PARKER,W O Duke Power Co 80/11/14 2pp 06992.132

BO11230291 Responds to NRC 801112 request for addl info re environ qualifications of pressure switches Util provided info re NRC concerns on 801107
PARKER,W O Duke Power Co 80/11/20 1p 07056.081

Q Inspection reports, IE Bulletins & correspondence

BO11130068 Forwards response to IE Circular 80-21, "Regulation of Refueling Crews " Senior reactor operator can supervise activities more effectively from refueling operations ctr in control room than from reactor bldg refueling deck
PARKER,W O Duke Power Co 80/10/20 2pp 06956 348

BO11110139 Forwards order for mod of Licenses DPR-38,DPR-47 & DPR-55 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID,R W Operating Reactors Branch 4 80/10/24 2pp.

--BO11110155 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0589 required by B20630,Complete records must be available by 801201.
EISENHUT,D O Division of Licensing 80/10/24, 6pp

--BO11110171 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp

BO11060117 Ack receipt of 801003 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-269/80-28, 80-270/80-24 & 80-287/80-21
LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/10/28 1p 06912 177

--BO11060128 Responds to NRC 800911 ltr re violations noted in IE Insp Repts 80-269/80-28,80-270/80-24 & 80-287/80-21 Corrective actions stud matl verified to be correct matl & matl control instructions reviewed w/all appropriate personnel
PARKER,W O. Duke Power Co. 80/10/03 3pp. 06912.178.

--BO11060136 Forwards IE Insp Repts 80-269/80-28,80-270/80-24 & 80-287/80-21 on BO0701-31 & notice of violation.
LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/11 2pp 06912 181.

DOCKETED ITEMS.

--8011060149 IE Insp Repts 50-269/80-28, 50-270/80-24 & 50-287/80-21 on 800701-31 Noncompliance noted failure to maintain traceability & accountability of QA matl used on safety-related sys
ORDERS, W. MYERS, D Region 2, Atlanta, Office of the Director
MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/04 17pp 06912 184

801100429 Requests extension of IE Bulletin 80-11 re masonry wall design schedule to accommodate new submittal dates Response to bulletin will be submitted 801108 & Dec 1981
PARKER, W D Duke Power Co 80/10/28 1p 06929 295

8011210440 Forwards 801101 Revision 5 to util 90-day response to IE Bulletin 79-01B, replacing Revision 4 in entirety w/o encl.
THIBS, A C Duke Power Co 80/10/31 2pp 07027 168

8011260330 Forwards addl response to IE Bulletin 80-11, "Masonry Wall Design." Re-evaluation of design adequacy of walls identified in 800707 response is underway
PARKER, W D Duke Power Co 80/11/04 16pp 07075 105

R Periodic operating reports & related correspondence

8011250188 Forwards description of facility changes in form of station mode, completed between Oct-Dec 1979 Mods listed by month.
PARKER, W D Duke Power Co 80/10/27 13pp. 07068 293.

801180582 Forwards monthly operating repts for Oct 1980
PARKER, W D Duke Power Co 80/11/13 1p 06988 041

801180592 Monthly operating repts for Oct 1980
REAVIS, J A Duke Power Co 80/11/13 16pp 06988 042

Reportable occurrences, LERs & related correspondence

1050043 Ack receipt of 800721 interim deficiency rept re Anchor drilling valve yokes
ARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/09/24, 1p 06896 293

1180711 Forwards LER 80-014/01T-0
ARKER, W D Duke Power Co 80/11/13 4pp 06915 001

011180722 LER 80-014/01T-0, on 801030, during review of 800902-12 QA audit, discovered that monthly fire protection equipment insp was not conducted during Apr 1980 Further review revealed addl deficiencies in fire hose station insps.
JONES, J L Duke Power Co. 80/11/13 3pp. 06915 001

1240288 Forwards LER 80-013/03L-1
ARKER, W D Duke Power Co 80/11/18 3pp 07042 356

011240289 LER 80-013/03L-1 on 800818, one hydraulic snubber was found w/o oil, reservoir was cracked & oil rings worn Cause of empty reservoir unknown Snubber removed from svc, tested, repaired & reinstalled & oil rings replaced
JONES, J L Duke Power Co. 80/11/18 1p 07042 359.

Operator Examinations

11070439 Forwards proposed revision to Tech Specs to incorporate NUREG-0578 Category A items, including shift technical advisor in response to NRC 800731 ltr requesting response to shift staffing criteria Operator staffing table encl
PARKER, W D Duke Power Co 80/11/03 3pp

DOCKET 50-288 REED COLLEGE RESEARCH REACTOR

1 Inspection reports, IE Bulletins & correspondence

011100065 Forwards IE Insp Rept 50-288/80-03 on 800908-10. No noncompliance noted
CREWS, J L Region 3, San Francisco, Reactor Operations Nuclear Support Branch. 80/09/29 2pp 06929 335

--801100069 IE Insp Rept 50-288/80-03 on 800908-10. No noncompliance noted. Major areas inspected operations procedures, maint, surveillance, operator requalification program & review & audit.
CARLSON, J D WILLETT, D J Region 3, San Francisco, Office of the Director STERNBERG, D M Region 3, San Francisco, Reactor Operations Nuclear Support Branch 80/09/25. 4pp. 06929 337.

DOCKET 50-287 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8011060431 Forwards comments in response to NRC 800909 ltr re Revision 2 to TMI-1 emergency plan Responses to remaining four questions will be forwarded in near future
HUKILL, H D Metropolitan Edison Co 80/11/03 41pp 02319 196

801170017 Forwards facility emergency planning info for placement in LPDR w/o encl
SOUDEK, J L Division of Rules and Records 80/11/04 1p 06978 267

801120065 Advises that NRC has completed review of 800610 emergency plan Plan may be implemented Requests that NRC be informed of implementation date
REID, R W Operating Reactors Branch 4 80/11/05. 4pp 07018 148

--801120067 Forwards NRC ltr to Met Ed advising that revised emergency plan for TMI-1 is in compliance w/App E to 10CFR50 Advises that revised plan will be implemented at facility
TOURTELLOTTE, J Hearing Branch 4 80/11/05 1p 07018 152

801190279 Forwards util response to NRC 800909 ltr re 23 comments on Revision 2 to emergency plan Svc list encl
ZAHNER, R E, Shaw, Pittman, Potts & Trowbridge 80/11/10 3pp 06916 001

--801190285 Agreement re availability of medical treatment during emergencies Attachment 1
HERBEIN, J O Metropolitan Edison Co FULGINITI, B A Milton B Hershey Medical Center Hershey, PA. 80/08/12 6pp 06916:001.

--801190292 Advises of availability of assistance in event of emergency situation Attachment 3 Attachments 4-11 re excerpts of emergency procedures encl
GODDARD, C E Commerce, Dept. of 80/09/08 41pp 06916 001

801190320 Advises that emergency plan is in compliance w/Dec 1970 10CFR50, App E, not current emergency planning rule effective 801103 Corrects intent of JR Tourtellotte 801105 ltr to ASLB
TOURTELLOTTE, J Hearing Branch 4 80/11/17 1p 06999 296

0 Adjudicatory correspondence

801190208 Petition to intervene alleging adverse psychological & economic consequences Questions Met Ed financial capability to comply w/technical & design changes. Certificate of Svc encl
MCQUAUGHIN, K. Three Mile Island Alert 79/09/12 8pp 06998 278

8011050138 Reply in opposition to licensee 800918 response objecting to Contention III A (L) re emergency plan New concerns re governmental responsibility for mandatory emergency requirements critical to restart w/Certificate of Svc.
PELL, D M Anti-Nuclear Group Representing York. PELL, D M Pell, D M 80/10/13 4pp 06897 302

8011050019 Forwards order for mod of license re environ qualification of safety-related electrical equipment Qualification info should be submitted by 801101
REID, R W Operating Reactors Branch 4 80/10/24 4pp 06894 303

--8011030021 Order amending License DPR-80 to add provisions to App A of Tech Specs Safety-related electrical equipment shall be qualified in accordance w/NUREG-0588 by 820630 Complete & auditable records must be available & maintained by 801201.
EISENHUT, D G Division of Licensing 80/10/24 8pp 06894 307

8011030352 Forwards Exhibits JC-504, JC-505, JC-506, JC-507 & JC-700, in response to JC Petersen data requests re significant regulatory developments affecting General Public Utilis
SWEENEY, L E Metropolitan Edison Co 80/10/27 5pp. 06867 287

801120606 Forwards GPU quarterly financial statement & info used in PA Electric Co current retail rate case, in support of restart hearing Updated set of index sheets listing exhibits & responses to interrogatories encl.
SPRINGER, E R. General Public Utilities - GPU Service Corp # Affiliation Unknown. 80/10/30 83pp 06916 001

8011050444 Forwards documents re safety implications of control sys & plant dynamics, supplied to NRC since DL Basdekas 801010 rept on sub j. w/o encl
CUTCHIN, J M Hearing Branch 3. 80/11/03. 3pp 06898 214

DOCKETED ITEMS

87

- 8011060401 Response to State of PA first set of interrogatories
Addresses guidance used in developing emergency response
Plans & implementation of agency responsibilities J Himes
Affidavit & Certificate of Svc encl
GRAY, J R. Hearing Branch 1 80/11/03 20pp 06911 122
- 801110388 Forwards "Mgt & Operations Study," performed for PA Public
Util Commission re restart hearing
CARROLL, B General Public Utilities - GPU Service Corp 80/11/03
1p. 06950 123
- 8011110393 "Mgt & Operations Study," performed for PA Public Util
Commission
* TBSA Group Co ,Theodore Barry & Associates. 80/09/30 200pp
06950 124
- 8011210343 Forwards info re significant regulatory developments
affecting General Public Utilis companies in restart
proceeding, in response to 790921 & 1109 requests
SNEENEY, L E Jersey Central Power & Light Co 80/11/05 1p
01741 019
- 8011210355 "General Public Utilis Transmission & Distribution Sys'
Planning Practices & Principles "
NEWTON, E General Public Utilities 80/10/24 25pp 01741 019
- 8011210378 Transcript of 801030 hearing before NJ Board of Public Utilis
in Newark, NJ re util petition for rate increase
Pp 3, 121-3, 212
* New Jersey, State of 80/10/30 92pp 01741.019
- 801140075 Status rept on Newberry Township TMI Steering Committee
emergency planning contentions, per ASLB 801031 directive
Contentions 3(b)(13), 3(b)(16) & 3(c)(7) withdrawn, NRC
notified re parties' views Certificate of Svc encl
ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman,
Potts & Trowbridge 80/11/06 7pp 06963 169
- 801140113 Forwards NUREG-0654 "Criteria for Preparation & Evaluation
of Radiological Emergency Response Plans & Preparedness in
Support of Nuclear Power Plants," FEMA-REP-1, Revision 1,
Provided in response to ASLB 801030 request re restart case
GRAY, J R Hearing Branch 1 80/11/10 1p 06963 198
- 801170231 Interrogatories directed to intervenor SC Sholly re restart
proceeding, Addresses Contentions 8(111)(B)-(D) re phased,
preplanned readiness & evacuation procedures Certificate of
Svc encl
ZAHLER, R E Metropolitan Edison Co. ZAHLER, R E Shaw, Pittman,
Potts & Trowbridge 80/11/10. 9pp 06982 002.
- 801190279 Forwards util response to NRC 800909 ltr re 23 comments on
Revision 2 to emergency plan Svc list encl.
ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 80/11/10 3pp
06916:001
- 801190285 Agreement re availability of medical treatment during
emergencies Attachment 1
HERBEIN, J. Q. Metropolitan Edison Co FULGINITI, S A. Milton B.
Hershey Medical Center Hershey, PA 80/08/12. 6pp 06916:001
- 801190292 Advises of availability of assistance in event of emergency
situation Attachment 3 Attachments 4-11 re excerpts of
emergency procedures encl.
GOODAL, C E Commerce, Dept of 80/09/08 41pp. 06916:001
- 801170096 Memorandum & order summarizing rulings taken during 801030-
31 oral argument re emergency planning issues Rules on
contentions of intervenors Aamodt, Antinuclear Group
Representing York, Sholly, TMI Steering Committee & others
SMITH, I W. Atomic Safety and Licensing Board Panel 80/11/12
20pp. 06978:100
- 801190196 Response in opposition to receipt of J Beyea 801003 prefiled
direct testimony re Antinuclear Group Representing York
Contention V(D) Testimony inconsistent w/admissibility
rulings re litigation of Class 9 risks, W/Certificate of Svc
BAXTER, T. A. Metropolitan Edison Co. BAXTER, T. A Shaw, Pittman,
Potts & Trowbridge 80/11/13 16pp 06998:261
- 801190268 Response to UCS 800925 interrogatories re NUREG-0578 Draft
Reg Guide 1.141, Revision 1, modified draft Reg Guide 1.97
Revision 1, Hemminger, Thatcher, Fitzpatrick, Phillips & Fields
affidavits & prof qualifications & Certificate of Svc encl
TOURTELLOTTE, J Hearing Branch 4 80/11/14 141pp. 06916:001.
- 801190020 Advises that emergency plan is in compliance w/Dac 1970
10CFR350, App E, not current emergency planning rule effective
801103 Corrects intent of JR Tourtellotte 801105 ltr to
ASLB.
TOURTELLOTTE, J. Hearing Branch 4. 80/11/17. 1p. 06999:296
- 8011280006 Memorandum advising of 801203 meeting where NRC will present
review of safety evaluation supplis on mgt issues Courtesy
notification & Certificate of Svc encl
SMITH, I W Atomic Safety and Licensing Board Panel 80/11/19 3pp.
07084 002
- 8011280232 Forwards addl financial info in response to Items 16 & 17
of NRC 800911 ltr re TMI-1 restart proceeding
HUXILL, H D Metropolitan Edison Co 80/11/20 36pp 07055 185
- H General correspondence

- 8011060098 Responds to 800821 ltr re restart of TMI-1 & action to bring
financial relief to General Public Utilis Suggests recipient
contact state public util commission & FERC
DENTON, H R Office of Nuclear Reactor Regulation, Director
80/09/22 1p 06912 212
- 8011060104 Discusses restart of TMI-1 & requests including TMI-1 in
util rate base to lessen financial burden on General Public
Utilis
LINZEY, H T , LINZEY, B Affiliation Unknown 80/09/21 3pp
06912 213.
- 8011060200 Responds to 800824 ltr re restart of TMI-1, Unit 2 cleanup
schedule & licensing of new nuclear facilities Public
hearing on restart will be conducted Summary of NUREG-0683
not encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
80/09/22. 1p. 02319 196
- 8011060206 Requests info re restart of TMI-1, Unit 2 cleanup schedule &
licensing of new nuclear facilities
RUTHRAUFF, F R , RUTHRAUFF, M B Affiliation Unknown 80/08/24
1p 02319 196
- 801190659 Responds to 800914 ltr re release of radioactive matl from
station & shutdown. Forwards copy of programmatic EIS,
NUREG-0462, Vol 1 & 2 & 800612 order for temporary mod of
license H/o encl
SNYDER, B J TMI Program Office 80/10/16 3pp 07001 230
- 801190664 Registers objections to party responsible for ordering
radioactive gases or water released into atmosphere &
Susquehanna River from plant All facts re accident have not
been revealed to public Demands objections be honored
PARSONS, C H Affiliation Unknown 80/09/14 2pp 07001 233
- 801100508 Responds to 800926 ltr to President Carter expressing
concern re delay in TMI-1 restart Public hearing held before
ASLB commenced on 801015 Commission will take Board
recommendation into account for restart decision
REID, R W Operating Reactors Branch 4 80/10/27 3pp 06931 216
- 801180112 Responds to 801010 ltr to President Carter re financial
burden on util resulting from Mar 1979 facility accident
Statutory authority does not permit direct federal financial
aid to assist in cleanup & recovery cost.
DENTON, H R Office of Nuclear Reactor Regulation, Director
80/10/30 3pp. 06992 139
- 801180117 Forwards 801010 ltr to President Carter requesting support
of federal grants to relieve financial burden on util &
customers by supporting NRC action for immediate facility
restart
SEAL, M M. President of US & Executive Offices 80/10/17 2pp
06992 142
- 801180087 Responds to 800908 ltr to JF Ahearns & President Carter re
comparison of Feb 1980 events at Crystal River facility &
Mar 1979 events at TMI-2, method of processing water at
TMI-2, delay in restart & financial impact to consumers
DENTON, H R. Office of Nuclear Reactor Regulation, Director
80/11/03 2pp. 06992 289.
- 801180092 Expresses concern re Commission delays in startup of
TMI-2 Questions methods used in facility cleanup &
compares procedure w/Crystal River accident Cost to
shareholders of util could be high.
KING, T A Affiliation Unknown 80/09/08 3pp 06992:294
- 801180064 Requests meeting w/NRC to discuss negative impact resulting
from TMI-2 accident
BDOOTH, J E Affiliation Unknown 80/11/05 1p. 06987 344.
- 801190187 Responds to 800218 request for revocation of util GL NRC
public hearing ordered re restart of Unit 1 Licensee
currently conducting feasibility studies re plant recovery
proposals for Unit 2
SNYDER, B J TMI Program Office 80/11/05 3pp. 06916:001.

DOCKETED ITEMS

--801190162 Requests revocation of util GL following nuclear plant accident
HARRIS, D Affiliation Unknown 80/02/18 2pp. 06916 001

801180056 Requests meeting w/NRC representatives re awaited restart of facility
MARTIN, L Z Affiliation Unknown 80/11/08 1p 06987 342

801180060 Requests meeting w/Commissioners to discuss TMI situation & solution for problems experienced by certain ratepayers
MELLINGER, C W Affiliation Unknown 80/11/11 1p 06987 343

801200305 Expresses support for restart of TMI-1 Restart will reduce util costs of purchasing replacement power & will enhance util ability to safely recover TMI-2
MOYER, R A Affiliation Unknown 80/11/11 2pp. 07021 280

801200265 Expresses support for return of TMI-1 to operational use
WORSHAM, C San Diego Voice of Energy 80/11/12 1p 07021, 316

801200246 Supports TMI-1 startup & urges NRC authorization in granting approval of operations.
DARLINO, R C International Brotherhood of Electrical Workers 80/11/13 1p 07021 317

801200225 Urges opening of facility as soon as possible
BACHOFER, M L Affiliation Unknown 80/11/14 1p 01741 019

801240287 Urges acceleration of TMI-1 restart Protests financial burden on ratepayers & alleges that unit is not more dangerous than any other reactor
SHAIN, W G Affiliation Unknown 80/11/15 1p 02227 001

801210463 Urges acceleration of TMI-1 restart Cites denial of permission as punitive action against util & ratepayers
BERNATH, L Affiliation Unknown 80/11/17 1p 07031 213

801240267 Requests TMI-1 restart. Met-Ed customers paying higher costs for replacement of power
CARPENTER, G R Affiliation Unknown 80/11/17 1p 02227.001

801240316 Opposes shutdown of TMI-1 because United States needs power that facility can provide Requests help in getting expedited restart of Unit 1.
SCHERER, C L Affiliation Unknown 80/11/18 1p 07049 362

801260139 Requests restart of Unit 1 w/o further delay Plant mods meet current NRC requirements Economic burden warrants NRC action
KIDD, O E American Society of Mechanical Engineers 80/11/18 1p 07080 094

801260177 Supports restart of facility w/new mods Expresses reservations on Met Ed being licensee, & would rather see PA Power & Light Co as licensee
EDWARDS, J J Affiliation Unknown 80/11/18 1p 07071 338

801250424 Forwards updated svc distribution list for facilities, as addressed in util 800930 1tr List supersedes all previous submittals
ARNOLD, R C Metropolitan Edison Co 80/11/19 2pp 07056:099

801260127 Recommends restart of facility & full power operation of all nuclear units
HARWOOD, F C Affiliation Unknown 80/11/19 1p 01741 019.

801280007 Urges restart of facility
LANDRY, E J Affiliation Unknown 80/11/21 1p 07084 005

I Financial information

801200901 Forwards responses to Questions 1, 2, 8, 9, 10, 11 & 12 of NRC 800911 request for financial info Responses to Questions 3, 4, 5, 6, 7, 16 & 17 will be provided by 801031
HUKILL, H D Metropolitan Edison Co 80/10/27 15pp 06872, 345

80120606 Forwards GPU quarterly financial statement & info used in PA Electric Co current retail rate case, in support of restart hearing Updated set of index sheets listing exhibits & responses to interrogatories encl
SPRINGNER, E R General Public Utilities - GPU Service Corp Affiliation Unknown 80/10/30, 83pp 06916 001

801250232 Forwards addl financial info in response to Items 16 & 17 of NRC 800911 1tr re TMI-1 restart proceeding
HUKILL, H D Metropolitan Edison Co 80/11/20 36pp 07055:185

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OL & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OL & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

801250416 Forwards two sets of addl microfilm reels re TMI data collected by General Public Utilis w/o encl
REED, E C Metropolitan Edison Co 80/10/20 1p 07056 078

801110770 Notifies that util 800729 application for Tech Spec Change Request 94 has received Class III fee determination & warrants addl remittance
MILLER, H O License Fee Management Branch 80/10/28 1p 06947 360

801030387 Responds to NRC 801001 ltr re BWR scram sys Reassessment of sys indicates that util complies w/applicable General Design Criteria (App A to 10CFR50). Results of sys re-evaluation, mods & implementation schedule will be submitted by 801215
FINFROCK, I R Jersey Central Power & Light Co 80/10/30 1p 06855 086

801190214 Forwards Amend 59 to License DPR-50, safety evaluation & notice of issuance & availability
REID, R W Operating Reactors Branch 4, 80/10/31 4pp. 06998 286

--801190234 Amend 59 to License DPR-50, eliminating temporary requirements to perform periodic special insp of containment ring girder & allowing future insp to be performed w/normal surveillance
REID, R W Operating Reactors Branch 4 80/10/31 11pp 06998 290

--801190239 Safety evaluation supporting Amend 59 to License DPR-50 * Office of Nuclear Reactor Regulation, Director 80/10/31 5pp 06998 301

--801190243 Notice of issuance & availability of Amend 59 to License DPR-50
REID, R W Operating Reactors Branch 4 80/10/31 2pp. 06998:306

801200346 "Adequacy of Station Electrical Distribution Sys Voltages," technical evaluation rpt, Revision 1
ROBERTS, E W EQ&O Idaho, Inc 801200346 80/10/31, 13pp. 07018 188

801110380 Forwards "Mgt & Operations Study," performed for PA Public Util Commission re restart hearing
CARROLL, D General Public Utilities - GPU Service Corp 80/11/05 1p 06950 123

--801110393 "Mgt & Operations Study," performed for PA Public Util Commission * TB&A Group Co, Theodore Barry & Associates 80/09/30 200pp 06950 124

801200016 Confirms util 800509 commitments to interim position on containment purging & venting, pending resolution of isolation valve operability Commitment should remain in effect pending NRC long-term review
REID, R W Operating Reactors Branch 4 80/11/05 4pp 07018 213.

801170505 Forwards Tech Specs Change Request 60A requesting amend 12 App A of OL
HUKILL, H D Metropolitan Edison Co 80/11/07 1p 06950 335

--801120513 Tech Specs Change Request 60A supporting request for amend to App A to OL, Certificate of Svc encl
HUKILL, H D Metropolitan Edison Co 80/11/07 3pp 06950 336

--801120518 Revised Tech Specs 3.5.3, 4.5.1 & 4.6.
* Metropolitan Edison Co 80/11/07 7pp 06950 339

8011130395 Responds to NRC 800916 ltr re audit of util control room during wk of 800721 Disagrees w/categories used to cite deficiencies List of corrective actions to be resolved before & after restart encl
HUKILL, H D Metropolitan Edison Co 80/11/07 95pp 04999 265

8011240151 Tech Spec Change Request 60A re License DPR-50 Certificate of Svc encl
HUKILL, H D Metropolitan Edison Co 80/11/07 3pp 07049 165

--8011240158 Tech Spec Change Request 60A, revising Sections 3 5, 4 1, 4 5 & 4 6 re instruments operation conditions, engineered safeguards protection sys actuation setpoints, emergency power sys periodic testing & channel description
Metropolitan Edison Co 80/11/07 8pp 07049 168

8011200333 Requests deletion of Page 4-57 containing Spec 4 14 from Tech Specs as Spec is redundant to Spec 4 12 2 on Page 4 356 re reactor bldg purge air treatment sys
HUKILL, H D Metropolitan Edison Co 80/11/17 1p 07019 027

8011200336 Requests extension until 801205 to provide info re environ qualification tests on facility equipment over next two yrs in response to NRC 801001 ltr
HUKILL, H D Metropolitan Edison Co 80/11/17 1p 07019 023

8011250498 Notifies that position on instrumentation for detection of inadequate core cooling is consistent w/util 801002 & B&W 801007 ltrs Response to TMI action plan Item II F 2 will be provided on 801010
HUKILL, H D Metropolitan Edison Co 80/11/20 1p 07048 254

8011260194 Forwards amend fee for Tech Spec Change Request 94 re revised steam generator tube insp program submitted to NRC on 800729
HUKILL, H D Metropolitan Edison Co 80/11/20 2pp 07080 112

G Inspection reports, IE Bulletins & correspondence

8011130043 Forwards IE Insp Rept 50-289/80-16 on 800623-27, 30, 0701-03 & 07-09 No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/03 2pp 06958 159

--8011130050 IE Insp Rept 50-289/80-16 on 800623-27, 30, 0701-03 & 07-09 No noncompliance noted Major areas inspected QA program & implementation in areas of design changes/mods, drawing document control & records
NAPUDA, O, SIMONETTI, O Region 1, Philadelphia, Office of the Director GREENMAN, E O Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/29 10pp 06958 161

8011130130 Forwards IE Insp Repts 50-289/80-08 & 50-320/80-05 on 800317-0430. No noncompliance noted
GRIER, B H Region 1, Philadelphia, Office of the Director, 80/09/13 2pp 06958 229

--8011130136 IE Insp Repts 50-289/80-08 & 50-320/80-05 on 800317-0430 No noncompliance noted Major areas inspected selected new & revised procedures submitted for NRC approval, health physics & environ areas & response to IE Bulletin 79-19
HAVERKAMP, D, CONTE, R, SHANBAKY, M, Region 1, Philadelphia, Office of the Director 80/08/01 10pp 06958 231

8011100269 Forwards IE Insp Rept 50-289/80-23 on 800823-29. No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/17 2pp 06929 091

--8011100276 IE Insp Rept 50-289/80-23 on 800823-29. No noncompliance noted. Major areas inspected review of documents & visual insp of masonry walls
CHAUDHARY, S K Region 1, Philadelphia, Office of the Director, EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch, 80/09/16 3pp, 06929 093

8011100282 Forwards IE Insp Rept 50-289/80-20 on 800711-0813 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch, 80/09/17 2pp 06929 094

--8011100292 IE Insp Rept 50-289/80-20 on 800711-0813 No noncompliance noted Major areas inspected work activities re restart program & unresolved items re verification of components per IE Bulletin 79-01B & compliance w/Bulletin 80-11
GADE, L., BASSANI, A Region 1, Philadelphia, Office of the Director EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch, 80/09/16 11pp 06929 098

8011100291 Forwards IE Insp Rept 50-289/80-07 on 800321 & 0731 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/17 2pp 06929 109

--8011100298 IE Insp Rept 50-289/80-07 on 800321 & 0731 No noncompliance noted Major areas inspected allegation re possible mismarking of ASTM welded stainless steel pipe
DURR, J P, REYNOLDS, S D Region 1, Philadelphia, Office of the Director YRIPP, L E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/15 9pp 06929 111

8011100321 Forwards IE Insp Rept 50-289/80-19 on 800723-25 No noncompliance noted
GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/29 2pp 06941 126

--8011100531 IE Insp Rept 50-289/80-19 on 800723-25 No noncompliance noted Major areas inspected shift technical advisors, staffing for startup testing program, onsite technical support ctr & onsite operational support ctr
KPMIO, R R, NORRHOLM, L J Region 1, Philadelphia, Office of the Director STERNBERG, D Region 5, San Francisco, Office of the Director, 80/09/25 14pp 06941 128

8011070055 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/30 1p 06924 321

8011210393 Forwards IE Investigation Rept 50-289/80-23 on 800701-0818 No noncompliance noted
GRIER, B H Region 1, Philadelphia, Office of the Director, 80/10/02 1p 07033, 199

--8011210402 IE Investigation Rept 50-289/80-23 on 800701-0818 No noncompliance noted Major areas investigated concerns identified in TMI Alert sworn depositions
CHRISTOPHER, R, SMITH, R H Region 1, Philadelphia, Office of the Director KEIMIO, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/01 105pp 07033 201

8010180484 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Review of safety-related sys showed that piping meets bulletin criteria
HUKILL, H D Metropolitan Edison Co 80/10/08 1p

8011030680 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Review of safety-related sys showed that piping meets bulletin criteria
HUKILL, H D Metropolitan Edison Co 80/10/08 1p 06860 159

801140289 Forwards final rept re IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Rept by Gilbert Associates, Inc encl Tables in App III A & B will be updated in next revision
HUKILL, H D Metropolitan Edison Co, 80/10/13 102pp 06960 003

8011060801 Forwards IE Mgt Insp Rept 50-289/80-21 on 800707-11, 14-18, 27-31 & 0801 No noncompliance noted, though portion of training area dealing w/nonlicensed personnel evaluated as poor Encl withheld (ref 10CFR2 790)
STELLG, V Office of Inspection & Enforcement, Office of the Director, 80/10/16, 8pp 06909 138

8011170791 Provides results of calculations performed in response to NRC 800724 ltr re IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " HPI pumps will provide flow
HUKILL, H D Metropolitan Edison Co 80/10/16 2pp, 06973 347

8011200518 Forwards IE Mgt Meeting Rept 50-289/80-18 on 800701 GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/22 2pp 07018 206

--8011200542 IE Mgt Meeting Rept 50-289/80-18 on 800701 Areas covered licensee mgt reviews/appraisals which will augment routine NRC insp program
HAVERKAMP, D R, FASANO, A N Region 1, Philadelphia, Office of the Director 80/10/17 3pp 07018 208

8011070249 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06924 235

DOCKETED ITEMS

8011140279 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06968 243

8011140585 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06963 145

8011170769 Forwards updated rept in response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " Master list of components, sys component evaluation work sheets, accident profiles & supporting radiation & thermal aging info encl
HUKILL, H D Metropolitan Edison Co. 80/10/31 300pp 06911 001

8011260077 Submits revised response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Currently installed control room switches prevent valves from leaving emergency mode upon reset of containment isolation signal
HUKILL, H D Metropolitan Edison Co 80/11/07 2pp 07071 311

8011260194 Forwards amend fee for Tech Spec Change Request 94 re revised steam generator tube insp program submitted to NRC on 800729
HUKILL, H D, Metropolitan Edison Co 80/11/20 2pp 07080.112

R Periodic operating reports & related correspondence

8011060080 Partial response to FOIA request for info re radiation levels of plant environs & dump sites & radiation levels in nine listed places Forwards documents listed in App A Search is continuing for documents re second part of request
FELTON, J H Division of Rules and Records 80/10/29 2pp.

--8011060137 Provides preliminary data rept for air & water samples collected on 800401-0407
SMITH, A E Environmental Protection Agency 80/04/09 2pp

--8011060146 Provides preliminary data rept for air & water samples collected on 800414-0423
CORKERN, W D, Environmental Protection Agency 80/04/25 2pp

8011070507 Submits corrections in response to NRC 801006 ltr re radioactive matts released from nuclear power plants in 1978. Errata to TH1 data encl
HUKILL, H D Metropolitan Edison Co 80/11/04 6pp 06910 001

111190270 Forwards monthly operating rept for Oct 1980
HUKILL, H D Metropolitan Edison Co 80/11/15 1p 06999 349

--8011190273 Monthly operating rept for Oct 1980.
MITCHELL, D O Metropolitan Edison Co. 80/11/15 5pp 06999 350

S Reportable occurrences, LERs & related correspondence

801120426 RO 80-18 confirms 801017 telcon re voltage discrepancy between station & replacement coils being installed in response to IE Bulletin 79-01A Corrective action to be described in followup rept
TOOLE, R J Metropolitan Edison Co 80/10/20. 1p 06953 360

8011070422 Forwards LER 80-01B/01T-0
HUKILL, H D Metropolitan Edison Co 80/11/04 1p. 06925 011

--8011070424 LER 80-01B/01T-0 on 801017, while replacing coils for ASCO solenoid valves per IE Bulletin 79-01A, coils were discovered to conflict w/station voltage range caused by incorrect purchase order for coils.
MITCHELL, D O Metropolitan Edison Co 80/11/04. 6pp 06925 012

8011250511 RO 80-013/03L-0 committed to forwarding final valve testing evaluation by 801101 Investigation requires more time than anticipated. Requests extension until 801219.
HUKILL, H D Metropolitan Edison Co. 80/11/17 1p 07068 274.

T Hearing transcripts on non-antitrust matters

8011030628 Forwards transcript of 801021 restart proceeding before NJ DOE Board of Public Utils, in response to request for info re significant regulatory developments.
SHEENEY, L. E. Jersey Central Power & Light Co 80/10/27 1p 01736.001

--8011030635 Transcript of 801021 restart hearing in Newark, NJ Pg 1,752-1,893
* New Jersey, State of 80/10/21 140pp

8011030641 Transcript of 801028 evidentiary hearing re facility restart in Harrisburg, PA Pg 3828-4034
* Atomic Safety and Licensing Board Panel 80/10/28 209pp 06853.162

8011060394 Testimony in response to ASLB Questions 6 e & f, showing that in event of feedwater loss, operation will provide adequate core cooling during feed & bleed mode Prof qualifications encl Related correspondence
JONES, R C Metropolitan Edison Co JONES, R C Babcock & Wilcox Co 80/10/28 7pp 06910 302

--8011060399 Testimony supplementing JH Correa, GT Urquhart & RC Jones 800915 testimony, in response to ASLB question on UCS Contentions 5 & 6 re valves & valve testing Safety valves designed to discharge two-phase fluid w/prof qualifications
CORREA, J H, URQUHART, G T Metropolitan Edison Co. CORREA, J H General Public Utilities - GPU Service Corp 80/10/28 8pp 06910 309

--8011060404 Testimony supplementing RC Jones & TO Broughton 800915 testimony, in response to ASLB question on Contention B re addl LOCA analysis Addresses NUREG-0565 & NUREG-0623 recommendations, w/prof qualifications & Certificate of Svc
JONES, R C, BROUGHTON, T O Metropolitan Edison Co JONES, R C Babcock & Wilcox Co 80/10/28 38pp 06910 317.

8011040412 Forwards 801027 transcript of hearing before NJ DOE Board of Public Utils, in response to NRC 790921 ltr requesting to be kept informed re significant regulatory developments
SHEENEY, L E Jersey Central Power & Light Co 80/10/29 1p 02319 194

--8011040414 Transcript of 801027 hearing before NJ DOE Board of Public Utils. Pg 2010-2061, Vol 18
* New Jersey, State of 80/10/27 51pp 02319.194

8011040435 Forwards transcript of 801023 hearing in Newark, NJ re TH1-l restart Pg 1,894-2,009
SHEENEY, L E Jersey Central Power & Light Co 80/10/29. 1p 02227.001

--8011040441 Transcript of 801023 hearing in Newark, NJ re TH1-l restart Pg 1,894-2,009
* New Jersey, State of 80/10/23 116pp 01741-019.

8011050398 Transcript of 801029 evidentiary hearing in Harrisburg, PA Pg 4,035-4,4213
* Atomic Safety and Licensing Board Panel 80/10/29 180pp 06873.338.

8011040542 Forwards TO Broughton 801033 testimony in response to ASLB Question 11 re NUREG-0578 Certificate of Svc encl
BAKTER, T A Shaw, Pittman, Potts & Trowbridge 80/10/30 5pp 06873.323

--8011040547 Testimony in response to ASLB Question 11 re Recommendation 2 1 9 c of NUREG-0578 Program implementation & training will be completed by Fall, 1981 Prof qualifications encl
BROUGHTON, T O Metropolitan Edison Co 80/10/30 9pp. 06873.328

8011050595 Transcript of 801030 restart hearing in Harrisburg, PA Pg 4,214-4,446
* Atomic Safety and Licensing Board Panel 80/10/30 250pp 06892.019

8011040467 Submittal of NRC testimony in response to ASLB questions re UCS Contentions 8 & 12 & Questions 2, 9 & 11 on sufficiency of proposed short-term & long-term actions Certificate of Svc encl
CUTCHILL, J M Hearing Branch 4 80/10/31 4pp 02319 194

--8011040473 Testimony in response to ASLB question re UCS Contention B Manual trip requirement is adequate in interim period during which need for automatic trip is evaluated under action plan Prof qualifications encl
JENSEN, W L Reactor Systems Branch 80/10/31 5pp 02319.194

--8011040480 Testimony in response to ASLB questions on UCS Contention 12 Corrective measures re submergence due to flooding will be completed prior to restart Prof qualifications encl.
ROBERTSON, Z R Reactor Systems Branch 80/10/31 4pp. 02319.194

DOCKETED ITEMS

91

--801104048B Testimony in response to ASLB Question 2 re sufficiency of proposed addl short-term & long-term requirements Actions provide reasonable assurance that plant may be operated w/o endangering health Prof qualifications encl
ROSEN, D F Division of Systems Integration 80/10/31 24pp
02319 196

--801104049I Testimony in response to ASLB Question 9 re groundwater contamination Quality of water monitored under routine operations, accident conditions & cleanup operations Supporting documentation & prof qualifications encl
JOHNSON, T L Assistant Director for Environmental Technology 80/10/31 15pp 02319 196

--801104050D Testimony in response to ASLB Question 9 b re groundwater contamination, Licensee commitment acceptable re reducing leakage from sys containing radioactive fluids Prof qualifications encl
BODDART, P G Assistant Director for Environmental Technology 80/10/31 6pp 02319 196

--801104050B Testimony in response to ASLB Question 11 re transient & accident analysis & procedures Current emergency procedures under review & will be completed prior to restart Operators are being retrained Prof qualifications encl
JENSEN, W L Reactor Systems Branch 80/10/31 6pp 02319 196

801130036 Transcript of 801031 restart hearing in Harrisburg, PA
Pp 4461-4523
* Atomic Safety and Licensing Board Panel 80/10/31 67pp
06938 086

801110281 Forwards transcript of 801029 hearing in Newark, NJ, per NRC 790921 & 1109 requests for info Handwritten numbers from Pages 3,000 to 3,120 should be disregarded
SWEENEY, L E Jersey Central Power & Light Co 80/11/04 1p
06915:001

--801110288 Transcript of 801029 hearing before Board of Public Utils. in Newark, NJ in response to NRC request for significant regulatory developments affecting General Public Utils companies. Pp 2,062-2,220
* New Jersey, State of 80/10/29 160pp 06915 001.

801140296 Transcript of 801104 restart hearing in Harrisburg, PA
Pp 4,524-4,661.
* Atomic Safety and Licensing Board Panel 80/11/04 139pp
06960 109.

801140300 Transcript of 801105 restart hearing in Harrisburg, PA
Pp 4,662-4,848.
* Atomic Safety and Licensing Board Panel 80/11/05, 188pp
06961:001.

801120343 Forwards info re significant regulatory developments affecting General Public Utils companies in restart proceeding, in response to 790921 & 1109 requests
SWEENEY, L E Jersey Central Power & Light Co 80/11/05 1p.
01741 019.

--801121037B Transcript of 801030 hearing before NJ Board of Public Utils in Newark, NJ re util petition for rate increase
Pp 3,121-3,212
* New Jersey, State of 80/10/30 92pp 01741:019

801140304 Transcript of 801106 restart hearing in Harrisburg, PA
Pp 4,839-5,031.
* Atomic Safety and Licensing Board Panel 80/11/06 195pp
06962, 100

801170580 Transcript of ASLB 801107 hearing in Harrisburg, PA re restart Pp 3,032-3,110.
* Atomic Safety and Licensing Board Panel 80/11/07 150pp.
06976, 001

8011180224 Forwards transcript of 801105 hearing in Newark, NJ in response to 790921 & 1109 requests to remain informed of significant regulatory developments in restart hearing
SWEENEY, L E Jersey Central Power & Light Co 80/11/10 1p
06915, 001

--8011180229 Transcript of 801105 hearing before NJ Board of Public Utils in Newark, NJ, re util petition for rate increase
Pp 3213-3417
* New Jersey, State of 80/11/05 204pp 06915 001.

8011240449 Transcript of 801111 restart hearing in Harrisburg, PA
Pp 5111-5287.
* Atomic Safety and Licensing Board Panel. 80/11/11 176pp.
02227:001.

8011210175 Transcript of 801112 hearing in Harrisburg, PA Pp 5288-5481
* Atomic Safety and Licensing Board Panel 80/11/12 192pp
07037 223

8011210182 Transcript of 801113 hearing in Harrisburg, PA Pp 5482-5657
* Atomic Safety and Licensing Board Panel 80/11/13 175pp
07031 360

8011240043 Transcript of 801114 restart hearing in Harrisburg, PA
Pp 5658-5742
* Atomic Safety and Licensing Board Panel 80/11/14 104pp
07038 304

8011240191 Transcript of 801118 restart hearing in Harrisburg, PA Pp 5763-5939
* Commissioners 80/11/18 180pp 07071 130

V Operator Examinations

8011210057 Responds to 801003 request for restart of licensing exam for 38 operators & senior operators between 810420-0508 Exam schedule dependent upon implementation of TH1-2 action plan items & results of restart hearing
COLLINS, P F Operator Licensing Branch 80/11/12 4pp 07031 001

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8011190499 Forwards safety evaluation of remaining open items of Amend 35 to DPR-35 covering fire protection Requests tentative schedule for implementing open items
IPPOLITO, T A Operating Reactors Branch 3, 80/10/07 7pp
06916:001

8011190603 Notifies of interim rule suspending completion dates for fire protection mods previously approved by NRC FR notice encl
EISENHUT, D G Division of Licensing 80/10/31 5pp 06996 219

0 Adjudicatory correspondence

8011070581 Forwards order for mod of License DPR-35 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp
06925 210

--8011070585 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by B20430. Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24, 6pp 06925 212

--8011070588 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06925 218

8011030192 Withdraws 801023 request for extension or for hearing per IE Bulletin 79-01B, Suppl 3
DIGNAM, T G Boston Edison Co DIGNAM, T G, Ropes & Gray 80/10/30 1p 06897 297

I Financial information

8011250359 Forwards data for compliance w/1975 amends to Price Anderson Act (Public Law 94-197) Annual Rept 1979, Form 10-G for quarter ending 800930 as filed w/Securities & Exchange Commission & cash flow forecast for 1991 encl
MAY, T J Boston Edison Co 80/11/21 57pp, 07068 133.

P Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition
GRINES, C I, Assistant Director for Engineers & Projects (Pre 790825), 79/03/02 2pp 03145, 305

8011050354 Ltr to all licensees of operating plants, applicants for GLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

DOCKETED ITEMS

801100486 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101 EISENHUT, D O Division of Licensing 80/10/01 5pp.

801190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance info should be submitted within 25 days
EISENHUT, D O Division of Licensing 80/10/01 2pp 07000 087.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lameilar Tearing on Component Supports" W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

801180193 Confirms plans for 801030 mgt meeting at facility to discuss regulatory performance Agenda encl
GRIER, B H Region 1, Philadelphia, Office of the Director.
80/10/16. 4pp 06987 299

8011070381 Forwards order for mod of License DPR-35 re environ qualification of safety-related electrical equipment
Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24. 2pp.
06925.210

--8011070383 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0388 required by 820630
Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24. 4pp 06925.212

--8011070588 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing. 80/10/24 2pp 06925 218

8011060473 Responds to NRC 800812 request for addl info re containment leakage testing Discusses feedwater sys check valves, reactor core isolation cooling pump discharge, isolation check valves in reactor water cleanup return & core spray to reactor
MORISI, A V Boston Edison Co 80/10/27 5pp 06912 238.

8011040502 Informs of status of NUREG-0378 Category B items. Addl requirements addressed in IE Bulletin 79-018 place constraints on implementation schedule, delivery dates, matl descriptions, lead time & vendors encl
MORISI, A V Boston Edison Co 80/10/29 3pp. 06873.137

8011060459 Forwards response to NRC 801001 request for info re environ qualification of safety-related equipment Notification of testing dates will be forwarded to NRC
MORISI, A V Boston Edison Co 80/10/29 2pp 06916-206

8011070457 Requests temporary relief from limiting condition in Tech Spec Section 3.5 B re operability of salt svc water sys during tornados
MORISI, A Boston Edison Co 80/10/31 1p. 06924 350

8011020343 Responds to NRC 800904 ltr requesting addl info re adequacy of electric distribution sys voltages at facility Analysis of voltage profiles proved that safety-related buses will not exceed max voltage rating for Class IE equipment
MORISI, A V. Boston Edison Co 80/11/03 4pp 06952 008.

011210578 Responds to NRC 800707 ltr re Tech Spec changes concerning control rod drive scram discharge vol capability No Tech Spec changes are necessary Lists supporting info addressing Tech Spec concerns.
MORISI, A V Boston Edison Co. 80/11/13 2pp. 07034.182

Inspection reports, IE Bulletins & correspondence

11060237 Ack receipt of 800310 ltr re corrective actions & payment of civil penalty Noncompliance stands
STELLO, V Office of Inspection & Enforcement, Office of the Director. 80/07/14 3pp 06911.224

1070036 Forwards Suppl 2 to IE Bulletin 79-018, "Environ qualification of Class IE Equipment" No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director
8/09/30 1p 06924.309

8011030092 Immediate Action Ltr 80-33 confirms util 801001 telcon commitment re 801001 reactor trip & resulting transient at facility Util will determine & correct specific problems which caused Safety Relief Valve D to stick open
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/02 2pp 06855 144

8011030072 Immediate Action Ltr 80-37 confirms 800907 telcon re RC9 depressurizations Util will determine causes for opening of Safety Relief Valve A & for inability to close Valves A & D.
GRIER, B H Region 1, Philadelphia, Office of the Director.
80/10/08 1p 06855 125

8011170448 Provides suppl response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power." Mods & testing of sys ring circuits in NRC ofc trailer extension phones completed on 800930
MORISI, A V Boston Edison Co 80/10/08 1p 06977.323

8011040309 Responds to 801001 ltr re BWR scram sys Reassessment of present sys completed & results forwarded in response to IE Bulletin 80-17. Sys meets final design criteria contingent upon equipment availability & planned unit outages.
MORISI, A V Boston Edison Co 80/10/24 2pp. 06873 140

8011060659 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director.
80/10/24 1p. 06909 353.

8011070276 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24. 1p. 06921 280

8011170408 Forwards final response to IE Bulletin 79-018 "Environ Qualification of Class IE Equipment" Response addresses TNI equipment installed to date Future installations have been rescheduled for 820101
MORISI, A V. Boston Edison Co 80/10/29 300pp 06911.001

8011050152 Withdraws 801023 request for extension or for hearing per IE Bulletin 79-018, Suppl 3
DIONAN, T O Boston Edison Co DIONAN, T O Ropes & Gray. 80/10/30 1p. 06897 299.

8011210623 Discusses IE insp on 800303-21 & forwards amended notice of violation & notice of proposed imposition of civil penalty
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/10/30 2pp 07029 277

--8011210627 Amended notice of violation from insp on 800303-21 Noncompliance noted senior operator undertook fuel movement w/o consent of on-duty watch engineer
* Office of Inspection & Enforcement, Office of the Director
80/10/30 1p 07029 279

--8011210630 Notice of proposed imposition of civil penalty in amount of \$4000 00 for item of noncompliance noted in IE insp on 800303-21
* Office of Inspection & Enforcement, Office of the Director.
80/10/30. 1p 07029 280

--8011210637 Ack receipt of 800801 ltr & forwards, amended notice of violation
STELLO, V Office of Inspection & Enforcement, Office of the Director. 80/10/30. 2pp 07029 281

--8011210641 Amended notice of violation from insp on 800303-21 Noncompliance noted senior operator undertook fuel movement w/o verifying secondary containment integrity & w/o consent of watch engineer.
* Office of Inspection & Enforcement, Office of the Director.
80/10/30 2pp 07029:283

8011140272 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31. 1p. 06968.237

8011140394 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Velcor Engineering Corp" No written response required
GRIER, B H. Region 1, Philadelphia, Office of the Director.
80/10/31. 1p. 06963 131

8011240477 Submits updated response to IE Bulletin 80-11, "Masonry Wall Design," re wall re-evaluation schedule
MORISI, A V Boston Edison Co 80/11/03 4pp 07049 077

R. Periodic operating reports & related correspondence

8011100403 "Marine Ecology Studies Re Operation of Pilgrim Station
Semiannual Rept 16 Jan-June 1980 "
ANDERSON, R D, SCOTTON, L M, MOGOLESKO, F J Boston Edison Co
80/10/31 125pp 06916 001

8011180427 Forwards monthly operating rept for Oct 1980
MACHON, R D Boston Edison Co 80/11/10 1p 06989 197

--8011180434 Monthly operating rept for Oct 1980
WHITNEY, Q O, Boston Edison Co 80/11/10 6pp 06989 198

S. Reportable occurrences, LERs & related correspondence

8011040470 Forwards LER 80-072/01T-0
MACHON, R D, Boston Edison Co 80/10/27, 1p 06884 197

--8011040521 LER 80-072/01T-0 on 801002, reactor protection sys trip level
setting was adjusted to nonconservative level due to
calculation error. Procedure 7.4.14 being processed to
clearly delineate method for calculating set points
HOLLAND, P, Boston Edison Co, 80/10/27 2pp 06884.198

801100434 Forwards LER 80-061/03X-1
MACHON, R D Boston Edison Co 80/10/27 1p 06929 321

--8011100459 LER 80-061/03X-1 on 800825, surveillance testing initiated
because of HPCI sys failure, determined that A loop of core
spray sys was inoperable. Caused by core spray valve
MD 1400-24A being partially stuck open
MCLOUGHLIN, M T, Boston Edison Co 80/10/27 1p 06929 322

8011050299 Forwards LER 80-077/03L-0
MACHON, R D, Boston Edison Co 80/10/30, 1p 06899 286

--8011050305 LER 80-077/03L-0 on 800930, excessive moisture in sample
lines prevented chemical personnel from obtaining
representative sample of drywell atmosphere Caused by
condensation accumulating in lines & saturating C-19
MCLOUGHLIN, M T Boston Edison Co 80/10/30 1p, 06899.287

8011060283 EN-80-31A on 800708, amended notices of violation mailed to
util & senior reactor operator re exceeding limiting
condition of operation when irradiated fuel was moved w/o
secondary containment integrity.
BROCKETT, T H, RIESLAND, J Office of Inspection & Enforcement,
Office of the Director 80/10/30, 1p, 06911 164.

8011060483 Forwards LER 80-079/03L-0
MACHON, R D, Boston Edison Co 80/10/31 1p 06910.355

--8011060484 LER 80-079/03L-0 on 801001, following scram, D relief valve
stuck open causing complete depressurization of reactor.
Probably caused by scoring on main piston Valve replaced
MCLOUGHLIN, M T, Boston Edison Co, 80/10/31 3pp 06910 356.

8011070409 RO 80-078/01X-0 on 801030, analysis of salt svc water sys
conducted in response to IE Bulletin 79-14 indicated design
deficiency. Caused by installation of anchor point outside
tornado missile barrier Relocation planned.
MCLOUGHLIN, M T, Boston Edison Co 80/10/31 1p 06910:001.

801110376 PNO-I-80-159 on 801031, during full power operation, Target
Rock relief valve opened & failed to reset. Manual scram was
initiated & reactor is being cooled down via main condenser
Valve reclosed at 340 psi w/ reactor stable. Cause unknown.
JOHNSON, J, MARTIN, T T, BRUNNER, E J Region I, Philadelphia, Office
of the Director 80/10/31 1p 06943:123.

8011120520 Forwards LER 80-081/03L-0.
MACHON, R D, Boston Edison Co, 80/11/03 1p, 06953:349.

--8011120526 LER 80-081/03L-0 on 801005, during shutdown to perform maint
on reactor bldg vent sample pumps due to repeated blown
fuses, flow alarm was annunciating on control room panel
C-903. Caused by instrument drift. Erroneous alarm reset.
MCLOUGHLIN, M T, Boston Edison Co, 80/11/03 1p 06953:350

8011180638 Forwards LER 80-082/03L-0.
MACHON, R D, Boston Edison Co, 80/11/07, 1p, 06988:260

--8011180630 LER 80-082/03L-0 on 801008, containment isolation valve
MD-1001-34B did not close when actuated by control switch
Caused by failure of valve torque switch Valve replaced,
satisfactorily tested & returned to svc
MCLOUGHLIN, M T Boston Edison Co 80/11/07 2pp 06988 261

8011170420 Forwards LER 80-083/04T-0
MACHON, R D Boston Edison Co 80/11/10 1p 06976 360

--8011170429 LER 80-083/04T-0 on 801103, analyses rept indicated that
concentration of Cs-137 found in cranberries from Manomet
Point Bog on 800919 was 354 picocuries/kg Caused by fallout
MCLOUGHLIN, M T, Boston Edison Co 80/11/08 1p 06976 361

8011190407 Forwards LER 80-078/01T-0
MACHON, R D Boston Edison Co, 80/11/13 1p 06998-071

--8011190411 LER 80-078/01T-0 on 801030, review of results of salt svc
water sys per IE Bulletin 79-14, indicated design deficiency
Caused by installation of salt svc water anchor point
outside area tornado missile barrier protection
MCLOUGHLIN, M T, Boston Edison Co 80/11/13 2pp 06998 072

8011190442 Forwards LER 80-080/01T-0
MACHON, R D Boston Edison Co 80/11/14 1p 06998 080

--8011190444 LER 80-080/01T-0 on 801031, reactor vessel relief valve
RV 203-3A opened Caused by nitrogen regulator valve which
froze in open position Drywell instruments will be operated
by compressed air w/nitrogen supply isolated
MCLOUGHLIN, M T Boston Edison Co 80/11/14 2pp 06998.081.

8011210516 Forwards LER 80-075/03L-0
MACHON, R D, Boston Edison Co 80/11/14 1p 07029-242

--8011210521 LER 80-075/03L-0 on 790222 & 0807, fire detection alarms &
master solenoid relay found inoperable Caused by defective
wiring & moisture. Wiring changed & detector dried
MCLOUGHLIN, M T, Boston Edison Co, 80/11/14 1p 07029-243

8011240302 RO 80-084/01X-0 on 801113, during repairs to D MSN discovered
water leaking from 2 inch vessel drain line which connects
to RMCV sys Caused by defective 2 inch pipe coupling weld
Leak isolated & coupling rewelded
MCLOUGHLIN, M T, Boston Edison Co 80/11/14 2pp 02227 001

V. Operator Examinations

8011040514 Responds to 800731 ltr re interim criteria for shift
staffing Compliance w/criteria could be achieved by 811231,
as administrative procedures governing staffing shall be in
conjunction w/implementation of staffing objective
MORISI, A V, Boston Edison Co, 80/10/15 2pp 06873 130

DOCKET 80-295 ZION NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8011170335 Forwards comments on revised emergency plan per requirements
of NUREG-0454 Plan should be revised to address comments
EISENHUT, D G, Division of Licensing 80/10/02, 5pp

8011050428 Forwards draft public info package re emergency
preparedness for facilities. Package has been distributed
to States of IL, IA & WI for comment. Requests NRC comment
by 801121
DELEOROE, L O, Commonwealth Edison Co 80/11/03 3pp.

8011170011 Forwards facility emergency planning info for placement
in LPRR w/o encl
BOUDER, J L, Division of Rules and Records 80/11/04 1p
06978-266

8011260213 Forwards addl info re facility fire protection program, per
NRC 800324 request Twenty-one oversize drawings encl.
TRAMM, T R, Commonwealth Edison Co, 80/11/24 3pp, 07072 061.

--8011260224 "Diesel Generator 1A Feed Breaker " Page AP30.
+ Sargent & Lundy, Inc. 3782 75/09/08 1p 07072 064

--8011260225 "Main Feed Breaker, Electronic Switching Sys, Bus 149."
+ Sargent & Lundy, Inc 3782 72/07/21, 1p, 07072:066

--8011260228 "Reserve Feed Breaker, Electronic Switching Sys, Bus 149."
Page AP34.
+ Sargent & Lundy, Inc 3782 74/06/12, 1p 07072.068.

DOCKETED ITEMS

--8011260231 "RHR Pump 1A Unit Cooler," Page AV1
+ Sargent & Lundy, Inc 3782 73/03/30 1p 07072 070

--8011260234 "Safety Injection Pump 1A Unit Cooler " Page AV3
+ Sargent & Lundy, Inc 3782 73/03/30 1p 07072 072

--8011260237 "Centrifugal Charging Pump 1A Unit Cooler " Page AV7
+ Sargent & Lundy, Inc 3782 73/03/30 1p 07072 074

--8011260241 "Diesel Generator Fuel Oil Transfer Pump 1AE " Page D01
+ Sargent & Lundy, Inc 3782 72/11/03 1p 07072 076

--8011260243 "Diesel Generator Fuel Oil Transfer Pump 1AH " Page D02
+ Sargent & Lundy, Inc 3782 72/11/03 1p 07072 078

--8011260245 "Residual Heat Pump 1A " Page RH1
+ Sargent & Lundy, Inc 3782 73/03/30 1p 07072 080

--8011260247 "Residual Heat Pump 1B " Page RH2
+ Sargent & Lundy, Inc 3782 73/03/30 1p 07072 082

--8011260249 "Safety Injection Pump 1A " Page S11
+ Sargent & Lundy, Inc 3782 73/03/30 1p 07072 084

--8011260253 "Centrifugal Charging Pump 1A " Page VC1
+ Sargent & Lundy, Inc 3782 76/09/16 1p 07072 086

--8011260259 "Centrifugal Charging Pump 1A, Auxiliary Lube Oil Pump " Page VC4
+ Sargent & Lundy, Inc 3782 72/08/29 1p 07072 088

--8011260262 "Centrifugal Charging Pump 1B, Auxiliary Lube Oil Pump " Page VC5
+ Sargent & Lundy, Inc 3782 72/03/13 1p 07072 090

--8011260268 "Loop Schematic Diagram Steam Generator Sys - Part 4 "
+ Sargent & Lundy, Inc 3782 79/07/16 1p

--8011260273 "Loop Schematic Diagram RCS - Part 9 "
+ Sargent & Lundy, Inc 3782 79/07/16 1p

--8011260276 "Loop Schematic Diagram RCS - Part 10 "
+ Sargent & Lundy, Inc 3782 80/07/10 1p

--8011260278 "Loop Schematic Diagram RCS - Part 17 "
+ Sargent & Lundy, Inc 6102-00 80/10/27 1p

--8011260284 "Loop Schematic Diagram RCS - Part 52 "
+ Sargent & Lundy, Inc 6102-00 80/10/27 1p

--8011260290 "Relay Meter / Voltage Regulator Diagram Standby Diesel Generator 1A "
+ Sargent & Lundy, Inc 3782 77/10/25 1p

--8011260296 "Relaying & Metering Diagram 4kV & 480 Volt Buses 14B, 149, 13B & 139."
+ Sargent & Lundy, Inc 3782 76/09/15 1p

8011260301 "Relay & Metering Diagram 4kV Motors "
+ Sargent & Lundy, Inc 3782 78/06/20 1p

Adjudicatory correspondence

01110373 Forwards orders for mod of Licenses DPR-39 & DPR-48 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, S A Operating Reactors Branch 1 80/10/24 2pp 06946 235

--801110580 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06946, 237

801110385 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06946 243

--801110591 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
+ Division of Licensing 80/10/24 2pp 06946 249

8011050183 Order granting extension until 801113 for Commission to consider ALAB-616
CHILK, S J Office of the Secretary of the Commission 80/10/30 1p 06899 064,

8011050433 Withdraws until 801023 request for hearing in view of info presented in Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment "
STEPTOE, P P Isham, Lincoln & Seale 80/10/31 1p

801170892 Order granting extension until 801120 for Commission to consider ALAB-616
CHILK, S J, Commissioners 80/11/13 1p, 06978 099

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing, 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of B00827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lameilar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011050427 Forwards addl info re bypass & reset of engineered safety features, per MRC request Requests MRC approval of purge valve analysis Twenty-one oversize drawings encl
HAUGHTON, W R Commonwealth Edison Co 80/10/15 7pp 02319 196

--8011050430 "Sys Operating Instruction SOI-04B Heating & Ventilation " SCHUMANN, C E, Commonwealth Edison Co 75/07/11 14pp 02319 196

801110573 Forwards orders for mod of Licenses DPR-39 & DPR-48 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, S A Operating Reactors Branch 1 80/10/24 2pp 06946 235

--801110580 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06946 237

--801110591 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
+ Division of Licensing 80/10/24 2pp 06946 249

8011060298 Notification of 801106 meeting w/utills in Bethesda, MD to discuss task action plan
OLSHAN, L, WIGGINTON, D Operating Reactors Branch 1 80/10/27 1p 06911 289

8011070167 Notification of cancellation of 801106 meeting w/utills in Bethesda, MD to discuss status of task action plan
OLSHAN, L, WIGGINTON, D Operating Reactors Branch 1 80/10/27 2pp 06920 298

801170456 Forwards corrected Page 194 to Amends 57 & 54 to Licenses DPR-39 & DPR-48, respectively, issued on 800909
VARQA, S A Operating Reactors Branch 1 80/10/27 2pp 06977 320

--801170460 Corrected Page 194 to Amends 57 & 54 to Licenses DPR-39 & DPR-48, respectively, issued on 800909
+ Operating Reactors Branch 1 80/10/27 1p 06977 322

801120107 Forwards corrected FR notice of issuance & availability of Amends 55 & 52 to Licenses DPR-39 & DPR-48, respectively. Requests that incorrect application date of 801026 be changed to 791001
VARQA, S A Operating Reactors Branch 1 80/10/29 2pp, 06956, 251

DOCKETED ITEMS

95

--801120410 Corrected notice of issuance & availability of Amends 35 & 32 to Licenses DPR-39 & DPR-48, respectively. Correct amend application date is 7/10/01
VARQA, S A Operating Reactors Branch 1 80/10/27 1p
06956 253

8011210443 Forwards request for addl info generated from review of "Asymmetric LOCA Loading," WCAP-7628 & 7748, dtd Nov 1979 & June 1980, respectively
LAINAB, Q C Assistant Director for Safety Assessment 80/10/29 27pp

8011040370 Forwards Vols 1-3 of "Environ Qualification of Class IE Equipment & Addl Equipment Recognized as Essential for Safe Shutdown," in response to revised order for mod of license Provides info re IE Bulletins 79-018 & 79-018, Suppl 2
ABEL, J B Commonwealth Edison Co 80/10/31 3pp 06884 311

--8011040373 "Environ Qualification of Class IE Equipment & Addl Equipment Recognized as Essential for Safety Shutdown," Vols 1-3
* Sargent & Lundy, Inc 80/10/30 1100pp 06886 314

8011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201
ABEL, J B Commonwealth Edison Co 80/10/31 1p

801120317 Advises that plant design features in combination w/ administration controls provide adequate protection re min water depth above irradiated fuel, in response to NRC 800815 ltr No Tech Spec changes necessary
TRAMM, T R Commonwealth Edison Co 80/10/31 2pp 06956 262

801170477 Discusses remaining items contained in util 800328 response to 800229 confirmatory order Item B 2 re control room habitability remains open Request to delay habitability studies under review
VARQA, S A Operating Reactors Branch 1 80/10/31 2pp 06977 316

801103389 Forwards page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments
TRAMM, T R Commonwealth Edison Co 80/11/05 2pp

801180335 Forwards partial response re controls for handling of heavy loads near spent fuel, per NRC 800731 ltr. Second rept not due for another three months. Oversize drawings encl
TRAMM, T R Commonwealth Edison Co 80/11/07 12pp 06987 275.

--801180338 "Diesel Generator Room Hoist Load Path Plan Ground Floor Elevation 592 Ft."
* Sargent & Lundy, Inc 3782.3838 80/11/07 1p 06987 287

--801180342 "Polar Crane Load Paths. Plan Mezzanine Floor Elevation 617 Ft."
* Sargent & Lundy, Inc 3782.3838 80/11/07 1p 06987 288

--801180340 "Hoist Load Path Plan Main Floor Elevation 642 Ft."
* Sargent & Lundy, Inc. 3782.3838 80/11/07 1p 06987 289

--801180346 "Hoist Load Path Crib House"
* Sargent & Lundy, Inc 3782.3838 80/11/07. 1p 06987.290

801190218 Application to amend Licenses DPR-39 & DPR-48, changing App A Tech Specs to assure redundancy in decay heat removal capability & adopt format of STB Class I & II amend fees encl
TRAMM, T R Commonwealth Edison Co 80/11/07 3pp 07000 059

--801190222 Proposed Tech Specs Sections 3.0.4.0, 5.0 & 6.0 to assure redundancy in decay heat removal capability & adopt format of STB Reason for changes encl
* Commonwealth Edison Co 80/11/07 24pp 07000 062

Q Inspection reports, IE Bulletins & correspondence

8011060487 Forwards IE Insp Repts 50-295/80-12, 50-304/80-12, 50-295/80-14 & 50-304/80-14 documenting insp of portion of licensee actions per NRC 800229 confirmatory orders. No open items remain
BRYAN, B.E. Division of Reactor Operations Inspections 80/08/28 1p. 02319 196.

8011040180 Forwards IE Insp Repts 50-295/80-19 & 50-304/80-19 on 800827-28 & 0916-18. No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/09/30 2pp 06884.347.

--8011040184 IE Insp Repts 50-295/80-19 & 50-304/80-19 on 800827-28 & 0916-18. No noncompliance noted. Major areas inspected licensee actions re IE-79-14
VIN, I T, COSTELLO, J R Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/01 7pp 06884 349

8011240074 Forwards IE Insp Repts 50-295/80-17 & 50-304/80-17 on 800801-0930 & notice of violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/16 2pp 07038 288

--8011240079 Notice of violation from insp on 800801-0930
* Region 3, Chicago, Office of the Director 80/10/14 1p 07038 290

--8011240084 IE Insp Repts 50-295/80-17 & 50-304/80-17 on 800801-0930. Noncompliance noted hydrogen purge fan IRV021, made inoperable & required surveillance on fan IRV020 not performed
KOHLE, J E, WATERB, J R, SPESSARD, R L Region 3, Chicago, Office of the Director 80/10/14 13pp 07038 291

8011060172 Confirms 801031 meeting w/RL Bessard in Chicago, IL to discuss regulatory performance
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/10/21 3pp

801120415 Forwards monthly status rept re evaluations performed at facilities in response to IE Bulletin 79-14 H/O encl.
JANECEK, R F Commonwealth Edison Co 80/10/21 2pp

8011070285 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/10/24 1p 06921 300

801110573 Forwards orders for mod of Licenses DPR-39 & DPR-48 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl.
VARQA, S A Operating Reactors Branch 1. 80/10/24 2pp.

--801110580 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0598 required by 820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06946 237

--801110591 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp

801190040 Updates NRC 800903 ltr re site access of Region 3 personnel. New badges are currently being issued. Interim questions re inspector identification should be directed to Region 3 ofc. Badge examples encl
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/10/28 3pp

8011040370 Forwards Vols 1-3 of "Environ Qualification of Class IE Equipment & Addl Equipment Recognized as Essential for Safe Shutdown," in response to revised order for mod of license Provides info re IE Bulletins 79-018 & 79-018, Suppl 2
ABEL, J B Commonwealth Edison Co 80/10/31 3pp. 06884 311

--8011040373 "Environ Qualification of Class IE Equipment & Addl Equipment Recognized as Essential for Safety Shutdown," Vols 1-3
* Sargent & Lundy, Inc 80/10/30 1100pp 06884 314

8011200539 Forwards IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-265/80-27, 50-295/80-21 & 50-304/80-23 on 801031. No noncompliance noted
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/11/06. 2pp

--8011200544 IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-265/80-27, 50-295/80-21 & 50-304/80-23 on 801031. No noncompliance noted. Major areas discussed performance of activities
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/06 26pp

8011250296 Forwards response to IE Bulletin 80-11, "Masonry Wall Design." Operability assessment performed on walls classified as safety-related but failed to meet acceptance criteria. Safe shutdown capability not jeopardized.
ABEL, J B Commonwealth Edison Co 80/11/06 23pp.

DOCKETED ITEMS

R Periodic operating reports & related correspondence

801110209 Forwards monthly operating repts for Oct 1980
GRAESSER, K L Commonwealth Edison Co 80/11/07 1p 06944 030

--801110214 Monthly operating repts for Oct 1980
COOK, J M Commonwealth Edison Co. 80/11/07 11pp 06944-031

B. Reportable occurrences, LERs & related correspondence

8011100401 Forwards LER 80-044/03L-0
GRAESSER, K L Commonwealth Edison Co 80/10/31 1p 06928 062

--8011100407 LER 80-044/03L-0 on 801001, during routine surveillance, maint personnel found 1C RX coolant flow channel 1F-424 comparator setpoint low contrary to Tech Specs Caused by instrument drift Comparator recalibr & returned to svc.
JENKINS, R V Commonwealth Edison Co 80/10/31 1p 06928 063

8011100410 Forwards LER 80-043/03L-0
GRAESSER, K L Commonwealth Edison Co 80/10/31 1p 06928 059

--8011100416 LER 80-043/03L-0 on 801001, while testing charcoal filter banks DAV040 & DAV041, found filter banks 95% below required Tech Specs Caused by change in Tech Specs Charcoal filters replaced.
STAMMER, F H Commonwealth Edison Co 80/10/31 2pp 06928 060

8011070378 Forwards LER 80-045/01T-0
GRAESSER, K L Commonwealth Edison Co. 80/11/03 1p 06925 087

--8011070379 LER 80-045/01T-0, on 801024, basic solution from waste neutralization tank drained to fire sump causing excessive pH Caused by cracked drain valve left open inadvertently Valves chain locked
GURUNATHAN, S Commonwealth Edison Co. 80/11/03 1p 06925 088

8011100716 Forwards LER 80-046/03L-0
GRAESSER, K L Commonwealth Edison Co 80/11/07 1p 06991 307

--8011100723 LER 80-046/03L-0 on 801009, during normal operation, passive failure gas monitor IRT-PR15 repeatedly tripped off Caused by burned limit switch due to loose contacts Valve actuator replaced Monitor returned to svc
AKER, R E Commonwealth Edison Co 80/11/07 1p 06991 308

8011100334 Forwards LER 80-047/01T-0
GRAESSER, K L Commonwealth Edison Co 80/11/10 1p 06961 337

--8011100441 LER 80-047/01T-0 on 801101, approx 27,000 gallons of 4.45 pH wastewater discharged into condenser cooling water Caused by draining of stagnant acidic water in firebox of heating boiler into floor drains Mod to halt draining in progress
GURUNATHAN, S Commonwealth Edison Co 80/11/10 1p 06961 338

8011250330 Forwards LER 80-048/03L-0
GRAESSER, K L Commonwealth Edison Co 80/11/14 1p 07068 339

--8011250337 LER 80-048/03L-0 on 801016, during normal operation, calibr of rad monitors 1 & 2 was not completed within 6-month calibr interval Caused by delay in delivery of calibr gas (Kr-B5) by vendor Personnel re-instructed on procedures
AKER, R E Commonwealth Edison Co 80/11/14 1p 07068 339

8011250338 Forwards updated LER 80-006/01X-1
GRAESSER, K L Commonwealth Edison Co. 80/11/20 1p 07068 340.

--8011250343 Updated LER 80-006/01X-1 on 800821, during normal operation, surveillance of auxiliary bldg ventilation sys revealed inoperable charcoal filters Caused by improper installation of dampers controlling fuel bldg ventilation paths
STAMMER, F Commonwealth Edison Co 80/11/20, 4pp 07068-341

V Operator Examinations

8011100481 Forwards response to NRC 800731 ltr transmitting interim criteria for shift staffing & requesting until schedule for compliance. Vacancies may create situations requiring overtime in excess of NRC guidelines
JANECEK, R F Commonwealth Edison Co 80/11/05 5pp

801120492 Forwards response to NRC 800731 request for schedule per interim shift staffing requirements
JANECEK, R F Commonwealth Edison Co 80/11/05, 5pp.

DOCKET 80-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3F Security, medical, emergency & fire protection plans

8011060563 Notification of 801027 meeting w/util in Bethesda, MD to discuss emergency planning for facilities
STAHLER, C Licensing Branch 2 80/10/16 3pp

8011030627 Forwards response to NRC 800822 comments on guard training & qualification plan Plan withheld (ref 10CFR2.790)
MILLS, L M Tennessee Valley Authority 80/10/24 1p 06855 085

8011290406 Forwards addl comments on draft test plan for replication test for fire protection sys Requests meeting w/NRC for resolution of comments & issues w/proposed test plan
MILLS, L M Tennessee Valley Authority 80/11/20 4pp 07056 114

G Adjudicatory correspondence

8011070516 Forwards order for mod of Licenses DPR-33, DPR-52 & DPR-68 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp, 06925 156

--8011070523 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06925 158.

--8011070531 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06925 164

801120280 Requests reconsideration of NRC issuance of Amends 60, 55 & 32 to Licenses DPR-33, DPR-52 & DPR-68 respectively Amends authorize temporary storage of low level radwaste in pavilions not designed to withstand winds over 80 mph
PAUL, T W, HORN, S, ELY, D Safe Energy Alliance 80/10/28 3pp, 06952 087

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05, 209pp

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing, 80/10/01 5pp

8011190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance Info should be submitted within 25 days
EISENHUT, D O Division of Licensing 80/10/01 2pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011060058 FDIA request for Ofc of Analysis & Evaluation of Operational Data 800930 rept, "Interim Equipment & Procedures at Browns Ferry to Detect Water in Scram Discharge Vol 1"
WEISS, E R Sheldon, Harmon & Weiss 80/10/14 1p.

8011070516 Forwards order for mod of Licenses DPR-33, DPR-52 & DPR-68 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp

--8011070523 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp

DOCKETED ITEMS

97

--8011070531 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp

8011060951 Responds to FOIA request for Ofc of Analysis & Evaluation of Operational Data 800930 rept, "Interim Equipment & Procedures at Browns Ferry to Detect Water in Scram Discharge Vol." Forwards rept
FELTON, J.M. Division of Rules and Records 80/10/31 1p

8011100317 Notification of 801107 meeting w/util in Bethesda, MD to discuss NRC position on util application for long-term onsite storage of low level waste
CLARK, R.A. Operating Reactors Branch 3 80/11/04 2pp 06929 144

8011140107 Ack receipt of E020 rept, "Summary Rept BWR Augmented Offgas Treatment Sys Operating Experience." No comment
MILLS, L.M. Tennessee Valley Authority 80/11/06 1p 06968 001

8011140118 Advises that detailed plan & schedule re environ qualification testing of equipment in safety-related sys will be submitted as soon as available in response to NRC 801001 request
MILLS, L.M. Tennessee Valley Authority 80/11/06 1p 06964 362

8011170753 Notification of 801107 meeting between Div of Human Factors Safety, Div of Sys Integration & IE in Bethesda, MD to review interim equipment & procedures to detect water in scram discharge vol
GOODMAN, M.J. Procedures & Test Review Branch 80/11/06 2pp 06978 332

8011240164 Revises 800731 application to amend Licenses DPR-33, DPR-52 & DPR-68, to authorize onsite low level radiowaste storage at facilities for 5 yrs
MILLS, L.M. Tennessee Valley Authority 80/11/17, 2pp 07049 163

Q Inspection reports, IE Bulletins & correspondence

8011100104 Forwards IE Insp Repts 80-259/80-31, 80-260/80-24 & 80-256/80-25 on 800727-0801 No noncompliance noted
STOHR, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/17 2pp 06930 302

--8011100111 IE Insp Repts 80-259/80-31, 80-260/80-24 & 80-256/80-25 on 800727-0801 No noncompliance noted Major areas inspected: licensee shipper compliance w/DDT & NRC regulations for shipping paper & placarding requirements
MACARTHUR, T.C., POTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 8pp 06930 304

8011060154 Forwards response to IE Bulletin 80-07, "BWR Jet Pump Assembly Failure." Ultrasonic exam of Unit 2 jet pump holddown beams & visual insps of jet pump assembly were made No indications detected
MILLS, L.M. Tennessee Valley Authority 80/10/03 2pp 06914:398

8011040090 Forwards monthly status rept for work as of 801001 re IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys."
MILLS, L.M. Tennessee Valley Authority 80/10/10, 37pp 06874.073

8011040140 Forwards Progress Rept 5 re IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls." Rept reflects work progress since util 800910 ltr
MILLS, L.M. Tennessee Valley Authority 80/10/14 4pp 06874 063.

8011130119 Forwards response to IE Bulletin 80-13, "Cracking in Core Spray Spargers." Visual insp of spargers conducted on 800911 No abnormalities found
MILLS, L.M. Tennessee Valley Authority 80/10/15, 2pp 06956 354

8011170669 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/24, 1p 06976.280

8011280083 Forwards final response to IE Bulletin 80-11, "Masonry Wall Design." Encl discusses results of re-evaluation program & info requested in Item 2b.
GROSS, J.L. Tennessee Valley Authority 80/11/07, 42pp 06918:001.

R. Periodic operating reports & related correspondence

8011040529 Forwards quarterly fish impingement rept for period ending 800930.
MILLS, L.M. Tennessee Valley Authority 80/10/28 1p. 06873:115.

--8011040534 Fish impingement rept for quarter ending 800930
* Tennessee Valley Authority 80/10/28 13pp 06873 116

8011180588 Forwards monthly operating repts for Oct 1980
ABERCROMBIE, H. Tennessee Valley Authority 80/11/10 1p 06988:001.

--8011180594 Monthly operating rept for Oct 1980
THOM, T., GREEN, D. Tennessee Valley Authority 80/11/02 32pp 06988 002

S Reportable occurrences, LERs & related correspondence

8011140025 RD on 801004, w/unit operating at 749 MW, load limited, HPCI declared inoperable due to high level indication in exhaust drain pot indicating blockage of drain line Caused by faulty D-ring in level sensing line
ABERCROMBIE, H. Tennessee Valley Authority 80/10/06 1p 06911 001

8011030629 Part 21 rept re failure of condition containment atmosphere monitoring sys, reported on 801023 Sensors fail to provide accurate hydrogen concentration measurements following LOCA Analysis of defect re BWRs encl
SHERWOOD, O.O. General Electric Co. 80/10/24 1ipp

8011120389 Forwards LER 80-041/03L-0
GREEN, H.J. Tennessee Valley Authority 80/11/03 1p 06950 292

--8011120595 LER 80-041/03L-0 on 801007, breakers 1918 & 1924 tripped when lift pumps on cooling tower 3 started, de-energizing switchgear B Caused by removal of temp sensors on pumps for maint, tripping breakers Breakers reclosed
* Tennessee Valley Authority 80/11/03 2pp 06950:293

8011120580 Forwards LER 80-040/03L-0
GREEN, H.J. Tennessee Valley Authority 80/11/07 1p 06916 001

--8011120585 LER 80-040/03L-0 on 801010, diesel generator 3EB lube oil circulating pump found inoperable Caused by locking of double-row ball bearing Lube oil circulating pump replaced
* Tennessee Valley Authority 80/11/07 2pp 06916 001

8011120586 Forwards LER 80-044/01T-0
GREEN, H.J. Tennessee Valley Authority 80/11/12 1p 07032 218

--8011120596 LER 80-044/01T-0 on 801031, notification received that drywell pressure transmitter 3-PT-64-67 was not qualified for radiation environ following LOCA, per IE Bulletin 79-01B Transmitter Model GENAC 556 replaced w/Foxboro E110M.
* Tennessee Valley Authority 80/11/12 1p 07032 216

8011120598 Forwards LER 80-042/03L-0
GREEN, H.J. Tennessee Valley Authority 80/11/14, 1p 07029 162

--8011120606 LER 80-042/03L-0 on 801017, while performing special instruction 4 2 B-3, drywell high pressure switch 2 on PB-64-58B operated at 0.07 psig above Tech Spec limits Caused by instrument drift Switch recalibr & retested satisfactorily
* Tennessee Valley Authority, 80/11/14 2pp 07029 163.

8011120409 Forwards LER 80-043/03L-0
GREEN, H.J. Tennessee Valley Authority 80/11/17 1p 07056 343

--8011120419 LER 80-043/03L-0 on 801019, flow bias circuitry of average power range monitor high flux drifted high & declared inoperative Caused by water from removal of RHR heat exchanger head draining on panel 25-7, shorting out leads
* Tennessee Valley Authority 80/11/17 2pp 07056 344

U. Congressional/Executive Correspondence

8011030046 Responds to request for assessment of causes & possible consequences of control rod sys failure Rept on 800628 partial failure to SCRAM event prepared by Ofc for Analysis & Evaluation of Operational Data encl.
AHEARNE, J.F. Commissioners 80/10/23 4pp 06907.168

--8011030062 Requests Commission assessment of causes of 800628 event & possible consequences had control rod failures occurred during full power operation & following design basis event.
UDALL, M.K. House of Rep, Interior & Insular Affairs 80/07/16, 1p 06907:172

DOCKETED ITEMS

--8011090068 Re-requests Commission assessment of 800628 vent, requested in 800716 ltr Concerned that delay is result of NRC inability to calculate consequences of failures that might occur following transients at full power.
UDALL, M K House of Rep, Interior & Insular Affairs 80/09/17
1p 06907 173

V Operator Examinations

801120298 Advises of plans to comply w/requirements for senior reactor operator by 810630 & for reactor operator by 820630, in response to NRC 800731 ltr transmitting interim criteria
MILLS, L M Tennessee Valley Authority 80/11/03 1p 06953 277

801140325 Forwards info describing operator training & qualification programs which comply w/criteria addressed in 800328 ltr to all power reactor applicants & licensees
MILLS, L M Tennessee Valley Authority 80/11/10 8pp 06960 347

DOCKET 50-298 COOPER NUCLEAR STATION

F Security, medical, emergency & fire protection plans

801110748 Forwards rept of change to physical security plan, Revision 9 Plan Withheld (ref 10CFR2 790)
PILANT, J M Nebraska Public Power District 80/10/29 2pp, 06943 104

G Adjudicatory correspondence

8011070370 Forwards order for mod of License DPR-46 re environ qualification of safety-related electrical equipment Revised Tech Specs encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp 06925 068

--8011070371 Order for mod of license re environ qualification of safety-related electrical equipment, Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06925 070

--8011070372 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24. 2pp 06925 076.

P Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition.
GRINES, C I Assistant Director for Engineers & Projects (Pre 790625). 79/03/02 2pp 03145 305

71050354 Ltr to all licensees of operating plants, applicants for DLs holders of CPs re preliminary clarification of TMI action on requirements. Provides summary listing of all approved -2 related requirements
EISENHUT, D O. Division of Licensing 80/09/05 209pp

800486 Ltr to all licensees of operating plants & applicants for & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01 5pp

190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance Info should be submitted within 25 days
EISENHUT, D O. Division of Licensing 80/10/01 2pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Anomalous Tearing on Component Supports." W/o encl
EISENHUT, D O. Division of Licensing 80/10/06 6pp.

70370 Forwards order for mod of License DPR-46 re environ qualification of safety-related electrical equipment Revised Tech Specs encl.
IPPOLITO, T A Operating Reactors Branch 2. 80/10/24. 2pp 15-068

--8011070371 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06925 070

--8011070372 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06925 076.

8011060462 Requests Tech Specs revision to incorporate higher exposure points to max average planar linear heat generation rate curves Exposure points were generated using approved methodology of NEDO-24045
PILANT, J M Nebraska Public Power District 80/10/30 4pp 06913 302

G Inspection reports, IE Bulletins & correspondence

8011050383 Forwards IE Insp Rept 50-298/80-12 on 800818-21 No noncompliance noted.
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/09/02 2pp 06899 326

--8011050386 IE Insp Rept 50-298/80-12 on 800818-21 No noncompliance noted Major areas inspected previously inspected items, housekeeping, LERS, IE bulletins & administration
SPANGLER, R O, ROBERTS, M J, WESTERMAN, T F Region 4, Dallas, Office of the Director 80/08/29 5pp, 06899 328

8011060093 Forwards IE Insp Rept 50-298/80-13 on 800908-11 & notices of violation & deviation
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/09/24 2pp 06912:219

--8011060099 Notice of violation from insp on 800908-11
* Region 4, Dallas, Office of the Director 80/09/23 1p 06912:221

--8011060101 Notice of deviation from insp on 800908-11
* Region 4, Dallas, Office of the Director 80/09/23 1p 06912:222

--8011060110 IE Insp Rept 50-298/80-13 on 800908-11. Noncompliance noted requalification program lecture series not initiated for 1980 training cycle beginning in Feb 1980
SPANGLER, R O, ANESHANSLEV, M, YANDELL, L Region 4, Dallas, Office of the Director 80/09/23 8pp 06912:223

801140117 Forwards IE Circular 80-22 "Confirmation of Employee Qualifications." No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/02 1p. 06963 200.

8011060745 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting." No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/10/10 1p 06914:341

8011260105 Forwards IE Insp Rept 50-298/80-15 on 800929-1002 No noncompliance noted.
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch, 80/10/21 2pp 07075 356

--8011260106 IE Insp Rept 50-298/80-15 on 800929-1002 No noncompliance noted Major areas inspected audit program & implementation & followup on LERS.
SPANGLER, R O, WESTERMAN, T F Region 4, Dallas, Office of the Director. 80/10/21 5pp 07075 358

8011070370 Forwards order for mod of License DPR-46 re environ qualification of safety-related electrical equipment Revised Tech Specs encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp

--8011070371 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24. 6pp 06925 070

8011070325 Responds to IE Bulletin 79-018, "Environ Qualification of Class IE Electrical Equipment." Unit could be placed into cold shutdown & long-term cooling established for postulated LOCA.
PILANT, J M, Nebraska Public Power District 80/10/31 3pp. 06918.001

DOCKETED ITEMS

99

--8011070329 "Master List of Class IE Equipment "
* Nebraska Public Power District 80/10/31 700pp 03711,235

8011240045 Ack receipt of 801016 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-298/80-13. Addl info needed re implementation of requalification program on continual basis. Written response requested in 20 days
KADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/13 2pp 07070 338

--8011240051 Responds to NRC 800924 ltr re violations noted in IE Insp Rept 80-298/80-13. Corrective actions quizzes graded promptly to assure proper monitoring of requalification program. QA training will be incorporated into station training program.
PILANT, J M Nebraska Public Power District 80/10/16 4pp 07070,340.

R Periodic operating reports & related correspondence

801140018 Forwards monthly operating rept for Oct 1980.
LESSOR, L C Nebraska Public Power District 80/11/07, 1p, 06961 315

--801140020 Monthly operating rept for Oct 1980
BALLINGER, P L Nebraska Public Power District 80/11/07, 4pp 06961:316

S Reportable occurrences, LERs & related correspondence

8011210495 Forwards LER 80-036/03L-0
LESSOR, L.C. Nebraska Public Power District 80/10/31, 2pp 07029 235.

--8011210499 LER 80-036/03L-0 on 801003, valve RW-AD-95 would not close within time limit. Caused by Miller-64A one piston air operator, which is valve operator on discharge valve, not closing. Valve tested satisfactorily for last four wks.
SCHEER, J L Nebraska Public Power District 80/10/31 1p, 07029, 237.

8011210564 Forwards LER 80-037/03L-0
LESSOR, L C Nebraska Public Power District, 80/11/03 2pp 07034 933

--8011210570 LER 80-037/03L-0 on 801006, during surveillance testing of RHR svc water sys, SW throttle valve on discharge of B heat exchanger would not allow sys flow to pass. Caused by missing disc skirt. Disc & stem nut for SW-MQ-89B replaced.
DOHAN, P F Nebraska Public Power District 80/11/03, 1p 07034:035

8011210488 Forwards LER 80-040/03L-0.
LESSOR, L.C. Nebraska Public Power District 80/11/07 2pp, 07035 115.

--8011210491 LER 80-040/03L-0 on 801017, during normal operation, auxiliary switch failed to return to normal position when 4160-volt breaker EOI tripped. Caused by excessive friction in switch operating mechanism. Switch & linkage will be replaced.
LAHRENCE, L I. Nebraska Public Power District 80/11/07 1p 07035 117

V Operator Examinations

801140031 Notifies that estimated date for compliance w/interim criteria for shift staffing, submitted in NRC 800731 ltr, will be Jan 1982.
PILANT, J M. Nebraska Public Power District, 80/10/31 3pp 06961,192

DOCKET 80-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8011030595 Forwards comments on 800505 & 0725 emergency plan submittals. Requests addl info to satisfy NUREG-0454 criteria
CLARK, R.A. Licensing Branch 2 80/09/26 7pp 06860 084.

8011060071 Forwards supplemental safety evaluation re fire protection mods identified as incomplete in 790802 safety evaluation. Summary of requirements to resolve open items & protection review status encl
CLARK, R.A. Operating Reactors Branch 3, 80/10/21 3pp 06916,168

--8011060075 Safety evaluation suppl re resolution of open items concerning fire protection mods. Fourteen items in Sections 3 i & 3 2 of 790802 safety evaluation remain unresolved
* Operating Reactors Branch 3 80/10/21, 11pp 06916 171.

8011060016 Forwards emergency planning info for housing in Two Rivers, WI LPDR. W/o encl
BOUDER, J L Division of Rules and Records 80/10/22 1p 06914 146

8011060012 Forwards emergency planning info for housing in Two Rivers, WI LPDR. W/o encl.
BOUDER, J L Division of Rules and Records 80/10/23 1p 06914 144

801170126 Forwards facility emergency planning info for placement in LPDR W/o encl
BOUDER, J C Division of Rules and Records 80/10/29 1p 06975,335.

O Adjudicatory correspondence

8011070562 Forwards order for mod of Licenses DPR-24 & DPR-27 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06925 189

--8011070570 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 800630. Complete records must be available by 801201.
EISENHUT, D O Division of Licensing 80/10/24 6pp 06925 191.

--8011070576 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 4pp 06925 197

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants: applicants for DLs & holders of CPs re preliminary clarification of YMI action plan requirements. Provides summary listing of all approved YMI-2 related requirements
EISENHUT, D O Division of Licensing, 80/09/05, 209pp

801190059 Notifies that NRC review of licensee safety analysis for postulated uncontrolled boron dilution events indicates nonconservative plant conditions. Recalculation of boron dilution & Tech Spec mod recommended. W/supporting info
CLARK, R.A. Operating Reactors Branch 1 80/09/30 4pp 06916 001.

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 80101.
EISENHUT, D O, Division of Licensing, 80/10/01, 5pp.

801100937 Ltr to all power reactor licensees & applicants forwarding summary of 800527 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl.
EISENHUT, D.O. Division of Licensing 80/10/06 6pp

8011060930 Informs of approval of responses to concerns stated in NRC 790921 ltr re inadvertent safety injection actuations during surveillance testing
CLARK, R.A. Operating Reactors Branch 2 80/10/21 2pp 06915 280.

801100223 Notifies of duplicate fees required for util 800919 Tech Spec Change Request 64
DIGGS, R M. License Fee Management Branch 80/10/23 1p 06928 267

8011070562 Forwards order for mod of Licenses DPR-24 & DPR-27 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp

--8011070570 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 800630. Complete records must be available by 801201.
EISENHUT, D.O. Division of Licensing, 80/10/24, 6pp

--8011070576 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 4pp

DOCKETED ITEMS

801120443 Forwards request for addl info generated from review of "Asymmetric LOCA Loading," WCAP-7628 & 9748, dtd Nov 1979 & June 1980, respectively
LAINAS, G C Assistant Director for Safety Assessment 80/10/29 27pp

8011070322 Ack receipt of NRC 801006 ltr re licensee 790718 request for proprietary treatment of info describing technical & mgt resources Public disclosure of experience & training of util personnel serves no purpose Nonproprietary rept encl
FAY, C W Wisconsin Electric Power Co 80/10/30 14pp 06924 259

8011040420 Submits environ qualification testing program equipment description, sys, location & cognizant licensee contact re safety-related pressure & differential pressure transmitters per NRC 801001 request
FAY, C W Wisconsin Electric Power Co 80/10/31 2pp 06880:184.

801120358 Submits addl clarification of proposed instrument bus mods, in response to NRC request Describes provisions for preventing parallel operation of new & old batteries
FAY, C W Wisconsin Electric Power Co 80/11/03 4pp 06952:023

801170112 Confirms 801107 meeting w/util at facility to discuss evaluation of regulatory performance
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/11/04, 1p 06978 261

801180436 Discusses license amend approval fees Only single Class 1 duplicate amend fee appropriate since all amend changes have been provided & should be processed & issued at same time.
FAY, C W Wisconsin Electric Power Co 80/11/14 1p 06988:161

G Inspection reports, IE Bulletins & correspondence

801120485 Forwards IE Insp Repts 50-266/80-14 & 50-301/80-14 on 800801-31 & notice of violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/09/29 2pp 03720 238

--801120286 Notice of violation from insp on 800801-31
* Region 3, Chicago, Office of the Director 80/09/22 2pp 03720 260

--801120489 IE Insp Repts 50-266/80-14 & 50-301/80-14 on 800801-31 Noncompliance noted failure to comply w/ASME Section XI code requirements for valve inservice testing, exceeding Tech Specs due to improper valve testing on containment sys.
GULDEKOND, W O., HAGUE, R L, CHOULEB, N C Region 3, Chicago, Office of the Director 80/09/22 9pp 03720 262

8011210142 Forwards IE Insp Repts 50-266/80-15 & 50-301/80-15 on 800902-30. No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/16 2pp 07037 154

--8011210149 IE Insp Repts 50-266/80-15 & 50-301/80-15 on 800902-30 No noncompliance noted Major areas inspected, operational safety verification, monthly maint observation & IE bulletin & circular followup
GULDEKOND, W O., HAGUE, R L, WARRICK, R F Region 3, Chicago, Office of the Director 80/10/15 7pp 07037:156.

8011070294 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/24, 1p. 06921 316

8011070562 Forwards order for mod of Licenses DPR-24 & DPR-27 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24. 2pp

--8011070576 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24. 4pp

801190067 Updates NRC 800903 ltr re site access of Region 3 personnel. New badges are currently being issued. Interim questions re inspector identification should be directed to Region 3 ofc. Badge examples encl
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/28 1p 06979 189.

801190377 Responds to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " Response includes final revision of master list of electrical equipment, component evaluation worksheets, svc profiles & equipment qualification plan
FAY, C W Wisconsin Electric Power Co 80/10/30 130pp 06997:281.

8011060448 Submits seventh supplemental response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Provides analysis & design effort progress rept Analytical schedule for unreleased piping isometric drawings encl
FAY, C W Wisconsin Electric Power Co 80/10/31 4pp 06912:266.

8011280192 Ack receipt of 800910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/80-12 & 50-301/80-12 Downgrades Item 1 noncompliance to deficiency
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/10 2pp 07082 352

--8011280196 Responds to NRC 800822 ltr re violations noted in IE Insp Repts 50-266/80-12 & 50-301/80-12 Corrective actions, refutes NRC allegation of violation of procedure re normal entry & exit from controlled zone
BURSTEIN, B Wisconsin Electric Power Co 80/09/10 3pp, 07082:354

8011280081 Responds to IE Bulletin 80-11, "Masonry Wall Design " Forwards rept on function & configuration of walls, const practices & re-evaluation criteria Wall analysis survey will be submitted within 30 days
FAY, C W, Wisconsin Electric Power Co 80/11/14 41pp. 07081 238

R Periodic operating reports & related correspondence

801170490 Forwards monthly operating repts for Oct 1980.
BURSTEIN, B Wisconsin Electric Power Co. 80/11/10 1p. 06975:062.

--801170492 Monthly operating repts for Oct 1980
FAY, C W, Wisconsin Electric Power Co 80/11/05. 8pp 06975:063

8011250206 Forwards monthly operating repts for Oct 1980.
BURSTEIN, B Wisconsin Electric Power Co 80/11/10 1p. 07036 280.

V. Operator Examinations

801170076 Responds to util 800807 ltr relaying procedures for selection & training of senior operators, Conformance w/Item A 2 of NRC 800328 ltr cannot be deferred
GULLINS, P F, Operator Licensing Branch 80/10/28 1p 06978:272

801120325 Responds to NRC 800731 ltr re interim criteria for shift staffing Util commits to six shifts of eight personnel plus nine others for relief by 820701
FAY, C W Wisconsin Electric Power Co 80/11/03 6pp 06952:072

801120368 Advises that technical advisor training cannot be completed by 810101 as committed to in 791231 ltr Extension to 810301 requested, at which time training program & evidence of conformance w/800903 recommendations will be provided.
FAY, C W, Wisconsin Electric Power Co. 80/11/03 2pp 06952 051.

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

D NRC Draft/Final Environmental Statements, supp & correspondence

8011102270 Partial response to FOIA request for four categories of info re facility & six identified plants reporting high radioactive 1-131 Lists responses to request under Paragraphs 1-4 & forwards documents listed in App A.
FELTON, J M, Division of Rules and Records 80/11/06 3pp 06945 093

--801110303 Excerpt from FES re proposed facility.
* Atomic Energy Commission. 73/05/31 5pp

F. Security, medical, emergency & fire protection plans

8011030041 Forwards NRC position on licensee fire protection program & evaluation of acceptable items.
REID, R W Operating Reactors Branch 4. 80/10/14. 6pp 06855:100.

8011040190 Forwards up-to-date schedule for completion of fire protection mods identified in Encl 2 of NRC 801014 ltr Responses to items not yet approved will be submitted by 801215.
BAYNARD, P Y Florida Power Corp 80/10/29. 5pp. 06884:268.

DOCKETED ITEMS

101

Q. Adjudicatory correspondence

8011140630 Forwards order for mod of License DPR-72 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp 06965 348

--8011140638 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06965 350

--8011140647 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06965 356.

H General correspondence

801110296 FOIA request for four categories of info re facility & six identified plants reporting high radioactive I-131.
DWINELL, B E Affiliation Unknown. 80/10/11 1p 06945 096

8011180150 Addl response to FOIA request for four categories of info re Crystal River 3 & info re six facilities NRC has no analyses subj to Paragraph 3 request
FELTON, J M Division of Rules and Records 80/11/07. 1p.

J Insurance & indemnity information

8011070387 Forwards Endorsement 43 to NELIA Policy NF-195.
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div. 80/11/03 2pp. 06921-048

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O. Division of Licensing 80/09/05 209pp.

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D.O. Division of Licensing. 80/10/01 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D.O. Division of Licensing 80/10/06 6pp.

8011040159 Withdraws Tech Specs Change Request 47, implementing items contained in NRC 790316 confirmatory order. Util considers specs requested in Eisenhut 800702 ltr & provided in Change Request 64; Revision 1, as representing latest position
BRIGHT, R.M. Florida Power Corp 80/10/24. 3pp 06877 011

8011040167 Requests withdrawal of outstanding aspects of Tech Spec Change Request 3 Certificate of Svc encl
BRIGHT, R.M. Florida Power Corp 80/10/24 3pp 06884-274.

8011040204 Requests withdrawal of Tech Spec Change Request 17 in entirety.
BRIGHT, R.M. Florida Power Corp 80/10/24. 3pp 06884-262

8011060322 Forwards "Reactor Containment Bldg Integrated Leak Rate Test."
BRIGHT, R.M. Florida Power Corp 80/10/24. 2pp 06909:165

--8011060329 "Reactor Containment Bldg Integrated Leak Rate Test."
* Gilbert/Commonwealth Cos. 2182 80/09/03 40pp 06909,167

8011060334 "Local Leak Rate Test Rept."
BROWN, J.A. ; TITTLE, L.B. Florida Power Corp 80/09/26. 56pp. 06909:212

801140630 Forwards order for mod of License DPR-72 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
REID, R.W. Operating Reactors Branch 4. 80/10/24. 2pp. 06965:348.

--801140638 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06965:350

--801140647 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06965 356

8011030192 Addl response to FOIA request for several categories of documents re facility Forwards "Response to NRC Request for Info on Reactor Vessel Matl Surveillance Program of Crystal River 3 " Info partially withheld (ref FOIA Exemption 4)
FELTON, J.M. Division of Rules and Records 80/10/28 1p 06860 176.

--8011030189 "Response to NRC Request for Info on Reactor Vessel Matl Surveillance Program of Crystal River 3 " Info partially withheld (ref FOIA Exemption 4)
* Florida Power Corp 80/10/28 7pp

8011030611 Informs that util has no plans for conducting environ qualification testing of safety-related equipment at this time.
BAYNARD, P Y Florida Power Corp 80/10/30 2pp 06855 074

8011030488 Responds to NRC 800924 ltr re development of RCS instrumentation for detection of inadequate core cooling. Licensee plans to develop alternative instrumentation sys & test schemes at LOFT facility
BAYNARD, P.Y. Florida Power Corp 80/10/31 3pp. 06894-037.

801110230 Forwards 801031 "Cycle 3 Startup Rept "
BRIGHT, R M Florida Power Corp 80/11/04 1p. 06943 138

--801110233 "Cycle 3 Startup Rept "
PODLE, D , BRIGHT, R M Florida Power Corp 80/10/31 68pp 06943.139

801110243 Submits response to items re interim reliability evaluation program study recommendations, per 800900 ltr
BAYNARD, P Y Florida Power Corp 80/11/06 4pp 06943:132.

8011210299 Requests 801210 meeting w/B&W owners group & NRC to discuss concerns identified in NRC 801031 ltr re review of existing small break LOCA model to meet code criteria
BAYNARD, P.Y. Florida Power & Light Co. 80/11/17. 2pp 07035 081.

8011250349 Forwards written confirmation of info provided in response to 801024 telecopy of NRC questions re twing check valve in decay heat removal sys
BAYNARD, P.Y. Florida Power Corp 80/11/19 App. 07036-124

Q. Inspection reports, IE Bulletins & correspondence

8011040531 Forwards IE Insp Rept 90-302/80-31 on 800825-26 No noncompliance noted
MURPHY, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/26 2pp 06877 292

--8011040537 IE Insp Rept 90-302/80-31 on 800825-26 No noncompliance noted Major areas inspected, procedures & controls adopted to implement evaluation & reporting requirements of 10CFR21
BROWNLEE, V L Region 2, Atlanta, Office of the Director
COLON, T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/26 3pp. 06877 294

8011170056 Forwards IE Insp Rept 90-302/80-28 on 800801-29 No noncompliance noted
LEWIS, R C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/10/01 2pp. 06981-319

--8011170066 IE Insp Rept 90-302/80-28 on 800801-29 No noncompliance noted Major areas inspected plant operations, security, radiological controls, post-refueling testing, LERs & licensee action on previous insp items
STEKA, T., SMITH, B., BURNETT, P. Region 2, Atlanta, Office of the Director 80/10/01. 9pp 06981.321

8011040147 Forwards revised response to IE Bulletin 80-10. "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ " No cross-ties exist w/contaminated sys
BRIGHT, R.M. Florida Power Corp 80/10/14. 6pp 06874.057

DOCKETED ITEMS

8011070634 Responds to IE Bulletin 80-18 re maint of adequate min flow through centrifugal charging pumps following secondary side high energy line rupture Calculations confirm adequate min flow available for cooling makeup purps
BRIGHT, R M Florida Power Corp 80/10/24 2pp 06925 250

8011140630 Forwards order for mod of License DPR-72 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp 06945:348

--8011140638 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06945:350

8011050222 Ack receipt of ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/80-24
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/10/29 1p 06899 094

--8011050227 Responds to NRC 800903 ltr re violations noted in IE Insp Rept 50-302/80-24, Corrective actions reopened test well
HANGCOCK, J A Florida Power Corp 80/10/06 2pp 06899 095

--8011050231 Forwards IE Insp Rept 50-302/80-24 on 800602-0731 & notice of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/09/03 2pp 06899 097

--8011050235 Notice of violation from insp on 800602-0731
" Region 2, Atlanta, Office of the Director 80/09/02 1p, 06899 099

--8011050241 IE Insp Rept 50-302/80-24 on 800602-0731, Noncompliance noted, failure to obtain samples from Test Well 4 & failure to obtain Commission approval prior to changing ETS 3 & 5
STETHAM, T F, SMITH, B W, HUNT, M D Region 2, Atlanta, Office of the Director 80/09/02 29pp 06899 100

8011200464 Forwards revised Page 7 to IE Insp Rept 50-302/80-28
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/10/31 1p 07020 134

8011200468 Revised Page 7 to IE Insp Rept 50-302/80-28
" Region 2, Atlanta, Office of the Director 80/10/31 1p 07020, 135,

210249 Forwards revised response to IE Bulletin 80-16 re potential application of pressure transmitters, Eight transmitters Output Code A installed No corrective action necessary
WYNARD, P Y Florida Power Corp 80/10/31, 4pp 07030 115

11210384 Forwards rept prepared by Gilbert Associates, Inc in response to IE Bulletin 79-010 re environ qualification of Class IE equipment, Replaces 800630 issue W/o encl
BAYNARD, P Y Florida Power Corp 80/10/31 3pp 07030, 187,

8011280118 Notifies of delay in response to item 2b of IE Bulletin 80-11, "Masonry Wall Design " Response will be completed by 801120,
BRIGHT, R M Florida Power Corp 80/11/07 2pp, 07093 276

Periodic operating reports & related correspondence

11180608 Forwards monthly operating rept for Oct 1980
BRIGHT, R M Florida Power Corp 80/11/10 1p 06988 120

801180614 Monthly operating rept for Oct 1980
CULVER, M W Florida Power Corp 80/11/03 5pp 06988 121,

Reportable occurrences, LERs & related correspondence

11140930 RD on 800821, during surveillance of circulating water discharge temp, temp at point of discharge exceeded 103 F, contrary to EIS 2 i 2 Cause not stated Detailed rept to follow,
POOLE, D C Florida Power Corp, 80/08/21, 1p 06911:001,

11040482 Forwards LER 80-041/03L-0
HANGCOCK, J A Florida Power Corp 80/10/29 1p 06874 123

--8011040499 LER 80-041/03L-0 on 801002, during normal operation, reactor coolant tank isolation valve HDV-94 would not close due to inadequate torque switch setting Setting adjusted to higher value
" Florida Power Corp 80/10/27 2pp 06874 124

8011140037 RD 80-057-01P on 801029 reactor bldg exhaust monitor RM-A1 discovered operating in degraded mode due to improper detector installation & valve lineup Detailed rept follows within 14 days,
POOLE, D C Florida Power Corp 80/10/30 2pp 06961 190

8011140110 RD on 801023, reactor bldg exhaust monitor RM-A1 was discovered operating in degraded mode, Caused by maint action Reactor bldg purge terminated at time of discovery Detailed rept will follow within 14 days
POOLE, D C Florida Power & Light Co 80/10/30 2pp 06911 001

8011110321 Forwards LER 80-042/03L-0
HANGCOCK, J A Florida Power Corp 80/11/05 1p 06944 177

--8011110328 LER 80-042/03L-0 on 801008, dose equivalent I-131 exceeded 1 O uCi/g creating event contrary to Tech Spec 3.4.8 Caused by leaking fuel pins & anticipated iodine transient following RCS transient Purification flow increased
HERNANDEZ, V A Florida Power Corp 80/11/05 13pp 06944 178

8011120486 Forwards LER 80-044/04L-0
HANGCOCK, J A, POOLE, D Florida Power Corp 80/11/05 1p 06953:103

--8011120490 LER 80-044/04L-0 on 800905, pH results not reported for waste water ponds, test wells or intake & discharge canals Discovered on 801010 Probably caused by loss of pH analysis data Personnel instructed to follow procedures precisely
HERNANDEZ, V A Florida Power Corp 80/11/05 2pp 06953 104

8011140045 Forwards LER 80-045/01T-0
HANGCOCK, J A Florida Power Corp 80/11/07 1p 06961 349

--8011140050 LER 80-045/01T-0 on 801028, purge isolation valves AHV-1A & 1B were inoperable Caused by radiation monitor RM-A1 not representatively sampling reactor bldg atmosphere due to maint actions involving detector removal/replacement
LAMASTER, K F Florida Power Corp 80/11/07 2pp 06961 350

8011180981 Forwards LER 80-046/03L-0
HANGCOCK, J A Florida Power Corp 80/11/13 1p 06988 278

--8011180987 LER 80-046/03L-0 on 801016, during normal operation emergency diesel generator would not start Cause not known No problem found during troubleshooting Procedures revised to require leaving alarm annunciator as is until failure determined
HERNANDEZ, V A Florida Power Corp 80/11/13 2pp 06988 279

V Operator Examinations

8011200335 Responds to NRC 800731 ltr to licensees re shift staffing All shift manning requirements have been implemented Tech Spec Table & 2-1 is being revised to require two senior reactor operators at plant during operation
BRIGHT, R M Florida Power Corp 80/01/13 3pp 07019 024,

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8011170336 Forwards comments on revised emergency plan per requirements of NUREG-0454, Plan should be revised to address comments,
EISENHUT, D G Division of Licensing, 80/10/02 5pp

8011050428 Forwards draft public info package re emergency preparedness for facilities Package has been distributed to States of IL, IA & WI for comment Requests NRC comment by 801121
DELEGORGE, L O Commonwealth Edison Co 80/11/03 8pp

8011170011 Forwards facility emergency planning info for placement in LPOR, W/o encl,
SOUVER, J L Division of Rules and Records 80/11/04 1p 06978, 266

8011260213 Forwards addl info re facility fire protection program, per NRC 800324 request, Twenty-one oversize drawings encl,
TRAMM, T R Commonwealth Edison Co 80/11/24 3pp 07072, 061

DOCKETED ITEMS

103

G Adjudicatory correspondence

801110573 Forwards orders for mod of Licenses DPR-39 & DPR-48 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA,B A Operating Reactors Branch 1 80/10/24 2pp 06946 235

--801110585 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT,D O Division of Licensing 80/10/24 6pp 06946 243

--801110591 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 249

8011050183 Order granting extension until 801113 for Commission to consider ALAB-616
CHILK,B J. Office of the Secretary of the Commission 80/10/30 1p 06899 044

8011060453 Withdraws until 801023 request for hearing in view of info presented in Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment"
STEPTOE,P P Isham, Lincoln & Deale 80/10/31 1p

8011170892 Order granting extension until 801120 for Commission to consider ALAB-616
CHILK,B J. Commissioners 80/11/13 1p 06978-099

F. Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLA & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TH1-2 related requirements
EISENHUT,D O. Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLA & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT,D O. Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports" W/o encl
EISENHUT,D O. Division of Licensing 80/10/06 6pp

8011030427 Forwards addl info re bypass & reset of engineered safety features per NRC request Requests NRC approval of purge valve analysis Twenty-one oversize drawings encl
KAUOHTON,W R Commonwealth Edison Co 80/10/15 7pp 02319 196

--8011050430 "By Operating Instruction SOI-048 Heating & Ventilation"
SCHUMAKR,C.E. Commonwealth Edison Co. 79/07/11 14pp 02319 196

801110573 Forwards orders for mod of Licenses DPR-39 & DPR-48 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA,B A Operating Reactors Branch 1 80/10/24 2pp.

--801110585 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT,D O. Division of Licensing 80/10/24 6pp 06946 243

--801110591 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment.
* Division of Licensing. 80/10/24. 2pp

8011060298 Notification of 801106 meeting w/utills in Bethesda, MD to discuss task action plan
OLEHAN,L. Operating Reactors Branch 1. 80/10/27. 1p

8011070167 Notification of cancellation of 801106 meeting w/utills in Bethesda, MD to discuss status of task action plan
OLEHAN,L. Operating Reactors Branch 1 80/10/27 2pp

8011170456 Forwards corrected Page 194 to Amends 57 & 54 to Licenses DPR-39 & DPR-48, respectively, issued on 800709
VARQA,B A. Operating Reactors Branch 1 80/10/27 2pp 06977 320.

--8011170460 Corrected Page 194 to Amends 57 & 54 to Licenses DPR-39 & DPR-48, respectively, issued on 800709
* Operating Reactors Branch 1 80/10/27 1p 06977 322

8011120407 Forwards corrected FR notice of issuance & availability of Amends 55 & 52 to Licenses DPR-39 & DPR-48, respectively Requests that incorrect application date of 801026 be changed to 791001
VARQA,B A Operating Reactors Branch 1 80/10/29 2pp 06956 251

--8011120410 Corrected notice of issuance & availability of Amends 55 & 52 to Licenses DPR-39 & DPR-48, respectively Correct amend application date is 791001
VARQA,B A Operating Reactors Branch 1 80/10/29 1p 06956 253

8011210443 Forwards request for addl info generated from review of "Asymmetric LOCA Loading," WCAP-9628 & 9748, dtd Nov 1979 & June 1980, respectively
LAINAS,O C Assistant Director for Safety Assessment 80/10/29 27pp

8011040370 Forwards Vols 1-3 of "Environ Qualification of Class IE Equipment & Addl Equipment Recognized as Essential for Safe Shutdown," in response to revised order for mod of license Provides info re IE Bulletins 79-01B & 79-01B, Suppl 2
ABEL,J B Commonwealth Edison Co 80/10/31 3pp 06886 311

--8011040373 "Environ Qualification of Class IE Equipment & Addl Equipment Recognized as Essential for Safety Shutdown," Vols 1-3.
* Sargent & Lundy, Inc 80/10/30 1100pp 06886 314

8011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201
ABEL,J B Commonwealth Edison Co 80/10/31 1p

8011120317 Advises that plant design features in combination w/ administration controls provide adequate protection re min water depth above irradiated fuel, in response to NRC 800815 ltr No Tech Spec changes necessary
TRAHM,T R Commonwealth Edison Co 80/10/31 2pp 06956 262

8011170477 Discusses remaining items contained in util 800328 response to 800229 confirmatory order Item B 2 re control room habitability remains open Request to delay habitability studies under review
VARQA,B A Operating Reactors Branch 1. 80/10/31 2pp 06977 316

8011100389 Forwards page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments
TRAHM,T R Commonwealth Edison Co. 80/11/05 2pp

8011180335 Forwards partial response re controls for handling of heavy loads near spent fuel per NRC 800731 ltr Second rept not due for another three months Oversize drawings encl
TRAHM,T R Commonwealth Edison Co 80/11/07 12pp. 06987 275.

--8011180346 "Hoist Load Path Crib House."
* Sargent & Lundy, Inc 3782, 3838 80/11/07 1p 06987 290

8011190218 Application to amend Licenses DPR-39 & DPR-48, changing App A Tech Specs to assure redundancy in decay heat removal capability & adopt format of STB Class I & II amend fees encl.
TRAHM,T R Commonwealth Edison Co. 80/11/07 3pp 07000 059

--8011190222 Proposed Tech Specs Sections 3.0.4, 3.0.5 & 6.0 to assure redundancy in decay heat removal capability & adopt format of STB Reason for changes encl.
* Commonwealth Edison Co 80/11/07 24pp 07000 062

G Inspection reports, IE Bulletins & correspondence

8011060487 Forwards IE Insp Repts 50-295/80-12, 50-304/80-12, 50-295/80-14 & 50-304/80-14 documenting insp of portion of licensee actions per NRC 800229 confirmatory orders No open items remain
BRYAN,B E. Division of Reactor Operations Inspections 80/08/28 1p. 02319 196

8011040180 Forwards IE Insp Repts 50-295/80-19 & 50-304/80-19 on 800827-28 & 0916-18 No noncompliance noted
FIORELLI,O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/09/30 2pp 06884 347

DOCKETED ITEMS

--8011040184 IE Insp Repts 50-295/80-17 & 50-304/80-17 on 800827-28 & 0916-18 No noncompliance noted Major areas inspected licensee actions re IEB-77-14
YIN, I T, COSTELLO, J R Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/01 7pp 06884 349

8011240074 Forwards IE Insp Repts 50-295/80-17 & 50-304/80-17 on 800801-0930 & notice of violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/16 2pp 07038 288

--8011240084 IE Insp Repts 50-295/80-17 & 50-304/80-17 on 800801-0930 Noncompliance noted hydrogen purge fan IRV021 made inoperable & required surveillance on fan IRV020 not performed
KOHLER, J E, WATERS, J R, SPESSARD, R L Region 3, Chicago, Office of the Director 80/10/14 13pp 07038 291

8011060172 Confirms 801031 meeting w/RL Spessard in Chicago, IL to discuss regulatory performance
KEPLER, J G Region 3, Chicago, Office of the Director 80/10/21 3pp

801120413 Forwards monthly status rept re evaluations performed at facilities in response to IE Bulletin 77-14 W/o encl
JANECEK, R F Commonwealth Edison Co 80/10/21 2pp

8011070785 Forwards Suppl 3 to IE Bulletin 77-01B, "Environ Qualification of Class IE Equipment " No written response required
KEPLER, J G Region 3, Chicago, Office of the Director 80/10/24 1p.

801110573 Forwards orders for mod of Licenses DPR-39 & DPR-48 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
VARGA, S A Operating Reactors Branch 1 80/10/24 2pp

--801110585 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines on NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp.

--801110591 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment.
4 Division of Licensing 80/10/24 2pp

8011190040 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc
Badge examples encl
KEPLER, J G Region 3, Chicago, Office of the Director 80/10/28 3pp.

8011040370 Forwards Vols 1-3 of "Environ Qualification of Class IE Equipment & Addl Equipment Recognized as Essential for Safe Shutdown," in response to revised order for mod of license. Provides info re IE Bulletins 77-01B & 79-01B, Suppl 2
ABEL, J. B. Commonwealth Edison Co 80/10/31 3pp

--8011040373 "Environ Qualification of Class IE Equipment & Addl Equipment Recognized as Essential for Safety Shutdown," Vols 1-3
4 Bargent & Lundy, Inc 80/10/30 1100pp 06886 314

8011200537 Forwards IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-265/80-27, 50-293/80-21 & 50-304/80-23 on 801031. No noncompliance noted.
KEPLER, J G Region 3, Chicago, Office of the Director. 80/11/06, 2pp

--8011200544 IE Mgt Meeting Repts 50-010/80-20, 50-237/80-22, 50-249/80-26, 50-254/80-26, 50-265/80-27, 50-293/80-21 & 50-304/80-23 on 801031 No noncompliance noted Major areas discussed: performance of activities
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/06 26pp.

8011250696 Forwards response to IE Bulletin 80-11, "Masonry Wall Design " Operability Assessment performed on walls classified as safety-related but failed to meet acceptance criteria. Safe shutdown capability not jeopardized
ABEL, J. B. Commonwealth Edison Co 80/11/06, 23pp.

R Periodic operating reports & related correspondence

801110209 Forwards monthly operating repts for Oct 1980
GRAFESSER, K L Commonwealth Edison Co 80/11/07 1p 06944-030

--801110214 Monthly operating repts for Oct 1980
COOK, J M Commonwealth Edison Co 80/11/07 11pp 06944-031

S Reportable occurrences, LERs & related correspondence

8011250318 Forwards LER 80-025/01T-0
GRAFESSER, K L. Commonwealth Edison Co 80/11/14 1p 07068 327

--8011250375 LER 80-025/01T-0 on 801101, during normal operation, leak was discovered on lube oil piping of diesel generator 2A Caused by vibration induced fatigue Pipe was replaced
KRAWCZAK, A T Commonwealth Edison Co 80/11/14 2pp 07068, 328

V Operator Examinations

8011100481 Forwards response to NRC 800731 ltr transmitting interim criteria for shift staffing & requesting util schedule for compliance Vacancies may create situations requiring overtime in excess of NRC guidelines
JANECEK, R F Commonwealth Edison Co 80/11/08 5pp

8011120492 Forwards response to NRC 800731 request for schedule per interim shift staffing requirements
JANECEK, R. F Commonwealth Edison Co 80/11/08 5pp

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8011100538 Requests addl info & commitments re review of emergency plan against NUREG-0634 criteria Plan should be revised to reflect encl comments
VARGA, S A Operating Reactors Branch 1 80/10/15 14pp 06931 235

G Adjudicatory correspondence

8011170287 Forwards order for mod of License DPR-43 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
VARGA, S A Operating Reactors Branch 1 80/10/24 2pp 06978 318

--8011170294 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines on NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06978 320

--8011170302 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
4 Division of Licensing 80/10/24 2pp 06978 326.

P Operating license stage documents & correspondence

8011090354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D G, Division of Licensing. 80/09/09 209pp

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D G, Division of Licensing 80/10/01, 3pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports," W/o encl
EISENHUT, D G Division of Licensing 80/10/06, 6pp.

8011050585 Summary of 801020 meeting w/util re limited number of outstanding licensing actions.
LIGGIARDO, R. B Operating Reactors Branch 1, 80/10/24 4pp. 06902, 082

DOCKETED ITEMS

105

801170787 Forwards order for mod of License DPR-43 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, S A Operating Reactors Branch 1 80/10/24 2pp 06978 318

--801170294 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 800630
Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 4pp 06978 320

--801170302 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06978 326

8011030520 Requests relief from 80101 installation date for TMI mode re safety grade pressure & water level containment & auxiliary feedwater due to supply shipment delays Shift training program description to be submitted by end of 1980
MATHEWS, E R Wisconsin Public Service Corp 80/10/27 3pp 06955 233

8011040532 Discusses necessary changes to ETS re annual release from neutralizing tank & fish impingement program App B to Tech Specs should be completely deleted since State of WI has authority to regulate nonradioactive discharges from plant
MATHEWS, E R Wisconsin Public Service Corp 80/10/29 2pp 06973 071

8011040404 Responds to NRC 801001 ltr re environ qualification of safety-related equipment Qualification for Foxboro & Rosemount pressure & differential pressure transmitters being performed by WYLE labs Discusses IE Bulletin 79-01B
MATHEWS, E R Wisconsin Public Service Corp 80/10/31 2pp 06973 344.

8011040428 Notifies that util is changing sampling point to post-LOCA Hydrogen control panel location to facilitate containment sampling & post-accident w/o exceeding 10CFR20 limits per NUREG-0578, Item 2.1 B a
MATHEWS, E R Wisconsin Public Service Corp 80/10/31 1p 06980 186

8011210577 Discusses implementation of improved range of radiation monitors per NUREG-0578 Several mods will be performed to reduce hazards that may be encountered during implementation Mods should be completed by Apr-May, 1981
MATHEWS, E R Wisconsin Public Service Corp. 80/11/14 2pp 07034 210.

0 Inspection reports, IE Bulletins & correspondence

8011050135 Forwards IE Insp Rept 50-305/80-18 on 800801, 04-08, 11-15, 18-22 & 25-29 & notice of violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/02 2pp 06897 274

--8011050137 Notice of violation from insp on 800801, 04-08, 11-15, 18-22 & 25-29
* Region 3, Chicago, Office of the Director 80/09/30 1p 06897 276.

--8011050142 IE Insp Rept 50-305/80-18 on 800801, 04-08, 11-15, 18-22 & 25-29 Noncompliance noted Failure to fully implement inservice testing of pumps & valves
NELSON, R L, FITZPATRICK, B, WARNICK, R F Region 3, Chicago, Office of the Director 80/09/30 6pp 06897 277

8011050391 Ack receipt of 800820 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/80-15
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/06 2pp 06899 333

--8011050394 Responds to NRC 800728 ltr re violations noted in IE Insp Rept 50-305/80-15 Corrective actions operational test was performed & proved satisfactory prior to releasing pump for operation
MATHEWS, E R Wisconsin Public Service Corp 80/08/20 2pp 06899 335.

8011210164 Forwards IE Insp Rept 50-305/80-17 on 800909-10, No noncompliance noted
HEISHMAN, R F, Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/10/17 2pp 07037 217

--8011210174 IE Insp Rept 50-305/80-17 on 800909-10 No noncompliance noted Major areas inspected core power distribution limits, core thermal power evaluation & reactor shutdown margin determination
CHOULES, N C, ROBINSON, D L, HOPKINS, J B Region 3, Chicago, Office of the Director 80/10/16 4pp 07037 219

8011210419 Forwards IE Insp Rept 50-305/80-19 on 800908 No noncompliance noted.
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/10/21 2pp 07034 021

--8011210424 IE Insp Rept 50-305/80-19 on 800908 No noncompliance noted Major areas inspected emergency planning re drill & test communications
OESTMANN, M J, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/10/08 4pp 07034 023

8011070266 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/24 1p 06921 236

801170287 Forwards order for mod of License DPR-43 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, S A Operating Reactors Branch 1 80/10/24 2pp 06978 318

8011210115 Informs that integration of Westinghouse emergency operating instruction guidelines into emergency procedures is acceptable Notice of deviation w/IE Insp Rept 50-305/80-06 is withdrawn FR excerpt re NRC policy encl.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28 1app 06916 001

801170051 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc
Badges examples encl
KEPPLER, J O, Region 3, Chicago, Office of the Director 80/10/28 3pp 06999 183

8011040404 Responds to NRC 801001 ltr re environ qualification of safety-related equipment Qualification for Foxboro & Rosemount pressure & differential pressure transmitters being performed by WYLE labs Discusses IE Bulletin 79-01B
MATHEWS, E R Wisconsin Public Service Corp 80/10/31 2pp 06873 344

8011210730 Ack receipt of 801024 & 10 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/80-10
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/12 1p. 07029 099

--8011210732 Responds to NRC 800919, 0807 & 0618 ltrs re violations noted in IE Insp Rept 50-305/80-10 Corrective actions, Insp rept & subsequent correspondence distributed to shift supervisors.
MATHEWS, E R Wisconsin Public Service Corp. 80/10/10 2pp 07029 100

--8011210738 Suppl 801010 reply to violations noted in IE Insp Rept 50-305/80-10 Guidance provided in IE Info Notice 80-06 suppl will be adhered to, but requests further interpretive guidance from NRC.
MATHEWS, E R Wisconsin Public Service Corp. 80/10/24 1p 07029 102

R Periodic operating reports & related correspondence

8011140922 Forwards monthly operating rept for Oct 1980
MATHEWS, E R Wisconsin Public Service Corp 80/11/07 1p 06961 322

--8011140924 Monthly operating rept for Oct 1980
RUITER, Q H Wisconsin Public Service Corp 80/11/03 4pp 06961 323

S Reportable occurrences, LERs & related correspondence

8011180670 Forwards LER 80-034/03L-0.
MATHEWS, E R Wisconsin Public Service Corp 80/11/12 1p. 06988 145.

--8011180678 LER 80-034/03L-0, on 801014, nondestructive examination revealed cracks in balance weight welds Caused by lack of fusion Fan blade assembly replaced.
SMOKER, C B Wisconsin Public Service Corp 80/11/13 1p. 06988 146

DOCKETED ITEMS

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8011190598 Notices of interim rule suspending completion dates for fire protection mods previously approved by NRC FR notice encl
EISENHUT, D O Division of Licensing 80/10/31 5pp 06996 214

8011180156 Notification of 801112 meeting w/utl in Minneapolis, MN to provide further clarification of emergency planning requirements
MARTIN, R E Operating Reactors Branch 3 80/11/10 2pp 06987 217

8011260222 Requests addl info & commitments for review of onsite emergency plan against NUREG-0654 criteria Revised plan should address encl comments
CLARK, R A Operating Reactors Branch 3 80/11/14 17pp 07074-093

O Adjudicatory correspondence

8011140683 Forwards order for mod of Licenses DPR-42 & DPR-60 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06968 199

--8011140672 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 800630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06968 201.

--8011140673 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 4pp 06968 207

P. Operating license stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for GLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100215 "LWR In-Plant Measurement Program," informal monthly progress rept for Aug 1980
HANDLER, J W EG&Q Idaho, Inc FIN A-6075 801100215 80/09/19, 4pp 06931 129

801100486 Ltr to all licensees of operating plants & applicants for GLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01, 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl.
EISENHUT, D O. Division of Licensing, 80/10/06 6pp.

8011140683 Forwards order for mod of Licenses DPR-42 & DPR-60 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
CLARK, R A Operating Reactors Branch 3 80/10/24, 2pp.

--8011140672 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 800630 Complete records must be available by 801201
EISENHUT, D. O. Division of Licensing 80/10/24 6pp

--8011140673 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24, 4pp

8011190224 Forwards request for addl info necessary to continue review of 800131 license amend request re spent fuel storage mod
CLARK, R A Operating Reactors Branch 3 80/11/03 13pp 06999 335.

8011170217 Responds to NRC 801001 request for info re environ qualification tests to be conducted within 2 yrs Provides schedule for valve monitoring sys re pressurizer power operated relief safety valves
MAYER, L O. Northern States Power Co 80/11/06 2pp 06768 359

8011140263 Documents util commitment to perform mods to satisfy NRC interim position re containment purge & vent valve operation prior to resuming purging Purge & vent valve circuitry being reviewed Results will be transmitted in approx 4 wks
MAYER, L O Northern States Power Co 80/11/07 2pp 06961 286

8011170555 Responds to NRC 801031 ltr requesting implementation dates for revised post-TMI requirements Advises that NRC ltr was not received until 801110, reducing 45-day response time by 10 days Efforts will be undertaken to prepare response
MAYER, L O Northern States Power Co 80/11/14 2pp 06977-311

8011210484 Informs NRC that work on distribution sys voltage evaluation was deferred due to heavy work load Some progress has been made in completing evaluation Remaining work should be completed within 8 wks
MAYER, L O Northern States Power Co 80/11/17 1p 07033 114

8011250410 Requests relief from TMI action plan implementation schedule of NUREG-0737, item II F 2, re final instrumentation for detection of inadequate core cooling Affidavit encl
MAYER, L O Northern States Power Co 80/11/20 5pp 07056 108

8011260022 Requests amend to Licenses DPR-42 & DPR-60 re decay heat removal capability Water depth over irradiated fuel Tech Spec changes also proposed
* Northern States Power Co 80/11/24 1p 07084-127

8011280063 Forwards application for amend of Licenses DPR-42 & DPR-60, changing Tech Specs re decay heat removal & water depth over irradiated fuel Class III fee encl
MAYER, L. O. Northern States Power Co 80/11/24 1p 07082-234.

--8011280066 Application for amend of Licenses DPR-42 & DPR-60, changing Tech Specs Section 3 & Table 4 1-2A re decay heat removal & water depth over irradiated fuel
MAYER, L O Northern States Power Co 80/11/24 3pp 07082 235

--8011280068 Proposed changes to Tech Specs Section 3 & Table 4 1-2A re decay heat removal & water depth over irradiated fuel
* Northern States Power Co 80/11/24, 6pp 07082 258

Q Inspection reports, IE Bulletins & correspondence

8011060212 Forwards IE Insp Rept 50-306/80-14 & on 800903-03 No noncompliance noted
HIND, J A Region 3, Chicago, Safeguards Branch 80/09/19 2pp 06912 063

--8011060218 IE Insp Rept 50-306/80-14 on 800903-03 No noncompliance noted. Major areas inspected facility organization & operation, measurements & controls & storage & internal control inventory Details withheld (ref IOCFR2 790)
HIND, J A Region 3, Chicago, Safeguards Branch FINLEY, A. O., PATTERSON, J P Region 3, Chicago, Office of the Director, 80/09/18 1p. 06912 065

8011070035 Forwards IE Insp Repts 50-282/80-14 & 50-306/80-15 on 800801-31, No noncompliance noted
HEISHMAN, R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/09/19 2pp 06921-041

--8011070040 IE Insp Repts 50-282/80-14 & 50-306/80-15 on 800801-31 No noncompliance noted Major areas inspected, plant operation maint, surveillance, security, radiation protection, organization, training & followup on IE bulletins.
FEIERABEND, C. D. BURGESS, B L, LITTLE, W B Region 3, Chicago, Office of the Director 80/09/19 5pp. 06921 043.

8011070263 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required.
KEPPLER, J G. Region 3, Chicago, Office of the Director 80/10/24 1p. 06929-255

8011140683 Forwards order for mod of Licenses DPR-42 & DPR-60 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
CLARK, R A Operating Reactors Branch 3, 80/10/24, 2pp.

--801140692 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201 EISENHUT, D G Division of Licensing 80/10/24 6pp

--801140695 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 4pp

8011050147 Forwards IE Insp Repts 90-282/80-15 & 50-306/80-16 on 800901-30 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch, 80/10/28 2pp 06897 283

--8011050153 IE Insp Repts 90-282/80-15 & 50-306/80-16 on 800901-30 No noncompliance noted Major areas inspected operation, maint, surveillance, security, radiation protection & refueling activities
FEIERABEND, C D, BURGESS, B L, LITTLE, W S Region 3, Chicago, Office of the Director 80/10/08 6pp 06897 283

801190034 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc Badge examples encl.
KEPPLER, J D Region 3, Chicago, Office of the Director 80/10/28 3pp 06999 162

801190019 Forwards final response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Replacement of solenoid valves, limit switches & other instruments is being accomplished as matl is received
GILBERT, D E Northern States Power Co 80/10/31 130pp 06999 191

801190079 Submits addl response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds," Two outstanding Unit 1 welds examined ultrasonically & found acceptable.
GILBERT, D E Northern States Power Co 80/10/31 1p 06999 206

8011240471 Forwards final response to IE Bulletin 80-11, "Masonry Wall Design," containing schedule for field mods & updated response to Items 1, 2a & 3 w/o encl
GILBERT, D E Northern States Power Co 80/11/04 2pp 07049 075

R Periodic operating reports & related correspondence

801170308 Forwards monthly operating repts for Oct 1980.
MAYER, L D Northern States Power Co 80/11/11 1p 06975 086

--801170310 Monthly operating repts for Oct 1980.
HUNSTAD, A A Northern States Power Co 80/11/01 8pp 06975 087

S Reportable occurrences, LERs & related correspondence

8011040615 Informs that matter of inadvertent safety injection during surveillance testing resolved per util 791107 response to NRC 790921 & 0626 ltrs
CLARK, R A Operating Reactors Branch 3 80/10/23 2pp 06875 166

8011060484 Forwards LER 80-028/03L-0
MAYER, L D Northern States Power Co 80/10/31 1p 06910 359.

--8011060488 LER 80-028/03L-0 on 801003, previously acknowledged annunciator indicating fan coil unit 24 was noticed in LOCAL control Caused by personnel error. Switch returned to REMOTE & personnel cautioned to exercise care
HUNSTAD, A A Northern States Power Co 80/10/31 1p 06910 360.

8011060494 Forwards LER 80-029/03L-0
MAYER, L D Northern States Power Co 80/10/31 1p 06911 346.

--8011060496 LER 80-029/03L-0 on 801004, inverter 23 failed, leaving panel 213 de-energized Caused by failure of 501a constant voltage transformer. Panel transferred & transformer replaced.
HUNSTAD, A A Northern States Power Co. 80/10/31 1p 06911 347.

801110331 Forwards LER 80-030/03L-0
MAYER, L D Northern States Power Co 80/11/07 1p 06944 202

--801110341 LER 80-030/03L-0 on 801008, diesel generator D2 tripped on high crankcase pressure when eductor hose failed. Caused by burst eductor hose Hose replaced on both diesel engines.
HUNSTAD, A A Northern States Power Co. 80/11/07 1p 06944 203.

801180680 Forwards LER 80-032/03L-0
MAYER, L D Northern States Power Co 80/11/12 1p 06992 094

--801180689 LER 80-032/03L-0 on 801013, during refueling, circulating water intake bay was drained Caused by inoperable printing exhaust & cooling water pump 21 Piping mods are being considered to allow maint w/o effecting operation
HUNSTAD, A A Northern States Power Co 80/11/12 1p 06992 095

801170802 Describes status of environ qualification deficiency re NACD EA-180 limit switch installation discovered during IE Bulletin 79-018 Investigations Matl necessary to upgrade switch installation has been ordered
MAYER, L D Northern States Power Co 80/11/13 2pp 06968 275

8011260181 Forwards LER 80-034/03L-0
MAYER, L D Northern States Power Co 80/11/21 1p 07074 335

--8011260182 LER 80-034/03L-0 on 801031, auxiliary bldg special vent exhaust fan 122 tripped Caused by actuation of thermal overload protective device Device replaced
HUNSTAD, A A Northern States Power Co 80/11/21 1p 07074 336

V Operator Examinations

8011040122 Responds to NRC 800731 ltr re interim criteria for shift staffing Requirements outlined have been implemented re administrative procedures, movement of key individuals about the plant & overtime work
MAYER, L D Northern States Power Co 80/10/29 1p 06874 071

DOCKET 90-309 MAINE YANKEE ATOMIC POWER PLANT

F. Security, medical, emergency & fire protection plans

801100055 Ack receipt of 800909 ltr re preparation of state emergency response plan & agrees to meet w/Nuclear Safety Advisory Committee. FEMA is responsible for reviewing state emergency plans for nuclear power plant environs
AHEARNE, J F Commissioners 80/10/14 1p 06928 256

--801100062 Advises of state preparation of emergency response plan & proposes meeting between NRC & newly appointed Nuclear Safety Advisory Committee
BRENNAN, J E Maine, State of 80/09/09 2pp 06928 257

8011030434 Notification of 801104 meeting w/util in Bethesda, MD to discuss results of NRC review of Facility emergency plan
REGUA, G, Operating Reactors Branch 3 (Pre 800428) 80/10/24 2pp 06857 013

801180328 Forwards facility emergency planning info for placement in LPDR H/o encl
BOUDER, J L Division of Rules and Records 80/11/04 1p 06991 161

G Adjudicatory correspondence

801110442 Forwards order for mod of License DPR-36 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06944 266

--801110448 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06944 268

--801110455 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944 274.

H. General correspondence

8011060199 Responds to 800925 ltr to President Carter re anti-nuclear opposition to facility. NRC not involved in examination of legalities of Facility referendum. NRC cannot predict future use of facility or nuclear power Related memos & ltr encl.
INGRAM, F. Office of Public Affairs 80/10/21 3pp 02319 196

801120047 Responds to 801002 ltr to DOE Secretary Duncan re Facility shutdown voter referendum Facility continued to operate during vote & is currently in operation Related ltrs encl
INGRAM, F. Office of Public Affairs. 80/10/21 3pp 06916 001

DOCKETED ITEMS

P Operating license stage documents & correspondence

8011030394 Ltr to all licensees of operating plants, applicants for OLS & holders of CPs re preliminary clarification of TH1 action plan requirements. Provides summary listing of all approved TH1-2 related requirements.
EISENHUT, D O Division of Licensing 80/09/05 209pp

801104466 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 80101.
EISENHUT, D O Division of Licensing 80/10/01 5pp.

8011030049 Confirms 801016 meeting w/util at facility to discuss NRC assessment of regulatory performance. Agenda encl.
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/02 2pp 06835 113

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issues A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl.
EISENHUT, D O Division of Licensing 80/10/06 6pp

801100415 Advises of review of util 791212 ltr confirming commitment to NRC 791023 interim position on containment purging & venting. Commitments are acceptable, pending completion of long-term review of isolation valve operability.
CLARK, R A Operating Reactors Branch 3 80/10/22 2pp. 06928.004

801110442 Forwards order for mod of License DPR-36 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl.
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06944.266.

--801110448 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 800630. Complete records must be available by 801201.
EISENHUT, D O Division of Licensing 80/10/24, 6pp. 06944.268

--801110455 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing. 80/10/24. 2pp 06944.274

8011030711 Notification of 801028-30 meetings w/util in Augusta, ME & Hiscasset, ME for onsite & offsite util review for proposed Tech Spec changes.
REGUA, O Operating Reactors Branch 3. 80/10/27 2pp. 06860.121.

801120051 Forwards shielding design review including calculated dose rates, in response to TH1 accident requirements outlined in NRC 791030 ltr. Encl review supersedes preliminary shielding rept forwarded in 800305 ltr.
ORRICE, R H Maine Yankee Atomic Power Co 80/11/06. 11pp 06932:054

801170303 Informs of delay in response to NRC 801002 ltr re degraded grid voltage protection. Delay caused by recent diversion of significant manpower resources to comply w/800523 memorandum & order. Anticipates response no later than 801222.
ORRICE, R H Maine Yankee Atomic Power Co 80/11/10 1p. 06996.251.

801180169 Forwards App A & B to License DPR-36. "LP Turbine Disc Info" updating Westinghouse info on disc properties & stresses of both low pressure turbine rotors App A withheld (ref 10CFR2.790)
MOODY, D E Maine Yankee Atomic Power Co. 80/11/13 27pp. 06988.059

Q Inspection reports, IE Bulletins & correspondence

8011070023 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
ORIER, B H Region 1, Philadelphia, Office of the Director. 80/09/30 1p 06924.283.

8011250689 Forwards IE Insp Rept 50-309/80-11 on 800818-0901. No noncompliance noted.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/01. 2pp. 07056:034.

--8011250692 IE Insp Rept 50-309/80-11 on 800818-0901. No noncompliance noted. Major areas inspected: control room, turbine, spent fuel, spray bldgs & auxiliary feed pump areas.
LAZARUS, W J, SWETLAND, P D Region 1, Philadelphia, Office of the Director MARTIN, T T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/26 7pp 07056 036

8011200172 Responds to IE Bulletin 80-19 re failure of mercury-wetted matrix relays. Ten relays have failed, causing increased surveillance testing & eventual replacement w/dry-contact relays.
MOODY, D E Maine Yankee Atomic Power Co 80/10/21 2pp 07021 227.

8011060675 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required.
ORIER, B H Region 1, Philadelphia, Office of the Director. 80/10/24 1p 06914 320.

8011070339 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required.
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06922 041

801110442 Forwards order for mod of License DPR-36 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl.
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06944.266.

--801110448 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 800630. Complete records must be available by 801201.
EISENHUT, D O Division of Licensing. 80/10/24, 6pp 06944:268.

--801110455 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing. 80/10/24 2pp 06944.274

8011210326 Ack receipt of 801009 ltr informing NRC of steps taken to correct violations noted in IE Waste Packaging Insp Rept 15000039/80-07.
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/10/24 1p. 07030 144

--8011210336 Responds to NRC 800917 ltr re violations noted in IE Waste Packaging Insp Rept 15000039/80-07. Corrective actions labels will be affixed to survive inclement weather & waste checklist will be modified.
MOODY, D E Maine Yankee Atomic Power Co 80/10/09 2pp. 07030 145.

--8011210336 Forwards IE Waste Packaging Insp Rept 15000039/80-07 on 800516 & notice of violation.
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/17 2pp 07030 147

--8011210363 Notice of violation from Insp on 800516
* Region 1, Philadelphia, Office of the Director NRC 80/08/18 1p 07030 149.

--8011210373 IE Waste Packaging Insp Rept 15000039/80-07 on 800516. Noncompliance noted: outside of package containing low specific activity radioactive matl not stencilled or otherwise marked to identify contents.
MACARTHUR, T C, POTTER, J P Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/18. 4pp. 07030:151

801140072 Forwards IE Circular 80-23, "Potential Defects in Bafcoit Power Sys Emergency Generators " No written response required.
ORIER, B H Region 1, Philadelphia, Office of the Director. 80/10/31. 1p 06968:233

801140609 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required.
ORIER, B H Region 1, Philadelphia, Office of the Director. 80/10/31 1p 06963,245

801170583 Forwards revised response to IE Bulletin 79-018 re environ qualification of safety-related electrical equipment. Response supersedes util 800602 submittal.
JOHNSON, W P Maine Yankee Atomic Power Co. 80/10/31. 200pp. 06977:001.

DOCKETED ITEMS

109

R. Periodic operating reports & related correspondence

8011040528 Forwards discharge monitoring rept for Sept 1980
GARRITY,J.H. Maine Yankee Atomic Power Co 80/10/28 2pp
06873,315.

--8011040536 Discharge monitoring rept for Sept 1980
* Maine Yankee Atomic Power Co 80/10/28 6pp 06873 317

8011060080 Partial response to FOIA request for info re radiation
levels of plant environs & dump sites & radiation levels in
nine listed places Forwards documents listed in App A Search
is continuing for documents re second part of request
FELTON,J.M Division of Rules and Records 80/10/29 2pp

--8011060122 Excerpts from environ monitoring annual repts. Includes
Indian Point rept for 1978 & ME Yankee & JA Fitzpatrick
Repts for 1979
* Consolidated Edison Co of New York 80/10/29 15pp

R. Reportable occurrences, LERs & related correspondence

8011240341 RD-80-014/OIT-O results from Charpy V-notch impact data for
vessel wall irradiated surveillance indicated higher NDT
shift than originally predicted Followup rept will be
submitted in approx 30 days
WOOD,E.C. Maine Yankee Atomic Power Co 80/06/04. 2pp 07049:094

8011210563 Provides addl details re 801027 collection of decomposing
shortnose sturgeon faked from trash rack B during routine
cleaning, as reported on 801028 Sturgeon transported to Dept
of Marine Resources pathologist
GARRITY,J.H. Maine Yankee Atomic Power Co. 80/11/14. 1p.
07032 229

DOCKET 80-311 BALEH NUCLEAR GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

801100486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs. Info needed by 801101.
EISENHUT,D.O Division of Licensing. 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12. "Potential for Low Fracture Toughness &
Small Tear on Component Supports " W/o encl.
EISENHUT,D.O Division of Licensing. 80/10/06. 6pp

F. Security, medical, emergency & fire protection plans

8011040619 Summary of 801007 meeting w/Lower Alloways Creek fire dept
(LACFD) re LACFD role in facility fire protection plan.
KERRIGAN,J. Licensing Branch 3 80/10/24. 3pp. 06875:168.

801103026 Clarifies 800808 ltr re upgrading of emergency support
facilities Requirements for technical support ctr &
emergency operations facility will be implemented in
accordance w/NRC schedules.
MITTL,R.L. Public Service Electric & Gas Co. of New Jersey
80/11/06. 2pp. 06939 241.

Q. Adjudicatory correspondence

801100098 Forwards order for mod of license to change Tech Specs re
environ qualification of safety-related electrical
equipment.
MIRALTA,F. Licensing Branch 3 80/10/30. 2pp 06915 001.

--8011070109 Order for mod of License DPR-75 to change Tech Specs,
codifying documentation requirements for environ
qualification of safety-related electrical equipment. License
page encl. W/o guidelines & NUREG-0588
PURPLE,R.A. Division of Licensing. 80/10/30. 8pp. 06915:001.

--8011070114 Required Tech Spec 6.10.2 codifying documentation
requirements for environ qualification of safety-related
equipment.
* Division of Licensing. 80/10/30. 2pp. 06915:001.

H. General correspondence

8011050551 Responds to 800903 ltr directed to H Denton re issuance of
full power OL Director's 800416, 18 & 29 decisions under
10CFR2 206 are final agency actions that address concern
Plant emergency plans being reviewed
TEDESCO,R.L. Division of Licensing. 80/10/20 4pp 06901 296

--8011050553 Objects to issuance of full-term OL & expresses concerns re
emergency plans
COLEMAN,E.G. Affiliation Unknown. 80/09/03 2pp 06901:000.

8011080150 Addl response to FOIA request for four categories of info re
Crystal River 3 & info re six facilities NRC has no analyses
subj to Paragraph 3 request
FELTON,J.M. Division of Rules and Records 80/11/07 1p

J. Insurance & indemnity information

8011050586 Forwards Endorsement 33 to MAELU Policy MF-90
CORREA,M.A. Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc
Div 80/11/11 2pp 06992 122.

P. Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TH1 action
plan requirements Provides summary listing of all approved
TH1-2 related requirements
EISENHUT,D.O. Division of Licensing 80/09/05 209pp.

8011200136 Confirms notification of 801023 mgt meeting w/NRC at
facility to discuss util regulatory performance Agenda
encl.
GRIER,B.H. Region I, Philadelphia, Office of the Director
80/10/09 2pp 07019.322.

8011030189 Notification of 801030 meeting w/util in Bethesda, MD re
equipment qualification concerns.
GRIMES,C. Licensing Branch 3. 80/10/28. 2pp 06897:257.

8011070398 Forwards order for mod of license to change Tech Specs re
environ qualification of safety-related electrical
equipment.
MIRALTA,F. Licensing Branch 3 80/10/30 2pp 06915:001

--8011070109 Order for mod of License DPR-75 to change Tech Specs,
codifying documentation requirements for environ
qualification of safety-related electrical equipment. License
page encl. W/o guidelines & NUREG-0588
PURPLE,R.A. Division of Licensing. 80/10/30. 8pp. 06915:001.

--8011070114 Required Tech Spec 6.10.2 codifying documentation
requirements for environ qualification of safety-related
equipment.
* Division of Licensing 80/10/30. 2pp. 06915:001

8011070237 Summary of 801030 meeting w/util in Bethesda, MD re environ
qualification of equipment.
GRIMES,C.I. Licensing Branch 3 80/11/05 8pp 06913.001.

8011070057 Summary of 800819 meeting w/util re proposed Tech Specs
KERRIGAN,J. Licensing Branch 3. 80/11/06. 3pp. 06981:330.

8011200143 Summary of 800815 meeting w/util re status of licensing
review.
KERRIGAN,J. Licensing Branch 3. 80/11/06 4pp. 07021:219

8011040448 Discusses 800707 ltr re feedwater hammer test procedure.
Procedure should be revised to provide info re test
prerequisites, precautions, special test equipment &
instrumentation & data logs. Requests resubmission.
TEDESCO,R.L. Assistant Director for Licensing. 80/11/07. 2pp
06998:087.

8011250296 Forwards application for amend of Licenses DPR-70 & DPR-75,
changing Apps A & B Tech Specs re administrative controls.
Class II & Class I fees encl.
LEBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey.
80/11/20. 1p. 07052:206.

--8011250300 Application for amend of Licenses DPR-70 & DPR-75, changing
Apps A & B Tech Specs re administrative controls.
SCHNEIDER,F.W. Public Service Electric & Gas Co. of New Jersey.
80/11/20. 3pp. 07052:287.

DOCKETED ITEMS

--8011250698 Proposed changes to Tech Specs, Section 6 re administrative controls
 * Public Service Electric & Gas Co of New Jersey 80/11/20
 9pp 07032 302

--8011250697 Proposed changes to ETS, Section 5 re administrative controls
 * Public Service Electric & Gas Co of New Jersey 80/11/20 1p
 07032 311

Q Inspection reports, IE Bulletins & correspondence

8011130954 Forwards IE Insp Rept 50-311/80-15 on 800812-15 No noncompliance noted
 SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/24 2pp 06958 183

--8011130960 IE Insp Rept 50-311/80-15 on 800812-15 No noncompliance noted Major areas inspected chemistry & radiochemistry tests, radiation monitoring & shielding evaluation & effluent monitoring sys
 CLEMONS, P Region 1, Philadelphia, Office of the Director
 KNAPP, P J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/17 6pp 06958 185

8011180439 Ack receipt of 800915 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/80-17 & 50-311/80-13 Util ltr to be withheld (ref 10CFR2 790)
 MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/10/09 1p 06989 204

--8011180443 Forwards IE Insp Repts 50-272/80-17 & 50-311/80-13 on 800714-18 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/08/22 2pp 06989 205

--8011180450 IE Insp Repts 50-272/80-17 & 50-311/80-13 on 800714-18 Noncompliance noted failure to keep isolation zone clear of structures & failure to secure opening in auxiliary relay room wall Details withheld (ref 10CFR2 790)
 BAILEY, R J Region 1, Philadelphia, Office of the Director
 DEVLIN, J W Region 1, Philadelphia, Safeguards Branch 80/08/20 1p 06989 207

8011200282 Suppls response to IE Bulletin 80-06 re engineered safety feature reset controls Addl containment isolation valve identified which could reopen upon reset of isolation signal Circuitry will be revised
 SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey 80/10/20 1p 07020 018

8011180800 Ack receipt of 801010 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/80-20 & 50-311/80-16
 GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/21 1p 06992 038

--8011180803 Responds to NRC 800917 ltr re violations noted in IE Insp Repts 50-272/80-20 & 50-311/80-16 Corrective actions emphasized to operators importance of constant surveillance & proper procedures. Affixed new tags on active matl
 SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey 80/10/10 3pp 06992 039

--8011180808 Forwards IE Insp Repts 50-272/80-20 & 50-311/80-16 on 800801-31 & notice of violation
 BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/17 2pp 06992 042

--8011180811 Notice of violation from insp on 800801-31, * Region 1, Philadelphia, Office of the Director 80/09/16 1p 06992 044

--8011180814 IE Insp Repts 50-272/80-20 & 50-311/80-16 on 800801-31. Noncompliance noted control console reading sheets not initiated, refueling water storage tank level less than Tech Spec min & valves not tagged
 NORRHOLM, L J HILL, W M Region 1, Philadelphia, Office of the Director
 KEINIG, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/16 14pp 06992 045

8011060656 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
 GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06909 349

8011130908 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required
 GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/28 1p 06965 320

8011250237 Forwards inservice insp program
 LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey 80/10/29 1p 07055 158

--8011250238 Inservice insp program
 * Public Service Electric & Gas Co of New Jersey 80/10/29 26pp 07055 159

8011120316 Forwards environ qualification review repts for facility which supersedes all previous info submitted in response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " Proprietary info withheld (ref 10CFR2 790)
 SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey 80/10/31 500pp 07027 001

8011140076 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
 GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06968 257

8011170869 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
 GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06979 360

8011260013 Submits updated response to IE Bulletin 80-11, "Masonry Wall Design," to correct error identified in Item 1 of util 800707 ltr Requests extension for submittal of final rept & evaluation until 801203
 SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey 80/11/04 2pp 07070 328

R Periodic operating reports & related correspondence

8011180621 Forwards NPDES discharge monitoring rept, Jul 1980 Util 800821 ltr to EPA transmitting repts encl
 MIDURA, H J Public Service Electric & Gas Co. of New Jersey 80/11/05 2pp 06915 001

--8011180627 NPDES discharge monitoring rept, Jul 1980
 * Public Service Electric & Gas Co of New Jersey 80/10/07 12pp 06915 001

8011180583 Forwards monthly operating rept for Oct 1980.
 MIDURA, H J Public Service Electric & Gas Co. of New Jersey 80/11/10 1p 06988 034

--8011180587 Monthly operating rept for Oct 1980
 MILLER, L K Public Service Electric & Gas Co of New Jersey 80/11/10 6pp 06988 035

B Reportable occurrences, LERs & related correspondence

8011060419 RO 80-54/01P on 801016, one available fire pump failed to start on receipt of automatic initiation signal & was inoperable per Tech Spec requirements. Cause unknown Pump will be manually started until cause is determined.
 MIDURA, H J Public Service Electric & Gas Co of New Jersey 80/10/17 1p 02319 196

V Operator Examinations

8011060416 Notifies that shift technical advisors will report directly to operating engineer to effect greater involvement in shift operation & improved awareness of plant conditions
 LIBRIZZI, F P Public Service Electric & Gas Co. of New Jersey 80/10/29 1p 06909 039

8011190757 Responds to 800716 ltr to BS Hanauer re status of licensed operating personnel Provides list of info needed to make determination re request for waiver of senior operator license exam application requirement.
 TEDESQU, R L Assistant Director for Licensing 80/10/31 2pp 06996 257

8011260086 Discusses telcon re shift experience requirements for license candidates Min of 3 months experience is necessary, but should be separated into multiple wk segments on specific topics. Course schedules encl.
 SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey 80/11/17 9pp 07071 313

DOCKETED ITEMS

111

DOCKET 80-312 RANCHO SECO NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8011240261 Discusses acceptability of Sacramento County suggestion re location of emergency operations facility at city hall & community ctr in Oalt, CA NRC response re adequacy of Oalt facilities requested by 801215 Two oversize drawings encl BOSSERMAIER, W Sacramento Municipal Utility District 80/11/17 11pp 07049 282

D Adjudicatory correspondence

801110459 Forwards order for mod of License DPR-54 re environ qualification of safety related electrical equipment Revised Tech Specs also encl REID, R.W Operating Reactors Branch 4 80/10/24 3pp 06944 276

--801110464 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201 EISENHUT, D.O Division of Licensing 80/10/24 6pp 06944 279

--801110470 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment. * Division of Licensing. 80/10/24 2pp 06944 285

F Operating license stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements EISENHUT, D.O Division of Licensing 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101 EISENHUT, D.O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports " W/o encl EISENHUT, D.O Division of Licensing 80/10/06 6pp

8011070328 Ack receipt of proposed Amend 67 to facility license to correct error in organizational chart & clarify requirement for surveillance testing Class II fee should be remitted MILLER, W.D. License Fee Management Branch 80/10/17 1p 06919 316.

8011030340 Provides recommendations for implementing provisions of NUREG-0496, "Functional Criteria for Emergency Response Facilities " MATTINGOE, J.J Sacramento Municipal Utility District 80/10/20 5pp. 06867 280

801110459 Forwards order for mod of License DPR-54 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl REID, R.W Operating Reactors Branch 4 80/10/24 3pp 06944 276.

--801110464 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201 EISENHUT, D.O Division of Licensing 80/10/24 6pp 06944 279.

--801110470 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment * Division of Licensing. 80/10/24 2pp 06944 285.

8011040208 Application for Amend 74 to License DPR-54 to change Tech Specs re reactor decay heat removal capability, per IE Bulletin 80-12. MATTINGOE, J.J. Sacramento Municipal Utility District. 80/10/27. 3pp. 06884 253.

--8011040214 Tech Specs 3.1 & 3.8 re reactor coolant sys & fuel loading & refueling. * Sacramento Municipal Utility District. 80/10/27. 6pp. 06884 256.

801120478 Responds to NRC 800924 ltr re request for util to commit to development of instrumentation sys for detection of inadequate core cooling Util maintains position that installed instrumentation at facility is adequate MATTINGOE, J.J Sacramento Municipal Utility District 80/10/29 1p 06953 352

801120416 Discusses B&W integrated reactor vessel matls surveillance program Present reactor vessel matl irradiation Tech Specs remain valid & limits will be modified prior to expiration MATTINGOE, J.J Sacramento Municipal Utility District 80/10/31 2pp 06950 333

801120456 Forwards Class II fee for License Amend 67, in response to NRC 801017 ltr MATTINGOE, J.J Sacramento Municipal Utility District 80/10/31 1p 06953 095

--801120464 Requests processing of util 801031 ltr & fee payment DIGGS, R.M License Fee Management Branch 80/11/07 1p 06953 096

8011200051 Forwards requests for addl info re proposed Amend 70, flux to flow ratio changes, in response to 800811 ltr REID, R.W Operating Reactors Branch 4 80/11/07 4pp 07018 163

801180655 Forwards addl info requested by NRC 801107 ltr re proposed Amend 70 to License DPR-54 MATTINGOE, J.J Sacramento Municipal Utility District 80/11/10 3pp 06991 248.

8011240522 Ack receipt of 800909 ltr re denial of request for access to private land for positioning of TLD environ monitors Relocating monitors to Helms Road acceptable Requests copy of drawing showing relocation REID, R.W Operating Reactors Branch 4. 80/11/12 2pp 07047 012

8011210519 Forwards B&W upgraded design, "Auxiliary Feedwater Sys for SHUD " Requests NRC approval prior to design freeze & preparation of equipment purchase specs on 801203 Oversize drawings available in Central Files BOSSERMAIER, W Sacramento Municipal Utility District 80/11/17 2pp 07044 232

--8011210524 "Auxiliary Feedwater Sys for SHUD " FIRTH, D.J Babcock & Wilcox Co 15-1120580-00 80/07/24 31pp 07044 234

8011240169 Application for proposed Amend 6B, Revision 1, as discussed in 801114 ltr Specific changes include all items submitted on 800619 in proposed Amend 4B & R Reid 800925 ltr Revision 1 is compilation of all ltrs & agreements BOSSERMAIER, W Sacramento Municipal Utility District 80/11/17 1p 07049 100

--8011240174 Proposed Amend 6B, Revision 1, to Tech Specs re fire suppression sys * Sacramento Municipal Utility District 80/11/17 13pp 07049 101.

8011250448 Requests meeting w/NRC on 801210 to discuss methods used for small break LOCA analyses Detailed scope & implementation schedule deferred pending discussion Existing model meets code requirements BOSSERMAIER, W. Sacramento Municipal Utility District 80/11/18 1p. 07058 362

G. Inspection reports, IE Bulletins & correspondence

801100070 Forwards IE Insp Rept 80-312/80-28 on 800902-05 No noncompliance noted SPENCER, G.S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/10/07 2pp 06929 341.

--801100076 IE Insp Rept 80-312/80-28 on 800902-05 No noncompliance noted. Major areas inspected license response to IE Bulletin 79-01B "Environ Qualification of Class IE Equipment " ELIN, J.D. Region 5, San Francisco, Office of the Director. DDDDB, R.T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 80/10/04 7pp 06929 343

8011060763 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting." No written responses required ENGELKEN, R.H. Region 5, San Francisco, Office of the Director 80/10/10 1p. 06909 061

DOCKETED ITEMS

801100017 Provides addl response to IE Bulletin 79-14 Walkdown has been performed & pictures taken to confirm as-built isometrics Revised summary sheet showing final disposition for stress problem encl
MATTIMOE, J J Sacramento Municipal Utility District 80/10/10
3pp 06928 342

801110459 Forwards order for mod of License DPR-54 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 3pp 06944 276

--801110464 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06944 279

--801110470 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944 285

801130016 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment," to aid in written responses required by 801101
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/24 1p 06937 263

801190201 Informs of steps taken re IE Bulletin 80-1B re maint of adequate min flow through centrifugal charging pumps HP18 reviewed & calculations performed No corrective action necessary
MATTIMOE, J J Sacramento Municipal Utility District, 80/10/27 1p 06998 260

801130330 Forwards final response to IE Bulletin 79-01B & Suppls 1-3, "Environ Qualification of Class IE Equipment." All outstanding items identified will be reviewed by 820630
MATTIMOE, J J Sacramento Municipal Utility District 80/10/31 7B2pp 06934 110

801170644 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/31 1p 06977 270

801200026 Forwards IE Insp Rept 50-312/80-30 on 801020-23 No noncompliance noted Encl withheld (ref 10CFR2 790)
NORDBERHAUG, L R Region 5, San Francisco, Safeguards Branch 80/11/03, 2pp 07020 219

801260154 Forwards response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment."
MATTIMOE, J J Sacramento Municipal Utility District 80/11/12 1p 07074 344

R. Periodic operating reports & related correspondence

801110222 Forwards monthly operating rept for Oct 1980
RODRIGUEZ, R J Sacramento Municipal Utility District 80/11/04 1p 06944-044

--801110226 Monthly operating rept for Oct 1980
COLOMB, R W Sacramento Municipal Utility District 80/11/04 7pp 06944 045

S Reportable occurrences, LERs & related correspondence

8011030615 Forwards LER 80-042/04T-0
MATTIMOE, J J Sacramento Municipal Utility District 80/10/28 2pp 06855 230

--8011030622 LER 80-042/04T-0 on 801009, six of 19 environ TLD monitors indicated dose rates above Tech Specs, App B, requirements Caused by TLD being passed through X-ray prior to being brought onsite TLD no longer passed through machines
COLOMB, R W Sacramento Municipal Utility District 80/10/28 1p 06855 232

801120386 RO 80-44, IE Bulletin 79-01B review determined that no qualification documentation available for main steam sys pressure switches Cause not stated New sys for main steam line failure logic will be installed
RODRIGUEZ, R J Sacramento Municipal Utility District 80/11/03 1p 06916 001

801120472 RO 80-45 IE Bulletin 79-01B review determined that air-operated containment isolation valve limit switches were not in compliance w/current environ qualification criteria Cause not stated Switches to be replaced
RODRIGUEZ, R J Sacramento Municipal Utility District 80/11/03 1p 06916 001.

801120479 RO 80-43 on 801031, during review of IE Bulletin 79-01B, air-operated containment isolation valves did not meet Tech Spec requirements Valves will be replaced w/environmentally qualified units
RODRIGUEZ, R J Sacramento Municipal Utility District 80/11/03 1p 06915 001

801120599 RO 80-045 on 801031, as result of IE Bulletin 79-01B review, util reported that NAMCO limit switches on air operated containment isolation valves do not meet environ criteria Switches will be replaced
RODRIGUEZ, R J Sacramento Municipal Utility District 80/11/03 2pp 07029 160

801120601 RO 80-44 providing addl info on inability to obtain qualification documentation for Melstron pressure switches Review concluded two credible failure modes, short & ground, would not produce malfunction Interim operation justified
RODRIGUEZ, R J Sacramento Municipal Utility District 80/11/05 2pp 06930 295

801120889 RO 80-044 on 801103, inability to obtain qualification documentation for Melstron pressure switches was addressed by ltr in accordance w/IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." Design reviewed
RODRIGUEZ, R J Sacramento Municipal Utility District 80/11/05, 2pp 07032 213

8011240314 Forwards LER 80-043/01T-0.
BOSENMAIER, W Sacramento Municipal Utility District 80/11/17 2pp 02227 001

--8011240318 LER 80-043/01T-0 on 801031, per IE Bulletin 79-01B review, found limit switches utilized on air operated containment isolation valves do not meet environ qualification criteria. Switches will be replaced by 820630
* Sacramento Municipal Utility District 80/11/14 1p 02227 001

8011240356 Forwards LER 80-043/01T-0
BOSENMAIER, W, Sacramento Municipal Utility District 80/11/17, 2pp 07049 128.

--8011240362 LER 80-043/01T-0 on 801031, IE Bulletin 79-01B review determined that air-operated valves utilize solenoid pilot valves which do not meet current environ qualification criteria Cause not stated Valves will be replaced
COLUMB, R W Sacramento Municipal Utility District 80/11/14, 1p, 07049 130

8011240368 Forwards LER 80-044/01T-0
BOSENMAIER, W, Sacramento Municipal Utility District 80/11/17, 2pp 02227.001

--8011240372 LER 80-044/01T-0 on 801031, IE Bulletin 79-01B review determined that no qualification documentation available for pressure switches utilized in main steam sys Cause not stated New sys will be installed or old switches replaced
COLUMB, R W Sacramento Municipal Utility District 80/11/14 1p 02227 001

V Operator Examinations

801120370 Discusses current staffing practices & capabilities & schedules to meet criteria, in response to NRC 800731 ltr Schedule for training encl
MATTIMOE, J J Sacramento Municipal Utility District 80/11/03 3pp 06952 036

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F Security, medical, emergency & fire protection plans

8011040001 Forwards proprietary results of NRC-sponsored vital area analysis for facility Mods to security plan may be necessary to assure protection in accordance w/code requirements. Results withheld (ref 10CFR2 790)
REID, R W Operating Reactors Branch 4 80/10/15, 2pp 06885.039.

8011060102 Forwards NRC position on mods needed to resolve open items to meet fire protection requirements identified in NRC 800822 safety evaluation
REID, R W Operating Reactors Branch 4 80/10/24 4pp 06916.148

0 Adjudicatory correspondence

801170373 Forwards order for mod of License DPR-51 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID,R W Operating Reactors Branch 4 80/10/24 2pp 06975 169

--801170384 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT,D O Division of Licensing 80/10/24 6pp 06975 171

--801170394 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06975 177

I Financial information

8011040426 Forwards annual financial statements & cash flow projections to meet current guarantee requirements under Price-Anderson Act
LAHOBSTON,N E Arkansas Power & Light Co 80/10/31 9pp 06874 139

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants; applicants for OLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT,D O Division of Licensing 80/09/05 209pp 02319 196

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT,D O Division of Licensing 80/10/01 5pp 06940 388

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT,D O Division of Licensing 80/10/06 6pp 06940 347

8011060169 Notification of 801022 meeting w/util in Bethesda, MD to discuss fouling of svc water sys by Asian clams, silt & corrosion products & observed 40-inch difference in water levels in downcomers of steam generators A & B
MARTIN,R E Operating Reactors Branch 3 80/10/17 3pp 02319 196

8011060528 Informs of approval of responses to concerns stated in NRC 790921 ltr re inadvertent safety injection actuations during surveillance testing
REID,R W Operating Reactors Branch 4 CLARK,R A Operating Reactors Branch 3 80/10/21 2pp 06915 282

801170373 Forwards order for mod of License DPR-51 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID,R W Operating Reactors Branch 4 80/10/24 2pp 06975 169.

--801170384 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT,D O Division of Licensing 80/10/24 6pp 06975 171

--801170394 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06975 177.

8011040413 Forwards corrected summary of radioactive effluents released in 1978 in response to NRC 801008 ltr
TRIMBLE,D C Arkansas Power & Light Co 80/10/28 1p 01741 019

--8011040418 Forwards draft summary of radioactive effluents released from facility in 1978 Comments & changes requested by 801023 response encl
HARTFIELD,R A Licensee Operators Evaluation Branch 80/10/08 69pp 01741 019

8011040543 Notifies AR Dept of Public Safety of 801030 meeting at plant to initiate review process re memorandum of understanding for notification of releases of radioactive matl due to expire on 801101 Identical ltr to AR Dept of Health encl
O'HAULOH,J P Arkansas Power & Light Co 80/10/29 2pp 06873 069

8011070509 Responds to NRC 800524 ltr re Lessons Learned Task Force Short-Term Requirement 2.1.3.b Existing instrumentation is sufficient to detect inadequate core cooling Reactor vessel level indication is unwarranted
TRIMBLE,D C Arkansas Power & Light Co 80/10/29 3pp 06921 018

801170471 Verifies that seal ring has been removed from cavity annulus area & is not potential missile hazard Concludes that safety issue has been satisfactorily resolved
REID,R W Operating Reactors Branch 4 80/10/30 3pp 06977 318

8011040245 Forwards "Cycle 5 Reload Rept " Amend to Cycle 5 reload rept & proposed Tech Spec changes to be submitted by 800102 due to early shutdown for refueling
TRIMBLE,D C Arkansas Power & Light Co 80/10/31 1p 06880 104

--8011040249 "Cycle 5 Reload Rept "
* Babcock & Wilcox Co BAW-1606 80/07/31 80pp 06880 105

8011070411 Application to amend Licenses DPR-51 & NPF-6, changing Tech Specs re waste gas sys hydrogen/oxygen concentration limits Class III & I fees encl
CAVANAUGH,W Arkansas Power & Light Co 80/10/31 3pp 06919 349

--8011070419 Proposed Tech Specs 2.4.3 & 2.2.3 re waste gas sys hydrogen/oxygen concentrations & monitoring requirements
* Arkansas Power & Light Co 80/10/31 4pp 06919 352

801100377 Application to amend Licenses DPR-51 & NPF-6, submitted as proposed Tech Spec re decay heat removal capability, per NRC 800611 ltr
CAVANAUGH,W Arkansas Power & Light Co 80/10/31 2pp 06928 073

--801100382 Proposed Tech Spec 3.1 re reactor coolant sys
* Arkansas Power & Light Co 80/10/31 13pp 06928 075

801130197 Application to amend Licenses DPR-51 & NPF-6, changing Tech Specs re mode resulting from implementation of TH1-2 Lessons Learned Category A items Class I & IV fees encl
CAVANAUGH,W Arkansas Power & Light Co 80/10/31 2pp 06959 223

--801130205 Proposed Tech Specs re TH1-2 Lessons Learned Category A items, including emergency power supply, valve position indication, instrumentation for inadequate core cooling, containment isolation & auxiliary feedwater sys
* Arkansas Power & Light Co 80/10/31 16pp 06959 225

801140187 Forwards proposed Tech Specs change to include electromagnetic relief valve setpoint as condition for operability when RCS pressure exceeds low pressure trip setpoint, in response to NRC request
CAVANAUGH,W Arkansas Power & Light Co 80/10/31 2pp 06961 270

--801140197 Proposed revision to Tech Spec 3.1.1.5 & Table 4.1-2 to include electromagnetic relief valve setpoint as condition for operability when RCS pressure exceeds low pressure trip setpoint.
* Arkansas Power & Light Co 80/10/31 3pp 06961 272

801140420 Application for amend to 790402 application requesting Tech Spec change of License DPR-51, to exclude reactor bldg purging during power operation Class III fee encl
CAVANAUGH,W Arkansas Power & Light Co 80/10/31 2pp 06963 001

--801140424 Proposed changes to Tech Specs 3.23 & 4.26 for reactor bldg purge valves
* Arkansas Power & Light Co 80/10/31 2pp 06963 003

801100513 Resubmits NRC approved QA Topical Rept, APL-TOP-1A, Revision 5
TRIMBLE,D C Arkansas Power & Light Co 80/11/06 1p 06999 001

--801180243 Revision 5 to approved QA manual - operations
* Arkansas Power & Light Co. APL-TOP 1A RS. 80/10/10 73pp 06999 003

80110703 Forwards "Extended-Burnup Lead Test Assembly Design Rept," addl ref document to 801031 Cycle 5 reload rept
TRIMBLE,D C Arkansas Power & Light Co 80/11/06 1p 06950 072

DOCKETED ITEMS

--801110308 "Extended-Burnup Lead Test Assembly-Design Rept "
* Babcock & Wilcox Co BAH-1624 80/10/31 47pp 06950 073

801140278 Documents commitments & responses made as result of 801022 meeting between util & NRC re svc water, steam generator level & bolting concerns
TRIMBLE, D C Arkansas Power & Light Co 80/11/06 5pp 06960 355

8011240292 Responds to request for review of NUREG-0660 "Clarification of TMI Action Plan Requirements " Proposes 801210 meeting to discuss detailed response & possible updating of NUREG's Small break LOCA model in compliance
TRIMBLE, D C Arkansas Power & Light Co 80/11/14 1p 07049 349

8011260173 Forwards Amends 47 & 17 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability
CLARK, R A Operating Reactors Branch 3 REID, R W Operating Reactors Branch 4. 80/11/14 5pp 07074 292

--8011260174 Amends 47 & 17 to Licenses DPR-51 & NPF-6 respectively, modifying Tech Specs Apps A & B dealing w/util mgt organizational structure
REID, R W Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 80/11/14 34pp 07074 293

--8011260176 Safety evaluation supporting Amends 47 & 17 to Licenses DPR-51 & NPF-6, respectively
* Office of Nuclear Reactor Regulation, Director 80/11/14 2pp 07074 328

--8011260178 Notice of issuance & availability of Amends 47 & 17 to Licenses DPR-51 & NPF-6, respectively
CLARK, R A Operating Reactors Branch 3 80/11/14 2pp 07074.330.

G Inspection reports, IE Bulletins & correspondence

8011060670 Forwards IE Insp Repts 80-313/80-16 & 80-368/80-16 on 800902-05 & notice of violation
MADSEN, Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/09/26 2pp 06914 305

--8011060676 Notice of violation from insp on 800902-05
* Region 4, Dallas, Office of the Director 80/09/19 1p. 06914 307

--8011060682 IE Insp Repts 80-313/80-16 & 80-368/80-16 on 800902-05 Noncompliance noted plant safety committee had not reviewed audit repts or associated audit finding repts for six of seven QA audits that were reviewed by inspector
GAOLARDO, J E ; JAUDON, J P ; HUNNICUTT, D M Region 4, Dallas, Office of the Director 80/09/19 8pp 06914 308

801140123 Forwards IE Circular 80-22 "Confirmation of Employee Qualifications." No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/02 1p 06963 203

8011060774 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting." No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/10, 1p. 06909:086

801110228 Ack receipt of 801010 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-313/80-16 & 80-368/80-16
MADSEN, Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch. 80/10/23 2pp 06944 052

--801110236 Responds to NRC 800926 ltr re violations noted in IE Insp Repts 80-313/80-16 & 80-368/80-16 Corrective actions QA procedures to be revised to clarify use of AFR
TRIMBLE, D C Arkansas Power & Light Co 80/10/10 3pp 06944 054

801170373 Forwards order for mod of License DPR-51 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl.
REID, R W. Operating Reactors Branch 4 80/10/24 2pp 06975 169.

8011280098 Responds to items of noncompliance noted in IE Insp Repts 80-313/80-12 & 80-368/80-12 on 770708-0809 & forwards full payment of civil penalties Corrective actions, notification method & evaluation log being used for both units
CAVANAUGH, W Arkansas Power & Light Co 80/11/12. 14pp. 07083, 246.

8011260272 Ack receipt of 800923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-313/80-15 & 80-368/80-15
MADSEN, Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch. 80/11/14 1p 07074 152

--8011260280 Responds to NRC 800903 ltr re violations noted in IE Insp Repts 80-313/80-15 & 80-368/80-15 Corrective actions Radiation Protection Procedure 1602 27 revised & addl radiation survey instruments provided w/specific directions
TRIMBLE, D C Arkansas Power & Light Co 80/09/25 2pp 07074 153

R Periodic operating reports & related correspondence

801140414 Forwards NPDES rept for third quarter 1980. Forwarding ltrs encl
TRIMBLE, D C Arkansas Power & Light Co. 80/11/06, 5pp 06911 001.

--801140416 NPDES rept for third quarter 1980
* Arkansas Power & Light Co 80/10/20. 15pp 06911 001

S Reportable occurrences, LERs & related correspondence

801110261 Forwards revised LER 80-012/03X-1
TRIMBLE, D C. Arkansas Power & Light Co 80/11/06 1p 06944:070.

--801110273 Revised LER 80-012/03X-1 on 800406, emergency feedwater supply valve CV-2667 failed to open Valve failed next day along w/emergency feedwater supply valve CV-2617. Caused by loose bolts securing actuator to valve.
SHIVELY, C N Arkansas Power & Light Co 80/11/07. 1p 06944:071

801170484 Forwards updated LER 80-011/03X-7
TRIMBLE, D. C. Arkansas Power & Light Co 80/11/10. 1p. 06975.058

--8011170489 Updated LER 80-011/03X-7, on 800401, IE Bulletin 79-14 review revealed 37 inoperable hangers Cause not stated. Hangers repaired or modified within time frame allowed by Tech Specs
BRAHLETT, L S Arkansas Power & Light Co 80/11/10. 3pp. 06975.059

8011180669 Forwards LER 80-038/03L-0
TRIMBLE, D C Arkansas Power & Light Co 80/11/11 1p. 06988, 256.

--8011180676 LER 80-038/03L-0 on 801013, during monthly surveillance testing of number one diesel generator, voltage regulator failed to respond to higher or lower signal. Caused by internal mechanical wear Regulator replaced.
BRAHLETT, L S Arkansas Power & Light Co 80/11/11 1p 06988, 257

8011210609 Forwards updated LER 79-010/01X-1
TRIMBLE, D C Arkansas Power & Light Co 80/11/17 1p. 07029 154.

--8011210626 Updated LER 79-010/01X-1 on 800714, during design review of main steam piping, piping restraints were discovered not designed for steam hammer transient forces resulting from sudden closure of main steam stop valves
SHIVELY, C N Arkansas Power & Light Co 80/11/17 4pp 07029:155

8011230316 Forwards LER 80-040/99X-0
TRIMBLE, D. C. Arkansas Power & Light Co 80/11/19 1p. 07068:324

--8011230380 LER 80-040/99X-0 on 801001, during routine plant tour, Rx bldg emergency hatch local leak rate test connections found untested. Caused by failure to specify connections on P&IDs, test procedures or checklists. Caps replaced.
BRAHLETT, L. S. Arkansas Power & Light Co 80/11/19. 2pp 07068:325

8011230469 Forwards revised LER 80-035/99X-1.
TRIMBLE, D C. Arkansas Power & Light Co. 80/11/21 1p 07068, 287

--8011230477 Revised LER 80-035/99X-1 on 800916, RB cooling units VCC-2C & 2D found partially plugged w/Asian clams Caused by live & dead clams in supply manifolds on svc water inlet to coolers. Clams removed by backflushing
COBBURN, T. Arkansas Power & Light Co 80/11/21 1p. 07068:288.

V Operator Examinations

BO11050463 Submits plans, schedules & commitments for meeting interim criteria for shift staffing in response to NRC 800731 ltr. Recent NRC requirements hinder until ability to conform to mandated changes in staffing levels.
TRIMBLE, D. C. Arkansas Power & Light Co 80/10/31 2pp 06894 040

DOCKET 30-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

BO11180194 Requests revision to responsibility matrix of security plan & response to NRC 800630 request for addl info re plan interrelationship between decisionmaking & action-taking requires clarification. Response requested in 30 days.
VARQA, S. A. Operating Reactors Branch 1 80/10/31 2pp 06987 303

BO11190212 Confirms telcon & forwards identification info re NRC contractor BO1103-07 site visit to perform engineering analysis to identify vital areas at plant Encl withheld due to personnel info.
VARQA, S. A. Operating Reactors Branch 1 80/10/31 2pp 07000 035

Q Adjudicatory correspondence

BO1110431 Forwards orders for mod of Licenses DPR-58 & DPR-74 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
VARQA, S. A. Operating Reactors Branch 1 80/10/24 2pp 06944 247

--BO1110439 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201.
EISENHUT, D. O. Division of Licensing 80/10/24 6pp 06944 249

--BO1110445 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 3pp 06944 235

--BO1110451 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201.
EISENHUT, D. O. Division of Licensing 80/10/24 6pp 06944 257

--BO1110457 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 3pp 06944.263

P. Operating license stage documents & correspondence

BO11050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements. Provides summary listing of all approved TH1-2 related requirements.
EISENHUT, D. O. Division of Licensing 80/09/03 209pp

BO11100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D. O. Division of Licensing 80/10/01 5pp

BO11060214 Forwards Amends 42 & 24 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability.
VARQA, S. A. Operating Reactors Branch 1 80/10/06 3pp. 06912:033.

--BO11060222 Amends 42 & 24 to Licenses DPR-58 & DPR-74, respectively, adding locked or secured valves to surveillance requirements of valves in auxiliary feedwater sys.
VARQA, S. A. Operating Reactors Branch 1 80/10/06 10pp. 06912:036

--BO11060232 Safety evaluation supporting Amends 42 & 24 to Licenses DPR-58 & DPR-74, respectively.
* Office of Nuclear Reactor Regulation, Director 80/10/06. 13pp. 06912.046.

--BO11060241 Notices of issuance & availability of Amends 42 & 24 to Licenses DPR-58 & DPR-74, respectively.
VARQA, S. A. Operating Reactors Branch 1 80/10/06. 2pp. 06912:061

BO11100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issues A-12. "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports" w/o encl.
EISENHUT, D. O. Division of Licensing 80/10/06 6pp

BO1110431 Forwards orders for mod of Licenses DPR-58 & DPR-74 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
VARQA, S. A. Operating Reactors Branch 1 80/10/24 2pp 06944 247

--BO1110439 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201.
EISENHUT, D. O. Division of Licensing 80/10/24 6pp 06944 249

--BO1110445 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 3pp 06944 235

BO11210443 Forwards request for addl info generated from review of "Asymmetric LOCA Loading," WCAP-9628 & 9748, dtd Nov 1979 & June 1980, respectively.
LAINAS, G. C. Assistant Director for Safety Assessment 80/10/29 27pp

BO11140636 Forwards request for addl info re auxiliary feedwater automatic initiation & flow indication sys. Written response required by 801201.
VARQA, S. A. Operating Reactors Branch 1 80/10/31 3pp 06963 257

BO11170735 Informs that 791114 response re inadvertent safety injection during surveillance testing adequately addresses concerns stated in NRC 790921 ltr. Matter considered resolved.
VARQA, S. A. Operating Reactors Branch 1 80/10/31 2pp 06977.284

BO11100394 Forwards responses to questions contained in Encl 2 to DQ Eisenhut 791030 ltr re flow design basis of auxiliary feedwater sys.
HUNTER, R. S. Indiana & Michigan Electric Co 80/11/03 16pp 06928 318

BO11180426 Forwards info re environ qualification testing programs voluntarily supplied per NRC 801001 ltr.
HUNTER, R. S. Indiana & Michigan Electric Co 80/11/12 2pp 06989 089

Q Inspection reports, IE Bulletins & correspondence

BO11070270 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/24 1p 06921:264

BO1110431 Forwards orders for mod of Licenses DPR-58 & DPR-74 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
VARQA, S. A. Operating Reactors Branch 1 80/10/24 2pp

--BO1110439 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201.
EISENHUT, D. O. Division of Licensing 80/10/24 6pp 06944-249.

--BO1110445 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 3pp 06944 235

BO11170557 Updates NRC 800903 ltr re site access of Region 3 personnel to facilities. All NRC personnel & contractors are being issued new photo identification badges. Examples encl.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/28 3pp. 06978.001.

BO11200005 Forwards revised second set of responses to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," to 800829 order for mod of license revised in 800919 ltr & to IE Bulletin 79-018 Suppls 2 & 3.
MALONEY, G. P. Indiana & Michigan Electric Co 80/10/31 65pp. 07015.201

DOCKETED ITEMS

801110017 Ack receipt of 801022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-315/80-14 & 80-316/80-13
HIND, J A Region 3, Chicago, Safeguards Branch 80/11/03 1p
06943-249

--801110023 Responds to NRC 800911 ltr re violations noted in IE Insp Repts 80-315/80-14 & 80-316/80-13 Corrective actions withheld (ref 10CFR2 90)
HUNTER, R B Indiana & Michigan Electric Co 80/10/22 2pp
06943-280

R Periodic operating reports & related correspondence

8011180615 Forwards monthly operating rept for Oct 1980
SHALLER, D V Indiana & Michigan Electric Co 80/11/12 1p
06988-126

--8011180625 Monthly operating rept for Oct 1980
GILLET, W T Indiana & Michigan Electric Co 80/11/04 6pp
06988-127

V Operator Examinations

8011140095 Forwards present shift staffing requirements, plans, schedules & commitments to meet interim criteria by 820701, per NRC 800731 request
HUNTER, R B Indiana & Michigan Electric Co 80/11/07 4pp
06965-005

DOCKET 80-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8011180194 Requests revision to responsibility matrix of security plan & response to NRC 800630 request for addl info re plan interrelationship between decisionmaking & action-taking requires clarification Response requested in 30 days
VARQA, B A Operating Reactors Branch 1 80/10/31 2pp 06987-303

8011190212 Confirms telcon & forwards identification info re NRC contractor 801103-07 site visit to perform engineering analysis to identify vital areas at plant Encl withheld due to personnel info
VARQA, B A Operating Reactors Branch 1 80/10/31 2pp 07000-035

Q Adjudicatory correspondence

801110431 Forwards orders for mod of Licenses DPR-5B & DPR-74 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, B A Operating Reactors Branch 1 80/10/24 2pp. 06944-247

--801110451 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp. 06944-257

--801110457 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 3pp 06944-263

P Operating license stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D G Division of Licensing 80/10/01 5pp.

8011060214 Forwards Amends 42 & 24 to Licenses DPR-5B & DPR-74, respectively, safety evaluation & notice of issuance & availability
VARQA, B A. Operating Reactors Branch 1. 80/10/06. 3pp. 06912-033

--8011060222 Amends 42 & 24 to Licenses DPR-5B & DPR-74, respectively, adding locked or secured valves to surveillance requirements of valves in auxiliary feedwater sys
VARQA, B A Operating Reactors Branch 1 80/10/06 10pp.
06912-036

--8011060232 Safety evaluation supporting Amends 42 & 24 to Licenses DPR-5B & DPR-74, respectively
* Office of Nuclear Reactor Regulation, Director 80/10/06 19pp 06912-046

--8011060241 Notices of issuance & availability of Amends 42 & 24 to Licenses DPR-5B & DPR-74, respectively
VARQA, B A Operating Reactors Branch 1 80/10/06 2pp
06912-061

8011100937 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

801110431 Forwards orders for mod of Licenses DPR-5B & DPR-74 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, B A Operating Reactors Branch 1 80/10/24 2pp

--801110451 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201.
EISENHUT, D G Division of Licensing. 80/10/24 6pp. 06944-257.

--801110457 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 3pp. 06944-263.

8011210443 Forwards request for addl info generated from review of "Asymmetric LOCA Loading," WCAP-9628 & 9748, dtd Nov 1979 & June 1980, respectively
LAINAS, G C Assistant Director for Safety Assessment 80/10/29, 27pp

8011140636 Forwards request for addl info re auxiliary feedwater automatic initiation & flow indication sys. Written response required by 801201
VARQA, B A Operating Reactors Branch 1 80/10/31 3pp 06963-257

8011170735 Informs that 79114 response re inadvertent safety injection during surveillance testing adequately addresses concerns stated in NRC 790921 ltr. Matter considered resolved.
VARQA, B A Operating Reactors Branch 1. 80/10/31 2pp. 06977-284

8011100394 Forwards responses to questions contained in Encl 2 to D0 Eisenhut 791030 ltr re flow design basis of auxiliary feedwater sys
HUNTER, R B Indiana & Michigan Electric Co. 80/11/03. 16pp.
06928-318

8011180426 Forwards info re environ qualification testing programs voluntarily supplied per NRC 801001 ltr
HUNTER, R B Indiana & Michigan Electric Co 80/11/12. 2pp
06989-089.

Q Inspection reports, IE Bulletins & correspondence

8011070270 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
KEPLER, J O. Region 3, Chicago, Office of the Director 80/10/24, 1p 06921-264.

801110431 Forwards orders for mod of Licenses DPR-5B & DPR-74 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, B A. Operating Reactors Branch 1 80/10/24. 2pp.

--801110451 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201.
EISENHUT, D G Division of Licensing 80/10/24. 6pp.

--801110457 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing. 80/10/24 3pp.

801110337 Updates NRC 800903 ltr re site access of Region 3 personnel to facilities All NRC personnel & contractors are being issued new photo identification badges Examples encl
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/28 3pp 06978-001

801120005 Forwards revised second set of responses to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," to 800829 order for mod of license revised in 800919 ltr & to IE Bulletin 79-018 Suppls 2 & 3
MALONEY, O. P. Indiana & Michigan Electric Co 80/10/31 45pp 07015.201

801110019 Ack receipt of 801022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-315/80-14 & 80-316/80-13
HIND, J. A. Region 3, Chicago, Safeguards Branch, 80/11/03 1p 06943.249

--801110023 Responds to NRC 800911 ltr re violations noted in IE Insp Repts 80-315/80-14 & 80-316/80-13. Corrective actions withheld (ref 10CFR2 90).
HUNTER, R. B. Indiana & Michigan Electric Co 80/10/22 2pp. 06943:250

R Periodic operating reports & related correspondence

801180641 Forwards monthly operating rept for Oct 1980.
SMALLER, D. V. Indiana & Michigan Electric Co. 80/11/12 1p. 06988 135.

--801180657 Monthly operating rept for Oct 1980
OILLETT, W. T. Indiana & Michigan Electric Co. 80/11/04 7pp. 06988:136

V. Operator Examinations

801140095 Forwards present shift staffing requirements, plans, schedules & commitments to meet interim criteria by 820701, per NRC 800731 request
HUNTER, R. B. Indiana & Michigan Electric Co 80/11/07 4pp 06965.005

DOCKET 80-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

801106065 Forwards comments on emergency plan submitted June 1980 Requests addl info & commitments required to meet criteria in NUREG-0654, effective 801103. Plan should be revised within 60 days.
CLARK, R. A. Operating Reactors Branch 3 80/10/24. 24pp. 06911:169.

801170274 Notifies of Commission approval of revised final version of proposed rule containing schedules for completion for fire protection mods. Interim rule on encl FR notice suspends completion dates for fire protection mods.
EISENHUT, D. G. Division of Licensing. 80/10/31. 5pp. 06978.281.

G Adjudicatory correspondence

801107097 Forwards order for mod of Licenses DPR-53 & DPR-69 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
CLARK, R. A. Operating Reactors Branch 3 80/10/24. 2pp. 06925:234

--8011070605 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactor guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201.
EISENHUT, D. G. Division of Licensing. 80/10/24. 12pp. 06925.236.

--8011070611 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24. 2pp 06925:242

H. General correspondence

8011060468 Requests svc list be revised per encl list for plant correspondence.
CLARK, R. C. Baltimore Gas & Electric Co. 80/10/30. 2pp. 06912:264.

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D. G. Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D. G. Division of Licensing 80/10/01 3pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl.
EISENHUT, D. G. Division of Licensing. 80/10/06 6pp

8011030608 Forwards list of addl info needed to complete review of Cycle 5 reload 800922 request Info requested by 801031
CLARK, R. A. Operating Reactors Branch 3 80/10/16 4pp 06873 018.

8011060557 Summary of 801009 meeting w/util & C-E re delay in statistical combustion of uncertainties review as related to Cycle 5 relay review List of attendees, phase review & action schedule encl
NOVAK, T. H. Assistant Director for Operating Reactors. 80/10/20 6pp. 06916.187

8011030108 Forwards request for addl info re FIESTA code contained in CEN-133 re Cycle 5 reload
CLARK, R. A. Operating Reactors Branch 3 80/10/24. 3pp 06857:154

8011070397 Forwards order for mod of Licenses DPR-53 & DPR-69 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CLARK, R. A. Operating Reactors Branch 3. 80/10/24. 2pp 06925:234

--8011070605 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactor guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D. G. Division of Licensing 80/10/24 12pp 06925 236

--8011070611 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing. 80/10/24 2pp 06925 242.

8011060210 Notification of 801112 meeting w/util in Bethesda, MD to discuss Cycle 5 reload analysis.
LI, C. Y. Operating Reactors Branch 3 80/10/27 2pp 06912 067.

8011030522 Forwards responses to NRC questions re amend to License DPR-53, fifth cycle license application
LUNDVALL, A. E. Baltimore Gas & Electric Co 80/10/31. 7pp 06861:132

8011050416 Forwards responses to NRC questions concerning application to amend License DPR-53 to support fifth cycle operation.
LUNDVALL, A. E. Baltimore Gas & Electric Co 80/11/01 2pp. 06894:115.

8011050328 Forwards proprietary & nonproprietary info in response to NRC questions re amend to License DPR-53, fifth cycle license application Affidavit encl Proprietary info withheld (ref 10CFR2.790)
LUNDVALL, A. E. Baltimore Gas & Electric Co 80/11/02 36pp 06893 323

--8011050331 Nonproprietary version of "Calvert Cliffs Unit 1 Cycle 5 NRC Reload Questions Response - Answers on CESEC Model Used in SLB Analysis"
* Combustion Engineering, Inc 80/10/31. 15pp 06894:001

8011050488 Forwards proprietary & nonproprietary responses to NRC questions re application to amend License DPR-53 to support fifth cycle operation Affidavit for withholding info (ref 10CFR2 790) encl
LUNDVALL, A. E. Baltimore Gas & Electric Co 80/11/03 21pp 06897.011.

801170276 Forwards request for addl info for Cycle 5 reload review Response should be submitted by 801107
CLARK, R. A. Operating Reactors Branch 3 80/11/03 5pp. 06978:286

DOCKETED ITEMS

8011050506 Forwards Suppl 1 to application for amend of License DPR-53 to allow fifth cycle operation Safety analyses ensure conservative operation at rated thermal power of 2,700 MWT
LUNDVALL, A E Baltimore Gas & Electric Co 80/11/04 2pp 06896 167

--8011050510 Suppl 1 to application for amend of License DPR-53 to allow fifth cycle operation
* Baltimore Gas & Electric Co 80/11/04 82pp 06896 167

--8011050515 Proposed Tech Specs, Sections 2, 3, 4 & 5 to allow fifth cycle operation
* Baltimore Gas & Electric Co 80/11/04 27pp 06896 252

8011200075 Forwards request for addl info re containment sump & insulation for operating reactors Requests info be provided within 90 days
CLARK, R A Operating Reactors Branch 3 80/11/04 4pp 07018 137

8011140201 Application to amend Licenses DPR-53 & DPP-69, changing Tech Specs re emergency power supply requirements, value position indication, instrumentation for adequate core cooling & containment isolation W/o proposed Tech Specs.
LUNDVALL, A E Baltimore Gas & Electric Co 80/11/10 3pp 06961 275

8011140208 Forwards responses to NRC questions re application for amend of License DPR-53 re fifth cycle operation
LUNDVALL, A E Baltimore Gas & Electric Co 80/11/10 4pp 06961 282

8011140205 Forwards responses to NRC questions re application for amend to License DPR-53 re fifth cycle operation
LUNDVALL, A E Baltimore Gas & Electric Co 80/11/11 4pp 06961 278

8011260219 Forwards request for addl info for review of 800922 Cycle 5 reload request Response required by 801119 to meet review completion schedule
CLARK, R A Operating Reactors Branch 3 80/11/14 7pp 07074 084

8011240134 Forwards responses to NRC questions re application for amend to License DPR-53 re fifth cycle operation.
LUNDVALL, A E Baltimore Gas & Electric Co 80/11/18 26pp 02227 001

8011250307 Submit info re auxiliary feedwater sys. per NRC requirements. Three oversize drawings encl
LUNDVALL, A E Baltimore Gas & Electric Co 80/11/18 4pp 07068 292

--8011250311 "P&ID Auxiliary Feedwater Sys. Unit 1, Modified Design"
* Bechtel Power Corp (subs. of Bechtel Corp.) 4750 80/11/07 1p

--8011250315 "Auxiliary Feedwater Actuation Sys (AFAS), Unit 1, Logic Diagram," Sheet 1 of 2
* Bechtel Power Corp (subs. of Bechtel Corp.) 11865 80/10/17 1p

--8011250317 "Auxiliary Feedwater Actuation Sys (AFAS), Unit 1, Logic Diagram," Sheet 2 of 2
* Bechtel Power Corp (subs. of Bechtel Corp.) 11865 80/10/17 1p

8011210271 Forwards response to NRC questions re application to amend License DPR-53 re fifth cycle operation info includes startup test program, asymmetric steam generator trip instrumentation & thermal margin/low pressure trip setpoint
LUNDVALL, A E Baltimore Gas & Electric Co 80/11/19 31pp 07035 050

8011260270 Nonproprietary version of "Response to Request for Addl Info on Calvert Cliffs 1 Cycle 5 Licensing Submittal"
Notarized affidavit included
* Combustion Engineering, Inc. CEN-144(B)-NP 80/11/19 23pp 07075 299

G. Inspection reports, IE Bulletins & correspondence

8011070098 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/09/30 1p 06924 324

8011250663 Forwards IE Insp Repts 80-317/80-14 & 80-318/80-13 No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/02 2pp 07036 012

--8011250673 IE Insp Repts 80-317/80-14 & 80-318/80-13 on 800801-31, No noncompliance noted Major Areas inspected control room, portions of auxiliary, turbine, svc & intake bldgs, physical security & radiation protection
ARCHITZEL, R E, GASSANI, A Region 1, Philadelphia, Office of the Director MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/01 14pp 07036 014

8011060649 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06909 341

8011070305 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/10/24 1p 06921 340

8011140277 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06968 241

8011170111 Updates 800527 response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" Fisher & Porter Transmitters & ABCO solenoid valves will be replaced. Records re Class IE items maintained separately
LUNDVALL, A E Baltimore Gas & Electric Co 80/10/31 200pp 06915 001

8011170901 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp" No written response is required.
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/10/31 1p 06981 229

8011260056 Responds to NRC 801023 ltr re util 800821 response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power." Info resubmitted under oath of affirmation.
LUNDVALL, A E Baltimore Gas & Electric Co 80/10/31 2pp 07070 331

8011200148 Provides addl info re IE Bulletin 80-11 Two temporary walls removed & another wall in auxiliary bldg will be removed & replaced w/design utilizing different fire barrier mats. Complete rept will be filed by 801019 Bechtel comments encl.
LUNDVALL, A E Baltimore Gas & Electric Co 80/11/06 49pp 07021 136

8011190358 Responds to EL Conner request re summary of findings on Unit 1 reactor coolant pump studs per IE Notice 80-27 Insp of four pumps reveals that 27 of 64 studs have indications of corrosion or flaws due to pump venting techniques.
ASH, R. F. Baltimore Gas & Electric Co. 80/11/13 3pp 06999 357.

R. Periodic operating reports & related correspondence

8011000045 Forwards rept of changes, tests & experiments completed on facilities covering period from last rept through 791231
LUNDVALL, A E Baltimore Gas & Electric Co 80/11/03 4pp 06916 001

8011240319 Forwards monthly operating repts for Oct 1980.
MERBON, B D Baltimore Gas & Electric Co 80/11/13 1p 07050 125

--8011240324 Monthly operating repts for Oct 1980
MERBON, B D Baltimore Gas & Electric Co. 80/11/13 17pp 07050 126

S. Reportable occurrences, LERs & related correspondence

8011060489 Forwards LER 80-057/03L-0.
RUSSELL, L B Baltimore Gas & Electric Co 80/10/31 1p 06910 361.

--8011060490 LER 80-057/03L-0, on 801028, discovered auxiliary feedwater pump turbine 12 was tripped. Probably caused by personnel error. Personnel directed to stay clear of pumps.
LAGIENSKI, J S, ROBERSON, M E, Baltimore Gas & Electric Co. 80/10/31 1p 06910 362.

8011070332 Forwards LER 80-035/03L-0
RUBBELL, L. B. Baltimore Gas & Electric Co. 80/10/31 1p
06918 215

--8011070336 LER 80-035/03L-0, on 801001, during normal operation
containment atmosphere particulate RMS detector failed On
801008, channel failed again Caused by water inside sampler
wetting detector & connector & broken signal lead
WENDERLICH, R. L., RIZZO, P. G. Baltimore Gas & Electric Co.
80/10/31. 2pp 06918 216

801140462 RD 80-49 on 801106, bus 21 4 kV not realigned to 500 kV black
bus after maint. resulting in continued supply from 500 kV
red bus. Caused by personnel oversight Generators 12 & 21 &
500 kV red bus verified
RUBBELL, L. B. Baltimore Gas & Electric Co. 80/11/07 2pp
06963:062

801140456 Forwards LER 80-039/03L-0
RUBBELL, L. B. Baltimore Gas & Electric Co. 80/11/11 1p
06963 060

--801140460 LER 80-039/03L-0, on 801011, unidentified RCS leakage exceeded
Tech Spec limit Caused by leaking motor operated valve
RC-405 Valve repacked
LADIEWSKI, J. B., HUBERY, D. E. Baltimore Gas & Electric Co.
80/11/11 1p. 06963, 061

8011210526 Forwards LER 80-060/03L-0.
RUBBELL, L. B. Baltimore Gas & Electric Co. 80/11/17 1p.
07029 244.

--8011210534 LER 80-060/03L-0, on 801018, surveillance testing found RC-200
& RC-201 lift setpoints to be 70 psi & 56 psi, respectively,
above max Tech Spec Cause not stated Setpoints adjusted
WENDERLICH, R. L., MIERNICKI, M. J. Baltimore Gas & Electric Co.
80/11/17. 2pp. 07029 245

8011240468 PND-I-80-166, on 801116, plant emergency declared upon receipt
of radiation alarm during transfer of spent resin from
deborating ion exchanger. Caused by partially open discharge
valve. Max noble gas release was 9% of limit.
MCCABE, E. C., KNAPP, P. J., BRUNNER, E. J. Region 1, Philadelphia, Office
of the Director. 80/11/17 1p 07039 257

V. Operator Examinations

8011030526 Responds to 800731 interim criteria for shift staffing.
Two senior operator license holders assigned to shift
during operation of one or both units per 800731 criteria
LUNDVALL, A. E. Baltimore Gas & Electric Co. 80/10/27. 1p.
06855 032

DOCKET 80-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8011060063 Forwards comments on emergency plan submitted June 1980.
Requests addl info & commitments required to meet criteria
in NUREG-0654, effective 801103 Plan should be revised
within 60 days.
CLARK, R. A. Operating Reactors Branch 3. 80/10/24. 24pp
06911.169

801170274 Notifies of Commission approval of revised final version of
proposed rule containing schedules for completion for fire
protection mods. Interim rule on encl FR notice suspends
completion dates for fire protection mods.
EISENHUT, D. O. Division of Licensing. 80/10/31. 5pp 06978:281.

G. Adjudicatory correspondence

8011070897 Forwards order for mod of Licenses DPR-53 & DPR-69 re
environ qualification of safety-related electrical
equipment Revised Tech Specs also encl
CLARK, R. A. Operating Reactors Branch 3. 80/10/24. 2pp 06925:234.

--8011070605 Order for mod of license re environ qualification of safety-
related electrical equipment. Compliance w/Div of Operating
Reactor guidelines or NUREG-0588 required by 820630. Complete
records must be available by 801201.
EISENHUT, D. O. Division of Licensing. 80/10/24 12pp. 06925:236.

--8011070611 Revised Tech Spec pages per 801024 order for mod of license
re environ qualification of safety-related electrical
equipment.
* Division of Licensing. 80/10/24. 2pp. 06925:242.

H General correspondence

8011060468 Requests svc list be revised per encl list for plant
correspondence
OLSON, R. C. Baltimore Gas & Electric Co. 80/10/30 2pp 06912 264

P Operating license stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TMI action
plan requirements Provides summary listing of all approved
TMI-2 related requirements
EISENHUT, D. O. Division of Licensing 80/07/05 209pp

8011040486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs Info needed by 801101
EISENHUT, D. O. Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D. O. Division of Licensing 80/10/06 6pp

8011070597 Forwards order for mod of Licenses DPR-53 & DPR-69 re
environ qualification of safety-related electrical
equipment Revised Tech Specs also encl.
CLARK, R. A. Operating Reactors Branch 3 80/10/24. 2pp

--8011070605 Order for mod of license re environ qualification of safety-
related electrical equipment Compliance w/Div of Operating
Reactor guidelines or NUREG-0588 required by 820630.
Complete records must be available by 801201
EISENHUT, D. O. Division of Licensing 80/10/24. 12pp

--8011070611 Revised Tech Spec pages per 801024 order for mod of license
re environ qualification of safety-related electrical
equipment.
* Division of Licensing. 80/10/24 2pp

8011200075 Forwards request for addl info re containment sump &
insulation for operating reactors Requests info be provided
within 90 days.
CLARK, R. A. Operating Reactors Branch 3 80/11/04 4pp 07018:137

801140201 Application to amend Licenses DPR-53 & DPR-69, changing
Tech Specs re emergency power supply requirements, valve
position indication, instrumentation for adequate core
cooling & containment isolation W/o proposed Tech Specs
LUNDVALL, A. E. Baltimore Gas & Electric Co. 80/11/10. 3pp
06961 275.

8011250307 Submits info re auxiliary feedwater sys. per NRC
requirements Three oversize drawings encl.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 80/11/18 4pp
07068, 292

--8011250311 "P&ID Auxiliary Feedwater Sys. Unit 1, Modified Design."
* Bechtel Power Corp. (subs of Bechtel Corp.) 6750 80/11/07.
1p

--8011250315 "Auxiliary Feedwater Actuation Sys (AFAS), Unit 1, Logic
Diagram " Sheet 1 of 2
* Bechtel Power Corp (subs of Bechtel Corp.). 11865 80/10/17.
1p.

--8011250317 "Auxiliary Feedwater Actuation Sys (AFAS), Unit 1, Logic
Diagram," Sheet 2 of 2
* Bechtel Power Corp. (subs of Bechtel Corp.). 11865. 80/10/17.
1p

Q Inspection reports, IE Bulletins & correspondence

8011070058 Forwards Suppl 2 to IE Bulletin 79-018, "Environ
Qualification of Class IE Equipment." No written response
required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
80/09/30. 1p 06924.324

8011250663 Forwards IE Insp Repts 80-317/80-14 & 80-318/80-13, No
noncompliance noted.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch. 80/10/07 2pp 07056.012.

DOCKETED ITEMS

--8011290675 IE Insp Repts 80-317/80-14 & 80-318/80-13 on 800801-31 No noncompliance noted Major areas inspected control room, portions of auxiliary, turbine, svc & intake bldgs, physical security & radiation protection
ARCHITZEL, R E., SASSANI, A Region 1, Philadelphia, Office of the Director
MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/01 14pp 07056 014

8011060649 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06909 341

8011070305 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06921 340

801140277 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06968 241

8011170111 Updates 800927 response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " Fisher & Porter Transmitters & ASCU solenoid valves will be replaced Records re Class IE items maintained separately
LUNDVALL, A E Baltimore Gas & Electric Co 80/10/31 200pp
06915 001

8011170901 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06981 229

8011260056 Responds to NRC 801023 ltr re util 800821 response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power " Info resubmitted under oath of affirmation
LUNDVALL, A E Baltimore Gas & Electric Co 80/10/31 2pp
07070 351

8011200148 Provides addl info re IE Bulletin 80-11 Two temporary walls removed & another wall in auxiliary bldg will be removed & replaced w/design utilizing different fire barrier mats
Complete rept will be filed by 80109 Bchtel comments encl
LUNDVALL, A E Baltimore Gas & Electric Co 80/11/06 49pp
07021 156

R Periodic operating reports & related correspondence

8011100945 Forwards rept of changes, tests & experiments completed on facilities covering period from last rept through 791231
LUNDVALL, A E Baltimore Gas & Electric Co 80/11/05 4pp
06916 001

8011240319 Forwards monthly operating repts for Oct 1980
MERSON, S D Baltimore Gas & Electric Co 80/11/13 1p 07050 125

--8011240324 Monthly operating repts for Oct 1980
MERSON, S D Baltimore Gas & Electric Co 80/11/13 17pp
07050 126

S Reportable occurrences, LERs & related correspondence

8011070405 Forwards LER 80-058/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 80/11/04 1p
06918 124

--8011070410 LER 80-058/03L-0 on 801021, during Mode 1, control room air conditioning Unit 12 tripped Air temp remained within design limit of 120 degrees Caused by normal temp control action
Proposed mod will add indications to determine trip type
WENDERLICH, R L, RIZZO, P G Baltimore Gas & Electric Co 80/11/04 1p 06918 125

8011100452 Forwards LER 80-058/01T-1
RUSSELL, L B Baltimore Gas & Electric Co 80/11/05 1p
06929 319

--8011100453 LER 80-058/01T-1 on 801021, control room air conditioning Unit 12 tripped while unit 11 was out of svc Caused by normal temp control action Proposal for mod underway
WENDERLICH, R L, RIZZO, P G Baltimore Gas & Electric Co 80/11/05 1p 06916 001

8011140462 RO 80-49 on 801106, bus 21 4 kV not realigned to 500 kV black bus after maint, resulting in continued supply from 500 kV red bus Caused by personnel oversight Generators 12 & 21 & 500 kV red bus verified
RUSSELL, L B Baltimore Gas & Electric Co 80/11/07 2pp
06963 062

8011180634 Forwards LER 80-047/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 80/11/14 1p
06988 238

--8011180662 LER 80-047/03L-0 on 801014, during normal operation, containment RMB pump failed resulting in loss of gaseous & particulate radiation monitors Caused by normal end of life failure Pump removed from svc & replaced
* Baltimore Gas & Electric Co 80/11/14, 1p 06988 239

8011190416 Forwards LER 80-045/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 80/11/17 1p
06998 074

--8011190421 LER 80-045/03L-0 on 801017, failure of CTMT particulate radioactivity detector discovered Caused by open termination within connector assembly for detector due to age & handling Open lead repaired
WENDERLICH, R L, RIZZO, P G Baltimore Gas & Electric Co 80/11/17 2pp 06998 075

8011250360 Forwards LER 80-048/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 80/11/19 1p
07055 091

--8011250363 LER 80-048/03L-0 on 801019, during withdrawal of control element assemblies to control axial shape index, assemblies dropped into core Cause unknown Review of control element assembly drop occurrences is underway.
LAZIENSKI, J S, RIZZO, P G Baltimore Gas & Electric Co 80/11/19 1p 07056 092

8011260183 Forwards LER 80-049/01T-0
RUSSELL, L B Baltimore Gas & Electric Co 80/11/20 1p
07074 337

--8011260184 LER 80-049/01T-0 on 801106, buses 21 & 24 4kV both found powered off 500 kV red bus for 13-h w/o performance of periodic demonstration of operability of remaining ac sources per Tech Specs Caused by operator error
WENDERLICH, R L Baltimore Gas & Electric Co 80/11/20 2pp
07074 338

V Operator Examinations

8011030526 Responds to 800731 interim criteria for shift staffing
Two senior operator license holders assigned to shift during operation of one or both units per 800731 criteria
LUNDVALL, A E Baltimore Gas & Electric Co 80/10/27, 1p
06855 032

DOCKET 80-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8011170017 Forwards facility emergency planning info for placement in LPDR w/o encl.
BOUDER, J L Division of Rules and Records 80/11/04, 1p
06978 267

G Adjudicatory correspondence

8011120038 Responds to 791129 ltr transmitting 791120 resolution opposing proposed release of Kr-85 from facility NRC evaluations conclude that purging method is quickest & safest No significant environ impact will result
BIVDER, B J TMI Program Office 80/10/28 2pp, 06953 239

--801120044 Submits 791120 resolution opposing util proposal to release Kr-85 into atmosphere
CLEMENS, H W Newberry Township, York Haven, PA, 79/11/29 1p, 06953 241

8011250009 Informs that final regulations discussed in HJ Miller 800226-27 testimony published in 801003 FR & that Kern-McOee filed petition for review on 801003 to have regulations declared invalid
BORDENICK, B M Hearing Branch 4, 80/11/19 3pp, 07056, 163.

DOCKETED ITEMS

121

8011260020 Notice of issuance of amend to 800211 order to provide for use of mini decay heat removal sys Requests proposed Tech Specs be formally modified in accordance w/order
CHANDLER, L J Hearing Branch 1 80/11/20 2pp 07074 157

--8011260023 Forwards order deleting operability requirements for certain balance-of-plant sys & adding operability requirements for mini decay heat removal sys. safety evaluation & proposed Tech Specs
SNYDER, B J TMI Program Office 80/11/14 4pp 07074 159

--8011260027 Order amending 800211 order to provide for use of mini decay heat removal sys
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/11/14 11pp 07074 163

--8011260031 Safety evaluation supporting mod of 800211 order by providing for use of mini decay heat removal sys
* Office of Nuclear Reactor Regulation, Director 80/11/14 11pp 07074 174

--8011260034 Proposed Tech Specs Pages 3 1-1,3 1-2,3 4-1,3 7-1,3 7-2, 3 8-4, B 3/4 4-1 & B 3/4 7-1 providing for use of mini decay heat removal sys Certificate of Svc encl
* Office of Nuclear Reactor Regulation, Director 80/11/14 29pp 07074 185

H General correspondence

8011060200 Responds to 800824 ltr re restart of TMI-1, Unit 2 cleanup schedule & licensing of new nuclear facilities Public hearing on restart will be conducted Summary of NUREG-0683 not encl
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/09/22 1p. 02319 176

--8011060206 Requests info re restart of TMI-1, Unit 2 cleanup schedule & licensing of new nuclear facilities
RUTHRAUFF, F R , RUTHRAUFF, M B Affiliation Unknown. 80/08/24 1p 02319 176

8010240636 Responds to encl 800329 telegram to President Carter alleging NRC has responded inadequately to TMI accident
Licenses of all operating plants have been instructed to take specific actions
SNYDER, B J. TMI Program Office 80/10/06 3pp 06799 194

801040102 Responds to 800430 ltr to President Carter re purging of radioactive krypton gas NRC concluded that purging method is quickest & safest for workers at facility NUREG-0662, Vol 1 & 2, 800612 memorandum & order encl W/o encl
SNYDER, B J TMI Program Office, 80/10/16 7pp 02319 196.

801040108 Responds to encl ltr to President Carter re effects of radiation from facility. Preparation of rept on possible health effects resulting from operation &/or accident underway
SNYDER, B J. TMI Program Office 80/10/16 4pp. 02319 196

801190659 Responds to 800914 ltr re release of radioactive matl from station & shutdown Forwards copy of programmatic EIS, NUREG-0662, Vol 1 & 2 & 800612 order for temporary mod of license W/o encl.
SNYDER, B. J TMI Program Office 80/10/16 3pp 07001 230

--801190664 Registers objections to party responsible for ordering radioactive gases or water released into atmosphere & Susquehanna River from plant All facts re accident have not been revealed to public Demands objections be honored
PARSONS, G H. Affiliation Unknown 80/09/14 2pp 07001:233

801190678 Responds to ltr expressing concern re purging radioactive krypton gas from reactor bldg. Forwards NUREG-0662, programmatic EIS & 800612 order for temporary mod of license W/o encl
SNYDER, B. J. TMI Program Office 80/10/16. 4pp. 07001 236

--801190684 Demands cessation of release of radioactive gases & use of EPICOR-II Suggests alternatives to nuclear power & will no longer vote for any pro-nuclear representative
STULL, J. E Affiliation Unknown 79/09/01 2pp. 07001-240

--801190690 Demands revocation of license. Suggests NRC is aware of nuclear dangers. Will no longer support any pro-nuclear official
STULL, J. E. Affiliation Unknown. 79/08/09 1p. 07001 242

8011040075 Provides comments re release of radioactive krypton gas, radwaste disposal & health effect associated w/radiation exposure
BULHART, B A Affiliation Unknown 80/03/29 1p 06874 120

8011040070 Responds to 800329 ltr re effect of accident Draft Programmatic EIS, NUREG-0662 Vols 1 & 2, 800612, memorandum & orders, summaries of NUREG-0668 & 0958 & press release encl W/o encl
SNYDER, B J TMI Program Office 80/10/20 4pp 06874, 116

8011060208 Responds to 790912 ltr re cleanup operations & release of radwaste at facility NRC has evaluated alternative methods for disposal of Kr-B5 to determine what effect decontamination would have on public health & safety
SNYDER, B J TMI Program Office 80/10/20 3pp 06915 318

--8011060213 Expresses concern re release of radwaste from facility & physical & psychological effect on residents Requests facility be shut down
FRIED, D Affiliation Unknown 79/09/12 1p 06915 321

8011060221 Responds to 791130 ltr to HR Denton re release of Kr-B5 NRC has evaluated alternative methods for disposal of Kr-B5 to determine what effect decontamination would have on public health & safety & environ
SNYDER, B J TMI Program Office 80/10/20 2pp 06915:315

8011060237 Responds to 791212 ltr to President Carter re release of Kr-B5 NRC has evaluated alternative methods for disposal of Kr-B5 to determine what effect decontamination would have on public health & safety & environ
SNYDER, B J TMI Program Office 80/10/20 2pp 06915 307

--8011060249 Forwards related memo & 791212 ltr to President Carter re release of Kr-B5 from facility Requests response
RATHKOPF, C L Energy, Dept of 80/01/25 3pp 06915 309

8011060319 Responds to ltr re environ assessment of disposal of radioactive water from facility Only low or nondetectable levels of radioactivity are permitted to be released EPICOR-II processed water is not released
SNYDER, B J TMI Program Office 80/10/20 2pp 06915 291

--8011060321 Requests full environ impact study be performed re disposal of radioactive water from facility Alternatives to EPICOR-II should be explored Requests assurance that no radwaste is released to environ
LUTA, V R Affiliation Unknown 80/11/03 1p 06915 293

8011060611 Responds to 791210 ltr to President Carter re release of Kr-B5 Alternative methods for releasing Kr-B5 have been evaluated by util & NRC to determine what effect decontamination would have on public health & safety
SNYDER, B J TMI Program Office 80/10/20 2pp 06915 274

--8011060617 Forwards TJ Lyng 791210 ltr to President Carter for response to comments re release of Kr-B5 into atmosphere Related memo & ltr encl
RATHKOPF, C. L. Energy, Dept of 80/01/25 4pp 06915 276

8011070168 Responds to 790803 ltr to President Carter & NRC re release of radwaste from facility NRC has evaluated alternative methods for disposal of Kr-B5 to determine what effect decontamination would have on public health
SNYDER, B J TMI Program Office 80/10/20 3pp 06918 264.

--8011070173 Expresses concern re release of radwaste from facility, util mishandling of problem & NRC pro-nuclear position Related ltr & 790803 ltr to President Carter encl
FEEHRER, J. Affiliation Unknown 79/08/03 4pp 06918 267

8011060704 Responds to 801013 ltr to JM Hendrie re facility release of radwaste & conversion from nuclear energy to coal NRC responsible for regulating nuclear power, not for making general decision as to whether nuclear power should be used
INGRAH, F Office of Public Affairs 80/10/21 1p 06915 257

--8011060709 Expresses opinion about situation at facility & effect on family Concerns include release of radwaste & why more coal-powered plants are not used in PA
AULTHOUSE, D L Affiliation Unknown 80/10/13 1p 06915 258

801100271 Responds to 790328 ltr expressing concern re release of radioactive noble gases from TMI-2 Kr-B5 has not released in any significant quantities due to relatively small amounts available for release
SNYDER, B. J TMI Program Office 80/10/21 1p 06916 001

DOCKETED ITEMS

01100234 Responds to 800731 ltr expressing concern re release of Kr-85 from TMI Potential health impact on public from use of any proposed strategies for removing Kr-85 is negligible.
SNYDER,B J TMI Program Office 80/10/24 2pp 06931 272

-801100238 Expresses concern re release of Kr-85 from TMI
WOLF,R Affiliation Unknown 80/07/31 2pp 06931 274

01100247 Responds to 800728 ltr expressing concern re NUREG-0698 NRC is establishing TMI-2 Advisory Panel consisting of state & local govt representatives, independent scientific community members & public
SNYDER,B J TMI Program Office 80/10/24 2pp 06916 001

-801100255 Comments on NUREG-0698 & expresses concern re membership of proposed TMI-2 advisory panel
LEWIS,M I Affiliation Unknown 80/07/28 2pp 06916 001

01100493 Responds to 790731 ltr expressing concern re effects of release of radioactive matl from TMI & effects on family
Potential physical health impact from krypton release is negligible
SNYDER,B J TMI Program Office 80/10/24 4pp 06914 001

001100510 Expresses concern re effects of release of radioactive matl from TMI & effect on family
HARTER,M R Affiliation Unknown 79/07/31 2pp 06916 001

11130167 Responds to encl 800329 ltr to President Carter re effects of radiation & release of radioactive matl from TMI
Potential physical health impact from using any of proposed strategies for Kr-85 is negligible
SNYDER,B J TMI Program Office 80/10/24 4pp 06936 336

1110626 Responds to encl 800324 ltr to President Carter urging govt supervision of cleanup operations NRC has authority to ensure protection of public health if util is unable to carry out responsibilities w/o encl programmatic EIS
SNYDER,B J TMI Program Office 80/10/28 4pp 06945 001

1110788 Forwards response to ltr to NRC requesting technical answers to questions re TMI
SNYDER,B J TMI Program Office 80/10/28 3pp 06948 013

1120017 Responds to 800304 ltr opposing release of Kr-85 from TMI
NRC evaluations conclude that purging method is quickest & safest No significant environ impact will result Conversion to coal-fired operation is util decision
SNYDER,B J TMI Program Office 80/10/28 2pp 06914 001

01120021 Ack receipt of NRC 800228 ltr TMI venting Opposes Kr-85 release Facility should be converted to coal operation.
HUGHES,C Affiliation Unknown 80/03/04 3pp 06916 001

1180922 Responds to ltr suggesting ways for decontaminating water at MI Programmatic EIS forwarded for comments w/o encl.
SNYDER,B J TMI Program Office 80/10/28 1p 06915 001.

01180524 Describes methods for decontaminating water at TMI
BOHTRAVER,A J Affiliation Unknown 80/10/28 3pp 06915 001.

1180112 Responds to 801010 ltr to President Carter re financial burden on util resulting from Mar 1979 facility accident
Statutory authority does not permit direct federal financial aid to assist in cleanup & recovery cost
ENTON,H R Office of Nuclear Reactor Regulation, Director 3/10/80 3pp 06992 139

01180119 Forwards 801010 ltr to President Carter requesting support of federal grants to relieve financial burden on util & customers by supporting NRC action for immediate facility restart
SEAL,M H President of US & Executive Offices 80/10/17 2pp 06992 142

170927 Responds to encl 800626 ltr to President Carter re venting -85 & health effects of accident NRC has evaluated alternative methods for disposal of Kr-85 to determine what effect decontamination would have on public health.
BYDER,R J TMI Program Office 80/10/31 3pp 06976 353

170045 Responds to 800701 ltr suggesting addl radiation monitoring facility area Monitoring is being performed by EPA, Commonwealth of PA, NRC & util Fixed thermoluminescent detectors are more appropriate than personal film badges.
BYDER,B J TMI Program Office 80/10/31 2pp 06911 001.

--801170048 Recommends use of personal dosimeter film badges by residents near facility Badges would give continuous, accurate & personalized record of exposure to vented Kr-85
KOVALSKI,B Affiliation Unknown 80/07/01 2pp 06911 001

801170102 Responds to 800628 telegram to President Carter re venting Kr-85 from facility NRC has evaluated alternative methods for disposal of Kr-85 to determine what effect decontamination would have on public health
SNYDER,B J TMI Program Office 80/10/31 3pp 06976 320

801180077 Responds to 800522 ltr to JF Ahearn re venting Kr-85 from facility & health effects of accident NRC has evaluated alternative methods for disposal of Kr-85 to determine effect on decontamination on public health
SNYDER,B J TMI Program Office 80/10/31 2pp 06915 001

--801180081 Recommends use of high altitude research balloons for venting Kr-85 from facility
DE JARDOS,J A Affiliation Unknown 80/05/22 1p 06915 001

801180087 Responds to ltr re venting Kr-85 from facility & effects of radiation on food NRC has evaluated alternative methods for disposal of Kr-85 to determine what effects decontamination would have on public health & safety
SNYDER,B J TMI Program Office 80/10/31 2pp 06915 001

801120393 Responds to ltr expressing concern re release of Kr-85 from TMI Potential physical health impact on public from using any of proposed strategies for removing Kr-85 is negligible w/o supporting documents
SNYDER,B J TMI Program Office 80/11/03 3pp 06916 001.

--801120359 Expresses concern re venting of radioactive gas from TMI
HERBEIN,K Affiliation Unknown 79/08/29 6pp 06916 001

801170889 Responds to encl 800628 telegram to President Carter expressing concern re venting of Kr-85 from TMI Potential physical health impact from any of proposed strategies for Kr-85 removal is negligible w/o supporting documents
SNYDER,B J TMI Program Office 80/11/03 3pp 06981 222

801180087 Responds to 800908 ltr to JF Ahearn & President Carter re comparison of Feb 1980 events at Crystal River facility & Mar 1979 events at TMI-2 method of processing water at TMI-2 delay in restart & financial impact to consumers.
DENTON,H R Office of Nuclear Reactor Regulation, Director 80/11/03 2pp 06992 289

--801180092 Expresses concern re Commission delays in startup of TMI-2 Questions methods used in facility cleanup & compares procedure w/Crystal River accident Cost to shareholders of util could be high
KINIO,T A Affiliation Unknown 80/09/08 3pp 06992 294

801180926 Responds to ltr expressing concern re release of radioactive matl from TMI Potential impact on public physical health from any of proposed strategies for removing Kr-85 is negligible w/o supporting documents.
SNYDER,B J TMI Program Office 80/11/03 2pp 06991 237

--801180528 Expresses concern re release of radioactive matl from TMI
MARCHETTI,A Affiliation Unknown 80/08/08 2pp 06991 239

801180064 Requests meeting w/NRC to discuss negative impact resulting from TMI-2 accident.
BOOTH,J E Affiliation Unknown 80/11/05 1p 06987 344

801180177 Responds to questions concerning TMI-2 accident & public safety Release of contaminated water not permitted Facility mods & emergency plan upgrading underway. Licensee is conducting feasibility studies re plant recovery.
SNYDER,B J TMI Program Office 80/11/05 6pp 06915 001.

--801180180 Opposes restart of nuclear plant. Questions NRC actions taken to insure public health & safety from radiation.
MANI,K A Affiliation Unknown 80/08/10 4pp 06915 001.

801180188 Responds to offer to participate in citizen monitoring program in TMI-2 area Prospective participants in DOE/Estate of PA offsite monitoring program should contact EPA
SNYDER,B J TMI Program Office 80/11/05 1p 06987 297

801180747 Responds to 800411 request for info re plant status & disposal of radioactive water Release of contaminated water not permitted. Info re plant condition & waste disposal available in draft EIS Emergency plan upgrading underway
SNYDER,B J TMI Program Office 80/11/05 2pp 06915 001

- B01180752 Requests info re plant status, disposal of radioactive water from containment bldg & emergency planning
SHELLY, F L Affiliation Unknown 80/04/11 4pp 06915.001
- B01190138 Responds to 790607 ltr to JM Hendrie re facility NRC authority to license & regulate handling of radwaste comes from Atomic Energy Act of 1954, Energy Reorganization Act of 1974 & NEPA of 1974
BNYDER, B J TMI Program Office 80/11/05 2pp 06996.266
- B01190143 Requests info re TMI accident & what NRC plans to do about public health & nuclear wastes Safety drills should be conducted at plants
MARKEY, D R Affiliation Unknown 79/06/07 2pp 06996.268
- B01190157 Responds to B00218 request for revocation of util OL NRC public hearing ordered re restart of Unit 1 Licensee currently conducting feasibility studies re plant recovery proposals for Unit 2
BNYDER, B J TMI Program Office 80/11/05 3pp 06916.001
- B01190162 Requests revocation of util OL following nuclear plant accident.
HAAK, D Affiliation Unknown 80/02/18 2pp 06916.001
- B01190168 Responds to B00322 ltr re radioactive releases & risks to public health & safety resulting from nuclear accident or sabotage. Offsite dose calculations re 790328 accident determined minimal risks to environ
BNYDER, B J TMI Program Office 80/11/05 3pp 06916.001
- B01190172 Comments on radioactive releases & environ impact of nuclear accidents or sabotage.
SCHUH, M Affiliation Unknown 80/03/22 3pp 06916.001
- B01190181 Responds to ltr commenting on status of facility & cleanup operations NRC assessment of decontamination at facility concludes that no significant environ impact would result from proposed cleanup operations
BNYDER, B J TMI Program Office 80/11/05 3pp 06916.001
- B01190189 Forwards draft EIS & annual rept re decontamination & disposal of radwaste resulting from TMI-2 accident in response to B01004 request Automatic shutdown of PWR would occur in event of LOCA W/o encl
BNYDER, B J TMI Program Office 80/11/05 1p 06916.001
- B01190193 Requests draft EIS re TMI-2 accident & info on consequences of pump failure or condenser circulation line clogging
CONNAUGHTON, N Affiliation Unknown 80/10/04 2pp 06916.001
- B01180016 Responds to B00304 ltr to DOE requesting info re facility accident EPICOR-II water treatment sys will be used for processing wastewater stored in auxiliary bldg tanks Forwards programmatic EIS for further info W/o encl.
BNYDER, B J TMI Program Office 80/11/06 2pp 06992.306
- B01180020 Forwards DL Berry B00304 ltr, misdirected to DOE, requesting info re facility accident.
WIENER, J H Energy, Dept. of 80/05/02 2pp 06992.308
- B01190351 Forwards Rogovin rept & NRC 1979 annual rept re accident & NRC responses to recommendations made by President's Commission on Accident at TMI in response to B00506 request for info W/o encl
BNYDER, B J TMI Program Office 80/11/06 1p 06996.245
- B01190369 Requests info re changes in NRC regulations resulting from facility accident.
PARKS, S D Affiliation Unknown 80/05/06 1p 06996.246
- B01190535 Responds to B00620 ltr to President Carter favoring continued use of nuclear energy. Licensee has primary responsibility to carry out decontamination operations. Existing statutes give NRC final authority.
BNYDER, B J TMI Program Office 80/11/06 3pp 07001.286
- B01190545 Responds to encl B00820 ltr to President Carter requesting federal help for facility Licensee has primary responsibility to carry out decontamination NRC has final authority should util be unable to continue adequately.
BNYDER, B J TMI Program Office 80/11/06 2pp 07001.284
- B01190549 Responds to encl B00505 ltr to President Carter requesting improvement to nuclear plants. Full-time inspectors have been assigned to all B&W plants as result of accident. PWR licensees must take action re status of certain items.
BNYDER, B J TMI Program Office 80/11/06 3pp 07001.281
- B01190553 Responds to encl B00324 ltr to President Carter urging restoration & preservation of facility financial integrity NRC has statutory authority to ensure public health & safety when licensee responsibility is lacking
BNYDER, B J TMI Program Office 80/11/06 3pp 06916.001
- B011200424 Forwards info requested in encl ltr to President re repair of damage at TMI Programmatic EIS will be prepared & public hearing held to address cleanup operations
BNYDER, B J TMI Program Office 80/11/06 4pp 01741.019
- B011200305 Expresses support for restart of TMI-1 Restart will reduce util costs of purchasing replacement power & will enhance util ability to safely recover TMI-2
MOYER, R A Affiliation Unknown 80/11/11 2pp 07021.280
- B011250424 Forwards updated svc distribution list for facilities, as addressed in util B00930 ltr List supersedes all previous submittals
ARNOLD, R C Metropolitan Edison Co 80/11/19 2pp 07056.099
- P Operating license stage documents & correspondence
- B011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp
- B01100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by B01101
EISENHUT, D O Division of Licensing 80/10/01 5pp
- B01110615 Forwards comments, on behalf of MD Waterman's Association on NUREG-0683 Susquehanna River & Chesapeake Bay must be protected.
GEORGE, D Affiliation Unknown 80/10/02 4pp 06945.324
- B01100537 Ltr to all power reactor licensees & applicants forwarding summary of B00827 meeting re guidance from Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp
- B011030237 Requests addl time to examine TMI accident rept.
PETERSON, N B Affiliation Unknown 80/10/08 1p 01756.001
- B01100066 Submits info re creation of TMI-2 advisory committee to obtain input & views from residents re decontamination & cleanup at facility Draft charter for panel encl
AHEARNE, J F Commissioners 80/10/08 4pp 06928.259
- B01103042 Requests 45-day extension for public discussion of rept re TMI decontamination & disposal of radwaste Requests copy of final EIS
AUSTIN, M P Affiliation Unknown 80/10/12 1p 01756.001
- B011040522 Forwards list of questions & requests for addl info re review of design criteria documents for interim solid waste staging facility discussed in util B00812 ltr
COLLINS, J T TMI Program Office 80/10/20 5pp 06915.285
- B011250416 Forwards two sets of addl microfilm reels re TMI data collected by General Public Utils W/o encl.
REED, E C Metropolitan Edison Co 80/10/20 1p 07056.098
- B01140678 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Role of panel is to consult NRC on activities required for safe & expeditious cleanup of facility
AHEARNE, J F Commissioners 80/10/23 3pp 06963.317
- B01140681 Advises that Commission has approved recommendations of SECY-80-406 as revised by WJ Dircks B00926 memo
CHILK, S J Office of the Secretary of the Commission 80/10/01 1p 06963.320
- B01140687 Recommends approval of SECY-80-406 re establishment of TMI-2 Advisory Panel.
HENDRIE, J M Commissioners 80/09/10 1p 06963.321
- B01170410 Notifies of appointment to chairmanship of Advisory Panel for Decontamination of TMI-2 Panel will consult w/k provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J F Commissioners 80/10/23 3pp 06975.107

DOCKETED ITEMS

- 801170413 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Panel will consult w/& provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J F Commissioners 80/10/23. 2pp. 06975 109.
- 801170418 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Panel will consult w/& provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J F Commissioners 80/10/23 2pp. 06975 111
- 801170419 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Panel will consult w/& provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J F Commissioners 80/10/23. 2pp. 06975 113.
- 801170421 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Panel will consult w/& provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J F Commissioners. 80/10/23. 2pp. 06975 115
- 801170422 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Panel will consult w/& provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J F Commissioners 80/10/23 2pp 06975 117
- 801170428 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Panel will consult w/& provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J F Commissioners 80/10/23. 2pp 06975 119.
- 801170433 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Panel will consult w/& provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J. F Commissioners 80/10/23 2pp 06975 121.
- 801170434 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Panel will consult w/& provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J F. Commissioners 80/10/23 2pp 06975 123
- 801170436 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Panel will consult w/ & provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J. F Commissioners 80/10/23 2pp. 06975 125
- 801170442 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Panel will consult w/& provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J F. Commissioners 80/10/23 2pp. 06975 127
- 801170445 Notifies of appointment to Advisory Panel for Decontamination of TMI-2 Panel will consult w/& provide advice to NRC on major activities required to accomplish expeditious & safe cleanup of facility.
AHEARNE, J F Commissioners. 80/10/23 2pp. 06975 129
- 11040388 Advises of inability to provide responses to public comments re programmatic EIS under time frame requested in NRC 801006 & 15 ltrs Reply will be submitted by 801120
HOVEY, Q K. Metropolitan Edison Co. 80/10/24. 1p. 06874 173
- 11100227 Comments on Util 801006 ltr re disposal of EPICOR-II & low activity SDS ion exchange media. Completion dates for logic activities requested
COLLINS, J. T TMI Program Office 80/10/27. 4pp 06928 268
- 1110762 Expresses gratitude re svcs rendered during public meeting on draft programmatic EIS.
SNYDER, B. J TMI Program Office. 80/10/27. 2pp 06947 358.
- 11120603 Forwards transcript of 800930 public meeting re draft programmatic EIS on TMI-2 cleanup & list of locations where transcripts will be available for public insp. Transcript not incl.
SNYDER, B. J. TMI Program Office. 80/10/27 2pp. 06953 180
- 1120607 Forwards transcript of recent public meeting re draft programmatic EIS on TMI-2 cleanup & list of locations where transcripts will be available for public insp. Transcript & list not incl.
SNYDER, B. J. TMI Program Office. 80/10/27 1p. 06953 182.
- 8011060062 Forwards comments received subsequent to 801015 ltr re draft programmatic EIS for decontamination & disposal of radwaste resulting from 790328 accident. Requests responses to comments by 801114.
SNYDER, B. J TMI Program Office 80/10/28 30pp 02319 196.
- 8011030527 Responds to NRC 801001 ltr re BWR scram sys Reassessment of sys indicates that util complies w/applicable General Design Criteria (App A to 10CFR50) Results of sys re-evaluation, mods & implementation schedule will be submitted by 801215
FINFROCK, I R Jersey Central Power & Light Co 80/10/30 1p 06853 086.
- 8011040458 Forwards recovery GA plan for review Organization & program described will enhance efforts for recovery of facility.
HOVEY, Q K Metropolitan Edison Co 80/10/30. 1p. 06884 074.
- 8011040461 GA plan for facility recovery, Revision 0.
LONG, R. L., HOVEY, Q. K., CLARK, P. R. Metropolitan Edison Co. 80/07/14 100pp 06084 079
- 8011070352 Updates NRC 800527 ltr re control of dissolved oxygen in RCS water Results of online testing program for Orbisphere provided Start up test program results compare favorably w/ analysis results for expected Oxygen levels
HOVEY, Q. K Metropolitan Edison Co 80/10/30. 1p 06918 207
- 8011130001 Ack receipt of comments on draft programmatic EIS. W/o encl NRC 1979 Annual Rept
SNYDER, B J TMI Program Office. 80/10/30 1p. 02227 001.
- 8011130006 Comments on draft programmatic EIS, Update of Aug 1976 aerial radiological survey recommended NRC 1979 & 1980 Annual Repts requested.
CHARLES, E Affiliation Unknown. 80/10/30 1p 02227 001
- 8011040501 Comments on DES for decontamination of facility. Opposes dumping waste water in Susquehanna River due to inadequacies & unanswered questions not addressed in EIS. H Hughes 801003 ltr to President Carter encl.
HELTON, A. H Maryland. State of. 80/10/31 2pp. 06877 201
- 8011030417 Forwards missing documents previously provided by util to NRC/TMI Special Inquiry Group Includes startup problem rept: THINS Forms 1616-1, MTX 24.2 drawings & condensate operator log book.
HOVEY, Q. K. Metropolitan Edison Co 80/10/31. 1p. 02319 196.
- 8011050418 Startup problem rept for facility.
* Metropolitan Edison Co. 78/03/30. 8pp. 02319 196.
- 8011050420 Info related to MTX 24.2 drawings.
* Metropolitan Edison Co. 78/05/06. 131pp. 02319 196.
- 8011070288 Forwards License Amend Request 1, changing Section 2.E.(3) of License DPR-73
HOVEY, Q K. Metropolitan Edison Co. 80/10/31. 1p. 06919 274.
- 8011070291 License Amend Request 1, changing Section 2.E.(3) of License DPR-73 re tankage for storage of wastewater
* Metropolitan Edison Co. 80/10/31 4pp 06919 277.
- 8011070356 Forwards TMI-2 recovery program preliminary sys description Task T8-27, mini decay heat removal sys, Revision 4, for closeout of outstanding items.
HOVEY, Q. K Metropolitan Edison Co. 80/10/31. 1p. 06918 127.
- 8011070358 TMI-2 recovery program preliminary sys description Task T8-27, mini decay heat removal sys, Revision 4, Prepared for util.
* Burns & Roe Co 80/10/07. 63pp 06918 128.
- 8011180413 Forwards MDHR sys description Revision 4, incorporating resolutions to previous NRC comments W/o encl
HOVEY, Q K. Metropolitan Edison Co. 80/10/31. 2pp. 06988 158.
- 8011120310 Responds to NRC 800806 ltr & fulfills commitment made in 800822 ltr re contingency plan for transfer & storage of reactor containment bldg sump water. Submerged demineralizer sys scheduled for operation by late Mar 1981.
ARNOLD, R. C. Metropolitan Edison Co. 80/11/04. 4pp. 06956 266.
- 8011120380 Requests addl info re TMI-2 cleanup, waste transport & storage site in response to EIS.
CHARLES, E., CHARLES, M. A Affiliation Unknown. 80/11/04. 3pp. 06916 001.

801120381 Notifies that if NRC approves until 801031 request to amend License DPR-73 to delete requirement for retaining tankage in TMI-1, then required reserve tankage will be provided in Unit 2 coolant bleed tank 1C & lower tanks of tank farm
HOVEY, O. K. Metropolitan Edison Co 80/11/05 1p 06952 050

801180425 Informs that required reserve wastewater tankage will be provided in reactor coolant bleed tank 1C & lower tanks of tank farm
HOVEY, O. K. Metropolitan Edison Co 80/11/05 1p 06988.159.

801120092 Forwards update to 801028 list of comments from federal, state & local agencies re draft programmatic EIS re decontamination & disposal of radwaste Response to comments should be submitted by 801121
BNYDER, B. J. TMI Program Office 80/11/05 2pp 07022.100

801190334 Responds to 801009 ltr re importance of public hearings in obtaining adequate input into draft programmatic EIS for decontamination of facility Current NRC program is consistent w/council views
AHEARNE, J. F. Commissioners 80/11/06 2pp. 07000 105.

--801190342 Forwards list of meetings w/public, local elected officials & interested organizations re draft programmatic EIS
BNYDER, B. J. TMI Program Office. 80/10/08 3pp. 07000.107

--801190348 Forwards proposed response to CEG 801009 ltr re importance of public hearing re draft programmatic EIS for TMI cleanup
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/10/21 4pp. 07000 110

--801190353 Discusses importance of public hearings in obtaining input into draft programmatic EIS for decontamination of facility.
SPETH, G. Council on Environmental Quality 80/10/09. 2pp 07000:114.

801120501 Forwards comments on draft programmatic EIS re decontamination & disposal of radwaste resulting from TMI-2 accident, in response to NRC 800814 ltr
HOVEY, O. K. Metropolitan Edison Co. 80/11/07 61pp 06953:108.

801128011 Requests updating technical evaluation rept for submerged demineralizer sys to include info contained in ORNL/TM-7448 & forwards request for addl info Updated listing of P&ID required.
COLLINS, J. T. TMI Program Office 80/11/07. 7pp 07083.267.

8011280105 Clarifies NRC position re interim solid waste staging facility Approval of design criteria document does not imply approval to construct or operate facility
COLLINS, J. T. TMI Program Office 80/11/10 5pp. 07083:262.

801180642 Comments on TMI programmatic EIS Document is redundant & discounts psychological effects of TMI accident on residents. Uncertainty of licensee's future has direct bearing on every aspect of decontamination.
LUTA, V. R. Affiliation Unknown 80/11/11. 9pp 06915.001

801180556 Discusses draft programmatic EIS re decontamination & disposal of radwastes resulting from 790328 accident. Analysis of radionuclide concentration & absorbed radiation dose in fish-eating birds should be included.
OUTH, R. W. RFF Ecological Associates. 80/11/12 1p. 06988.314

801190299 Advises of forwarding of proprietary documents, "EPICOR-II Resin Irradiation Data," & "Evaluation of EPICOR-II Wastes." Determination of NRC acceptance of documents as proprietary has not been received.
HOVEY, O. K. Metropolitan Edison Co 80/11/14. 1p. 06996.252.

801190485 Submits metallurgical evaluation of EPICOR-II liners. Document should be revised & re-reviewed prior to release. Commitment date for evaluation submittal revised to 801121.
HOVEY, O. K. Metropolitan Edison Co. 80/11/14 1p. 06996:244.

8011250297 Requests status of proprietary documents. 800716 "EPICOR II Resin Irradiation Data" & 800908 "Evaluation of EPICOR II Wastes." Requests date of determination of NRC acceptance
HOVEY, O. K. Metropolitan Edison Co 80/11/14. 2pp. 02227:001

8011250304 Informs of delay in until 801103 commitment to submit EPICOR II liner metallurgical evaluation by 801114. Due to necessary revisions, addl review & unanticipated travel of key personnel, evaluation to be submitted by 801121.
HOVEY, O. K. Metropolitan Edison Co 80/11/14. 2pp. 07056.079.

8011240315 Forwards "Specs for EPICOR 2 Resin Solidification."
HOVEY, O. K. Metropolitan Edison Co. 80/11/17. 1p 07042:235

--8011240317 "Specs for EPICOR 2 Resin Solidification"
FREEMAN, R. H., GREENBERG, J., RUBBELL, T. A. Metropolitan Edison Co 80/11/14 75pp 07042.236

8011260020 Notice of issuance of amend to 800211 order to provide for use of mini decay heat removal sys Requests proposed Tech Specs be formally modified in accordance w/order
CHANDLER, L. J. Hearing Branch 1 80/11/20 2pp 07074 157

--8011260034 Proposed Tech Specs Pages 3 1-1, 3 1-2, 3 4-1, 3 7-1, 3 7-2, 3 8-4, B 3/4 4-1 & B 3/4 7-1 providing for use of mini decay heat removal sys Certificate of Evc encl
* Office of Nuclear Reactor Regulation, Director 80/11/14 29pp 07074.185

G Inspection reports, IE Bulletins & correspondence

8011130130 Forwards IE Insp Repts 80-289/80-08 & 80-320/80-05 on 800317-0430 No noncompliance noted
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/09/15 2pp. 06958 229

--8011130136 IE Insp Repts 80-289/80-08 & 80-320/80-05 on 800317-0430 No noncompliance noted Major areas inspected selected new & revised procedures submitted for NRC approval, health physics & environ areas & response to IE Bulletin 79-19
HAVERKAMP, D., CONTE, R., SHANAKY, M. Region 1, Philadelphia, Office of the Director. 80/08/01. 10pp. 06958:231

8011260064 Forwards IE Investigation Rept 80-320/80-04 on 800305-07 & 11-14 No noncompliance noted
MARTIN, W. O. Region 1, Philadelphia, Safeguards Branch 80/10/01 2pp. 07070:358.

--8011260069 IE Investigation Rept 80-320/80-04 on 800305-07 & 11-14. No noncompliance noted Major areas inspected employee allegation re unauthorized entry in pumphouse, resulting in river pump trip
MADDEN, W., CHRISTOPHER, K. Region 1, Philadelphia, Office of the Director. DEVLIN, J. Region 1, Philadelphia, Safeguards Branch. 80/09/13 18pp. 07070:360

801140279 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/10/31 1p 06968.243.

801140585 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/10/31. 1p. 06963.145.

R. Periodic operating reports & related correspondence

8011060380 Forwards TMI Program Ofc weekly status rept for 801012-18.
COLLINS, J. T. TMI Program Office. 80/10/20 3pp. 06914:148

801120083 Forwards facility status rept for wk of 801019-25
COLLINS, J. T. TMI Program Office 80/10/27. 6pp 06953 318.

8011060080 Partial response to FOIA request for info re radiation levels of plant environs & dump sites & radiation levels in nine listed places. Forwards documents listed in App A Search is continuing for documents re second part of request
FELTON, J. M. Division of Rules and Records. 80/10/29. 2pp

--8011060137 Provides preliminary data rept for air & water samples collected on 800401-0407.
SMITH, A. E. Environmental Protection Agency. 80/04/09 2pp.

--8011060146 Provides preliminary data rept for air & water samples collected on 800414-0423
CORKERN, W. D. Environmental Protection Agency 80/04/25. 2pp

8011140644 Weekly status rept for wk ending 801101
COLLINS, J. T. TMI Program Office. 80/11/03 5pp 06963:269.

8011070507 Submits corrections in response to NRC 801006 ltr re radioactive matls released from nuclear power plants in 1978 Errata to TMI data encl.
HUKILL, H. D. Metropolitan Edison Co. 80/11/04. 6pp 06910:001.

801100523 Forwards "TMI Aquatic Study Monthly Rept for Sept 1980," for placement in PDR.
HICKEY, C. R. Environmental Engineering Branch 80/11/06. 1p 06931:024.

DOCKETED ITEMS

01100528 "TMI Aquatic Study Monthly Rpt for Sept 1980"
NARDACCI, G A. Ichthyological Associates, Inc 80/11/06 28pp
06931 025

1200351 Forwards status rpt for wk of 801102-08
DLINB, J T TMI Program Office 80/11/10 6pp 07019 003

1250262 Forwards Rpt 11, "Tritium Concentrations for 800125-1015,"
PA Bureau of Water Quality Mgt Rpt consists of facility
roundwater data. Tritium concentrations in monitoring &
bservation wells show decrease during Oct 1980
ETHLE, W E General Public Utilities - GPU Service Corp 80/11/19
4pp 07052 319

011250264 Rpt 11, "Tritium Concentrations for 800125-1015"
* General Public Utilities - GPU Service Corp 80/11/18 17pp
07052 323.

Reportable occurrences, LERs & related correspondence

1200352 RD 80-48/1P on 801027, four relief valves w/ unauthorized ABME
✓ code symbol stamp discovered Followup action being
initiated
IVEY, Q K Metropolitan Edison Co. 80/10/28 1p. 01741.019

1040449 Forwards LER 80-045/03L-0
IVEY, Q K Metropolitan Edison Co. 80/10/29. 1p. 06873.232.

11040457 LER 80-045/03L-0 on 800929, diesel failed to start while
performing surveillance procedure on emergency diesel
generator. Caused by personnel error Control reset &
operators reinstructed
CHAPLIN, S D Metropolitan Edison Co 80/10/29 3pp 06873 233.

1040436 Forwards LER 80-046/01L-0.
IVEY, Q K. Metropolitan Edison Co 80/10/30. 1p. 06874.196

11040445 LER 80-046/01L-0 on 800930, feeder breakers for buses 2-3B
& 2-4B were removed for maint & remained out of svc in
excess of Tech Spec limit Caused by failure to initiate time
clock bus feeder breakers replaced
CHAPLIN, S D Metropolitan Edison Co. 80/10/30 2pp 06874 197

120612 Discusses LER-80-035/03L-0 re failure of fire detectors
in white balance of plant diesel generators Plans to
submit Tech Spec change request as part of pkg of multiple
changes.
IVEY, Q K Metropolitan Edison Co 80/10/31 1p 06952 039.

170788 PNO-TMI-80-49 on 801106, licensee commenced loss to ambient
at (loss of reactor decay heat to reactor bldg ambient
st) Test demonstrates sufficient heat transfer occurs from
actor coolant sys to reactor bldg to cool core
NYE, R J, FABANO, A N NRC Three Mile Island Task Force.
LLINB, J T TMI Program Office 80/11/06. 2pp 06968.273

140570 PNO-TMI-80-050 on 801106, fire discovered in trailer on Unit
side of site. Trailer located outside protected area, but
side owner-controlled fences approx 20 yards from onsite
C complex. Trailer sustained heavy smoke & water damage.
NYE, R J, FABANO, A N NRC Three Mile Island Task Force.
LLINB, J T TMI Program Office 80/11/07. 2pp 06960 340

200146 PNO-TMI-80-051 on 801113, fourth entry into reactor bldg was
mpleted. Three separate entries were made by 12 men. No
try member exceeded 500 millirem total exposure. Max time
side for any one person was 90 minutes Photographs taken
LMAN, G, BELLAMY, R R. NRC Three Mile Island Task Force
LLINB, J T. TMI Program Office 80/11/13 2pp. 07021.277

240291 Forwards LER 80-047/03L-0
VEY, Q K Metropolitan Edison Co 80/11/17 1p 07042 353

11240296 LER 80-047/03L-0 on 801016, airlock inner door was leak
tested & leak rate exceeded Tech Specs Apparently caused by
foreign matl on sealing surface Sealing surface cleaned &
leak rate tested satisfactorily.
CHAPLIN, S D. Metropolitan Edison Co. 80/11/17. 2pp 07042:354

240294 RD 80-52/1P on 801113 following leak test of personnel
lock 2, inner door leak rate test failed to meet required
ch Spec limit Door could not be returned to svc within
-h required limit.
VEY, Q K. Metropolitan Edison Co. 80/11/17. 2pp 02227:001

240311 RD 80-53/1P on 801108, incare thermocouples N-3 & N-9
terminated to be failed.
VEY, Q K. Metropolitan Edison Co. 80/11/17 2pp 02227:001.

8011250540 Forwards LER 80-048/03L-0
HOVEY, Q K Metropolitan Edison Co 80/11/17 1p 07068 268

--8011250547 LER 80-048/03L-0 on 801017, after sampling A core flood tank,
inner containment isolation valve CF-VII15 failed to close
Apparently caused by motor & control circuits grounding out,
induced by water leakage Valve closed & deactivated.
CHAPLIN, S D Metropolitan Edison Co 80/11/17. 2pp 07068 269

8011250517 RD 80-053/01P submitted on 801117 contained incorrect date
Condition entered 801117 not 801108
HOVEY, Q K Metropolitan Edison Co 80/11/18. 2pp 02227.001

T Hearing transcripts on non-antitrust matters

8011040626 Forwards transcript of 800930 public meeting in Annapolis, MD
re draft EIS on TMI-2 cleanup Pp 1-93.
BNYDER, B J. TMI Program Office 80/10/27 2pp 06875 171

--8011040631 Transcript of 800930 public meeting in Annapolis, MD re draft
EIS on TMI-2 cleanup Pp 1-93
* TMI Program Office 80/09/30 95pp 06875.173.

801110566 Forwards transcript of 801007 public meeting in Camp Hill, PA
re draft programmatic EIS on facility cleanup
BNYDER, B J TMI Program Office 80/10/28. 2pp 06915.001

--801110568 Transcript of 801007 public meeting in Camp Hill, PA re
draft programmatic EIS on facility cleanup
* TMI Program Office * Pennsylvania, State of *
Environmental Protection Agency. 80/10/07 91pp. 06949 332.

8011120062 Forwards transcript of NRC 801020 public meeting re draft
programmatic EIS concerning TMI-2 cleanup
BNYDER, B J TMI Program Office 80/10/30. 2pp. 06951:193.

--8011120064 Transcript of 801020 public meeting in Middletown, PA re
draft programmatic EIS concerning TMI-2 cleanup Pp 1-112
* TMI Program Office 80/10/20. 113pp 06951 195

8011050575 Forwards transcript of 801008 public meeting in Newberry
Township, PA
BNYDER, B J TMI Program Office 80/10/31 2pp 06901.312.

--8011050580 Transcript of 801008 public meeting in Newberry Township, PA.
Pp 1-75
* TMI Program Office 80/10/08 77pp 06901.314.

801130049 Forwards transcript of NRC 801023 public meeting w/
representatives of PA Medical Soc re draft programmatic EIS
BNYDER, B J TMI Program Office 80/11/03. 2pp. 06956 292

--801130056 Transcript of 801023 public meeting w/representatives of PA
Medical Soc in Lancaster, PA Pp 1-92.
* TMI Program Office. 80/10/23. 53pp. 06956.293.

8011260190 Transcript of Advisory Panel for TMI-2 Decontamination
801112 meeting in Harrisburg, PA Pp 1-110.
* Commissioners 80/11/12 113pp. 07071.017.

U Congressional/Executive Correspondence

8011040476 Commends NRC efforts to encourage public comment on TMI
draft programmatic EIS Extension of comment period until
801120 requested
BARBARIE, P S Senate. 80/10/16 2pp

8011100618 Discusses formation of Citizens Advisory Panel on TMI in
advance of NRC authorization bill for FY81. Since bill has
not yet been approved, provisions of Federal Advisory
Committee Act will apply to panel. N/o encl member list.
AHEARNE, J F. Commissioners 80/10/31 2pp. 03716 283.

--8011100621 Discusses formation of Citizens Advisory Panel on TMI in
advance of NRC authorization bill for FY81. Since bill has
not yet been approved, provisions of Federal Advisory
Committee Act will apply to panel. N/o encl member list.
AHEARNE, J F. Commissioners. 80/10/31. 2pp. 03716.285

--8011100624 Discusses formation of Citizens Advisory Panel on TMI in
advance of NRC authorization bill for FY81. Since bill has
not yet been approved, provisions of Federal Advisory
Committee Act will apply to panel Membership list encl
AHEARNE, J F. Commissioners 80/10/31. 4pp. 03716:287.

8011200315 Requests info re NRC plans to authorize General Public Util actions to speed up TMI cleanup operations
BEVILL, T House of Rep, Appropriations 80/11/12 2pp
07022 089

DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8011030062 Ack receipt of util 801003 ltr forwarding amend to Chapter 10 of security plan for facilities Changes per 10CFR50.54(p) can be made w/o prior NRC approval.
REID, R W Operating Reactors Branch 4 80/10/15 2pp 06855 122

8011060148 Notification of 801104 meeting w/util in Bethesda, MD to discuss util proposed concept for physical plans for alerting population in event of emergency
VERRELLI, D M Operating Reactors Branch 4 80/10/20 2pp
06912.335

8011250642 Forwards summary of 801104 meeting w/util re proposed sys to provide prompt notification in event of emergency Meeting satisfies request for NRC response to util 800912 ltr
REID, R W Operating Reactors Branch 4. 80/11/07. 2pp 07056.028

--8011280655 Summary of 801104 meeting w/util in Bethesda, MD re licensees proposal for sys providing prompt notification of public in event of emergency. Plan is predicated on NOAA willingness to participate.
VERRELLI, D Operating Reactors Branch 4 80/11/07 4pp.
07056.030

G. Adjudicatory correspondence

801110600 Forwards order for mod of Licenses DPR-57 & NPF-5 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp 06946 279.

--801110606 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by B20630. Complete records must be available by 801201
EISENHUT, D O. Division of Licensing 80/10/24. 6pp. 06946:281

--801110614 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment.
* Division of Licensing. 80/10/24 4pp 06946 287.

F. Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition
GRIMEB, C. I. Assistant Director for Engineers & Projects (Pre 790625). 79/03/02. 2pp 03145 305.

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D O. Division of Licensing. 80/09/05. 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01. 5pp.

801190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mode to assure adequate short-term performance. Info should be submitted within 25 days
EISENHUT, D O. Division of Licensing. 80/10/01 2pp

801100937 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12; "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D O. Division of Licensing. 80/10/04. 6pp

801110600 Forwards order for mod of Licenses DPR-57 & NPF-5 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl.
REID, R W. Operating Reactors Branch 4. 80/10/24. 2pp. 06946:279.

--801110606 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by B20630. Complete records must be available by 801201
EISENHUT, D O. Division of Licensing 80/10/24 6pp 06946 281

--801110614 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 4pp 06946 287

801140264 Forwards Amends 79 & 18 to Licenses DPR-57 & NPF-5, respectively, safety evaluation & notice of issuance & availability
REID, R W Operating Reactors Branch 4 80/10/28 2pp 06961 238

--801140267 Amends 79 & 18 to Licenses DPR-57 & NPF-5, respectively, incorporating certain TMI-2 lessons learned Category A requirements
REID, R W Operating Reactors Branch 4 80/10/28 24pp
06961.240

--801140270 Safety evaluation supporting Amends 79 & 18 to Licenses DPR-57 & NPF-5, respectively
* Office of Nuclear Reactor Regulation, Director. 80/10/28. 4pp
06961.264

--801140276 Notice of issuance & availability of Amends 79 & 18 to Licenses DPR-57 & NPF-5, respectively
REID, R W Operating Reactors Branch 4 80/10/28. 2pp
06961 268.

8011070277 Application for amend to App A Tech Specs of License DPR-57, revising Section 3.5 J 2a to allow plant to operate for up to 7 days w/both diesel generator & standby svc water pump inoperable Class III amend fee encl
WIDNER, W A Georgia Power Co 80/10/29. 3pp 06919 271

--8011070282 Proposed changes to App A Tech Specs, revising Section 3.5 J 2a re limiting conditions for operation of plant svc water sys
* Georgia Power Co 80/10/29 2pp 06919 274

8011070425 Errata to 801029 proposed change to Tech Specs. First line of second page should read "inoperable"
WIDNER, W A Georgia Power Co 80/10/30 1p 06919 356

801120583 Notifies that Class I & II license amend fees transmitted w/801003 application re security plan amend will be refunded. Change does not require prior NRC approval.
MILLER, W O License Fee Management Branch 80/10/30. 1p
06953:261.

8011060500 Provides info re environ qualification of safety-related equipment in response to DO Eisenhut 801001 ltr. Util is willing to participate in establishment of standardized equipment environ qualification acceptance criteria
WIDNER, W A Georgia Power Co 80/10/31 1p 06915.298

801190146 Confirms NRC authorization to revise Tech Specs, in response to util 801029 request re operability requirements of standby svc water pump
NOVAK, T M Assistant Director for Operating Reactors. 80/11/03 2pp 06999 223.

--801190151 Revised Tech Specs 3 B.3 & 4.5 J re operability requirements of standby svc water pump.
* Assistant Director for Operating Reactors. 80/11/03 1p.
06999 225.

8011200083 Confirms util commitments to interim position on containment purging & venting, pending resolution of isolation valve operability. Commitment will remain in effect pending NRC long-term review
REID, R W Operating Reactors Branch 4. 80/11/04 2pp 07022:095.

8011260258 Notifies that 801015 proposed change in QA program of FSAR does not require prior NRC approval. Change in procedures should not decrease effectiveness of QA program
REID, R W. Operating Reactors Branch 4 80/11/07 2pp 07074.144.

8011260199 Forwards Amend 80 to License DPR-57, safety evaluation & notice of issuance & availability.
REID, R W. Operating Reactors Branch 4. 80/11/13. 2pp 07071:349.

--8011260201 Amend 80 to License DPR-57, changing operability requirements to reflect availability of alternate cooling water source to Diesel Generator 1B.
REID, R W. Operating Reactors Branch 4 80/11/13 4pp.
07071:351

DOCKETED ITEMS

--8011260202 Safety evaluation supporting Amend 80 to License DPR-57
* Office of Nuclear Reactor Regulation, Director 80/11/13 2pp
07071 355

--8011260205 Notice of issuance & availability of Amend 80 to License
DPR-57
REID, R W Operating Reactors Branch 4 80/11/13 2pp
07071 357

8011210611 Advises that concerns re small break LOCA should be
addressed to NBSB vendor Questions re scope & schedule of
response to TMI action plan, Item II K 30 C, should be
addressed to OE manager of BWR sys licensing, RH Buchholz;
WIDNER, W A Georgia Power Co 80/11/14, 1p 07029.153

3 Inspection reports, IE Bulletins & correspondence

8011060263 Forwards IE Insp Repts 50-321/80-39 & 50-366/80-39 on
800816-0912 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/09/29 2pp 06911 227

--8011060270 IE Insp Repts 50-321/80-39 & 50-366/80-39 on 800816-0912, No
noncompliance noted Major areas inspected: Tech Spec
compliance, maint & mgt.
ROGERS, R F Region 2, Atlanta, Office of the Director DANCE, H C
Region 2, Atlanta, Reactor Operations Nuclear Support Branch
80/09/29 3pp 06911.229.

8011260380 Forwards IE Insp Repts 50-321/80-37 & 50-366/80-37 on 800916
-17 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/10/07 2pp 07072 311

--8011260387 IE Insp Repts 50-321/80-37 & 50-366/80-37 on 800916-17 No
noncompliance noted Major areas inspected, followup on items
of noncompliance re Part 21 evaluation & reporting matters
BROOKLEE, V L Region 2, Atlanta, Office of the Director
CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/10/03 2pp 07072 313

8011030260 Forwards IE Insp Repts 50-321/80-38 & 50-366/80-38 on
800922-26 No noncompliance noted
KENNA, W B, Region 2, Atlanta, Safeguards Branch 80/10/17 2pp
06857 213

--8011030267 IE Insp Repts 50-321/80-38 & 50-366/80-38 on 800922-26 No
noncompliance noted Major areas inspected, review of
security plan, security program audit & security
organization Details withheld (ref 10CFR2 790)
TILLMAN, A Region 2, Atlanta, Office of the Director
MCQUINNE, D R Region 2, Atlanta, Safeguards Branch 80/10/17 1p.
06857 215

801170427 Describes responses to IE Bulletin 80-15 contained in 800829
ltr which was not notarized Details 800815 test conducted to
assure that emergency notification sys is satisfactory
WIDNER, W A Georgia Power Co 80/10/23 1p 06977-329

8011050501 Ack receipt of 801005 ltr informing NRC of steps taken to
correct violations noted in Health Physics Appraisal Repts
50-321/80-27 & 50-366/80-27
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety
Branch, 80/10/24 1p 06900 150

--8011050508 Responds to NRC 800912 ltr re violations noted in Health
Physics Appraisal Repts 50-321/80-27 & 50-366/80-27
Corrective actions health physics program modified,
instruments replaced & health physics supervisors increased
WIDNER, W A Georgia Power Co 80/10/06 10pp 06900 151

--8011050512 Forwards Health Physics Appraisal Repts 50-321/80-27 &
50-366/80-27 on 800616-27, notice of violation & notice of
significant findings
O'REILLY, J P Region 2, Atlanta, Office of the Director
80/09/12 4pp 06900 161

--8011050516 Notice of violation from health physics appraisal on
800616-27
* Region 2, Atlanta, Office of the Director, 80/09/05 2pp
06900 165

--8011050519 Health Physics Appraisal Repts 50-321/80-27 & 50-366/80-27
on 800616-27 Noncompliance noted failure to follow written
procedures & to perform safety analysis.
HOBBS, C M, DAVIS, J H Region 2, Atlanta, Office of the Director
Q185014 F Region 2, Atlanta, Fuel Facility & Materials Safety
Branch, 80/09/05 26pp 06900 167.

801110600 Forwards order for mod of Licenses DPR-37 & NPF-5 re environ
qualification of safety-related electrical equipment Revised
Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp

--801110606 Order for mod of licenses re environ qualification of
safety-related electrical equipment Compliance w/Div of
Operating Reactors guidelines or NUREG-0588 required by
820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp

--801110614 Revised Tech Spec pages per 801024 order for mod of licenses
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 4pp

8011050536 Ack receipt of 801007 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-321/80-35 &
50-366/80-35
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/10/29 1p 06902 094

--8011050559 Responds to NRC 800911 ltr re violations noted in IE Insp
Repts 50-321/80-35 & 50-366/80-35 Corrective actions
replacement of two scram discharge vol level switches &
revision of surveillance procedures
WIDNER, W A Georgia Power Co 80/10/07 2pp 06902 095

--8011050564 Forwards IE Insp Repts 50-321/80-35 & 50-366/80-35 on
800715-0815 & notice of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/09/11 2pp 06902 097.

--8011050569 Notice of violation from insp on 800715-0815
* Region 2, Atlanta, Office of the Director 80/09/11 1p
06902 099

--8011050574 IE Insp Repts 50-321/80-35 & 50-366/80-35 on 800715-0815.
Noncompliance noted reactor plant taken to Modes 1 & 2 w/A &
D scram discharge vol level switches inoperable subsequent
to scrams on 800602, 14, 0711 & 26
ROGERS, R F Region 2, Atlanta, Office of the Director DANCE, H C
Region 2, Atlanta, Reactor Operations Nuclear Support Branch
80/09/11, 4pp 06902 100

8011260152 Confirms understanding re IE Bulletin 80-17 Util will change
frequency of surveillance on residual water in scram
discharge vol scram switches to once per day as of 801028
WIDNER, W A Georgia Power Co 80/10/30 1p 07080 106

801100478 Forwards response to IE Bulletin 79-018 re environ
qualification of electrical equipment Demonstrates that
equipment is capable of satisfying safety requirements
W/o encl
WIDNER, W A Georgia Power Co 80/10/31 1p 06940 346

8011260142 Forwards final response to IE Bulletin 80-08, "Examination
of Containment Liner Penetration Welds " Review of
containment boundary penetrations identified several design
type penetrations
WIDNER, W A Georgia Power Co 80/11/03 7pp 07080 095

8011210257 Responds to IE Bulletin 80-11 re masonry wall design Nine
walls shown to have stresses above allowable design during
earthquake load application Design mods in progress
WIDNER, W A Georgia Power Co 80/11/04 2pp 07030 123

8011240050 Confirms 801103 agreement to exempt daily surveillance
requirement for scram discharge vol components in shutdown
reactor units
WIDNER, W A Georgia Power Co 80/11/04 1p 07038.287

R Periodic operating reports & related correspondence

8011190290 Forwards monthly operating rept for Oct 1980
HARRY, M. Georgia Power Co 80/11/10 1p 06996 168

--8011190293 Monthly operating rept for Oct 1980
UNDERWOOD, P R Georgia Power Co 80/11/10 7pp 06996.169.

S Reportable occurrences, LERs & related correspondence

801100217 Forwards supplemental info to RD 50-321/1979-021, Revision 5
Updated data provided for tritium levels in groundwater
samples taken from locations where average level for third
quarter of 1980 exceeded Tech Specs
HARRY, M Georgia Power Co 80/10/30 4pp, 06928.263

DOCKETED ITEMS

129

8011190392 Forwards LER 80-112/03L-0
MANNRY, M. Georgia Power Co 80/11/11 1p 0699B 065

--8011190400 LER 80-112/03L-0 on 801023, four fire doors protecting safety-related areas failed surveillance tests. Caused by lack of closers on three doors & damage to remaining door. Maint requests issued & closers installed.
COOQIN, C L Georgia Power Co 80/11/11 2pp 0699B 066

8011190405 Forwards LER 80-106/03L-0
MANNRY, M Georgia Power Co 80/11/11 1p 0699B 068

--8011190412 LER 80-106/03L-0 on 801022, chlorine monitor, 1Z41-N022A, sample fan found inoperative. Caused by sample fan bearing drag, abetted by dried bearing oil lubricator wicks. Wicks oiled & procedure revised to oil wicks monthly.
NIX, R T Georgia Power Co 80/11/11 2pp 0699B 069

8011190417 Forwards LER 80-115/01T-0
MANNRY, M Georgia Power Co 80/11/11 1p 0699B 077

--8011190422 LER 80-115/01T-0 on 801031, util notified that nine masonry block walls in control bldg show local stresses above allowable codes. Caused by equipment mounted on walls after original installation. Walls will be reinforced.
COOQIN, C L Georgia Power Co 80/11/11 2pp 0699B 078

8011280060 Forwards LER 80-116/03L-0
MANNRY, M Georgia Power Co 80/11/18 1p 07084 103

--8011280062 LER 80-116/03L-0 on 801105, reactor recirculation pump A motor generator tripped. Cause unknown. Generator set restarted & no problems found.
BAKLEY, S. X Georgia Power Co 80/11/18, 2pp. 07084, 104.

V Operator Examinations

8011060466 Notifies that facilities are in compliance w/interim criteria for shift staffing per DO Eisenhower 800731 ltr info completes actions re NUREG-0460, Item I A 1.3.
WIDNER, W A Georgia Power Co 80/10/31 1p 06915 301

DOCKET 80-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

8009110742 Notification of 800904-05 meeting w/Mark II owners group to discuss plants chugging C/O & lateral load specs.
ANDERSUN, C Containment Systems Branch 80/08/29 14pp

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D O Division of Licensing 80/09/05 209pp.

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01 5pp.

8011100937 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" N/A encl.
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011050555 Forwards request for addl info re emergency procedure guidelines. Schedule must be submitted by 801027. GE 800630 guidelines acceptable for trial implementation. Training program must account for possible mod.
EISENHUT, D O Division of Licensing 80/10/21 8pp 06902.086.

F Security, medical, emergency & fire protection plans

8011180323 Forwards facility emergency planning info for placement in LPDR N/A encl.
BOUBER, J L Division of Rules and Records. 80/11/04 1p 06991, 160

G Adjudicatory correspondence

8011040411 Motion for indefinite deferral of briefing on Commission 800620 policy statement requested in ASLB 800626 order. ASLB will be advised of progress re particularization of Contention 7.
LATHAM, S B Shoreham Opponents Coalition 80/10/23 2pp 06873 268

8011050182 Order granting Shoreham Opponent Coalition 801023 motion for indefinite deferral of briefs on TMI policy statement requested in ASLB 800626 order.
BOHERS, E B Atomic Safety and Licensing Board Panel 80/10/31 1p 02317 176

8011140105 Response in support of Shoreham Opponents Coalition motion to defer briefing on TMI policy statement.
OILMARTIN, D J ; DEMPSEY, P A Suffolk County, NY 80/10/31 1p. 06963 197

8011190024 Advises of availability of transcripts of ACRS 800807-09 meetings in Washington, DC FDR.
BORDENICK, B M Hearing Branch 3 80/11/17 1p 06999 297

8011250004 Responds to 80111 ltrs requesting contractor repts. Repts forwarded on 800908. Issue of local municipality participation should be topic of 801217 meeting.
BORDENICK, B M Hearing Branch 4 80/11/20 2pp 07056 180

8011280046 Notice of availability of procedural assistance in adjudicatory licensing proceedings, published in 800728 FR. In order to qualify for aid, intervenor must submit statement showing need to ASLB.
BOHERS, E B Atomic Safety and Licensing Board Panel 80/11/24 1p. 07084, 090.

H. General correspondence

8011040408 Requests FI Bialik name be added to svc lists for all matters re facilities, BNL & transport of nuclear mats in NY.
BIALIK, E I New York, State of 80/10/31 1p

8011240309 Requests that funds be appropriated to investigate facility cost overruns. Public should decide need for facility which might increase utility rates by 50%.
WEISS, E. Affiliation Unknown 80/11/07 1p 07049 328

8011250014 Forwards IE Insp Repts 80-322/80-14 & 80-322/80-15 per request. IE Insp Repts 80-10 & 80-12 & repts issued subsequent to 80-15 will be forwarded upon disclosure W/o encl.
BORDENICK, B. M Hearing Branch 4 80/11/19 1p 07056 186

8011250006 Forwards loan copies of NRC human factors engineering control room review & FSAR draft App M, environ qualification of electrical equipment.
BORDENICK, B. M Hearing Branch 4 80/11/20 1p 07056 182

K. Utility Final Safety Analysis Report (FSAR) & amends

8011030061 Certifies svc of Amend 37 to license application, consisting of Revision 19 to FSAR, on 801017.
MORIN, J. P Long Island Lighting Co 80/10/21 1p 06897 268

Q Inspection reports, IE Bulletins & correspondence

8011060531 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" IEB 79-018 & suppl dtd 800229, not previously transmitted, also encl. No written response required.
GRIER, S. H. Region 1, Philadelphia, Office of the Director 80/09/30 1p 06911, 352

8011200269 Responds to IE Bulletin 80-19. No mercury-wetted relays have been utilized in reactor protection sys.
NOVARRO, J. P Long Island Lighting Co. 80/10/08 1p 07020 011

8011170566 Ack receipt of 800922 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-322/80-10.
CARLBON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/10 1p 06976 329

--8011170571 Responds to NRC 800812 ltr re violations noted in IE Insp Rept 80-322/80-10. Corrective actions ANSI N13.1-1967 guidance incorporated into sampling sys installation instructions.
MOFFORD, A. W Long Island Lighting Co 80/09/22 2pp 06976 330

DOCKETED ITEMS

--B011170590 Forwards IE Insp Rept 50-322/80-10 on 800617-20 & notice of violation
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/12 2pp 06976 332

--B011170595 Notice of violation from Insp on 800617-20
* Region 1, Philadelphia, Office of the Director 80/08/01 2pp 06976 334

--B011170603 IE Insp Rept 50-322/80-10 on 800617-20 Noncompliance noted failure to conform to ANSI-13.1-67 for radiation monitoring sampling lines & failure to meet spec requirements for conduit separation
NARRON, L., PADLINO, R J Region 1, Philadelphia, Office of the Director
MCOAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 9pp 06976 336

B011200185 Responds to IE Bulletin 80-20 re malfunction of Westinghouse Type W-2 switches No such switches used in safety-related applications at facility
NOVARRO, J P Long Island Lighting Co 80/10/10 1p 07021 239

B011060635 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06909 305

B011070238 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06924 223

B011140135 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06968 223

B011140620 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06963 249

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

B011050354 Ltr to all licensees of operating plants, applicants for OLS & holders of CPs re preliminary clarification of THI action plan requirements Provides summary listing of all approved THI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

B011100486 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by B01101
EISENHUT, D G Division of Licensing 80/10/01 5pp

B011100937 Ltr to all power reactor licensees & applicants forwarding summary of B00927 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " i/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp.

B011040079 Forwards list of info needed for completing review of GE emergency procedure guidelines Guidelines have been approved for trial implementation at LaSalle, Zimmer, Shoreham, Fermi 2 & Susquehanna Facilities
EISENHUT, D G Division of Licensing 80/10/21 8pp 02319 196

B011210308 Forwards response to NRC B00801 ltr containing Hydrologic Engineering Branch generic questions re Executive Order 11588 concerning floodplain mgmt for plants near completion
CRANE, P A Pacific Gas & Electric Co 80/11/13 22pp, 07035 083

B011210318 Responds to NRC B00303 request for info re environ qualification program using NUREG-0588 Forwards environ qualification program for safety-related electrical equipment evaluation & tabulation of Class IE equipment.
CRANE, P A Pacific Gas & Electric Co 80/11/13 45pp 02227 001.

B011260125 Forwards info re evaluation of environ qualification program for safety-related electrical & Class IE equipment, in response to 791102 ltrs.
CRANE, P A Pacific Gas & Electric Co. 80/11/13 45pp, 01741 019

0 Adjudicatory correspondence

B011170574 Notification of contract execution, Mod 2 to "Technical Assistance in Preparation of NRC Appeal Brief on Diablo Canyon Nuclear Power Plant Hearing " Contractor NM Newmark
HAIRSTON, C A, GLAGOLA, A F Technical Assistance Contracts Branch FIN B-6874 80/09/30 1p 06981 273

--B011170578 Mod 2, modifying scope of work & authorized representative & extending period of performance, to "Technical Assistance in Preparation of NRC Appeal Brief on Diablo Canyon Nuclear Power Plant Hearing "
NEWMARK, N M N M Newmark Consulting Engineering Services
HALMAN, E L Division of Contracts FIN B-6874 80/09/30 2pp 06981 274

B011050406 Request for reconsideration of ASLB B01024 order granting extension until B01203 for Joint intervenors to file contentions Previously granted extensions sufficient Filing date of B01110 more realistic w/Certificate of Svc
CRANE, P A, OEH, A C, NORTON, B Pacific Gas & Electric Co 80/10/27 5pp 06898 166

B011050165 Amended notice of appearance, replacing JA Kline Certificate of Svc encl
GEORGIU, B B California, State of 80/10/30 4pp 06897, 311

B011040422 Response in opposition to San Luis Obispo Mothers for Peace B01013 motion for reconsideration of ASLB B01010 order re rejected Contention 12 Intervenor failed to show why access to security plan was not sufficient Certificate of Svc encl
OLMSTEAD, W J Hearing Branch 4 80/10/31 5pp 06873:273

B011040453 Response in opposition to PG&E B01027 motion for reconsideration of ASLB B01024 order granting extension for fuel loading & low power testing contentions Certificate of Svc encl
BROWN, H H, LANPHER, L C California, State of BROWN, H H, Hill Christopher & Phillips 80/10/31 4pp 06873 288

B011100241 Motion for reconsideration of ASLB order scheduling B01110 hearing in security proceeding Urges deferral until B01111 to accommodate flight schedule, Certificate of Svc encl
BROWN, H H Illinois, State of BROWN, H H Hill Christopher & Phillips 80/10/31 3pp 06929 071

B011060227 Petition for directed certification of ASLAB B01017 order re Part 3 deciding that hearings on security adequacy will be held in San Francisco, CA Choice of applicant premises compromises impartiality Certificate of Svc encl
WILLIS, H H, BALDWIN, W A San Luis Obispo Mothers for Peace, BALDWIN, W A Baldwin, W A 80/11/01 5pp 06912 015

B011070198 Order affirming present schedule re holding of on camera hearing in San Francisco, CA from B01110 until full completion
BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/11/03, 2pp, 06921, 009

B011070234 Statement in support of San Luis Obispo Mothers for Peace petition for certification of ASLAB B01017 order re site of hearing Use of PG&E facilities should be preceded by statements of necessity & cost Certificate of Svc encl.
BROWN, H H, GEORGIU, B B California, State of BROWN, H H Hill Christopher & Phillips 80/11/03, 3pp 06924 216

B011100427 Forwards subpoena form directing util to bring to hearing all records re selection, qualifications & discharge of KK Weaver & LW Houls Signature requested Newspaper article & Certificate of Svc encl
BROWN, L H, Hill Christopher & Phillips 80/11/03 5pp 06928, 017.

B011050451 Lists objections agreed to by parties re Joint Intervenor Exhibits R-6 through R-9 & R-17 Ref should not be made to exhibits as evidence in proceeding
OLMSTEAD, W J Hearing Branch 4 80/11/04 3pp 06878 218.

B011070057 Submits parties' proposal re order of B01110 hearing presentation in San Francisco, CA about security issues Suggests commencement w/applicant presentation, then Intervenor & State of CA & closing w/applicant rebuttal
OLMSTEAD, W J Hearing Branch 2 80/11/05 1p, 06924 323

B011070230 Response to San Luis Obispo Mothers for Peace B01011 petition for review of ASLAB B01017 order re site of security hearings, NRC rests on B01014 response to ASLB B01006 order Certificate of Svc encl
OLMSTEAD, W J Hearing Branch 2 80/11/05 4pp 06924, 208.

801100210 Response in opposition to applicant 801027 motion for reconsideration of ASLB 801024 order which set 801203 for filing contentions re fuel loading & low power testing. Plans already made by parties Certificate of Svc encl
FLEISCHAKER, D., REYNOLDS, J. San Luis Obispo Mothers for Peace, FLEISCHAKER, D. Fleischaker, D. S. 80/11/05 5pp 06929,043

801100246 Order advising that PQ&E 801027 motion for reconsideration of ASLB 801024 order is not persuasive Confirms 801203 filing date & urges parties to meet re fuel loading & low power testing contentions
BOWERS, E. S. Atomic Safety and Licensing Board Panel 80/11/05, 3pp 06929 074

801100263 Order accepting parties' agreement evidenced per encl WJ Olmstead 801104 ltr re portions of Joint Intervenor Exhibits R6-R9 & R-17 that are not relevant to proceeding
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 80/11/05 1p. 06929 082

--801100273 Submits stipulation reached among parties identifying portions of Joint Intervenor Exhibits R7-R9 & R-17 that will not be introduced into evidence due to irrelevancy to seismic proceedings.
OLMSTEAD, W. J. Hearing Branch 2 80/11/04. 3pp. 06929 083

801120075 Subpoena directed to PA Crane of PQ&E to produce refs described in PQ&E 801017 supplemental response to San Luis Obispo Mothers for Peace Interrogatories, Answer A-4
Production must take place at 801110 security plan hearing
BALZMAN, R. S. Atomic Safety and Licensing Appeal Panel 80/11/05 1p. 06932-182

--801120100 Subpoena directed to PA Crane of PQ&E to produce contracts & documents evidencing agreements w/security force, at 801110 security plan hearing, Certificate of Svc encl.
BALZMAN, R. S. Atomic Safety and Licensing Appeal Panel. 80/11/05. 4pp 06932-183.

8011070025 Notice of withdrawal from proceeding upon departure from NRC.
DAVIS, L. D. Hearing Branch 4 80/11/06 1p. 06924-300

8011260002 Proposed findings of fact & conclusions of law addressing questions propounded in app to 800624 ALAB-59B Areas addressed include 791015 Imperial Valley earthquake & related soil info Certificate of Svc encl
CRANE, P. A. Pacific Gas & Electric Co. 80/11/21 59pp. 07075 187.

8011280057 Notice of availability of procedural assistance in adjudicatory licensing proceedings, published in 800725 FR. In order to qualify for aid, Intervenor must submit statement showing need to ASLB
BOWERS, E. S. Atomic Safety and Licensing Board Panel. 80/11/24 1p. 07084-101.

H General correspondence

8011180344 Responds to 800710 ltr urging immediate licensing of facility. Favorable partial initial decision issued but was appealed by Joint Intervenor & hearing reopened by ASLB. NRC presently working on timely resolution of safety issues.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 80/10/08 4p 06915:001

8011030086 Responds to 800307 postcard requesting reconsideration of lifting moratorium for licensing facilities. All new applications for DLs are required to modify plant design to conform to TMI-related requirement
MIRAOLIA, F. J. Resource & Scheduling Branch 80/10/14. 2pp 01756-001

--8011030102 Requests reconsideration of lifting moratorium on licensing facilities.
JOYNER, J. Affiliation Unknown. 80/03/07. 1p 01756-001.

8011090662 Forwards response to 800618 ltr directed to President Carter re proximity of Hosgri fault to plant location. License application is sub. of contested adjudicatory proceeding during which concern will be addressed
MIRAOLIA, F. J. Licensing Branch 3 80/10/20 3pp. 06902:104

8011060097 Forwards response to 800610 ltr directed to President Carter re proximity of Hosgri fault to plant location. License application is sub. of contested adjudicatory proceeding during which concern will be addressed.
MIRAOLIA, F. J. Licensing Branch 3 80/10/20 4pp. 06912 215

801190643 Responds to 800601 ltr to President Carter re potential for const deficiencies at plant & concern over recent earthquake activity in area
MIRAOLIA, F. J. Resource & Scheduling Branch 80/10/20 2pp 07001-243

--801190648 Requests response to J & S Baumpartner ltr to President Carter re potential for const deficiency
SEAL, M. H. President of US & Executive Offices 80/06/20 1p 07001:246

8011060037 Responds to 800624 ltr to HR Denton re emergency planning, radiation monitoring & safety issues based on TMI accident
Subj documents can be found in LPDR at CA Polytechnic State Univ Library Response re alternative fuel source encl
MIRAOLIA, F. J. Licensing Branch 3 80/10/24 4pp 02319 196

8011060039 Responds to 800610 ltr to President Carter re effects of low level radiation & emergency preparedness & evacuation of area surrounding plant in view of TMI accident Hearings re security plan scheduled on or about 801110
MIRAOLIA, F. J. Licensing Branch 3 80/10/24. 5pp 02319 196

801170514 Responds to 790329 ltr expressing concern re licensing of facilities NRC has reacted positively to improve safety of all nuclear power plants based on TMI lessons learned.
MIRAOLIA, F. J. Licensing Branch 3 80/10/31 3pp 06911 001

--801170524 Expresses concern re licensing of facilities in light of TMI accident
SHIDA, G. Affiliation Unknown 79/03/29 1p 06911.001

801130407 Forwards Norwood 801029 ltr expressing concerns re security hearings Response requested
LAGOMARINO, R. House of Rep., Foreign Affairs 80/11/03 2pp. 06939,145

8011210721 Responds to 800616 ltr to HR Denton re licensing of facility. Major delays to completion of const have been due to plant mods resulting from seismic re-evaluation of facility & TMI-2 lessons learned requirements
MIRAOLIA, F. J. Licensing Branch 3. 80/11/12 2pp. 07029 134.

--8011210726 Urges NRC to license facility for full power operation
Consumers of PQ&E want plant opened to reduce high util bills Amount of oil wasted due to delay is drain on energy reserves Supporting publications encl
WRINKLE, H. H. Affiliation Unknown. 80/06/16 5pp. 07029,136.

8011210731 Responds to 800430 postcard to JF Ahearne re licensing of facility. Major delays to completion of const have been due to plant mods resulting from seismic re-evaluation of facility & TMI-2 lessons learned requirements
MIRAOLIA, F. J. Licensing Branch 3 80/11/12 2pp. 07174:228.

--8011210735 Urges NRC to move ahead w/licensing of facility at earliest possible date No safer or cleaner large-scale source of electricity currently available.
CURTIS, D. J. Affiliation Unknown 80/04/30 3pp 02227 001.

G. Advisory Committee on Reactor Safeguards reports & correspondence

8011180072 Transcript of ACRS 247th general meeting on 801107 in Washington, DC Pp 145-391 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 80/11/07 258pp 06984:201

801190385 Discusses PQ&E study of possible adverse interactions of nonsafety sys on plant safety as result of earthquake. Util examination of interactions is suitable & provides add assurance re plant ability to withstand earthquake
PLESBET, M. S. ACRS - Advisory Committee on Reactor Safeguards 80/11/12. 2pp 06996 192

G. Inspection reports, IE Bulletins & correspondence

8011060779 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No written response required
ENDELKEH, R. H. Region 5, San Francisco, Office of the Director. 80/10/10 1p 06909,054

801100014 Responds to IE Bulletin 80-18 re flow through centrifugal charging pumps Util will review any permanent vendor recommended design mods when available
CRANE, P. A. Pacific Gas & Electric Co 80/10/16. 2pp. 06928,340

DOCKETED ITEMS

11100061 Act receipt of 800617 ltr informing NRC of steps taken to correct violations noted in IE insp rept
SPENCER, G S Region 3, San Francisco, Reactor Construction & Engineering Support Branch 80/10/16 1p 06929 332

801100057 Responds to NRC 800519 ltr re violations noted in IE insp rept Corrective actions minor variation E-222 initiated to document problem Vital raceway supports inspected per GC Procedure GCP-9
CRANF, P A Pacific Gas & Electric Co 80/06/17 2pp 06929 333

11130014 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required
ENGELKEM, R H Region 3, San Francisco, Office of the Director, 80/10/24 1p 06957 259

11170631 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators" No written response required
ENGELKEM, R H Region 3, San Francisco, Office of the Director, 80/10/31 1p 06977 274

Reportable occurrences, LERs & related correspondence

11200162 PNS-V-80-09 on 801114, NRC resident inspector discovered bomb threat on automatic telephone recorder Male caller of unknown identity stated, "there was a bomb set to go off." Time given was unintelligible
POHNER, J, SCHUSTER, M D Region 3, San Francisco, Office of the Director 80/11/14 1p 07021 274

Hearing transcripts on non-antitrust matters

11103049 Transcript of 801022 hearing re geologic issues in San Luis Obispo, CA Pp 462-564 Related documentation encl.
* Atomic Safety and Licensing Board Panel 80/10/22 300pp
06864 009

11120591 Transcript of 801106 Affirmation Session 80-50 in Washington, DC re SECY-A-80-173 on facility physical security proceeding motion to move hearing site Pp 1-3
* Commissioners 80/11/06 6pp 06953 334

Congressional/Executive Correspondence

11100394 Forwards ASLAP 801017 order in facility security plan proceeding Order details why Board decided to hold hearing at applicant San Francisco, CA facility W/o encl.
CHO, J Atomic Safety and Licensing Appeal Panel 80/11/04 1p 06928 272

CKET 80-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

Adjudicatory correspondence

11110548 Forwards orders for mod of Licenses DPR-62 & DPR-71 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp 06946 199

801110555 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06946 201.

801110558 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 207

801110559 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06946 209

801110561 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 215.

P Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition
GRIMES, C I Assistant Director for Engineers & Projects (Pre 79062b). 79/03/02 2pp. 03145 305

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D O Division of Licensing 80/09/03 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp.

801110237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance Info should be submitted within 25 days.
EISENHUT, D O Division of Licensing. 80/10/01 2pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issues A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl.
EISENHUT, D O Division of Licensing. 80/10/06 6pp

801110548 Forwards orders for mod of Licenses DPR-62 & DPR-71 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp 06946 199

--801110539 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06946 209.

--801110561 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 215.

8011030592 Confirms 801020 telcon re potential impact of Brunswick Energy Co proposed oil refinery on util plant Requests NRC cooperation as agency prevent duplication of DES effort.
Telcon participant list encl
HUGHES, R K Army, Dept of, Corps of Engineers 80/10/28 4pp 06835 225

8011060569 Forwards response to NRC 800919 order for mod of license re environ qualification of electrical equipment Responds to concerns noted in 800919 draft interim technical evaluation rept Splice analysis encl
ZULLA, S B Power Authority of the State of New York 80/10/30 10pp. 06914 164.

--8011060572 "Design Approval Tests on Mats Used in Westinghouse Penetrations for Brunswick Station of Carolina Power & Light Co."
CARPENTER, P E, KORNER, R L, SHAFFER, R Westinghouse Electric Corp 72/08/11 43pp 06914 174

801120307 Confirms that units are in conformance w/general design criteria, App A 10CFR50, in response to NRC 801001 ltr requesting review of scram sys Util will participate in BWR owners group subgroup to address BWR scram sys
UTLEY, E E Carolina Power & Light Co 80/11/05 1p. 06956 270.

801120393 Submits info re environ qualification testing of safety-related electrical equipment, in response to NRC 801001 request Complete schedule of tests to be performed within next 2 yrs not available
UTLEY, E E Carolina Power & Light Co. 80/11/05 2pp 06953 093.

801130222 Application for amend to Tech Specs of Licenses DPR-71 & DPR-62, to provide one-time extensions for performing several insp, surveillances & tests, Class II amend fees encl
UTLEY, E E Carolina Power & Light Co 80/11/05 2pp. 06959 243.

--8011130230 Proposed changes to Tech Specs Sections 3.0 & 4.0, providing one-time extensions for performing insps, surveillances & tests to electrical power sys, reactivity control sys, ECCS & instrumentation
* Carolina Power & Light Co 80/11/05 20pp 06959 245

8011180377 Forwards proposed Tech Spec changes for control rod drive scram discharge vol capability in response to NRC 800707 ltr, requesting Tech Specs to provide surveillance requirements for SDV vent & drain valves
UTLEY, E.E. Carolina Power & Light Co 80/11/13 2pp 06992 162

--8011180384 Proposed Tech Spec changes to control rod drive scram discharge vol capability
* Carolina Power & Light Co 80/11/13 14pp 06992 164

Q Inspection reports, IE Bulletins & correspondence

8011040313 Forwards IE Insp Repts 50-324/80-32 & 50-325/80-35 on 800801-31 No noncompliance noted
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/25 2pp 06885 026

--8011040319 IE Insp Repts 50-324/80-32 & 50-325/80-35 on 800801-31 No noncompliance noted. Major areas inspected plant logs, vital areas, physical security barriers & followup on IE Bulletin 80-17.
DUZTS, J.E. Region 2, Atlanta, Office of the Director
KELLOGG, P.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/24 4pp 06885 028

8011105748 Forwards orders for mod of Licenses DPR-62 & DPR-71 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T.A. Operating Reactors Branch 2 80/10/24 2pp.

--801110559 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D.G. Division of Licensing 80/10/24 6pp 06946 209

--801110561 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06946 215

8011106640 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/24 1p 06976 238

8011260293 Forwards Revision 1 to 90-day rept re IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Response contains data developed since 800919 w/o rept.
FURR, B.J. Carolina Power & Light Co 80/10/30 1p 07153 104

8011280143 Requests extension for response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," to accommodate extensive revisions & expansion of scope
UTLEY, E.E. Carolina Power & Light Co 80/10/30 2pp

8011240118 Suppl 800919 response to IE Bulletin 80-17 re manual & automatic scram testing Per LER 2-80-72, Rod 38-15 took 13-s for full-in indication. Cause now believed to be foreign debris in drive unit seal area
FURR, B.J. Carolina Power & Light Co 80/11/04 2pp 07042 350

8011280040 Forwards response to Item 2b of IE Bulletin 80-11, "Masonry Wall Design" Reactor bldg info will be provided by 801123
Diesel generator bldg info will be provided by 801209
FURR, B.J. Carolina Power & Light Co. 80/11/05 29pp. 07082 225

8011280125 Notifies that required testing of emergency notification sys per IE Bulletin 80-13, "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power," has been rescheduled for Spring 1981.
FURR, B.J. Carolina Power & Light Co 80/11/06 1p 07083 278.

8011210255 Confirms 801113 telcon re meeting to discuss recent insp findings & mgt programs
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/11/07 1pp 07030 122.

8011210459 Ack receipt of 801027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/80-34 & 50-325/80-37.
KENNA, W.B. Region 2, Atlanta, Safeguards Branch. 80/11/12 1p. 07029 209.

--8011210460 Responds to NRC 801008 ltr re violations noted in IE Insp Repts 50-324/80-34 & 50-325/80-37 Corrective actions withheld (ref 10CFR2 790)
FURR, B.J. Carolina Power & Light Co 80/10/27 1p 07029 210

--8011210462 Forwards IE Insp Repts 50-324/80-34 & 50-325/80-37 on 800908-12 & notice of violation Details & notice of violation withheld (ref 10CFR2 790)
KENNA, W.B. Region 2, Atlanta, Safeguards Branch 80/10/08 2pp 07029 211

--8011210464 IE Insp Repts 50-324/80-34 & 50-325/80-37 on 800908-12 Noncompliance noted failure to perform personnel search & failure to provide written security procedure Details withheld (ref 10CFR2 790)
HOWELL, J.C., TILLMAN, A., MCGUIRE, D.R. Region 2, Atlanta, Office of the Director 80/10/07 1p 07029 213

R Periodic operating reports & related correspondence

8011140394 Forwards monthly operating repts for Oct 1980
TOLLISSON, A.C. Carolina Power & Light Co 80/11/10 1p 06963 032

--8011140397 Monthly operating repts for Oct 1980
WILLIS, E.A. Carolina Power & Light Co 80/11/03 6pp 06963 033

S Reportable occurrences, LERs & related correspondence

8011030410 Forwards updated LER 79-072/03L-1
TOLLISSON, A.C. Carolina Power & Light Co 80/10/14 1p 06857 206.

--8011030414 Updated LER 79-072/03L-1 on 790812, vessel conductivity exceeded 2 umhos for approx 33-h Caused by inoperability of reactor water cleanup sys Heat exchanger was sealed w/ Furmanite
TOLLISSON, A.C. Carolina Power & Light Co 80/10/15 2pp. 06857 207

8011030618 Forwards updated LER 80-030/03L-1.
TOLLISSON, A.C. Carolina Power & Light Co 80/10/14 1p 06860 180

--8011030624 Updated LER 80-030/03L-1 on 800412, during RHR svc water piping insp, heat exchanger rib plate on RHR heat exchanger 2B found partially buckled Apparently caused by water hammer event Rib plate will be replaced
TOLLISSON, A.C. Carolina Power & Light Co 80/10/15 2pp 06860 181

8011140023 ROs 80-095-01P & 80-086-01P, review of containment atmospheric dilution sys in response to NUREG-0578, indicated logic circuit relay in Units 1 & 2 which did not meet single active failure criteria of sys as stated in FSAR
TOLLISSON, A.C. Carolina Power & Light Co 80/10/16 4pp 06911 001.

801120577 Confirms 801021 telcon On 801020, during reactor core isolation cooling flow controller FIC-03325 maint, controller failed in automatic position Caused by bad solder connection in printed circuit Connection repaired
TOLLISSON, A.C. Carolina Power & Light Co 80/10/22 1p 06933 345

8011030413 Forwards LER 80-074/03L-0
TOLLISSON, A.C. Carolina Power & Light Co 80/10/24 1p 06857 204.

--8011030418 LER 80-074/03L-0 on 800927, primary containment oxygen concentration was not reduced to less than 4% within 24-h after 15% reactor power had been reached Caused by insufficient nitrogen for initial inerting Nitrogen added
TOLLISSON, A.C. Carolina Power & Light Co 80/10/24 1p. 06857 205

8011030421 Forwards LER 80-073/03L-0
TOLLISSON, A.C. Carolina Power & Light Co 80/10/27 1p. 06857 198.

--8011030425 LER 80-073/03L-0 on 800927, containment atmospheric oxygen analyzer 2-CAC-ATH-1259-2 would not run due to low sample flow Caused by water in analyzer due to excessive condensate in analyzer air dryer Water blown out & regulator replaced.
TOLLISSON, A.C. Carolina Power & Light Co 80/10/27 2pp. 06857 199.

8011040454 Forwards LER 80-079/03L-0.
TOLLISSON, A.C. Carolina Power & Light Co 80/10/29 1p. 06884 223.

DOCKETED ITEMS

--8011040462 LER 80-079/03L-0 on 801015, review of containment atmospheric dilution sys in response to NUREG-0578 revealed logic circuit relay which does not meet single active failure criteria of sys as stated in FSAR Revision written
TOLLISON, A C Carolina Power & Light Co 80/10/29 2pp
06884 224

8011100462 Forwards LER 80-074/03L-1
TOLLISON, A C Carolina Power & Light Co 80/10/30 1p 06930 359

--8011100465 LER 80-074/03L-1 on 800927, primary containment oxygen concentration exceeded 4% for one hour Caused by insufficient nitrogen for initial Inerting Nitrogen added to primary containment & personnel counseled
TOLLISON, A C Carolina Power & Light Co 80/10/30 1p
06930 360

8011120450 Forwards LER 80-058/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/03 1p 06953 354

--8011120460 LER 80-058/03L-0 on 801011, during source & intermediate range monitor test, PT 1 IO, source-range monitors C failed to withdraw Caused by sticking relay in detector drive control circuitry Relay mechanically exercised
TOLLISON, A C Carolina Power & Light Co 80/11/03 1p
06953 355

8011140010 Forwards LER 80-053/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/07 1p 06961 307.

--8011140013 LER 80-053/03L-0 on 801008, switch 1 of 1-B21-LIS-N017B & C activated out of tolerance Caused by instrument drift Instruments recalibr
TOLLISON, A C Carolina Power & Light Co 80/11/07 1p
06961 308

8011140442 Forwards LER 80-054/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/10 1p 06963 055

--8011140450 LER 80-054/03L-0 on 801011, main turbine control valve CV-V3 fast closure relay C72-K24C failed to de-energize when valve fast closure test button depressed Caused by disconnected threaded connector on solenoid control cable
TOLLISON, A C Carolina Power & Light Co 80/11/10 2pp
06963 056

8011180713 Forwards LER 80-078/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/10 1p 06991 299

--8011180721 LER 80-078/03L-0 on 801014, during normal operation w/power at 80A, primary containment oxygen concentration exceeded Tech Specs Caused by operator removal of clearance from CAC sys w/o allowing time for primary containment inerting
TOLLISON, A C Carolina Power & Light Co 80/11/10 2pp
06991 300

8011180574 RO 2-80-83 on 801017, piping support on Unit 2 HPCI discharge lines outside drywell was found to have cracked weld Caused by lack of fusion at weld point Support repaired & strengthened Unit 1 found satisfactory
TOLLISON, A C Carolina Power & Light Co 80/11/11 1p 06992 124.

8011180661 RO 80-83 on 801017, during routine insp, cracked weld found on HPCI discharge line piping support Caused by lack of fusion at weld point Support repaired & reinforced Facsimile LER encl
TOLLISON, A C Carolina Power & Light Co 80/11/11 3pp
06991 233

8011180718 Forwards LER 80-077/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/12 1p 06991 304

--8011180725 LER 80-077/03L-0 on 801017, during normal surveillance, containment atmospheric monitor oxygen analyzer 2-CAC-AT-1239-2 was indicating downscale Caused by instrument drift Analyzer & transmitter were recalibr
TOLLISON, A C Carolina Power & Light Co 80/11/12 2pp
06991 305

8011210451 Forwards LER 80-080/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/17 1p 07029 200.

--8011210452 LER 80-080/03L-0 on 801019, during testing, reactor instrument penetration isolation valves, X76-B, failed to reopen Caused by bakelite nipple breaking off actuation switch, Switch module replaced & valve successfully cycled
TOLLISON, A C Carolina Power & Light Co 80/11/17 1p
07029 201

8011250414 Forwards LER 80-088/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/17 1p 07068 106

--8011250417 LER 80-088/03L-0 on 801028, during checks on reactor low water level Numbers 2 & 3, found low level switch 2-B21-L18-N031D-3 actuated at 118 inches of water Caused by instrument drift Switch recalibr
TOLLISON, A C Carolina Power & Light Co 80/11/17 1p
07068 107

8011250422 Forwards LER 80-087/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/17 1p 07068 103

--8011250426 LER 80-087/03L-0 on 801025, w/diesel generator 2 out of svc for maint, generator 3 failed to start within required 10-s Caused by defective check valve in diesel 3 fuel oil supply line Check valve replaced
TOLLISON, A C Carolina Power & Light Co 80/11/17 2pp
07068 104

8011250431 Forwards LER 80-075/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/17 1p 07068 100

--8011250446 LER 80-075/03L-0 on 801022, during normal operation, A loop RHR svc water sys low suction annunciator alarmed despite normal sys pressure Caused by cracked pressure sensing line on Switch 1-BH-PB-1176 Switch assembly replaced
TOLLISON, A C Carolina Power & Light Co 80/11/17 2pp
07068 101

8011250374 Forwards LER 80-090/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/19 1p 07068 116

--8011250377 LER 80-090/03L-0 on 801026, during control rod operability check P T 14 1, rod 34-23 would not select During routine surveillance checks, rod 18-23 would not select Caused by failure of rod select switches Switches replaced
TOLLISON, A C Carolina Power & Light Co 80/11/19 1p
07068 117

8011250382 Forwards LER 80-086/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/19 1p 07068 113

--8011250386 LER 80-086/03L-0 on 801024, during routine surveillance, reactor instrument penetration isolation valve X51D found w/o position indication Caused by valve position limit switches out of adjustment Switches readjusted
TOLLISON, A C Carolina Power & Light Co 80/11/19 2pp
07068 114

8011250486 Forwards LER 80-085/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/19 1p 07068 285.

--8011250490 LER 80-085/03L-0 on 801024, containment atmosphere dilution sys valves 2-CAD-V55 & 56 would not fully open Caused by deformed stem seals in each valve operator New stem seals installed.
TOLLISON, A C Carolina Power & Light Co 80/11/19 1p
07068 286

8011250489 Forwards LER 80-084/03L-0
TOLLISON, A C Carolina Power & Light Co 80/11/20 1p 07056 360

--8011250497 LER 80-084/03L-0 on 801024, containment atmosphere dilution tank flow control valves 2-CAC-FCV-2717 & 2720 would not operate, Caused by accumulation of water in electropneumatic converter of valve 2720 Water removed.
TOLLISON, A C Carolina Power & Light Co 80/11/20 2pp
07056 361

V Operator Examinations

8011120437 Submits info re shift staffing in response to NRC 800731 ltr transmitting interim criteria
UTLEY, E E Carolina Power & Light Co 80/11/05 1p 06953 092.

DOCKET 80-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

0 Adjudicatory correspondence

8011110548 Forwards orders for mod of Licenses DPR-62 & DPR-71 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPFOLITO, T A Operating Reactors Branch 2 80/10/24 2pp
06946 199.

--801110535 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 802630. Complete records must be available by 801201. EISENHUT,D O Division of Licensing 80/10/24 6pp 06946 201

--801110558 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment * Division of Licensing 80/10/24 2pp 06946 207

P. Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition. ORIHES, C. I Assistant Director for Engineers & Projects (Pra 790623) 79/03/02 2pp 03145 305

8011090354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements. EISENHUT,D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101. EISENHUT,D O Division of Licensing 80/10/01 3pp

8011190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability. IE Bulletin 80-17 required mods to assure adequate short-term performance. Info should be submitted within 25 days. EISENHUT,D O Division of Licensing 80/10/01 2pp 07000 087.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl. EISENHUT,D O Division of Licensing 80/10/06 6pp

801110548 Forwards orders for mod of Licenses DPR-62 & DPR-71 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl. IPPOLITO, T A Operating Reactors Branch 2. 80/10/24. 2pp

--801110535 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 802630. Complete records must be available by 801201. EISENHUT,D.O. Division of Licensing. 80/10/24. 6pp 06946.201

--801110558 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment * Division of Licensing 80/10/24 2pp. 06946 207

8011030592 Confirms 801020 telcon re potential impact of Brunswick Energy Co proposed oil refinery on util plant Requests NRC cooperation as agency prevent duplication of DEB effort Telcon participant list encl. HUGHES,R K Army, Dept of, Corps of Engineers 80/10/28 4pp. 06855.225.

8011060569 Forwards response to NRC 800919 order for mod of license re environ qualification of electrical equipment. Responds to concerns noted in 800919 draft interim technical evaluation rept. Eplice analysis encl. ZULLA,B S. Power Authority of the State of New York 80/10/30. 10pp. 06914.164

--8011060572 "Design Approval Tests on Metals Used in Westinghouse Penetrations for Brunswick Station of Carolina Power & Light Co." CARPENTER,P E, KORNER,R L, SHAFFER,R. Westinghouse Electric Corp. 72/08/11. 43pp. 06914:174

801120307 Confirms that units are in conformance w/general design criteria. App A 10CFR50, in response to NRC 801001 ltr requesting review of scram sys Util will participate in BWR owners group subgroup to address BWR scram sys. UTLEY,E.E. Carolina Power & Light Co. 80/11/05 1p. 06956 270.

801120393 Submits info re environ qualification testing of safety-related electrical equipment in response to NRC 801001 request. Complete schedule of tests to be performed within next 2 yrs not available. UTLEY,E.E. Carolina Power & Light Co. 80/11/05. 2pp 06953.093

801130222 Application for amend to Tech Specs of Licenses DPR-71 & DPR-62, to provide one-time extensions for performing several insps, surveillances & tests Class II amend fees encl. UTLEY,E E Carolina Power & Light Co 80/11/05 2pp 06959 243

--801130230 Proposed changes to Tech Specs Sections 3.0 & 4.0, providing one-time extensions for performing insps, surveillances & tests to electrical power sys, reactivity control sys, ECCS & instrumentation * Carolina Power & Light Co 80/11/05 20pp 06959 245

801180377 Forwards proposed Tech Spec changes for control rod drive scram discharge vol capability in response to NRC 800707 ltr, requesting Tech Specs to provide surveillance requirements for BDV vent & drain valves. UTLEY,E E Carolina Power & Light Co 80/11/13 2pp 06992 162

--801180384 Proposed Tech Spec changes to control rod drive scram discharge vol capability * Carolina Power & Light Co 80/11/13 14pp 06992 164

801210202 Forwards corrected Page 2 re R-factor calculations for OE rept NEDO-24239, "Supplemental Reload Licensing Submittal for Brunswick Steam Electric Plant Unit 1, Reload 2 " UTLEY,E E Carolina Power & Light Co 80/11/18 1p 07032 320

--801210206 Corrected Page 2 re R-factor calculations for "Supplemental Reload Licensing Submittal for Brunswick Steam Electric Plant Unit 1, Reload 2 " * General Electric Co NEDO-24239 80/11/18 1p 07032 321

Q. Inspection reports, IE Bulletins & correspondence

8011040313 Forwards IE Insp Repts 50-324/80-32 & 50-325/80-35 on 800801-31. No noncompliance noted. LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/25 2pp 06885 026

--8011040319 IE Insp Repts 50-324/80-32 & 50-325/80-35 on 800801-31. No noncompliance noted. Major areas inspected plant logs, vital areas, physical security barriers & followup on IE Bulletin 80-17. QUZTS,J E Region 2, Atlanta, Office of the Director. KELLOGG,P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/24 4pp. 06885 028

801110548 Forwards orders for mod of Licenses DPR-62 & DPR-71 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl. IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp

--801110535 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 802630. Complete records must be available by 801201. EISENHUT,D O Division of Licensing 80/10/24 6pp

--801110558 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment * Division of Licensing 80/10/24 2pp

801170660 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required. O'REILLY,J P Region 2, Atlanta, Office of the Director 80/10/24 1p 06976:258.

8011260793 Forwards Revision 1 to 90-day rept re IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " Response contains data developed since 800919 W/o rept. FURR,B J Carolina Power & Light Co 80/10/30 1p 07153 104

8011280143 Requests extension for response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment," to accommodate extensive revisions & expansion of scope. UTLEY,E E Carolina Power & Light Co 80/10/30 2pp. 07083 282

8011240118 Suppls 800919 response to IE Bulletin 80-17 re manual & automatic scram testing Per LER 2-80-72, Rod 38-15 took 13-s for full-in indication Cause now believed to be foreign debris in drive unit seal area. FURR,B J. Carolina Power & Light Co 80/11/04 2pp 07042 350

8011280040 Forwards response to Item 2b of IE Bulletin 80-11, "Masonry Wall Design." Reactor bldg info will be provided by 80125. Diesel generator bldg info will be provided by 801209. FURR,B J. Carolina Power & Light Co 80/11/05. 29pp. 07082:225.

DOCKETED ITEMS

8011280125 Notifies that required testing of emergency notification sys per IE Bulletin 80-13, "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power," has been rescheduled for Spring 1981
 FURR,B J Carolina Power & Light Co 80/11/06 1p 07083 278

8011210255 Confirms 801113 telcon re meeting to discuss recent insp findings & mgt programs
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/11/07 1pp 07030 122

8011210459 Ack receipt of 801027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-324/80-34 & 80-325/80-37
 KENNA, W B Region 2, Atlanta, Safeguards Branch, 80/11/12, 1p 07029 207

8011210460 Responds to NRC 801008 ltr re violations noted in IE Insp Repts 80-324/80-34 & 80-325/80-37 Corrective actions withheld (ref 10CFR2 790)
 FURR,B J Carolina Power & Light Co 80/10/27 1p 07029 210

8011210462 Forwards IE Insp Repts 80-324/80-34 & 80-325/80-37 on 800908-12 & notice of violation Details & notice of violation withheld (ref 10CFR2 790)
 KENNA, W B Region 2, Atlanta, Safeguards Branch 80/10/08 2pp 07029 211

8011210464 IE Insp Repts 80-324/80-34 & 80-325/80-37 on 800908-12 Noncompliance noted failure to perform personnel search & failure to provide written security procedures. Details withheld (ref 10CFR2 790)
 HOWELL, J C, TILLMAN, A, MCGUIRE, D R Region 2, Atlanta, Office of the Director 80/10/07 1p 07029 213.

Periodic operating reports & related correspondence

8011140394 Forwards monthly operating repts for Oct 1980.
 TOLLISON, A C Carolina Power & Light Co 80/11/10 1p 06963 032

8011140397 Monthly operating repts for Oct 1980
 WILLIS, E A Carolina Power & Light Co 80/11/03 App 06963 033

Reportable occurrences, LERs & related correspondence

11140023 RO: 80-095-01P & 80-086-01P review of containment atmospheric dilution sys in response to NUREG-057B, indicated logic circuit relay in Units 1 & 2 which did not meet single active failure criteria of sys as stated in FSAR
 TOLLISON, A C Carolina Power & Light Co 80/10/16 App. 06911 001

11100469 Forwards LER 80-078/03L-0
 TOLLISON, A C Carolina Power & Light Co. 80/10/28 1p. 06931-015

8011100473 LER 80-078/03L-0 on 801007, while verifying rod positions, control rod 30-39 had no full out indication Caused by defective rod position indication reed switch Repair set for next long outage Work request re generic problem written
 TOLLISON, A C Carolina Power & Light Co 80/10/28, 2pp 06931, 016

1140039 Forwards LER 80-081/03L-0
 TOLLISON, A C Carolina Power & Light Co 80/11/07 1p 06961:339.

8011140044 LER 80-081/03L-0 on 801010, diesel generator 3 failed to start within required 10-s Caused by stuck manual test button on starting air pilot valve of cylinder 1 Button & housing disassembled & cleaned & button sanded.
 TOLLISON, A C Carolina Power & Light Co 80/11/07 2pp 06961 340

1180661 RO 80-83 on 801017, during routine insp, cracked weld found on PCI discharge line piping support Caused by lack of fusion & weld point Support repaired & reinforced. Facsimile LER ncl
 TOLLISON, A C Carolina Power & Light Co 80/11/11 3pp 6991-253

1210470 Forwards updated LER 80-055/03L-1
 TOLLISON, A C Carolina Power & Light Co 80/11/12 1p 07029.214

8011210472 Updated LER 80-055/03L-1 on 800812.14 & 15, vessel conductivity levels found excessive Caused by breakdown of organics in reactor vessel Conductivity reduced to within specified limits by condensate makeup & reject operations
 TOLLISON, A C Carolina Power & Light Co 80/11/12 2pp. 07029 215

8011250478 Forwards LER 80-076/03L-0
 TOLLISON, A C Carolina Power & Light Co 80/11/19 1p 07056:357.

8011250485 LER 80-076/03L-0 on 801022, primary containment oxygen analyzer 1-CAT-AT-1259-2 observed indicating upscale Caused by failed magnetic analyzer sample cell Magnetic unit replaced & analyzer returned to satisfactory operation
 TOLLISON, A C Carolina Power & Light Co 80/11/19 2pp 07056 358

V Operator Examinations

8011120437 Submits info re shift staffing in response to NRC 800731 ltr transmitting interim criteria
 UTLEY, E E Carolina Power & Light Co. 80/11/05 1p 06953 092.

DOCKET 80-326 UNIV. OF CALIFORNIA AT IRVINE RES REACTOR

J Insurance & indemnity information

8011030283 Requests endorsements & copy of Amend 7 to Policy E-53.
 DINITZ, I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 1p. 06857 207

8011140003 Informs that endorsements, indemnity agreements or most current amendments have not been received & requests provision of all referenced agreements
 DENESS, B J California, Univ of, Berkeley 80/10/31, 1p 06961:220

8011260014 Amend 7 to Indemnity Agreement E-53, changing financial info in Article III, Paragraph 4(b)(2)
 BALTMAN, J. Utility Finance Branch (formerly Antitrust & Indemnity). 80/11/13 1p 07075 294

P Operating license stage documents & correspondence

8011140381 Repts two changes in administrative personnel & const & occupation of add'l living spaces on campus Forwards map showing current status of residential occupancy. Const is in accordance w/Mar 1968 SAR
 MILLER, O E California, Univ of, Irvine 80/11/05 2pp 06963 336

DOCKET 80-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
 EISENHUT, D G Division of Licensing, 80/10/01 3pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
 EISENHUT, D G, Division of Licensing 80/10/06, 6pp

F. Security, medical, emergency & fire protection plans

8011060563 Notification of 801027 meeting w/util in Bethesda, MD to discuss emergency planning for facilities.
 STAHL, C. Licensing Branch 2 CLARK, R A Operating Reactors Branch 2 80/10/16 3pp. 06916.222

8011030347 Forwards add'l info & revisions to security personnel training & qualification plans Info withheld (ref 10CFR2 790).
 MILLS, L M Tennessee Valley Authority 80/10/27 1p. 06867.285

8011030475 Advises that util is revising schedule for technical support ctr as result of guidance in NUREG-0496 & NRC 800903 ltr
 MILLS, L.M. Tennessee Valley Authority 80/10/28, 1p 06860 173.

8011170132 Forwards facility emergency planning info for placement in LPDR, W/o encl
 EDUOER, J.L Division of Rules and Records 80/10/30 1p. 06976 317

DOCKETED ITEMS

O Adjudicatory correspondence

8011280226 Forwards order for mod of license changing license & Tech Specs re documentation requirements for qualification of safety-related equipment
SCHWENCER, A Licensing Branch 2 80/11/06 3pp 06915 001

--8011280229 Order for mod of License DPR-77, adding License Condition 2 C & Tech Spec 6 10 2(a) re documentation requirements for qualification of safety-related equipment Revised license pages encl
EISENHUT, D O Division of Licensing 80/11/06 8pp

--8011280230 Tech Spec 6 10 2(a) re documentation requirements for qualification of safety-related equipment
* Division of Licensing 80/11/06 1p 06915 001

O Advisory Committee on Reactor Safeguards reports & correspondence

8011180003 Transcript of ACRS 247th general meeting to discuss status re: hydrogen control at Sequoyah Units 1 & 2 on 801108 in Washington, DC Pp 392-414
* ACRS - Advisory Committee on Reactor Safeguards 80/11/08 25PP. 06986-039

P Operating license stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

8011050148 Expresses appreciation for cooperation & assistance provided by RG Wallace in establishing TLD program
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/10/23 2pp 06898-347

8011030554 Requests 90-day extension to permit mod granted per 800731 ltr, due to operational problems encountered w/vendor solidification sys Operable solidification sys expected to be available by 801114
EL-ASHRY, M T Tennessee Valley Authority 80/10/28 4pp 01756-001

8011040164 Provides status of installation of interim distributed ignition sys Preoperational testing indicates sys effective & durable Further testing re igniter operability & effects of post-burn environ on matl to be submitted in 801216 rept
MILLS, L M Tennessee Valley Authority 80/10/30 2pp 06878 057

801110239 Forwards test rept re auxiliary feedwater pumps endurance run Util reviewing case of turbine-driven pump bearing exceeding bearing temp acceptance criteria
MILLS, L M Tennessee Valley Authority 80/11/04 1p 06943 067

--801110242 "Test Rept Auxiliary Feedwater Pump Endurance Run"
* Tennessee Valley Authority 80/10/31 37pp 06943.068

801109474 Requests NRC concurrence in change to startup test program sequence Justifications for proposed changes encl
MILLS, L M Tennessee Valley Authority. 80/11/09 2pp 06931 103

8011200354 Informs of approving 801105 ltr requesting concurrence in change to startup test program sequence, delaying three tests until after plant has operated at 50% power plateau Tests are to be performed before 801130. Safety evaluation encl
TEDESCO, R L Assistant Director for Licensing 80/11/03. 1p 01741-017

--8011200355 Safety evaluation supporting 801105 request to delay startup test program sequence until after plant has operated at 50% power
* Office of Nuclear Reactor Regulation, Director 80/11/05 2pp 01741-019

8011260256 Forwards request for addl info re reactor coolant sys vents Response required within 30 days
SCHWENCER, A Operating Reactors Branch 2 80/11/05 4pp 07074 140

8011280226 Forwards order for mod of license changing license & Tech Specs re documentation requirements for qualification of safety-related equipment
SCHWENCER, A Licensing Branch 2 80/11/06 3pp 06915 001

--8011280229 Order for mod of License DPR-77, adding License Condition 2 C & Tech Spec 6 10 2(a) re documentation requirements for qualification of safety-related equipment Revised license pages encl
EISENHUT, D O Division of Licensing 80/11/06 8pp

--8011280230 Tech Spec 6 10 2(a) re documentation requirements for qualification of safety-related equipment
* Division of Licensing 80/11/06 1p 06915 001

8011180469 Forwards "Determination of Ignition Performance Characteristics of Glow Plug Hydrogen Ignitor," conducted by Fenwal Corp Tests constitute Phase 1 of glow plug ignitor performance tests Complete results will be sent by 801201
MILLS, L M Tennessee Valley Authority 80/11/13 1p 06989

--8011180477 "Determination of Ignition Performance Characteristics of Glow Plug Hydrogen Ignitor"
DALZELL, W O, GILLIS, J P Walter Kilde & Co, Inc; Fenwal, 80/11/10 11pp 06989 078

8011210271 Forwards application for amend to License DPR-77, to re concerns addressed in IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture"
MILLS, L M Tennessee Valley Authority 80/11/18 2pp 02227

--8011210276 Application to amend License DPR-77, to resolve concerns addressed in IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture" Response & justification encl
* Tennessee Valley Authority 80/11/18 14pp 02227 001.

8011260148 Forwards application for amend to License DPR-77 to authorize storage of low level radwaste generated by onsite plant operation
MILLS, L M Tennessee Valley Authority 80/11/24 2pp 07072

--8011260161 Application for amend to License DPR-77, authorizing of low level radwaste generated by onsite plant operation
* Tennessee Valley Authority 80/10/31 60pp 07072 003

O Inspection reports, IE Bulletins & correspondence

8011050507 Forwards IE Insp Rept 50-327/80-29 on 800706-31 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Supp Branch 80/09/08. 2pp. 06900 203

--8011050513 IE Insp Rept 50-327/80-29 on 800706-31 No noncompliance noted Major areas inspected operational safety verification, startup test witnessing, verification of license conditions & followup on plant incidents
GOTTLIEB, T, BUTLER, B D, DANCE, H C Region 2, Atlanta, Office of the Director 80/09/08 9pp 06900-203

8011210405 Forwards IE Waste Packaging Insp Repts 50-327/80-33 & 50-328/80-18 on 800811 & 25 No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/15 2pp 07034 014

--8011210415 IE Waste Packaging Insp Repts 50-327/80-33 & 50-328/80-18 & 25 No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels & removable contamination
MACARTHUR, T C, PUCKETT, J M, POTTER, J P, Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/14 3pp 07034 010

801140271 Forwards response to IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture" Mode will be completed by 801115
MILLS, L M Tennessee Valley Authority 80/10/16 14pp 0696

801170669 Forwards Suppl 3 to IE Bulletin 79-010, "Environmental Qualification of Class IC Equipment" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/11/16 1p.

801130232 Ack receipt of 801006 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-327/80-31
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Supp Branch. 80/10/30. 1p 06959.134

DOCKETED ITEMS

--801130241 Responds to NRC 800911 ltr re violations noted in IE Insp Rept 80-327/80-31 Refutes item of noncompliance Reinstucted employees to prevent future problems re startup test program documentation
MILLS,L M Tennessee Valley Authority 80/10/06 3pp
06959 138

--801130248 Forwards IE Insp Rept 80-327/80-31 on 800722-25 & notice of violation
LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/11 2pp 06959 138

--801130250 Notice of violation from insp on 800722-25
* Region 2, Atlanta, Office of the Director 80/09/10 1p
06959 140

--801130256 IE Insp Rept 80-327/80-31 on 800722-25, Noncompliance noted. Failure to document Test SU-76 deficiency when inaccuracy of control rod reactivity worth measurement data was noted
JULIAN,C A Region 2 Atlanta, Office of the Director DANCE,H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/10 4pp 06959 141

8011210068 Act receipt of 801020 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-327/80-34.
STOHR,J P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/11/07 1p 07031 190

--8011210078 Responds to NRC 800926 ltr re violations noted in IE Insp Rept 80-327/80-34 Corrective actions,untrained operators immediately removed from fire brigade duties.
MILLS,L M Tennessee Valley Authority 80/10/20 2pp
07031 191

--8011210083 Forwards IE Insp Rept 80-327/80-34 on 800820-22 & notice of violation
STOHR,J P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/26 2pp 07031:193

--8011210087 Notice of violation from insp on 800820-22
* Region 2, Atlanta, Office of the Director 80/09/25 1p
07031 195

--8011210093 IE Insp Rept 80-327/80-34 on 800820-22 Noncompliance noted failure to implement procedures re training requirements for fire brigade duties
ANDREWS,D L , ALLEN,J R , OIBSON,O Region 2, Atlanta, Office of the Director 80/09/29, 13pp 07031 196

011210271 Forwards application for amend to License DPR-77, to resolve concerns addressed in IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture"
MILLS,L M Tennessee Valley Authority 80/11/18 2pp 02227.001

--8011210276 Application to amend License DPR-77, to resolve concerns addressed in IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture" Response & justification encl
* Tennessee Valley Authority. 80/11/18 14pp 02227 001

Periodic operating reports & related correspondence

31180568 Forwards monthly operating rept for Oct 1980.
HALLERTINE,J M Tennessee Valley Authority 80/11/12. 1p.
06989-277

--801180571 Monthly operating rept for Oct 1980
DUPREE,D. Tennessee Valley Authority 80/10/31 10pp
06989 278

Reportable occurrences, LERs & related correspondence

111020534 Forwards LER 80-160/03L-0
CALHOUN,J R Tennessee Valley Authority 80/10/24. 1p. 06855-033

8011030540 LER 80-160/03L-0 on 800926,containment differential pressure re annulus exceeded Tech Spec limits during RCS heatup
Caused by containment atmosphere heatup & normal control air leakage,Pressure reduced by venting
COTTLE,W T , KIRK,O B Tennessee Valley Authority. 80/10/24 2pp 06855-034.

11040573 Forwards LER 80-166/03L-0
CALHOUN,J R Tennessee Valley Authority 80/10/24 1p 06873 092.

--8011040575 LER 80-166/03L-0 on 800927,during normal operation in mode 4,output breaker for vital inverter 2-IV tripped rendering vital instrument power board 2-IV inoperable Caused by bad auxiliary switch on KI relay Auxiliary switch replaced
ROMINE,W D Tennessee Valley Authority 80/10/24 2pp
06873-093

8011040389 Forwards LER 80-158/01T-0
CALHOUN,J R Tennessee Valley Authority 80/10/28 1p 02319-196

--8011040393 LER 80-158/01T-0 on 801015,emergency gas treatment sys discharge dampers to shield bldg exhaust stack would not operate in manual or automatic from main control room
Caused by const electrician error Leads replaced
COTTLE,W T , KELSTON,A H Tennessee Valley Authority 80/10/28 1p 02319 196

8011040443 Forwards LER 80-150/03L-0
CALHOUN,J R Tennessee Valley Authority 80/10/28 1p 06884:228

--8011040453 LER 80-150/03L-0 on 800927 during surveillance in Mode 3, check valve leak rate exceeded Tech Spec limit Caused by valve 63-635 stuck in open position due to interference between disc nut lockwire tack weld & valve body
COTTLE,W T , KIRK,O B Tennessee Valley Authority 80/10/28 2pp 06884 229

8011040599 Forwards LER 80-159/01T-0
GREEN,H J Tennessee Valley Authority 80/10/28 1p 06873 103

--8011040606 LER 80-159/01T-0 on 801015,util notified that major feedwater line rupture on either steam generator 3 or 4 concurrent w/loss of Channel 1-1 vital instrument power could prevent auxiliary feedwater sys from operating
COTTLE,W T , MADDOX,B G Tennessee Valley Authority 80/10/28 2pp 06873:106

8011040193 NP088 noncompliance notification re Permit TN0026450 on 801022,cooling tower blowdown sample exceeded limitations
Caused by decrease in cooling tower blowdown flow w/o decrease in boron waste tank flow Blowdown flow increased
EL-ASHRY,H T Tennessee Valley Authority 80/10/29 2pp
02319 196

8011120421 Forwards LER 80-161/03L-0
GREEN,H J Tennessee Valley Authority 80/10/31. 1p 06916 001

--8011120428 LER 80-161/03L-0 on 801004 & 11,pressurizer relief tank level indicator LI-68-312C found inoperable Caused by transmitter dry leg being full of water Leg drained.
COTTLE,W T , KIRK,O B Tennessee Valley Authority 80/10/31 1p
06916 001

8011120432 Forwards LER 80-162/03L-0
GREEN,H J Tennessee Valley Authority 80/10/31 1p 06916-001

--8011120439 LER 80-162/03L-0 on 801002,RCS average temp decreased below Tech Spec 3 1 1.4 limit of 341 F Caused by overfeeding water to steam generators Feedwater flow decreased,allowing RCS temp to increase above lower limit
COTTLE,W T , KIRK,O B Tennessee Valley Authority. 80/10/31 2pp 06916 001

8011120455 Forwards LER 80-164/03L-0
GREEN,H J Tennessee Valley Authority 80/10/31 1p. 06916-001

--8011120462 LER 80-164/03L-0 on 801003,condensate storage tank B water vol decreased below Tech Spec 3 7 1 3 limit of 190,000 gallons.Caused by makeup water supply being out of svc for regeneration of demineralizers
RECORD,D J Tennessee Valley Authority 80/10/31 1p
06916 001

8011120481 Forwards LER 80-153/03L-0
GREEN,H J Tennessee Valley Authority 80/10/31 1p. 06916-001

--8011120488 LER 80-153/03L-0 on 801002,operator observed RCS indicator TI-68-44D was reading low Caused by one lead of resistance temp detector cable w/excessive resistance.Cable transferred to spare penetration
COTTLE,W T , KIRK,O B Tennessee Valley Authority. 80/10/31 1p
06916:001

8011120488 Forwards LER 80-144/03L-0
GREEN,H J Tennessee Valley Authority 80/11/03 1p 06952.195.

DOCKETED ITEMS

13

--B01120475 LER 80-144/03L-0 on B01005, performance of SI-276 discovered auxiliary feedwater sys valves LCV-3-174 & LCV-3-173 would not operate automatically Caused by isolation of pressure switch PS-3-1388 Switch returned to svc
HECK, P S Tennessee Valley Authority 80/11/03 3pp. 06932 196.

B011180640 Forwards LER 80-163/03L-0
GREEN, H J Tennessee Valley Authority 80/11/10 1p 06992 003.

--B011180648 LER 80-163/03L-0 on B01012, both ventilation chlorine detectors O-CLAN-43-203A & B declared inoperable due to clogged electrolyte flow to sensor Caused by clogged electrolyte in capillary tubing & felt filter Parts cleaned
COTTE, W T, WILKEY, A M Tennessee Valley Authority 80/11/10, 1p. 06992 004

B011180707 Forwards updated LER 80-156/01X-1
GREEN, H J Tennessee Valley Authority 80/11/10 1p 06915 001

--B011180719 Updated LER 80-156/01X-1 on B01005, leakage noted from seal injection line to reactor coolant pump 3 Caused by line failure due to vibration Line replaced & addl pipe supports installed
COTTE, W T Tennessee Valley Authority 80/11/10 3pp 06915 001

B011180624 Forwards LER 80-169/03L-0
GREEN, H J Tennessee Valley Authority 80/11/12 1p 06988 133

--B011180633 LER 80-169/03L-0 on B01014, output breaker for vital inverter 2-111 tripped rendering vital instrument power board inoperable Caused by failure of clock card RBB Clock card replaced
COTTE, W T, MADDOX, S G Tennessee Valley Authority 80/11/12 1p. 06988 134

B011180634 Forwards LER 80-165/03L-0.
GREEN, H J Tennessee Valley Authority. 80/11/12 1p. 06992 001.

--B011180644 LER 80-165/03L-0 on B01014, essential raw cooling water monitors O-RE-90-134 & -141 declared inoperable Caused by auxiliary feedwater sys header pulsations causing pressure switches to chatter Snubbers added
COTTE, W T, WILKEY, A M Tennessee Valley Authority. 80/11/12, 1p 06992 002

B011180682 Forwards LER 80-167/03L-0
GREEN, H J Tennessee Valley Authority. 80/11/12 1p. 06988 147.

--B011180691 LER 80-167/03L-0 on B01013, auxiliary bldg vent monitor O-RH-90-110 declared inoperable Caused by loss of sampling pump due to circuit breaker tripping during momentary overload. Circuit breaker reset & monitor returned to svc
RABURRY, J L Tennessee Valley Authority. 80/11/12 1p 06988 148.

B011210492 Forwards LER 80-170/03L-0
GREEN, H J Tennessee Valley Authority 80/11/14, 1p 07034 074

--B011210497 LER 80-170/03L-0 on B01016, while in Mode 4, two intermediate deck doors in ice condenser discovered frozen closed. Caused by failed heat tapes on air handling unit drain line Heat tape replaced & ice removed
COTTE, W T, KIRK, Q B Tennessee Valley Authority. 80/11/14 2pp 07034 075

B011210569 Forwards LER 80-175/03L-0.
GREEN, H J Tennessee Valley Authority 80/11/14 1p. 07034 031.

--B011210574 LER 80-175/03L-0 on B01016, while performing SI-28, containment air fan damper B-B would not open Caused by lubrication needed on damper bearings Damper bearings lubricated & damper retested
COTTE, W T, KIRK, Q B Tennessee Valley Authority 80/11/14 1p. 07034 032

B011240332 Forwards LER 80-177/03L-0
GREEN, H J Tennessee Valley Authority 80/11/14 1p. 02227 001.

--B011240337 LER 80-177/03L-0 on B01016, lower inlet doors to ice condenser opened during test. Caused by leakage through improperly secured inlet damper Doors closed, damper rescrewed & damper will be covered during future tests.
* Tennessee Valley Authority. 80/11/14 1p. 02227 001.

B011210502 NPDES Noncompliance Notification of Discharge 19 on B01016 & 20, samples of svc bldg sump discharge contained 24 mg/l 17 mg/l, respectively, of oil & grease Caused by accumulation in sump & mixing w/ discharge water Sump cleaned
EL-ASHRY, M T Tennessee Valley Authority 80/11/17 2pp 02227 001

B011250395 Forwards LER 80-171/03L-0
GREEN, H J Tennessee Valley Authority 80/11/17 1p. 07056 337

--B011250403 LER 80-171/03L-0 on B01016, diesel generator 18-B tripped during performance of SI-7 1 Caused by replacing of red indicating light of O60A relay Socket repaired
COTTE, W T, MADDOX, S G Tennessee Valley Authority 80/11/17, 2pp 07056 338

B011250336 Forwards LER 80-176/03L-0
GREEN, H J Tennessee Valley Authority 80/11/21 1p 07056 318.

B011250387 Forwards LER 80-178/01T-0
GREEN, H J Tennessee Valley Authority 80/11/21, 1p. 07056 335

--B011250390 LER 80-178/01T-0 on B01031, containment Upper compartment temp found too cool Caused by entering of Unit 1 into Mode 1 w/ temp too cool Upper compartment temp increased above min required level
COTTE, W T, KIRK, Q Tennessee Valley Authority 80/11/21 1p 07056 336

B011250449 Forwards LER 80-173/01T-0
GREEN, H J Tennessee Valley Authority 80/11/24 1p. 07056 349.

--B011250455 LER 80-173/01T-0 on B01103, potential discovered for line failure during seismic event due to missing hangers on component cooling water supply piping to centrifugal charging pump mechanical seals Caused by drawing omission.
* Tennessee Valley Authority 80/11/24 1p 07056 350

V Operator Examinations

B011140325 Forwards info describing operator training & qualification programs which comply w/ criteria addressed in B00328 ltr to all power reactor applicants & licensees.
MILLER, L M Tennessee Valley Authority 80/11/10 8pp

B011180527 Forwards "Bequoyah Nuclear Plant Shift Technical Advisor Training & Requalification Program Outline."
MILLER, L M Tennessee Valley Authority. 80/11/13 1p 06989 045.

--B011180530 "Bequoyah Nuclear Plant Shift Technical Advisor Training & Requalification Program Outline "
* Tennessee Valley Authority 80/11/13 31pp. 06989 046.

DOCKET 80-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

B011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by B01101.
EISENHUT, B O. Division of Licensing 80/10/01 5pp

B011100537 Ltr to all power reactor licensees & applicants forwarding summary of B00827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " w/o encl.
EISENHUT, B O Division of Licensing 80/10/06 6pp

B011180777 Requests Class II fee for B00307 application to extend completion date for CRR-73 Ofc of Nuclear Reactor Regulation extended completion date on B00404.
DIOGB, R License Fee Management Branch 80/10/20 1p 06991 339.

B011050148 Expresses appreciation for cooperation & assistance provided by RO Wallace in establishing TLD program
STOHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/10/23 2pp 06898 347

B011200186 Informs that French have taken no action re installation of reactor vessel vents Necessity of vents under study by French licensing authorities.
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/10/24 2pp 07021 214

DOCKETED ITEMS

--B011200199 Informs of telcon re reviews by French authorities of reactor sys venting French have taken no action in this regard & studies under review indicate installation of vents on pressure vessel not necessary for safety
LAFLEUR, J D Office of International Programs, Director
80/09/02 1p 07021 216

--B011200165 Staff requirements memo directing staff to evaluate hydrogen control issue, requesting draft Insp Rept 50-328/80-39 info on status of installation of reactor vessel vents on French reactors.
CHILK, S J Office of the Secretary of the Commission, 80/08/25.
2pp. 07021 217

B011030954 Requests 90-day extension to permit mod granted per B00731 ltr, due to operational problems encountered w/vendor solidification sys. Operable solidification sys expected to be available by B01014
EL-ASHRY, M T Tennessee Valley Authority 80/10/28 4pp
01756:001

B011260236 Forwards request for addl info re reactor coolant sys vents. Response required within 30 days
SCHNEIDER, A Operating Reactors Branch 2 80/11/05. 4pp.
07074 140

B011140439 Requests that NRC revise scheduling to support facility current B010304 fuel loading date
MILLS, L M Tennessee Valley Authority 80/11/10. 1p 06963 359

B011180345 Informs that licensee has resumed testing of RCS & reactor pressure vessel baseline insps, caliber of instrumentation & loop tests of instrumentation circuits, & preoperational tests commenced prior to B01110
MILLS, L M Tennessee Valley Authority 80/11/12 1p. 06988 249.

B011210481 Informs that proposed deletion of high pressure blowdown tests acceptable
TEDESCO, R L Assistant Director for Licensing 80/11/14. 3pp.
07029:230

B011260148 Forwards application for amend to License DPR-77 to authorize storage of low level radwaste generated by onsite plant operation.
MILLS, L M Tennessee Valley Authority 80/11/24 2pp 07072:001.

--B011260161 Application for amend to License DPR-77, authorizing storage of low level radwaste generated by onsite plant operation.
* Tennessee Valley Authority 80/10/31 40pp. 07072.003

F Security, medical, emergency & fire protection plans

B011040963 Notification of B01027 meeting w/util in Bethesda, MD to discuss emergency planning for facilities
RYAN, L E, Licensing Branch 2, CLARK, R A Operating Reactors Branch 2, 80/10/16 3pp 06916 222

B011020347 Forwards addl info & revisions to security personnel training & qualification plans info withheld (ref LOCFR2 790)
MILLS, L M Tennessee Valley Authority 80/10/27. 1p 06867:285.

B011030475 Advises that util is revising schedule for technical support ctr as result of guidance in NUREG-0676 & NRC B00903 ltr
MILLS, L M Tennessee Valley Authority 80/10/28 1p. 06860:175

D Advisory Committee on Reactor Safeguards reports & correspondence

B011809003 Transcript of ACRS 247th general meeting to discuss status reft re hydrogen control at Sequoyah Units 1 & 2 on B01108 in Washington, DC Pp 392-414
* ACRS - Advisory Committee on Reactor Safeguards. 80/11/08. 25PP.
06908:059

P. Operating license stage documents & correspondence

B011030354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D O. Division of Licensing. 80/09/03. 207pp.

3. Inspection reports, IE Bulletins & correspondence

11210405 Forwards IE Waste Packaging Insp Repts 50-327/80-33 & 50-328/80-18 on B00811 & 25. No noncompliance noted
YOH, J P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/10/13. 2pp. 07034:014

--B011210415 IE Waste Packaging Insp Repts 50-327/80-33 & 50-328/80-18 on B00811 & 25. No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels & removable contamination
MACARTHUR, T. C , PUCKETT, J M , POTTER, J. P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/14 3pp 07034:016

B01170687 Forwards Suppl 3 to IE Bulletin 79-018, "Environment Qualification of Class IE Equipment " No written response required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/24. 1p. 06976 234

S Reportable occurrences, LERs & related correspondence

B011030590 Fourth interim deficiency reft re qualification of Class IE equipment in valve room Reft revises erroneous info in third interim reft re replacement of pressure transmitters. Next reft will be forwarded by B01211
MILLS, L M Tennessee Valley Authority 80/10/24 1p 06860 165

B011040193 NPDES noncompliance notification re Permit TN0026450 on B01022, cooling tower blowdown sample exceeded limitations. Caused by decrease in cooling tower blowdown flow w/o decrease in boron waste tank flow. Blowdown flow increased
EL-ASHRY, M T Tennessee Valley Authority 80/10/29 2pp
02319 196

B011050462 Final interim deficiency reft first reported B00516, re design criteria for secondary side pipe breaks. Design did not adequately protect steam generator blowdown lines. Supports & barrier required to mitigate any pipe rupture
MILLS, L M Tennessee Valley Authority 80/10/29 2pp. 06897:252.

B011070429 First interim deficiency reft re seismic analysis of check valve in chemical & vol control sys. During design review, 3-inch check valve overlooked in piping analysis. Will perform re-analysis
MILLS, L M Tennessee Valley Authority. 80/10/31 2pp. 06921:055.

B01130391 Final deficiency reft originally submitted B01006 re essential raw cooling water pump motor relays OE IAC65 overcurrent relays w/tap range of 2.5 to 5.0 amperes have been installed for 700 horsepower pumps
MILLS, L M Tennessee Valley Authority 80/11/05. 2pp 06959:218

B01140049 Final deficiency reft originally reported on B01007 re auxiliary feedwater design deficiency. Mods will provide independent control power supply to auxiliary feedwater sys turbine-driven pump
MILLS, L M Tennessee Valley Authority 80/11/05 2pp 06963.235

B011210580 First interim deficiency reft re nonreinforced concrete masonry block walls. Walls have been identified & design criteria developed for usage in structural analysis. Next reft will be submitted by B01020
MILLS, L M Tennessee Valley Authority 80/11/14 2pp. 07031.355

B011250395 First interim deficiency reft re offsite power voltage fluctuation. Util attempting to obtain vendor documentation to substantiate 85% voltage starting capability. Next reft will be submitted by B01027.
MILLS, L M Tennessee Valley Authority 80/11/19. 2pp. 07055:156.

V. Operator Examinations

B01140325 Forwards info describing operator training & qualification programs which comply w/criteria addressed in B00328 ltr to all power reactor applicants & licensees
MILLS, L M Tennessee Valley Authority. 80/11/10 8pp

B011180527 Forwards "Sequoyah Nuclear Plant Shift Technical Advisor Training & Requalification Program Outline "
MILLS, L M Tennessee Valley Authority 80/11/13. 1p. 06989:045.

--B011180530 "Sequoyah Nuclear Plant Shift Technical Advisor Training & Requalification Program Outline."
* Tennessee Valley Authority. 80/11/13 31pp. 06989:046.

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A. Application/construction stage documents & correspondence

B007290759 Submits fourth bi-monthly ltr for period B00520-0720 re interagency agreement. Pending NRC acceptance. Subtask 1 of Task 1 & Subtask 1 of Task 2 complete. Oversize chart encl.
MCALLISTER, P. Army, Dept of, Corps of Engineers. 80/07/25 3pp
06026:318.

8011050354 Ltr to all licensees of operating plants, applicants for OLS & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D. G. Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D. G. Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D. G. Division of Licensing, 80/10/06 6pp

801110170 Forwards table listing settlement stresses of profiled sys for underground piping Requests info re methodology used to obtain results
TEDESCO, R. L. Division of Licensing 80/10/20 4pp 06943 343

8011060621 Forwards addl Category I masonry wall drawings to replace 800903 submittals.
COOK, J. W. Consumers Power Co 80/10/21 2pp 06913 001.

--8011060624 "Miscellaneous Plans & Details," Sheet 1.
* Bechtel Corp. 7220 78/08/16 1p

--8011060640 "Auxiliary Bldg Section D"
* Bechtel Corp. 7220 79/10/06 1p.

--8011060643 "Interior Elevations Auxiliary Bldg Concrete Block Walls at Elevation 599 Ft." Sheet 1 of 2
* Bechtel Corp. 7220 76/11/23. 1p

--8011060647 "Interior Elevations - Auxiliary Bldg Concrete Block Walls at Elevation 599 Ft." Sheet 2 of 2
* Bechtel Corp. 7220 76/11/23 1p

--8011060651 "Interior Elevations Auxiliary Bldg Concrete Block Walls at Elevation 614 Ft."
* Bechtel Corp. 7220 76/12/01 1p

--8011060654 "Interior Elevations Auxiliary Bldg Concrete Block Walls at Elevation 614 Ft & 624 Ft"
* Bechtel Corp. 7220 77/02/04 1p

--8011060657 "Interior Elevations Auxiliary Bldg Concrete Block Walls at Elevation 614 Ft & 624 Ft"
* Bechtel Corp. 7220. 77/02/04. 1p.

--8011060662 "Interior Elevations Auxiliary Bldg Concrete Block Walls at Elevation 634 Ft-6 Inches, 643 Ft"
* Bechtel Corp. 7220. 77/02/28. 1p.

--8011060666 "Auxiliary & Reactor Bldg Floor Plan Elevation 614 Ft & 626 Ft (W Area)."
* Bechtel Corp. 7220 80/07/11 1p

--8011060671 "Auxiliary Bldg Floor Plan Elevation 646 Ft."
* Bechtel Corp. 7220. 80/07/11. 1p.

801180424 Responds to 801001 ltr re "Environ Qualification of Safety-Related Equipment" Encl list represents planned environ qualification testing to be performed during 1981-82.
COOK, J. W. Consumers Power Co. 80/11/10. 3pp. 06992.136.

8011210225 Advises of decision to support 800914 request for relief from making addl borings & associated soil tests in 18 areas by relaxing six penetration tests in vicinity of plant. Details, including changed boring locations, will be provided.
TEDESCO, R. L. Assistant Director for Licensing. 80/11/10. 1p. 02227:001.

8011280138 Informs that operability test program now included for preservice insp & preoperational testing of snubber thermal motion. Forwards request that Chapter 14 of FBAR be revised to reflect acceptance.
TEDESCO, R. L. Assistant Director for Licensing. 80/11/13. 14pp

801180151 Forwards Bechtel Corp rept, "Summary of Settlement Stress Calculations for Buried Piping." Requests followup meeting w/NRC consultants Differential settlement piping stress calculational input sheets encl.
COOK, J. W. Consumers Power Co. 80/11/14 1p. 06913:001.

--801180155 "Summary of Settlement Stress Calculations for Buried Piping"
* Bechtel Associates Professional Corp 80/11/14 88pp 06913 001

8011260083 Forwards Amend B5 to application for CPs & OLS, incorporating responses to Questions 34-33 & info re plant fill & updating info re piezometer & settlement readings, plots of cross sections for new boring locations & commitment dates
COOK, J. W. Consumers Power Co 80/11/21 2pp 07085 211

--8011260087 Amend B5 to application for CPs & OLS, incorporating responses to Questions 39-33 & info re plant fill & updating info re piezometer & settlement readings, plots of cross-sections for new boring locations & commitment dates
* Consumers Power Co 80/11/21 1400pp 07085 215

C Utility Environmental Report (ER), amends & correspondence

8011060461 Comments on environ rept, Amend B2, Revision 11 Water quality data presented in Section 2.2.4 should be incorporated as app
* Interior, Dept of, Fish & Wildlife Service 80/10/24. 1p 02319:196.

F. Security, medical, emergency & fire protection plans

801170003 Forwards facility emergency planning info for placement in LPDR W/o encl.
BOUDER, J. L. Division of Rules and Records 80/11/04 1p 06978.264

G. Adjudicatory correspondence

8011140042 Notice of 801117 & 19 depositions of O. Gallagher for NRC & J.W. Simpson for Corps of Engineers, respectively Oral examination will address issues of 791206 order modifying CPs & contentions of ASLB 801024 prehearing order
FARNELL, A. S. Consumers Power Co. FARNELL, A. S. Isham, Lincoln & Beale. 80/11/05 2pp 06961 344

--8011140047 Notice of continuation of J. Kane & L. Heller depositions on 801202 & 04, respectively Certificate of Bvc encl
FARNELL, A. S. Consumers Power Co. FARNELL, A. S. Isham, Lincoln & Beale. 80/11/05 3pp 06961:346

8011140466 Forwards documents in response to RJ Vollen 800918 request for production Remaining discoverable documents will be provided when identified
OULDERO, S. C. Hearing Branch 2. 80/11/07. 3pp 06965.130

--8011140538 Discusses followup actions to 791113 meeting Consultants will be guided to use decision point meetings that culminate in declaration of final NRC position, DOD 800211 internal memo & summary of 791113 meeting encl.
KNIGHT, J. P. Assistant Director for Engineering 79/11/14 13pp. 06965 168

--8011140546 Submits status of geotechnical review by Corps of Engineers. One reviewer made cursory examination of info & visited both plants. Three-man review team needed to accomplish review DOD 800201 internal memo encl
HELLER, L. W. Geosciences Branch NRC-03-89-167. 80/01/23 7pp 06965:181

8011140552 Forwards depositions of L.W. Heller, J. Kane, T. Cooke, D. Horn, O. Keely & S. Afifi taken during Oct 1980 W/o encl
JONES, B. H. Hearing Branch 2 80/11/12 2pp 06963:216

801180166 Appeal from ASLB 800910 prehearing order which stands moot re jurisdiction over soil settlement & compacted fill matls Urges admission of intervenor 800927 ltr Certificate of Bvc encl.
MARSHALL, W. H. Mapleton Intervenors. 80/11/12. 15pp. 06987 221

8011190126 First set of interrogatories directed to NRC re acceptance criteria cited in 791206 order modifying CPs & items of info requested by NRC after issuance of order Certificate of Bvc encl.
FARNELL, A. S. Consumers Power Co FARNELL, A. S. Isham, Lincoln & Beale. 80/11/12. 9pp. 06999.138.

801170881 Order granting intervenors, Other Than Dow Chemical, opportunity to submit written briefs & proposed findings re remanded proceeding, by 801229. Parties are given 30 days for responses, from date of such filing
MILLER, M. E. Atomic Safety and Licensing Board Panel 80/11/14 4pp. 06978.089.

DOCKETED ITEMS

8011200303 Responds to 801112 request that appeal papers be reproduced & forwarded to parties in proceeding Procedural assistance, per NRC regulations does not extend to appeal papers Relevant FR notice encl
CHD, J Atomic Safety and Licensing Appeal Panel 80/11/14 5pp.
01741 019

G Inspection reports, IE Bulletins & correspondence

8011040291 Forwards IE Insp Repts 50-329/80-24 & 50-330/80-25 on 800826-27 No noncompliance noted
KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/16 2pp 06911 266

--8011060295 IE Insp Repts 50-329/80-24 & 50-330/80-25 on 800826-27 No noncompliance noted Major areas inspected mgt control & implementation & results of preoperational radiological & nonradiological environ protection requirements
GREER, R J, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/09/09 3pp 06911 268

8011030978 Forwards IE Insp Repts 50-329/80-21 & 50-330/80-22 on 800716-18, 0804-06 & 11-14 & notice of violation
KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/17 2pp 06857 180

--8011030105 Notice of violation from insp on 800716-18, 0804-06 & 11-14, * Region 3, Chicago, Office of the Director, 80/09/12 1p 06857 182

--8011030111 IE Insp Repts 50-329/80-21 & 50-330/80-22 on 800716-18, 0804-06 & 11-14 Noncompliance noted failure to perform audit of Photon Testing, Inc re svc to qualify welders
VANDEL, T E, LEE, E W K, KNOPF, R C Region 3, Chicago, Office of the Director 80/09/12 12pp 06857 183

8011060284 Forwards IE Insp Repts 50-329/80-29 & 50-330/80-30 on 800901-30 No noncompliance noted
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/03 2pp 06911 245

--8011060292 IE Insp Repts 50-329/80-29 & 50-330/80-30 on 800901-30 No noncompliance noted Major areas inspected site conditions, damage to generator rotor, welding procedures & tightness of GC insps
COOK, J W, KNOPF, R C Region 3, Chicago, Office of the Director 80/10/03 6pp 06911 247

8011200287 Forwards IE Insp Repts 50-329/80-28 & 50-330/80-29 on 800923-25 & notice of violation
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/08 2pp 07020 019

--8011200290 Notice of violation from insp on 800923-25 * Region 3, Chicago, Office of the Director 80/10/07 1p 07020 021

--8011200294 IE Insp Repts 50-329/80-28 & 50-330/80-29 on 800923-25 Noncompliance noted weld control record indicated that authorized nuclear inspector hold point on weld drawing not initiated & dtd before work
LEE, E W K Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/07 6pp 07020 022

8011040163 Forwards final response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " No design changes for nitrogen/hydrogen cover gas sys required
COOK, J W Consumers Power Co 80/10/10 3pp 06885 088

8011190311 Responds to IE Bulletin 80-19, Revision 1 re CP Clare Model H02X-1011 mercury-wetted relays Relays neither used nor planned for use in logic matrix of facility reactor protection sys Approx 14 manhours expended for review
COOK, J W Consumers Power Co 80/10/22 1p 06996 278

8011260019 Advises of status of actions to correct errors in 790703 & 0815 responses to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "
COOK, J W Consumers Power Co 80/10/31 3pp 07070 330

11190445 Ack receipt of 801022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/80-21 & 50-330/80-22
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/05 1p 06998 083

--8011190446 Responds to NRC 800917 ltr re violations noted in IE Insp Repts 50-329/80-21 & 50-330/80-22 Corrective actions Zack Co initiated purchase order addressing applicable requirements of 10CFR30, App B
COOK, J W Consumers Power Co 80/10/22 3pp 06998 084

S Reportable occurrences, LERs & related correspondence

8011040399 Final deficiency rept re inconsistent cross-referencing between B&W & Bechtel numbering sys affecting instrument sys Utilis agreed that no changes in component numbering are required instrument index & electric schemes to be revised
COOK, J W, ANDERSON, J M, CURTIS, L H Consumers Power Co 80/10/31 3pp 02319 196

8011040405 Interim deficiency rept re sway struts containing loose or totally disengaged rod end bushings Insp will be conducted to determine if bushings are loose or improperly installed. Next rept by 801219
COOK, J W, Consumers Power Co 80/10/31 12pp 06874 178.

8011040511 Interim deficiency rept re safe shutdown boration capability assuming restrictive core condition & control rod of highest worth stuck out-of-core FBAR being revised Equipment to be installed by Sept 1981 Next rept to be sent by 801717.
COOK, J W Consumers Power Co 80/10/31 2pp

801100620 Interim deficiency rept re containment internal structures coating deficiency Submits Bechtel interim Rept 3, updating evaluation & corrective action on decontaminable coating Sys 9 failure Interim or final rept to be submitted by 810301
COOK, J W Consumers Power Co 80/10/31 239pp 06930 022.

8011170181 Ack receipt of 801010 interim deficiency rept re small break/reactor coolant pump operation interaction.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch, 80/11/03 1p 06981 206

8011170206 Ack receipt of 801010 interim deficiency rept re letdown cooler supports.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/03 1p 06969 053

8011140038 Confirmatory deficiency rept originally reported on 801008 re effect of failure of component cooling water on nonessential & essential safety-related portions Component cooling water surge tank level will be maintained.
COOK, J W Consumers Power Co 80/11/07 7pp 06960 228

T Hearing transcripts on non-antitrust matters

8011240443 Transcript of 801029 deposition of SA Afifi in Ann Arbor, MI Pp 1-123 Prof qualifications encl
AFIFI, S A Bechtel Corp 80/10/29 123pp 07048 233

V Operator Examinations

8011060074 Notification of 801029 meeting w/util in Bethesda, MD to discuss operator training & qualification programs
HOOD, D Licensing Branch 3 80/10/17 4pp 06912:345

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8007290759 Submits fourth bi-monthly ltr for period 800520-0720 re interagency agreement Pending NRC acceptance, Subtask 1 of Task 1 & Subtask 1 of Task 2 complete, Oversize chart encl
MCALLISTER, P Army, Dept of, Corps of Engineers 80/07/25 3pp 06026 318

8011030354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D G Division of Licensing, 80/09/03 209pp

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D G Division of Licensing, 80/10/01 5pp.

8011100837 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports," W/o encl.
EISENHUT, D G Division of Licensing 80/10/06 6pp.

801110170 Forwards table listing settlement stresses of profiled sys for underground piping Requests info re methodology used to obtain results
TEDESCO, R L Division of Licensing 80/10/20 4pp 06943 343

8011060621 Forwards addl Category I masonry wall drawings to replace 800903 submittals
COOK, J W Consumers Power Co 80/10/21 2pp 06913 001

--8011060624 "Miscellaneous Plans & Details " Sheet 1
* Bechtel Corp 7220 78/08/16 1p

--8011060640 "Auxiliary Bldg Section D "
* Bechtel Corp 7220 79/10/06 1p

--8011060643 "Interior Elevations Auxiliary Bldg Concrete Block Walls at Elevation 599 Ft " Sheet 1 of 2
* Bechtel Corp. 7220 76/11/23 1p

--8011060647 "Interior Elevations - Auxiliary Bldg Concrete Block Walls at Elevation 599 Ft. " Sheet 2 of 2
* Bechtel Corp. 7220 76/11/23 1p

--8011060651 "Interior Elevations Auxiliary Bldg Concrete Block Walls at Elevation 614 Ft "
* Bechtel Corp. 7220 76/12/01 1p

--8011060654 "Interior Elevations Auxiliary Bldg Concrete Block Walls at Elevation 614 Ft & 624 Ft "
* Bechtel Corp. 7220 77/02/04 1p.

--8011060657 "Interior Elevations Auxiliary Bldg Concrete Block Walls at Elevation 614 Ft & 624 Ft "
* Bechtel Corp. 7220 77/02/04 1p

--8011060662 "Interior Elevations Auxiliary Bldg Concrete Block Walls at Elevation 634 Ft-6 Inches, 645 Ft "
* Bechtel Corp. 7220 77/02/28 1p

--8011060666 "Auxiliary & Reactor Bldg Floor Plan Elevation 614 Ft & 626 Ft (W Area) "
* Bechtel Corp 7220 80/07/11 1p

--8011060671 "Auxiliary Bldg Floor Plan Elevation 646 Ft "
* Bechtel Corp. 7220 80/07/11 1p

801180424 Responds to 801001 ltr re "Environ Qualification of Safety-Related Equipment " Encl 1st represents planned environ qualification testing to be performed during 1981-82.
COOK, J W Consumers Power Co 80/11/10 3pp 06992 136

8011210225 Advises of decision to support 800914 request for relief from making addl borings & associated soil tests in 18 areas by relaxing six penetration tests in vicinity of plant. Details, including changed boring locations, will be provided
TEDESCO, R L Assistant Director for Licensing 80/11/10 1p 02227:001.

8011280138 Informs that operability test program now included for preservice insp & preoperational testing of snubber thermal motion. Forwards request that Chapter 14 of FSAR be revised to reflect acceptance.
TEDESCO, R L Assistant Director for Licensing 80/11/13 14pp

801180131 Forwards Bechtel Corp rept, "Summary of Settlement Stress Calculations for Buried Piping " Requests followup meeting w/NRC consultants Differential settlement piping stress calculational input sheets encl
COOK, J W. Consumers Power Co 80/11/14 1p 06915 001.

--801180195 "Summary of Settlement Stress Calculations for Buried Piping "
* Bechtel Associates Professional Corp 80/11/14, 88pp 06915.001.

8011260083 Forwards Amend B5 to application for CPs & QLS, incorporating responses to Questions 34-53 & info re plant fill & updating info re piezometer & settlement readings, plots of cross sections for new boring locations & commitment dates.
COOK, J W. Consumers Power Co. 80/11/21 2pp 07085:211.

--8011260087 Amend B5 to application for CPs & QLS, incorporating responses to Questions 39-53 & info re plant fill & updating info re piezometer & settlement readings, plots of cross-sections for new boring locations & commitment dates.
* Consumers Power Co. 80/11/21. 1400pp. 07085:215.

C Utility Environmental Report (ER), amends & correspondence

8011060461 Comments on environ rept, Amend B2, Revision 11 Water quality data presented in Section 2 2 2 4 should be incorporated as app
* Interior, Dept of, Fish & Wildlife Service 80/10/24 1p 02319 196

F Security, medical, emergency & fire protection plans

801170003 Forwards facility emergency planning info for placement in LPDR W/o encl
BOUDER, J L Division of Rules and Records 80/11/04, 1p 06978 264

G Adjudicatory correspondence

801140042 Notice of 801117 & 19 depositions of O Gallagher for NRC & JW Simpson for Corps of Engineers, respectively Oral examination will address issues of 791206 order modifying CPs & contentions of ASLB 801024 prehearing order
FARNELL, A S Consumers Power Co FARNELL, A S Isham, Lincoln & Beale 80/11/05 2pp 06961 344

--801140047 Notice of continuation of J Kane & L Heller depositions on 801202 & 04, respectively Certificate of Svc encl
FARNELL, A S Consumers Power Co FARNELL, A S Isham, Lincoln & Beale 80/11/05 3pp 06961 346

801140466 Forwards documents in response to RJ Vollen 800918 request for production Remaining discoverable documents will be provided when identified
QOLDSBERG, S C Hearing Branch 2 80/11/07 3pp 06963 130.

--801140538 Discusses followup actions to 791113 meeting Consultants will be guided to use decision point meetings that culminate in declaration of final NRC position DOD 800211 internal memo & summary of 791113 meeting encl
KNIGHT, J P Assistant Director for Engineering 79/11/14 13pp. 06963.168

--801140546 Submits status of geotechnical review by Corps of Engineers. One reviewer made cursory examination of info & visited both plants Three-man review team needed to accomplish review DOD 800201 internal memo encl
HELLER, L W Geosciences Branch NRC-03-B9-167 80/01/23 7pp 06963 181

801140552 Forwards depositions of LW Heller, J Kane, T Cooke, D Horn, Q Keely & S Afifi taken during Oct 1980 W/o encl.
JOHNS, B W Hearing Branch 2 80/11/12, 2pp 06963.216

801180166 Appeal from ASLB 800910 prehearing order which stands moot re jurisdiction over soil settlement & compacted fill matls Urges admission of intervenor 800827 ltr, Certificate of Svc encl
MARSHALL, W H. Mapleton Intervenor 80/11/12 15pp 06987 221

801190126 First set of interrogatories directed to NRC re acceptance criteria cited in 791206 order modifying CPs & items of info requested by NRC after issuance of order Certificate of Svc encl
FARNELL, A S Consumers Power Co FARNELL, A S Isham, Lincoln & Beale 80/11/12 9pp 06999 138

801170881 Order granting Intervenor, Other Than Dow Chemical, opportunity to submit written briefs & proposed findings re remanded proceeding, by 801229. Parties are given 30 days for responses, from date of such filing
MILLER, M E Atomic Safety and Licensing Board Panel 80/11/14, 4pp. 06978 089.

8011200303 Responds to 801112 request that appeal papers be reproduced & forwarded to parties in proceeding Procedural assistance, per NRC regulations, does not extend to appeal papers Relevant FR notice encl
CHQ, J Atomic Safety and Licensing Appeal Panel. 80/11/14 5pp. 01741 019

G. Inspection reports, IE Bulletins & correspondence

8011060291 Forwards IE Insp Repts 50-329/80-24 & 50-330/80-25 on 800826-27 No noncompliance noted
KEPPLER, J G. Region 3, Chicago, Office of the Director. 80/09/16, 2pp. 06911:266.

DOCKETED ITEMS

--B011060275 IE Insp Repts 50-329/80-24 & 50-330/80-25 on B00826-27 No noncompliance noted Major areas inspected mgt control & implementation & results of preoperational radiological & nonradiological environ protection requirements
GREER, R J, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/09/09 3pp 06911 268

B01103098 Forwards IE Insp Repts 50-329/80-21 & 50-330/80-22 on B00716-18 B004-06 & 11-14 & notice of violation
KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/17 2pp 06857 180

--B011030105 Notice of violation from Insp on B00716-18, B004-06 & 11-14
* Region 3, Chicago, Office of the Director 80/09/12 1p 06857 182

--B011030111 IE Insp Repts 50-329/80-21 & 50-330/80-22 on B00716-18, B004-06 & 11-14 Noncompliance noted failure to perform audit of Photon Testing, Inc re svc to qualify welders
VANDEL, T E, LEE, E W K, KNOP, R C Region 3, Chicago, Office of the Director 80/09/12 12pp 06857 183

B011060284 Forwards IE Insp Repts 50-329/80-29 & 50-330/80-30 on B00901-30 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/03 2pp 06911 245

--B011060292 IE Insp Repts 50-329/80-29 & 50-330/80-30 on B00901-30 No noncompliance noted Major areas inspected site conditions, damage to generator rotor, welding procedures & timeliness of QC Insps
COOK, R J, KNOP, R C Region 3, Chicago, Office of the Director, 80/10/03 6pp 06911 247

B011200287 Forwards IE Insp Repts 50-329/80-28 & 50-330/80-29 on B00923-25 & notice of violation
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/08 2pp 07020 019

--B011200290 Notice of violation from Insp on B00923-25
* Region 3, Chicago, Office of the Director 80/10/07 1p 07020 021

--B011200294 IE Insp Repts 50-329/80-28 & 50-330/80-29 on B00923-25 Noncompliance noted weld control record indicated that authorized nuclear inspector hold point on weld drawing not initiated & dtd before work
LEE, E W K Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/07, 6pp 07020 022.

B011040163 Forwards final response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " No design changes for nitrogen/hydrogen cover gas sys required
COOK, J W Consumers Power Co 80/10/10 3pp 06885 088

B011190911 Responds to IE Bulletin 80-19, Revision 1 re CP Clare Model H02X-1011 mercury-wetted relays Relays neither used nor planned for use in logic matrix of facility reactor protection sys Appror 14 manhours expended for review
COOK, J W Consumers Power Co. 80/10/22 1p 06996 275

B011260019 Advises of status of actions to correct errors in 790703 & 0815 responses to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "
COOK, J W Consumers Power Co 80/10/31 3pp 07070 330

B011190445 Ack receipt of B01022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/80-21 & 50-330/80-22
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/05 1p 06998 083

--B011190446 Responds to NRC B00917 ltr re violations noted in IE Insp Repts 50-329/80-21 & 50-330/80-22 Corrective actions Zack Co initiated purchase order addressing applicable requirements of 10CFR50, App B
COOK, J W Consumers Power Co 80/10/22 3pp 06998 084

B Reportable occurrences, LERs & related correspondence

B011040399 Final deficiency rept re inconsistent cross-referencing between B&H & Bechtel numbering sys affecting instrument sys Utils agreed that no changes in component numbering are required Instrument index & electric schemes to be revised
COOK, J W, ANDERSON, J M, CURTIS, L H Consumers Power Co 80/10/31 3pp, 02317 196

B011040405 Interim deficiency rept re sway struts containing loose or totally disengaged rod end bushings Insp will be conducted to determine if bushings are loose or improperly installed
Next rept by B01219
COOK, J W Consumers Power Co 80/10/31 12pp 06874 178

B011040511 Interim deficiency rept re safe shutdown boration capability assuming restrictive core condition & control rod of highest worth stuck out-of-core FBAR being revised Equipment to be installed by Sept 1981 Next rept to be sent by B010717
COOK, J W Consumers Power Co 80/10/31 2pp

B01100620 Interim deficiency rept re containment internal structures coating deficiency Submits Bechtel interim Rept 3, updating evaluation & corrective action on decontaminable coating Sys 9 failure interim or final rept to be submitted by B010301
COOK, J W Consumers Power Co 80/10/31 237pp, 06930 022

B011170181 Ack receipt of B01010 interim deficiency rept re small break/reactor coolant pump operation interaction
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/03 1p 06981 236

B011170206 Ack receipt of B01010 interim deficiency rept re letdown cooler supports
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/03 1p 06969 055.

B01140038 Confirmatory deficiency rept originally reported on B01008 re effect of failure of component cooling water on nonessential & essential safety-related portions Component cooling water surge tank level will be maintained
COOK, J W Consumers Power Co 80/11/07 7pp 06963 228

T Hearing transcripts on non-antitrust matters

B011240443 Transcript of B01029 deposition of SA Afifi in Ann Arbor, MI Pp 1-123 Prof qualifications encl
AFIFI, S A Bechtel Corp 80/10/29 123pp 07048 253

V Operator Examinations

B011060074 Notification of B01029 meeting w/util in Bethesda, MD to discuss operator training & qualification programs
HODD, D Licensing Branch 3 80/10/17 4pp, 06912 345

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F Security, medical, emergency & fire protection plans

B011040397 Discusses upcoming appraisal of health physics program, to begin B01110 List of personnel requiring access badges encl
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/24 3pp 06875 158

G Adjudicatory correspondence

B011070466 Forwards order for mod of License DPR-49 re environ qualification of safety-related electrical equipment, Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp 06925 114

--B011070474 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by B020630 Complete records must be available by B01201
EISENHUT, D O Division of Licensing 80/10/24, 6pp 06925 116

--B011070480 Revised Tech Spec pages per B01024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing, 80/10/24 2pp 06925 122

J Insurance & indemnity information

B011250272 Forwards Natl Rural Utils Cooperative Finance Corp B00731 ltr advising of application approval for credit for short-term loans, to comply w/Price-Anderson Act re guarantee of ability to respond to call for retrospective premium.
TOYNE, G W Corn Belt Power Cooperative 80/11/14 3pp 07052 344.

P Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-19 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition
GRIMES, C I Assistant Director for Engineers & Projects (Pre 790625) 79/03/02 2pp 03145 305

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp

801190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mods to assure adequate short-term performance info should be submitted within 25 days
EISENHUT, D G Division of Licensing 80/10/01 2pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports," W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

8011070466 Forwards order for mod of License DPR-49 re environ qualification of safety-related electrical equipment, Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2 80/10/24 2pp 06925 114

--8011070474 Order for mod of license re environ qualification of safety-related electrical equipment, Compliance w/Div of Operating Reactors guidelines or NUREG-0988 required by 802630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06925 116

--8011070480 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06925 122

801140088 Advises that listed OE technical info repts submitted on behalf of Mark I owners group are applicable to facility Requests that listed documents be made official part of Docket 90-331
ROOT, L D Iowa Electric Light & Power Co 80/11/07 3pp 06943, 347.

Q Inspection reports, IE Bulletins & correspondence

8011200002 Forwards IE Insp Rept 90-331/80-13 on 800801-31 & notice of violation.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/03 2pp 07020 241

--8011200004 Notice of violation from insp on 800801-31
* Region 3, Chicago, Office of the Director 80/09/24 1p 07020 243

--8011200007 IE Insp Rept 90-331/80-13 on 800801-31 Noncompliance noted failure to have approved procedures for operating reactor water cleanup sys w/o reactor water cleanup pumps in operation
CHRISTIANSON, W, CLARDY, L B, LITTLE, W. S. Region 3, Chicago, Office of the Director 80/09/24 7pp. 07020 244.

8011050023 Forwards final response to Revision 2 to IE Bulletin 79-02 re pipe support baseplate designs using concrete expansion anchor bolts, Approx \$6 million expended in preparation of rept & corrective action.
ROOT, L. D. Iowa Electric Light & Power Co 80/10/17 30pp. 06894:273

8011050605 Forwards final response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Submits expenditure made in preparation of rept & corrective action
ROOT, L. D. Iowa Electric Light & Power Co 80/10/17 250pp. 06915:002

8011070315 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/24 1p 06922 005

801190220 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc
Badge examples encl
KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/28 3pp 07000 037

801190098 Forwards final response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," & responds to NRC 801001 ltr re equipment testing Outstanding components will be tested, shielded & relocated by June 1982
ROOT, L D Iowa Electric Light & Power Co 80/10/31 2pp 06916 001

8011280028 Forwards 180-day final rept, "Concrete Masonry Wall Design," in response to IE Bulletin 80-11 Review revealed possible localized overstressing of three block walls during seismic event & one block wall under postulated pipe break
ROOT, L D Iowa Electric Light & Power Co 80/11/10 2pp 07082 151

--8011280029 "Concrete Masonry Wall Design," 180-day final rept in response to IE Bulletin 80-11
* Bechtel Associates Professional Corp 80/11/07 53pp 07082 153

R Periodic operating reports & related correspondence

8011200302 Forwards monthly operating rept for Oct 1980
MINECK, D L Iowa Electric Light & Power Co 80/11/14 1p 07020 042

--8011200309 Monthly operating rept for Oct 1980
VAN SICKEL, J Iowa Electric Light & Power Co 80/11/14 6pp 07020 043

S Reportable occurrences, LERs & related correspondence

801180316 RO on 801110, following reactor transient from low power involving stuck open relief valve, average rate of reactor coolant temp change was observed to be 120 F for first hour Temp dropped from 520 F to 418 F Normal rates established
MINECK, D L Iowa Electric Light & Power Co 80/11/11 1p 06992 284

801180325 RO on 801110, relief valve stuck in open position approx 7 5 minutes during manual cycling to clear slight valve leak
Indication Reactor placed in cold shutdown pending repair & retesting of relief valve
MINECK, D L Iowa Electric Light & Power Co 80/11/11 2pp 06992 282

801180410 RO on 801111, lockout relay starting A standby gas treatment sys failed to trip when reactor vessel water level dropped 7 inches below instrument zero Caused by wiring error made in design change work during 1980 outage Error corrected
MINECK, D L Iowa Electric Light & Power Co 80/11/11 2pp 06992 156

8011250228 RO on 801110 during normal reactor startup w/reactor power at 7% found temp higher than normal on discharge line from main steam relief valve 4405 Caused by MSIV closure from steam line pressure Relief valve to be repaired & retested
MINECK, D L Iowa Electric Light & Power Co. 80/11/11 2pp 07055 221.

801180611 Forwards updated LER 80-009/01X-1
MINECK, D L Iowa Electric Light & Power Co 80/11/13 1p 06992:114

--801180619 Updated LER 80-009/01X-1 on 800304, while performing refueling outage insp of main HPCL pump, section of split ring was found lodged in impeller first reported on 800318
Caused by improper split ring retention device
RAGGER, H S Iowa Electric Light & Power Co 80/11/12 2pp. 06992:115

801180623 Forwards updated LER 79-025/01X-1
MINECK, D L Iowa Electric Light & Power Co 80/11/13 1p 06992:111.

DOCKETED ITEMS

--801180631 Updated LER 79-023/01X-1 on 790927, seismic restraints Q88-23-B-R-15B & Q88-23-SR-169 & pipe hanger Q88-23-H-152 on RHR to fuel pool line were found not intact Cause attributed to water hammer Q88-23-160 was repaired on 791002
RAGER, M S Iowa Electric Light & Power Co 80/11/12 2pp
06992 112

801180696 Forwards LER 80-052/03L-0
MINECK, D L Iowa Electric Light & Power Co 80/11/13 1p
06991 286

--801180705 LER 80-052/03L-0 on 801015, during surveillance testing, alarm which indicates auxiliary cooling sys of RHR running did not clear when initiating signals from RHR pumps were secured Caused by stuck microswitch
RAGER, M S Iowa Electric Light & Power Co 80/11/12 1p
06991 287

801180702 Forwards LER 80-051/03L-0
MINECK, D L Iowa Electric Light & Power Co 80/11/13 1p
06991 293

--801180708 LER 80-051/03L-0 on 801014, during surveillance testing of emergency diesel generators, 10-21 was unresponsive to voltage control Caused by cam switches becoming loose, resulting in unresponsive potentiometer motor
RAGER, M S Iowa Electric Light & Power Co 80/11/12 1p
06991 294

8011260234 RO on 801111, reactor vessel excessive cooldown rate in apparent violation of Tech Spec 3 & A 3 Evaluation determined Tech Spec not violated Event not reportable
MINECK, D L Iowa Electric Light & Power Co 80/11/19 1p
07071 339

V Operator Examinations

8011210603 Responds to 800711 ltr Compliance w/shift staffing interim criteria will be achieved by 820701 Schedule of actions for implementation of specified requirements attached
ROOT, L D Iowa Electric Light & Power Co 80/11/03 2pp
07034 027

8011210610 Forwards Attachment 2 to training schedule criteria transmitted by 801103 ltr
ROOT, L D Iowa Electric Light & Power Co 80/11/06 2pp
07034 043

DOCKET 30-332 BARNWELL REPROCESSING PLANT

G Adjudicatory correspondence

8011040392 Responds to 801013 ltr transmitting J Courtney request for resumption of OESMO proceeding Comments will be taken into account in NRC review re proceeding
KAMMERER, C Office of Congressional Affairs 80/10/22 1p
06873 294

DOCKET 30-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

801170546 Forwards review of fire protection safety evaluation supplements Requests final disposition of unacceptable & incomplete items within 30 days
IPPOLITO, T A Operating Reactors Branch 3 80/10/03 10pp,
06911 001

8011070290 Forwards Page 4-2 of security force training & qualification plan Page withheld (ref 10CFR2 790)
MALTESE, M J Power Authority of the State of New York 80/11/03, 1p. 06919 281

8011280015 Forwards electrical cable penetration qualification, fire pump capacity diagram & safe shutdown analysis in response to request for final disposition of fire protection safety evaluation open items Encls available in Central Files only.
BAYNE, J P Power Authority of the State of New York 80/11/20 4pp. 07076 006

G Adjudicatory correspondence

8011070391 Forwards order for mod of License DPR-59 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
IPPOLITO, T A Operating Reactors Branch 2. 80/10/24, 2pp.

--8011070394 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing. 80/10/24 4pp. 06925 106

--8011070399 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06925 112

8011260311 Forwards payment of civil penalties in amount of \$48,000, in response to NRC 801029 order
BAYNE, J P Power Authority of the State of New York 80/11/07, 4pp 07080 114.

H General correspondence

8011040408 Requests FI Bialik name be added to svc lists for all matters re facilities, BNL & transport of nuclear mats in NY.
BIALIK, E I New York, State of. 80/10/31 1p

801180150 Addl response to FOIA request for four categories of info re Crystal River 3 & info re six facilities NRC has no analyses suby to Paragraph 5 request.
FELTON, J M Division of Rules and Records 80/11/07 1p

801190498 Petitions for denial of Con Ed & PABNY petition to resume operations pending full investigation of safety issues to be adjudicated at forthcoming hearings
SCHNEIDER, B Affiliation Unknown. 80/11/18 4pp.

J Insurance & indemnity information

8011050438 Forwards until 790307 ltr forwarding Endorsements 32 & 33 to MAELU Policy MF-77 & Endorsements 38-40 to NELIA Policy NF-20B, in response to 800924 request.
DEEO, F H Power Authority of the State of New York. 80/10/31. 1p
06894 103

F. Operating license stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition
GRIMES, C I Assistant Director for Engineers & Projects (Pres 790626) 79/03/02 2pp. 03145:303

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D O Division of Licensing. 80/09/05. 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D O Division of Licensing. 80/10/01. 5pp.

801190237 Ltr to all BWR licensees requesting info on plans to assure long-term scram sys reliability IE Bulletin 80-17 required mode to assure adequate short-term performance Info should be submitted within 25 days
EISENHUT, D O Division of Licensing 80/10/01. 2pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports," w/b encl.
EISENHUT, D O. Division of Licensing. 80/10/06 6pp.

8011070391 Forwards order for mod of License DPR-59 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl.
IPPOLITO, T A Operating Reactors Branch 2. 80/10/24 2pp. 06925 104.

--8011070394 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201.
EISENHUT, D O. Division of Licensing. 80/10/24. 4pp. 06925 106.

--801070397 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06923:112

8011060509 Forwards response to NRC 800422 ltr re spent fuel pool cooling sys. Clarifies 780726 amend application & 791010 Tech Spec amend proposal. Twenty-two oversize drawings available in Central Files only. Aperture cards in PDR
BAYNE, J.P. Power Authority of the State of New York 80/10/31 8pp 06918:101

8011070490 Informs NRC that requested info re environ qualification tests on safety-related equipment will be provided when available. Util is finalizing response to IE Bulletin 79-018
BAYNE, J.P. Power Authority of the State of New York. 80/10/31 1p 06921:011.

801110490 Forwards "Cycle 4 Startup Test Rept" for facility.
PASTERNAK, R.J. Power Authority of the State of New York. 80/11/07. 1p 06950:061.

--801110492 "Cycle 4 Startup Test Rept."
* Power Authority of the State of New York 80/11/07. 10pp. 06950:062

Q Inspection reports, IE Bulletins & correspondence

8008130621 Forwards addl info on instrument surveillance procedure requested at 800805 meeting & required by IE Bulletin 80-17
PASTERNAK, R.J. Power Authority of the State of New York. 80/08/09. 11pp. 06329:102.

--8008130627 "Scram Discharge Vents & Drains"
* Power Authority of the State of New York. 80/08/09. 1p. 03273:105

801100381 Forwards IE Insp Rept 80-333/80-13 on 800818-22 No noncompliance noted
MARTIN, W.O. Region 1, Philadelphia, Safeguards Branch 80/09/16. 2pp 06929:288.

--801100385 IE Insp Rept 80-333/80-13 on 800818-22. No noncompliance noted. Major areas inspected: security plan, security program audit, security organization, physical barriers & access control. Details withheld (ref 10CFR2.790).
SMITH, G. Region 1, Philadelphia, Office of the Director.
DEVLIN, J. Region 1, Philadelphia, Safeguards Branch. 80/09/15. 1p. 06929:290

8011070029 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/09/30. 1p 06924:302

8011060680 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/24. 1p. 06914:328.

8011070317 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/24. 1p 06922:009

8011060716 Discusses IE insp on 800414-18 & 23-25 & forwards order imposing civil monetary penalties.
STELLO, V. Office of Inspection & Enforcement, Office of the Director 80/10/29. 2pp. 06912:027.

--8011060225 Order imposing civil penalty in amount of \$48,000 for item of noncompliance noted in IE insp on 800414-18 & 23-25.
STELLO, V. Office of Inspection & Enforcement, Office of the Director 80/10/29. 4pp. 06912:029.

8011070490 Informs NRC that requested info re environ qualification tests on safety-related equipment will be provided when available. Util is finalizing response to IE Bulletin 79-018.
BAYNE, J.P. Power Authority of the State of New York. 80/10/31. 1p. 06921:011.

801140073 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director 80/10/31 1p. 06968:255

8011170831 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 80/10/31 1p 06979:220

8011260311 Forwards payment of civil penalties in amount of \$48,000, in response to NRC 801029 order
BAYNE, J.P. Power Authority of the State of New York 80/11/07 4pp. 07080:114

R Periodic operating reports & related correspondence

8011060080 Partial response to FOIA request for info re radiation levels of plant environs & dump sites & radiation levels in nine listed places. Forwards documents listed in App A Search is continuing for documents re second part of request.
FELTON, J.M. Division of Rules and Records 80/10/29 2pp

--8011060122 Excerpts from environ monitoring annual repts. Includes Indian Point rept for 1978 & ME Yankee & JA Fitzpatrick Repts for 1979
* Consolidated Edison Co of New York 80/10/29. 15pp

801120483 Forwards monthly operating rept for Oct 1980
PASTERNAK, R.J. Power Authority of the State of New York 80/11/06 1p. 06952:204.

--801120487 Monthly operating rept for Oct 1980
ZUFELT, E. Power Authority of the State of New York. 80/11/06 7pp 06952:205

S. Reportable occurrences, LERs & related correspondence

8011060277 EN-80-37A, on 801029, order imposing civil penalties issued for items of noncompliance associated w/implementation of physical security plan.
BROCKETT, T.W., THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/10/29 1p 06911:165

8011060498 Forwards LER 80-078/03L-0.
PASTERNAK, R.J. Power Authority of the State of New York. 80/11/03 1p. 06911:348.

--8011060501 LER 80-078/03L-0 on 801003, drywell equipment drain sump integrator (20-PG-530) & flow recorder (20-FR-528) were found inoperable. Cause not stated. Flow transmitter replaced. No problem found w/integrator or recorder.
CHILDS, W.V. Power Authority of the State of New York. 80/11/03. 1p 06911:349.

8011060503 Forwards LER 80-077/03L-0
PASTERNAK, R.J. Power Authority of the State of New York 80/11/03. 1p. 06911:350

--8011060506 LER 80-077/03L-0 on 801003, drywell equipment drain sump pump (20-P-58) motor tripped on high overload. Caused by thrust bearing failure resulting in pump impeller rubbing against casing. Pump rebuilt & tested.
CHILDS, W.V. Power Authority of the State of New York. 80/11/03 1p. 06911:351.

801120543 Forwards LER 80-080/03L-0
PASTERNAK, R.J. Power Authority of the State of New York. 80/11/07. 1p. 06950:288.

--801120549 LER 80-080/03L-0 on 801011, primary containment isolation valve 10-MOV-57 from RHR to radwaste would not close when required operable by Tech Spec 3.7.D. Caused by installation of scaffolding for mods, disengaging motor operator clutch.
CHILDS, W.V. Power Authority of the State of New York. 80/11/07. 1p 06950:289.

801120556 Forwards LER 80-079/03L-0.
PASTERNAK, R.J. Power Authority of the State of New York. 80/11/07. 1p. 06950:290.

--801120568 LER 80-079/03L-0 on 801008, RCIC sys made inoperable to allow repair of steam leaks on manual valves associated w/steam line drains. Leaks caused by normal aging & thermal cycling. Valve body to bonnet gaskets replaced.
CHILDS, W.V. Power Authority of the State of New York. 80/11/07. 1p 06950:291.

DOCKETED ITEMS

8011250356 LER 80-081/03L-0 on 801023, carbon dioxide sys associated w/north cable run room would not actuate from heat detectors or local push button. Caused by wiring changes due to mods resulting in wire physically preventing proper operation. CHILDS, W V Power Authority of the State of New York 80/11/21 1p, 07036 325

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

801100423 Forwards results of NRC-sponsored vital area analysis for facility ENCL withheld (ref 10CFR2 790) VARQA, B A Operating Reactors Branch 1 80/10/01 2pp 06916 001

8011040294 Forwards revised physical security plan, Issue 2, Revision 7 & summary of changes ENCLs withheld (ref 10CFR2 790) DUNN, C N Duquesne Light Co 80/10/30 2pp 06873 195

8011040375 Forwards addl info re fire protection sys mods, per NRC 801001 request. Oversize drawings encl DUNN, C N Duquesne Light Co 80/10/30 13pp 06868, 044

8011080337 Forwards facility emergency planning info for placement in LPDR, W/o encl. BOUDER, J L Division of Rules and Records 80/11/04 1p 06991 164

G. Adjudicatory correspondence

801110088 Forwards order for mod of License DPR-66 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl VARQA, B A Operating Reactors Branch 1 80/10/24 3pp 06943, 297.

--801110099 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201. EISENHUT, D O Division of Licensing 80/10/24 4pp 06943 300.

--801110105 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment * Division of Licensing 80/10/24 2pp 06943 306

H General correspondence

8011180130 Addl response to FOIA request for four categories of info re Crystal River 3 & info re six facilities NRC has no analyses subj to Paragraph 5 request FELTON, J M Division of Rules and Records 80/11/07 1p.

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements. EISENHUT, D O Division of Licensing 80/09/05 209pp.

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101. EISENHUT, D O, Division of Licensing, 80/10/01 5pp

8011100275 Notices of collating error in Amend 30 to License DPR-66 Tech Specs Pages 3/4-27 & 3/4-28 encl VARQA, B A Operating Reactors Branch 1, 80/10/03 3pp 06928, 273.

--8011100280 Errata to Amend 30 of License DPR-66, consisting of revised Tech Specs Pages 3/4-27 & 3/4-28 VARQA, B A Operating Reactors Branch 1 80/10/03, 2pp 06928; 276

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl EISENHUT, D O Division of Licensing 80/10/06 6pp.

8011130041 Forwards NRC "Evaluation of Licensees Compliance w/Category A Items of NRC Recommendations Resulting from TMI-2 Lessons Learned." Evaluation does not address Tech Specs re limiting conditions for operation & modified sys VARQA, B A Operating Reactors Branch 1 80/10/09 21pp, 06956 271.

8011030200 Forwards Amend 34 to License DPR-66, safety evaluation & notice of issuance & availability VARQA, B A Operating Reactors Branch 1 80/10/20 1p 06857 263.

--8011030209 Amend 34 to License DPR-66, removing nine hydraulic snubbers from Table 3 7-4 of Tech Specs VARQA, B A Operating Reactors Branch 1 80/10/20 10pp 06857 264

--8011030218 Safety evaluation supporting Amend 34 to License DPR-66, * Office of Nuclear Reactor Regulation, Director 80/10/20 2pp, 06857 274

--8011030223 Notice of issuance & availability of Amend 34 to License DPR-66 VARQA, B A Operating Reactors Branch 1 80/10/20 2pp, 06857 276

801110088 Forwards order for mod of License DPR-66 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl VARQA, B A Operating Reactors Branch 1 80/10/24 3pp 06943; 297.

--801110099 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201. EISENHUT, D O Division of Licensing 80/10/24 4pp 06943; 300

--801110105 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment. * Division of Licensing 80/10/24 2pp 06943 306.

8011060507 Advises that util has not made plans to conduct any qualification tests during next 2 yrs NRC will be notified in event of decision to conduct tests DUNN, C N Duquesne Light Co 80/10/31 1p 06915 294.

8011200108 "Degraded Grid Protection for Class IE Power Sys, Beaver Valley Power Station," technical evaluation rept. CLEVELAND, C J E&O Idaho, Inc FIN A-6236 8011200108 80/10/31, 10pp 07022; 106

8011200113 "Inservice Testing Program for Pumps & Valves, Beaver Valley Power Station Unit 1," safety evaluation for 800130-810929 FEHRINGER, J M, ROCKHOLD, H C E&O Idaho, Inc. FIN A-6238 8011200113 80/10/31 68pp 07022; 116

8011210113 Notification of 801112 meeting w/util in Bethesda, MD re concerns associated w/pressure relief & safety valves. ROSS, W J Operating Reactors Branch 1 80/11/12, 2pp, 07037; 089.

8011140465 Forwards Isometrics 6 24-349 & 350 & 12690 89-SK-P6 & P5, describing pressurizer safety & relief valve discharge piping Oversized drawings available in Central Files only. BALKM, F, Duquesne Light Co, 80/11/13 46pp 06966; 268

8011280075 Forwards proprietary (WCAP-9731) & nonproprietary (WCAP-9769) versions of "First Cycle Performance of Beaver Valley 1 Fuel" Application for withholding & affidavit encl. DUNN, C N Duquesne Light Co 80/11/24 11pp 07080; 118

--8011280077 Nonproprietary version of "First Cycle Performance of Beaver Valley 1 Fuel." KOTSENAS, W O, MELEHAN, J B, ROBERTS, E Westinghouse Electric Corp WCAP-9769, 80/08/31 39pp, 07080; 129.

Q Inspection reports, IE Bulletins & correspondence

8011030288 Response to IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture" Availability of min cooling flow not assured for all conditions Westinghouse 800618 ltr encl. DUNN, C N, Duquesne Light Co, 80/09/24 10pp, 06865; 035.

8011070069 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required. GRIER, B H Region 1, Philadelphia, Office of the Director, 80/09/30, 1p 06920; 009

8011200043 Ack receipt of 800929 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-334/80-23
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/15 1p. 07020 251

--8011200046 Responds to NRC 800902 ltr re violations noted in IE Insp Rept 80-334/80-23 Corrective actions review of abnormal procedures completed by licensed operators
DUNN, C. N. Duquesne Light Co. 80/09/29 3pp 07020 252.

--8011200049 Forwards IE Insp Rept 80-334/80-23 on 800804-07 & notice of violation
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/02 2pp. 07020.255

--8011200053 Notice of violation from insp on 800804-07.
* Region 1, Philadelphia, Office of the Director 80/08/29 1p 07020.257

--8011200056 IE Insp Rept 80-334/80-23 on 800804-07. Noncompliance noted failure to document review of all abnormal procedures by all licensed operators
BETTENHAUSEN, L., TROSKOSKI, W., WIGGINS, J. Region 1, Philadelphia, Office of the Director 80/08/29. 10pp 07020.258

8011200276 Suppl 800304 response to IE Bulletin 79-27. Response inadequate in that loss of power not addressed Review of area now complete; no mods required.
DUNN, C. N. Duquesne Light Co. 80/10/21. 2pp. 07020.013

8011200179 Forwards supplemental response to IE Bulletin 79-02 re pipe support base plate anchor designs Testing program ensures that Seismic Category I sys will perform intended function
DUNN, C. N. Duquesne Light Co 80/10/23 10pp 07021.229.

8011060648 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/10/24 1p. 06909:337.

8011070341 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/10/24. 1p 06925:038

8011100888 Forwards order for mod of License DPR-66 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARGA, B. A. Operating Reactors Branch 1. 80/10/24 3pp. 06943.297

--8011100999 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0888 required by 820630. Complete records must be available by 801201.
EISENHUT, D. G. Division of Licensing 80/10/24. 6pp. 06943:300.

--801110106 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24. 2pp 06943 306.

8011170796 Forwards response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." Justification for continued operation in light of qualification irregularities included.
DUNN, C. N. Duquesne Light Co 80/10/30. 90pp. 06911:001

801140137 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/10/31. 1p. 06968:227

8011170909 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/10/31. 1p. 06981 231.

R. Periodic operating reports & related correspondence

8011040376 Forwards "NPDES Discharge Monitoring Rept, Sept. 1980"
MOORE, O. W. Duquesne Light Co 80/10/29 1p. 06874:149.

--8011040377 "NPDES Discharge Monitoring Rept, Sept 1980."
MOORE, O. W., STEED, L. S. Duquesne Light Co. 80/10/30. 12pp 06874 150.

801180473 Forwards monthly operating rept for Oct 1980
DUNN, C. N. Duquesne Light Co 80/11/13 1p 06989 260

--801180476 Monthly operating rept for Oct 1980
TIMKO, D. R. Duquesne Light Co 80/11/03 5pp 06989 261

S. Reportable occurrences, LERs & related correspondence

8010150834 RO 80-075/01P on 801008, analysis revealed overstress condition existed at pipe support H-43 on reactor coolant fill header from high head charging pumps Cause not determined. Mod will be completed prior to plant startup
WERLING, J. A. Duquesne Light Co 80/10/08 3pp. 06712 027

8011030479 Forwards LER 80-072/03L-0
WERLING, J. A. Duquesne Light Co 80/10/28 2pp 06872 319.

--8011030484 LER 80-072/03L-0 on 800930, w/plant in Mode 3 w/A train priority, leak found on 2A boric acid pump (CH-P-2A) Caused by worn mechanical seal While replacing seal, hair-line crack found in pump shaft Seal & shaft will be replaced
LACEY, W. S. Duquesne Light Co 80/10/28 1p 06872 321

801120351 Forwards LER 80-082/03L-0
WERLING, J. A. Duquesne Light Co 80/10/29 2pp 06952 065

--801120354 LER 80-082/03L-0, on 801001, while performing surveillance test on main filter bank flow, found bank filters isolated. Caused by procedural error Sign-off will be required when test completed
LACEY, W. S. Duquesne Light Co 80/10/29 2pp 06952:067

801120442 Forwards LER 80-074/03L-0
WERLING, J. A. Duquesne Light Co. 80/10/29. 2pp. 06953:356

--801120447 LER 80-074/03L-0 on 801001, during operational surveillance test on high head safety injection pump CH-P-1C discharge check valve did not reseal Caused by antirotation devices on valve disc & disc binding
LACEY, W. S. Duquesne Light Co 80/10/29. 2pp 06953 358

8011240298 Forwards updated LER 80-069/01T-1
WERLING, J. A. Duquesne Light Co 80/11/14. 2pp 07049 350

--8011240301 Updated LER 80-069/01T-1 on 800920, motor-driven fire pump motor failed after rebuild Cause being investigated. Motor sent offsite to be rebuilt again
LACEY, W. S. Duquesne Light Co 80/11/14 2pp 07049 352

8011240273 RO 80-078/01P on 801114 it was discovered that code safety valves challenged w/water loop seal on inlets would result in overstress of pressurizer safety & power operated relief valve piping. Drainage of seals would prevent condition
WERLING, J. A. Duquesne Light Co 80/11/17 3pp. 02227.001

8011240307 RO 80-77/01P on 801114, evaluation per IE Bulletin 79-14 indicated that support on A main steam header line was less conservative than assumed in Tech Specs Support mods were complete on 801115
WERLING, J. A. Duquesne Light Co 80/11/17 3pp 02227.001.

8011250513 Forwards LER 80-077/01T-0
WERLING, J. A. Duquesne Light Co 80/11/17 2pp 07055:120

--8011250520 LER 80-077/01T-0 on 801114, overstress condition determined to exist on main steam line branch line support Caused by thermal movement of main steam line affecting branch line support Pipe support red completed
LACEY, W. S. Duquesne Light Co 80/11/17 2pp 07055:122.

8011250542 PNO-1-80-148: on 801117, reactor tripped due to low steam pressure signal Caused by placing wrong channel in trip when intermittent fault became evident on another instrument Outage expected to last two days for restoration & repairs
McCABE, E. C., BRUNNER, E. J. Region 1, Philadelphia, Office of the Director. 80/11/17 1p 07068 271.

8011250461 Forwards LER 80-078/01T-0
WERLING, J. A. Duquesne Light Co 80/11/19 2pp 07056 351

--8011250470 LER 80-078/01T-0, on 801114, determined that, if safety or relief valves challenged w/water loop seals on inlet, downstream piping could be overstressed Caused by inadequate design Loop seal drains installed.
LACEY, W. S. Duquesne Light Co 80/11/19 4pp 07056:353.

DOCKETED ITEMS

8011260185 Forwards LER 80-076/03L-0

WERLING, J A Duquesne Light Co 80/11/20 2pp 07074 340

--8011260186 LER 80-076/03L-0 on 801021 test interval exceeded when containment entry mode & airlock operational surveillance test performed per Tech Specs Caused by delays in entering into Mode 4 Responsible personnel informed & test succeeded
LACEY, W S Duquesne Light Co 80/11/20 2pp 07074 342

V Operator Examinations

8011040386 Advises of status re shift staffing, in response to interim criteria in NRC 800731 ltr
DUNN, C N Duquesne Light Co 80/10/29 3pp 06874:170

DOCKET 80-335 ST LUCIE PLANT, UNIT 1

Q Adjudicatory correspondence

8011070504 Forwards order for mod of License DPR-67 re environ qualification of safety-related electrical equipment
Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06925 146

--8011070508 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06925 148

--8011070512 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 2pp 06925 154

P Operating license stage documents & correspondence

8011200255 Application to amend License DPR-67 by upgrading rated power from 2,360 MW to 2,700 MW Forwards proposed Tech Spec changes & supporting matl.
UHRIG, R E Florida Power & Light Co 80/11/14 5pp 07016 001

8008280384 Forwards partial response to NRC 800708 ltr. Question 1 re natural circulation cooldown Encl 1 explains how reactor vessel upper head can be cooled by drain & fill procedure. Encl 2 & 3 describes analytical model & model results
UHRIG, R E Florida Power & Light Co 80/08/25 17pp 04435:192

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TH1 action plan requirements. Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

8011030302 Responds to 800820 request re status of Task action plan A-44 in light of ASLAP decision re St Lucie 2 longer term portions of plan involve extensive use of reliability & risk assessment studies
DIRCKS, W J Office of the Executive Director for Operations 80/09/26 2pp 06865:112

8011030311 Task action plan A-44 "Station Blackout"
* Office of Nuclear Regulatory Research, Director 80/09/26 21pp 06865 114

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Amellar Tearing on Component Supports" W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011070462 Forwards R-8007, "Response Time of Platinum Resistance Thermometers Using Loop Current Step Response Techniques"
MOTT, J E Technology for Energy Corp 80/10/08 1p 06921:058

8011070467 "Response Time of Platinum Resistance Thermometers Using Loop Current Step Response Techniques"
MOTT, J E, ROBINSON, J C, JONES, J E Technology for Energy Corp R-8007, 78/04/19 65pp 06921 059

8011060278 Lists concerns re design & operating features contribution to or detractor from safe plant response to complete loss of ac power Requests analysis of safe control of facility during total loss of ac power
EISENHUT, D O Division of Licensing 80/10/10 3pp 06915:312

8011030604 Requests info be provided within 30 days after receipt of ltr re Question 1 concerning establishment of optimum cooldown rate based on analyses showing upper head voiding would not occur at optimum cooldown rate
CLARK, R A Operating Reactors Branch 3 80/10/17 3pp 06873 015

8011070504 Forwards order for mod of License DPR-67 re environ qualification of safety-related electrical equipment
Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06925:146

--8011070508 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06925 148

--8011070512 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06925 154

8011200255 Proposed Tech Spec changes for upgrading rated power from 2,360 MW to 2,700 MW Supporting documentation encl
* Florida Power & Light Co 80/11/14 650pp 07016 006

801120508 Application for amend to License DPR-67, deleting ETS Sections 3.1.B & 4.1 upon issuance of NPDES permit containing proposed biological monitoring program & adding Sections 5.1.5, 2.5.3 & 3.7.1 a Class II fee encl
UHRIG, R E Florida Power & Light Co 80/10/27 3pp 06953 169

--801120512 Proposed ETS Sections 5.1.5, 2.5.3 & 5.7.1 a re organizational changes of Environ Affairs Dept.
* Florida Power & Light Co 80/10/27 5pp 06953 172

8011030556 Application for amend to License DPR-67 consisting of changes to Tech Specs
UHRIG, R E Florida Power & Light Co 80/10/30 1p 06855 238

--8011030561 Tech Spec 3/4.4 for reactor coolant sys.
* Florida Power & Light Co 80/10/30 12pp 06855:239

8011040220 Notifies that 801114 has been scheduled as revised due date for responding to NRC 801010 ltr re potential for transient total loss of ac power at operating reactors
UHRIG, R E Florida Power & Light Co 80/10/30 2pp 06884:251

801100490 Requests amend to App A of License DPR-67, Forwards proposed Tech Spec changes, per NRC 800702 request
UHRIG, R E Florida Power & Light Co 80/10/31 2pp 06931 072

--801100491 Proposed Tech Spec change re TH1 Lessons Learned
* Florida Power & Light Co 80/10/31 24pp 06931 074

8011210050 Forwards request for addl info re sump design & effect on long-term post-LOCA cooling to assist in developing appropriate range of test parameters & to evaluate potential significance of debris formation from insulation matls
CLARK, R A Operating Reactors Branch 3 80/11/07 4pp 02227:001

8011190317 Forwards corrected Tech Spec Page B 3/4 9-2, Section 3/4 9.8, "Coolant Circulation" Previous submittal on 801030 inadvertently contained paragraph which should have been deleted
UHRIG, R E Florida Power & Light Co 80/11/13 1p 06996 253

--8011190323 Corrected Tech Spec Page B 3/4 9-2, Section 3/4 9.8, "Coolant Circulation" which should be substituted for page contained in 801030 submittal
* Florida Power & Light Co 80/11/13 2pp 06996 254

8011250193 Forwards responses to NRC 801010 request for info re loss of ac power at facility
UHRIG, R E Florida Power & Light Co 80/11/18 8pp 07068 307

Q Inspection reports, IE Bulletins & correspondence

8011200494 Forwards IE Insp Rept 80-335/80-04 on 800128-0201, Details & notice of violation withheld (ref 10CFR2.790)
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 2pp 07020 137

--8011200497 IE Insp Rept 80-335/80-04 on 800128-0201 Noncompliance noted. Failure to establish, maintain & follow adequate written procedures re security organization Details withheld (ref 10CFR2 790)
 PERRY, C. D. Region 2, Atlanta, Office of the Director.
 TOBIN, H. J. Region 2, Atlanta, Safeguards Branch 80/03/31 2pp
 07020 139

8011060803 Forwards IE Insp Rept 80-335/80-24 on 800805-10 No noncompliance noted
 LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/29 2pp 06909 146

--8011060806 IE Insp Rept 80-335/80-24 on 800805-10 No noncompliance noted Major areas inspected, operational practices & followup on events occurring while at site
 GRAHAM, M. J. Region 2, Atlanta, Office of the Director MARTIN, R. Region 2, Atlanta, Reactor Operations Nuclear Support Branch
 80/09/23, 4pp. 06909 148

801130356 Forwards IE Insp Repts 80-250/80-28, 80-251/80-27, 80-335/80-28 & 80-389/80-11 on 800827-29 No noncompliance noted.
 MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/03 2pp. 06960 292.

--801130368 IE Insp Repts 80-250/80-28, 80-251/80-27, 80-335/80-28 & 80-389/80-11 on 800827-29 No noncompliance noted. Major areas inspected; followup of noncompliance re 10CFR21 procedures
 BROWNLEE, V. L. Region 1, Philadelphia, Office of the Director
 COMLON, T. E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/03 2pp. 06960 294.

801170391 Forwards IE Insp Rept 80-335/80-30 on 800904-07. No noncompliance noted.
 LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/10/03. 2pp 06975 186.

--801170399 IE Insp Rept 80-335/80-30 on 800904-07. No noncompliance noted. Major areas inspected, bulletin, circular & info notice review & plant operations.
 ELROD, S. A. Region 2, Atlanta, Office of the Director. MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch
 80/10/03, 4pp. 06975 188

8011070308 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201.
 EISENHUT, D. O. Division of Licensing. 80/10/24. 4pp. 06925 148.

801170666 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24. 1p. 06976 234.

8011260133 Responds to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E." CP Clare Model MO 2X-1101 relays are currently being tested
 UHRIG, R. E. Florida Power & Light Co 80/10/29. 1p 07080 107.

8011280101 Responds to IE Bulletin 80-11, "Masonry Wall Design " Re-evaluations of 96 safety-related walls in progress. Final rept scheduled for 810209.
 UHRIG, R. E. Florida Power & Light Co. 80/11/04 2pp. 07083 279.

8011280135 Advises that util has determined that notification of NRC re natural circulation cooldown, discussed in IE Insp Rept 80-335/80-17, should have been submitted within 1-h of variations in pressurizer level. Plant operators briefed
 UHRIG, R. E. Florida Power & Light Co 80/11/10 1p. 07083 281.

R. Periodic operating reports & related correspondence

8011070311 Forwards comments on suppl info to draft effluent & waste disposal semiannual rept for 1978 encl in 801006 ltr.
 UHRIG, R. E. Florida Power & Light Co. 80/10/23. 13pp. 06911 001.

801180599 Forwards monthly operating repts for Oct 1980.
 SCHMIDT, A. D. Florida Power & Light Co. 80/11/08. 1p. 06988 097.

--801180604 Monthly operating repts for Oct 1980.
 CHILSON, V. T. Florida Power & Light Co. 80/11/08 9pp.
 06988 098.

S Reportable occurrences, LERs & related correspondence

8011040497 Forwards LER 80-060/03L-0
 SCHMIDT, A. D. Florida Power & Light Co 80/10/29. 1p. 06874 121.

--8011040492 LER 80-060/03L-0 on 800929, design review of Unit 2 determined tie line between condensate storage tank & Unit 1 auxiliary feedwater did not meet intent of design Caused by design error. Tie line to be modified
 PACE, P. L. Florida Power & Light Co 80/10/29 1p 06874 122

801100476 Forwards LER 80-036/03L-0
 SCHMIDT, A. D. Florida Power & Light Co 80/10/30. 1p. 06931 018

--801100480 LER 80-036/03L-0 on 801001, diesel generator 1A cooling water sys relief valve found relieving continuously Caused by air in cooling water sys Sys partially drained, vented & refilled to eliminate air voids
 PACE, P. L. Florida Power & Light Co 80/10/30 2pp 06931 019

V Operator Examinations

8011070299 Ack receipt of NRC 800731 ltr providing interim criteria for shift staffing Util will be in compliance w/criteria by 810601
 UHRIG, R. E. Florida Power & Light Co 80/11/03 1p 06919 309

DOCKET 80-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8011060114 Forwards safety evaluation re acceptable fire protection items w/attached summary of requirements to resolve open items. Status of all previously identified unacceptable items encl
 CLARK, R. A. Operating Reactors Branch 3 80/10/21 3pp. 06915 354

--8011060119 Safety evaluation re acceptable fire protection items w/attached summary of requirements to resolve open items
 * Operating Reactors Branch 4 80/10/21. 5pp. 06915 357

801170007 Forwards facility emergency planning info for placement LPDR, W/o encl.
 SQUERO, J. L. Division of Rules and Records 80/11/04 1p 06978 265.

O Adjudicatory correspondence

8011070595 Forwards order for mod of License DPR-65 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
 CLARK, R. A. Operating Reactors Branch 3 80/10/24 2pp 06925 224

--8011070601 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201.
 EISENHUT, D. O. Division of Licensing. 80/10/24. 4pp. 06925 226

--8011070604 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
 * Division of Licensing. 80/10/24. 2pp. 06925 232.

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants; applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
 EISENHUT, D. O. Division of Licensing. 80/09/05 209pp.

8011070472 Forwards "Response Time Qualification of Resistance Thermometers in Nuclear Power Plant Safety Sys." No proprietary info contained in rept
 KERLIN, T. W. Analysis & Measurement Services Corp 80/09/11 1p 06921 125

--8011070478 "Response Time Qualification of Resistance Thermometers in Nuclear Power Plant Safety Sys"
 KERLIN, T. W. Analysis & Measurement Services Corp. 80/09/11 126pp. 06921 126.

DOCKETED ITEMS

- 801100486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs Info needed by 801101,
EISENHUT, D O Division of Licensing 80/10/01 5pp
- 801100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp
- 8011070575 Forwards order for mod of License DPR-65 re environ
qualification of safety-related electrical equipment Revised
Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06925 224
- 8011070601 Order for mod of license re environ qualification of safety-
related electrical equipment Compliance w/Div of Operating
Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06925 226
- 8011070604 Revised Tech Spec pages per 801024 order for mod of license
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 2pp 06925 232
- 8011070403 Advises of discrepancy between delays cited in util
800520 analysis re use of two electrically driven auxiliary
feedwater pumps in automatic initiation scheme. Multiple
conservatism justify validity of analysis
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast
Utilities) 80/10/31 2pp 06919 347
- 801100468 Submits addl info re automatic surveillance testing of
coincident logic circuits associated w/engineered safety
features actuation sys. to support 761227 application for
proposed Tech Specs
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast
Utilities) 80/10/31 2pp 06931 286
- 801140007 Forwards implementation status of TMI action plan items
which cannot be implemented by 810101 identified
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
80/10/31 17pp 06961 203
- 8011200069 Forwards request for addl info re containment sumps &
insulation for operating reactors
CLARK, R A Operating Reactors Branch 3 80/11/06 4pp 0701B 144
- 8011210555 Forwards summary of SEP efforts completed & committed to by
owners for NRC SEP progress evaluation
SCHAFFSTALL, R SEP Owners Group 80/11/17 5pp
- 0 Inspection reports, IE Bulletins & correspondence
- 8011200100 Forwards IE Insp Rept 50-336/80-13 on 800827-29 No
noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/09/25 2pp 07020 355
- 8011200104 IE Insp Rept 50-336/80-13 on 800827-29 No noncompliance
noted Major areas inspected inservice insp activities
JERNIGAN, E P Region 1, Philadelphia, Office of the Director
TRIPP, L E Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/09/24 5pp 07020, 357
- 8011070044 Forwards Suppl 2 to IE Bulletin 79-018, "Environ
Qualification of Class IE Equipment " No written response
required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/09/30 1p 06924 312
- 8011200667 Responds to IE Bulletin 80-19 re mercury-wetted relays
Mercury-wetted relays are used but no failure has occurred
Replacement relays will be available by Nov 1980
COUNSIL, W O Northeast Utilities 80/10/20 3pp 07021 223.
- 801190595 Forwards IE Mgt Meeting Repts 50-245/80-15 & 50-336/80-16 on
800911 No noncompliance noted
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/21 2pp 07001 201
- 801190602 IE Mgt Meeting Repts 50-245/80-15 & 50-336/80-16 on 800911
No noncompliance noted Major areas discussed results of
appraisal board formed to evaluate performance of facility
from Jul 1979-Jul 1980 re refueling & protection
SHEDLOSKEY, J T, SMITH, T H, CONIGORS, E L Region 1, Philadelphia,
Office of the Director 80/10/15 7pp 07001 203
- 8011060746 Forwards IE Info Notice 80-37, "Containment Cooler Leaks &
Reactor Cavity Flooding At Indian Point Unit 2 " No written
response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06914 345
- 8011070296 Forwards Suppl 3 to IE Bulletin 79-018, "Environ
Qualification of Class IE Equipment " No written response
required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06921 320
- 8011040423 Forwards "Environ Qualification of Safety-Related Electrical
Equipment " & App 1, "Master Listing of Electrical Components
by Sys," in response to NRC 800919 order for mod of license
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast
Utilities), 80/10/31 5pp 06905 099
- 8011040427 "Environ Qualification of Safety-Related Electrical
Equipment " Includes App 2, providing sys component
evaluation work sheets & justification for continued
operation, & App 3, providing response to 801014 audit rept
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
80/10/31 200pp 06905 104
- 8011040431 App 1, "Master Listing of Electrical Components by Sys,"
to "Environ Qualification of Safety-Related Electrical
Equipment "
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
80/10/31 500pp 06905 342
- 801140063 Forwards IE Circular 80-23, "Potential Defects in Deloit
Power Sys Emergency Generators " No written response
required.
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06968 245
- 801170887 Forwards IE Info Notice 80-37, "Malfunction of Solenoid
Valves Mfg by Valcor Engineering Corp " No written response
is required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06981 220
- R Periodic operating reports & related correspondence
- 8011210396 Forwards monthly operating rept for Oct 1980
MROCKZKA, E J Northeast Nuclear Energy Co (subs of Northeast
Utilities) 80/11/13 1p 07034 006
- 8011210400 Monthly operating rept for Oct 1980
HOWLETT, G H Northeast Nuclear Energy Co (subs of Northeast
Utilities) 80/11/06 7pp 07034 007
- S Reportable occurrences, LERs & related correspondence
- 8011040463 Forwards LER 80-033/03L-0
MROCKZKA, E J Northeast Utilities 80/10/28 1p 06873 292.
- 8011040472 LER 80-033/03L-0 on 800930, one of two wide range neutron
flux instrumentation (NI) channels failed Caused by
personnel lifting NI signal leads to install heat shrink
tubing over cable connector Leads reterminated.
ROTHGEB, R Northeast Utilities 80/10/28 1p 06873 293
- 8011210455 Forwards LER 80-035/03L-0
MROCKZKA, E J Northeast Nuclear Energy Co (subs. of Northeast
Utilities), 80/11/14, 1p 07029 204
- 8011210456 LER 80-035/03L-0 on 801016, fire barrier between cable
spreading room & east containment electrical penetration
room found breached Apparently caused by removal of
temporary cables w/o proper sealing Barrier resealed
CRISCIONE, J L Northeast Nuclear Energy Co (subs of Northeast
Utilities) 80/11/14, 1p 07029 205
- 8011210489 Forwards LER 80-034/03L-0
MROCKZKA, E J Northeast Nuclear Energy Co. (subs. of Northeast
Utilities) 80/11/14 1p 07029 233

DOCKETED ITEMS

--8011210493 LER 80-034/03L-0 on 801017, turbine driven auxiliary feedwater pump P-4 taken out of svc to repair drain Valve 2-MB-342 Caused by steam cut on valve seating surface Valve seat lapped & disk repaired
CRISGIDNE, J L Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/11/14 1p 07029 234.

8011250313 Forwards LER 80-036/03L-0
NRQCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/11/20 1p 07056 137

--8011250320 LER 80-036/03L-0 on 801023, during power ascension testing, reactor protection sys channel D tripped on high power Caused by reversal of upper & lower detector signal cable connections Cables switched & recalibrated
BATES, R W Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/11/20 1p 07056 138

V Operator Examinations

8011040158 Responds to NRC 800731 ltr re interim criteria for shift staffing Util commits to having two licensed senior reactor operators, two licensed reactor operators & min of two auxiliary operators at each operating reactor by 820701
COUNSILL, W O Northeast Utilities 80/10/22 6pp. 06884 277

8011260233 Requests written & oral operator exams be given to PJ Dellarco following completion of necessary qualifications on 801208 PJ Dellarco resume encl
COUNSILL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) 80/11/06 2pp 07074 110

DOCKET 80-338 NORTH ANNA POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8011040487 Forwards State of VA & Caroline, Orange, Hanover, Louisa & Spotsylvania Counties radiological emergency plans; in response to NRC request
BAUM, E A Virginia Electric & Power Co. 80/10/09 1p 06745 004

--8011040491 State of VA, Spotsylvania County, radiological emergency response plan, standing operating procedures checklists
* Affiliation Unknown 80/08/31 62pp 03641 071

--8011040495 State of VA, Louisa County, radiological emergency response plan, standing operating procedures checklists
* Louisa County, VA 80/08/31 73pp 03641 145

--8011040498 State of VA, Hanover County, radiological emergency response plan, standing operating procedures checklists
* Hanover County, VA 80/08/31 100pp 03641 217

--8011040501 State of VA, Caroline County, radiological emergency response plan, standing operating procedures checklists
* Affiliation Unknown 80/08/31 73pp 03641 324

--8011040502 State of VA, Orange County, radiological emergency response plan, standing operating procedures checklists
* Affiliation Unknown 80/08/31 74pp 03642 034

--8011040505 Commonwealth of VA, emergency operations plan Vol II, "Radiological Emergency Response Plan," Annex I-V Standing Operating Procedures Checklists
* Virginia, State of 80/10/09 300pp 03637 024

8011030645 Forwards response to NRC review of facility emergency plan re emergency action levels & revision to plan Encls located in Central Files only
SYLVIA, B R Virginia Electric & Power Co 80/10/29 1p. 06860 183.

801120593 Forwards facility emergency planning info for placement in LPDR, W/o encl
SQUER, J L Division of Rules and Records 80/10/29 1p. 06953 333

801120138 Forwards facility emergency planning info for placement in LPDR, W/o encl.
SQUER, J L Division of Rules and Records 80/10/29 1p 06974 316.

801120683 Summary of 801027 meeting w/util in Bethesda, MD re emergency response facilities.
BROMERICK, A W, Licensing Branch 1 80/11/05 5pp. 06977.353.

G Adjudicatory correspondence

801110068 Forwards order for mod of License NPF-4 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06943 27

--801110077 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06943, 276

--801110083 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 3pp 06943 282

8011140522 Forwards B&W summary rept on turbine missile damage probability analysis prepared for VEPCC Long-term measures re turbine disk cracking will be submitted when prepared
CHRISTIAN, J N Hunton & Williams 80/11/06 4pp 06963 118

--8011140545 "Turbine Missile Damage Probability Analysis for North Anna Units 1 & 2," summary rept prepared for util
* Stone & Webster Engineering Corp 80/11/06 18pp 06963 122

8011170899 Notice of ASLAB reconstitution consisting of AS Rosenthal, chairman, JH Buck & LR Quarles, members
BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/11/12 1p 06978 120

8011240491 Order directing delay of Unit 1 shutdown until 810101 ALAR-389 clarified to state unit is not to resume operation until results of turbine insps are evaluated
BISHOP, C J, Atomic Safety and Licensing Appeal Panel 80/11/18 2pp 07047 283

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OL & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp.

8011100486 Ltr to all licensees of operating plants & applicants for OL & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800927 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

801110068 Forwards order for mod of License NPF-4 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06943 27

--801110077 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06943 276

--801110083 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 3pp 06943 282

8011140522 Forwards B&W summary rept on turbine missile damage probability analysis prepared for VEPCC Long-term measures re turbine disk cracking will be submitted when prepared
CHRISTIAN, J N Hunton & Williams 80/11/06 4pp 06963 118

--8011140545 "Turbine Missile Damage Probability Analysis for North Anna Units 1 & 2," summary rept prepared for util.
* Stone & Webster Engineering Corp 80/11/06 18pp. 06963 122

8011200397 Notification of 801203 meeting w/util in Bethesda, MD to discuss util plans in area of core reload licensing in upcoming yr.
BERGOREN, J B Standardization & Special Projects Branch. 80/11/06 2pp. 07020.068

DOCKETED ITEMS

801100367 Submits info re reactor containment mat response spectra per 800711 request
 SYLVIA, B R Virginia Electric & Power Co 80/11/07 13pp
 06930 342

801110320 Submits info re environ qualification tests to be conducted on safety-related equipment per 801031 request Describes test programs to assist in planning & scheduling of NRC audits of test programs
 SYLVIA, B R Virginia Electric & Power Co. 80/11/07 3pp
 06943 212

801110335 Submits revised schedule for Phase II of multiple structure ARS evaluation Proposed schedule acceptable since all sys required for accident mitigation Groups 1-5 will be completed by 801131
 SYLVIA, B R Virginia Electric & Power Co 80/11/07 3pp
 06943 215

8011230395 Responds to NUREG-0737 re TMI Action Plan Items II K 3 9 & II K 3 12 Rate time constants on proportional integral derivatives set equal to zero Anticipatory reactor trip upon turbine trip confirmed
 SYLVIA, B R Virginia Electric & Power Co 80/11/21 1p
 07056 122

G Inspection reports, IE Bulletins & correspondence

8011040151 Suppls 800821 response to IE Bulletin 79-18, "Audibility Problem Encountered on Evacuation of Personnel From High Noise Areas" Installation of permanent visual evacuation was completed on 800915
 SYLVIA, B R Virginia Electric & Power Co 80/10/10 1p
 06874 056

8011100431 Requests extension of IE Bulletin 80-11 deadline for completion of masonry wall re-evaluation program Based on current schedule & available manpower, reanalysis is scheduled for completion by Jul 1981
 SYLVIA, B R Virginia Electric & Power Co 80/10/24 2pp
 06929 296

801110068 Forwards order for mod of License NPF-4 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
 CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06943 274

--801110077 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
 EISENHUR, D G Division of Licensing 80/10/24 6pp 06943 276

--801110083 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
 * Division of Licensing 80/10/24 3pp 06943 282.

8011170672 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required.
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24 1p. 06976 246

8011040327 Forwards response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," & 800829 order for mod of license re environ qualification of electrical equipment, submitted as 90-day rept Master list encl.
 SYLVIA, B R Virginia Electric & Power Co 80/10/31. 500pp
 06878 334

8011070479 Forwards updated response to IE Bulletin 80-11, submitting re-evaluation criteria used to evaluate masonry walls & informing of progress & schedule for completing re-evaluation program
 SYLVIA, B R Virginia Electric & Power Co. 80/11/03 49pp
 06918 218

8011260338 Updates 800707 response to IE Bulletin 80-11, "Masonry Wall Design." Walls not meeting initial conservative acceptance criteria are being analyzed using more refined analytical techniques Final results will be submitted upon completion
 SYLVIA, B R Tennessee Valley Authority 80/11/03 47pp
 07078 121.

R. Periodic operating reports & related correspondence

8011200298 Forwards monthly operating repts for Oct 1980.
 SYLVIA, B R Virginia Electric & Power Co 80/11/17 1p.
 07020:032.

--8011200300 Monthly operating repts for Oct 1980
 NEUFER, A O, WOODSMALL, W A Virginia Electric & Power Co.
 80/11/09 7pp 07020 033

S Reportable occurrences, LERs & related correspondence

8011030516 Forwards LER 80-083/03L-0
 CARTWRIGHT, W R Virginia Electric & Power Co 80/10/24 1p.
 06853 087

--8011030524 LER 80-083/03L-0 on 800927, pressurizer level transmitter LT-1461 was observed indicating 3 3/4 from average reading & declared inoperable Caused by failure in temp compensator on differential pressure unit Transmitter replaced
 CARTWRIGHT, W R Virginia Electric & Power Co 80/10/24 2pp
 06853 088

8011070430 Forwards LER 79-104/01X-1
 CARTWRIGHT, W R Virginia Electric & Power Co 80/10/30 1p
 06925 008

--8011070434 LER 79-104/01X-1 on 790823, during review of containment breaker protection, discovered feeder breakers to electrical penetrations were improperly set to protect penetration integrity. Caused by personnel error in original analysis
 CARTWRIGHT, W R Virginia Electric & Power Co. 80/10/30. 2pp
 06925 009

8011070340 Forwards LER 80-086/03L-0
 CARTWRIGHT, W R Virginia Electric & Power Co 80/11/03 1p
 06918 211

--8011070342 LER 80-086/03L-0 on 801023, while running steam driven auxiliary feedwater pump, relief valve 1-FW-RV-100 failed to reset properly Affected feedwater pump declared inoperable. Cause by damaged seating surface Valve repaired
 CARTWRIGHT, W R Virginia Electric & Power Co 80/11/03 3pp
 06918 212

8011070344 Forwards LER 80-083/03L-0
 CARTWRIGHT, W R Virginia Electric & Power Co 80/11/03. 1p
 06918 208

--8011070346 LER 80-083/03L-0, on 801011, during Mode 1, pressurizer level indication of LT-1461 deviated from average reading & was declared inoperable Caused by technicians securing ref leg tubing Leg properly secured & transmitter operable
 CARTWRIGHT, W R Virginia Electric & Power Co 80/11/03. 2pp
 06916 209

8011170450 Forwards LER 80-088/03L-0
 CARTWRIGHT, W R Virginia Electric & Power Co 80/11/10 1p
 06975 028

--8011170458 LER 80-088/03L-0 on 801017, reactor power was increased to 52 1/4 as determined by calorimetric test Caused by change in reactor power between time nuclear instrumentations were set & time next calorimetric test performed Power reduced
 CARTWRIGHT, W R Virginia Electric & Power Co 80/11/10 2pp
 06975 029

8011170457 Forwards LER 80-087/03L-0
 CARTWRIGHT, W R Virginia Electric & Power Co 80/11/10 1p.
 06975 031

--8011170461 LER 80-087/03L-0 on 801015, turbine trip valve tripped on overspeed upon starting 1-FW-P-2 pump Caused by air trapped in governor oil passages Governor purged of air & reset
 CARTWRIGHT, W R Virginia Electric & Power Co 80/11/10 2pp.
 06975 032

8011170407 Forwards LER 80-091/01T-0
 CARTWRIGHT, W R Virginia Electric & Power Co 80/11/12 1p
 06976 356

--8011170414 LER 80-091/01T-0 on 801030, damage probabilities re turbine missile damage probability analysis indicated higher than previously analyzed in FSAR Westinghouse analysis indicates probability increase caused by cracking mechanisms
 CARTWRIGHT, W R Virginia Electric & Power Co. 80/11/12. 3pp
 06976 357

8011240387 Forwards LER 80-090/03L-0
 CARTWRIGHT, W R Virginia Electric & Power Co. 80/11/18 1p.
 07049.122

DOCKETED ITEMS

--8011240391 LER 80-090/03L-0 on 801028, containment particulate radiation monitor RM-RMS-159 inoperable due to failed filter paper drive motor. Caused by motor overheating Motor replaced
CARTWRIGHT, W R Virginia Electric & Power Co 80/11/18 2pp
07049 123

8011250361 Forwards LER 80-090/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 80/11/18 1p
07056:325

--8011250364 LER 80-090/03L-0 on 801022, containment particulate radiation monitor RM-RMS-159 inoperable due to failed filter paper drive motor. Caused by overheating Motor replaced
CARTWRIGHT, W R Virginia Electric & Power Co 80/11/18 2pp
07056:327

8011240098 Forwards LER 80-094/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 80/11/19 1p
07049:119

--8011240402 LER 80-094/03L-0 on 801029, discovered valve in service insp periodic test not performed as required. Caused by personnel error. Valves tested
CARTWRIGHT, W R Virginia Electric & Power Co 80/11/19 2pp
07049:120

V Operator Examinations

8011260089 Informs NRC that corporate ofc personnel will be utilized as certifiers re startup certification program in order to regain independence from power station staffs & in light of basis for NRC approval of certification program
FERGUSON, J H Virginia Electric & Power Co. 80/11/20 1p.
07071:322.

DOCKET 80-339 NORTH ANNA POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8010160487 Forwards State of VA & Caroline, Orange, Hanover, Louisa & Spotsylvania Counties radiological emergency plans, in response to NRC request
BAUM, E A Virginia Electric & Power Co 80/10/09 1p. 06745 004.

--8010160491 State of VA, Spotsylvania County, radiological emergency response plan, standing operating procedures checklists
* Affiliation Unknown. 80/08/31. 62pp. 03641 071

--8010160493 State of VA, Louisa County, radiological emergency response plan, standing operating procedures checklists
* Louisa County, VA. 80/08/31 73pp 03641 145

--8010160498 State of VA, Hanover County, radiological emergency response plan, standing operating procedures checklists
* Hanover County, VA 80/08/31. 100pp 03641:217.

--8010160501 State of VA, Caroline County, radiological emergency response plan, standing operating procedures checklists
* Affiliation Unknown 80/08/31 73pp 03641:324

--8010160502 State of VA, Orange County, radiological emergency response plan, standing operating procedures checklists.
* Affiliation Unknown 80/08/31 74pp 03642:034

801030645 Forwards response to NRC review of facility emergency plan re emergency action levels & revision to plan Encs located in Central Files only
SYLVIA, B R. Virginia Electric & Power Co 80/10/29. 1p
06860:183

801120593 Forwards facility emergency planning info for placement in LPDR, W/o encl.
BOUDER, J. L. Division of Rules and Records 80/10/29. 1p.
06983:333.

801170138 Forwards facility emergency planning info for placement in LPDR W/o encl
BOUDER, J. L. Division of Rules and Records 80/10/29. 1p
06976:316.

801170483 Summary of 801027 meeting w/util in Bethesda, MD re emergency response facilities.
BROMERICK, A W. Licensing Branch 1. 80/11/05 5pp.

G Adjudicatory correspondence

801140522 Forwards B&W summary rept on turbine missile damage probability analysis prepared for VEPD Long-term measures re turbine disk cracking will be submitted when prepared
CHRISTMAN, J N Hunton & Williams 80/11/06 4pp 06963 118

--801140545 "Turbine Missile Damage Probability Analysis for North Anna Units 1 & 2." summary rept prepared for util
* Stone & Webster Engineering Corp 80/11/06 18pp 06963 122

8011200039 Forwards order of mod of License NPF-7 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
YOUNGBLOOD, B J Licensing Branch 1 80/11/07 2pp 07020 230.

--8011200045 Order for mod of license re environ qualification of saf related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0988 required by 820630
Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/11/07 6pp. 07020 232

--8011200048 Revised Tech Specs pages per 801024 order for mod of lic re environ qualification of safety-related electrical equipment
* Licensing Branch 1 80/11/07 3pp 07020 238

801170899 Notice of ABLAB reconstitution consisting of AS Rosenthal, chairman, JH Buck & LR Quarles, members.
BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/11/12 1p 06978 120

8011240491 Order directing delay of Unit 1 shutdown until 810101
ALAB-589 clarified to state unit is not to resume operation until results of turbine insps are evaluated
BISHOP, C J. Atomic Safety and Licensing Appeal Panel 80/11/18. 2pp 07047 285

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OL & holders of CPs re preliminary clarification of THI action plan requirements Provides summary listing of all approved THI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

8010230078 Submits trip rept re visit to B&W to discuss NRC confirmatory piping calculations for plant
HARTZMAN, H., TERAD, D Mechanical Engineering Branch 80/10/09 2pp. 03560:001

8011050020 Notifies that util has satisfactorily completed matters re Conditions 2 C (6), 2 C (7) & 2 C (8) for License NPF-7
EISENHUT, D G Division of Licensing 80/10/17 2pp 06896:284.

8011040011 Forwards requested addl info prepared by B&W re seismic design review of facility
MURRAY, W R Virginia Electric & Power Co 80/10/30 115pp
02319 196.

801140298 Forwards request for addl info re RCS reactor vessel head vent & pressurizer vent for THI task action plan requirement.
TEDESCO, R L Assistant Director for Licensing 80/10/30 3pp
06960 283.

8011040312 Forwards results of review of NUREG-0988, "Environ Qualification of Safety-Related Electrical Equipment," & licensing requirements for compliance w/800923 memorandum & order (CLI-80-21).
SYLVIA, B R Virginia Electric & Power Co 80/10/31 450pp.
02319 196

DOCKETED ITEMS

8011060310 Application for amend of License NPF-7, changing Tech Spec 4 4 & 2 2 to require leak testing of pressure isolation valves prior to entering Mode 2 Class III fee encl
FERGUSON, J. H. Virginia Electric & Power Co 80/11/04 3pp
06909 161.

--8011060317 Proposed Tech Spec 4 4 & 2 2, requiring leak testing of pressure isolation valves prior to entering Mode 2
* Virginia Electric & Power Co 80/11/04. 1p 06909 164

801100309 Responds to Item 2 re conservations used in generation of amplified response spectra curves, requested at NRC 800922 meeting w/Util & S&H Response to Item 3 will be addressed in separate ltr. Discussion of seismic design piping encl
BYLVIA, B. R. Virginia Electric & Power Co 80/11/05 4pp.
06931 039.

8011200044 Forwards request for addl info re low head safety injection pumps & operability & anchoring of outside recirculation spray pumps
TEDESCH, R. L. Assistant Director for Licensing. 80/11/05 5pp
07018 220

801140322 Forwards S&H summary rept on turbine missile damage probability analysis prepared for VEPCO Long-term measures re turbine disk cracking will be submitted when prepared
CHRISTIAN, J. N. Hunton & Williams 80/11/06 4pp 06963:118.

--801140345 "Turbine Missile Damage Probability Analysis for North Anna Units 1 & 2," summary rept prepared for Util
* Stone & Webster Engineering Corp 80/11/06 18pp 06963.122

801100367 Submits info re reactor containment mat response spectra per 800711 request.
BYLVIA, B. R. Virginia Electric & Power Co. 80/11/07. 13pp
06930 342

801100464 Forwards "Summary of Unit 2 Turbine Driven Auxiliary Feedwater Pump Endurance Test"
BYLVIA, B. R. Virginia Electric & Power Co. 80/11/07 1p.
06931.252

--801100467 "Summary of Unit 2 Turbine Driven Auxiliary Feedwater Pump Endurance Test"
* Virginia Electric & Power Co 80/11/07 5pp 06931-253

801100320 Submits info re environ qualification tests to be conducted on safety-related equipment per 801031 request. Describes test programs to assist in planning & scheduling of NRC audits of test programs
BYLVIA, B. R. Virginia Electric & Power Co 80/11/07 3pp

801100335 Submits revised schedule for Phase II of multiple structure ARE evaluation. Proposed schedule acceptable since all sys required for accident mitigation Groups 1-5 will be completed by 800131
BYLVIA, B. R. Virginia Electric & Power Co. 80/11/07. 3pp.
06943 215

8011200039 Forwards order of mod of License NPF-7 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
YOUNGBLOOD, B. J. Licensing Branch 1 80/11/07 2pp 07020 230

--8011200045 Order for mod of license re environ qualification of safety-related electrical equipment. Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820430. Complete records must be available by 801201.
EISENHUT, D. O. Division of Licensing. 80/11/07 6pp 07020 232.

--8011200048 Revised Tech Specs pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Licensing Branch 1 80/11/07 3pp. 07020 238

8011200220 Forwards safety evaluation supporting 801010 info re backup overcurrent protection sys
TEDESCH, R. L. Assistant Director for Licensing. 80/11/10 1p.
07019 332

--8011200224 Safety evaluation approving overcurrent protection sys for containment electrical penetrations.
* Assistant Director for Licensing 80/11/10. 3pp 07019:333.

8011260248 Forwards Amend 1 to License NPF-7, safety evaluation & notice of issuance & availability
YOUNGBLOOD, B. J. Licensing Branch 1. 80/11/17. 2pp. 07072:093.

--8011260251 Amend 1 to License NPF-7, changing one Tech Spec re leak testing of certain pressure isolation valves prior to entering Mode 2 rather than Mode 4
YOUNGBLOOD, B. J. Licensing Branch 1 80/11/17 4pp. 07072:093.

--8011260255 Notice of issuance & availability of Amend 1 to License NPF-7
YOUNGBLOOD, B. J. Licensing Branch 1 80/11/17 2pp. 07072 099.

--8011260257 Safety evaluation supporting Amend 1 to License NPF-7
* Office of Nuclear Reactor Regulation, Director. 80/11/17. 3pp 07072.101.

8011260263 Responds to 801105 ltr requesting info on low head safety injection & outside recirculation spray pump operability
Info will be submitted on or about 801126.
BYLVIA, B. R. Virginia Electric & Power Co 80/11/18. 1p.
07071 340

8011240321 Proposed amend to License NPF-7, revising implementation dates for post-THI requirements to correspond w/ implementation dates in NUREG 0737 re equipment qualification & procurement delays
FERGUSON, J. H. Virginia Electric & Power Co 80/11/20. 6pp.
07049.355

8011250355 Responds to NUREG-0737 re THI Action Plan Items II K 3 9 & II K 3 12. Rate time constants on proportional integral derivatives set equal to zero Anticipatory reactor trip upon turbine trip confirmed.
BYLVIA, B. R. Virginia Electric & Power Co. 80/11/21 1p

Q. Inspection reports, IE Bulletins & correspondence

801100431 Requests extension of IE Bulletin 80-11 deadline for completion of masonry wall re-evaluation program Based on current schedule & available manpower, reanalysis is scheduled for completion by Jul 1981
BYLVIA, B. R. Virginia Electric & Power Co. 80/10/24 2pp

801170672 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24 1p.

801070479 Forwards updated response to IE Bulletin 80-11, submitting re-evaluation criteria used to evaluate masonry walls & informing of progress & schedule for completing re-evaluation program
BYLVIA, B. R. Virginia Electric & Power Co 80/11/03. 49pp.

8011260338 Updates 800707 response to IE Bulletin 80-11, "Masonry Wall Design." Walls not meeting initial conservative acceptance criteria are being analysed using more refined analytical techniques Final results will be submitted upon completion.
BYLVIA, B. R. Tennessee Valley Authority 80/11/03. 47pp

R. Periodic operating reports & related correspondence

8011070376 Forwards revised monthly operating rept for Sept 1980
BYLVIA, B. R. Virginia Electric & Power Co. 80/10/31 1p.
06925:082.

--8011070377 Revised monthly operating rept for Sept 1980.
NEUFER, A. O., WOODBEMALL, W. A. Virginia Electric & Power Co. 80/10/24. 4pp.
06925 083.

8011200298 Forwards monthly operating repts for Oct 1980
BYLVIA, B. R. Virginia Electric & Power Co. 80/11/17 1p.
07020 032.

--8011200300 Monthly operating repts for Oct 1980
NEUFER, A. O., WOODBEMALL, W. A. Virginia Electric & Power Co 80/11/09. 9pp 07020 033.

S Reportable occurrences, LERs & related correspondence

8011040572 Forwards LER 80-065/03L-0
CARTWRIGHT, W. R. Virginia Electric & Power Co. 80/10/30 1p
06873:089.

--8011040580 LER 80-065/03L-0 on 801002, while operating in Mode 1 at 73% power, block valve MOV-2536 did not open upon demand. Cause undetermined. Problem is under investigation & will be corrected during next maint outage.
CARTWRIGHT, W. R. Virginia Electric & Power Co 80/10/30 2pp.
06873.090.

DOCKETED ITEMS

157

8011040583 Forwards LER 80-067/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/10/30 1p
06873 098

--8011040588 LER 80-067/03L-0 on 801007, while operating in Mode 1 at
88% power, neutron flux distribution exceeded Tech Specs
Caused by power reduction which resulted in inserting
control rods Boren added to RCS Control rods withdrawn
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/10/30. 2pp.
06873:097.

8011070513 Forwards LER 80-074/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/03. 1p
06921:021

--8011070517 LER 80-074/03L-0 on 801015, at 100% power, fuel oil vol in
emergency diesel generator IH day tank found lower than 750
gallons Caused by inoperable fuel oil transfer pump, due to
low oil level in day tank Pump started & tank refilled
CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/11/03 3pp.
06921:022.

801100433 Forwards LER 80-072/03L-0,
CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/11/03 1p.
06929:298.

--801100434 LER 80-072/03L-0 on 801028 & 20, boren injection tank & boric
acid storage tank were sampled & found to contain boren
concentration below Tech Spec limit Caused by leakage past
water shutoff valve. Valves readjusted
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/03 3pp.
06929:297.

801100494 Forwards LER 80-068/03L-0,
CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/11/03 1p.
06931:065.

--801100498 LER 80-068/03L-0 on 801004, summing amp card was discovered
out of cal. Caused by procedural inadequacy resulting in
undetected setpoint drift Summing amps recalibr
CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/11/03. 3pp.
06931:066.

801120433 Forwards LER 80-071/03L-0,
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/05. 1p
06932:192.

--801120440 LER 80-071/03L-0 on 801009, safety injection accumulator 1A
boren concentration found too high. Caused by stratification
of stagnant solution Accumulator placed in recirculation
w/Unit 2.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/11/05. 2pp
06932:193.

801120494 Forwards LER 80-070/03L-0,
CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/11/05. 1p
06932:214

--801120503 LER 80-070/03L-0 on 801008, radiation monitoring channels
2-RH-289 & -260 declared inoperable when sample pumps
failed. Caused by motor failure Motor replaced on one pump &
monitoring sys returned to svc
CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/11/05. 2pp
06932:213

801180554 Forwards LER 80-069/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/11/05. 1p.
06989:274.

--801180564 LER 80-069/03L-0 during 801012-14, F(G) limit was exceeded
three times. Caused by rod movement at beginning of core
life. Rods fully withdrawn while controlling power by
borating.
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/05 2pp
06989:275

801180687 Forwards LER 80-073/03L-0,
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/05 1p.
06988:149

--801180693 LER 80-073/03L-0 on 801015, comparator card in Channel II
low pressure reactor trip circuit found inoperative. Caused
by dirty connector in card Card replaced.
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/05. 2pp.
06988:150.

801180700 Forwards LER 80-081/03L-0,
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/05 1p
06988:155.

--801180710 LER 80-081/03L-0 on 801021, deviation of greater than 12
steps observed between indication for control bank B rod D10
& shutdown bank A rod J03 & respective group demand
position. Caused by instrument drift Channels recalibr
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/05 2pp
06988:156.

8011170449 Forwards LER 80-079/03L-0,
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/10. 1p
06975:036

--8011170478 LER 80-079/03L-0 on 801017, discovered that on 800918, nuclear
power range channels indicated power levels lower than
determined by daily calorimetric procedure Caused by
misinterpretation of acceptance criteria Channel adjusted
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/10. 2pp
06975:037.

8011240323 Forwards LER 80-086/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/19 1p.
07050:143.

--8011240328 LER 80-086/03L-0 on 801025, containment sump flow integrator
FTD-DA-215 stopped totalling flow Caused by foreign matl
lodged in integrator mechanism. Matl removed
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/19. 2pp.
07050:144.

8011240343 Forwards LER 80-078/03L-0,
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/19 1p
07049:134.

--8011240346 LER 80-078/03L-0 on 801024, seismic hanger auxiliary on
feedwater pump 2-FW-P-3A recirculation line discovered
missing. Caused by inadequate implementation of established
procedures. Personnel instructed
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/19. 2pp.
07049:135.

8011240345 Forwards LER 80-080/03L-0,
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/19 1p
07049:131

--8011240352 LER 80-080/03L-0 on 801025, temp indicator TI-2412B
associated w/Loop A failed low. Caused by leads from recorder
connected upstream of isolation amplifier Procedure changed
to connect recorder leads to isolated points of circuit
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/19. 2pp
07049:132.

8011240379 Forwards LER 80-089/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/11/19 1p.
07049:125.

--8011240383 LER 80-089/03L-0 on 801031, PT-26.3 axial power distributi
monitoring periodic tests) not performed as required Caused
by personnel error. Test performed
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/19 2pp.
07049:126

8011260179 Forwards LER 80-077/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co 80/11/20. 1p.
07074:332.

--8011260180 LER 80-077/03L-0 on 801022, improper breaker alignment caus
number of operable high head safety injection pumps to be
reduced to one. Caused by failure to follow proper procedure,
Breakers realigned,
CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/11/20 2pp
07074:333

U. Congressional/Executive Correspondence

8011050090 Responds to B00821 ltr re issuance of DL w/o formal
Commission approval. Issuance of license was in accord w/
Oct 1975 & June 1980 policy statements License was issued
only after formal vote of Commission
AHEARNE, J. F. Commissioners 80/10/03 1p. 03709:237

V. Operator Examinations

8011240089 Informs NRC that corporate ofc personnel will be utilized as
certifiers re startup certification program in order to
regain independence from power station staffs & in light of
basis for NRC approval of certification program.
FERGUSON, J. H. Virginia Electric & Power Co. 80/11/20. 1p

DOCKETED ITEMS

DOCKET 50-340 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLS & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D O Division of Licensing, 80/10/06 6pp.

DOCKET 50-341 ENRICO FERM1 ATOMIC POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition.
GRIMES, C I Assistant Director for Engineers & Projects (Pre 790623), 79/03/02 2pp 03145 305

8011050354 Ltr to all licensees of operating plants, applicants for OLS & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101.
EISENHUT, D O Division of Licensing, 80/10/01 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011050355 Forwards request for addl info re emergency procedure guidelines. Schedule must be submitted by 801027 GE 800630 guidelines acceptable for trial implementation Training program must account for possible mod
EISENHUT, D O Division of Licensing, 80/10/21 8pp. 06902 086

8011050275 Summary of 801001 meeting w/util re applicant plan for high density fuel storage.
KINTNER, L L Licensing Branch 1 80/10/24 3pp 06899-173

--8011030294 "Licensing Input on High Density Spent Fuel Racks for Fermi 21 Project."
BENJH, K P Joseph Oat Corp. TURNER, B Southern Science, Inc. TM-586 80/10/24 100pp 06899-177

801100499 Forwards request for addl info re FSAR Also requests that FSAR be amended to comply w/encl requests NRC should be informed within 7 days of receipt of ltr if info will not be available by 801230
TEDESCO, R L Assistant Director for Licensing 80/11/04 1p 07018:223

8011070319 Forwards Certificate of Evc which indicates that copies of Amend 31 to OL have been served on appropriate parties.
MATHERS, B R Detroit Edison Co. 80/11/10 3pp 06977 332

F. Security, medical, emergency & fire protection plans

8011180331 Forwards facility emergency planning info for placement in LPDR (W/o encl)
BOUDER, J L Division of Rules and Records 80/11/04. 1p. 06991:162

8011260244 Notification of 801123 meeting w/util in Bethesda, MD to discuss applicant plans for onsite emergency response facilities.
KINTNER, L L Licensing Branch 2 80/11/14 3pp 07072.322.

K Utility Final Safety Analysis Report (FSAR) & amends

8011030578 Forwards Amend 31 to FSAR
THOMAS, E B, LeBoeuf, Lamb, Leiby & MacRae 80/10/31 1p 06861 029

--8011030684 Amend 31 to FSAR
* Detroit Edison Co 80/10/31 89pp 06861.031

d Inspection reports, IE Bulletins & correspondence

801100034 Forwards IE Insp Rept 50-341/80-14 on 800801-31 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/10/02. 2pp 06929.159

801100037 IE Insp Rept 50-341/80-14 on 800801-31 No noncompliance noted. Major areas inspected review of licensee action on previous insp findings, IE bulletin & circular followup & plant tours.
LITTLE, B H, BYRON, P M, LITTLE, W B Region 3, Chicago, Office of the Director 80/10/01 1p. 06929:161

8011180793 Forwards IE Insp Rept 50-341/80-16 on 800924-26 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/08 2pp 06991:350

--8011180797 IE Insp Rept 50-341/80-16 on 800924-26 No noncompliance noted Major areas inspected pipe support & restraint installation, procedure review & followup on previous hanger program noncompliances
VIN, I T Region 3, Chicago, Office of the Director, DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/07. 7pp. 06991:352.

8011200150 Forwards IE Insp Rept 50-341/80-11 on 800728-30, 0813 & 0910-12 & notice of violation.
FIORELLI, C Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/08 2pp 07021 203.

--8011200153 Notice of violation from insp on 800728-30, 0813 & 0910-12.
* Region 3, Chicago, Office of the Director 80/10/07. 1p. 07021:207.

--8011200160 IE Insp Rept 50-341/80-11 on 800728-30, 0813 & 0910-12 Noncompliance noted prompt corrective action not taken to assure that accurate & current documents used at controlled distribution locations
LANDSMAN, R B, BARRETT, P A, KNOP, R C Region 3, Chicago, Office of the Director 80/10/07. 6pp 07021.208

8011070278 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
KEPPLER, J Q Region 3, Chicago, Office of the Director. 80/10/24. 1p. 06921.284.

S Reportable occurrences, LERS & related correspondence

8011070454 Final deficiency rept re Agastat relay bases Each Agastat relay base of type in question in five GE supplied panels will be modified by insertion of micarta spacer under relay base.
HINES, E Detroit Edison Co 80/11/03 2pp 06924.363

801190685 Part 21 rept re pump malfunction creating excessive pressure which could rupture diaphragm & breach containment integrity, reported 800623 Kit to prevent deadheading will be made available.
HINES, E. Detroit Edison Co. 80/11/03. 2pp 07001.248

8011180991 Interim deficiency rept re cut rebar that may have resulted in reduced floor load capacity in reactor auxiliary bldg first reported on 791227 Sargent & Lundy Engineering has completed analysis of five most critical slabs
HINES, E. Detroit Edison Co 80/11/04. 2pp. 06992:120.

DOCKET 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC

F Security, medical, emergency & fire protection plans

8011040416 Forwards replacement pages to Security Plan POE-1417, Revision 5, Plan withheld (ref 10C-R2, 790)
WITHERS, B D Portland General Electric Co 80/10/28. 1p 06880:183.

DOCKETED ITEMS

151

O Adjudicatory correspondence

801110418 Forwards order for mod of License NPF-1 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06944 237

--801110426 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06944 239

--801110434 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944-245

8011260006 Informs of concrete voids discovered as result of inspa conducted per 780526 order for mod of license. Repairs in progress to restore seismic capacity Deficiency repts encl
JOHNSON, R W Portland General Electric Co 80/11/19 26pp 07075.266.

H General correspondence

8011100331 Responds to 800905 ltr transmitting CA Snow concerns re safe operation of facility during activity of Mount St Helens. Affidavit of RB McMullen re impact of volcanic activity on safety of facility encl
DIRCKS, W J Office of the Executive Director for Operations. 80/10/27. 3pp. 06916 001.

P Operating license stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101,
EISENHUT, D O Division of Licensing 80/10/01 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011060253 Summary of 800930 meeting w/Util & Westinghouse re lab examination results for steam generator Row 1 U-bend tube samples removed from plant
TRAMHELL, C M Operating Reactors Branch 3 80/10/20 53pp 02319.196.

8011060001 Informs of approval of responses to concerns stated in NRC 790921 ltr re inadvertent safety injection actuations during surveillance testing
CLARK, R A Operating Reactors Branch 3 80/10/21. 2pp 06911 147

8011060143 Forwards safety evaluation re implementation of recommendations for auxiliary feedwater sys Requests response to two unresolved items identified in rept within 45 days.
CLARK, R A. Operating Reactors Branch 3 80/10/23 2pp 06915-330

--8011060145 Safety evaluation re implementation of recommendations for auxiliary feedwater sys
* Operating Reactors Branch 3 80/10/23 22pp 06915 332

801110418 Forwards order for mod of License NPF-1 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06944 237

--801110426 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D O. Division of Licensing 80/10/24. 6pp. 06944-239

--801110434 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 2pp. 06944 245

8011100299 Forwards Amend 52 to License NPF-1 & notice of issuance & availability.
CLARK, R A. Operating Reactors Branch 3 80/10/28 2pp 06929.120

--8011100306 Amend 52 to License NPF-1, revising corporate (offsite) organization for facility support by placing all nuclear support activities in single corporate div
CONNOR, E L Operating Reactors Branch 3 80/10/28 16pp 06929 123

--8011100313 Notice of issuance & availability of Amend 52 to License NPF-1
CONNOR, E L Operating Reactors Branch 3 80/10/28 3pp 06929 139

8011200023 Forwards Amend 51 to License NPF-1 & notice of issuance & availability
CLARK, R A Operating Reactors Branch 3 80/10/28 3pp 07020 206

--8011200028 Amend 51 to License NPF-1, requiring implementation of secondary water chemistry monitoring program to inhibit steam generator tube degradation
CONNOR, E L Operating Reactors Branch 3 80/10/28 7pp. 07020.210

--8011200033 Notice of issuance & availability of Amend 51 to License NPF-1.
CONNOR, E L Operating Reactors Branch 3 80/10/28 2pp. 07020.217.

8011030369 Forwards Change Application 64 to License NPF-1 in response NRC request Certificate of Svc encl
WITHERS, B D Portland General Electric Co. 80/10/29 2pp 06861.166.

--8011030580 Change Application 64 to License NPF-1, to clarify definition of "operable" & add Tech Specs, Sections 3.0 & 4.0 re single failure criterion for safety-related sys.
WITHERS, B D. Portland General Electric Co. 80/10/29 3pp 06861.168

--8011030587 Proposed Tech Specs Sections 1.0, 3.0 & 4.0, to clarify definition of "operable" & identify applicable requirements re single failure criterion for safety-related sys
* Portland General Electric Co 80/10/29 6pp 06861.171

8011050269 Forwards POE-1026, "Cycle 3 Startup & Power Escalation Testing Rept: Trojan Nuclear Plant " Rept withheld (ref 10CFR2 790)
WITHERS, B D Portland General Electric Co 80/10/29 1p 06873.359.

8011040279 Forwards Change Application 69 for amend to License NPF-1, modifying App A Tech Specs re implementation of TMI Lessons Learned Category A action items Certificate of Svc & Class III fee encl.
WITHERS, B D Portland General Electric Co 80/10/31. 3pp 06873.171

--8011040285 Change Application 69 for amend to License NPF-1, modifying App A Tech Specs re implementation of TMI Lessons Learned Category A action items
WITHERS, B D. Portland General Electric Co 80/10/31 5pp 06873.174.

--8011040290 Proposed Tech Specs, Sections 3.0, 4.0 & 6.0 re implementation of TMI Lessons Learned Category A action items.
* Portland General Electric Co. 80/10/31 16pp 06873 179

8011200091 Informs that ASLB 800827 condition imposed re mods of control bldg design deficiencies must be added to FSAR Tech Spec 5.7.2 & should be modified Response requested within 30 days
CLARK, R A Operating Reactors Branch 3 80/11/04 13pp 07020 322.

--8011200095 "Rept on Criteria & Methodology for Evaluation of Out-of-Plane Loading on Masonry Walls at Trojan Power Plant."
COLEVILLE, J, Affiliation Unknown 80/07/31 8pp 07020.335

8011180381 Forwards License Change Application 67 requesting amend of License NPF-1, Class III fee & Certificate of Svc encl
WITHERS, B D. Portland General Electric Co 80/11/12 2pp 06991 188

DOCKETED ITEMS

--801180394 License Change Application 67 to amend License NPF-1, adding App A Tech Spec re 4 16 kV emergency bus undervoltage protection sys
WITHERS, B D, Portland General Electric Co 80/11/12 5pp.
06991 190

--801180402 Proposed Tech Specs 4 7 & 4 8 re 4 16 kV emergency bus undervoltage protection
* Pacific Gas & Electric Co 80/11/12 6pp. 06991 195

8011200413 Notification of 801217 meeting w/Util & Westinghouse in Bethesda, MD to discuss final lab examination results of steam generator Row 1 U-bend samples removed from facility.
TRAMMELL, C M Operating Reactors Branch 3 80/11/12 2pp
07020 103

8011210562 Application for Amend 57 to DL, changing Tech Specs re limiting condition for operation & surveillance requirements for reactivity control sys movable control assemblies
Class III fee encl
WOLLEVER, E J Duquesne Light Co 80/11/14 2pp 07034 080

--8011210568 Proposed Tech Specs, 3 1 3 & 4.1.3, changing limiting condition for operation & surveillance requirements for reactivity control sys movable control assemblies
* Duquesne Light Co 80/11/14 4pp 07034 082

8011260208 Forwards addl info re eruption of Mount St Helens & effect on facility per 801030 request
BROEHL, D J Portland General Electric Co 80/11/21 8pp
07070, 320

0 Inspection reports, IE Bulletins & correspondence

8011050400 Forwards IE Insp Rept 80-344/80-22 on 800908-12 No noncompliance noted
SPENCER, O S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/10/02 2pp 06898 157

--8011050402 IE Insp Rept 80-344/80-22 on 800908-12. No noncompliance noted. Major areas inspected facility mod activities & activities re IE Bulletins 79-13 & 80-08
NARBUT, P P Region 5, San Francisco, Office of the Director
DODDS, R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/10/01 4pp 06898, 159

8011060767 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting." No written response required.
ENDELKEIN, R H Region 5, San Francisco, Office of the Director
80/10/10 1p 06909 072

8011030276 Forwards NRC regional evaluation of licensee performance for Sept 1979-Aug 1980 as discussed at 801010 meeting w/Util in Portland, OR. NRC plans to increase frequency &/or scope of future insps of identified areas
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/10/14 1p 01756:001

--8011030280 Submits regional evaluation of facility for Sept 1979-Aug 1980. Recommends that increased special insp activity be performed in functional areas of mgt control & design changes & mods.
STERNBERG, D M, FIEB, R F, NARBUT, P P, Region 5, San Francisco Office of the Director. 80/09/25. 13pp

8011050342 Forwards IE Insp Rept 80-344/80-24 on 800902-30 No noncompliance noted
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/10/15 2pp. 06899 294.

--8011050347 IE Insp Rept 80-344/80-24 on 800902-30. No noncompliance noted. Major areas inspected included plant operations, surveillance testing & physical security
MALIKRDS, M H, JOHNSTON, O W Region 5, San Francisco, Office of the Director STERNBERG, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/10/14. 6pp 06899-296

8011170597 Forwards WCAP-9613, "Integrity Assessment of Feedwater Line Indications, Trojan Nuclear Plant," to suppl response to IE Bulletin 79-13 re cracking. Rept concludes that indication adjacent to nozzle-to-reducer weld is acceptable
BROEHL, D J, Portland General Electric Co 80/10/17 1p
06973 192

--8011170601 "Integrity Assessment of Feedwater Line Indications, Trojan Nuclear Plant"
BAIFORD, W H, DAVIDSON, J A Westinghouse Electric Corp., Nuclear Energy Systems WCAP-9613. 79/09/30. 34pp. 06973 193.

8011100008 Forwards 800814 response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power
Action committed to in response to item 3 completed
WITHERS, B D, Portland General Electric Co 80/10/23 1p
06928 336

--8011100011 Responds to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power. Visual insp determined station package is powered from telephone company
GODWIN, C Portland General Electric Co 80/08/14 3pp
06928 337

801110418 Forwards order for mod of License NPF-1 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06944 237

--801110426 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHART, D O Division of Licensing 80/10/24 6pp 06944:239

--801110434 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944 245

8011130011 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class 1E Equipment," to aid in written response required by 801101
ENDELKEIN, R H Region 5, San Francisco, Office of the Director
80/10/24 1p 06958 001

8011170638 Forwards IE Circular 80-23, "Potential Defects in Boloit Power Sys Emergency Generators." No written response required.
ENDELKEIN, R H Region 5, San Francisco, Office of the Director.
80/10/31 1p 06977 272

R Periodic operating reports & related correspondence

8011120425 Forwards monthly operating rept for Oct 1980
YUNDT, C P Portland General Electric Co 80/11/03 1p 06952 187.

--8011120429 Monthly operating rept for Oct 1980
BAIR, O O Portland General Electric Co 80/11/03. 4pp
06952-188

S Reportable occurrences, LERs & related correspondence

8011180810 PMS-1-80-22 on 801027, door between top floor of primary auxiliary bldg & fuel bldg found forcibly opened w/lock destroyed. Search initiated of fuel bldg & contiguous areas. No damage found. Door will be replaced
DEVLIN, J, MARTIN, W, MCCABE, E Region 1, Philadelphia, Office of the Director 80/10/28 1p 06991 341

8011070415 Forwards LER 80-023/03L-0
YUNDT, C P Portland General Electric Co 80/10/31 2pp
06919 337

--8011070420 LER 80-023/03L-0 on 801003, following trip, main feedwater regulating valve B failed to close automatically. Caused by misposition or blockage of manual vent throttle valve
Valve reset
FERRY, J C Portland General Electric Co 80/10/31 1p.
06919-359

8011070496 Forwards LER 80-021/01T-0
YUNDT, C P Portland General Electric Co 80/10/31 2pp
06921, 012

--8011070502 LER 80-021/01T-0 on 801003, during temporary plant test, M81V C did not fully close. Caused by component failure. Valve was shut w/steam flow. Permanent corrective action under investigation
FERRY, J C Portland General Electric Co 80/10/31 1p.
06921-014

8011070521 Forwards LER 80-022/01T-0
YUNDT, C P Portland General Electric Co 80/10/31 3pp.
06921 025.

--8011070526 LER 80-022/01T-0 on 801028, review of IE Bulletin 79-018 resulted in discovery of safety-related equipment not meeting environ qualification. Caused by change in criteria for environ qualification of safety-related equipment
PERRY, J C Portland General Electric Co 80/10/31 1p
06921 028

8011180671 Forwards LER 80-024/03L-0
YUNDT, C P Portland General Electric Co 80/11/10 2pp
06992 096.

--8011180677 LER 80-024/03L-0 on 801011, during troubleshooting on steam generator sample valves, blown fuse was discovered in automatic start circuit of diesel-driven auxiliary feedwater pump. Caused by ground in unrelated but connected circuit
PERRY, J C Portland General Electric Co 80/11/10 1p
06992 098

8011250451 Forwards updated LER 80-021/03L-1
YUNDT, C P Portland General Electric Co 80/11/19 2pp
07068, 097

--8011250464 Updated LER 80-021/03L-1 on 801003, during temporary plant test, C main steam isolation valve did not fully close. Caused by component failure. Test completed successfully & valve closed
PERRY, J C Portland General Electric Co 80/11/19 1p
07068 099

8011260006 Informs of concrete voids discovered as result of insep conducted per 780526 order for mod of license. Repairs in progress to restore seismic capacity. Deficiency repts encl
JOHNSON, R W Portland General Electric Co 80/11/19 26pp.
07075 266

V Operator Examinations

8011040518 Responds to 800731 ltr. Licensee will be in compliance w/shift staffing requirements for having two senior reactor operators, two reactor operators & two nonlicensed operators on shift during Operational Modes 1-4 by 820701
WITHERS, B D Portland General Electric Co 80/10/30. 2pp
06877 288

DOCKET 80-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

801110223 Forwards Revisions 14 & 15 to industrial security plan. AD 1808 OO. Plan withheld (ref 10CFR2 790)
CROUSE, R P Toledo Edison Co 80/11/04 1p 06943 131

G. Adjudicatory correspondence

801110474 Forwards order for mod of License NPF-3 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp 06944 287.

--801110480 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06944 289.

--801110484 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing. 80/10/24 2pp 06944 295

J Insurance & indemnity information

8011040402 Forwards Endorsements 30 & 24 to MAELU & NELIA Policies NF-236 & MF-92, respectively
CROUSE, R P Toledo Edison Co 80/10/30 3pp 06873 346

P. Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D O Division of Licensing 80/09/05. 209pp.

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" H/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011200347 Notification of 801020 meeting w/B&W in Bethesda, MD to discuss corrective action re undetectable Vellian check valve failures. Daily highlight dtd 801009 encl
POLK, J Operating Reactors Branch 2 80/10/20 3pp 07019 020

801110474 Forwards order for mod of License NPF-3 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp 06944 287

--801110480 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06944 289

--801110484 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944 295

8011040475 Forwards licensing fees for completion of Phase I of fish impingement study, review of License Condition 2 C(3)(e) & review of License Condition 2 C(3)(r)
CROUSE, R P Toledo Edison Co 80/10/27 2pp 02319 196

8011104035 Forwards summary & status of DB-L instrument sys analysis & testing in response to commitments set forth in NRC 770926 ltr re instrument-station groundgrid sys identified grounds do not affect plant operation
CROUSE, R P Toledo Edison Co 80/11/04 7pp 06963 330

8011170551 Forwards "Analog & Digital Isolation Device Qualification," & Addendum A Fault testing program did not render engineered safety features actuation sys noise test program unable to perform protective functions within specified limits
CROUSE, R P Toledo Edison Co 80/11/10 2pp 06911:001

--8011170553 "Analog & Digital Isolation Device Qualification," & Addendum A
* Bachtel Corp * Consolidated Controls Corp (subs of Condec Corp.). 80/10/14 41pp 06911 001

8011250279 Submits partial response to 801031 Existing small break LOCA model meets requirements of 10CFR50 App K Progress meeting w/NRC & owners of B&W to discuss further details of response to support evaluation scheduled for 801216
CROUSE, R P Toledo Edison Co 80/11/17 1p 07036 084

G. Inspection reports, IE Bulletins & correspondence

8011240103 Forwards IE Insp Rept 80-346/80-25 on 800818-22, 25-29, 0902-05, 08-12 & 15-19 & notice of violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/15 2pp 07049 269

--8011240108 Notice of violation from insp on 800818-22, 25-29, 0902-05, 08-12 & 15-19
* Region 3, Chicago, Office of the Director 80/10/14 1p.
07049 271

--8011240113 IE Insp Rept 80-346/80-25 on 800818-22, 25-29, 0902-05, 08-12 & 15-19. Noncompliance noted; procedure used by operators to align makeup & purification sys not latest revision.
REYER, L A; ROGERS, W O; SMITH, J D Region 3, Chicago, Office of the Director 80/10/14 10pp 07049 272

8011070301 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/24. 1p. 06921 332.

801110474 Forwards order for mod of License NPF-3 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl.
REID, R W Operating Reactors Branch 4 80/10/24 2pp 06944, 287

DOCKETED ITEMS

801110480 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT,D G Division of Licensing 80/10/24 4pp 06944 289

801110484 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 2pp 06944 293

011170411 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc. Models 1151 & 1152 Pressure Transmitters w/ Either A or D Output Codes " Transmitters cannot be exposed to input pressures that result in anomalous output signals
CROUSE,R P Toledo Edison Co 80/10/24 1p 06977 330

011190379 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc
Badges examples encl
KEPPLER,J G Region 3, Chicago, Office of the Director 80/10/28 3pp 06999 158

011170122 Forwards Revision 2 response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " Response includes re-evaluation of radiation doses in Room 314, revision of evaluation worksheets & new Section 4
CROUSE,R P Toledo Edison Co 80/10/31 300pp 06969 164

011280089 Forwards response to Items 2b & 3 of IE Bulletin 80-11, "Masonry Wall Design " Final rept will be submitted by 810601
CROUSE,R P Toledo Edison Co 80/11/04 81pp 07083 109

Periodic operating reports & related correspondence

011110197 Forwards monthly operating rept for Oct 1980
MURRAY,T D Toledo Edison Co 80/11/07 1p 06915 001

801110203 Monthly operating rept for Oct 1980
BARBOUR,B Toledo Edison Co 80/11/07 13pp 06944 017

Reportable occurrences, LERs & related correspondence

01100484 Forwards LER 80-045/03L-1
MURRAY,T D Toledo Edison Co 80/10/30 1p 06931 021

8011100489 LER 80-045/03L-1 on 800609, coax cable from NI-2 not completely connected to NIMBINS equipment in control room
Caused by lack of written procedures, instructing technicians re correct NIMBINS connection
WERNER,J Toledo Edison Co 80/07/30 2pp 06931.022

01110308 Forwards LER 80-066/03L-1
MURRAY,T D Toledo Edison Co 80/10/30 1p 06944.170

8011110317 LER 80-066/03L-1 between 800829 & 0921, doors to spent fuel pool area blocked open on nine occasions
Caused by personnel error on part of const workers Two memos issued to reinforce Special Order BB-1 previously issued
MELSTAD,K Toledo Edison Co 80/09/26 3pp 06944 171

01060476 Forwards LER 80-072/03L-0
MURRAY,T D Toledo Edison Co 80/10/31 1p 06909 357

8011060481 LER 80-072/03L-0 on 801002, during testing, smoke noted issuing from valve operator motor on CV5011E, air sample return inlet valve to containment
Caused by component failure in valve New parts installed
O'NEILL,J Toledo Edison Co 80/10/31 3pp 06909 358.

0110247 Forwards LER 80-075/03L-0
MURRAY,T D Toledo Edison Co 80/11/05 1p 06944 066

011110258 LER 80-075/03L-0 on 801008, steam generator level instrument to steam & feedwater rupture control sys cabinet channel 3 maintained 18-inch error over entire scale
Caused by zero shift in transmitter Transmitter being monitored.
TRAUTMAN,D Toledo Edison Co 80/11/09 3pp 06944 067

0110293 Forwards LER 80-074/03L-0
MURRAY,T D Toledo Edison Co 80/11/05 1p 06944.162

--801110392 LER 80-074/03L-0 on 801003, test frequency for containment air lock test exceeded
Caused by procedural deficiency Mods to plant procedures made to provide assurance of completing required testing
KOCIS,R Toledo Edison Co 80/11/05 3pp 06944 163

801110316 Forwards LER 80-073/03L-0
MURRAY,T D Toledo Edison Co 80/11/05 1p 06944 174

--801110322 LER 80-073/03L-0 on 801003, inner door of containment personnel lock could not be latched
Caused by two broken CAMROL cam follower bearings in door operating mechanism control linkage Broken bearings replaced
SVSLD,J Toledo Edison Co 80/11/05 2pp 06944 175

8011180602 Forwards LER 80-061/03L-1
MURRAY,T D Toledo Edison Co 80/11/05 1p 06988 116

--8011180610 LER 80-061/03L-1 on 800812, valve SV5005 installed 762826 for temporary use was never replaced
Caused by inadequate implementation of administrative control Valve secured in closed position & facility change request implemented
ISLEY,T Toledo Edison Co 80/09/10 3pp 06988 117

801110263 Forwards LER 80-076/03L-0.
MURRAY,T D Toledo Edison Co 80/11/07 1p 06944.072

--801110272 LER 80-076/03L-0 on 801008, gross back leakage observed through core flood valve 30
Caused by disengagement of disc unit from body block New bolt plates & locking plate properly installed.
STOTZ,J Toledo Edison Co 80/11/07 3pp 06944 073

8011140426 Forwards LER 80-077/03L-0
MURRAY,T D Toledo Edison Co 80/11/07 1p 06963 052

--8011140432 LER 80-077/03L-0 on 801013, nine of 20 control room normal ventilation dampers did not close within 10-s limit
Caused by insufficient bleedoff capacity for control air header which feeds & bleeds 10 dampers per header
MELSTAD,K, ISLEY,T Toledo Edison Co 80/11/10 2pp 06963-053

8011250329 RD on 801117 all four containment pressure transmitters found to be inoperable due to surveillance test procedure error
Emergency Tech Spec relief requested
CROUSE,R P Toledo Edison Co 80/11/18 2pp 07055 139

V. Operator Examinations

801070463 Submits response to 800731 ltr requesting compliance to NRC interim criteria for shift staffing Lists requirements w/responses & when util plans to comply
CROUSE,R P Toledo Edison Co 80/10/31 3pp 06942 031

DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

801050354 Ltr to all licensees of operating plants, applicants for CLs & holders of CPs re preliminary clarification of TMI action plan requirements, Provides summary listing of all approved TMI-2 related requirements
EISENHUT,D G Division of Licensing 80/09/05 209pp 02319 196

D. NRC Draft/Final Environmental Statements, supp & correspondence

8011030359 Forwards addendum to NUREG-0727, "FEB Re Operation of Joseph M Farley Nuclear Plant, Units 1 & 2 "
SCHWENGER,A Licensing Branch 2 80/10/08 3pp 06873 053

F. Security, medical, emergency & fire protection plans

8011050471 Forwards emergency plan, Revision 4 per NUREG-0654, FEMA-REP-1 & emergency planning final rule requirements, Response to NUREG-0694 requirements encl. Plan available in Central Files only.
CLAYTON,F.L Alabama Power Co 80/10/28 10pp 06913 003

8011120300 Forwards fire protection info for Fire Area 13, per NRC request.
CLAYTON,F.L Alabama Power Co 80/11/04 3pp 06953 274

8011240147 Notifies of privacy review of encl util emergency plan Plan may be made publicly available
FELTON, J. H. Division of Rules and Records 80/11/24 1p
07051 086

--8011240364 Forwards public version of State of AL radiological emergency plan, Revision 4 Also forwards emergency implementing procedures required by App E
CLAYTON, F. L. Alabama Power Co 80/11/07 2pp 07051 088

--8011240375 Public version of facility emergency plan implementing procedure, "Emergency Organization & Control Room Access"
HARRISTON, W. S. Alabama Power Co 80/11/03 7pp 07051 089

--8011240384 Public version of emergency plan implementing procedure, "Duties of Individual Who Discovers an Emergency Condition"
HARRISTON, W. S. Alabama Power Co 80/11/03 4pp 07051 096

--8011240394 Public version of facility emergency plan implementing procedure, "Duties of Shift Supervisor"
HARRISTON, W. S. Alabama Power Co 80/11/03 2pp 07051 100

--8011240477 Public version of facility emergency procedure, "Duties of Emergency Director"
HARRISTON, W. S. Alabama Power Co 80/11/03 3pp 07051 102

--8011240485 Public version of facility emergency procedure, "Chemistry & Health Physics Support to Emergency Plan"
HARRISTON, W. S. Alabama Power Co 80/11/03 10pp 07051 105

--8011240495 Public version of facility emergency plan implementing procedure, "Maint Support to Emergency Plan."
HARRISTON, W. S. Alabama Power Co 80/11/03 3pp 07051 115

--8011240508 Public version of facility emergency plan implementing procedure, "Technical Support to Emergency Plan"
HARRISTON, W. S. Alabama Power Co 80/11/03 8pp 07051 118

--8011240519 Public version of facility emergency plan implementing procedure, "Security Support to Emergency Plan."
HARRISTON, W. S. Alabama Power Co 80/11/03 3pp 07051 126

--8011240526 Public version of facility emergency plan implementing procedure, "Radiation Exposure Estimation & Classification of Emergencies."
HARRISTON, W. S. Alabama Power Co 80/11/06 21pp 07051 131

--8011240542 Public version of facility emergency plan implementing procedure, "Evacuation & Personnel Accountability."
HARRISTON, W. S. Alabama Power Co 80/11/06 9pp 07051 152

--8011240555 Public version of facility emergency plan procedure, "Handling of Injured Personnel"
HARRISTON, W. S. Alabama Power Co 80/11/06 14pp 07051 161

--8011240562 Public version of facility emergency plan implementing procedure, "Alert"
HARRISTON, W. S. Alabama Power Co 80/11/06 9pp 07051 175

--8011240567 Public version of facility emergency plan implementing procedure, "Fire Emergencies"
HARRISTON, W. S. Alabama Power Co 80/11/06 12pp 07051 184

--8011240482 Public version of facility emergency implementation procedures, "Re-entry Procedures"
HARRISTON, W. S. Alabama Power Co 80/11/06 4pp 07051 196

--8011240488 Public version of facility emergency implementation procedure, "Emergency Drills"
HARRISTON, W. S. Alabama Power Co 80/11/06 5pp 07051 200

--8011240497 Public version of facility emergency implementation procedure, "Notification of Unusual Event."
HARRISTON, W. S. Alabama Power Co 80/11/06 7pp 07051 205

--8011240507 Public version of facility emergency implementation procedure, "General Emergency."
HARRISTON, W. S. Alabama Power Co 80/11/06 7pp 07051 212

--8011240515 Public version of facility emergency implementation procedure, "Recovery - EOF"
HARRISTON, W. S. Alabama Power Co 80/11/06 7pp 07051 219

--8011240528 Public version of facility emergency implementation procedure, "Recovery - TSC"
HARRISTON, W. S. Alabama Power Co 80/11/06 3pp 07051 229

--8011240575 Public version of State of AL radiological emergency response plan
* Alabama Power Co 80/11/17 250pp 07051 233

Q Adjudicatory correspondence

801110078 Forwards order for mod of License NPF-2 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, S. A. Operating Reactors Branch 1 80/10/24 2pp 06943:285

--801110085 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0388 required by B20630 Complete records must be available by 801201
EISENHUT, D. O. Division of Licensing 80/10/24 6pp 06943 287

--801110091 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 4pp 06943.293

K Utility Final Safety Analysis Report (FSAR) & amends

8011140091 Forwards Amend 75 to FSAR for Unit 1 & to OL application for Unit 2
CLAYTON, F. L. Alabama Power Co 80/11/07 1p 06965.206

--8011140096 Amend 75 to application for OL for Unit 2 Certificate of Bvc encl.
CLAYTON, F. L. Alabama Power Co 80/11/07 3pp 06965.207

--8011140098 Amend 75 to FSAR for Unit 1
* Alabama Power Co 80/11/07 50pp

P Operating license stage documents & correspondence

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D. O. Division of Licensing 80/10/01 5pp 06940:338

801100537 Ltr to all power reactor licensees & applicants forwarding summary of B00827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D. O. Division of Licensing 80/10/06 6pp 06940.347

801110078 Forwards order for mod of License NPF-2 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
VARQA, S. A. Operating Reactors Branch 1. 80/10/24 2pp 06943.285

--801110085 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0388 required by B20630 Complete records must be available by 801201
EISENHUT, D. O. Division of Licensing 80/10/24 6pp 06943:287

--801110091 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 4pp 06943.293

8011050611 Forwards Amend 16 to License NPF-2, safety evaluation & notice of issuance & availability
VARQA, S. A. Operating Reactors Branch 1 80/10/30 2pp 06898:333

--8011050615 Amend 16 to License NPF-2, lowering core elevation radial peaking factor, Fxy, for remainder of Cycle 2 & for upcoming Cycle 3
VARQA, S. A. Operating Reactors Branch 1 80/10/30 5pp 06898:335

--8011050617 Safety evaluation supporting Amend 16 to License NPF-2
* Office of Nuclear Reactor Regulation, Director 80/10/30 2pp 06898:340

--8011050618 Notice of issuance & availability of Amend 16 to License NPF-2
VARQA, S. A. Operating Reactors Branch 1. 80/10/30 2pp 06898:342

DOCKETED ITEMS

801140448 Advises that application to amend DL is not required for operation during Cycle 3 since no unreviewed safety questions are involved u/reload Results of std tests & core loading map will be submitted within 90 days of startup
CLAYTON, F L Alabama Power Co 80/10/31 2pp 06963 357

8011070470 Forwards info re low pressure turbine disc in response to NRC 800225 request Calculations in response to Question I D. have been repeated to account for thermal & steam bending stresses Encl withheld (ref 10CFR2 790)
CLAYTON, F L Alabama Power Co 80/11/04 2pp. 06919 360

8011260239 Forwards requests for addl info for review of alternate shutdown capability & auxiliary feedwater initiation in safety analyses. Proposed mods should be submitted prior to installation Response for Unit 1 requested in 30 days
TEDESCO, R L Assistant Director for Licensing 80/11/05 17pp 07074 115

8011210985 Forwards summary of Hittman Nuclear & Development Corp. "Demineralization & Filtration Evcs" Rept constitutes basis for revised process control program
GEORGE, R L Alabama Power Co 80/11/07. 1p 07034 184

--8011210588 Summary of "Demineralization & Filtration Evcs"
* Hittman Corp 80/05/31. 22pp. 07034 185

Q Inspection reports, IE Bulletins & correspondence

8011040365 Forwards IE Insp Repts 50-348/80-25 & 50-364/80-36 on 800827-29. No noncompliance noted
STOKER, J. F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/22 2pp 06875 151

--8011040568 IE Insp Repts 50-348/80-25 & 50-364/80-36 on 800827-29. No noncompliance noted Major areas inspected radiological environ monitoring program mgt controls
ALLEN, J. R., MACARTHUR, T C Region 2, Atlanta, Office of the Director, JENKINS, G R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/22 3pp 06875 153

8011050273 Forwards IE Insp Repts 50-348/80-27 & 50-364/80-39 on 800801-29 No noncompliance noted
LEWIS, R. C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/29 2pp 06899 143

--8011050278 IE Insp Repts 50-348/80-27 & 50-364/80-39 on 800801-29 No noncompliance noted Major areas inspected plant operation & security
BRADORD, W H., MURKEY, J P Region 2, Atlanta, Office of the Director, MARTIN, R. D Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/29. 8pp. 06899 145

8011070629 Suppls 800707 response to IE Bulletin 80-11 re commitment to complete re-evaluation of masonry walls by 801107
Necessary preparation of as-built engineering drawings of walls will delay re-evaluation
CLAYTON, F L Alabama Power Co 80/10/22. 2pp 06925 248.

801110078 Forwards order for mod of License NPF-2 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
VARGA, S. A Operating Reactors Branch 1. 80/10/24. 2pp 06943 285

--801110085 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 800630
Complete records must be available by 801201.
EISENHUT, D O Division of Licensing 80/10/24. 6pp 06943 287

--801110091 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 4pp. 06943 293

8011100485 Forwards response to IE Bulletin 79-01B re environ qualification of electrical equipment Submittal addresses equipment acceptability inside containment & outstanding items & clarifies original response.
CLAYTON, F. L Alabama Power Co 80/10/30 43pp. 06941 083.

8011200436 Ack receipt of 801014 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-348/80-20 & 50-364/80-25.
MURPHY, G E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/03 1p 07020 109

--8011200442 Responds to NRC 800917 ltr re violation noted in IE Insp Repts 50-348/80-20 & 50-364/80-25 Corrective actions
sufficient number of qualified personnel to man fire brigade ensured
CLAYTON, F L Alabama Power Co 80/10/14 2pp 07020 110

--8011200449 Forwards IE Insp Repts 50-348/80-20 & 50-364/80-25 on 800804-07 & notice of violation
MURPHY, G E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/17 2pp 07020 112

--8011200453 Notice of violation from insp on 800804-07
* Region 2, Atlanta, Office of the Director 80/09/04 1p 07020 114

--8011200463 IE Insp Repts 50-348/80-20 & 50-364/80-25 on 800804-07 Noncompliance noted: failure to assign qualified personnel to perform fire brigade functions.
MILLER, W H Region 2, Atlanta, Office of the Director
CONLON, T E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/04. 9pp 07020 115.

8011240114 Responds to IE Bulletin 79-02. Util intends to upgrade addl concrete expansion anchor bolts within existing safety factors
CLAYTON, F L Alabama Power Co 80/11/03. 1p 07042 352

8011210361 Forwards IE Mgt Meeting Rept 50-348/80-30 on 801007 No noncompliance noted
MURPHY, G E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/10 2pp 07030 154

--8011210368 IE Mgt Meeting Rept 50-348/80-30 on 801007. Major areas discussed. Anticipated resolutions of problems w/containment bldg tendon surveillance insps performed in Spring 1978 & 1980
LENAHAM, J J Region 2, Atlanta, Office of the Director CONLON, T Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/06. 3pp 07030 158

8011280090 Forwards Revision 2 to util response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." Revision contains minor clarification in Section C 1 & minor editorial corrections
CLAYTON, F L Alabama Power Co 80/11/12 55pp. 07083 190

R Periodic operating reports & related correspondence

8011210398 Forwards addl info re "Semiannual Radioactive Effluent Release Rept, Jan-June 1980" Source of Ar-41 for continuous release mode described.
CLAYTON, F L Alabama Power Co 80/11/13 3pp 07034 047

8011210377 Forwards monthly operating rept for Oct 1980
CLAYTON, F. L Alabama Power Co 80/11/14 1p 07030 182.

--8011210381 Monthly operating rept for Oct 1980.
HAIRSTON, W. G Alabama Power Co. 80/11/01 4pp 07030 183

S Reportable occurrences, LERs & related correspondence

8011070373 Forwards LERs 80-058/03L-0 & 80-059/03L-0
CLAYTON, F L Alabama Power Co 80/11/04 1p 06925 078

--8011070374 LER 80-058/03L-0 on 801007, discrepancies between tendon installation QC records & as-found conditions detected
Visual insp planned to verify QC records on all tendons which will be tested in 1981
* Alabama Power Co. 80/11/04. 2pp 06925 079

--8011070375 LER 80-059/03L-0 on 801004, B train exhaust fan failed to start Caused by shorted switchgear auxiliary relay resulting in blown fuses Relay & fuses replaced.
* Alabama Power Co. 80/11/04 1p. 06925 081

8011180476 Forwards LER 80-060/03L-0
CLAYTON, F. L Alabama Power Co. 80/11/10 1p 06988 323

--8011180300 LER 80-060/03L-0 on 801009, while performing surveillance test FNP-1-STP-28.1 (diesel generator QC operability test), capacity of manually controlling diesel generator frequency failed. Caused by short circuit in voltage regulator.
HAIRSTON, W O. Alabama Power Co 80/11/10 1p. 06988 324.

8011210504 Forwards LERs 80-061/01T-0 & 80-062/03L-0
CLAYTON, F. L Alabama Power Co 80/11/17. 1p 07029 238.

--B011210506 LER 80-061/01T-O on B01104, fire protection water tanks A & B fell below Tech Spec min level during flush on Unit 2 fire header. Caused by equipment operator being placed on emergency job & missing reading Tanks refilled
HAIRSTON, W. G. Alabama Power Co 80/11/17 2pp 07029 239.

--B011210512 LER 80-062/03L-O on B01017, diesel generator failed to reach rated voltage within Tech Spec time limit. Voltage could not be controlled from emergency power board & BIF sequencer step six was below setpoint Cause not determined.
HAIRSTON, W. G. Alabama Power Co 80/11/17 1p 07029 241

B011240305 Forwards LER 80-064/03L-O
CLAYTON, F. L. Alabama Power Co 80/11/18 1p 07049 334

--B011240310 LER 80-064/03L-O on B01021, Unit 1 diesel generator 1B output breaker was racked out Caused by personnel error Individual counseled
HAIRSTON, W. G. Alabama Power Co 80/11/18 1p 07049 335.

B011250328 Forwards LERs 80-063/03L-O & 80-067/03L-O
CLAYTON, F. L. Alabama Power Co 80/11/20 1p 07068 334.

--B011250341 LER 80-063/03L-O on B01020, while performing emergency core cooling valves inservice test, valve 1-CVC-MQV-11SD would not open from main control board Caused by contact arm 4 being out of adjustment. Contact arm was readjusted
HAIRSTON, W. G. Alabama Power Co 80/11/20 1p 07068 335

--B011250347 LER 80-067/03L-O on B01020, svc water A train battery sys was declared inoperable Caused by close terminal post proximity & poor terminal post seal design. Battery was cleaned & placed on charge
HAIRSTON, W. G. Alabama Power Co 80/11/20 2pp. 07068 336.

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

A. Application/construction stage documents & correspondence

B011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D. G. Division of Licensing. 80/09/05 209pp

B009290378 Forwards Amend 24 to application for DL & revised Pages to PBAR, Summary description of amend revision encl.
BRADLEY, E. J. Philadelphia Electric Co. 80/09/24 4pp 06623 154

--B009290380 Amend 24 to application for DL Revises PBAR Pages 5, 12-13 & 5, 2-16 Certificate of Svc encl
BOYER, V. S. Philadelphia Electric Co 80/09/24 4pp 06623 158.

B01100484 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by B01101.
EISENHUT, D. G. Division of Licensing 80/10/01 5pp.

B01100537 Ltr to all power reactor licensees & applicants forwarding summary of B00827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl.
EISENHUT, D. G. Division of Licensing. 80/10/06 6pp.

B011030825 Requests that encl preservice insp & testing requirements to ensure snubber operability be included in licensing process & be implemented at facility
TEDESOD, R. L. Assistant Director for Licensing 80/10/17. 4pp. 06873:002.

B011190527 Summary of B01002 meeting w/utl in Bethesda, MD re interim status reft on risk evaluation study.
SELLS, D. Licensing Branch 2. 80/10/20. 5pp 06998:133.

B011180497 Submits info re environ qualification of safety-related equipment, in response to NRC B01001 ltr One environ qualification test planned for Peach Bottom w/pertinent info encl. Info for Limerick will be provided B01128.
KEMPER, J. B. Philadelphia Electric Co 80/11/12. 2pp. 06988 254

B011240008 Requests announcement of NRC B01209 meeting at Pottstown, PA be transmitted for publication in newspapers Announcement & newspapers list encl.
SCHWENCER, A. Licensing Branch 2. 80/11/17. 3pp. 02227:001.

B Utility Preliminary Safety Analysis Report, amends

B009290378 Forwards Amend 24 to application for DL & revised Pages to PBAR Summary description of amend revision encl
BRADLEY, E. J. Philadelphia Electric Co 80/09/24 4pp 06623 154.

--B009290380 Amend 24 to application for DL Revises PBAR Pages 5, 12-13 & 5, 2-16 Certificate of Svc encl
BOYER, V. S. Philadelphia Electric Co 80/09/24 4pp 06623 158.

--B009290382 Amend 24 to PBAR, revising Pages 5 2-13 & 5 2-16
* Philadelphia Electric Co 80/09/24 3pp 06623 162

F. Security, medical, emergency & fire protection plans

B011170001 Forwards facility emergency planning info for placement in LPDR, W/o encl
BOUDER, J. L. Division of Rules and Records 80/11/04 1p 06978 263

H General correspondence

B011120328 Trip rept of B01016 visit to Philadelphia, PA to meet w/Association of Community Organizations for Reform Now re licensing process Organization demands that const be stopped at facility
SELLS, D. E. Licensing Branch 2 80/10/27 3pp. 06956:234

G. Inspection reports, IE Bulletins & correspondence

B01100321 Forwards IE Insp Repts 50-352/80-14 & 50-353/80-12 on B00701-18 & 28-31 No noncompliance noted
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/09/16 2pp 06929:186

--B01100332 IE Insp Repts 50-352/80-14 & 50-353/80-12 on B00701-18 & 28-31. No noncompliance noted. Major areas inspected: safety-related piping & supports, equipment storage & const electrical activities
MATTIA, J. C. Region 1, Philadelphia, Office of the Director. MCGAUOHY, R. W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/19. 9pp 06929:186.

B011170522 Forwards IE Insp Repts 50-352/80-16 & 50-353/80-14 on B00804-29 No noncompliance noted
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/09/17. 2pp. 06981:281

--B011170634 IE Insp Repts 50-352/80-16 & 50-353/80-14 on B00804-29. No noncompliance noted Major areas inspected: electrical activities, pipe hanger installation, document control & new reh activities.
MATTIA, J. C. , MCGAUOHY, R. W. Region 1, Philadelphia, Office of the Director. 80/08/17. 5pp. 06981:253

B011060535 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." IE 79-018 & suppl dtd B00229, not previously transmitted, also encl. No written responses required
ORIER, B. H. Region 1, Philadelphia, Office of the Director 80/09/30 1p 06911:355

B011190284 Ack receipt of B00926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-12 & 50-353/80-10.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/10. 1p. 06995:133

--B011190307 Responds to NRC B00827 ltr re violations noted in IE Insp Repts 50-352/80-12 & 50-353/80-10 Corrective actions: halted insp by unqualified inspector, replaced defective thermometer & removed unauthorized weld tacks.
KEMPER, J. B. Philadelphia Electric Co. 80/09/26 6pp. 06996:134.

--B011190319 Forwards IE Insp Repts 50-352/80-12 & 50-353/80-10 on 11-27 & notice of violation
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/08/27. 2pp. 06996:140.

--B011190324 Notice of violation from insp on B00616-27.
* Region 1, Philadelphia, Office of the Director. 80/08/26. 4pp. 06996:142.

DOCKETED ITEMS

- 801190329 IE Insp Repts 50-352/80-12 & 50-353/80-10 on 800616-27 Noncompliance noted failure to properly qualify inspector, use of inaccurate thermometers & failure to follow field const drawing procedures & design drawing requirements MATTIA, J C, WALTON, O, REYNOLDS, S Region 1, Philadelphia, Office of the Director 80/08/26 22pp 06996 146
- 8011030525 Requests that encl preservice insp & testing requirements to ensure snubber operability be included in licensing process & be implemented at facility TEDESCO, R L Assistant Director for Licensing 80/10/17. 4pp 06873 002
- 8011060442 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06909 235
- 8011070308 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06921 348
- 8011140235 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director, 80/10/31 1p 06968 233
- 8011140598 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Hfg by Valcor Engineering Corp " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06963 239
- B Reportable occurrences, LERs & related correspondence**
- 8011050040 Ack receipt of 800925 interim deficiency rept re ASME bolts, nuts & studs obtained from unapproved sources Matter will be reviewed following receipt of final rept CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/01 1p 06896 290
- 8011140396 Final deficiency rept (Significant Deficiency Rept 17) re Colt Industries emergency diesel generator possible field insulation damage All info provided in vendor 800922 Part 21 rept KEMPER, J S Philadelphia Electric Co 80/11/06 2pp 06962 342
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2**
- A Application/construction stage documents & correspondence**
- 8011050334 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements EISENHUT, D O Division of Licensing 80/09/05. 209pp
- 8009290378 Forwards Amend 24 to application for OL & revised Pages to PBAR, Summary description of amend revision encl BRADLEY, E J Philadelphia Electric Co 80/09/24 4pp 06623 154
- 8009290380 Amend 24 to application for OL, Revises PBAR Pages 5 12-13 & 3 2-16 Certificate of Svc encl BOYER, V S Philadelphia Electric Co 80/09/24 4pp 06623 158
- 8009290382 Amend 24 to PEAR, revising Pages 5 2-13 & 5 2-16 * Philadelphia Electric Co 80/09/24 3pp 06623 162
- 8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101 EISENHUT, D O. Division of Licensing 80/10/01 3pp
- 8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " H/o encl EISENHUT, D O Division of Licensing 80/10/06 6pp
- 8011030525 Requests that encl preservice insp & testing requirements to ensure snubber operability be included in licensing process & be implemented at facility TEDESCO, R L Assistant Director for Licensing 80/10/17. 4pp. 06873-002
- 8011190527 Summary of 801002 meeting w/util in Bethesda, MD re interim status rept on risk evaluation study BELL, D Licensing Branch 2 80/10/20 5pp 06998 133
- 8011180497 Submits info re environ qualification of safety-related equipment, in response to NRC 801001 ltr One environ qualification test planned for Peach Bottom, w/pertinent info encl, Info for Limerick will be provided 801128 KEMPER, J S Philadelphia Electric Co 80/11/12 2pp
- 8011240005 Requests announcement of NRC 801209 meeting at Pottstown, PA be transmitted for publication in newspapers Announcement & newspapers list encl SCHWENGER, A. Licensing Branch 2 80/11/17 3pp 02227 001
- B Utility Preliminary Safety Analysis Report, amends**
- 8009290378 Forwards Amend 24 to application for OL & revised Pages to PBAR, Summary description of amend revision encl BRADLEY, E J Philadelphia Electric Co 80/09/24 4pp 06623 154
- 8009290380 Amend 24 to application for OL, Revises PBAR Pages 5 12-13 & 3 2-16, Certificate of Svc encl BOYER, V S Philadelphia Electric Co 80/09/24. 4pp 06623 158
- F. Security, medical, emergency & fire protection plans**
- 8011170001 Forwards Facility emergency planning info for placement in LPDR H/o encl. BOUDER, J L Division of Rules and Records 80/11/04 1p 06978 263.
- H General correspondence**
- 801120328 Trip rept of 801016 visit to Philadelphia, PA to meet w/Association of Community Organizations for Reform Now re licensing process. Organization demands that const be stopped at facility. BELL, D E Licensing Branch 2 80/10/27 3pp. 06956 254
- G Inspection reports, IE Bulletins & correspondence**
- 8011100321 Forwards IE Insp Repts 50-352/80-14 & 50-353/80-12 on 800701-18 & 28-31 No noncompliance noted CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/16 2pp 06929 186
- 8011100332 IE Insp Repts 50-352/80-14 & 50-353/80-12 on 800701-18 & 28-31 No noncompliance noted Major areas inspected: safety-related piping & supports, equipment storage & const electrical activities. MATTIA, J C. Region 1, Philadelphia, Office of the Director MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/15 9pp 06929 188
- 8011170622 Forwards IE Insp Repts 50-352/80-16 & 50-353/80-14 on 800804-29. No noncompliance noted CARLSON, R T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/17 2pp 06981 251
- 8011170634 IE Insp Repts 50-352/80-16 & 50-353/80-14 on 800804-29. No noncompliance noted Major areas inspected, electrical activities, pipe hanger installation, document control & rework activities MATTIA, J C, MCGAUGHY, R W. Region 1, Philadelphia, Office of the Director 80/08/17 5pp 06981 253
- 8011060535 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." IEB 79-01B & suppl 2 800229, not previously transmitted, also encl No written response required. GRIER, B H Region 1, Philadelphia, Office of the Director, 80/09/30 1p 06911 355
- 8011190786 Ack receipt of 800926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-12 & 50-353/80-10 CARLSON, R T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/10/10. 1p. 06996 133.
- 8011190307 Responds to NRC 800827 ltr re violations noted in IE Insp Repts 50-352/80-12 & 50-353/80-10 Corrective actions: halted insp by unqualified inspector, replaced defective thermometer & removed unauthorized weld tacks. KEMPER, J S Philadelphia Electric Co 80/09/26. 6pp 06996 134.

--8011190319 Forwards IE Insp Repts 50-352/80-12 & 50-353/80-10 on 800616-27 & notice of violation
CARLSON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/08/27 2pp 06996 140

--8011190324 Notice of violation from insp on 800616-27
+ Region 1, Philadelphia, Office of the Director 80/08/26 4pp.
06996 142

--8011190329 IE Insp Repts 50-352/80-12 & 50-353/80-10 on 800616-27
Noncompliance noted failure to properly qualify inspector,
use of inaccurate thermometers & failure to follow field
const drawing procedures & design drawing requirements.
MATTIA, J. C., WALTON, O., REYNOLDS, B Region 1, Philadelphia, Office
of the Director 80/08/26 22pp 06996 146

8011030525 Requests that encl preservice insp & testing requirements to
ensure snubber operability be included in licensing process
& be implemented at facility
TEDESCO, R.L. Assistant Director for Licensing 80/10/17. 4pp

8011060442 Forwards IE Info Notice 80-37, "Containment Cooler Leaks &
Reactor Cavity Flooding At Indian Point Unit 2 " No written
response required
ORIER, B.H. Region 1, Philadelphia, Office of the Director
80/10/24 1p 06909 325

8011070308 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " No written response
required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director
80/10/24. 1p. 06921.348

8011140235 Forwards IE Circular 80-23, "Potential Defects in Beloit
Power Sys Emergency Generators." No written response
required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director
80/10/31. 1p 06968 233

8011140598 Forwards IE Info Notice 80-39, "Malfunction of Solenoid
Valves Mfg by Valcor Engineering Corp " No written response
required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director
80/10/31 1p 06963 239

B Reportable occurrences, LERs & related correspondence

8011050040 Ack receipt of 800925 interim deficiency rept re ASME bolts,
nuts & studs obtained from unapproved sources Matter will be
reviewed following receipt of final rept
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/10/01. 1p 06896 290.

8011140396 Final deficiency rept (Significant Deficiency Rept 17) re
Coit Industries emergency diesel generator possible field
insulation damage. All info provided in vendor 800922 Part 21
rept.
KEPPER, J.B. Philadelphia Electric Co 80/11/06. 2pp. 06962 342

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of
Mark I owners group to discuss pool swell load definition
techniques & methodology for condensation, oscillation,
chugging & lateral load definition.
GRIMEB, C.I. Assistant Director for Engineers & Projects (Pre
790625) 79/03/02. 2pp. 03143 305.

8011050354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TH1 action
plan requirements. Provides summary listing of all approved
TH1-2 related requirements.
EISENHUT, D.O. Division of Licensing. 80/09/05 209pp.

801100484 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs. Info needed by 801101
EISENHUT, D.O. Division of Licensing. 80/10/01. 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issues A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D.O. Division of Licensing. 80/10/06. 6pp.

8011170371 Responds to NRC 801001 request for info re environ
qualification of safety-related equipment test & schedule
Info will be completed by 801201
MITTL, R.L. Public Service Electric & Gas Co of New Jersey
80/11/05 1p 06976 269

O Adjudicatory correspondence

8011250009 Informs that final regulations discussed in HJ Miller
800226-27 testimony published in 801003 FR & that Kerr-
McGee filed petition for review on 801003 to have
regulations declared invalid
BORDENICK, B.M. Hearing Branch 4 80/11/19 3pp

G Inspection reports, IE Bulletins & correspondence

8011180466 Forwards IE Insp Repts 50-354/80-12 & 50-355/80-12 on
800806-0901 No noncompliance noted
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/09/16 2pp 06989 250

--8011180472 IE Insp Repts 50-354/80-12 & 50-355/80-12 on 800806-0901 No
noncompliance noted Major areas inspected backfill
operations, storage of mats & equipment, concrete repairs,
caddwaling & concrete placement operations
BATEMAN, W.H., MCGAUGHY, R.W. Region 1, Philadelphia, Office of the
Director 80/09/15. 8pp 06989 252

801130076 Forwards IE Insp Repts 50-354/80-13 & 50-355/80-13 on
800826-29, 0902-03 & 09 No noncompliance noted
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch. 80/09/22 2pp 06958 203

--801130084 IE Insp Repts 50-354/80-13 & 50-355/80-13 on 800826-29,
0902-03 & 09 No noncompliance noted Major areas inspected
work in progress for concrete placement of lower bioshield
wall & repts on heave/settlement measurement program
VARELA, A.A. Region 1, Philadelphia, Office of the Director
EBNETER, S.D. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/09/19 6pp 06958 205

8011050925 Ack receipt of 800827 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-354/80-04 &
50-355/80-04
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/09/29 1p 06900 221

--8011050529 Suppl 800721 response to violations noted in IE Insp Repts
50-354/80-04 & 50-355/80-04 Responsible GC inspector knew
free fall concrete requirements but could not implement
procedure due to absence of field engineer
MARTIN, T.J. Public Service Electric & Gas Co of New Jersey
80/08/27. 1p. 06900 222

8011060548 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " IE 79-01B & suppl
dtd 800229, not previously transmitted, also encl No written
response required
ORIER, B.H. Region 1, Philadelphia, Office of the Director
80/09/30 1p 06909 280

8011260425 Forwards IE Insp Repts 50-354/80-15 & 50-355/80-15 on
800909. No noncompliance noted
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch. 80/10/01 2pp 07072 355

--8011260428 IE Insp Repts 50-354/80-15 & 50-355/80-15 on 800909 No
noncompliance noted Major areas inspected GA program
procedures & implementation
PACILIND, R.J. Region 1, Philadelphia, Office of the Director
EBNETER, S.D. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/09/30 4pp 07072 357

8011060661 Forwards IE Info Notice 80-37, "Containment Cooler Leaks &
Reactor Cavity Flooding At Indian Point Unit 2 " No written
response required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director
80/10/24. 1p 06914 293

8011070323 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment." No written response
required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director
80/10/24 1p. 06922 017

8011140083 Forwards IE Circular 80-23, "Potential Defects in Beloit
Power Sys Emergency Generators." No written response
required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director
80/10/31. 1p. 06965 318.

DOCKETED ITEMS

801170877 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/10/31 1p 06981 218

S Reportable occurrences, LERs & related correspondence

8011050978 Ack receipt of 800915 interim deficiency rept re incomplete documentation on biological shield wall insp Rept will be reviewed & evaluated
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/29 1p 06896 303

--8011050119 Second interim deficiency rept re 800701 notification of incomplete documentation for biological shield wall insp Bechtel performed ultrasonic survey of outer shell to base plate weld & plate
MARTIN, T J Public Service Electric & Gas Co of New Jersey
80/09/15, 2pp 06896 304

801190487 Interim deficiency rept, originally reported on 801009, re two Class 2 carbon steel pipes supplied by LaBarge Inc lacking radiography of longitudinal weld seam Matl returned to LaBarge. Next rept to be submitted on 801209
MARTIN, T J Public Service Electric & Gas Co of New Jersey.
80/11/10 2pp 07000 027

801190512 Deficiency rept suppl, originally reported on 801010, re spool weld buildup insufficient exam Bechtel Power Corp currently determining corrective actions Reportability determination will be completed by 801212
MARTIN, T J Public Service Electric & Gas Co of New Jersey
80/11/12 2pp 07000 003

V Operator Examinations

8011260086 Discusses talcon re shift experience requirements for license candidates Min of 3 months experience is necessary, but should be separated into multiple wk segments on specific topics Course schedules encl.
SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey
80/11/17 7pp 07071 313

DOCKET 50-355 MOPE CREEK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7903200201 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation, oscillation, chugging & lateral load definition
GRIMES, C I Assistant Director for Engineers & Projects (Pre 790623) 79/03/02 2pp 03145 305

8011050354 Ltr to all licensees of operating plants, applicants for OLS & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
ETSEKHUT, D O Division of Licensing. 80/09/05. 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
ETSEKHUT, D O Division of Licensing 80/10/01 3pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports " W/o encl
ETSEKHUT, D O Division of Licensing 80/10/06 6pp

801170371 Responds to NRC 801001 request for info re environ qualification of safety-related equipment test & schedule. Info will be completed by 801201
MITTL, R L Public Service Electric & Gas Co of New Jersey.
80/11/05 1p 06976 269

G Adjudicatory correspondence

8011250009 Informs that final regulations discussed in MJ Miller 800226-27 testimony published in 801003 FR & that Kerr-McGee filed petition for review on 801003 to have regulations declared invalid
BORDENICK, B M Hearing Branch 4 80/11/19. 3pp.

G Inspection reports, IE Bulletins & correspondence

801180466 Forwards IE Insp Repts 50-354/80-12 & 50-355/80-12 on 800806-0901 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/16 2pp 06989 250

--801180472 IE Insp Repts 50-354/80-12 & 50-355/80-12 on 800806-0901 No noncompliance noted Major areas inspected backfill operations, storage of matls & equipment, concrete repairs, caddwelding & concrete placement operations
BATEMAN, W.H., MCGAUOHY, R W Region 1, Philadelphia, Office of the Director 80/09/15 8pp 06989 252

801130076 Forwards IE Insp Repts 50-354/80-13 & 50-355/80-13 on 800826-29, 0902-03 & 09 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/22 2pp 06958 203

--801130084 IE Insp Repts 50-354/80-13 & 50-355/80-13 on 800826-29, 0902-03 & 09 No noncompliance noted Major areas inspected work in progress for concrete placement of lower bioshield wall & repts on heave/settlement measurement program
VARELA, A A Region 1, Philadelphia, Office of the Director.
EBNETER, S.D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/19. 6pp 06958 205

8011050925 Ack receipt of 800827 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80-04 & 50-355/80-04
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/29 1p 06900 221

--8011050929 Suppls 800721 response to violations noted in IE Insp Repts 50-354/80-04 & 50-355/80-04 Responsible GC inspector knew free fall concrete requirements but could not implement procedure due to absence of field engineer
MARTIN, T J Public Service Electric & Gas Co of New Jersey.
80/08/27, 1p 06900 222

8011060348 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " IEB 79-01B & suppl dtd 800229, not previously transmitted, also encl No written response required.
GRIER, B.H Region 1, Philadelphia, Office of the Director
80/09/30, 1p 06909 280

8011260425 Forwards IE Insp Repts 50-354/80-15 & 50-355/80-15 on 800909 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/01 2pp 07072 355

--8011260428 IE Insp Repts 50-354/80-15 & 50-355/80-15 on 800909 No noncompliance noted Major areas inspected QA program procedures & implementation
PAOLINO, R J Region 1, Philadelphia, Office of the Director
EBNETER, S.D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/30 4pp. 07072.357.

8011060661 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
GRIER, B.H Region 1, Philadelphia, Office of the Director
80/10/24 1p 06914 293

8011070323 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director.
80/10/24, 1p 06922 017

801140083 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators " No written response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director
80/10/31, 1p 06965.318.

801170877 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
GRIER, B H. Region 1, Philadelphia, Office of the Director
80/10/31 1p. 06981 218.

S Reportable occurrences, LERs & related correspondence

801190487 Interim deficiency rept, originally reported on 801009, re two Class 2 carbon steel pipes supplied by LaBarge Inc lacking radiography of longitudinal weld seam Matl returned to LaBarge. Next rept to be submitted on 801209.
MARTIN, T.J. Public Service Electric & Gas Co of New Jersey.
80/11/10. 2pp. 07000:027

DOCKETED ITEMS

169

801190512 Deficiency rept suppl. originally reported on 801010, re spoil
weld buildup insufficient exam Bechtel Power Corp currently
determining corrective actions Reportability determination
will be completed by 801212
MARTIN, T J Public Service Electric & Gas Co of New Jersey
80/11/12 2pp 07000 003

V Operator Examinations

8011260086 Discusses telcon re shift experience requirements for
license candidates Min of 3 months experience is
necessary, but should be separated into multiple wk segments
on specific topics Course schedules encl
SCINEIDER, F.W Public Service Electric & Gas Co of New Jersey
80/11/17 9pp

DOCKE: 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TMI action
plan requirements Provides summary listing of all approved
TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports " H/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

801170188 Summary of 801015 meeting w/util in Bethesda, MD re potential
sifting problem at river intake, describing progress made to
date & changes in original approach
PELTIER, I A Licensing Branch 1 80/10/17 6pp 06919 001

8011050535 Forwards request for addl info re emergency procedure
guidelines. Schedule must be submitted by 801027 OE 800630
guidelines acceptable for trial implementation Training
program must account for possible mod
EISENHUT, D O Division of Licensing 80/10/21 8pp 06902 086.

8011140491 Provides info on design, procurement & installation of
inserting sys
EISENHUT, D O Division of Licensing 80/10/24 2pp 06911 001.

8011030591 Forwards Amend 13 to Mark II containment design assessment
rept
BORGMANN, E A Cincinnati Gas & Electric Co 80/10/31 1p
06898 003

--8011030593 Amend 13 to "Mark II Containment Design Assessment Rept "
* Cincinnati Gas & Electric Co 80/10/31 650pp. 06898 004

8011040579 Responds to NRC staff positions on degraded grid voltage &
protection of reactor containment electrical penetrations
Existing load shedding sys is designed to prevent
inadvertent load shed operations
FLYNN, J D Cincinnati Gas & Electric Co 80/10/31 3pp
06873:095.

801120385 Responds to NRC 800821 ltr re permitted exemptions per
14B-1270(b)(1) of ASME Code, Section II. Alleges current NRC
interpretation differs from previous yrs. States position re
pipe & weld joint exemptions to resolve discrepancy
FLYNN, J D Cincinnati Gas & Electric Co 80/11/04 2pp
06950:326

801120328 Responds to NRC 801001 ltr to all licensees of operating
plants & applicants for OLs re environ qualification of
safety-related equipment Info will be transmitted when
available
FLYNN, J D Cincinnati Gas & Electric Co 80/11/04 1p 06953 348

801130182 Forwards Revision 67 to FSAR, constituting Amend 110 to OL
application
BORGMANN, E A Cincinnati Gas & Electric Co 80/11/07 2pp
06957 011.

8011240378 Responds to NRC 800910 request for supplemental info on
masonry wall design Info is being sent under separate
cover
FLYNN, J D Cincinnati Gas & Electric Co 80/11/19 1p 07046 328

8011260209 Forwards response to questions contained in RL Tedesco
800910 ltr re masonry wall design Five oversize drawings
available in Central Files only
FLYNN, J D Cincinnati Gas & Electric Co 80/11/19 1p 07076 001.

--8011260210 Responds to 800910 ltr re Category 1 masonry wall design
info Forwards supplement to info provided in 800718
ltr Five oversize drawings available in Central Files only
FLYNN, J D Cincinnati Gas & Electric Co 80/11/19 130pp
07076 002

F Security, medical, emergency & fire protection plans

8011060019 Forwards emergency planning info for housing in Batavia, OH
LPDR H/o encl
BOUDER, J L Division of Rules and Records 80/10/23 1p
06914,145.

O Adjudicatory correspondence

801180069 Notice of Kosik withdrawal & JH Feldman substitution in
proceeding Certificate of Bvc encl
KOSIK, L, FELDMAN, J H Miami Valley Power Project. KOSIK, L Kosik,
L B 80/09/25 2pp 06987 345

8011060175 Response to NRC 801010 interrogatories re B&W study on
population evacuation Study is subj to revision due to
development of NRC position & state & local emergency plans
W/Certificate of Bvc Related correspondence
BORGMANN, E A Cincinnati Gas & Electric Co 80/10/28 6pp
06912 147

8011250578 Motion to require NRC to provide justification of inability
to proceed. More incantation of TMI proceedings is no longer
justification Certificate of Bvc encl
CONNER, T B, WEYTERHAHN, M J Conner, Moore & Corber. 80/11/19
9pp 07068 349

I Financial information

8011210483 Forwards revised pages to 750910 amend application &
response to 781127 request for addl financial info.
BORGMANN, E A Cincinnati Gas & Electric Co 80/11/19 2pp.
07034 212

--8011210486 Revised pages to 750910 amend & response to 781127 request
for addl financial info
* Cincinnati Gas & Electric Co 80/11/14 1015pp. 07034 214

K. Utility Final Safety Analysis Report (FSAR) & amends

801130182 Forwards Revision 67 to FSAR, constituting Amend 110 to OL
application
BORGMANN, E A Cincinnati Gas & Electric Co 80/11/07 2pp.
06957 011

--801130186 Revision 67 to FSAR,
* Cincinnati Gas & Electric Co 80/11/30 30pp. 06957 013

8011240086 Forwards Certificate of Bvc of Amend 110 to application for
licenses, in form of Revision 67 to FSAR
BORGMANN, E A Cincinnati Gas & Electric Co 80/11/14 2pp
07049 138

M Antitrust correspondence

8011200400 Forwards notice of supplementary antitrust review of OL
application which has been sent to FR for publication.
SCHWENCER, A Licensing Branch 2 80/11/06 2pp 01741 019

--8011200401 Notice of issuance & availability of supplementary antitrust
review of OL application
SCHWENCER, A Licensing Branch 2. 80/11/06 2pp 01741 019.

G Inspection reports, IE Bulletins & correspondence

801100039 Ack receipt of 800926 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 80-358/80-20.
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/10/17 1p 06928 359

DOCKETED ITEMS

--801100043 Responds to NRC 800902 ltr re violations noted in IE Insp Rept 50-358/80-20 Corrective actions special process procedure manual has been revised to implement ENT-TC-1A 1975 edition
BORGMANN, E A Cincinnati Gas & Electric Co 80/09/26 2pp
06928 360

8011030132 Ack receipt of 801001 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/80-16
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/20 1p 06897 251

--8011030138 Responds to NRC 800903 ltr re violations noted in IE Insp Rept 50-358/80-16 Corrective actions revised OA manual will be issued on 801031 & FSAR will be revised to reflect program changes
BORGMANN, E A Cincinnati Gas & Electric Co 80/10/01 2pp
06897 292

8011030248 Ack receipt of 800910 ltr informing NRC of steps taken re preoperational environ protection insp on 800806-08 NRC is presently contacting other companies re use of poles
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/21 1p 06897 216

--8011030253 Responds to NRC ltr re preoperational environ protection insp on 800806-08 Pole locations compiled indicating ownership & use of poles Requests advance notice when poles are to be used
BORGMANN, E A Cincinnati Gas & Electric Co 80/09/10 3pp
06897 217

8011070310 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/24 1p 06921-332

8011040168 Forwards response to NRC 800606 request for addl info re IE Bulletin 80-07 item on BMR jet pump holddown beams.
FLYNN, J D Cincinnati Gas & Electric Co 80/10/31 2pp
06877-014

801110007 Ack receipt of 801008 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/80-19.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/04 1p 06943-218

--8011100014 Responds to NRC 800919 ltr re violations noted in IE Insp Rept 50-358/80-19 Corrective actions revision to RHR sys release was promulgated via correct form on 800823.
BORGMANN, E A Cincinnati Gas & Electric Co 80/10/08 4pp
06943 219

8 Reportable occurrences, LERs & related correspondence

8011030616 Third interim deficiency rept re two of 37 HVAC damper actuators 1V009VB & 1VC26Y, failing recycling test Actuators returned to IIT Next rept by 801113
BORGMANN, E A Cincinnati Gas & Electric Co 80/10/24 2pp
06893-072

8011190733 Ack receipt of 801013 interim deficiency rept re failure of five Gould, Inc Type J-13 auxiliary relays.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/30 1p 06916 001

--8011190742 Interim deficiency rept re failure of five Gould, Inc Type J-13 auxiliary relays Failures of relays on dc circuits have been from open circuited coils. Gould, Inc has been notified & is investigating failures.
BORGMANN, E A Cincinnati Gas & Electric Co 80/10/13 1p
06916:001

8011140355 Interim deficiency rept originally reported on 801014 re defective heating, ventilation & air conditioning isolation dampers. Caused by seismically unqualified actuators Supplier submitted proposed mod procedure to vendor
BORGMANN, E A Cincinnati Gas & Electric Co 80/11/04 2pp
06963 237

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements. Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

8011170304 Expresses concern re adequacy of delta earthquake model re Parkfield earthquake analysis Large motion near fault appears due to near-field effect of crack tip passage, rather than focusing effect proposed in delta calculation
AKI, K Massachusetts Institute of Technology 80/09/16 2pp
06978 190

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports" W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

801100378 Forwards util responses to NRC 800829 human factors engineering control room design review Responses reflect NRC 800916 comments & satisfy concerns per NRC 800804-08 audit
BASKIN, K P Southern California Edison Co 80/10/29 15pp
06931 001

8011040212 Forwards "Natl Register Assessment Program of Cultural Resources of 230 kV Transmission Line Rights-of-Way From San Onofre to Black Star Canyon & Santiago Substation & to Encina & Mission Valley Substation," Vol 1
BASKIN, K P Southern California Edison Co 80/10/31 2pp
06880 190

--8011040219 "Natl Register Assessment Program of Cultural Resources of 230 kV Transmission Line Rights-of-Way From San Onofre to Black Star Canyon & Santiago Substation & to Encina & Mission Valley Substation," Vol 1 Prepared for util
MCCOY, L C, PHILLIPS, R Westec Services, Inc. 80/09/30 350pp
06880-192

8011210010 Forwards request for addl info needed as result of review of FSAR Revised emergency plan meets requirements but needs revision addressing new rule & 10CFR50 schedule Emergency response exercise must be conducted prior to DL issuance
TEDESCO, R L Division of Licensing 80/11/07 62pp 07030 244

8011250460 Forwards emergency operating instructions for facilities re LOCA steam generator tube rupture, loss of feedwater & steam generator level & determination of adequate core cooling
BASKIN, K P Southern California Edison Co 80/11/12 1p
07058-310

--8011250471 Emergency Operating Procedure S023-3-6, "LOCA"
MORAN, H E, CURRAN, J M Southern California Edison Co 80/11/06 11pp 07058 311

--8011250482 Emergency Operating Procedure S023-3-5 29, "Steam Generator Tube Rupture"
MORAN, H E Southern California Edison Co CURRAN, J M South Carolina Electric & Gas Co 80/11/06 11pp 07058 322

--8011250494 Emergency Operating Procedure S023-3-5 30, "Loss of Feedwater or Steam Generator Level"
MORAN, H E, CURRAN, J M Southern California Edison Co 80/11/06 7pp 07058 333

--8011250503 Emergency Operating Procedure S023-3-2 30, Revision 1, "Determination of Adequate Core Cooling"
MORAN, H E, CURRAN, J M Southern California Edison Co 80/11/06 11pp 07058 340

8011250285 Advises that completion of LOCA qualification testing of cable w/insulated repairs identified in significant deficiency rept now scheduled for 810415
NUNN, D E Southern California Edison Co 80/11/14 1p 07058:083

8011250349 Forwards participation agreement among Southern CA Edison Co, San Diego Gas & Electric Co & Cities of Riverside & Anaheim, CA re ownership of facilities for amend to CP.
BASKIN, K P Southern California Edison Co 80/11/14 1p
07058-017

--8011250357 Participation agreement among Southern CA Edison Co, San Diego Gas & Electric Co, City of Riverside, CA & City of Anaheim, CA re ownership of facilities.
BORKLUND, J Southern California Edison Co, San Diego Gas & Electric Co BROWN, A Riverside, CA 80/10/23 300pp
07058 016

8011200197 Forwards proprietary & nonproprietary versions of CEN-140 (B), "Data Transmittal for Southern CA Edison Fuel Audit," in response to NRC 800909 request Affidavit for withholding encl.
BASKIN, K.P. Southern California Edison Co 80/11/18 6pp
07022.049.

--8011200207 Nonproprietary version of CEN-140(B)-NP, "Data Transmittal for Southern CA Edison Fuel Audit Analysis"
* C-E Power Systems. CEN-140(B)-NP 80/10/10 33pp 07022 054

8011200247 Responds to request for addl info Forwards insert pages for fuel handling bldg calculations submitted in 790706 ltr & seawall structural design info in response to FSAR Question 131.34 Info withheld (ref 10CFR2 790)
BASKIN, K.P. Southern California Edison Co 80/11/18. 1p
07018.102

8011250298 Forwards Technical Apps A-M Vols II & III of Natl Register Assessment Program of Cultural Resources of 230 kV Transmission Line Rights-of-Way Documents withheld per Archaeological Resources Protection Act of 1979
BASKIN, K.P. Southern California Edison Co. 80/11/19 1p
07058.351.

8011280071 Forwards "Auxiliary Feedwater Sys Design Review & Reliability Evaluation."
BASKIN, K.P. Southern California Edison Co 80/11/24 1p.
07082.265.

--8011280073 "Auxiliary Feedwater Sys Design Review & Reliability Evaluation"
* Southern California Edison Co 80/10/31. 79pp. 07082:266

8011280099 Forwards "Secondary Water Chemistry Monitoring Program for San Onofre Nuclear Generating Station Units 2 & 3," per 790824 ltr. FSAR will be amended to include program
BASKIN, K.P. Southern California Edison Co. 80/11/25 1p
07084:128.

--8011280011 "Secondary Water Chemistry Monitoring Program for San Onofre Nuclear Generating Station Units 2 & 3"
* Southern California Edison Co 80/11/30 62pp 07084:129.

F Security, medical, emergency & fire protection plans

8011040177 Forwards emergency planning info for housing in Mission Viejo, CA LPDR W/o encl
BOUDER, J.L. Division of Rules and Records. 80/10/23 1p.
04911.343.

8011210010 Forwards request for addl info needed as result of review of FSAR Revised emergency plan meets requirements but needs revision addressing new rule & 10CFR30 schedule Emergency response exercise must be conducted prior to DL issuance
TEDESOD, R.L. Division of Licensing. 80/11/07 62pp 07030 244

G. Adjudicatory correspondence

8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREG-0625, "Rept of Siting Policy Task Force." Documents 6-B & 13 are available in PDR. Forwards remaining documents.
FELTON, J.M. Division of Rules and Records. 80/09/04. 1p
04584:288.

--8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features.
MINOQUE, R.B. Office of Standards Development. Director SECY-79-362 79/06/04. 7pp.

--8009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards.
SCINTO, J.F. Hearings Division. 79/04/04. 16pp.

8011040504 Petition to deny OLS.
PAPP-NOODAND, P., CHRISTOPH, A., KIPPER, W. Affiliation Unknown. 80/10/11. 1p. 02319:196.

H General correspondence

8011050037 Responds to 800929 ltr discussing B Feldman concerns re nuclear insurance & liability coverage Price-Anderson Act provides \$560 million to pay public liability claims for personal injury & property damage resulting from incidents
DIRCKB, W.J. Office of the Executive Director for Operations 80/10/22 3pp 06894 117

I. Financial information

8011250549 Forwards participation agreement among Southern CA Edison Co, San Diego Gas & Electric Co & Cities of Riverside & Anaheim, CA re ownership of facilities for amend to CP
BASKIN, K.P. Southern California Edison Co 80/11/14 1p
07058:017

--8011250557 Participation agreement among Southern CA Edison Co, San Diego Gas & Electric, City of Riverside, CA & City of Anaheim, CA re ownership of facilities
BJORKLUND, J. Southern California Edison Co + San Diego Gas & Electric Co BROWN, A. Riverside, CA 80/10/23 300pp
07058:018

K Utility Final Safety Analysis Report (FSAR) & amends

8011210148 Forwards Amend 21 to FSAR
DIETCH, R. Southern California Edison Co 80/11/14 4pp
07059.001

--8011210157 Amend 21 to FSAR, Vols 1 & 2, providing info re open items, responding to addl NRC 800523 & 0728 questions & providing FSAR level details on TMI changes previously transmitted on 800912
DIETCH, R. Southern California Edison Co 80/11/14 1.175pp.
07059 003

Q Inspection reports, IE Bulletins & correspondence

8011040753 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting" No written response required
ENGELWEN, R.H. Region 5, San Francisco, Office of the Director 80/10/10. 1p. 04909 051

8011130034 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required.
ENGELWEN, R.H. Region 5, San Francisco, Office of the Director 80/10/24 1p 04958:082

8011040118 Ack receipt of 801006 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-361/80-12
CREWS, J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/10/27 1p 04912 144

--8011040126 Responds to NRC 800917 ltr re violations noted in IE Insp Rept 50-361/80-12 Corrective actions const sys turnover packages & turnover package change requests in EDMC reviewed to assure of proper signatures
PAPAY, L.T. Southern California Edison Co 80/10/06 3pp
04912:165

--8011040131 Forwards IE Insp Rept 50-361/80-12 on 800718-0815 & notice of violation
CREWS, J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/09/17. 2pp 04912:168

--8011040135 Notice of violation from insp on 800718-0815
* Region 5, San Francisco, Office of the Director 80/09/16 1p
04912:170

--8011040144 IE Insp Rept 50-361/80-12 on 800718-0815 Noncompliance noted: no criteria provided for determining when station mgt must sign turnover packages. Some turnover packages & changes to packages not signed
JOHNSON, A.D., PATE, R.J., CHAFFEE, A. Region 5, San Francisco, Office of the Director 80/09/16 6pp. 04912 171.

8011170640 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators" No written response required.
ENGELWEN, R.H. Region 5, San Francisco, Office of the Director 80/10/31 1p. 04976:349.

DOCKETED ITEMS

S Reportable occurrences, LERs & related correspondence

8011170547 Interim deficiency rept re undersize socket weld connections in ASME code piping in safety-related sys Program initiated to reinsp socket welds on all ASME Section III piping 2 inches in diameter & smaller PAPAY, L T Southern California Edison Co 80/11/07 3pp 06977 313

8011210432 Part 2i rept re DSRV standby diesel generator component defect Util unable to meet schedule for insp due to incomplete const SVC engineers will witness final detailed installation & prestart checking Util 801009 1br encl MARTINI, D Transamerica Delaval, Inc 80/11/11 3pp 07034 001

8011250285 Advises that completion of LOCA qualification testing of cable w/insulated repairs identified in significant deficiency rept now scheduled for 810415 NUNN, D E Southern California Edison Co 80/11/14 1p 07056 083

8011250301 Final deficiency rept originally submitted 801022 re low pressure safety injection valve failure Valve manufacturer modified valve design to eliminate flow induced vibration Other Target Rock globe valves have guided valve discs PAPAY, L T Southern California Edison Co 80/11/18 4pp 07059 152

DOCKET 80-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements EISENHUT, D G Division of Licensing 80/09/03 207pp

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101 EISENHUT, D G Division of Licensing 80/10/01 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl. EISENHUT, D G Division of Licensing 80/10/06 6pp

801100378 Forwards util responses to NRC 800829 human factors engineering control room design review Responses reflect NRC 800916 comments & satisfy concerns per NRC 800804-08 audit BASKIN, K P Southern California Edison Co 80/10/29 15pp 06931 001

8011040212 Forwards "Nat'l Register Assessment Program of Cultural Resources of 230 kV Transmission Line Rights-of-Way From San Onofre to Black Star Canyon & Santiago Substation & to Encina & Mission Valley Substation," Vol 1 BASKIN, K P Southern California Edison Co 80/10/31 2pp 06980 190

--8011040219 "Nat'l Register Assessment Program of Cultural Resources of 230 kV Transmission Line Rights-of-Way From San Onofre to Black Star Canyon & Santiago Substation & to Encina & Mission Valley Substation," Vol 1, Prepared for utility HCCDY, L C, PHILLIPS, R Westec Services, Inc 80/09/30 350pp 06980 192

8011210010 Forwards request for addl info needed as result of review of FSAR Revised emergency plan meets requirements but needs revision addressing new rule 8 10CFR50 schedule Emergency response exercise must be conducted prior to DL issuance TEDESCO, R L Division of Licensing 80/11/07 62pp 07030 244

8011250460 Forwards emergency operating instructions for facilities re LOCA steam generator tube rupture, loss of feedwater & steam generator level & determination of adequate core cooling BASKIN, K P Southern California Edison Co 80/11/12 1p 07058 310

--8011250471 Emergency Operating Procedure 8023-5 6, "LOCA" MORGAN, H E, CURRAN, J M Southern California Edison Co 80/11/06 11pp 07058 311

--8011250482 Emergency Operating Procedure 8023-3-5.29, "Steam Generator Tube Rupture" MORGAN, H E Southern California Edison Co, CURRAN, J M South Carolina Electric & Gas Co 80/11/06 11pp 07058 322

--8011250494 Emergency Operating Procedure 8023-3-5.30, "Loss of Feedwater or Steam Generator Level" MORGAN, H E, CURRAN, J M Southern California Edison Co 80/11/06 7pp 07058 333

--8011250503 Emergency Operating Procedure 8023-3-2 30, Revision 1, "Determination of Adequate Core Cooling" MORGAN, H E, CURRAN, J M Southern California Edison Co 80/11/06 11pp 07058 340

8011250285 Advises that completion of LOCA qualification testing of cable w/insulated repairs identified in significant deficiency rept now scheduled for 810415 NUNN, D E Southern California Edison Co 80/11/14 1p 07056 083

8011250549 Forwards participation agreement among Southern CA Edison Co, San Diego Gas & Electric Co & Cities of Riverside & Anaheim, CA re ownership of facilities for amend to CP BASKIN, K P Southern California Edison Co 80/11/14 1p 07058 017

--8011250557 Participation agreement among Southern CA Edison Co, San Diego Gas & Electric, City of Riverside, CA & City of Anaheim, CA re ownership of facilities BJORKLUND, J Southern California Edison Co * San Diego Gas & Electric Co BROWN, A Riverside, CA 80/10/23 300pp 07058 018

8011200199 Forwards proprietary & nonproprietary versions of CEN-140 (B), "Data Transmittal for Southern CA Edison Fuel Audit," in response to NRC 800909 request Affidavit for withholding encl BASKIN, K P Southern California Edison Co 80/11/18 6pp 07022 049

--8011200207 Nonproprietary version of CEN-140(B)-NP, "Data Transmittal for Southern CA Edison Fuel Audit Analysis," * C-E Power Systems CEN-140(B)-NP 80/10/10 33pp 07022 056

8011200247 Responds to request for addl info Forwards insert pages for fuel handling bldg calculations submitted in 790706 1tr & seawall structural design info in response to FSAR Question 131 34 info withheld (ref 10CFR2 7501) BASKIN, K P Southern California Edison Co 80/11/18 1p 07018 102

8011250298 Forwards Technical Apps A-M Vols II & III of Nat'l Register Assessment Program of Cultural Resources of 230 kV Transmission Line Rights-of-Way " Documents withheld per Archaeological Resources Protection Act of 1979 BASKIN, K P Southern California Edison Co 80/11/19 1p 07058 351

8011280071 Forwards "Auxiliary Feedwater Sys Design Review & Reliability Evaluation" BASKIN, K P Southern California Edison Co 80/11/24 1p 07082 265

--8011280073 "Auxiliary Feedwater Sys Design Review & Reliability Evaluation" * Southern California Edison Co 80/10/31 79pp 07082 266

8011280009 Forwards "Secondary Water Chemistry Monitoring Program for San Onofre Nuclear Generating Station Units 2 & 3," per 790824 1tr, FSAR will be amended to include program, BASKIN, K P Southern California Edison Co 80/11/25 1p 07084 128

--8011280011 "Secondary Water Chemistry Monitoring Program for San Onofre Nuclear Generating Station Units 2 & 3," * Southern California Edison Co 80/11/30 62pp 07084 129

F Security, medical, emergency & fire protection plans

8011060177 Forwards emergency planning info for housing in Mission Viejo, CA LPDR, W/o encl BOUDER, J L Division of Rules and Records 80/10/23 1p 06911 343

8011210010 Forwards request for addl info needed as result of review of FSAR Revised emergency plan meets requirements but needs revision addressing new rule 8 10CFR50 schedule Emergency response exercise must be conducted prior to DL issuance, TEDESCO, R L Division of Licensing 80/11/07 62pp

Q Adjudicatory correspondence

8009190299 Responds to FOIA request for 15 documents listed in bibliography re NUREG-0625, "Rept of Siting Policy Task Force." Documents 6-8 & 13 are available in PDR Forwards remaining documents
FELTON, J. M. Division of Rules and Records 80/09/04 1p.

--8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features
MINOQUE, R. B. Office of Standards Development, Director
SECY-79-362 79/06/04 7pp

--8009190630 Requests that encl, "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards
SCINTO, J. F. Hearings Division 79/04/04 16pp

8011040504 Petition to deny OLs
POPP-WOODLAND, P., CHRISTOPH, A., KIPPER, W. Affiliation Unknown
80/10/11 1p. 02319 196

H General correspondence

8011050037 Responds to 800929 ltr discussing B Feldman concerns re nuclear insurance & liability coverage Price-Anderson Act provides \$560 million to pay public liability claims for personal injury & property damage resulting from incidents.
DIRCKS, W. J. Office of the Executive Director for Operations.
80/10/22 5pp 06894 117

K Utility Final Safety Analysis Report (FSAR) & amends

8011210148 Forwards Amend 21 to FSAR
DIETCH, R. Southern California Edison Co 80/11/14 4pp
07059:001.

--8011210157 Amend 21 to FSAR, Vols 1 & 2, providing info re open items, responding to addl NRC 800523 & 0728 questions & providing FSAR level details on TMI changes previously transmitted on 800912
DIETCH, R. Southern California Edison Co 80/11/14 1,175pp
07059:005

G Inspection reports, IE Bulletins & correspondence

8011060753 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting." No written response required.
ENCKELKEN, R. H. Region 5, San Francisco, Office of the Director.
80/10/10. 1p. 06909.091

801130034 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
ENCKELKEN, R. H. Region 5, San Francisco, Office of the Director.
80/10/24 1p 06958:082

801170640 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.
ENCKELKEN, R. H. Region 5, San Francisco, Office of the Director.
80/10/31. 1p. 06976 349

B. Reportable occurrences, LERs & related correspondence

801170547 Interim deficiency rept re undersize socket weld connections in ASME code piping in safety-related sys. Program initiated to reinsp socket welds on all ASME Section III piping 2 inches in diameter & smaller
PAPAY, L. T. Southern California Edison Co 80/11/07 3pp
06977:313

8011210432 Part 21 rept re DSRV standby diesel generator component defect. Util unable to meet schedule for insp due to incomplete const. Svc engineers will witness final detailed installation & prestart checking. Util 801009 ltr encl.
MARTINI, D. Transamerica Delaval, Inc 80/11/11. 3pp 07034.001.

8011250301 Final deficiency rept, originally submitted 801022, re low pressure safety injection valve failure Valve manufacturer modified valve design to eliminate flow induced vibration. Other Target Rock globe valves have guided valve discs.
PAPAY, L. T. Southern California Edison Co 80/11/18. 4pp.
07055.152.

DOCKET 80-363 FORKED RIVER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D. G. Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101
EISENHUT, D. G. Division of Licensing 80/10/01. 3pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D. G. Division of Licensing 80/10/06 6pp

8011060052 Notification of 801021 meeting w/util in Bethesda, MD to discuss proposed new ECGB to replace core spray spargers
PAULSON, W. Operating Reactors Branch 5 80/10/15 3pp 06912 356

G Inspection reports, IE Bulletins & correspondence

8011060556 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." IE 79-01B & suppl dtd 800229, not previously transmitted, also encl No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/09/30 1p. 06909 289

8011060633 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/10/24 1p 06909 301

8011070286 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/10/24 1p 06921:304

801140132 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/10/31. 1p 06968:223.

801140588 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Hfg by Valcor Engineering Corp." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/10/31 1p. 06969:147

DOCKET 80-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D. G. Division of Licensing. 80/09/05. 209pp

8010020309 Forwards evaluation entitled, "Floodplain Aspects of Farley Nuclear Plant Site."
LEAR, O. E. Hydrologic & Geotechnical Engineering Branch 80/09/16. 1p. 03610:350.

--8010020311 "Floodplain Aspects of Farley Nuclear Plant Site."
* Hydrologic & Geotechnical Engineering Branch. 80/09/16. 3pp 03610.351.

8011030031 Forwards evaluation of floodplain aspects of facility site.
SCHEWENGER, A. Licensing Branch 2 80/09/17. 1p. 06873:048

8011060223 Summary of 800624 meeting w/util, Westinghouse & Bechtel in Bethesda, MD re outstanding items on Unit 2 OL review
KINTNER, L. L. Operating Reactors Branch 2 80/09/25. 8pp
06912.020.

DOCKETED ITEMS

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101 EISENHUT, D G Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800927 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl EISENHUT, D G Division of Licensing 80/10/06 4pp

801100576 Notification of 801030 meeting w/Util & Bechtel Corp in Bethesda, MD to discuss Util proposed means for over current protection of electrical cables in containment penetrations KINTNER, L L Licensing Branch 2 80/10/15 3pp 06912 317

801100589 Notification of 801022 meeting w/Util, Bechtel Corp & Westinghouse in Dethan, AL to review auxiliary feedwater sys. Proposed agenda encl KINTNER, L L Licensing Branch 2 80/10/16 4pp 06912 340

801100469 Forwards responses to questions asked by NRC consultants at BNL re seismic qualification review Discharge piping flange joined to pump discharge flange through bellows-type expansion joint to minimize pipe loads CLAYTON, F L Alabama Power Co 80/10/27 5pp 06873 337

801100308 Forwards addl info re environ qualification of electrical equipment in response to NUREG-0588 CLAYTON, F L Alabama Power Co 80/10/30 35pp 06873 197

801100447 Forwards response to NRC question 210 1, Item 4 re containment sump design Drawings available in Central Files only CLAYTON, F L Alabama Power Co 80/11/04 10pp 06954 001.

I NRC Draft/Final Environmental Statements, supp's & correspondence

011030359 Forwards addendum to NUREG-0727, "FEB Re Operation of Joseph M Farley Nuclear Plant, Units 1 & 2 " SCHWENGER, A Licensing Branch 2 80/10/08 3pp 06873 053

Security, medical, emergency & fire protection plans

011050471 Forwards emergency plan, Revision 4 per NUREG-0654, FEMA-REP-1 & emergency planning final rule requirements Response to NUREG-0694 requirements encl Plan available in Central Files only. CLAYTON, F L Alabama Power Co 80/10/28 10pp 06913 003

11120300 Forwards fire protection info for Fire Area 13, per NRC request CLAYTON, F L Alabama Power Co 80/11/04 3pp 06933 274

11240147 Notifies of privacy review of encl Util emergency plan Plan may be made publicly available FELTON, J M Division of Rules and Records 80/11/24 1p 07031 086

8011240364 Forwards public version of State of AL radiological emergency plan, Revision 4 Also forwards emergency implementing procedures required by App E CLAYTON, F L Alabama Power Co. 80/11/07 2pp 07031 088

8011240375 Public version of facility emergency plan implementing procedure, "Emergency Organization & Control Room Access " HARRISTON, W S Alabama Power Co 80/11/03 7pp 07031:089.

8011240384 Public version of emergency plan implementing procedure, "Duties of Individual Who Discovers an Emergency Condition " HARRISTON, W S. Alabama Power Co. 80/11/03 4pp 07031:096

8011240394 Public version of facility emergency plan implementing procedure, "Duties of Shift Supervisor." HARRISTON, W S Alabama Power Co 80/11/03. 2pp. 07031 100.

8011240477 Public version of facility emergency procedure, "Duties of Emergency Director " HARRISTON, W S, Alabama Power Co 80/11/03 3pp. 07031:102

8011240485 Public version of facility emergency procedure, "Chemistry & Health Physics Support to Emergency Plan " HARRISTON, W S Alabama Power Co 80/11/03. 10pp 07031:103.

--8011240495 Public version of facility emergency plan implementing procedure, "Maint Support to Emergency Plan " HARRISTON, W S Alabama Power Co 80/11/03 3pp 07031 115

--8011240508 Public version of facility emergency plan implementing procedure, "Technical Support to Emergency Plan " HARRISTON, W S Alabama Power Co 80/11/03 8pp 07031 118

--8011240519 Public version of facility emergency plan implementing procedure, "Security Support to Emergency Plan " HARRISTON, W S Alabama Power Co 80/11/03 3pp 07031 126.

--8011240526 Public version of facility emergency plan implementing procedure, "Radiation Exposure Estimation & Classification of Emergencies " HARRISTON, W S Alabama Power Co 80/11/06 21pp 07031 131

--8011240542 Public version of facility emergency plan implementing procedure, "Evacuation & Personnel Accountability " HARRISTON, W S Alabama Power Co 80/11/06 9pp 07031 132

--8011240555 Public version of facility emergency plan procedure, "Handling of Injured Personnel " HARRISTON, W S Alabama Power Co 80/11/06 14pp 07031 161

--8011240562 Public version of facility emergency plan implementing procedure, "Alert " HARRISTON, W S Alabama Power Co. 80/11/06 9pp 07031:175

--8011240567 Public version of facility emergency plan implementing procedure, "Fire Emergencies " HARRISTON, W S Alabama Power Co. 80/11/06 12pp. 07031:184.

--8011240482 Public version of facility emergency implementation procedure, "Re-entry Procedures " HARRISTON, W S Alabama Power Co 80/11/06 4pp 07031 196

--8011240488 Public version of facility emergency implementation procedure, "Emergency Drills " HARRISTON, W S Alabama Power Co 80/11/06 5pp 07031:200

--8011240497 Public version of facility emergency implementation procedure, "Notification of Unusual Event " HARRISTON, W S Alabama Power Co 80/11/06 7pp 07031:203.

--8011240507 Public version of facility emergency implementation procedure, "General Emergency " HARRISTON, W S, Alabama Power Co 80/11/06 7pp 07031:212

--8011240515 Public version of facility emergency implementation procedure, "Recovery - EDF " HARRISTON, W S Alabama Power Co 80/11/06 7pp 07031 219

--8011240528 Public version of facility emergency implementation procedure, "Recovery - TSC " HARRISTON, W S Alabama Power Co. 80/11/06 3pp 07031 229

--8011240573 Public version of State of AL radiological emergency response plan
* Alabama Power Co. 80/11/17. 250pp 07031:233

J Insurance & indemnity information

8011240389 Forwards Amend 7 to Indemnity Agreement B-81 for License NPF-B, per NRC 801023 ltr CLAYTON, F L Alabama Power Co. 80/11/04. 2pp. 07034 062

P Operating license stage documents & correspondence

8011050004 Forwards License NPF-B authorizing fuel loading & low power testing Forwards FR notice & Amend 7 to Indemnity Agreement B-81, W/o Amend 7 to Indemnity Agreement B-81 EISENHUT, D.O. Division of Licensing 80/10/23 3pp. 06895 003

--8011030006 License NPF-B for facility Environ protection plan & Tech Specs encl. DENTON, H.R Office of Nuclear Reactor Regulation, Director. 80/10/23 18pp. 06895:006.

--8011030008 Tech Specs, App A to License NPF-B
* Office of Nuclear Reactor Regulation, Director. NUREG-0697, 80/10/31 400pp Available at OPD. 06895:022.

- B011090009 Environ protection plan (nonradiological) for facility App B to License NPF-B
* Office of Nuclear Reactor Regulation, Director B010/23
13pp 06896 130
- B011050012 Notice of issuance of License NPF-B, authorizing fuel loading & low power testing of facility
YOUNGBLOOD, B J Licensing Branch 1 B010/23 2pp 06896 165
- B011120041 Discusses status of facility licensing License for fuel loading & low power testing issued B01023 Initial criticality scheduled for late Dec Safety evaluation is completed for 3 of 19 non-TMI items & 4 of 15 TMI items
KINTNER, L Licensing Branch 2 B010/28 2pp 06953 330
- B011120611 Application for amend to App A Tech Specs to replace FY limits Proposed revisions to Tech Spec encl
CLAYTON, F L Alabama Power Co B011/03 2pp 06952 040
- B011120614 Proposed revision to Tech Specs re power distribution limits & surveillance requirements & administrative control concerning radial peaking factor limit repts
* Alabama Power Co B011/03 4pp 06952 042
- B011120303 Forwards response to NRC questions re operability of 18-inch containment mini-purge valves
CLAYTON, F L Alabama Power Co B011/04 3pp 06953 001
- B011210490 Forwards addl info re plant Q-list, requested in NRC B01024 telcon Util will document repairs & mods to sys Replacement parts will meet original specs
CLAYTON, F L Alabama Power Co B011/04 2pp 07034 045
- B011260239 Forwards requests for addl info for review of alternate shutdown capability & auxiliary feedwater initiation in safety analyses. Proposed mods should be submitted prior to installation Response for Unit 1 requested in 30 days
TEDESCO, R L, Assistant Director for Licensing B011/05 17pp 07074 115
- B011140091 Forwards Amend 75 to FSAR for Unit 1 & to OL application for Unit 2
CLAYTON, F L Alabama Power Co B011/07 1p 06965 206
- B011140096 Amend 75 to application for OL for Unit 2 Certificate of Bvc encl
CLAYTON, F L Alabama Power Co B011/07 3pp 06965 207,
- B011210585 Forwards summary of Hittman Nuclear & Development Corp, "Demineralization & Filtration Svcs" Rept constitutes basis for revised process control program
GEORGE, R L Alabama Power Co B011/07 1p 07034 184
- B011210588 Summary of "Demineralization & Filtration Svcs,"
* Hittman Corp. B010/31 22pp 07034 185
- B011210394 Forwards addl info re auxiliary feedwater sys Station air compressors, atmospheric relief valve & condenser steam dump valve power supply described
CLAYTON, F L Alabama Power Co B011/12 12pp 07034 050
- B011260164 Submits core subcooling monitor upgrade info, in response to NRC B01106 request Readout of core subcooling monitor will be changed Programming & hardware will be modified
CLAYTON, F L Alabama Power Co B011/12, 2pp, 07074 079,
- B011260156 Forwards info re containment penetration overcurrent protection, in response to NRC Position 40 15 presented at B01030 meeting. Util plans to administratively control cable penetrations to protect against inadvertent energization
CLAYTON, F L Alabama Power Co, B011/17 53pp 01741 019
- B011210344 Application to amend OL involving one-time-only request for Tech Spec relief from Surveillance Requirements 4 B 1.1 2 c 7 & 4 B 1.2 re diesel generator operability Marked-up Tech Specs encl
CLAYTON, F L Alabama Power Co B011/18 2pp, 07032 280,
- B011210370 Marked-up proposed Tech Specs & safety evaluation for changes to Tech Specs 4 B.1 1 2 c 7 & 4 B.1 2 re relief from diesel generator operability requirements.
* Alabama Power Co B011/18 3pp 07032 282,
- B011260159 Forwards addl info re operability of 18-inch containment mini-purge valves, in response to NRC B01107 request. No installations are 90 degrees out of plane of piping. Duct work damage is unlikely due to elimination of debris
CLAYTON, F L Alabama Power Co, B011/21 3pp 07074 074,
- G Inspection reports, IE Bulletins & correspondence
- B011040565 Forwards IE Insp Repts 50-348/80-25 & 50-364/80-36 on B00827-29 No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch B010/22 2pp 06875 151
- B011040568 IE Insp Repts 50-348/80-25 & 50-364/80-36 on B00827-29 No noncompliance noted Major areas inspected radiological environ monitoring program mgt controls
ALLEN, J R, MACARTHUR, T C Region 2, Atlanta, Office of the Director JENKINS, O R Region 2, Atlanta, Fuel Facility & Materials Safety Branch B010/22 3pp 06875 153
- B011050273 Forwards IE Insp Repts 50-348/80-27 & 50-364/80-39 on B00801-29 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B010/29 2pp 06899 143
- B011050278 IE Insp Repts 50-348/80-27 & 50-364/80-39 on B00801-29 No noncompliance noted Major areas inspected plant operation & security
BRADFORD, W H, MULKEY, J P Region 2, Atlanta, Office of the Director MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch B010/29 8pp 06899 145
- B011050281 Forwards IE Insp Rept 50-364/80-35 on B00903-05 No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch B010/30 2pp 06899 153
- B011050286 IE Insp Rept 50-364/80-35 on B00903-05 No noncompliance noted Major areas inspected radiation protection & waste mgt
TROUP, O L Region 2, Atlanta, Office of the Director O'BRIEN, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch B010/30 3pp 06899 155
- B011050290 Forwards IE Insp Rept 50-364/80-32 on B00820-22 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B010/30 2pp 06899 160
- B011050292 IE Insp Rept 50-364/80-32 on B00820-22 No noncompliance noted Major areas inspected followup insp of outstanding items
WHITENER, H L, QUICK, D R Region 2, Atlanta, Office of the Director, B010/30 4pp 06899 162
- B01110025 Provides supplemental response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Design & repair of anchors utilizes safety factor of five
CLAYTON, F L Alabama Power Co B010/15 1p 06943 105
- B01110033 Provides supplemental response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Correct measurements & comparisons in seismic analysis verified
CLAYTON, F L Alabama Power Co B010/15 1p 06943 106,
- B011050366 Ack receipt of B01001 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-364/80-26
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch, B010/27 1p 06899 314
- B011050371 Responds to NRC B00905 ltr re violations noted in IE Insp Rept 50-364/80-26 Corrective actions reinspected support & hanger & reviewed valve checklist
CLAYTON, F L Alabama Power Co B010/01 4pp 06899 315
- B011050375 Forwards IE Insp Rept 50-364/80-26 on B00730-0801 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch B010/03 2pp 06899 319
- B011050377 Notice of violation from Insp on B00730-0801.
* Region 2, Atlanta, Office of the Director B010/29 1p 06899 321,
- B011050381 IE Insp Rept 50-364/80-26 on B00730-0801. Noncompliance noted failure to follow pipe support & piping sys insp procedures
ANG, W P Region 2, Atlanta, Office of the Director, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch B010/29, 4pp 06899 322,

DOCKETED ITEMS

8011060153 Ack receipt of 800925 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-364/80-22
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/10/28 1p 06912 153

--8011060197 Responds to NRC 800905 ltr re violations noted in IE Insp Rept 50-364/80-22 Corrective actions held training session w/startup engineers re approved method of conducting tests & recording data
CLAYTON, F L Alabama Power Co 80/09/25 3pp 06912 154

--8011060160 Forwards IE Insp Rept 50-364/80-22 on 800708-17 & notice of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/05 2pp 06912 157

--8011060163 Notice of violation from insp on 800708-17
* Region 2, Atlanta, Office of the Director 80/09/05 1p 06912-159

--8011060168 IE Insp Rept 50-364/80-22 on 800708-18 Noncompliance noted failure to follow insp procedures & to record data properly
NAUMER, A O Region 2, Atlanta, Office of the Director
KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/05 4pp 06912 160

8011200436 Ack receipt of 801014 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-348/80-20 & 50-364/80-25
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/03 1p 07020 107

--8011200442 Responds to NRC 800917 ltr re violation noted in IE Insp Repts 50-348/80-20 & 50-364/80-25 Corrective actions sufficient number of qualified personnel to man fire brigade ensured
CLAYTON, F L Alabama Power Co. 80/10/14 2pp 07020 110.

--8011200449 Forwards IE Insp Repts 50-348/80-20 & 50-364/80-25 on 800804-07 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/17 2pp 07020 112

--8011200455 Notice of violation from insp on 800804-07.
* Region 2, Atlanta, Office of the Director 80/09/04 1p 07020 114

--8011200463 IE Insp Repts 50-348/80-20 & 50-364/80-25 on 800804-07. Noncompliance noted failure to assign qualified personnel to perform fire brigade functions
MILLER, W H Region 2, Atlanta, Office of the Director.
CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/04 9pp 07020 115

8011260370 Forwards branch questions & comments & request for addl info re util 800515 revised inservice insp program Comments will form basis for 801119-21 working session at site
REID, R W Operating Reactors Branch 4 80/11/14 14pp 07075 171

R Periodic operating reports & related correspondence

8011210387 Forwards monthly operating rept for Oct 1980.
CLAYTON, F L Alabama Power Co 80/11/14 2pp 07030 189

--8011210390 Monthly operating rept for Oct 1980
HAIRBTON, W. O. Alabama Power Co 80/11/01. 3pp 07030 190

DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8011030062 Ack receipt of util 801003 ltr forwarding amend to Chapter 10 of security plan for facilities Changes per 10CFR50.54(p) can be made w/o prior NRC approval
REID, R W Operating Reactors Branch 4 80/10/15. 2pp 06855 122

8011060148 Notification of 801104 meeting w/util in Bethesda, MD to discuss util proposed concept for physical plans for alerting population in event of emergency
VERRELLI, D M. Operating Reactors Branch 4 80/10/20. 2pp. 06912 335

8011250462 Forwards summary of 801104 meeting w/util re proposed sys to provide prompt notification in event of emergency Meeting satisfies request for NRC response to util 800912 ltr
REID, R W Operating Reactors Branch 4 80/11/07. 2pp 07056:028

--8011230693 Summary of 801104 meeting w/util in Bethesda, MD re util proposal for sys providing prompt notification of public in event of emergency Plan is predicated on NOAA willingness to participate
VERRELLI, D M. Operating Reactors Branch 4 80/11/07 4pp 07056 030

O Adjudicatory correspondence

8011106000 Forwards order for mod of Licenses DPR-57 & NPF-5 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp 06946 14

--8011106006 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 06946 13

--8011106014 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 4pp 06946-287

P Operating license stage documents & correspondence

7903200701 Notification of meeting on 790314-15 w/representatives of Mark I owners group to discuss pool swell load definition techniques & methodology for condensation oscillation, chugging & lateral load definition
GRINBERG, C I Assistant Director for Engineers & Projects (Pro 790623) 79/03/02 2pp 03145 305

8011050334 Ltr to all licensees of operating plants, applicants for C's & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for C's & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

8011190237 Ltr to all BWR licensees requesting info on plans to assure long-term steam sys reliability IE Bulletin 80-17 required mode to assure adequate short-term performance Info should be submitted within 25 days.
EISENHUT, D O. Division of Licensing 80/10/01 2pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports." W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011106000 Forwards order for mod of Licenses DPR-57 & NPF-5 re environ qualification of safety-related electrical equipment. Revised Tech Specs also encl
REID, R W Operating Reactors Branch 4 80/10/24 2pp

--8011106006 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630. Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24. 6pp.

--8011106014 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 4pp

801140264 Forwards Amends 79 & 18 to Licenses DPR-57 & NPF-5, respectively, safety evaluation & notice of issuance & availability.
REID, R W. Operating Reactors Branch 4 80/10/28 2pp. 06961 238

--801140267 Amends 79 & 18 to Licenses DPR-57 & NPF-5, respectively, incorporating certain TMI-2 lessons learned Category A requirements.
REID, R W. Operating Reactors Branch 4 80/10/28 24pp. 06961 240

--801140270 Safety evaluation supporting Amends 79 & 18 to Licenses DPR-57 & NPF-5, respectively
* Office of Nuclear Reactor Regulation, Director 80/10/28 4pp 06961 264

- 801140276 Notice of issuance & availability of Amends 79 & 18 to Licenses DPR-97 & NPF-5, respectively
REID, R W Operating Reactors Branch 4 80/10/28 2pp
06961 268
- 801120583 Notifies that Class I & II license amend fees transmitted w/801003 application re security plan amend will be refunded Change does not require prior NRC approval
MILLER, W O License Fee Management Branch 80/10/30 1p
04993 261.
- 8011060500 Provides info re environ qualification of safety-related equipment in response to DG Eisenhower 801001 ltr Util is willing to participate in establishment of standardized equipment environ qualification acceptance criteria
WIDNER, W A Georgia Power Co 80/10/31 1p 06915 298
- 801120083 Confirms util commitments to interim position on containment purging & venting, pending resolution of isolation valve operability Commitment will remain in effect pending NRC long-term review
REID, R W Operating Reactors Branch 4 80/11/04 2pp 07022 095
- 8011260258 Notifies that 801015 proposed change in QA program of FSAR does not require prior NRC approval Change in procedures should not decrease effectiveness of QA program
REID, R W Operating Reactors Branch 4 80/11/07 2pp 07074 144
- 801180432 Responds to verbal requests for info re reactor protection sys motor generator set power monitoring sys Logic is of same design previously reviewed on Unit 1 Collection of data re setpoint drift underway
WIDNER, W A Georgia Power Co 80/11/11 1p 06992-135
- 8011210611 Advises that concerns re small break LOCA should be addressed to HSSB vendor Questions re scope & schedule of response to TH1 action plan, Item 11 K 30 3, should be addressed to GE manager of BKR sys licensing, RH Buchholz
WIDNER, W A Georgia Power Co 80/11/14 1p 07029-153
- Q Inspection reports, IE Bulletins & correspondence
- 8011060263 Forwards IE Insp Repts 50-321/80-39 & 50-366/80-39 on 800816-0912 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/29 2pp 06911 227
- 8011060270 IE Insp Repts 50-321/80-39 & 50-366/80-39 on 800816-0912. No noncompliance noted Major areas inspected Tech Spec compliance, maint & mgt
ROGERS, R F Region 2, Atlanta, Office of the Director DANCE, H C, Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/29 3pp 06911-229
- 8011260380 Forwards IE Insp Repts 50-321/80-37 & 50-366/80-37 on 800916-17 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/07 2pp 07072-311.
- 8011260397 IE Insp Repts 50-321/80-37 & 50-366/80-37 on 800916-17 No noncompliance noted Major areas inspected followup on items of noncompliance re Part 21 evaluation & reporting matters
BROCKNLEE, V L Region 2, Atlanta, Office of the Director.
CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/03 2pp 07072-313.
- 8011030260 Forwards IE Insp Repts 50-321/80-38 & 50-366/80-38 on 800922-26 No noncompliance noted.
KENNA, W B Region 2, Atlanta, Safeguards Branch 80/10/17. 2pp
06997 213
- 8011030267 IE Insp Repts 50-321/80-38 & 50-366/80-38 on 800922-26 No noncompliance noted Major areas inspected review of security plan, security program audit & security organization Details withheld (ref 10CFR2 750)
TELLMAN, A Region 2, Atlanta, Office of the Director.
MCQUIRE, D R Region 2, Atlanta, Safeguards Branch 80/10/17. 1p.
06997 213.
- 801170427 Describes responses to IE Bulletin 80-13 contained in 800829 ltr which was not notarized Details 800815 test conducted to assure that emergency notification sys is satisfactory.
WIDNER, W A Georgia Power Co 80/10/23 1p. 06977-329.
- 8011050801 Ack receipt of 801006 ltr informing NRC of steps taken to correct violations noted in Health Physics Appraisal Repts 50-321/80-27 & 50-366/80-27.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/24 1p 06900 150
- 8011050508 Responds to NRC 800912 ltr re violations noted in Health Physics Appraisal Repts 50-321/80-27 & 50-366/80-27
Corrective actions health physics program modified, instruments replaced & health physics supervisors increased
WIDNER, W A Georgia Power Co 80/10/06 10pp 06900 151
- 8011050512 Forwards Health Physics Appraisal Repts 50-321/80-27 & 50-366/80-27 on 800616-27, notice of violation & notice of significant findings
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/12 4pp 06900 161
- 8011050516 Notice of violation from health physics appraisal on 800616-27
* Region 2, Atlanta, Office of the Director 80/09/05 2pp
06900 165
- 8011050519 Health Physics Appraisal Repts 50-321/80-27 & 50-366/80-27 on 800616-27 Noncompliance noted failure to follow written procedures & to perform safety analysis
HOSEY, C M, DAVIS, J H Region 2, Atlanta, Office of the Director
O'BRIEN, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/05 3pp 06900 167
- 801110600 Forwards order for mod of Licenses DPR-97 & NPF-5 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
REID, R W, Operating Reactors Branch 4 80/10/24 2pp
- 801110606 Order for mod of licenses re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G, Division of Licensing 80/10/24 6pp
- 801110614 Revised Tech Spec pages per 801024 order for mod of licenses re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 4pp
- 8011050536 Ack receipt of 801007 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-35 & 50-366/80-35
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/10/29 1p 06902 094
- 8011050559 Responds to NRC 800911 ltr re violations noted in IE Insp Repts 50-321/80-35 & 50-366/80-35 Corrective actions
replacement of two scram discharge vol level switches & revision of surveillance procedures
WIDNER, W A Georgia Power Co 80/10/07 2pp 06902-095
- 8011050564 Forwards IE Insp Repts 50-321/80-35 & 50-366/80-35 on 800715-0813 & notice of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/11 2pp 06902-097
- 8011050569 Notice of violation from insp on 800715-0815
* Region 2, Atlanta, Office of the Director 80/09/11. 1p
06902 099
- 8011050574 IE Insp Repts 50-321/80-35 & 50-366/80-35 on 800715-0815 Noncompliance noted reactor plant taken to Modes 1 & 2 w/A & D scram discharge vol level switches inoperable subsequent to scrams on 800602, 14, 0711 & 26
ROGERS, R F Region 2, Atlanta, Office of the Director DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/11 4pp 06902 100
- 8011260192 Confirms understanding re IE Bulletin 80-17 Util will change frequency of surveillance on residual water in scram discharge vol scram switches to once per day as of 801028
WIDNER, W A, Georgia Power Co 80/10/30 1p 07080-106
- 801100472 Forwards response to IE Bulletin 79-018 re environ qualification of electrical equipment Presents justification for continued operation & corrective action planned W/d encl
WIDNER, W A Georgia Power Co 80/10/31 1p 06940-345
- 8011260142 Forwards final response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds " Review of containment boundary penetrations identified several design type penetrations
WIDNER, W A, Georgia Power Co 80/11/03 7pp. 07080 095
- 8011210257 Responds to IE Bulletin 80-11 re masonry wall design Nine walls shown to have stresses above allowable design during earthquake load application Design mods in progress
WIDNER, W A, Georgia Power Co 80/11/04 2pp. 07030 123

DOCKETED ITEMS

8011240050 Confirms 801103 agreement to exempt daily surveillance requirement for steam discharge val components in shutdown reactor units
WIDNER, H A Georgia Power Co 80/11/04 1p 07038.287

B Reportable occurrences, LERs & related correspondence

801120445 Forwards LER 80-143/03L-0
HARRY, M Georgia Power Co 80/11/04 1p 06953 029

--801120452 LER 80-143/03L-0 on 801015, while performing HNP-1-9279, main steam line pressure switch, 2821-N015B tripped at 315 psig
Caused by setpoint drift Switch calibr per HNP-2-5279 & functionally tested per HNP-2-3105
NIX, R T Georgia Power Co 80/11/04 2pp 06953 030

801120499 Forwards LER 80-141/03L-0
HARRY, M Georgia Power Co 80/11/04 1p 06953 026

--801120519 LER 80-141/03L-0, on 801014, during power change from 2,180 to 1,980 Mwt & performance of HNP-2-3307, HPCI steamline DP switch actuated at 198 inches water DP Caused by setpoint drift, Barton Model 222A switch recalibr & tested
NIX, R T Georgia Power Co 80/11/04 2pp 06953 027.

801140378 Forwards LER 80-144/03L-0
HARRY, M Georgia Power Co 80/11/06 1p 06968 178

--801140380 LER 80-144/03L-0 on 801011, remote shutdown reactor pressure calibr procedure change found not reviewed Caused by personnel error. Personnel instructed in requirements & existing sys
NIX, R T Georgia Power Co 80/11/06 2pp 06968:179

801180698 Forwards LER 80-142/03L-0
HARRY, M Georgia Power Co 80/11/07 1p 06991.288

--801180706 LER 80-142/03L-0 on 801014, while operating at steady state 2,108 Mwt power level, break in 3-h fire rated wall identified Caused by personnel oversight in followup of sealing new penetrations Fire watch posted
NIX, R T Georgia Power Co 80/11/07 2pp 06991 289.

8011200781 Forwards LER 80-148/03L-0
HARRY, M Georgia Power Co 80/11/13 1p 07020 015.

--8011200288 LER 80-148/03L-0 on 801101, torus water level decreased to 145 8 inches, below 146-inch Tech Spec 3 & 2.1 c limit Caused by leaking discharge check valve 2E21-POD3A Torus level restored & maint request written
BAXLEY, S X Georgia Power Co 80/11/13 2pp 07020 016

V. Operator Examinations

8011060466 Notifies that facilities are in compliance w/interim criteria for shift staffing per DO Eisenhower 800731 ltr Info completes actions re NUREG-0660, Item I A 1 3
WIDNER, H A Georgia Power Co 80/10/31 1p 06915 301

DOCKET 80-367 BAILLY GENERATING STATION

A Application/construction stage documents & correspondence

8002260174 Requests tentatively arranging site visit on 800219-20 Site visit will expedite Corps of Engineers Detroit review
THOMPSON, D O Geosciences Branch 80/02/11 1p. 02401-073

8003250854 Discusses 800220 & 21 site visit w/Detroit District & North Central Div Corps of Engineers to familiarize reviewers w/site, next meeting scheduled for 800310 in Urbana, IL
THOMPSON, D O Geosciences Branch 80/03/06 4pp. 02510 284.

1007240759 Submits fourth bi-monthly ltr for period 800520-0720 re interagency agreement. Pending NRC acceptance. Subtask 1 of Task 1 & Subtask 1 of Task 2 complete. Oversize chart encl
MCALLISTER, P Army, Dept of, Corps of Engineers 80/07/25. 3pp. 06024 318.

011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01. 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp.

801170340 Forwards comparison of facility site w/each recommendation of Siting Policy Task Force rept, NUREG-0625, in response to 801014 memo
DENTON, H R Office of Nuclear Reactor Regulation, Director. 80/10/27 2pp 06975 336

--801170343 "Evaluation of Bailly Site W/Recommendations 1-9 of Siting Policy Task Force "
LYNCH, M D Licensing Branch 1 BOFFER, L Siting Analysis Branch. 80/10/24 14pp 06975 341.

--801170345 Requests comparison of facility site w/criteria in NUREG-0625 & w/recommendations of Siting Policy Task Force
AHEARNE, J F Commissioners 80/10/14 2pp 06975:355.

8011040429 Responds to NRC 801001 ltr Util does not have any safety-related equipment installed at facility Const of facility halted since Sept 1977 & awaiting NRC concurrence in facility foundation piling installation methodology.
SHORB, E M Northern Indiana Public Service Co 80/10/31. 1p 06880:187

801140466 Forwards documents in response to RJ Vollen 800918 request for production. Remaining discoverable documents will be provided when identified
GOLDBERG, S C Hearing Branch 2. 80/11/07. 3pp.

--801140471 Summary of 770923 site visit re placement of pilings. Resulting evaluation & determinations will be submitted later
KNIGHTON, Q W. Environmental Projects Branch 1. 77/09/26. 1p 06965:133

--801140474 Forwards input for preparation of minutes of 771025 meeting w/N Newmark re proposed installation of jetted piles
GREGG, J Hydrology Meteorology Branch HOFFMAYER, C POLK, H. Structural Engineering Branch 77/11/15. 4pp. 06965.134

--801140476 Advises of delay until mid-Feb 1978 for util to submit proposal re revised foundation piles design criteria & justification
LYNCH, M D. Light Water Reactors Branch 4 78/01/05. 1p. 06965:138

--801140479 Notification of 780206 meeting w/util in Bethesda, MD for util to present brief summary of foundation proposal.
LYNCH, M D. Light Water Reactors Branch 4 78/02/01 1p. 06965 139

--801140482 Proposes 780414 for review completion of util 780308 Rept 'SL-3629, "Design Analysis & Installation of Driven H-Pile Foundations " Const effort on safety-related structures suspended pending review of proposal
VASSALLO, D B Assistant Director for Light Water Reactors. 78/03/20 1p 06965.140

--801140485 Ack receipt of 771207 ltr re new proposal for shorter foundation piles Confirms understanding that design criteria will be submitted in mid-Feb 1978. Safety-related foundation differing significantly from PSAR will not be accepted
BOYD, R S Division of Project Management 78/02/11. 2pp. 06965.141.

--801140489 Forwards 780308 Rept SL-3627, "Design Analysis & Installation of Driven H-Pile Foundations " Urges immediate review & concurrence to allow Apr 1978 resumption of installation W/o encl
SHORB, E M Northern Indiana Public Service Co. 78/03/08. 1p. 06965:143

--801140490 Requests review of util 780308 Rept SL-3627, "Design, Analysis & Installation of Driven H-Pile Foundations " Urges submittal of ltr rept by 780419
HOFFMAYER, C H Structural Engineering Branch. 78/03/23. 1p. 06965.144

DOCKETED ITEMS

179

--8011140474 Advises of delay until 780428 for review completion of util Rept SL-3629 re design criteria for foundation piles
KNIGHT, J F Assistant Director for Engineering 78/03/24 1p
06965 143

--8011140497 Notification of 780425 meeting to discuss status, options & recommended actions re SL-3629 rept on foundation piles
LYNCH, M D Light Water Reactors Branch 4 78/04/24 1p
06965 150

--8011140500 Forwards request for addl info needed for review completion of pile foundation & analysis rept, SL-3629 W/o encl
BIHWEIL, I Structural Engineering Branch 78/05/12 1p
06965 151

--8011140505 Discusses 780517 meeting w/util re proposed foundation piles which will be detailed in meeting summary Acceptability of proposal is highly probable
LYNCH, M D Light Water Reactors Branch 4. 78/05/28 2pp.
06965 152

--8011140508 Forwards 780602 draft questions & positions including suggestions & recommendations re review of foundations W/o encl
HELLER, L W Geosciences Branch. 78/06/09. 1p. 06965 154

--8011140512 Submits status of indicator piles as of 780808. Soft spot found through auxiliary bldg does not constitute major problem
LYNCH, M D. Light Water Reactors Branch 4 78/08/09. 1p
06965 155.

--8011140517 Updates 790827 rept re status of post-CP review Davison should be retained to provide continuity in review effort
LYNCH, M D Light Water Reactors Branch 4. 79/10/05 1p
06965 158.

--8011140526 Notifies that US Army Corps of Engineers will review util 790827 rept "Supplementary Info, Hydrogeologic Evaluation of Const Dewatering " Review will be completed in Spring 1980
Handwritten summary of 791012 meeting & draft util ltr encl
JACKSON, R E. Geosciences Branch. 79/11/02. 7pp 06965 159

--8011140530 Responds to 790913 ltr re engineering assistance to NRC. Requests addl discussions re manpower problems
HEIDERO, E R. Army, Dept of, Corps of Engineers 79/11/02 2pp
06965 166

--8011140549 Notification of 800310 meeting w/consultants in Urbana, IL to discuss Corps of Engineers findings re applicant pile proposal acceptability, to identify unresolved issues & to formulate staff response for pile driving continuance.
THOMPSON, O O. Geosciences Branch 80/02/28. 1p

--8011140574 Submits first bimonthly status rept of items required by Interagency Agreement NRC-03-79-167 Identifies efforts completed during 790921-800120 & plans for next reporting period.
MCALLISTER, P. Army, Dept of, Corps of Engineers. NRC-03-79-167 80/02/28. 2pp 06965 192

8011210566 Forwards "Assessment of Influence of Dewatering at Bailly N-1," in response to Secretary of Interior 801003 ltr to Chairman Ahearne re possible impacts of const dewatering
SHORB, E M Northern Indiana Public Service Co. 80/11/20 2pp
07034.086

--8011210571 "Assessment of Influence of Dewatering at Bailly N-1,"
* D'Appolonia Consulting Engineers, Inc MW79-720. 80/11/20 89pp. 07034.088.

F. Security, medical, emergency & fire protection plans

801180336 Forwards facility emergency planning info for placement in LPDR, W/o encl.
SOUDER, J L. Division of Rules and Records 80/11/04. 1p
06991 163.

G. Adjudicatory correspondence

801180017 Discusses intervenor 800924 ltr to Chairman JF Ahearne re CP extension proceeding. Views will be given consideration in determination of whether EIB or supplemental statement is required
BENTON, H R Office of Nuclear Reactor Regulation, Director 80/10/24. 3pp. 06986 097

--801180024 Advises that granting CP extension constitutes major federal action affecting human environ & requiring revised or supplemental CEQ regulations & new info on nuclear power
PETERSON, R W National Audubon Society, Central Midwest Regional Office SHELTON, K P Sierra Club COCHRAN, T B Natural Resources Defense Council 80/09/24 17pp 06986 100

--801180030 Notifies of receipt of Natl Audubon Soc ltr re NEPA requirements re CP extension Ltr will be treated as ex parte communication
COCHRAN, T B Correspondence & Records Branch 80/10/01 1p
06986 117

8011030409 Response to Porter County Chapter 801014 request for order to compel production of documents Request moot since all requested documents furnished & all discovery requests satisfied. Certificate of Svc encl
EICHHORN, W H Northern Indiana Public Service Co EICHHORN, W H Eichhorn, Eichhorn & Link 80/10/29 5pp 06898 176

8011030730 Advises that EIA will be issued by 810115 Determination whether facility warrants early consideration per 800613 interim policy will be part of Director's decision under 10CFR2 206 re State of IL & City of Gary, IN requests
GOLDBERG, B C Hearing Branch 2 80/10/30. 2pp 06860 122

8011030446 Advises that safety evaluation on util pile installation proposal will not be issued by 801015 Technical merits of proposal not proper issue in proceeding per NRC 800818 response to ASLB questions
GOLDBERG, B C Hearing Branch 2 80/11/03 1p. 06898 217

8011060463 Ack receipt of 801022, 27 & 28 ltrs re delegated authority of LS Rubenstein to issue notice of opportunity for hearing Requests clarification of issues to be addressed
VOLLEN, R J Businessmen for the Public Interest 80/11/03 3pp
06911 340.

8011100199 Advises that util anticipated inservice date is now 1989. Revision will be reflected in amend to 790207 request for CP extension.
EICHHORN, W H Eichhorn, Eichhorn & Link 80/11/03 2pp 06929 041.

8011060446 Responds to 801028 order inviting City of Gary to comment on NRC position re delegated authority of LS Rubenstein to issue notice of opportunity for hearing No position taken pending further clarification of issues to be addressed
COHN, D B. Cohn, D B 80/11/04 1p 06911 326

8011140085 Corrects util 801103 ltr re CP extension proceeding Anticipated inservice date for facility is now 1989
EICHHORN, W H Eichhorn, Eichhorn & Link 80/11/04 2pp 06963 176.

8011140021 Concurs w/NRC conclusions re Rubenstein authority to issue notice of hearing opportunity on CP extension request, per ASLB 801028 memorandum & order.
EICHHORN, W H Eichhorn, Eichhorn & Link 80/11/05 2pp 06961 320.

8011070163 Response in opposition to Porter County Chapter 801017 motion to compel deposition of MD Lynch. Insistence that deposition be conducted in Chicago, IL rather than Bethesda, MD unreasonable & inconvenient.
GOLDBERG, B C Hearing Branch 2 80/11/06 5pp 06920 286

--8011070169 Affidavit stating that required deposition in Chicago, IL could significantly limit ability to meet responsibilities to agency & Family Certificate of Svc encl
LYNCH, M D Division of Licensing. 80/11/04 7pp. 06920 291

8011170312 Submits brief comments per 801105 telcon re LS Rubenstein authority to issue notice of opportunity for hearing City of Gary, IN et al does not take position re effect on validity of proceeding Finding of good cause for extension necessary.
COHN, D B. Cohn, D B 80/11/06 2pp 07183.001

8011170358 Comments on LS Rubenstein authority to issue notice of opportunity for hearing re CP extension NRC 801027 response fails to demonstrate presence of such authority Intervenor unable to take firm position. Certification of svc encl
VOLLEN, R J Isaac Walton League of America, Porter County Chapter. VOLLEN, R J Vollen, R J 80/11/06. 4pp 06975 153

8011170381 Third motion to compel production of documents directed to util Contains response opposing util 801023 motion for protective order. Request need not be as narrowly drawn as contention. W/Certificate of Svc Related correspondence
VOLLEN, R J Isaac Walton League of America, Porter County Chapter. VOLLEN, R J Vollen, R J 80/11/06. 7pp 06975 179

DOCKETED ITEMS

- 801140062 Motion for protective order re Porter County 801024 notice of EN O'Rourke deposition Urges issuance of subpoena conditioned on deponent place of business & reimbursement of expenses Requests deferral until rulings on contentions EDGAR, G L, GALLEN, K P General Electric Co EDGAR, G L Morgan, Lewis & Bockius 80/11/07 6pp 06963 153
- 801140065 Response in opposition to Porter County 801024 motion to compel production of contracts w/uttl Release of confidential business info may cause irreparable harm Urges issuance of protective order Certificate of Bvc encl EDGAR, G L, GALLEN, K P General Electric Co EDGAR, G L Morgan, Lewis & Bockius 80/11/07 10pp 06963 159
- 801140466 Forwards documents in response to RJ Vollen 800918 request for production Remaining discoverable documents will be provided when identified GOLDBERG, B C Hearing Branch 2 80/11/07 3pp 06965 130
- 801140471 Summary of 770923 site visit re placement of pilings Resulting evaluation & determinations will be submitted later KNIGHTON, O W Environmental Projects Branch 1 77/09/26 1p 06965 133
- 801140474 Forwards input for preparation of minutes of 771025 meeting w/N Newmark re proposed installation of jetted piles GREEVES, J Hydrology Meteorology Branch HOFMAYER, C, POLK, H Structural Engineering Branch 77/11/15 4pp 06965 134
- 801140476 Advises of delay until mid-Feb 1978 for uttl to submit proposal re revised foundation piles design criteria & justification LYNCH, M D Light Water Reactors Branch 4 78/01/05 1p 06965 138
- 801140479 Notification of 780206 meeting w/uttl in Bethesda, MD for uttl to present brief summary of foundation proposal LYNCH, M D Light Water Reactors Branch 4 78/02/01 1p 06965 139
- 801140482 Proposes 780414 for review completion of uttl 780308 Rept SL-3629, "Design Analysis & Installation of Driven H-Pile Foundations " Const effort on safety-related structures suspended pending review of proposal VABBALLO, D B, Assistant Director for Light Water Reactors 78/03/20 1p 06965 140
- 801140485 Ack receipt of 771207 ltr re new proposal for shorter foundation piles Confirms understanding that design criteria will be submitted in mid-Feb 1978 Safety-related foundation differing significantly from PSAR will not be accepted BOYD, R S Division of Project Management 78/02/11 2pp 06965 141
- 801140489 Forwards 780308 Rept SL-3627, "Design Analysis & Installation of Driven H-Pile Foundations " Urges immediate review & concurrence to allow Apr 1978 resumption of installation. W/o encl SHORR, E M Northern Indiana Public Service Co 78/03/08 1p 06965 143
- 801140490 Requests review of uttl 780308 Rept SL-3627, "Design, Analysis & Installation of Driven H-Pile Foundations " Urges submittal of ltr rept by 780419. HOFMAYER, C H Structural Engineering Branch 78/03/23 1p 06965 144
- 801140494 Advises of delay until 780428 for review completion of uttl Rept SL-3629 re design criteria for foundation piles KNIGHT, J P Assistant Director for Engineering 78/03/24 1p 06965 145
- 801140497 Notification of 780425 meeting to discuss status, options & recommended actions re SL-3629 rept on foundation piles LYNCH, D Light Water Reactors Branch 4 78/04/24 1p 06965 150
- 801140500 Forwards request for addl info needed for review completion of pile foundation & analysis rept; SL-3629 W/o encl SIMHEIL, I Structural Engineering Branch 78/03/12 1p 06965 151
- 801140505 Discusses 780517 meeting w/uttl re proposed foundation piles which will be detailed in meeting summary Acceptability of proposal is highly probable LYNCH, M D Light Water Reactors Branch 4 78/05/28 2pp 06965 152
- 801140508 Forwards 780602 draft questions & positions including suggestions & recommendations re review of foundations W/o encl. HELLER, L W Geosciences Branch 78/06/09 1p 06965 154
- 801140512 Submits status of indicator piles as of 780808 Soft spot found through auxiliary bldg does not constitute major problem LYNCH, M D Light Water Reactors Branch 4 78/08/09 1p 06965 155
- 801140517 Updates 790827 rept re status of post-CP review Davison should be retained to provide continuity in review effort LYNCH, M D Light Water Reactors Branch 4 79/10/05 1p 06965 158
- 801140526 Notifies that US Army Corps of Engineers will review uttl 790827 rept "Supplementary Info. Hydrogeologic Evaluation of Const Dewatering " Review will be completed in Spring 1980 Handwritten summary of 791012 meeting & draft uttl ltr encl JACKSON, R E Geosciences Branch 79/11/02 7pp 06965 159
- 801140530 Responds to 790913 ltr re engineering assistance to NRC. Requests addl discussions re manpower problems HENDERSON, E R Army, Dept of, Corps of Engineers 79/11/02 2pp 06965 166
- 801140538 Discusses followup actions to 791113 meeting. Consultants will be guided to use decision point meetings that culminate in declaration of final NRC position DOD 800211 internal memo & summary of 791113 meeting encl KNIGHT, J P Assistant Director for Engineering 79/11/14 13pp 06965 168
- 801140546 Submits status of geotechnical review by Corps of Engineers. One reviewer made cursory examination of info & visited both plants Three-man review team needed to accomplish review DOD 800201 internal memo encl HELLER, L W Geosciences Branch NRC-03-B9-167 80/01/23 7pp 06965 181
- 801140569 Notification of 800310 meeting w/consultants in Urbana, IL to discuss Corps of Engineers findings re applicant pile proposal acceptability, to identify unresolved issues & to formulate staff response for pile driving continuance. THOMPSON, O O Geosciences Branch 80/02/28 1p
- 801140574 Submits first bimonthly status rept of items required by Interagency Agreement NRC-03-79-167 Identifies efforts completed during 790921-800120 & plans for next reporting period. MCCALLISTER, P Army, Dept. of, Corps of Engineers NRC-03-79-167, 80/02/28 2pp 06965 192
- 801170214 Motion to file instant reply to uttl response re intervenors' motion to compel production of documents. Utll response misstates intervenors' position WHICHER, J M Isaac Walton League of America, Porter County Chapter WHICHER, J M, VOLLEN, R J Vollen, R J 80/11/07 1p 06981 350
- 801170272 Reply in opposition to uttl 801029 response re intervenors' motion to compel production of documents Utll misstates intervenors' position re propriety of documents tending to prove or disprove assertion. Certificate of Bvc encl WHICHER, J M Isaac Walton League of America, Porter County Chapter WHICHER, J M, VOLLEN, R J Vollen, R J 80/11/07 5pp 06981 351
- 801140498 Response to Porter County Chapter 801024 motion for order compelling production of GE contracts Production will be governed by ASLB ruling on GE 801014 motion for protective order. Certificate of Bvc encl SHEA, K H Northern Indiana Public Service Co SHEA, K H Lowenstein, Neuman, Reis, Axelrad & Toll + Eichhorn, Eichhorn & Link. 80/11/10 4pp 06963 070
- 8011240170 Motion to suspend litigation proceedings, including discovery matters, pending further order of Board Certificate of Bvc encl VOLLEN, R J, WHICHER, J M Porter County Chapter Intervenor. 80/11/13 12pp 07049 257
- 8011280005 Response in opposition to NRC 801106 request for protective order re MD Lynch deposition. Deposition should not be taken during illness of Lynch family member When taken, deposition should be in Chicago, IL Affidavit & Certificate of Bvc encl VOLLEN, R J, Isaac Walton League of America, Porter County Chapter VOLLEN, R J Vollen, R J 80/11/19 6pp 07083 358

DOCKETED ITEMS

181

8011250184 Forwards comments re requests for action under 10CFR2 206
Denial urged Certificate of Svc encl
BHEA, K M Lowenstein, Newman, Reis, Axelrad & Toll 80/11/20 17pp
07055 223

8011250643 Order re discovery stemming from Porter County Chapter
motions to compel NIPSCO to produce three main categories of
documents Sustains until objections re characterization of
documents as tending to prove or disprove any assertion
GROSSMAN, H. Atomic Safety and Licensing Board Panel 80/11/20.
7pp 07069 200

8011280001 Decision affirming ASLB 800807 denial of City of Gary et al
& Q Schulte intervention petitions CP extension proceeding
is not convened for purpose of conducting open-ended inquiry
into safety & environ aspects of reactor const & operation
BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/11/20
27pp 07083 322

8011280033 Forwards comments on requests for action under 10CFR2 206,
supplementing 800409 submittal Section 2 206 proceeding is
not vehicle for reconsideration of issues previously
decided in licensing proceedings Certificate of Svc encl
BHEA, K M Lowenstein, Newman, Reis, Axelrad & Toll 80/11/20. 17pp
07084 062

8011280014 Requests opportunity for City of Gary et al to respond to
util submittal & to file supplemental comments Action taken
since action per 10CFR2 206 may be only vehicle whereby
evacuation issue is considered Related correspondence
COHN, D B Cohn, D B 80/11/21 1p 07084 022

8011280030 Response in opposition to Porter County Chapter 801106 third
request for order compelling util to produce documents
requested in Paragraphs 9, 10 & 11 of second request for
production. Info irrelevant. Certificate of Svc encl
EICHHORN, W H. Northern Indiana Public Service Co EICHHORN, W H
Eichhorn, Eichhorn & Link 80/11/21 9pp 07084 053.

G Inspection reports, IE Bulletins & correspondence

8011070307 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " No written response
required.
KREPLER, J O Region 3, Chicago, Office of the Director 80/10/24
1p 06921.344

R Periodic operating reports & related correspondence

8011030400 Forwards well charts for 801008-15, Bailey wells w/o
recorders, pond levels, pneumatic pressure transducers, water
meter readings & USGS wells for 801015 & Lake MI levels for
800815, 0901, 15 & 1001
BOHN, R J. Northern Indiana Public Service Co 80/10/24 35pp
06867.308.

8011040493 Forwards well charts for 801015-22, Bailey wells w/o
recorders, pond levels, pneumatic pressure transducers, water
meter readings & USGS wells for 801022
BOHN, R J. Northern Indiana Public Service Co 80/10/28 34pp
06877.167.

801120544 Forwards well charts for 801022-29 & Bailey wells w/o
recorders, pond levels, pneumatic pressure transducers, water
meter readings & USGS wells for 801029
BOHN, R J. Northern Indiana Public Service Co 80/11/04 32pp.
06930 356.

8011180140 Forwards well charts for 801029-1105, Bailey wells w/o
recorders, pond levels, pneumatic pressure transducers, water
meter readings & USGS wells for 801105
BOHN, R J. Northern Indiana Public Service Co 80/11/11 32pp.
06985 280

8011250142 Forwards well charts for 801105-12, Bailey wells w/o
recorders, pond levels, pneumatic pressure transducers,
water meter readings & USGS wells for 801112 & rainfall data
for 800701-1031
BOHN, R J. Northern Indiana Public Service Co 80/11/21. 33
02227:001

U. Congressional/Executive Correspondence

801100574 Responds to 800521 memo re Atty General of IL 800512 ltr
expressing opposition to Facility. Position of IL Atty
General is well known to NRC through participation in
adjudicatory proceedings Draft ltr to EE Eisenstadt encl.
DIRCKS, W J Office of the Executive Director for Operations.
80/10/27. 12pp. 06916:001

--801100578 Forwards Senator Stevenson 800521 ltr requesting response to
encl Atty General of IL 800512 ltr opposing const of
Facility
SEAL, M H President of US & Executive Offices 80/06/05 6pp
05916 001

DOCKET 50-369 ARKANSAS NUCLEAR ONE, UNIT 2

F Security, medical, emergency & fire protection plans

8011200055 Advises that NRC has completed review of facility fire
protection program Status of unacceptable items, safety
evaluation & mod requirements encl
CLARK, R A Operating Reactors Branch 3 80/11/05 3pp 07018 155

--8011200057 Safety evaluation of acceptable fire protection items
* Operating Reactors Branch 3 80/11/05 5pp 07018 158

G Adjudicatory correspondence

801110327 Forwards order for mod of License NPF-6 re environ
qualification of safety-related electrical equipment Revised
Tech Specs also encl
CLARK, R A. Operating Reactors Branch 3 80/10/24 2pp 06944 191

--801110337 Order for mod of license re environ qualification of safety-
related electrical equipment Compliance w/Div of Operating
Reactors guidelines or NUREG-0388 required by 802630
Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06944.193

--801110347 Revised Tech Spec pages per 801024 order for mod of license
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 3pp 06944 199

I. Financial information

8011040426 Forwards annual financial statements & cash flow projections
to meet current guarantee requirements under Price-Anderson
Act
LANGSTON, H E Arkansas Power & Light Co 80/10/31 9pp
06874 139

P Operating license stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TMI action
plan requirements Provides summary listing of all approved
TMI-2 related requirements
EISENHUT, D G Division of Licensing. 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs Info needed by 801101
EISENHUT, D G. Division of Licensing 80/10/01 5pp.

801100937 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12. "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

8011030077 Forwards Amend 16 to License NPF-6, safety evaluation &
notice of issuance & availability
CLARK, R A. Operating Reactors Branch 3 80/10/09 2pp. 06855.126

--8011030077 Amend 16 to License NPF-6, changing Tech Specs to allow
reduced svc water flow through containment cooling units
CLARK, R A Operating Reactors Branch 3 80/10/09 3pp
06855 128

--8011030103 Safety evaluation supporting Amend 16 to License NPF-6.
* Operating Reactors Branch 3 80/10/09 5pp 06855.136.

--8011030107 Notice of Issuance & availability of Amend 16 to License
NPF-6
CLARK, R A Operating Reactors Branch 3 80/10/09 2pp.
06855.141

8011060169 Notification of 801022 meeting w/util in Bethesda, MD to
discuss fouling of svc water sys by Asian clams, silt &
corrosion products & observed 40-inch difference in water
levels in downcomers of steam generators A & B
MARTIN, R E Operating Reactors Branch 3 80/10/17 3pp.
02319 196.

DOCKETED ITEMS

- 8011040328 Informs of approval of responses to concerns stated in NRC 790721 ltr re inadvertent safety injection actuations during surveillance testing
REID, R W Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 80/10/21 2pp 06915 282
- 801110327 Forwards order for mod of License NPF-6 re environ qualification of safety-related electrical equipment Revised Tech Specs also encl
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06944 191
- 801110337 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06944 193
- 801110347 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 3pp 06944 199
- 8011040413 Forwards corrected summary of radioactive effluents released in 1978, in response to NRC 801008 ltr
TRIMBLE, D C Arkansas Power & Light Co 80/10/28 1p 01741 019
- 8011040418 Forwards draft summary of radioactive effluents released from facility in 1978 Comments & changes requested by 801023 response encl
HARTFIELD, R A Licensee Operators Evaluation Branch 80/10/08 69pp 01741 019
- 8011040543 Notifies AR Dept of Public Safety of 801030 meeting at plant to initiate review process re memorandum of understanding for notification of releases of radioactive matl. due to expire on 801101 Identical ltr to AR Dept of Health encl
O'HANLON, J P Arkansas Power & Light Co 80/10/29 2pp 06973 069
- 801100326 Forwards comments re inservice testing program, in response to 800321 ltr
TRIMBLE, D C Arkansas Power & Light Co 80/10/29 9pp 06928 222
- 8011070411 Application to amend Licenses DPR-51 & NPF-6, changing Tech Specs re waste gas sys hydrogen/oxygen concentration limits Class III & I fees encl
CAVANAUGH, W Arkansas Power & Light Co 80/10/31 3pp 06919 349.
- 8011070419 Proposed Tech Specs 2 4 3 & 2 2 3 re waste gas sys hydrogen/oxygen concentrations & monitoring requirements
* Arkansas Power & Light Co 80/10/31 4pp 06919 352
- 801100337 Application to amend Licenses DPR-51 & NPF-6, submitted as proposed Tech Spec re decay heat removal capability, per NRC 800611 ltr
CAVANAUGH, W Arkansas Power & Light Co 80/10/31 2pp 06928 073
- 801103382 Proposed Tech Spec 3 1 re reactor coolant sys
* Arkansas Power & Light Co 80/10/31 13pp 06928 075
- 8011130197 Application to amend Licenses DPR-51 & NPF-6, changing Tech Specs re mods resulting from implementation of TMI-2 Lessons Learned Category A items Class I & IV fees encl
CAVANAUGH, W Arkansas Power & Light Co 80/10/31 2pp 06939 223
- 8011130205 Proposed Tech Specs re TMI-2 Lessons Learned Category A items, including emergency power supply, Valve position indication, instrumentation for inadequate core cooling, containment isolation & auxiliary feedwater sys
* Arkansas Power & Light Co 80/10/31 16pp 06939 225
- 801100313 Resubmits NRC approved OA Topical Rept, APL-TOP-1A, Revision 5
TRIMBLE, D C Arkansas Power & Light Co 80/11/06 1p 06999 001
- 8011180243 Revision 5 to approved OA manual - operations
* Arkansas Power & Light Co APL-TOP 1A R5 80/10/10 75pp 06999 003
- 8011140278 Documents commitments & responses made as result of 801022 meeting between util & NRC re s/c water, steam generator level & bolting concerns
TRIMBLE, D C Arkansas Power & Light Co 80/11/06 3pp 06960 355.
- 8011240376 Proposes addl info exchange between NRC & owners, for clarification of TMI action plan requirements info provided in NUREG may not be adequate for sufficient response.
TRIMBLE, D C Arkansas Power & Light Co 80/11/14 1p 07049 058.
- 8011260173 Forwards Amends 47 & 17 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability
CLARK, R A Operating Reactors Branch 3 REID, R W Operating Reactors Branch 4 80/11/14 3pp 07074 292
- 8011260174 Amends 47 & 17 to Licenses DPR-51 & NPF-6 respectively, modifying Tech Specs Apps A & B dealing w/util mgt organizational structure
REID, R W Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 80/11/14 34pp 07074 295
- 8011260176 Safety evaluation supporting Amends 47 & 17 to Licenses DPR-51 & NPF-6, respectively
* Office of Nuclear Reactor Regulation, Director 80/11/14 2pp 07074 328
- 8011260178 Notice of issuance & availability of Amends 47 & 17 to Licenses DPR-51 & NPF-6, respectively
CLARK, R A Operating Reactors Branch 3 80/11/14 2pp 07074 330
- Q Inspection reports, IE Bulletins & correspondence

- 8011060670 Forwards IE Insp Repts 50-313/80-16 & 50-368/80-16 on 800902-05 & notice of violation
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/09/26 2pp 06914 305
- 8011060676 Notice of violation from insp on 800902-05.
* Region 4, Dallas, Office of the Director 80/09/19 1p 06914 307
- 8011060682 IE Insp Repts 50-313/80-16 & 50-368/80-16 on 800902-05 Noncompliance noted plant safety committee had not reviewed audit repts or associated audit finding repts for six of seven QA audits that were reviewed by inspector
GAOLIARO, J E, JAUDON, J P, HUNNICUTT, D M Region 4, Dallas, Office of the Director 80/09/19 8pp 06914 308
- 8011140123 Forwards IE Circular 80-22 "Confirmation of Employee Qualifications" No written response required.
BEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/02 1p 06963 203
- 8011060774 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting" No written response required.
BEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/10 1p 06909 086
- 801110728 Ack receipt of 801010 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-16 & 50-368/80-16
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/10/23 2pp 06944 052.
- 801110236 Responds to NRC 800926 ltr re violations noted in IE Insp Repts 50-313/80-16 & 50-368/80-16 Corrective actions: OA procedures to be revised to clarify use of AFR.
TRIMBLE, D C Arkansas Power & Light Co 80/10/10 3pp 06944 054.
- 801110327 Forwards order for mod of License NPF-6 re environ qualification of safety-related electrical equipment, Revised Tech Specs also encl.
CLARK, R A Operating Reactors Branch 3 80/10/24 2pp 06944 191.
- 801110337 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 06944 193.
- 801110347 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment.
* Division of Licensing 80/10/24 3pp 06944 199
- 8011280978 Responds to items of noncompliance noted in IE Insp Repts 50-313/80-12 & 50-368/80-12 on 790708-0809 & forwards full payment of civil penalties, Corrective actions notification method & evaluation log being used for both units.
CAVANAUGH, W Arkansas Power & Light Co 80/11/12 14pp 07083 246
- 8011260272 Ack receipt of 800925 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-15 & 50-368/80-15
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/14 1p 07074 152.

DOCKETED ITEMS

183

--8011260280 Responds to NRC 800903 ltr re violations noted in IE Insp Repts 80-313/80-15 & 80-368/80-15 Corrective actions
Radiation Protection Procedure 1602 27 revised & add'l
radiation survey instruments provided w/specific directions
TRIMBLE, D C Arkansas Power & Light Co 80/09/25 2pp
07074 193

R Periodic operating reports & related correspondence

8011140414 Forwards NPDES rept for third quarter 1980 Forwarding ltrs encl.
TRIMBLE, D C Arkansas Power & Light Co 80/11/06 5pp 06911-001

--8011140416 NPDES rept for third quarter 1980
Arkansas Power & Light Co 80/10/20 15pp 06911-001.

8011180417 Forwards monthly operating rept for Oct 1980
TRIMBLE, D. C. Arkansas Power & Light Co 80/11/14 1p 06989 189

--8011180420 Monthly operating rept for Oct 1980
PENDERGRAFT, R Arkansas Power & Light Co 80/11/14 5pp
06989:190.

S Reportable occurrences, LERs & related correspondence

8011100447 Forwards LER 80-073/03L-0
TRIMBLE, D. C. Arkansas Power & Light Co 80/10/31 1p 06929:307

--8011100449 LER 80-073/03L-0 on 801002, fire monitoring instrumentation, transformer 2X11, shorted out Caused by tie wire which was being discarded Winding lug replaced
PENDERGRAFT, R Arkansas Power & Light Co 80/10/31 2pp
06929:308.

8011100440 Forwards LER 80-074/03L-0
TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/03 1p 06929 305.

--8011100441 LER 80-074/03L-0 on 801004, steam generator level indicator 2LI-1031-2 failed acceptance criteria per surveillance test
Caused by indicating needle occasionally sticking Needle adjusted & calibr performed
PENDERGRAFT, R. Arkansas Power & Light Co. 80/11/03 1p
06929:306

8011100780 Forwards LER 80-070/03L-0.
TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/04 1p. 06944.078.

--801110289 LER 80-070/03L-0 on 801005, control room emergency chiller, 2VE-12, was found to be inoperable. Caused by improper pressure switch setting (80 psig rather than 150 psig). Pressure switch calibr
PENDERGRAFT, R Arkansas Power & Light Co. 80/11/04 1p.
06944:079.

801110795 Forwards LER 80-071/03L-0
TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/04 1p. 06944:166

--801110300 LER 80-071/03L-0 on 801006, wind speed indicator (WDR-9300) was found to be inoperable per Tech Spec 3.3 3 4. Caused by faulty amplifier on recorder. Amplifier replaced & WDR-9300 recalibr
PENDERGRAFT, R Arkansas Power & Light Co. 80/11/04 1p
06944:167.

8011140028 Forwards LER 80-075/03L-0
TRIMBLE, D. C. Arkansas Power & Light Co 80/11/05 1p. 06961:339

--8011140033 LER 80-075/03L-0 on 801007, A safety injection tank pressure found to be less than 600 psia per Tech Spec 3.5 1.d Caused by vol loss due to sampling w/o capability of remote repressurization due to inoperable control valve.
PENDERGRAFT, R. Arkansas Power & Light Co 80/11/05 1p.
06961:334.

8011140032 Forwards LER 80-077/03L-0,
TRIMBLE, D. C. Arkansas Power & Light Co 80/11/05 1p. 06961:335.

--8011140036 LER 80-077/03L-0 on 801007, auxiliary cooling sys 8001 (seismic accelerometer) discovered inoperable. Caused by water damage to connectors (short in sys). Instrument repaired & sealed
BRAHLETT, L. S. Arkansas Power & Light Co. 80/11/05 1p
06961:336.

801110277 Forwards revised LER 80-005/03X-1.
TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/07 1p. 06944:076.

--801110287 Revised LER 80-005/03X-1 on 800123, reactor coolant leakage calculation indicated approx 3.6 gpm unidentified leakage, exceeding Tech Spec 3.4 6 2 b Caused by leaking packing on pressurizer spray valves 2CV-4651 & 2CV-4652
SHIVELY, C N Arkansas Power & Light Co 80/11/07 1p
06944 077

8011140583 Forwards revised LER 80-072/01X-1
TRIMBLE, D C Arkansas Power & Light Co 80/11/07 1p 06968 184

--8011140384 Revised LER 80-072/01X-1 on 800903, surveillance indicated inadequate svc water flow rate Caused by buildup of Asian clams Cooling units backflushed & cleaned & acceptable flow rates verified
COGBURN, T Arkansas Power & Light Co 80/11/07 6pp 06968:185

8011140385 Forwards updated LER 80-050/03X-3
TRIMBLE, D C Arkansas Power & Light Co 80/11/07 1p 06968:191

--8011140386 Updated LER 80-050/03X-3 on 800717, 0804:29 & 1014, steam driven emergency feedwater pump 2P7A turbine driver 2K3 tripped on overspeed Caused by design-related problem Pump removed from svc for design mods
SHIVELY, C N Arkansas Power & Light Co 80/11/07 2pp
06968 192

8011170466 Forwards updated LER 80-058/03X-2
TRIMBLE, D C Arkansas Power & Light Co 80/11/07 1p 06975:034.

--8011170476 Updated LER 80-058/03X-2 on 800724, CEAC-2 found inoperable on three dates Cause not found. In all cases, CEAC-2 returned to operable status by reinitializing sys. Vendor evaluation in progress
PENDERGRAFT, R Arkansas Power & Light Co 80/11/07 1p
06975 035

8011180507 Forwards revised LER 80-024/03X-1
TRIMBLE, D. C. Arkansas Power & Light Co 80/11/10 1p 06987 347.

--8011180509 Revised LER 80-024/03X-1 on 800408, during Mode 3 operation, while testing PPB/A spray pump auto started & A containment spray header isolation valve opened causing boric acid solution to be sprayed in RX bldg Caused by low voltage
PENDERGRAFT, R Arkansas Power & Light Co 80/11/10 4pp
06987 348

8011170480 Forwards LER 80-078/03L-0
TRIMBLE, D. C. Arkansas Power & Light Co 80/11/11 1p 06975:056

--8011170487 LER 80-078/03L-0 on 801014, HPB1 pump B (2P878) tripped on overcurrent Caused by motor bearing misalignment on inboard motor bearing Corrective maint continued on pump.
PENDERGRAFT, R Arkansas Power & Light Co 80/11/11 1p.
06975 057

8011210595 Forwards LER 80-079/03L-0
TRIMBLE, D C Arkansas Power & Light Co 80/11/13 1p 07029:165

--8011210605 LER 80-079/03L-0 on 801015, during Mode 1, discovery made that cover panel to C HPB1 pump room cooler, 2 VUC-11B, had not been reinstalled Caused by insufficient procedural guidelines for transfer of maint activity responsibility
SHIVELY, C. N Arkansas Power & Light Co 80/11/13 1p
07029 166

8011210453 Forwards LER 80-080/03L-0
TRIMBLE, D C Arkansas Power & Light Co 80/11/14 1p. 07029:202

--8011210454 LER 80-080/03L-0 on 801017, 20, 21 & 23, CEAC 2 failed Caused by failure of optical isolator on first three days & failure of oxygen pressure module card on last day Optical isolator & oxygen pressure card were replaced
PENDERGRAFT, R Arkansas Power & Light Co 80/11/14 1p.
07029:203

8011210584 Forwards updated LER 80-009/03X-1.
TRIMBLE, D C Arkansas Power & Light Co 80/11/17 1p 07032 218

--8011210590 Updated LER 80-009/03X-1 on 800129, during Mode 3 operation following reactor trip from 100% power, I-131 dose equivalent value of 1.67 uCi/g was observed, which exceeded Tech Specs. Caused by expected spike following trip
SHIVELY, C. N. Arkansas Power & Light Co 80/11/17 3pp
07032:217

8011280049 Forwards updated LER 79-086/03X-1.
TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/21 1p 07084 091.

DOCKETED ITEMS

--8011280052 Updated LER 79-086/03X-1 on 791013.B shutdown cooling heat exchanger radiation monitor indication found increased
Caused by small vol tube leak in heat exchanger tube Q74
Heat exchangers & tubes examined Tube plugged
SHIVELY, C N Arkansas Power & Light Co 80/11/21 4pp
07084 092

V Operator Examinations

8011050463 Submits plans, schedules & commitments for meeting interim criteria for shift staffing in response to NRC 800731 ltr
Recent NRC requirements hinder util ability to conform to mandated changes in staffing levels
TRIMBLE, D C Arkansas Power & Light Co 80/10/31 2pp. 06894 040

DOCKET 80-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp.

8010210784 Forwards info on floodplain aspects of plant site.
YOUNGBLOOD, B J Licensing Branch 1 80/09/29 4pp 03645:359

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 3pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D O Division of Licensing 80/10/06 4pp.

8011060162 Notification of 801028-29 meeting w/util & Sandia Labs in Mecklenburg County, NC to discuss reliability analysis of auxiliary feedwater sys
BIRKEL, R A Licensing Branch 1 80/10/16 3pp 06912 329.

8011210312 Notification of 801103 meeting w/util in Mecklenburg County, NC re emergency operating procedures.
BIRKEL, R. Operating Reactors Branch 1 80/10/22 3pp 07030 139

8011040533 Informs that draft special low power test procedures being reviewed against safety evaluation & will be revised per Westinghouse safety evaluation which identified certain Tech Spec exemptions required to conduct test program
PARKER, W D Duke Power Co 80/10/28 1p 06877 290.

8011090390 Forwards addl info requested 801016 re Category I masonry wall design Info suppls 800923, 16 & 0702 ltrs.
PARKER, W D Duke Power Co 80/10/28 6pp 06897 332

8011070386 Submits updated response to "Duke Power Co, McGuire Nuclear Station, Response to TMI Concerns." Review includes changes to safety engineering group & to safety evaluation of low power test program
PARKER, W D Duke Power Co 80/10/29 9pp 06919-338

8011100330 Notification of 801117 rescheduled meeting w/util in Mecklenburg County, NC for facility tour & to observe & discuss safety features & operating procedures re prospective issuance of OL
BIRKEL, R A Licensing Branch 1 80/10/30 3pp 06928 356

8011070354 Forwards Revision 2 to "McGuire Nuclear Station Evaluation of Compliance w/NRC Branch Technical Position R8B5-1 on Design Requirements of RHR Sys." supplementing 791104 & 801008 ltrs Natural circulation cooldown test described
PARKER, W D Duke Power Co 80/10/31 16pp. 06918-191

8011180542 Amend 66 to application for OL Forwards updated electrical schematics Schematics available in Central Files only. Aperture cards will be available in FDR.
PARKER, W D Duke Power Co 80/11/09 2pp 07050 122

8011190137 Requests addl info re LOCA spectrum analyses for NRC review of FSAR through Revision 40
TEDESCO, R L Assistant Director for Licensing 80/11/05 2pp. 06999, 217

8011190572 Forwards request for addl info re util 800923 ltr re Category I masonry wall design Rigorous response spectra analysis requested
TEDESCO, R L Assistant Director for Licensing 80/11/05 3pp 06996 200

8011190592 Forwards 800903 assessment of floodplain aspects of site per Executive Order 11988 re floodplain mgmt
YOUNGBLOOD, B J Licensing Branch 1 80/11/05 5pp 06996, 209

8011190580 Responds to util 801010 ltr stating position on TMI Item 11 K.3 re verification of anticipatory reactor trip on turbine trip Licensee must commit to installation of trip function prior to fuel loading & issuance of OL
TEDESCO, R L Assistant Director for Licensing 80/11/06 2pp 06996 203

8011170046 Notification of 801120 meeting w/util in Bethesda, MD to discuss proposed Tech Specs for snubbers & applicant statistical analysis technique
BIRKEL, R A Licensing Branch 1 80/11/07 3pp 06981 311

8011180418 Forwards response to NRC/Sandia questions on reliability analysis of auxiliary feedwater sys for facility
PARKER, W D Duke Power Co 80/11/10 12pp 06992 144

8011210616 Notification of cancellation of 801120 meeting w/util in Bethesda, MD re proposed Tech Specs for snubbers & applicant statistical analysis technique
BIRKEL, R A Licensing Branch 1 80/11/14 3pp 07029 264

8011210498 Forwards Vols 1 & 2 of "Analysis of Hydrogen Control Measures at McGuire Nuclear Station." Describes results of util efforts in field of hydrogen control undertaken in response to TMI-2 accident
PARKER, W D Duke Power Co 80/11/17 1p 07036 083

--8011210500 "Analysis of Hydrogen Control Measures at McGuire Nuclear Station." Vols 1 & 2
* Duke Power Co 80/11/17 400pp 07036 084

8011250261 Responds to NRC 801008 request for info re holddown assembly springs Westinghouse will substitute springs of new design on nonfuel bearing components used for more than one cycle. No safety problem exists per code requirements
PARKER, W D Duke Power Co 80/11/18 7pp 07052 312

F Security, medical, emergency & fire protection plans

8011030356 Forwards Revision 9 to modified amended security plan Plan withheld (ref 10CFR27.790)
PARKER, W D Duke Power Co 80/10/27 1p 06867, 286

8011260752 Requests addl info & commitments for review of onsite emergency plan against NUREG-0654 criteria Emergency response exercise w/state & local govt required prior to issuance of OL Comments encl
TEDESCO, R L Assistant Director for Licensing 80/11/14 8pp 07074 132

G Adjudicatory correspondence

8011030143 Order denying Carolina Environ Study Group 801006 motion to reopen record & rejecting NRC 801027 motion for extension re spent fuel transshipments
HILLER, M E Atomic Safety and Licensing Board Panel 80/10/31 2pp.

8011060395 Initial decision denying util 780309 application for amend of SNM license authorizing transshipment of spent nuclear fuel from Oconee for storage in McGuire Initial decision shall constitute final action 45 days from issuance
HARDY, C H Atomic Safety and Licensing Board Panel 80/10/31 103pp.

8011070020 Notice of reconstitution of ASLAB in license amend proceeding, consisting of AS Rosenthal, Chairman & JH Buck & RB Salzman, members
TOLKINS, B A Atomic Safety and Licensing Appeal Panel 80/11/03 1p

8011070244 Comments on Commission 800926 order requesting positions of parties on Carolina Environ Study Group revised motion to reopen record Affirms prior view that CLI-80-16 has no direct bearing on motion Certificate of Svc encl
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman. 80/11/03 4pp. 06924-231

801120082 Suppl to 800904 response to Carolina Environ Study Group
800815 revised motion to reopen OL record Supports revised
motion & urges admission of intervenor contentions Hydrogen
generation control matters are litigable per CLI-80-16
ROTHSCHILD, M U Hearing Branch 1 80/11/07 4pp 06952 156

--801120087 Response in support of applicant 800930 motion for summary
disposition & expedited consideration re application for
license authorizing fuel loading & low power testing Util is
entitled to relief re hydrogen generation, as matter of law
CURTIS, J R Regulations Division ROTHSCCHILD, M U Hearing
Branch 1 80/11/07 7pp 06952 160

--801120089 Affidavit attesting to insignificance of potential for large
amount of hydrogen generation during low power operation
EQCS conforms w/NRC requirements Prof qualifications encl
LAUBEN, N Reactor Systems Branch 80/11/07 7pp 06952 169

--801120092 Suppl to statement of matl facts re absence of issues to be
heard Hydrogen generation event during worst case may be
terminated prior to onset of core damage Notice of MU
Rothschild appearance & Certificate of Svc encl
* Duke Power Co 80/11/07 4pp 06952 178

801140056 Response in opposition to Tittin 801025 ltr re reopening of
OL issuance hearing, if viewed as petition to intervene.
Limited appearance statement may be granted Certificate of
Svc encl
MCQARRY, J M, PORTER, W L Duke Power Co, MCQARRY, J M Debevoise &
Lieberman 80/11/07 4pp 06961 358

801170472 Response in opposition to applicant 800930 motion for
summary disposition re application for license authorizing
fuel loading Moves for consolidated hearing re provisional
& full term OLs Related correspondence
RILEY, J L Carolina Environmental Study Group 80/11/07 17pp
06975:039

--801170505 Affidavit re 801007 meeting w/R Tedesco in Charlotte, NC
Discussion addressed computer models for decay heat, timing
of hydrogen generation & most relevant computer study
finding Affirmation of svc encl
RILEY, J L Carolina Environmental Study Group 80/11/07 3pp
06975:053

801140504 Exceptions to ASLB 801031 initial decision which denied
trans-shipment of spent nuclear fuel from Oconee to McQuire
for storage purposes Oites 6B ASLB errors Certificate of
Svc encl.
MCQARRY, J M Duke Power Co 80/11/10 16pp

801180153 Supplemental filing re applicant motion for summary
disposition of application for fuel loading & low power
testing Calls attention to encl 801021 FR notice Urges
expedited consideration Certificate of Svc encl
MCQARRY, J M, PORTER, W L Duke Power Co MCQARRY, J M Debevoise &
Lieberman 80/11/12 4pp 06987 213

801200241 Suggests obtaining B Spitalny assistance in preparing appeal
brief of initial decision re McQuire/Oconee spent fuel
transportation
CHRISTENBURY, E Hearings Division 80/11/18 1p

H General correspondence

801040345 Requests reopening of hearings re facility safety controls.
TITTIN, M, TITTIN, A Affiliation Unknown 80/10/25 1p.
02319:196

801240197 Ack receipt of 800929 ltr requesting hearing re low pressure
containment & danger of hydrogen explosion. Forwards
Commission matl addressing concerns NRC reviewing evacuation
plans to determine compliance w/10CFR50 W/o encl.
KETCHEN, E G Office of the Executive Legal Director. 80/11/14
2pp. 02227:001.

801240201 Ack receipt of 800927 ltr requesting hearing re low pressure
containment & danger of hydrogen explosion Forwards
Commission matl addressing concerns NRC reviewing evacuation
plans to determine compliance w/10CFR50 W/o encl.
KETCHEN, E G Office of the Executive Legal Director 80/11/14
2pp 02227:001

801260457 Supports denial of application to ship spent fuel. Const of
new storage pools cheaper & safer than shipment
DYKES, V B Affiliation Unknown 80/11/17 3pp. 01741 019

P Operating license stage documents & correspondence

801040261 Approves request for withholding, per 10CFR2 790, info
contained in AW-80-26 re low pressure turbine disc integrity
for facility Release would jeopardize competitive status.
YOUNG, L ODD, B J Licensing Branch 1 80/10/22 2pp 06873 351

Q Inspection reports, IE Bulletins & correspondence

801170685 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " No written response
required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/10/24
1p. 06976 238

801210768 Clarifies 801020 ltr disagreeing w/IE Circular 80-21 re
directly supervised refueling operations Senior operator
should have freedom to determine location needing most
attention
PARKER, W O Duke Power Co 80/11/03 1p 07029 128

801210125 Ack receipt of IE Insp Rept 50-369/80-26 on 800915-19 No
proprietary info
PARKER, W O Duke Power Co 80/11/04 1p. 07037 116

--801210129 Forwards IE Insp Rept 50-369/80-26 on 800915-19 No
noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 80/10/15 2pp 07037 117

--801210137 IE Insp Rept 50-369/80-26 on 800915-19. No noncompliance
noted Major areas inspected emergency organization, emergency
classification sys & notification procedures
ANDREWS, D L Region 2, Atlanta, Office of the Director
JENKINS, G R Region 2, Atlanta, Fuel Facility & Materials Safety
Branch. 80/10/09 17pp. 07037-119

801240423 Suppl 801016 acknowledgement ltr re receipt of util 800811
ltr informing NRC of steps taken to correct violations noted
in IE insp repts Action noted in Paragraph b of IE 801016
ltr remains outstanding
MURPHY, C E Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/12 1p. 07075 170

801280738 Ack receipt of IE Insp Rept 50-369/80-27 on 800915-19.
No proprietary info
PARKER, W O Duke Power Co 80/11/12 1p 07083 312

--801280240 Forwards IE Insp Rept 50-369/80-27 on 800915-19 No
noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety
Branch. 80/10/22 2pp 07083 313

--801280242 IE Insp Rept 50-369/80-27 on 800915-19 No noncompliance
noted Major areas inspected, radwaste mgt & radiation
protection including installation of process & effluent
monitors
TROUP, G L Region 2, Atlanta, Office of the Director GIBSON, A F
Region 2, Atlanta, Fuel Facility & Materials Safety Branch.
80/10/21 7pp. 07083 315

R Reportable occurrences, LERs & related correspondence

801050442 80-369/80-18 & 370/80-18 on 800930, Valcor solenoid valves
V70900-21-3 failed Caused by coil failure due to
incompatibility between polyimide magnet wire insulation &
polyvinyl butyral binding agent All coils to be replaced
PARKER, W O Duke Power Co 80/10/30 3pp. 06897 254.

801190494 Significant Deficiency Repts 369/80-19 & 370/80-14 re
review of piping affecting pipe rupture environ in vital
equipment areas Main steam drain lines not considered for
pipe rupture effects
PARKER, W O Duke Power Co 80/11/14 3pp 07000 029.

DOCKET 50-370 WILLIAM B. MCQUIRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

801050354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TMI action
plan requirements Provides summary listing of all approved
TMI-2 related requirements.
EISENHUT, D G Division of Licensing 80/09/05. 209pp.

8010210784 Forwards info on floodplain aspects of plant site
YOUNG, L ODD, B J Licensing Branch 1. 80/09/29 4pp 03645 359

DOCKETED ITEMS

- 801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101 EISENHUT, D O Division of Licensing 80/10/01 3pp
- 801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports" w/o encl EISENHUT, D O Division of Licensing 80/10/05 4pp
- 8011060162 Notification of 801028-29 meeting w/util & Sandia Labs in Mecklenburg County, NC to discuss reliability analysis of auxiliary feedwater sys BIRKEL, R A Licensing Branch 1 80/10/16 3pp 06912 329
- 8011210312 Notification of 801103 meeting w/util in Mecklenburg County, NC re emergency operating procedures BIRKEL, R A Operating Reactors Branch 1 80/10/22 3pp 07030 139.
- 8011040333 Inform that draft special low power test procedures being reviewed against safety evaluation & will be revised per Westinghouse safety evaluation which identified certain Tech Spec exemptions required to conduct test program PARKER, W O Duke Power Co 80/10/28 1p 06977 240
- 8011050390 Forwards addl info requested 801016 re Category I masonry wall design Info supplis 800923, 16 & 0702 ltrs PARKER, W O Duke Power Co 80/10/28 4pp 06977 332
- 8011070386 Submits updated response to "Duke Power Co. McGuire Nuclear Station, Response to TMI Concerns" Review includes changes to safety engineering group & to safety evaluation of low power test program PARKER, W O Duke Power Co 80/10/29 9pp 06919 338
- 801100030 Notification of 801117 rescheduled meeting w/util in Mecklenburg County, NC for facility tour & to observe & discuss safety features & operating procedures re prospective issuance of OL BIRKEL, R A Licensing Branch 1 80/10/30 3pp 06928 356
- 8011070354 Forwards Revision 2 to "McGuire Nuclear Station Evaluation of Compliance w/NRC Branch Technical Position R885-1 on Design Requirements of FHR Sys." supplementing 791104 & 801008 ltrs Natural circulation cooldown test described PARKER, W O Duke Power Co 80/10/31 16pp 06918 191
- 801180542 Amend 66 to Application for OL Forwards updated electrical schematics Schematics available in Central Files only Aperture cards will be available in PDR PARKER, W O Duke Power Co 80/11/05 2pp 07030 122
- 801190137 Requests addl info re LOCA spectrum analyses for NRC review of FGRM through Revision 40 TEDESCO, R L Assistant Director for Licensing 80/11/05 2pp 06999 217
- 801190372 Forwards request for addl info re util 800923 ltr re Category I masonry wall design Rigorous response spectra analysis requested TEDESCO, R L Assistant Director for Licensing 80/11/05 3pp 06996 200
- 801190592 Forwards 800903 Assessment of floodplain aspects of site per Executive Order 11989 re floodplain nst YOUNG, S L O O Licensing Branch 1 80/11/05 5pp 06996 209
- 801190580 Responds to util 801010 ltr stating position on TMI Item II K 3 re verification of anticipatory reactor trip on turbine trip Licensee must commit to installation of trip function prior to fuel loading & issuance of OL TEDESCO, R L Assistant Director for Licensing 80/11/06 2pp 06996 203
- 8011210616 Notification of cancellation of 801120 meeting w/util in Bethesda, MD re proposed Tech Specs for snubbers & applicant statistical analysis technique BIRKEL, R A Licensing Branch 1 80/11/14 3pp 07029 264
- 8011210498 Forwards Vols 1 & 2 of "Analysis of Hydrogen Control Measures at McGuire Nuclear Station" Describes results of util efforts in field of hydrogen control undertaken in response to TMI-2 accident PARKER, W O Duke Power Co 80/11/17 1p 07034-083
- 8011210300 "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," Vols 1 & 2 * Duke Power Co 80/11/17 400pp 07036 084
- 8011250261 Responds to NRC 801008 request for info re holddown assembly springs Westinghouse will substitute springs of new design on nonfuel bearing components used for more than one cycle. No safety problem exists per code requirements PARKER, W O Duke Power Co 80/11/18 7pp 07052 312
- F Security, medical, emergency & fire protection plans
- 8011030356 Forwards Revision 9 to modified amended security plan Plan withheld (ref 10CFR2 790) PARKER, W O Duke Power Co 80/10/27 1p 06867 286
- 8011260722 Requests addl info & commitments for review of onsite emergency plan against NUREG-0654 criteria. Emergency response exercise w/state & local govt required prior to issuance of OL Comments encl TEDESCO, R L Assistant Director for Licensing 80/11/14 8pp 07074 132
- G Adjudicatory correspondence
- 8011030143 Order denying Carolina Environ Study Group 801006 motion to reopen record & rejecting NRC 801027 motion for extension re spent fuel transshipments. MILLER, M E Atomic Safety and Licensing Board Panel 80/10/31 2pp
- 8011040395 Initial decision denying util 780307 application for amend of BHM license authorizing transshipment of spent nuclear fuel from Oconee for storage in McGuire. Initial decision shall constitute final action 45 days from issuance. HAND, C H Atomic Safety and Licensing Board Panel 80/10/31 103pp
- 8011070020 Notice of reconstitution of ASLAB in license amend proceeding, consisting of AS Rosenthal, Chairman & JH Buck & RS Balaban, members TCHPKINS, B A Atomic Safety and Licensing Appeal Panel 80/11/03 1p
- 8011070244 Comments on Commission 800926 order requesting positions of parties on Carolina Environ Study Group revised motion to reopen record Affirms prior view that CLI-80-16 has no direct bearing on motion Certificate of Svc encl MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 80/11/03 4pp 06924 231
- 801120082 Suppl to 800904 response to Carolina Environ Study Group 800815 revised motion to reopen OL record Supports revised motion & urges admission of intervenor contentions Hydrogen generation control matters are litigable per CLI-80-16. ROTHCHILD, M U Hearing Branch 1 80/11/07 4pp 06952 156.
- 801120087 Response in support of applicant 800930 motion for summary disposition & expedited consideration re application for license authorizing fuel loading & low power testing Util is entitled to relief re hydrogen generation, as matter of law. CURTIS, J R Regulations Division ROTHCHILD, M U Hearing Branch 1 80/11/07 9pp 06952 160
- 801120089 Affidavit attesting to insignificance of potential for large amount of hydrogen generation during low power operation ECCS conforms w/NRC requirements Prof qualifications encl LAUBEN, M Reactor Systems Branch 80/11/07 9pp 06952 169.
- 801120092 Suppl to statement of mat facts re absence of issues to be heard Hydrogen generation event during worst case may be terminated prior to onset of core damage Notice of MU ROTHCHILD appearance & Certificate of Svc encl * Duke Power Co 80/11/07 4pp 06952 178.
- 801140056 Response in opposition to Tiffin 801025 ltr re reopening of OL issuance hearing, if viewed as petition to intervene. Limited appearance statement may be granted Certificate of Svc encl MCGARRY, J M, PORTER, W L Duke Power Co MCGARRY, J M, Debevoise & Liberman 80/11/07 4pp 06961:358
- 801170472 Response in opposition to applicant 800930 motion for summary disposition re application for license authorizing fuel loading Moves for consolidated hearing re provisionery & full term OLs, Related correspondence RILEY, J L Carolina Environmental Study Group 80/11/07 17pp 06975 059
- 801170505 Affidavit re 801007 meeting w/R Tedesco in Charlotte, NC. Discussion addressed computer models for decay heat, timing of hydrogen generation & most relevant computer study finding. Affirmation of svc encl RILEY, J L Carolina Environmental Study Group 80/11/07 3pp 06975 053.

DOCKETED ITEMS

187

011140304 Exceptions to ASLB 801031 initial decision which denied trans-shipment of spent nuclear fuel from Oconee to McGuire for storage purposes Cites 6B ASLB errors Certificate of Svc encl
MCGARRY, J. H. Duke Power Co 80/11/10 16pp.

011180153 Supplemental filing re applicant motion for summary disposition of application for fuel loading & low power testing Calls attention to encl 801021 FR notice Urges expedited consideration Certificate of Svc encl
MCGARRY, J. M., PORTER, W. L. Duke Power Co MCGARRY, J. H. Debevoise & Liberman 80/11/12 4pp 06987 213

0111200241 Suggests obtaining B Spitalny assistance in preparing appeal brief of initial decision re McGuire/Oconee spent fuel transportation
CHRISTENBURY, E. Hearings Division 80/11/18 1p

General correspondence

0111040545 Requests reopening of hearings re facility safety controls
TITIN, M., TITIN, A. Affiliation Unknown 80/10/25 1p
02319.196

0111240197 Ack receipt of 800929 ltr requesting hearing re low pressure containment & danger of hydrogen explosion. Forwards Commission matl addressing concerns NRC reviewing evacuation plans to determine compliance w/10CFR50, N/o encl
KETCHEN, E. O. Office of the Executive Legal Director 80/11/14 2pp. 02227.001

0111240201 Ack receipt of 800927 ltr requesting hearing re low pressure containment & danger of hydrogen explosion Forwards Commission matl addressing concerns NRC reviewing evacuation plans to determine compliance w/10CFR50, N/o encl
KETCHEN, E. O. Office of the Executive Legal Director. 80/11/14 2pp 02227.001

0111260457 Supports denial of application to ship spent fuel Const of new storage pools cheaper & safer than shipment
DYKES, V. B. Affiliation Unknown. 80/11/17 3pp. 01741-019.

b. Inspection reports, IE Bulletins & correspondence

0111170685 Forwards Suppl 3 to IE Bulletin 79-018, "Environment Qualification of Class IE Equipment" No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24 1p 06976-238

01111210153 Ack receipt of IE Insp Rept 50-370/80-14 on 800903-05 No proprietary info.
PARKER, W. D. Duke Power Co 80/10/29. 1p. 07037.163

--0111210158 Forwards IE Insp Rept 50-370/80-14 on 800903-05 No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/09 2pp. 07037.164.

--0111210166 IE Insp Rept 50-370/80-14 on 800903-05. No noncompliance noted Major areas inspected: unresolved items, IE bulletins & licensee identified items
MCARLAND, C. R. Region 2, Atlanta, Office of the Director.
BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/07 5pp. 07037.166.

0111210768 Clarifies 801020 ltr disagreeing w/IE Circular 80-21 re directly supervised refueling operations Senior operator should have freedom to determine location needing most attention
PARKER, W. D. Duke Power Co 80/11/03 1p. 07029.128

0111260423 Suppls 801016 acknowledgement ltr re receipt of util 800811 ltr informing NRC of steps taken to correct violations noted in IE Insp repts. Action noted in Paragraph b of IE 801016 ltr remains outstanding
MURPHY, C. E. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/12 1p. 07073-170

c. Reportable occurrences, LERs & related correspondence

0111050442 80-369/80-18 & 370/80-18 on 800930. Valcor solenoid valves V70900-21-3 failed. Caused by coil failure due to incompatibility between polyimide magnet wire insulation & polyvinyl butyral binding agent. All coils to be replaced.
PARKER, W. D. Duke Power Co. 80/10/30. 3pp. 06997.234

8011190494 Significant Deficiency Repts 369/80-19 & 370/80-14 re review of piping affecting pipe rupture environ in vital equipment areas Main steam drain lines not considered for pipe rupture effects
PARKER, W. D. Duke Power Co 80/11/14 3pp 07000 029

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLA & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D. O. Division of Licensing 80/09/05 209pp

8011140568 Forwards request for addl info re application of OE emergency procedure guidelines. Revision 0
EISENHUT, D. O. Division of Licensing 80/09/24 5pp 06911 001

8011100486 Ltr to all licensees of operating plants & applicants for OLA & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101
EISENHUT, D. O. Division of Licensing 80/10/01 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D. O. Division of Licensing 80/10/06 6pp

8011030553 Forwards request for addl info re emergency procedure guidelines. Schedule must be submitted by 801027 OE 800630 guidelines acceptable for trial implementation Training program must account for possible mod
EISENHUT, D. O. Division of Licensing 80/10/21 8pp

8011140491 Provides info on design, procurement & installation of inerting sys
EISENHUT, D. O. Division of Licensing 80/10/24 2pp 06911 001

8011030448 Forwards addl info in response to A Bournia 801002 informal inquiry re LCB-1 in-plant safety relief valve test Test objectives include determination of extent of thermal mixing in suppression pool during extended blowdown test condition
DELGEOERGE, L. O. Commonwealth Edison Co 80/10/27 17pp 06872 293

8011030450 Informs of intention to rely on nuclear heat addition in performance of hot hydrostatic test Addition is judged compatible w/current NRC position provided as part of review of OE topical rept, NEDO-21778 re transient pressure
DELGEOERGE, L. O. Commonwealth Edison Co 80/10/27 2pp 06867 361

8011030348 Notifies that util response to Effluent Treatment Sys Branch Questions 321 20 through 321 22 documented in 801020 ltr Sections L 28, L 36 & L 19, respectively Formal documentation to be addressed in future FSAR amend
DELGEOERGE, L. O. Commonwealth Edison Co 80/10/27 1p 06855 036

8011030363 Forwards response to NRC second round Questions 331.34 - 331.37 & FSAR test changes, per 800910 ltr
DELGEOERGE, L. O. Commonwealth Edison Co 80/10/27. 14pp 06855 039

8011030572 Forwards responses to Chemical Engineering Branch Questions 200 1 - 200 & per 800723 request. Matls will be formally documented in next amend to FSAR
DELGEOERGE, L. O. Commonwealth Edison Co 80/10/27 7pp 06855 057

8011040380 Forwards errata, constituting Revision 1 of assessment on Executive Order 11988 re floodplain mgmt
DELGEOERGE, L. O. Commonwealth Edison Co 80/10/28 8pp. 06874-162

8011040574 Responds to NRC informal inquiry re B/RV T-quencher air clearing lead assessment Range of 3.4-10 hertz was derived & demonstrated to be conservative.
DELGEOERGE, L. O. Commonwealth Edison Co. 80/10/28 3pp 06873:132.

8011100025 Notification of 801117-21 meeting w/util in Chicago, IL & at site to conduct onsite review of qualification program for seismic qualification review team
BOURNIA, A. Licensing Branch 3 80/10/28 3pp 06928:345

8011100571 Forwards human factors engineering control review conducted during wk of 800915. Meeting to discuss rept scheduled for 801106.
TEDESCO, R. L. Assistant Director for Licensing. 80/10/30 32pp 06949:292.

DOCKETED ITEMS

801170579 Forwards control room design review rept resulting from NRC 800915 site visit NRC will discuss content & solicit comments re rept in 801106 meeting w/utill.
TEDEBCCO, R. L. Assistant Director for Licensing. 80/10/30. 32pp
06978 192

8011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201.
ABEL, J. B. Commonwealth Edison Co. 80/10/31 1p.

8011040440 Forwards "Environ Qualification of Electrical Equipment," in response to NRC 800221 request Rept will be formally docketed as App M to FSAR
DELGEORGE, L. O. Commonwealth Edison Co. 80/10/31. 3pp. 06868 05B

--8011040446 "Environ Qualification of Electrical Equipment " Rept will be docketed as App M to FSAR
* Commonwealth Edison Co. 80/10/31 200pp. 03703 044.

801100389 Forwards page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments.
TRAMM, T. R. Commonwealth Edison Co. 80/11/05 2pp

801170209 Forwards Revision 4 of "In-Plant Safety Relief Valve Test."
DELGEORGE, L. O. Commonwealth Edison Co. 80/11/10 2pp. 06969 057.

--801170211 Revision 4 of "In-Plant Safety Relief Valve Test "
* Bargent & Lundy, Inc. 80/10/27. 106pp 06969 059.

8011240334 Forwards response to NRC informal inquiry re frequency range used for B/RV T-quencher air clearing load assessment.
Comments by Bargent & Lundy superseded in entirety, issue addressed in 801028 submittal.
DELGEORGE, L. O. Commonwealth Edison Co. 80/11/12. 3pp 07049 096.

8011210612 Summary of 801106 meeting w/utill in Bethesda, MD re areas of NRC concern per site visit to review control room
BOURNIA, A. Licensing Branch 1 80/11/14. 3pp. 07027 255

8011240342 Advises that util will inert primary containment structures at facilities. Commitment is conditioned on accepted Containment Sys Branch position & satisfies requirements of current rulemaking re hydrogen control assessment.
ABEL, J. B. Commonwealth Edison Co. 80/11/17. 2pp 07046 329

8011240369 Informs that control room habitability sys is designed in accordance w/BRP & reg guide requirements. Design satisfies guidance in named NRC positions. No further mods to facility are required
ABEL, J. B. Commonwealth Edison Co. 80/11/17. 1p. 07046 346

8011250212 Suppls util 801027 response to NRC questions re conformance to Reg Guide 1.36 Final documentation of info will be made in amend to FSAR
DELGEORGE, L. O. Commonwealth Edison Co. 80/11/20. 3pp. 07068 316.

F Seüurity, medical, emergency & fire protection plans

801170336 Forwards comments on revised emergency plan per requirements of NUREG-0654 Plan should be revised to address comments
EISENHUT, D. O. Division of Licensing. 80/10/02 5pp.

8011050428 Forwards draft public info package re emergency preparedness for facilities Package has been distributed to States of IL, IA & WI for comment. Requests NRC comment by 801121
DELGEORGE, L. O. Commonwealth Edison Co. 80/11/03 8pp.

G Adjudicatory correspondence

801170235 Requests substitution of PP Steptoe for deceased RE Powell on svc list
STEPTOE, P. P. Isham, Lincoln & Beale. 80/11/10. 1p 06981 398

K Utility Final Safety Analysis Report (FSAR) & amends

8011290284 Forwards affidavit certifying distribution of FSAR Amend 30.
DELGEORGE, L. O. Commonwealth Edison Co. 80/11/17. 2pp. 07052 353

8011240278 Forwards Amend 51 to FSAR including App M re environ qualification of electrical equipment.
ABEL, J. B. Commonwealth Edison Co. 80/11/18. 1p. 07050 148.

--8011240280 Amend 51 to FSAR.
* Commonwealth Edison Co. 80/11/18. 300pp. 07050 150.

8011240378 Forwards Amend 52 to FSAR consisting of revised Figure 9 B-1, "Fire Protection Sys."
ABEL, J. B. Commonwealth Edison Co. 80/11/20 1p 07050 146.

--8011240380 Amend 52 to FSAR
* Commonwealth Edison Co. 80/11/20 26pp 07050 147.

G Inspection reports, IE Bulletins & correspondence

7904040039 IE Insp Rept 50-373/79-10, 50-374/79-04, 50-454/79-04 & 50-455/79-04 on 790119, 790205 & 04 No noncompliance noted. Major areas inspected, tendon sys performance tests & proposed Inpyco, Inc tendon performance program
* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/02/23 4pp. 03133 271.

8011060202 Forwards IE Insp Rept 50-373/80-33 on 800813-15. No noncompliance noted.
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/09/03. 2pp 06912 081.

--8011060207 IE Insp Rept 50-373/80-33 on 800813-15 No noncompliance noted. Major areas inspected: radiation protection & radwaste programs.
FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch MILLER, D. E. Region 3, Chicago, Office of the Director 80/08/26 4pp 06912 083.

8011200036 Forwards IE Insp Repts 50-373/80-39 & 50-374/80-25 on 800904. No noncompliance noted.
FIORILLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/17 2pp 07020 224

--8011200040 IE Insp Repts 50-373/80-39 & 50-374/80-25 on 800904 No noncompliance noted. Major areas inspected reactor pressure vessel internals work & safety relief valve GC records.
NEISLER, J. H., ERB, C. M., WILLIAMS, C. C. Region 3, Chicago, Office of the Director. 80/09/16 4pp 07020 226.

8011030120 Forwards IE Insp Repts 50-373/80-38 & 50-374/80-24 on 800826-28. No noncompliance noted
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/09/26 2pp 06897 241

--8011030128 IE Insp Repts 50-373/80-38 & 50-374/80-24 on 800826-28. No noncompliance noted. Major areas inspected environ protection & confirmatory measurements including GA/GC.
OERTHAHN, M. J., PAPERIELLO, C. J. Region 3, Chicago, Office of the Director 80/09/25 8pp 06857 243

8011180856 Forwards IE Insp Rept 50-373/80-37 on 800728-0905 No noncompliance noted.
HEIBHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/10/06 2pp. 06992 069

--8011180860 IE Insp Rept 50-373/80-37 on 800728-0905. No noncompliance noted. Major areas inspected, review of previous insp findings, IE bulletins & circulars received, preoperational test procedures & plant walkthrough.
WALKER, R. O., SHEPLEY, S. E., SPESSARD, R. L. Region 3, Chicago, Office of the Director. 80/10/03 14pp 06992 071.

8011250136 Forwards IE Insp Repts 50-373/80-40 & 50-374/80-26 on 800829, 0902-05 & 10. No noncompliance noted.
KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/10/06. 2pp 07056 268.

--8011250144 IE Insp Repts 50-373/80-40 & 50-374/80-26 on 800829, 0902-05 & 10 No noncompliance noted. Major areas inspected: corrective actions on safety-related small bore piping suspension sys design installation
YIN, I. T. Region 3, Chicago, Office of the Director DANIELSON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/25 8pp. 07056 270

8011180400 Forwards IE Insp Repts 50-373/80-42 & 50-374/80-27 on 800923-24 No noncompliance noted
FIORILLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/09 2pp 06989 179

--8011180409 IE Insp Repts 50-373/80-42 & 50-374/80-27 on 800923-24. No noncompliance noted. Major areas inspected, post-tensioning activities, suppression pool mod, followup to IE bulletins, fire stop installation & safety-related piping activities.
NEISLER, J. H., HAWKINS, F. C., WILLIAMS, C. C. Region 3, Chicago, Office of the Director 80/10/08 6pp 06989 181.

8011210248 Forwards first biweekly rept as requested in IE Insp Repts 50-373/80-40 & 50-374/80-26.
WATTS, T. E. Commonwealth Edison Co. 80/10/22. 9pp. 07030 166.

8011040556 Forwards final response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies." Review revealed possible problem w/30 actuators A/E discussing problem w/vendor. Either springs or actuators will be replaced
RAUSCH, T. J. Commonwealth Edison Co. 80/10/23 2pp 04875.149.

8011070285 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required
KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/10/24 1p

8011210241 Forwards Biweekly Rept 2 as requested in IE Insp Repts 80-373/80-40 & 80-374/80-26.
WATTS, T. E. Commonwealth Edison Co. 80/11/05 2pp 07030.102.

8011210281 Informs that vendor evaluation re potential misapplication of pressure transmitters described in IE Bulletin 80-16 will be delayed due to issue complexity
RAUSCH, T. J. Commonwealth Edison Co. 80/11/10 1p 07030.119

B Reportable occurrences, LERs & related correspondence

8011170286 Responds to NRC 800904 ltr re followup requirements for resumption of use of Tech-Bil, Inc fire stop matl. Tech-Bil has provided assurance that const matls have traceable certifications.
DELGEOERGE, L. O. Commonwealth Edison Co. 80/10/28 5pp. 06978.291.

V Operator Examinations

8011100481 Forwards response to NRC 800731 ltr transmitting interim criteria for shift staffing & requesting util schedule for compliance. Vacancies may create situations requiring overtime in excess of NRC guidelines
JANECEK, R. F. Commonwealth Edison Co. 80/11/05 5pp.

801120492 Forwards response to NRC 800731 request for schedule per interim shift staffing requirements
JANECEK, R. F. Commonwealth Edison Co. 80/11/05 5pp.

DOCKET 80-374 LABALLE COUNTY STATION, UNIT 2

A Application/construction stage documents & correspondence

8011050334 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D. O. Division of Licensing. 80/09/05. 209pp.

801140568 Forwards request for addl info re application of OE emergency procedure guidelines, Revision 0
EISENHUT, D. O. Division of Licensing. 80/09/24. 5pp. 06911.001

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D. O. Division of Licensing. 80/10/01 5pp.

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl.
EISENHUT, D. O. Division of Licensing. 80/10/06. 6pp.

8011050535 Forwards request for addl info re emergency procedure guidelines. Schedule must be submitted by 801027. OE 800630 guidelines acceptable for trial implementation. Training program must account for possible mod
EISENHUT, D. O. Division of Licensing. 80/10/21. 8pp.

801140491 Provides info on design, procurement & installation of inserting sys.
EISENHUT, D. O. Division of Licensing. 80/10/24. 2pp.

8011030448 Forwards addl info in response to A Bournia 801002 informal inquiry re LSCB-1 in-plant safety relief valve test. Test objectives include determination of extent of thermal mixing in suppression pool during extended blowdown test condition.
DELGEOERGE, L. O. Commonwealth Edison Co. 80/10/27 17pp 06872.293

8011030450 Informs of intention to rely on nuclear heat addition in performance of hot hydrostatic test. Addition is judged compatible w/current NRC position provided as part of review of OE topical rept, NEDO-21778 re transient pressure.
DELGEOERGE, L. O. Commonwealth Edison Co. 80/10/27. 2pp. 06867.941.

8011030548 Notifies that util response to Effluent Treatment Sys Branch Questions 321.20 through 321.22 documented in 801020 ltr Sections L 28, L 36 & L 19, respectively. Formal documentation to be addressed in future FSAR amend
DELGEOERGE, L. O. Commonwealth Edison Co. 80/10/27 1p 06895.036.

8011030563 Forwards response to NRC second round Questions 331.34 - 331.37 & FSAR text changes, per 800910 ltr
DELGEOERGE, L. O. Commonwealth Edison Co. 80/10/27. 14pp 06895.039.

8011030572 Forwards responses to Chemical Engineering Branch Questions 200.1 - 200.6 per 800723 request. Matls will be formally documented in next amend to FSAR
DELGEOERGE, L. O. Commonwealth Edison Co. 80/10/27 7pp 06895.037

8011040380 Forwards errata, constituting Revision 1 of assessment on Executive Order 11988 re floodplain mgmt
DELGEOERGE, L. O. Commonwealth Edison Co. 80/10/28 8pp 06874.162

8011040524 Responds to NRC informal inquiry re B/RV T-quencher air clearing lead assessment. Range of 3.4-10 hertz was derived & demonstrated to be conservative
DELGEOERGE, L. O. Commonwealth Edison Co. 80/10/28 3pp. 06873.132

8011100328 Notification of 801117-21 meeting w/util in Chicago, IL & at site to conduct onsite review of qualification program for seismic qualification review team.
BOURNIA, A. Licensing Branch 3 80/10/28 3pp. 06928.348.

8011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201
ABEL, J. S. Commonwealth Edison Co. 80/10/31 1p

8011040440 Forwards "Environ Qualification of Electrical Equipment," in response to NRC 800221 request. Rept will be formally docketed as App M to FSAR
DELGEOERGE, L. O. Commonwealth Edison Co. 80/10/31. 3pp. 06868.038

--8011040446 "Environ Qualification of Electrical Equipment" Rept will be docketed as App M to FSAR
* Commonwealth Edison Co. 80/10/31. 200pp 03703.044.

8011100389 Forwards page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments.
TRAMM, T. R. Commonwealth Edison Co. 80/11/05 2pp.

8011170209 Forwards Revision 4 of "In-Plant Safety Relief Valve Test."
DELGEOERGE, L. O. Commonwealth Edison Co. 80/11/10 2pp 06969.057.

--8011170211 Revision 4 of "In-Plant Safety Relief Valve Test"
* Sargent & Lundy, Inc. 80/10/27 106pp 06969.059.

8011240334 Forwards response to NRC informal inquiry re frequency range used for B/RV T-quencher air clearing lead assessment. Comments by Sargent & Lundy supersede, in entirety, issue addressed in 801028 submittal
DELGEOERGE, L. O. Commonwealth Edison Co. 80/11/12 3pp 07049.096.

8011210612 Summary of 801106 meeting w/util in Bethesda, MD re areas of NRC concern per site visit to review control room.
BOURNIA, A. Licensing Branch 1. 80/11/14 5pp 07029.295.

8011240342 Advises that util will inert primary containment structures at facilities. Commitment is conditioned on accepted Containment Sys Branch position & satisfies requirements of current rulemaking re hydrogen control assessment
ABEL, J. S. Commonwealth Edison Co. 80/11/17. 2pp. 07046.329.

8011240369 Informs that control room habitability sys is designed in accordance w/SRP & reg guide requirements. Design satisfies guidance in named NRC positions. No further mods to facility are required
ABEL, J. S. Commonwealth Edison Co. 80/11/17. 1p. 07046.346

8011250212 Suppls util 801027 response to NRC questions re conformance to Reg Guide 1.56. Final documentation of info will be made in amend to FSAR.
DELGEOERGE, L. O. Commonwealth Edison Co. 80/11/20. 3pp 07068.316

F. Security, medical, emergency & fire protection plans

8011170336 Forwards comments on revised emergency plan per requirements of NUREG-0684. Plan should be revised to address comments
EISENHUT, D. O. Division of Licensing. 80/10/02 5pp.

DOCKETED ITEMS

8011050428 Forwards draft public info package re emergency preparedness for facilities Package has been distributed to States of IL, IA & WI for comment Requests NRC comment by 801121
DELGEORE, L. Q. Commonwealth Edison Co 80/11/03 8pp

O Adjudicatory correspondence

8011170235 Requests substitution of PP Steptoe for deceased RE Powell on svc list
STEPTOE, P. P. Isham, Lincoln & Seale 80/11/10 1p 06981 35B.

K Utility Final Safety Analysis Report (FSAR) & amends

8011250284 Forwards affidavit certifying distribution of FSAR Amend 50
DELGEORE, L. Q. Commonwealth Edison Co 80/11/17 2pp. 07052 353

8011240278 Forwards Amend 51 to FSAR including App M re environ qualification of electrical equipment
ABEL, J. S. Commonwealth Edison Co 80/11/18 1p 07050 14B

--8011240280 Amend 51 to FSAR
* Commonwealth Edison Co 80/11/18 300pp 07050.130

8011240378 Forwards Amend 52 to FSAR consisting of revised Figure 9-1, "Fire Protection Sys"
ABEL, J. S. Commonwealth Edison Co 80/11/20 1p 07050.146

--8011240380 Amend 52 to FSAR
* Commonwealth Edison Co 80/11/20 26pp 07050.147

G Inspection reports, IE Bulletins & correspondence

7904040038 IE Insp Rept 50-373/79-10, 50-374/79-04, 50-454/79-04 & 50-455/79-04 on 790119, 790205 & 06 No noncompliance noted
Major areas inspected tendon sys performance tests & proposed Inryco, Inc tendon performance program
* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/02/23 4pp 03133 271

8011200036 Forwards IE Insp Repts 50-373/80-39 & 50-374/80-23 on 800904 No noncompliance noted
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/17 2pp. 07020 224

--8011200040 IE Insp Repts 50-373/80-39 & 50-374/80-23 on 800904 No noncompliance noted Major areas inspected reactor pressure vessel internals work & safety relief valve GC records.
NEISLER, J. H.; ERB, C. M.; WILLIAMS, C. C. Region 3, Chicago, Office of the Director, 80/09/16 4pp 07020.226

8011030120 Forwards IE Insp Repts 50-373/80-38 & 50-374/80-24 on 800826-28 No noncompliance noted
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/09/26 2pp 06857 241

--8011030128 IE Insp Repts 50-373/80-3d & 50-374/80-24 on 800826-28 No noncompliance noted Major areas inspected environ protection & confirmatory measurements including QA/GC.
DESHAIN, M. J.; PAPERIELLO, C. J. Region 3, Chicago, Office of the Director 80/09/25 8pp 06857 243

8011250136 Forwards IE Insp Repts 50-373/80-40 & 50-374/80-26 on 800829, 0902-05 & 10 No noncompliance noted
KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/10/06 2pp 07056 268

--8011250144 IE Insp Repts 50-373/80-40 & 50-374/80-26 on 800829, 0902-05 & 10 No noncompliance noted Major areas inspected corrective actions on safety-related small bore piping suspension sys design installation
VIII, I. T. Region 3, Chicago, Office of the Director
DANIELSON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/25 8pp 07056 270.

801180400 Forwards IE Insp Repts 50-373/80-42 & 50-374/80-27 on 800923-24 No noncompliance noted
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/09 2pp 06989 179

--801180409 IE Insp Repts 50-373/80-42 & 50-374/80-27 on 800923-24, No noncompliance noted Major areas inspected post-tensioning activities, suppression pool mod, followup to IE bulletins, fire stop installation & safety-related piping activities.
NEISLER, J. H.; HAWKINS, F. C.; WILLIAMS, C. C. Region 3, Chicago, Office of the Director 80/10/08 6pp 06989.181

8011210248 Forwards first biweekly rept as requested in IE Insp Repts 50-373/80-40 & 50-374/80-26
WATTS, T. E. Commonwealth Edison Co 80/10/22 7pp 07030 106.

8011040356 Forwards final response to IE Bulletin 80-09, "Hydramtor Actuator Deficiencies" Review revealed possible problem w/30 actuators A/E discussing problem w/vendor Either springs or actuators will be replaced.
RAUSCH, T. J. Commonwealth Edison Co. 80/10/23 2pp. 06875 149

8011070285 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required
KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/10/24 1p.

8011210241 Forwards Biweekly Rept 2 as requested in IE Insp Repts 50-373/80-40 & 50-374/80-26
WATTS, T. E. Commonwealth Edison Co 80/11/05 2pp 07030 102

8011210251 Informs that vendor evaluation re potential misapplication of pressure transmitters described in IE Bulletin 80-16 will be delayed due to issue complexity
RAUSCH, T. J. Commonwealth Edison Co 80/11/10 1p 07030 119.

S. Reportable occurrences, LERs & related correspondence

8011030184 Ack receipt of 801002 interim deficiency rept re electrical penetrations.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/17. 1p. 06857 135

--8011030190 Interim deficiency rept re cracks in insulation of certain feed through conductors of entrance or exit of epoxy module portion of penetration. Rework procedure has not been formally submitted Supplemental rept expected by 810101
DELGEORE, L. Q. Commonwealth Edison Co 80/10/02 3pp. 06857 136

8011170286 Responds to NRC 800904 ltr re followup requirements for resumption of use of Tech-Sil, Inc fire stop matl. Tech-Sil has provided assurance that const matls have traceable certifications.
DELGEORE, L. Q. Commonwealth Edison Co 80/10/28. 5pp 06978 291.

V Operator Examinations

8011100481 Forwards response to NRC 800731 ltr transmitting interim criteria for shift staffing & requesting util schedule for compliance Vacancies may create situations requiring overtime in excess of NRC guidelines
JANECEK, R. F. Commonwealth Edison Co 80/11/05. 5pp

8011120492 Forwards response to NRC 800731 request for schedule per interim shift staffing requirements
JANECEK, R. F. Commonwealth Edison Co 80/11/05. 5pp.

DOCKET 50-375 NUCLEAR EXAMINATION REACTOR

J Insurance & indemnity information

8011140015 Forwards Endorsements 91, 92 & 93 to NELIA Policy NF-12 & Endorsements B1 & B2 to NELIA Policy NF-93
BRINDLEY, J. H. Rockwell International Corp., Energy Systems Div. 80/10/27. 8pp 06961 195

G Inspection reports, IE Bulletins & correspondence

8011060800 Forwards IE Insp Rept 50-375/80-03 on 800924-25, No noncompliance noted
BOOK, H. E. Region 3, San Francisco, Fuel Facility & Materials Safety Branch. 80/10/16 2pp 06909 134

--8011060809 IE Insp Rept 50-375/80-03 on 800924-25 No noncompliance noted Major areas inspected physical status of facility to determine license plans & timetable re reactor dismantling plan
CURTIS, J. R.; WENSLAWSKI, F. Region 3, San Francisco, Office of the Director
BOOK, H. E. Region 3, San Francisco, Fuel Facility & Materials Safety Branch 80/10/15 2pp. 06909 136.

DOCKET 50-376 NORTH COAST NUC PLANT

Q Adjudicatory correspondence

8011250576 Order allowing intervenors to file submission by 801204. Submission should address applicants & NRC argument that CP application should be dismissed w/o prejudice
WOLFE, J. Atomic Safety and Licensing Board Panel 80/11/19 2pp
07068 345

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D. O. Division of Licensing 80/09/05 207pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101.
EISENHUT, D. O. Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" w/o encl
EISENHUT, D. O. Division of Licensing 80/10/06 6pp.

8011060083 Notification of 801024 meeting w/util in Taft, LA to review staff concerns re area of initial test program
KANE, W. F. Licensing Branch 2 80/10/20 3pp 06912 349

8011070402 Advises of intent to utilize safety evaluation status rept in lieu of formal question & response approach for review of Subsection 3.6.2 through 3.9.6 of FSAR. Open items will be documented in Nov & Dec FSAR amendments
HYATT, J. M. Louisiana Power & Light Co 80/11/03 2pp. 06924 356.

8011210511 Forwards "Response to FSAR Question 11.1: Asymmetric Loads," requested by NRC at 801001 draft SER review meeting. Requests that NRC provide prompt review Comments received by 801201 will be included in amend
MAURIN, L. V. Louisiana Power & Light Co 80/11/14 50pp.
07032:232

8011240306 Forwards Amend 13 to OL application & to FSAR, including responses to addl info requests from Auxiliary Sys Branch, I&C Branch, Reactor Sys Branch & info on emergency feedwater sys Two hundred oversize drawings encl
ABWELL, D. L. Louisiana Power & Light Co 80/11/18 1p 07066 134.

--8011240320 Application for Amend 13 to OL application
ABWELL, D. L. Louisiana Power & Light Co 80/11/18 2pp
07066 135

E NRC Safety Evaluation Report (SER), supp's & correspondence

8011210511 Forwards "Response to FSAR Question 11.1: Asymmetric Loads," requested by NRC at 801001 draft SER review meeting. Requests that NRC provide prompt review Comments received by 801201 will be included in amend
MAURIN, L. V. Louisiana Power & Light Co 80/11/14 50pp
07032:232

K Utility Final Safety Analysis Report (FSAR) & amends

8011240306 Forwards Amend 13 to OL application & to FSAR, including responses to addl info requests from Auxiliary Sys Branch, I&C Branch, Reactor Sys Branch & info on emergency feedwater sys Two hundred oversize drawings encl
ABWELL, D. L. Louisiana Power & Light Co 80/11/18 1p 07066 134.

--8011240320 Application for Amend 13 to OL application.
ABWELL, D. L. Louisiana Power & Light Co 80/11/18 2pp.
07066 135.

--8011240326 Amend 13 to FSAR Package of 200 oversize drawings encl.
ABWELL, D. L. Louisiana Power & Light Co 80/11/18 350pp
07068 096.

8011250402 Certifies svc of updated Amend 13 to FSAR on 801121.
* Louisiana Power & Light Co 80/11/21 1p. 07056 096.

Q Inspection reports, IE Bulletins & correspondence

8011040660 Forwards IE Insp Rept 50-322/80-22 on 800902-05 No noncompliance noted
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/26 2pp 06875 360

--8011040665 IE Insp Rept 50-382/80-22 on 800902-05 No noncompliance noted Major areas inspected const activities re followon review of previously identified unresolved items & review of instrumentation installation
STEWART, R. C., CROSSMAN, W. A. Region 4, Dallas, Office of the Director 80/09/25 4pp 06876 001

8011190283 Forwards IE Insp Rept 80-382/80-27 on 800923-26 No noncompliance noted
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/10/09 2pp 06996 127

--8011190289 IE Insp Rept 50-382/80-27 on 800923-26 No noncompliance noted Major areas inspected electrical cable installation, including receiving, qualification & installation documentation & records
MARTIN, L. E., STEWART, R. C. Region 4, Dallas, Office of the Director JOHNSON, A. R. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/10/08 4pp 06996 127

8011060770 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting" No written response required
BEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/10/10 1p. 06909 079.

8011130048 Forwards Suppl 3 to IE Bulletin 79-01B, "Environment Qualification of Class IE Equipment" No written response required
BEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/10/24 1p 06938 175

8011170019 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2" No written response required
BEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/10/27 1p 06978 328

8011170615 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators" No written response required
BEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/10/31 1p. 06977 282

8011260413 Ack receipt of 801002 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/80-20
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/11/12 1p 07072 338

--8011260414 Responds to NRC 800909 ltr re violations noted in IE Insp Rept 50-382/80-20 Corrective actions anchor bolts 2200-2300 will be tested & incorrect spool will be replaced to provide proper alignment to pump
ABWELL, D. L. Louisiana Power & Light Co 80/10/02 3pp
07072 339

B Reportable occurrences, LERs & related correspondence

801110692 Discusses continuing evaluation of reportability of flexible liquid-tight wiring conduit covering failure Next rept will be sent by 800930
ABWELL, D. L. Louisiana Power & Light Co 80/09/02 1p 06944 329.

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D. O. Division of Licensing 80/09/05 207pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101.
EISENHUT, D. O. Division of Licensing 80/10/01 5pp.

DOCKETED ITEMS

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp.

801105055 Forwards request for addl info re emergency procedure guidelines Schedule must be submitted by 801027 OE 800630 guidelines acceptable for trial implementation Training program must account for possible mod
EISENHUT, D O Division of Licensing 80/10/21 8pp

801100408 Forwards request for addl info re core performance for review of OL application
TEDESCO, R L Assistant Director for Licensing 80/10/23 3pp
06928 001

801100421 Forwards Auxiliary Sys Branch request for addl info re Round 2 questions Util should modify response to questions re pressure loadings in compartment within reactor bldg & change Tech Specs for Units 1 & 2 cranes.
TEDESCO, R L Assistant Director for Licensing 80/10/23 3pp
06931 268

8011070133 Notification of 801114 rescheduled meeting w/util in Berwick, PA to discuss scheduled fuel load date per Curtis
800819 ltr to Eisenhut
STARK, R M Licensing Branch 1 80/10/29 2pp 06920 273

8011040126 Forwards "Environ Qualification of Class IE Equipment," Vols 1-3
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p
06881 222

--8011040132 "Environ Qualification of Class IE Equipment," Vol 1
* Pennsylvania Power & Light Co 80/10/31 325pp. 06881.223

--8011040134 "Environ Qualification of Class IE Equipment," Vol 2
* Pennsylvania Power & Light Co 80/10/31 350pp. 06882 195

--8011040142 "Environ Qualification of Class IE Equipment," Vol 3
* Pennsylvania Power & Light Co 80/10/31 104pp 06883 193

8011040225 Forwards Amend 25 to OL application, containing Revision 2 to emergency plan Emergency plan available in Central Files only
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p
06884 195

--8011040233 Amend 25 to 790731 OL application, containing Revision 2 to emergency plan
CURTIS, N W Pennsylvania Power & Light Co. 80/10/31 1p
06884 196

801110049 Responds to 801002 ltr re licensing schedule for facilities Ofc of Nuclear Reactor Regulation will strive to reduce impact of licensing process on fuel load dates List of outstanding unanswered NRC questions encl
YOUNGBLOOD, B J Licensing Branch 1 80/10/31 4pp. 06943 108

801120575 Discusses review of addl info requested for Revision 17 to FSAR, Section 13.2 & partial response to NRC 790212 second round questions Forwards guidance re revision to Section 13.2 Response re fire safety training program is acceptable
HANAUER, S H Division of Human Factors Safety 80/11/03 1p
06953 260

801140635 Forwards review of addl info submitted for Section 13.2 of FSAR, Revision 17 Concludes section should be revised to bring FSAR into conformance w/previously approved submittals & NUREG-0694
HANAUER, S H Division of Human Factors Safety 80/11/03 8pp
06968 211

8011200242 Forwards Chapter 5 to "Environ Qualification Rpt for Class IE Equipment"
CURTIS, N W Pennsylvania Power & Light Co 80/11/12 1p
07019 032.

--8011200249 Chapter 5 to "Environ Qualification Rpt for Class IE Equipment"
* Pennsylvania Power & Light Co. 80/11/12 200pp. 07019.033

F Security, medical, emergency & fire protection plans

8011040225 Forwards Amend 25 to OL application, containing Revision 2 to emergency plan Emergency plan available in Central Files only
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p
06884 195

--8011040233 Amend 25 to 790731 OL application, containing Revision 2 to emergency plan
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p
06884 196

G Adjudicatory correspondence

801100300 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
BRESENTHAN, T P Affiliation Unknown 80/10/17 1p 06931 278

801100305 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
NDREIKA, R Affiliation Unknown 80/10/17 1p 06931 276

801100312 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
NEVIN, A Affiliation Unknown 80/10/17 1p 06931 295

801100318 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
CHELL, W L Affiliation Unknown 80/10/17 1p 06931 274

801100322 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
LAOD, D R Affiliation Unknown 80/10/17 1p 06931 293

801100327 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
SULLIVAN, O Affiliation Unknown 80/10/17 1p 06931 292.

801100330 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
BOYLAN, J C P Affiliation Unknown 80/10/17 1p. 06931 291.

801100333 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
VITELLI, J B Affiliation Unknown 80/10/17 1p 06931.290.

801100339 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
WATAUS, C Affiliation Unknown 80/10/17 1p 06931 289

801100342 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
GILL, P Affiliation Unknown 80/10/17 1p 06931 288

8010220524 Requests to make limited appearance statement at licensing hearings
BHEARER, J Affiliation Unknown 80/10/20 1p 06779 301.

801100304 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
CONSIDINE, E E Affiliation Unknown 80/10/20 1p 06931.297

801050408 Response in opposition to Environ Coalition on Nuclear Power petition for Commission review of ALAB-613 Intervenor petition sets forth nothing which warrants different conclusion Certificate of Svc encl.
SILBERO, J E Pennsylvania Power & Light Co SILBERO, J E Shaw, Pittman, Potts & Troubridge 80/10/29 4pp 06898 172

801050207 Response in opposition to Environ Coalition on Nuclear Power 801014 petition for review of ALAB-613 Urges denial of intervenor request for funding Petition does not raise issue of important legal matter w/appearance & Certificate of Svc
LAVERY, J. H Hearing Branch 1 80/10/30 14pp 06899 074

DOCKETED ITEMS

19

801100253 Memorandum & order inviting further responses to applicants' motion for summary disposition of Contention 16 & part of Contention 17 Filing must be made within 21 days from svc BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/11/04 3pp 06929 077

801130334 Motion for partial summary disposition of Contention 2 re health effects of discharged chlorine Responses due within three wks from present filing
SILBERG, J E, TRAVIESO-DIAZ Pennsylvania Power & Light Co
SILBERG, J E Allegheny Electric Cooperative, Inc 80/11/06 2pp 06958 329

--801130350 Statement of matl facts re absence of issue to be heard, in support of motion for partial summary disposition of Contention 2 on health effects of discharged chlorine
SILBERG, J E, TRAVIESO-DIAZ Pennsylvania Power & Light Co.
SILBERG, J E Allegheny Electric Cooperative, Inc 80/11/06 2pp 06958 331

--801130361 Affidavit in support of motion for partial disposition of Contention 2 re health effects of discharged chlorine
Acid drainage & toxic chemical waste spills will not increase amount of chlorine. Prof qualifications encl
RIOS, J Bechtel Power Corp. (subs of Bechtel Corp) 80/11/04 3pp. 06958 333.

--801130375 Pleading in support of motion for partial summary disposition of Contention 2 re health effects of discharged chlorine Issue narrowed by intervenor/sponsor via response to RRC interrogatories w/Certificate of Svc
SILBERG, J E, SILBERG, J E Pennsylvania Power & Light Co
TRAVIESO-DIAZ Allegheny Electric Cooperative, Inc 80/11/06. 7pp. 06958 336.

801180052 Requests opportunity for limited appearance statement
MERRILL, B Affiliation Unknown 80/11/10 1p 06987 179

801170874 Memorandum & order granting applicants' 801007 motion to establish new discovery schedule re health & safety issues to extent indicated in present order Applicants must submit new emergency plans conforming w/new regulations
BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/11/12 8pp 06978 081

8011200243 Requests to make limited appearance at licensing hearing.
GEIDER, O Affiliation Unknown 80/11/17 1p 07019 350

8011260010 Request for extension until 801205 to respond to applicant 801027 motion for summary disposition of Contention 16 due to unavailability of counsel & technical staff Certificate of Svc encl
LAVERTY, J. H Hearing Branch 1 80/11/20 4pp 07075 290

8011280008 Order granting extension until 801201 For Commission to consider ALAB-613
CHILK, S J Office of the Secretary of the Commission 80/11/21 1p. 07084 006.

8011280013 Order granting extension until 801205 For NRC to respond to applicant motion for summary disposition of Contention 16 re cooling tower discharge
BECHHOEFER, C Atomic Safety and Licensing Board Panel. 80/11/21 1p 07084 021.

8011260167 Requests to make limited appearance statement at licensing hearing for facilities
TEDESCO, L Affiliation Unknown 80/11/24 1p 07074 081

--8011260168 Requests to make limited appearance statement at licensing hearing for facilities
BARTOR, H. Affiliation Unknown 80/11/24 1p 07074 082

--8011260170 Requests to make limited appearance statement at licensing hearing for facilities.
WOLFE, H. Affiliation Unknown 80/11/24 1p 07074 083

G. Inspection reports, IE Bulletins & correspondence

801100363 Forwards addendum to IE Insp Repts 50-387/79-04 & 50-388/79-05 on 800129-0221. No noncompliance noted
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/29 2pp. 06929.269

--801100373 Addendum to IE Insp Repts 50-387/79-04 & 50-388/79-05 on 800129-0221 No noncompliance noted Major areas inspected allegations re QC program
SMITH, R. H., VARELA, A A Region 1, Philadelphia, Office of the Director EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/25 10pp 06929 271

8011060539 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " IE 79-018 & suppl dtd 800229, not previously transmitted, also encl No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/30 1p. 06910 225

8011060645 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24, 1p 06909 333

8011070331 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24, 1p. 06922:029

8011210367 Ack receipt of 801016 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/80-16
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/27 1p 07030 161

--8011210374 Responds to NRC 800911 ltr re violations noted in IE Insp Rept 50-387/80-16 Corrective actions preoperational test being revised to incorporate integrated operation of recirculation sys
CURTIS, H. M. Pennsylvania Power & Light Co 80/10/16 2pp 07030 162

--8011210379 Forwards IE Insp Rept 50-387/80-16 on 800630-0801 & notice of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/11 2pp 07030 164

--8011210386 Notice of violation from insp on 800630-0801
* Region 1, Philadelphia, Office of the Director 80/09/08 1p 07030 166

--8011210395 IE Insp Rept 50-387/80-16 on 800630-0801 Noncompliance noted, failure to incorporate recirculation sys flow testing into preoperational test
GALLO, R. M., RHODAS, O O Region 1, Philadelphia, Office of the Director MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/08 15pp 07030 167

801140084 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/10/31 1p 06965 316

801140629 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31, 1p 06963 255

8011260071 Submits final response to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches." Warning notice will be added to applicable drawings to ensure against use of neutral position contacts
CURTIS, N. H. Pennsylvania Power & Light Co 80/11/03 1p 07071 016.

R Periodic operating reports & related correspondence

8011250515 Forwards "Radiological Environ Monitoring Program, 1979 Annual Rept" & "Ecological Studies of Susquehanna River in Vicinity of Susquehanna Steam Electric Station, Annual Rept for 1979 "
CRUISE, N. H. Pennsylvania Power & Light Co 80/11/19 1p 07057-001.

--8011250522 "Radiological Environ Monitoring Program, 1979 Annual Rept "
* Radiation Management Corp RMC-TR-80-01 80/03/31 83pp 07057 002.

--8011250531 "Ecological Studies of Susquehanna River in Vicinity of Susquehanna Steam Electric Station, Annual Rept for 1979 "
JACOBSEN, T. V. Ichthyological Associates, Inc 80/04/30 300pp 07057, 079

DOCKETED ITEMS

Reportable occurrences, LERs & related correspondence

011200164 Ack receipt of 800923 interim deficiency rept re Application of Hilti shell anchors
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/02 1p 07019 335

011050073 Ack receipt of 800927 final rept re power generation control complex/advanced control room cable connector deficiencies Rept will be reviewed & evaluated
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/08 1p 06876-301

011200088 Ack receipt of util 800923 ltr forwarding interim deficiency rept re defective limitorque limit switch rotors Final rept will be expected in Nov 1980
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/09 1p 07022 097

01170867 Ack receipt of util 801002 ltr re deficiency on Anchor Darling valve yokes
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/10 1p 06979 358

011200198 Ack receipt of 800929 final deficiency rept re cable damage during pulling operations
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/10 1p 07019 333

01170755 Ack receipt of 801006 deficiency rept re Pacific check valves
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/15 1p 06976 062

011210591 Interim deficiency rept re excessive voltage drops in 250-volt dc power cables supplying motor operated valves Caused by power cable lengths & line resistances Alternatives being evaluated Final rept will be submitted by Jan 1981
CURTIS, N W Pennsylvania Power & Light Co 80/11/17 2pp 07034 029

011250793 Final deficiency rept re cracks in limitorque limit switch rotors originally reported 800923 Caused by misalignment in holes in limit switch rotor & pinion shaft. Cracked rotors will be replaced
CURTIS, N W Pennsylvania Power & Light Co 80/11/19 App 07056 141

CKR 80-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

Application/construction stage documents & correspondence

11050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

11100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

11050555 Forwards request for addl info re emergency procedure guidelines Schedule must be submitted by 801027 GE 800630 guidelines acceptable for trial implementation Training program must account for possible mod
EISENHUT, D G Division of Licensing 80/10/21 8pp

1100408 Forwards request for addl info re core performance for review of DL application
EDESCH, R L Assistant Director for Licensing 80/10/23 3pp 06928 001

1100421 Forwards Auxiliary Sys Branch request for addl info re found 2 questions Util should modify response to questions re pressure loadings in compartment within reactor bldg & hange Tech Specs for Units 1 & 2 cranes
EDESCH, R L Assistant Director for Licensing 80/10/23 3pp 06931 268

1070193 Notification of 801114 rescheduled meeting w/util in scrulk, PA to discuss scheduled fuel load date per Curtis
TARK, R M Licensing Branch 1 80/10/29 2pp 06920, 273

8011040126 Forwards "Environ Qualification of Class IE Equipment," Vols 1-3
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p 06881 222

--8011040132 "Environ Qualification of Class IE Equipment," Vol 1
* Pennsylvania Power & Light Co 80/10/31 325pp 06881 223

--8011040136 "Environ Qualification of Class IE Equipment," Vol 2
* Pennsylvania Power & Light Co 80/10/31 350pp 06882 193

--8011040142 "Environ Qualification of Class IE Equipment," Vol 3
* Pennsylvania Power & Light Co 80/10/31 104pp 06883 193

8011040225 Forwards Amend 25 to DL application, containing Revision 2 to emergency plan Emergency plan available in Central Files only
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p

--8011040233 Amend 25 to 790731 DL application, containing Revision 2 to emergency plan
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p

801110049 Responds to 801002 ltr re licensing schedule for facilities Opc of Nuclear Reactor Regulation will strive to reduce impact of licensing process on fuel load dates List of outstanding unanswered NRC questions encl
YOUNGBL000, B J Licensing Branch 1 80/10/31 4pp 06943:108

8011120775 Discusses review of addl info requested for Revision 17 to FSAR, Section 13 2 & partial response to NRC 790212 second round questions Forwards guidance re revision to Section 13 2 Response re fire safety training program is acceptable.
HANAUER, S H Division of Human Factors Safety 80/11/03 1p 06933 260

8011140635 Forwards review of addl info submitted for Section 13 2 of FSAR, Revision 17 Concludes section should be revised to bring FSAR into conformance w/ previously approved submittals & NUREG-0694
HANAUER, S H Division of Human Factors Safety 80/11/03 8pp 06948 211

8011200242 Forwards Chapter 5 to "Environ Qualification Rept for Class IE Equipment"
CURTIS, N W Pennsylvania Power & Light Co 80/11/12 1p 07019 032

--8011200249 Chapter 5 to "Environ Qualification Rept for Class IE Equipment"
* Pennsylvania Power & Light Co 80/11/12 200pp 07019 033

F Security, medical, emergency & fire protection plans

8011040225 Forwards Amend 25 to DL application, containing Revision 2 to emergency plan Emergency plan available in Central Files only.
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p 06884 195

--8011040233 Amend 25 to 790731 DL application, containing Revision 2 to emergency plan
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p 06884 195

O Adjudicatory correspondence

8011100300 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
BRESEKFRAN, T P. Affiliation Unknown 80/10/17 1p 06931 298

8011100305 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made.
NOEIK, R. Affiliation Unknown 80/10/17 1p 06931 294.

8011100312 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
NEVIN, A Affiliation Unknown 80/10/17 1p 06931 295

8011100318 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
CHELL, W. L. Affiliation Unknown 80/10/17 1p 06931 294.

DOCKETED ITEMS

195

801100322 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
LADD, D R Affiliation Unknown 80/10/17 1p 06931 293

801100327 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
SULLIVAN, Q. Affiliation Unknown 80/10/17 1p 06931 292

801100330 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
BOYLAN, J C P Affiliation Unknown 80/10/17 1p 06931 291

801100333 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
VITELLI, J B Affiliation Unknown 80/10/17 1p 06931 290

801100339 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
WATAUS, C. Affiliation Unknown 80/10/17 1p 06931 289

801100342 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
GILL, P. Affiliation Unknown 80/10/17 1p 06931 288

8010220324 Requests to make limited appearance statement at licensing hearings
SHEARER, J Affiliation Unknown 80/10/20 1p 06779 301.

801100304 Requests time to make limited appearance statement at facility licensing hearings Requests info re date & location of hearings & when public comment can be made
CONSIDINE, E E Affiliation Unknown 80/10/20 1p 06931 297

801050408 Response in opposition to Environ Coalition on Nuclear Power petition for Commission review of ALAB-613 Intervenor petition sets forth nothing which warrants different conclusion, Certificate of Svc encl
SILBERO, J E Pennsylvania Power & Light Co SILBERO, J E Shaw, Pittman, Patts & Trowbridge 80/10/29 4pp 06898 172.

801050207 Response in opposition to Environ Coalition on Nuclear Power 801014 petition for review of ALAB-613 Urges denial of intervenor request for Funding Petition does not raise issue of important legal matter W/appearance & Certificate of Svc.
LAVERY, J H Hearing Branch 1 80/10/30 14pp. 06899 074

801100253 Memorandum & order inviting further responses to applicants' motion for summary disposition of Contention 16 & part of Contention 17. Filing must be made within 21 days from svc
BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/11/04. 5pp 06929 077.

801100334 Motion for partial summary disposition of Contention 2 re health effects of discharged chlorine Responses due within three wks from present filing.
SILBERO, J E, TRAVIESO-DIAZ Pennsylvania Power & Light Co
SILBERO, J E Allegheny Electric Cooperative, Inc 80/11/06. 2pp. 06938:329

--801100350 Statement of matl facts re absence of issue to be heard in support of motion for partial summary disposition of Contention 2 on health effects of discharged chlorine.
SILBERO, J E, TRAVIESO-DIAZ Pennsylvania Power & Light Co.
SILBERO, J E Allegheny Electric Cooperative, Inc 80/11/06. 2pp 06938:331

--801100361 Affidavit in support of motion for partial disposition of Contention 2 re health effects of discharged chlorine. Acid drainage & toxic chemical waste spills will not increase amount of chlorine. Prof qualifications encl.
RIOB, J. Bechtel Power Corp (subs of Bechtel Corp) 80/11/04 3pp. 06938:333

--801100375 Pleading in support of motion for partial summary disposition of Contention 2 re health effects of discharged chlorine Issue narrowed by intervenor/sponsor via response to NRC interrogatories W/Certificate of Svc.
SILBERO, J E, SILBERO, J E Pennsylvania Power & Light Co.
TRAVIESO-DIAZ Allegheny Electric Cooperative, Inc 80/11/06. 7pp 06938:336

801180052 Requests opportunity for limited appearance statement
MERRILL, S. Affiliation Unknown 80/11/10 1p 06987 179

801170874 Memorandum & order granting applicants' 801007 motion to establish new discovery schedule re health & safety issues to extent indicated in present order Applicants must submit new emergency plans conforming w/new regulations
BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/11/12 8pp 06978 081

801120043 Requests to make limited appearance at licensing hearing
GEIGER, Q. Affiliation Unknown 80/11/17 1p 07019 350

8011260010 Request for extension until 801205 to respond to applicant 801027 motion for summary disposition of Contention 16 due to unavailability of counsel & technical staff Certificate of Svc encl
LAVERY, J H Hearing Branch 1 80/11/20 4pp 07075 290

8011280008 Order granting extension until 801201 for Commission to consider ALAB-613
CHILK, S J Office of the Secretary of the Commission 80/11/21 1p 07084 086.

8011280013 Order granting extension until 801205 for NRC to respond to applicant motion for summary disposition of Contention 16 re cooling tower discharge
BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/11/21 1p. 07084 021

8011260167 Requests to make limited appearance statement at licensing hearing for facilities
TEDESCO, L Affiliation Unknown 80/11/24 1p. 07074 081

--8011260168 Requests to make limited appearance statement at licensing hearing for facilities
BARTOR, H. Affiliation Unknown 80/11/24 1p 07074 082.

--8011260170 Requests to make limited appearance statement at licensing hearing for facilities
WOLFE, W Affiliation Unknown 80/11/24 1p 07074 083.

G. Inspection reports, IE Bulletins & correspondence

801100363 Forwards addendum to IE Insp Repts 80-387/79-06 & 80-388/79-05 on 800129-0221 No noncompliance noted
CARLESON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/29 2pp 06929 269

--801100373 Addendum to IE Insp Repts 80-387/79-06 & 80-388/79-05 on 800129-0221 No noncompliance noted. Major areas inspected allegations re GC program
SMITH, R H, VARELA, A A Region 1, Philadelphia, Office of the Director, EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/25 10pp. 06929:271

8011060339 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" IES 79-01B & suppl dtd 800229, not previously transmitted, also encl No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/30. 1p 06910 223

8011060645 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2" No written response required
ORIER, B H. Region 1, Philadelphia, Office of the Director. 80/10/24. 1p. 06909 333

8011070331 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required
ORIER, B H. Region 1, Philadelphia, Office of the Director 80/10/24 1p 06922 024

801140084 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required
ORIER, B H. Region 1, Philadelphia, Office of the Director 80/10/31. 1p 06963 316

801140627 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response required
ORIER, B H. Region 1, Philadelphia, Office of the Director. 80/10/31. 1p. 06963:255

DOCKETED ITEMS

8011260071 Submits final response to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches." Warning notice will be added to applicable drawings to ensure against use of neutral position contacts
CURTIS, N W Pennsylvania Power & Light Co 80/11/03 1p
07071 016

R Periodic operating reports & related correspondence

8011250315 Forwards "Radiological Environ Monitoring Program, 1979 Annual Rept" & "Ecological Studies of Susquehanna River in Vicinity of Susquehanna Steam Electric Station, Annual Rept for 1979."
CURTIS, N W Pennsylvania Power & Light Co 80/11/19 1p.
07037 001

--8011250522 "Radiological Environ Monitoring Program, 1979 Annual Rept."
* Radiation Management Corp RMC-TR-80-01 80/03/31. 85pp
07037.002

--8011250531 "Ecological Studies of Susquehanna River in Vicinity of Susquehanna Steam Electric Station, Annual Rept for 1979."
JACOBSEN, T V Ichthyological Associates, Inc 80/04/30 300pp
07037 079.

S Reportable occurrences, LERs & related correspondence

8011200164 Ack receipt of 800925 interim deficiency rept re application of Hilti shell anchors
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/02 1p 07019 335

8011050073 Ack receipt of 800929 final rept re power generation control complex/advanced control room cable connector deficiencies. Rept will be reviewed & evaluated.
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/08 1p 06896-301

8011200088 Ack receipt of util 800923 ltr forwarding interim deficiency rept re defective Limitorque limit switch rotors. Final rept will be expected in Nov 1980
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/09 1p 07022-097

8011170867 Ack receipt of util 801002 ltr re deficiency on Anchor Darling valve yokes
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/10 1p 06979-338

8011170755 Ack receipt of 801006 deficiency rept re Pacific check valves.
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/18 1p 06976 062.

8011070407 Interim deficiency rept re loose contact modules found on QE Type CR2940 selector switches. Bechtel will perform analysis on CR2940 switches & pushbuttons. Final rept, including action taken, will be submitted in Jan 1981
CURTIS, N W Pennsylvania Power & Light Co. 80/10/28 3pp
06921 052

8011210591 Interim deficiency rept re excessive voltage drops in 250-volt dc power cables supplying motor operated valves. Caused by power cable lengths & line resistances. Alternatives being evaluated. Final rept will be submitted by Jan 1981
CURTIS, N W Pennsylvania Power & Light Co 80/11/17 2pp.
07034 029.

8011250993 Final deficiency rept re cracks in Limitorque limit switch rotors originally reported 800923. Caused by misalignment in holes in limit switch rotor & pinion shaft. Cracked rotors will be replaced
CURTIS, N W Pennsylvania Power & Light Co 80/11/19 4pp
07036 141.

DOCKET 80-389 ST LUCIE PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O. Division of Licensing 80/09/05. 209pp

8011030302 Responds to 800820 request re status of Task action plan A-44 in light of ABLAB decision re St Lucie 2. Longer term portions of plan involve extensive use of reliability & risk assessment studies
DIRCKS, J J Office of the Executive Director for Operations 80/09/26 2pp 06845 112

--8011030311 Task action plan A-44 "Station Blackout"
* Office of Nuclear Regulatory Research, Director. 80/09/26 2pp 06845 114

8011004486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D O. Division of Licensing 80/10/01 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports." W/o encl
EISENHUT, D O. Division of Licensing. 80/10/06 6pp

8011030688 Confirms OL review schedule & const schedule as discussed in 800918 meeting & util 801003 ltr. Const completion is projected for Dec 1983.
TEDESCO, R L Division of Licensing 80/10/17 2pp. 06860:160

8011040492 Informs of compiling info re environ qualification tests of safety-related equipment in response to request in NRC 801001 ltr. Response to be provided by 801130.
UHRIG, R E. Florida Power & Light Co 80/10/31 1p 06915:300

8011210635 Notifies that review of proposed use of Ameron NUKEM 730 caulk complete. Use of matl acceptable
YOUNGBLOOD, B J. Licensing Branch 1 80/11/07 2pp 07029:283

8011260316 Ack receipt of 800613 ltr re application for transfer of ownership interest & amend to CPPR-144. Approves transfer of ownership interest & forwards amend to CP & related notice
EISENHUT, D O. Division of Licensing. 80/11/14 2pp. 07072:207

--8011260322 Amend 2 to CPPR-144, authorizing transfer of ownership to Orlando, FL Utils Commission.
EISENHUT, D O. Division of Licensing 80/11/14 2pp 07072:209.

--8011260325 Notice of issuance of Amend 2 to CPPR-144
BOURNIA, A. Licensing Branch 1. 80/11/14 2pp 07072:211.

--8011260328 Safety evaluation supporting Amend 2 to CPPR-144.
* Office of Nuclear Reactor Regulation, Director 80/11/14 4pp.
07072.213

8011210357 Forwards const/startup monthly status rept for Oct 1980.
UHRIG, R E. Florida Power & Light Co 80/11/17 2pp 07032:283

F Security, medical, emergency & fire protection plans

8011040498 Forwards security plan. Plan withheld (ref 10CFR2.790).
UHRIG, R E. Florida Power & Light Co 80/10/29 1p. 06873 066.

G. Adjudicatory correspondence

8009190299 Responds to FOIA request for 15 documents listed in bibliography to NUREG-0623, "Rept of Siting Policy Task Force." Documents 6-8 & 13 are available in PDR. Forwards remaining documents.
FELTON, J H. Division of Rules and Records 80/09/04 1p.

--8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features.
MINOGUE, R B Office of Standards Development, Director. SECY-79-362 79/06/04. 7pp

--8009190630 Requests that encl: "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards
SCINTO, J F Hearings Division 79/04/04. 16pp.

M Antitrust correspondence

8011180047 Joint motion for extension until 801119 to reply to FL Cities response to 801009 joint motion Discussions w/FL Municipal Power Agency re FL Cities objections are taking place Certificate of Svc encl
DEWEY, L B Antitrust Division URBAN, J R Justice, Dept of
BOUKNIGHT, J A Florida Power & Light Co 80/11/12 App
06987:180

8011250036 Joint motion for extension until 801203 to reply to FL Cities 801009 answer to allow for continuing discussion Certificate of Svc encl
BOUKNIGHT, J A Florida Power & Light Co. URBAN, J R Interior, Dept of DEWEY, L B Antitrust Division 80/11/19 App
07056:197

8011260016 Forwards revised language of util commitment re control provision in Section VII(1) of license conditions. Meeting to reach agreement should be scheduled during wk of 801124
DEWEY, L B Antitrust Division 80/11/21 2pp 07075 297.

Q Inspection reports, IE Bulletins & correspondence

8011130356 Forwards IE Insp Repts 50-250/80-28, 50-251/80-27, 50-335/80-28 & 50-389/80-11 on 800827-29. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/03 2pp.

--8011130368 IE Insp Repts 50-250/80-28, 50-251/80-27, 50-335/80-28 & 50-389/80-11 on 800827-29 No noncompliance noted Major areas inspected, followup of noncompliance re 10CFR21 procedures.
BROWNLEE, V. L Region 1, Philadelphia, Office of the Director. 80/10/03 2pp

R. Periodic operating reports & related correspondence

8011210357 Forwards const/startup monthly status rept for Oct 1980
UHRIO, R. E Florida Power & Light Co 80/11/17. 2pp 07032:285

S Reportable occurrences, LERs & related correspondence

801140059 Final deficiency rept originally reported on 800325 re defective hydramotor actuators for dampers & louvers. Caused by mfg from incorrect matl Dampers reworked & retested. Dampers & louvers to be tested in preoperational program
UHRIO, R. E. Florida Power & Light Co. 80/10/31. 6pp 06960 317

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05. 209pp.

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01 3pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl.
EISENHUT, D. O. Division of Licensing 80/10/06. 6pp

8011100744 Advises that Class II fee & duplicate fee required re Util 790427 & 0928 applications to extend const completion dates for CPPR-91 & CPPR-92
DIQOS, R M License Fee Management Branch 80/10/23. 1p.
06931:276.

8011040172 Requests extension of latest completion date specified in CPPR-91 to May 1982 & CPPR-92 to Feb 1983 Extension required due to addl safety-related requirements resulting from NRC review
MILLS, L. M. Tennessee Valley Authority 80/10/30. 1p. 06884:273.

8011210481 Informs that proposed deletion of high pressure blowdown tests acceptable.
TEDEBECQ, R. L. Assistant Director for Licensing. 80/11/14. 3pp.
07029:230.

F Security, medical, emergency & fire protection plans

8011030347 Forwards addl info & revisions to security personnel training & qualification plans Info withheld (ref 10CFR2 790)
MILLS, L M Tennessee Valley Authority 80/10/27 1p 06867:285.

8011060527 Forwards revised fuel storage physical security plan Supersedes 800529 plan & 800814 & 29 suppl Plan withheld (ref 10CFR2 790)
MILLS, L M Tennessee Valley Authority 80/10/31 1p 06912:287

G Inspection reports, IE Bulletins & correspondence

8011040054 Forwards IE Insp Repts 50-390/80-27 & 50-391/80-21 on 800818-20 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/23 2pp 06884 283

--8011040060 IE Insp Repts 50-390/80-27 & 50-391/80-21 on 800818-20 No noncompliance noted Major areas inspected diesel generator bldg, const activities in auxiliary bldg & GA audits.
THOMAS, M Region 2, Atlanta, Office of the Director, CANTRELL, F B Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/23 5pp 06884:285

8011040553 Forwards IE Insp Rept 50-390/80-28 on 800826. No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/23 2pp 06875 144

--8011040558 IE Insp Rept 50-390/80-28 on 800826. No noncompliance noted. Major areas inspected observation & document review of ultrasonic testing for subcladding cracks in reactor vessel nozzle bores
ECANO, HOS, N Region 2, Atlanta, Office of the Director. HERDT, A R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/22 3pp. 06875:146.

8011100699 Forwards response to IE Bulletin 79-04, "Incorrect Heights for Swing Check Valves Mfg by Velan Engineering Corp." Info constitutes final deficiency rept re Velan valves Corrected valve weights do not create overstressing in pipes
MILLS, L M Tennessee Valley Authority. 80/10/20. 8pp 06947:343.

8011170687 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/10/24. 1p.

8011210124 Ack receipt of 800911 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/80-19 & 50-391/80-13
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/03 1p. 07037 093

--8011210134 Responds to NRC 801014 ltr re violations noted in IE Insp Repts 50-390/80-19 & 50-391/80-13 Revised corrective actions, nondestructive examiner retrained in proper acceptance criteria for liquid penetrant insps.
MILLS, L M Tennessee Valley Authority 80/10/23. 2pp 07037 096

--8011210144 Suppls response to NRC 801014 ltr re violations noted in IE Insp Repts 50-390/80-19 & 50-391/80-13. Revised corrective actions, nondestructive examiner retrained in proper acceptance criteria for liquid penetrant insps
MILLS, L. M Tennessee Valley Authority. 80/10/14. 2pp 07037.098

--8011210161 Responds to NRC 800820 ltr re violations noted in IE Insp Repts 50-390/80-19 & 50-391/80-13 Corrective actions: QC Procedure 4 13 being revised to require insp of one inch on both sides of weld
MILLS, L. M Tennessee Valley Authority. 80/09/11. 5pp. 07037.100.

--8011210169 Forwards IE Insp Repts 50-390/80-19 & 50-391/80-13 on 800630-0703 & notice of violation
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/20. 2pp. 07037:105.

--8011210173 Notice of violation from insp on 800630-0703.
* Region 2, Atlanta, Office of the Director. 80/08/19. 2pp. 07037:107

DOCKETED ITEMS

--8011210186 IE Insp Repts 50-390/80-19 & 50-391/80-13 on 800630-0703 Noncompliance noted failure to have documented instructions for control of welded joints & failure to comply w/acceptance criteria by nondestructive inspector. COLLEY, J L Region 2, Atlanta, Office of the Director HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/19 7pp 07037 109

8011210195 Ack receipt of 801021 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/80-25 & 50-391/80-19. MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/03 1p 07030.088

--8011210209 Responds to NRC 800926 ltr re violations noted in IE Insp Repts 50-390/80-25 & 50-391/80-19 Corrective actions: QC Procedure 4 23 rewritten to include addl insp items per IE Bulletin 79-02 & 79-14. MILLS, L M Tennessee Valley Authority 80/10/21 3pp 07030 089

--8011210219 Forwards IE Insp Repts 50-390/80-25 & 50-391/80-19 on 800819-21 & notice of violation MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/26 2pp 07030 092

--8011210226 Notice of violation from insp on 800819-21 * Region 2, Atlanta, Office of the Director. 80/09/26 2pp. 07030 094.

--8011210238 IE Insp Repts 50-390/80-25 & 50-391/80-19 on 800819-21 Noncompliance noted: failure to provide adequate procedures per IE Bulletin 79-02 & 79-14. HODENOB, L Region 2, Atlanta, Office of the Director HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/26 3pp 07030.096

R. Periodic operating reports & related correspondence

8011190117 Forwards "Environ Radioactivity Levels, Annual Rept 1979." MILLS, L M Tennessee Valley Authority. 80/11/12, 1p. 06997 232

--8011190122 "Environ Radioactivity Levels, Annual Rept 1979." * Tennessee Valley Authority. RM-80-8-WB1. 80/10/31 49pp 06997-233

B. Reportable occurrences, LERs & related correspondence

801110699 Forwards response to IE Bulletin 79-04, "Incorrect Weights for Sizing Check Valves Mfg by Velan Engineering Corp." Info constitutes final deficiency rept re Velan valves. Corrected valve weights do not create overstressing in pipes. MILLS, L M Tennessee Valley Authority. 80/10/20 8pp 06947.343.

8011030476 Second interim deficiency rept re damage to upper head injection piping hangers. Damaged hanger has been removed from site. Insulation stripped from pipe so examination of damage may be made. MILLS, L M Tennessee Valley Authority 80/10/24, 1p. 06872.318.

8011050454 Interim deficiency rept re surface cracks in Loop 1 steam generator. Caused by hydrogen-induced cracking. Indications near upper head girth weld removed by grinding & required nondestructive exams completed. MILLS, L M Tennessee Valley Authority 80/10/27, 1p. 06897.257

8011070429 First interim deficiency rept re seismic analysis of check valve in chemical & vol control sys. During design review, 3-inch check valve overlooked in piping analysis. Will perform re-analysis. MILLS, L M Tennessee Valley Authority 80/10/31 2pp. 06921-055.

8011070455 Fourth interim deficiency rept re QA breakdown & faulty fillet welds. Fillet weld insp & repair continued. Addl info to be provided by 810206. MILLS, L M Tennessee Valley Authority 80/10/31, 1p 06921 057

801100470 First interim deficiency rept re valve accelerations for piping analysis. Initially reported on 801002. Design criteria is being evaluated. Addl info will be submitted by 810113. MILLS, L M Tennessee Valley Authority. 80/11/03, 2pp. 06931:258.

801120378 Fifth interim deficiency rept re steam generator water level ref column error. Initially reported on 790706. Technical & contractual evaluations are being made to install microprocessors. Addl info to be submitted by 810115. MILLS, L M Tennessee Valley Authority. 80/11/03, 1p 06953:091.

801140067 Fifth interim deficiency rept originally reported on 790706 re steam generator water level ref column error. Technical & contractual evaluations being made between util & Westinghouse for installation of microprocessors. MILLS, L M Tennessee Valley Authority 80/11/03 1p 06960:323

801140049 Final deficiency rept originally reported on 801007 re auxiliary feedwater design deficiency. Mods will provide independent control power supply to auxiliary feedwater sys turbine-driven pump. MILLS, L M Tennessee Valley Authority 80/11/05, 2pp 06963.235

801190715 Part 21 rept re essential raw water cooling water pumps. Programs implemented to inspect essential raw cooling water pumps routinely for excessive damage to stud spacers or washers. Next rept will be sent by 810122. MILLS, L M Tennessee Valley Authority. 80/11/05 3pp 07001 181

801140016 Third interim deficiency rept originally reported on 800301 re safety injection sys train flow. Addl testing needed on sys for Unit 1 Train B. Addl info will be submitted by 810116. MILLS, L M Tennessee Valley Authority 80/11/06 1p 06963.226

801140011 Fifth interim deficiency rept originally reported on 790618 re Penn Ventilator QA program. Util documenting evaluation results of drawings & info supplied by Penn Ventilator. Addl info will be provided by 801219. MILLS, L M Tennessee Valley Authority. 80/11/07, 1p 06963:225

801140092 Final deficiency rept originally reported on 801010 re incorrect spec for full penetration welds for pipe supports. Affected supports redesigned & modified drawings issued. Mods to be completed by 810801 & 820105. MILLS, L M Tennessee Valley Authority 80/11/07 2pp 06960:326.

8011250305 Second interim deficiency rept re discrepancy in two MK-71 embedded plates. Reanalysis determined single studded embedded plates acceptable for plate loads. Random sampling of 20 addl embedments will be ultrasonically tested. MILLS, L M Tennessee Valley Authority 80/11/20, 1p 07055.131.

V. Operator Examinations

801140325 Forwards info describing operator training & qualification programs which comply w/criteria addressed in 800328 ltr to all power reactor applicants & licensees. MILLS, L M Tennessee Valley Authority 80/11/10 8pp.

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements. EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101. EISENHUT, D O Division of Licensing 80/10/01, 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports." W/d encl. EISENHUT, D O Division of Licensing. 80/10/06 6pp

801100264 Advises that Class II fee & duplicate fee required re util 790427 & 0928 applications to extend const completion dates for CFP-91 & CFP-92. DICKS, R M License Fee Management Branch 80/10/23 1p. 06931:276.

8011040172 Requests extension of latest completion date specified in CFP-91 to May 1982 & CFP-92 to Feb 1983. Extension required due to addl safety-related requirements resulting from NRC review. MILLS, L M Tennessee Valley Authority 80/10/30, 1p. 06884.273.

8011210481 Informs that proposed delation of high pressure blowdown tests acceptable. TEDESCO, R L Assistant Director for Licensing 80/11/14, 3pp. 07027.230

F Security, medical, emergency & fire protection plans

8011060191 Informs of approving fuel storage physical security plan submitted in 800529 ltr & as amended in 800814 & 29 ltrs. License will be amended to include license condition Plan must be fully implemented 30 days after receipt of ltr. MCCORMACK, O W Physical Security Development Branch 80/09/24 1p 06915,324.

8011030347 Forwards addl info & revisions to security personnel training & qualification plans Info withheld (ref 10CFR2 790) MILLS, L M Tennessee Valley Authority 80/10/27 1p

8011060527 Forwards revised fuel storage physical security plan Supersedes 800529 plan & 800814 & 29 suppl Plan withheld (ref 10CFR2 790) MILLS, L M Tennessee Valley Authority 80/10/31 1p 06912 257

G Inspection reports, IE Bulletins & correspondence

8011040054 Forwards IE Insp Repts 50-390/80-27 & 50-391/80-21 on 800818-20 No noncompliance noted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/23, 2pp 06884 283

--8011040060 IE Insp Repts 50-390/80-27 & 50-391/80-21 on 800818-20, No noncompliance noted Major areas inspected diesel generator bldg, const activities in auxiliary bldg & QA audits THOMAS, M Region 2, Atlanta, Office of the Director CANTRELL, F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/23 5pp. 06884 285.

801110699 Forwards response to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." Info constitutes final deficiency rept re Velan valves Corrected valve weights do not create overstressing in pipes MILLS, L M Tennessee Valley Authority 80/10/20. 5pp 06947,343.

8011170487 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required. O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24 1p.

8011210124 Ack receipt of 800911 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/80-19 & 50-391/80-13 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/03 1p 07037,095

--8011210134 Responds to NRC 801014 ltr re violations noted in IE Insp Repts 50-390/80-19 & 50-391/80-13 Revised corrective actions: nondestructive examiner instructed in proper acceptance criteria for liquid penetrant insps MILLS, L M Tennessee Valley Authority 80/10/23 2pp. 07037;096

--8011210144 Suppl response to NRC 801014 ltr re violations noted in IE Insp Repts 50-390/80-19 & 50-391/80-13 Revised corrective actions: nondestructive examiner instructed in proper acceptance criteria for liquid penetrant insps MILLS, L M Tennessee Valley Authority 80/10/14. 2pp. 07037;098.

--8011210161 Responds to NRC 800820 ltr re violations noted in IE Insp Repts 50-390/80-19 & 50-391/80-13 Corrective actions: QC Procedure 4.13 being revised to require insp of one inch on both sides of weld MILLS, L M Tennessee Valley Authority 80/09/11. 5pp. 07037-100

--8011210169 Forwards IE Insp Repts 50-390/80-19 & 50-391/80-13 on 800630-0703 & notice of violation MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/08/20. 2pp 07037 105.

--8011210173 Notice of violation from insp on 800630-0703 * Region 2, Atlanta, Office of the Director. 80/08/19. 2pp. 07037;107.

--8011210186 IE Insp Repts 50-390/80-19 & 50-391/80-13 on 800630-0703. Noncompliance noted. failure to have documented instructions for control of welded joints & failure to comply w/acceptance criteria by nondestructive inspector. COLEY, J L Region 2, Atlanta, Office of the Director. HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/08/19. 7pp. 07037 109

8011210195 Ack receipt of 801021 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/80-25 & 50-391/80-19 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/03 1p 07030 088

--8011210209 Responds to NRC 800926 ltr re violations noted in IE Insp Repts 50-390/80-25 & 50-391/80-19 Corrective actions: QC Procedure 4.23 rewritten to include addl insp items per IE Bulletins 79-02 & 79-14 MILLS, L M Tennessee Valley Authority 80/10/21 3pp 07030 089

--8011210219 Forwards IE Insp Repts 50-390/80-25 & 50-391/80-19 on 800819-21 & notice of violation MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/26 2pp 07030 092

--8011210226 Notice of violation from insp on 800819-21 * Region 2, Atlanta, Office of the Director 80/09/26 2pp 07030-094

--8011210238 IE Insp Repts 50-390/80-25 & 50-391/80-19 on 800819-21 Noncompliance noted failure to provide adequate procedures per IE Bulletins 79-02 & 79-14 MODENOS, L Region 2, Atlanta, Office of the Director HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/26 5pp 07030-096

R Periodic operating reports & related correspondence

8011190117 Forwards "Environ Radioactivity Levels, Annual Rept 1979" MILLS, L M Tennessee Valley Authority 80/11/12 1p. 06997,232

--8011190122 "Environ Radioactivity Levels, Annual Rept 1979" * Tennessee Valley Authority RH-80-B-WB1 80/10/31. 49pp 06997,233.

S Reportable occurrences, LERs & related correspondence

801110699 Forwards response to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." Info constitutes final deficiency rept re Velan valves Corrected valve weights do not create overstressing in pipes MILLS, L M Tennessee Valley Authority 80/10/20 5pp

8011030476 Second interim deficiency rept re damage to upper head injection piping hangers Damaged hanger has been removed from site Insulation stripped from pipe so examination of damage may be made. MILLS, L M Tennessee Valley Authority. 80/10/24 1p. 06872-318

8011070429 First interim deficiency rept re seismic analysis of check valve in chemical & vol control sys During design review, 3-inch check valve overlooked in piping analysis Will perform re-analysis MILLS, L M Tennessee Valley Authority. 80/10/31. 2pp. 06921 055.

8011070455 Fourth interim deficiency rept re QA breakdown & faulty fillet welds. Fillet weld insp & repair continued. Addl info to be provided by 810206 MILLS, L M Tennessee Valley Authority 80/10/31 1p 06921,057.

8011100470 First interim deficiency rept re valve accelerations for piping analysis, initially reported on 801002 Design criteria is being evaluated. Addl info will be submitted by 810113. MILLS, L M Tennessee Valley Authority. 80/11/03 2pp 06931 258

801120378 Fifth interim deficiency rept re steam generator water level ref column error, initially reported on 790706 Technical & contractual evaluations are being made to install microprocessors Addl info to be submitted by 810115 MILLS, L M Tennessee Valley Authority. 80/11/03 1p 06933-091

801140067 Fifth interim deficiency rept originally reported on 790706 re steam generator water level ref column error Technical & contractual evaluations being made between util & Westinghouse for installation of microprocessors. MILLS, L M Tennessee Valley Authority 80/11/03 1p 06960 323

801140049 Final deficiency rept originally reported on 801007 re auxiliary feedwater design deficiency Mods will provide independent control power supply to auxiliary feedwater sys turbine-driven pump MILLS, L M Tennessee Valley Authority 80/11/05 2pp. 06963 235.

DOCKETED ITEMS

8011190715 Part 21 rept re essential raw water cooling water pumps
Programs implemented to inspect essential raw cooling water
pumps routinely for excessive damage to stud spacers or
washers Next rept will be sent by 810122
MILLS, L. H. Tennessee Valley Authority 80/11/05. 3pp 07001 181

8011140016 Third interim deficiency rept originally reported on 800501
re safety injection sys train flow Addl testing needed on
sys for Unit 1 Train B Addl info will be submitted by
810116
MILLS, L. H. Tennessee Valley Authority 80/11/06 1p 06963 226.

8011140011 Fifth interim deficiency rept originally reported on 790618
re Penn Ventilator GA program Util documenting evaluation
results of drawings & info supplied by Penn Ventilator Addl
info will be provided by 801219
MILLS, L. H. Tennessee Valley Authority 80/11/07 1p 06963:225

8011140092 Final deficiency rept originally reported on 801010 re
incorrect spec for full penetration welds for pipe supports
Affected supports redesigned & modified drawings issued. Mods
to be completed by 810801 & 820105
MILLS, L. H. Tennessee Valley Authority 80/11/07 2pp 06960 326

8011250305 Second interim deficiency rept re discrepancy in two MK-71
embedded plates Reanalysis determined single studded
embedded plates acceptable for plate loads Random sampling
of 20 addl embedments will be ultrasonically tested
MILLS, L. H. Tennessee Valley Authority 80/11/20 1p 07055. 151

V Operator Examinations

8011140325 Forwards info describing operator training & qualification
programs which comply w/criteria addressed in 800328 ltr
to all power reactor applicants & licensees
MILLS, L. H. Tennessee Valley Authority 80/11/10 8pp

DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of THI action
plan requirements Provides summary listing of all approved
THI-2 related requirements
EISENHUT, D. O. Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs info needed by 801101.
EISENHUT, D. O. Division of Licensing 80/10/01 5pp

8011100937 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports " H/a encl
EISENHUT, D. O. Division of Licensing 80/10/06 6pp

8011060094 Notification of 801118 meeting w/util & LAGL in Bethesda, MD
to review applicant position & supporting info re reservoir
induced seismicity
KANE, H. F. Licensing Branch 2 80/10/17 3pp 06912.337

8011060226 Summary of 801009 meeting w/util re review & resolution of
util proposed mods to STS in Section 6 re administrative
controls
KANE, H. F. Licensing Branch 2 80/10/17 4pp. 06912 322

8011030404 Advises that recipient 801087 memo will be placed in docket
file to clarify 800925 summary of 800910 meeting
SCHWENGER, A. Operating Reactors Branch 1 80/10/21. 2pp.
06978.163

--8011050405 Protests misquote in recipient 800925 summary of 800910
meeting. Subj discussed was heat removal not core cooling
equipment
KNIGHT, J. P. Division of Engineering. 80/10/07 1p. 06998.165.

8011030600 Notification of 801106-07 meeting w/util in Jenkinsville, SC
to discuss const progress & scheduling
KANE, H. Standardization & Special Projects Branch. 80/10/23. 3pp.
06960.092

8011030494 Forwards "Starting & Load Acceptance Reliability Test
710806-10," final rept & "Farley 2 200 Cycles Start Test,"
in response to NRC open items on diesel generator
qualification Encl available in Central Files
NICHOLS, T. C. South Carolina Electric & Gas Co 80/10/28 7pp
02319 196

8011170439 Forwards Requests 321 14-16 for addl info needed to complete
review of THI matters Responses should be submitted by
801107.
TEDESCO, R. L. Assistant Director for Licensing 80/10/28 5pp.
06977.324

8011170774 Forwards request for addl info re 10 remaining open issues
in review of OL Responses should be provided by 801031
TEDESCO, R. L. Assistant Director for Licensing 80/10/28 10pp
06973 349

8011040268 Forwards addl calculations to show conformance in using fuel
rod models presented in NUREG-0630, "Fuel Clad Swelling &
Rupture Models for LOCA Analysis," in response to NRC 800826
request info is sufficient to resolve open items
NICHOLS, T. C. South Carolina Electric & Gas Co 80/10/29 6pp
06973 145

8011040274 Forwards responses to Reactor Sys Branch questions resulting
from 801008 meeting in Bethesda, MD Responses will be
incorporated in next FBAR amend Includes info re
overpressurization of reactor vessel at low temp pressure.
NICHOLS, T. C. South Carolina Electric & Gas Co 80/10/30 20pp
06973 151.

8011070161 Notification of 801112-14 meeting w/util in Jenkinsville, SC
to discuss safe shutdown sys, field audit results of
redundant class IE equipment & other SER open items
KANE, H. Licensing Branch 2 80/10/30 5pp 06920 281

8011060439 Responds to NRC 801023 ltr re augmented low power startup
test program requirements Program will consist of natural
circulation demonstration tests similar to those at
Sequoyah Chapter 14 of FBAR will be modified
NICHOLS, T. C. South Carolina Electric & Gas Co 80/10/31 3pp
06910 228.

8011003357 Submits info re control rod guide tube support pins, per
800530 request Info on level measurement & steam
generator mods will be submitted at later date
NICHOLS, T. C. South Carolina Electric & Gas Co 80/11/03 2pp
06930 340

8011100371 Forwards Revision 1, "Emergency Feedwater Sys Reliability
Assessment"
NICHOLS, T. C. South Carolina Electric & Gas Co. 80/11/05 1p
06928 089

--8011100376 "Emergency Feedwater Sys Reliability Assessment," Revision
1
* Gilbert/Commonwealth Cos 80/10/31 134pp 06928 089

8011130206 Forwards addl info re THI concerns of Effluent Treatment
Sys Branch, in response to NRC 801028 ltr request Info will
be incorporated into next FBAR amend
NICHOLS, T. C. South Carolina Electric & Gas Co 80/11/06 11pp.
06958:278.

8011120466 Submits environ qualification of safety-related equipment
used at Facility & scheduled for testing within next two
yrs per 801001 request
NICHOLS, T. C. South Carolina Electric & Gas Co. 80/11/10. 2pp
06952:123

8011260326 Forwards Human Factors Engineering Branch control room
design review/audit Deficiencies included difficulty in
locating specific controls, clusters of controls had no
demarcation Response required
TEDESCO, R. L. Assistant Director for Licensing 80/11/10 19pp.
07075.085.

8011200275 Forwards "Program Plan/Human Factors Engineering Evaluation
& Improvement of Virgil C Summer Station Control Room"
NICHOLS, T. C. South Carolina Electric & Gas Co. 80/11/12. 1p.
07021:319.

--8011200279 "Program Plan/Human Factors Engineering Evaluation &
Improvement of Virgil C Summer Station Control Room"
* South Carolina Electric & Gas Co 80/11/10 89pp 07021:320

DOCKETED ITEMS

201

8011210465 Forwards emergency operating procedures re safety injection actuation, reactor trip, natural circulation & inadequate core cooling Procedures incorporate NRC & PNWL comments Electrical loads on 480-volt buses (SR1B1 & 3C1 encl) NICHOLS, T C South Carolina Electric & Gas Co 80/11/14 4pp 07031 214

--8011210466 Emergency Operating Procedure EOP-1, Revision 1, "Safety Injection Actuation " * South Carolina Electric & Gas Co EOP-1 R1 80/10/14 67pp 07031 218

--8011210467 Emergency Operating Procedures EOP-5, Revision 2, "Reactor Trip " * South Carolina Electric & Gas Co EOP-5R2 80/10/06 9pp 07031 285

--8011210468 Emergency Operating Procedure EOP-13, "Natural Circulation " * South Carolina Electric & Gas Co EOP-13 80/10/09 10pp 07031 294

--8011210469 Emergency Operating Procedure EOP-14, "Inadequate Core Cooling " * South Carolina Electric & Gas Co EOP-14 80/11/10 6pp 07031 304

8011210503 Forwards lists of facility compliance w/10CFR20, 10CFR50 & 10CFR100 per RL Tedesco 801027 request NICHOLS, T C South Carolina Electric & Gas Co 80/11/14 25pp. 07031:322

8011260746 Notification of 801119 meeting w/util in Bethesda, MD to review responses to NRC questions on settlement of certain safety-related structures & actions required to resolve open items. KANE, W Licensing Branch 2 80/11/17 2pp 07071.362

8011260196 Forwards addl info re leak tight integrity of primary coolant pressure isolation valves, per NRC 801027 request Four P&ID oversize drawings encl NICHOLS, T C South Carolina Electric & Gas Co 80/11/20 3pp 07076:003

--8011260198 "RHR Sys, Flow Diagram " * Westinghouse Electric Corp 79/11/06 1p.

--8011260200 "Safety Injection Sys, Flow Diagram " Sheet 3 of 3 * Westinghouse Electric Corp 79/11/06 1p

--8011260204 "Safety Injection Sys, Flow Diagram " Sheet 1 of 3 * Westinghouse Electric Corp 79/11/06 1p

--8011260207 "Safety Injection Sys, Flow Diagram " Sheet 2 of 3 * Westinghouse Electric Corp 79/11/06 1p

8011260092 Forwards list of shielding mods being incorporated in plant design Completion of mods will be made prior to issuance of OL or by 820101 NICHOLS, T C South Carolina Electric & Gas Co 80/11/21 2pp 07071 323

D NRC Draft/Final Environmental Statements, suppl & correspondence

8011260318 Forwards suppl to DES for facility (NUREG-0534) & notice of availability R/o DES SCHWENGER, A Licensing Branch 2 80/11/06. 3pp. 01741:019

--8011260321 Notice of availability of suppl to DES for facility (NUREG-0534) SCHWENGER, A. Licensing Branch 2 80/11/06. 2pp. 01741 019

801130319 Forwards suppl to DES, NUREG-0534, addressing accident consideration. GOLDBERG, S C Hearing Branch 2 80/11/10. 1p 06957:267.

--801130325 DES suppl re proposed facility operation * Office of Nuclear Reactor Regulation, Director. NUREG-0534 SUPP. 80/11/30. 44pp 06957:268

8011260107 Forwards DES suppl re accident considerations. Draft will be published in FR for comments from federal, state & local agencies before preparation of FES N/o encl SCHWENGER, A Licensing Branch 2 80/11/10 1p 07080.093

801140344 Forwards comments from DA Rayer State of SC Wildlife & Marine Resources Dept. re draft environ statement for facility, per 790817 ltr NICHOLS, T C South Carolina Public Service Authority. 80/11/12 3pp 06960.344

801180546 Determines that EIS received on 801107 meets requirements of Section 1506 9 of CEQ regulations FR publication of availability scheduled for 801114 Public review period will terminate on 801229 WILSON, K L Environmental Protection Agency 80/11/12 1p 06988 317

F Security, medical, emergency & fire protection plans

801130103 Forwards emergency planning info for housing in Columbia, SC LPDR Documents should be placed in conspicuous area of library for easy accessibility, due to anticipated public interest BOUDER, J. L. Division of Rules and Records 80/10/23. 1p 06956 353

801190278 Summary of 801006-07 meeting w/util at facility re security plan KANE, W F. Licensing Branch 2 80/10/23 4pp. 06996 262.

8011040221 Forwards Amend 3 to physical security plan Amend 3 withheld (re 10CFR2 790) NICHOLS, T C South Carolina Electric & Gas Co 80/10/29 1p 06974 046

O Adjudicatory correspondence

8011050188 Notice of 801211 third prehearing conference in Columbia, SC re pending matters & further scheduling. GROSSMAN, H Atomic Safety and Licensing Board Panel. 80/10/31. 1p 02319.196

801100252 Forwards ASLB 780424 prehearing conference order re admitted contentions & SC Goldberg 800806 ltr re procedural assistance in adjudicatory licensing proceedings Suggests Mar 1981 for hearing. Will participate in settlement GOLDBERG, S C Hearing Branch 2. 80/11/04. 2pp. 06916:001

--8011100261 Order admitting contentions Discovery shall commence on 780505 & be completed on 780915 Motions for summary disposition must be served on 781003 & answered by 781013 Motions re order must be served on 780802 SMITH, I W. Atomic Safety and Licensing Board Panel. 78/04/24 16pp 06916:001

801140528 Notice rescheduling 801211 third prehearing conference for 801125 in Columbia, SC re pending matters Public invited w/o limited appearances GROSSMAN, H. Atomic Safety and Licensing Board Panel. 80/11/10. 1p. 06963:140

8011210279 Forwards applicant 801119 statement re matters for consideration at third prehearing conference Licensees will move to truncate appellate review should need arise. KNOTTS, J B Debevoise & Liberman 80/11/19 1p 07035:040.

--8011210285 Statement re matters for consideration at third prehearing conference. Licensees will move for expedited schedule leading to initial decision in advance of fuel loading Certificate of SVC encl. KNOTTS, J B. South Carolina Electric & Gas Co KNOTTS, J B. Debevoise & Liberman 80/11/19 9pp 07035 041.

H. General correspondence

801180699 Informs that WA Williams will replace HF Babb as general manager of nuclear operations, effective 801216 Internal memo encl NICHOLS, T. C. South Carolina Electric & Gas Co. 80/11/13 2pp. 06991.291.

K Utility Final Safety Analysis Report (FSAR) & amends

801180122 Forwards Amend 22 to FSAR NICHOLS, T C. South Carolina Electric & Gas Co. 80/11/17. 2pp. 06986:125

--801180126 Amend 22 to FSAR. * South Carolina Electric & Gas Co 80/11/17 400pp. 06986 127.

DOCKETED ITEMS

M Antitrust correspondence

8011040407 Forwards power sys coordination & integration agreement between SC Public Bv Authority & Central Electric Power Cooperative, Inc DOJ criteria re determination of significant change addressed
MORRIS, H P Cahill, Gordon & Reindel 80/10/28 135pp
06883 283

8011040415 Order advising that only part of util 801028 ltr re update on Santee Cooper & Central Electric Power Cooperative negotiation status will be considered Comment & argument on DOJ 801010 response will be disregarded
CHILK, S J Office of the Secretary of the Commission 80/10/31
2pp 06873 270

8011140501 Motion for order permitting discovery to be limited to DOJ stated facts Commission rules contemplates discovery use to resolve controversy over disputed questions of fact but only after factual matters in dispute resolved & found relevant
BRAND, W E Central Electric Power Cooperative, Inc BRAND, W E, Brand & Hall 80/11/07 7pp 06963 074

--8011140507 Request for production of documents directed to applicants, re imposition of territorial restrictions, refusal to negotiate for power exchange & coordinated development of base load generating unit Certificate of Svc encl
BRAND, W E Central Electric Power Cooperative, Inc BRAND, W E Brand & Hall 80/11/07 8pp 06963 081

8011140534 Advises that Central Electric Power Cooperative 801107 motion to conduct limited discovery is held in abeyance No answers are required until further order is issued
CHILK, S J Office of the Secretary of the Commission 80/11/10, 1p 06962 001

8011250596 Notice of appearance in proceeding.
MCGLATHLIN, C H South Carolina Public Service Authority 80/11/17
1p 07069 006

P Operating license stage documents & correspondence

8011060151 Notification of 801103-06 meeting w/util & SMHL in Zion, IL to discuss & run emergency procedures on Zion simulator
KANE, W F Operating Reactors Branch 2 80/10/16 3pp 06912 332

Q Inspection reports, IE Bulletins & correspondence

8011040541 Forwards IE Insp Rept 50-395/80-24 on 800825-29 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/23 2pp 06877:297

--8011040548 IE Insp Rept 50-395/80-24 on 800825-29, No noncompliance noted Major areas inspected preoperational test procedure, thermal expansion testing & procedure results
FORD, E J Region 2, Atlanta, Office of the Director QUICK, D R Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/22 3pp 06877 299

8011030747 Forwards IE Investigation Rept 50-395/79-42 on 791119-800807 No noncompliance noted
LONG, F J Region 2, Atlanta, Office of the Director. 80/09/26
2pp 06860 133

--8011030753 IE Investigation Rept 50-395/79-42 on 791119-800807, No noncompliance noted Major areas inspected allegations re 1975-76 intentional acts of substandard concrete const & welding
MARSH, R J, LONG, F. J. Region 2, Atlanta, Office of the Director. 80/09/23 13pp 06860 135

8011260346 Forwards IE Insp Rept 50-395/80-28 on 800923-25, No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/10 2pp 07072 276

-8011260352 IE Insp Rept 50-395/80-28 on 800923-25 No noncompliance noted Major areas inspected licensee action on previous insp findings, review of quality records & safety-related structures
RAUSCH, J K Region 2, Atlanta, Office of the Director
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/09 4pp 07072:278.

011060070 Summary of 801009 meeting w/util re preservice insp program
KANE, W F. Licensing Branch 2 80/10/17 4pp 06912 352.

8011060464 Responds to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation"
No mods proposed as result of review IE Circular 79-02 was reviewed again re power supply inverters
NICHOLS, T C South Carolina Electric & Gas Co 80/10/31 2pp
06914:360

8011210647 Ack receipt of 801003 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/80-20
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/10 1p 07029 287

--8011210663 Responds to NRC 800904 ltr re violations noted in IE Insp Repts 50-395/80-20 & 50-395/80-21 Corrective actions specific steps to ascertain adequacy of joint taken
NICHOLS, T C South Carolina Electric & Gas Co 80/10/03 2pp
07029 288

--8011210668 Forwards IE Insp Rept 50-395/80-20 on 800805-08 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/04 2pp 07029 290

--8011210673 Notice of violation from insp on 800805-08, * Region 2, Atlanta, Office of the Director 80/09/03 1p.
07029 292

--8011210680 IE Insp Rept 50-395/80-20 on 800805-08 Noncompliance noted fit-up condition not in accordance w/requirements of OAI
Drawing G-301-002 found for Weld FW-14 on 180 CC-25 in component cooling sys
KLEINSORGE, W P. Region 2, Atlanta, Office of the Director.
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/03, 6pp 07029 293

S Reportable occurrences, LERs & related correspondence

8011050479 Provides info re problem w/piping penetration assemblies
Damaged bellow found during testing of reactor bldg
penetrations Bellow will be replaced, Assembly will be purchased from Pathway Bellows
NICHOLS, T C South Carolina Electric & Gas Co 80/10/31. 2pp
06879 044

8011180549 Final deficiency rept originally submitted 801010, re parts on safety-related hanger installation sys Caused by failure to install & verify traceability on coded parts Nonsafety-related parts have been placed in controlled storage area
NICHOLS, T C. South Carolina Electric & Gas Co 80/11/11 3pp
06988 318

8011240329 Final deficiency rept re ASME code pipe radiographs, initially reported on 790312 All accepted safety-related radiographic film packets reviewed Reshots taken using more sensitive film, Weld discrepancies are being repaired
NICHOLS, T C South Carolina Electric & Gas Co 80/11/12 3pp
07046 021.

8011240333 Final deficiency rept re welded Hilti bolts initially reported on 790927 All bolts, have been reinspected & will be accepted as is or replaced Procedures have been revised to provide more QC coverage during installation
NICHOLS, T C. South Carolina Electric & Gas Co 80/11/14 3pp.
07046 324

V Operator Examinations

8011060068 Advises of augmented low power startup test program requirements Test 8 may be deleted if operator training includes simulation of event on simulator using Westinghouse & TVA test data Test 9B may be modified
TEDESCO, R L Assistant Director for Licensing 80/10/23 2pp
06916 182

8011040569 Responds to NRC request for addl info re operator training as it applies to TMI concerns Plans for operator training & qualification upgrading, administration of training programs & scope & criteria for licensing exams outlined
NICHOLS, T C South Carolina Electric & Gas Co 80/10/28. 7pp
06873. 074

8011070264 Forwards "Summary of Experience & Education for SC Electric & Gas Co NRC License Candidates," & summary of operator training program, in response to NUREG-0694, Item I A 2.1.
Paragraph 1 Repts available in Central Files only
NICHOLS, T C. South Carolina Electric & Gas Co 80/10/31. 3pp.
06919. 268.

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8010270291 Summarizes recent finding of possible capable fault on Cable Mountain, WA
TUSTUB, P. S. Geosciences Branch 80/09/02 2pp 03661 200

801050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports" W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

801030519 Notification of 801021 significant licensee meeting w/util in Walnut Creek, CA for licensee to provide info re restart of const installation activities at facility
* Region 3, San Francisco, Office of the Director. 80/10/17 1p.
06872:360.

801050555 Forwards request for addl info re emergency procedure guidelines Schedule must be submitted by 801027. GE 800630 guidelines acceptable for trial implementation. Training program must account for possible mod
EISENHUT, D. O. Division of Licensing 80/10/21. 8pp.

8011060300 Notification of 801024 meeting w/Burns & Roe in Bethesda, MD to discuss seismic qualification of electrical cabinets w/rigid conduit attached & tests performed by Hyle Labs.
JORDAN, E. L. Division of Reactor Operations Inspections 80/10/22. 2pp 06911:290.

8011140323 Requests info re steel containment at facility in support of TMI action plan Task II-B
YOUNGBLOOD, B. J. Licensing Branch 1. 80/10/30 2pp 06962 339

801170377 Forwards sections of FSAR & plant design assessment rept for safety relief valves & LOCA loads to assist in understanding nature of hydrodynamic loading phenomenon in Mark II containments & use in facility buckling analysis W/o encl
FREDENBURG, E. A. Washington Public Power Supply System 80/11/06 1p 06976:270.

8011070444 Informs that info requested in NRC 800731 ltr re environ qualification of safety-related equipment will be submitted by 801201.
RENBORG, D L. Washington Public Power Supply System 80/11/07. 1p. 06919:193.

801190654 Forwards request for addl info for Reactor Sys Branch facility review re FSAR items
TEDESCO, R L. Assistant Director for Licensing. 80/11/10. 25pp 07001:252.

8011210652 Forwards Suppl 1 to NUREG-0487, "Mark II Containment Lead Plant Program Load Evaluation & Acceptance Criteria..." Deviations, along w/basis for deviations, are to be documented in design assessment rept during review of FSAR
YOUNGBLOOD, B. J. Licensing Branch 1 80/11/10 2pp. 07036:009.

--8011210675 Suppl 1 to "Mark II Containment Lead Plant Program Load Evaluation & Acceptance Criteria Generic Technical Activities A-B & A-39"
ANDERSON, C. Generic Issues Branch. NUREG-0487 B1 80/09/30 72pp. Available at NTIS. 07036:011.

801190344 Requests 801216 meeting w/NRC to discuss geology issues raised during NRC 801016-17 site visit. List of attendees requested.
BOUCHEY, G. D. Washington Public Power Supply System. 80/11/12 1p. 06999:356.

D Inspection reports, IE Bulletins & correspondence

8011060773 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting" No written response required
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 80/10/10 1p 06909 083

801130329 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required.
ENGELKEN, R H Region 3, San Francisco, Office of the Director 80/10/24 1p 06958 078

8011280093 Withdraws 780427 commitment re IE Bulletin 78-04, "Environ Qualification of Certain Stem Mounted Switches Inside Reactor Containment" Analysis revealed that NAMCO Type D2400X switch does not perform safety-related function
RENBORG, D L. Washington Public Power Supply System 80/10/30 1p 07083 245

801170649 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators" No written response required
ENGELKEN, R H Region 3, San Francisco, Office of the Director 80/10/31 1p 06976:262

801170756 Forwards amends to 800617 notices of violation & proposed imposition of civil penalties, in response to util 800711 & 800812 ltrs Responses to original items of noncompliance may be incorporated in response to amended notices
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/11/06 2pp. 06978 273

--801170238 Amended notice of violation from investigation on 791127-800228.
* Office of Inspection & Enforcement, Office of the Director 80/11/06 5pp. 06978 275

--801170263 Amended notice of proposed imposition of civil penalties, reducing amount to \$59,500
* Office of Inspection & Enforcement, Office of the Director. 80/11/06 1p 06978 280

B Reportable occurrences, LERs & related correspondence

8011050433 Deficiency rept re Limitorque dc valve operators w/Class B insulation not qualified to IEEE 382 Caused by failure of Reliance Electric Co to impose matls control on sub-suppliers for dc motors. Defective operator will be replaced
RENBORG, D L. Washington Public Power Supply System. 80/10/30 2pp. 06899 022.

801140332 EN-80-021A on 801106, amended notice of violation & notice of proposed imposition of civil penalties of \$59,500 issued based on QA program deficiencies
HENDERSON, J. B. THORNBURG, H D Office of Inspection & Enforcement, Office of the Director 80/11/06 1p. 06965:205

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D. O. Division of Licensing 80/09/05. 209pp.

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D. O. Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports." W/o encl
EISENHUT, D O Division of Licensing 80/10/06. 6pp.

8011070436 Forwards specific data on environ qualification testing of safety-related equipment to be performed within next two yrs.
MCUFFIE, M A. Carolina Power & Light Co 80/11/03 5pp. 06925:003.

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

801130172 Ack receipt of 801023 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/29 1p 06959 122

--801130179 Suppls 800924 ltr re violation noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15
Corrective actions roads will be watered as necessary to provide adequate dust control
HONE, P W Carolina Power & Light Co. 80/10/23 1p. 06959 123.

--801130187 Ack receipt of 800924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15 Requests addl info
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/10/28 1p 06959 124

--801130196 Responds to NRC 800903 ltr re violations noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15
Corrective actions roads will be watered once per day to keep dust levels down
HONE, P W Carolina Power & Light Co 80/09/24 2pp 06959 123

--801130201 Ack receipt of IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15 on 800714-16 No proprietary info
HONE, P W Carolina Power & Light Co 80/09/15 1p. 06959 127

--801130207 Forwards IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15 on 800714-16 & notice of violations.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/09/05, 2pp 06959 128.

--801130215 Notice of violation from insp on 800714-16.
+ Region 2, Atlanta, Office of the Director 80/08/29 1p. 06959 130

--801130223 IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15 on 800714-16 Noncompliance noted excessive vehicular road dust due to infrequent waterings.
CUNNINGHAM, A L Region 2, Atlanta, Office of the Director
JENKINS, G R Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/08/29 3pp 06959 131

8011280143 Requests extension for response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment," to accommodate extensive revisions & expansion of scope.
UTLEY, E E Carolina Power & Light Co 80/10/30 2pp 07083 282.

801140431 Forwards position re variances w/ANSI N45.2.2 per IE insp on 800428-0502 Position meets overall intent of prescribed QA. Util will continue current practices pending branch review.
MC DUFFIE, M A Carolina Power & Light Co 80/11/10 6pp 06964 334

I. Reportable occurrences, LERs & related correspondence

01070413 Interim deficiency rept re 800903 discovery of unclear & incorrect weld symbols on Bergen-Patterson seismic Class 1 pipe hanger drawings. Caused by design drawings reaching field w/o corrections. Corrections will be made by 810301
CHIANG, N J Carolina Power & Light Co. 80/11/03 5pp. 06924 351.

011240365 Interim deficiency rept re procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Submittal of final rept delayed until 810119, pending completion of investigation
CHIANG, N J Carolina Power & Light Co. 80/11/14. 1p. 07045 345.

011240388 Interim deficiency rept re omission of protective coating & existence of damaged coating on containment liner, initially reported on 800917. Application of final coat of paint w/repairs to damaged areas & final rept expected by 810301.
CHIANG, N J Carolina Power & Light Co. 80/11/14. 2pp. 07049 054.

Operator Examinations

11070460 Informs that planned staffing levels described in FSAR are consistent w/interim criteria provided in 800731 ltr. Administrative procedures will be implemented prior to fuel loading.
MC DUFFIE, M A Carolina Power & Light Co. 80/11/03 1p. 06924 362.

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing. 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" w/o encl.
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011070436 Forwards specific data on environ qualification testing of safety-related equipment to be performed within next two yrs.
MC DUFFIE, M A Carolina Power & Light Co 80/11/03 5pp 06925 003

G Inspection reports, IE Bulletins & correspondence

801130172 Ack receipt of 801023 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/29 1p 06959 122.

--801130179 Suppls 800924 ltr re violation noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15.
Corrective actions roads will be watered as necessary to provide adequate dust control
HONE, P W Carolina Power & Light Co. 80/10/23 1p. 06959 123.

--801130187 Ack receipt of 800924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15. Requests addl info.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/28 1p 06959 124

--801130196 Responds to NRC 800903 ltr re violations noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15.
Corrective actions roads will be watered once per day to keep dust levels down
HONE, P W Carolina Power & Light Co. 80/09/24. 2pp 06959 123.

--801130201 Ack receipt of IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15 on 800714-16. No proprietary info.
HONE, P W Carolina Power & Light Co. 80/09/15. 1p 06959 127

--801130207 Forwards IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15 on 800714-16 & notice of violations.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/09/05. 2pp. 06959 128

--801130215 Notice of violation from insp on 800714-16
+ Region 2, Atlanta, Office of the Director 80/08/29. 1p. 06959 130.

--801130223 IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15 on 800714-16 Noncompliance noted excessive vehicular road dust due to infrequent waterings.
CUNNINGHAM, A L Region 2, Atlanta, Office of the Director.
JENKINS, G R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/08/29. 3pp 06959 131.

8011280143 Requests extension for response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment," to accommodate extensive revisions & expansion of scope.
UTLEY, E E Carolina Power & Light Co. 80/10/30. 2pp.

801140431 Forwards position re variances w/ANSI N45.2.2 per IE insp on 800428-0502. Position meets overall intent of prescribed QA. Util will continue current practices pending branch review.
MC DUFFIE, M A Carolina Power & Light Co. 80/11/10 6pp. 06964 334.

B Reportable occurrences, LERs & related correspondence

8011070413 Interim deficiency rept re 800903 discovery of unclear & incorrect weld symbols on Bergen-Patterson seismic Class 1 pipe hanger drawings. Caused by design drawings reaching field w/o corrections. Corrections will be made by 810501 CHIANQI, N. J. Carolina Power & Light Co 80/11/03 5pp. 06924 351

8011240365 Interim deficiency rept re procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads. Submittal of final rept delayed until 810119, pending completion of investigation. CHIANQI, N. J. Carolina Power & Light Co 80/11/14. 1p. 07046 345

8011240388 Interim deficiency rept re omission of protective coating & existence of damaged coating on containment liner. Initially reported on 800917. Application of final coat of paint w/repairs to damaged areas & final rept expected by 810301 CHIANQI, N. J. Carolina Power & Light Co 80/11/14 2pp 07049.056

V Operator Examinations

8011070460 Informs that planned staffing levels described in FBAR are consistent w/interim criteria provided in 800731 ltr. Administrative procedures will be implemented prior to fuel loading. MCDUFFIE, M. A. Carolina Power & Light Co 80/11/03. 1p 06924.362

DOCKET 80-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3A Application/construction stage documents & correspondence

8011050384 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements. Provides summary listing of all approved TH1-2 related requirements. EISENHUT, D. O. Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101 EISENHUT, D. O. Division of Licensing. 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl. EISENHUT, D. O. Division of Licensing. 80/10/06 6pp.

8011070436 Forwards specific data on environ qualification testing of safety-related equipment to be performed within next two yrs. MCDUFFIE, M. A. Carolina Power & Light Co 80/11/03. 5pp. 06925 003.

Q Inspection reports, IE Bulletins & correspondence

8011130172 Ack receipt of 801023 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-400/80-17, 80-401/80-15, 80-402/80-15 & 80-403/80-15. STOHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/10/29 1p 06959:122.

--8011130179 Suppl 800724 ltr re violation noted in IE Insp Repts 80-400/80-17, 80-401/80-15, 80-402/80-15 & 80-403/80-15. Corrective actions: roads will be watered as necessary to provide adequate dust control. HOWE, P. W. Carolina Power & Light Co 80/10/23. 1p. 06959:123.

--8011130187 Ack receipt of 800924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-400/80-17, 80-401/80-15, 80-402/80-15 & 80-403/80-15. Requests addl info. STOHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/10/28 1p. 06959:124.

--8011130196 Responds to NRC 800905 ltr re violations noted in IE Insp Repts 80-400/80-17, 80-401/80-15, 80-402/80-15 & 80-403/80-15. Corrective actions: roads will be watered once per day to keep dust levels down. HOWE, P. W. Carolina Power & Light Co. 80/09/24. 2pp. 06959:125.

--8011130201 Ack receipt of IE Insp Repts 80-400/80-17, 80-401/80-15, 80-402/80-15 & 80-403/80-15 on 800714-16. No proprietary info. HOWE, P. W. Carolina Power & Light Co. 80/09/15 1p. 06959:127.

--8011130207 Forwards IE Insp Repts 80-400/80-17, 80-401/80-15, 80-402/80-15 & 80-403/80-15 on 800714-16 & notice of violations. STOHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/09/05 2pp 06959 128

--8011130213 Notice of violation from insp on 800714-16. # Region 2, Atlanta, Office of the Director. 80/08/29 1p. 06959:130

--8011130223 IE Insp Repts 80-400/80-17, 80-401/80-15, 80-402/80-15 & 80-403/80-15 on 800714-16. Noncompliance noted: excessive vehicular road dust due to infrequent waterings. CUMMINGS, A. L. Region 2, Atlanta, Office of the Director. JENKINS, G. R. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/08/29 3pp 06959:131

8011280143 Requests extension for response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," to accommodate extensive revisions & expansion of scope. UTLEY, E. E. Carolina Power & Light Co 80/10/30 2pp

8011140431 Forwards position re variances w/ANSI N45 2.2 per IE insp on 800423-0502. Position meets overall intent of prescribed QA. Util will continue current practices pending branch review. MCDUFFIE, M. A. Carolina Power & Light Co 80/11/10. 6pp 06964:354.

B Reportable occurrences, LERs & related correspondence

8011070413 Interim deficiency rept re 800903 discovery of unclear & incorrect weld symbols on Bergen-Patterson seismic Class 1 pipe hanger drawings. Caused by design drawings reaching field w/o corrections. Corrections will be made by 810501 CHIANQI, N. J. Carolina Power & Light Co 80/11/03 5pp. 06924-351.

8011240365 Interim deficiency rept re procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads. Submittal of final rept delayed until 810119, pending completion of investigation. CHIANQI, N. J. Carolina Power & Light Co 80/11/14 1p 07046:345

8011240388 Interim deficiency rept re omission of protective coating & existence of damaged coating on containment liner. Initially reported on 800917. Application of final coat of paint w/repairs to damaged areas & final rept expected by 810301 CHIANQI, N. J. Carolina Power & Light Co 80/11/14 2pp 07049.056

V Operator Examinations

8011070460 Informs that planned staffing levels described in FBAR are consistent w/interim criteria provided in 800731 ltr. Administrative procedures will be implemented prior to fuel loading. MCDUFFIE, M. A. Carolina Power & Light Co. 80/11/03 1p. 06924:362

DOCKET 80-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4A Application/construction stage documents & correspondence

8011050384 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements. Provides summary listing of all approved TH1-2 related requirements. EISENHUT, D. O. Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101. EISENHUT, D. O. Division of Licensing 80/10/01. 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl. EISENHUT, D. O. Division of Licensing 80/10/06. 6pp.

8011070436 Forwards specific data on environ qualification testing of safety-related equipment to be performed within next two yrs. MCDUFFIE, M. A. Carolina Power & Light Co. 80/11/03. 5pp.

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

8011130172 Act receipt of 801023 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15
STOKER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/29 1p

--8011130179 Suppl 800924 ltr re violation noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15
Corrective actions roads will be watered as necessary to provide adequate dust control
HOWE, P W Carolina Power & Light Co 80/10/23 1p

--8011130187 Act receipt of 800924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15 Requests addl info
STOKER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/28 1p

--8011130196 Responds to NRC 800905 ltr re violations noted in IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15
Corrective actions roads will be watered once per day to keep dust levels down
HOWE, P W Carolina Power & Light Co 80/09/24 2pp

--8011130201 Act receipt of IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15 on 800714-16 No proprietary info.
HOWE, P W Carolina Power & Light Co 80/09/15 1p.

--8011130207 Forwards IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15 on 800714-16 & notice of violations
STOKER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/05 2pp

--8011130215 Notice of violation from insp on 800714-16
* Region 2, Atlanta, Office of the Director 80/08/29 1p

--8011130223 IE Insp Repts 50-400/80-17, 50-401/80-15, 50-402/80-15 & 50-403/80-15 on 800714-16 Noncompliance noted: excessive vehicular road dust due to infrequent waterings
GUMMINSOHN, A L Region 2, Atlanta, Office of the Director, 80/08/29 3pp.

8011280143 Requests extension for response to IE Bulletin 79-01B, "Environment Qualification of Class IE Equipment," to accommodate extensive revisions & expansion of scope
UTLEY, E E Carolina Power & Light Co. 80/10/30. 2pp.

8011140431 Forwards position re variances w/ANSI N45 2.2 per IE insp on 800428-0502 Position meets overall intent of prescribed QA. Util will continue current practices pending branch review
MC DUFFIE, M A Carolina Power & Light Co 80/11/10 6pp.

B Reportable occurrences, LERs & related correspondence

8011070413 Interim deficiency rept re 800903 discovery of unclear & incorrect weld symbols on Bergen-Patterson seismic Class 1 pipe hanger drawings Caused by design drawings reaching field w/o corrections Corrections will be made by 810301.
CHIANOTI, N J Carolina Power & Light Co. 80/11/03 3pp

8011240345 Interim deficiency rept re procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Submittal of final rept delayed until 810119, pending completion of investigation
CHIANOTI, N J Carolina Power & Light Co 80/11/14. 1p

V Operator Examinations

8011070460 Informs that planned staffing levels described in FSAR are consistent w/interim criteria provided in 800731 ltr. Administrative procedures will be implemented prior to fuel loading
MC DUFFIE, M A Carolina Power & Light Co 80/11/03. 1p

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3A Application/construction stage documents & correspondence

8011070432 Informs of status of review for environ qualification of safety-related electrical equipment Review suspended, pending results of feasibility study for facilities
BROWN, B C. Virginia Electric & Power Co. 80/10/31. 1p. 06923:002

F Security, medical, emergency & fire protection plans

8011120593 Forwards facility emergency planning info for placement in LPDR w/o encl
BOUDER, J L Division of Rules and Records. 80/10/29 1p
06953:333

8011170138 Forwards facility emergency planning info for placement in LPDR w/o encl
BOUDER, J L Division of Rules and Records 80/10/29. 1p.
06976:315

DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4A Application/construction stage documents & correspondence

8011070452 Informs of status of review for environ qualification of safety-related electrical equipment Review suspended, pending results of feasibility study for facilities
BROWN, B C. Virginia Electric & Power Co 80/10/31 1p. 06923:002

F Security, medical, emergency & fire protection plans

8011120593 Forwards facility emergency planning info for placement in LPDR w/o encl
BOUDER, J L Division of Rules and Records. 80/10/29. 1p.

8011170138 Forwards facility emergency planning info for placement in LPDR w/o encl
BOUDER, J L Division of Rules and Records 80/10/29 1p.

DOCKET 50-407 UNIV. OF UTAH RESEARCH REACTORP Operating license stage documents & correspondence

8011100001 Forwards Amends 4 & 11 to Licenses R-126 & R-23, respectively, revising physical security plans.
MILLER, J R Standardization & Special Projects Branch 80/10/17.
3pp 06928:231.

--8011100004 Amends 4 & 11 to Licenses R-126 & R-23, respectively, revising physical security plan
MILLER, J R Standardization & Special Projects Branch. 80/10/17
4pp 06928:234

DOCKET 50-409 LA CROSSE BOILING WATER REACTORA Application/construction stage documents & correspondence

8011240359 Application to amend License DPR-43, revising valve test program & removing relief request basis forms for Valves 62-25 001 & 62-83-011 Revisions encl
LINDER, F Dairyland Power Cooperative 80/11/19. 8pp. 07046:231.

F Security, medical, emergency & fire protection plans

8011120342 Submits plans & schedules for implementation of alternate shutdown capability Disagrees w/BNL rept stating "no reasonable assurance that fire protection will allow safe shutdown" w/supporting documentation & oversize drawings
LINDER, F Dairyland Power Cooperative. 80/11/03. 28pp. 06954:011

--8011120557 "Investigation of Surface Burning Characteristics of Solid Silicone Sheet Matl, NS-1," final rept
HAFFER, C A Southwest Research Institute 80/06/13. 16pp.
06954:059.

--8011120564 "Fire Endurance Test on Penetration Seal Sys in Precast Concrete Floor."
MAPEB, C R., PEARSON, R J., BUERGIN, R O. United Engineers & Constructors, Inc (subs. of Raytheon Co.). 78/06/27. 34pp
06954:077.

8011120397 Requests that LACBWR revisions to modified/amended security plan be withheld. Latest changes in security plan do not decrease effectiveness of plan. Encls withheld (ref 10CFR2.790).
LINDER, F. Dairyland Power Cooperative 80/11/07. 2pp. 06950:328

G. Adjudicatory correspondence

8011060628 Forwards revised 800829 order for mod of license which contained incorrect refs. Revision corrects refs.
EISENHUT, D O. Division of Licensing. 80/09/19 3pp. 06915:266

DOCKETED ITEMS

207

- 801060631 Revised 800929 order for mod of license Corrects refs
EISENHUT, D G Division of Licensing 80/09/19 6pp 06919 268
- 8011240070 Forwards order for mod of License DPR-45 re environ
Qualification of safety-related electrical equipment (SEP
Topic 111-12) Revised Tech Specs also encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/24 3pp
07038, 275
- 8011240076 Order for mod of license re environ qualification of safety-
related electrical equipment Compliance w/Div of Operating
Reactors guidelines or NUREG-0588 required by 820630
Complete records must be available by 801201
EISENHUT, D G Division of Licensing 80/10/24 6pp 07038 278
- 8011240081 Revised Tech Spec pages per 801024 order for mod of license
re environ qualification of safety-related electrical
equipment
* Division of Licensing 80/10/24 3pp 07038-284
- 8011303042 Response to util interrogatories. Intervenor's have not
engaged outside parties to study liquefaction issue. Dames &
Moore studies have not conclusively shown liquefaction will
not occur. Related correspondence
MORSE, A K Consolidated Intervenor's 80/10/27 3pp. 02319 196.
- 8011303044 Response to NRC interrogatories. Util should design & install
dewatering sys capable of protecting against O 12 lateral
acceleration Driven piles increase pore pressure. Certificate
of Bvc encl.
MORSE, A K Consolidated Intervenor's 80/10/27 5pp. 02319.196
- 8011304046 Memorandum & order affirming ASLB 800110 initial decision.
LBP-80-2, authorizing issuance of license amend Retains
jurisdiction re referred ruling & NRC exception pending
further order.
BISHOP, C J Atomic Safety and Licensing Appeal Panel. 80/10/29,
6pp. 06873, 261
- 8011320080 Motion for extension until 801114 to move for summary
disposition Technical personnel unavailable for consultation
due to prior commitments Parties have no objection to
requested extension. Certificate of Bvc encl.
BURNB, S. G., CYR, K. D Rulemaking & Enforcement Division 80/11/07,
3pp 06952 153.
- 8011340521 Order granting extension until 801114 for NRC to file
motions for summary disposition
HECHHOEFER, C Atomic Safety and Licensing Board Panel 80/11/10
1p 06963:117
- 8011370096 Memorandum & order scheduling 801216 prehearing conference
& evidentiary hearing in La Crosse, WI. Oral limited
appearance statements will be taken if relevant to order to
show cause re dewatering sys
HECHHOEFER, C Atomic Safety and Licensing Board Panel 80/11/12
6pp. 06978, 093.
- 8011390028 Motion for summary disposition of liquefaction issues in
favor of util NRC safety evaluation demonstrates absence of
genuine issue of matl fact to be litigated.
GALLEN, K. P., HIEBAND, G. S. Dairyland Power Cooperative GALLEN, K. P.
Morgan, Lewis & Bockius. 80/11/14 11pp 06999, 298
- 8011390033 Statement of matl facts re absence of issues to be heard in
support of summary disposition of liquefaction issues in
favor of util Addl measures re dedicated safe shutdown sys &
injection of concrete grouting provide adequate mitigation
GALLEN, K. P., HIEBAND, G. S. Dairyland Power Cooperative.
GALLEN, K. P. Morgan, Lewis & Bockius 80/11/14 6pp, 06999:309
- 8011390036 Affidavit explaining that addl soil investigation & test
boring programs demonstrate presence of adequate assurance
that soil beneath structures will not liquefy in event of
earthquake
NATARAJA, M S Dames & Moore. 80/11/14. 5pp. 06999:315
- 8011390041 Affidavit citing addl measures presently taken to assure
adequate mitigation of liquefaction effects in event of
earthquake. Certificate of Bvc encl
PARKYN, J. D Dairyland Power Cooperative 80/11/14. 4pp.
06999:320.
- 8011390144 Motion for affirmative summary disposition of issue re
stability of dense soils if adjacent soils undergo
liquefaction No genuine issue raised re boring program &
safety evaluation.
BURNB, S. G., CYR, K. D. Rulemaking & Enforcement Division. 80/11/14.
13pp. 06998:161
- 8011390152 Affidavit in support of NRC motion for affirmative summary
disposition of liquefaction issue Soil under pile-supported
structures is safe in event of earthquake W/prof
qualifications, supporting document & Certificate of Bvc
REEVES, J Y Hydrologic & Geotechnical Engineering Branch
80/11/14 20pp 06998 176
- 8011240176 Memorandum & order. ALAB-418, answering certified question of
ASLB re whether licensee should be required to install site
dewatering sys to prevent liquefaction Board has authority
to require such remedies as appropriate
ROSENTHAL, A S, BUCK, J H, MODRE, T S Atomic Safety and Licensing
Appeal Panel 80/11/17 12pp 07049 245
- 8011210508 Forwards M Nataraja & JD Parkyn statements of prof
qualifications, inadvertently omitted from affidavits.
supporting licensee 801114 motion for summary disposition in
show cause proceeding Certificate of Bvc encl
GALLEN, K. P. Morgan, Lewis & Bockius 80/11/19 8pp. 07031 347
- 8011280021 Request for 2-wk extension for filing motion to compel
discovery from NRC
MORSE, A K Coulee Region Energy Coalition 80/11/21 1p.
07084 040
- 8011280023 Request for order compelling licensee & NRC to respond to
801002 interrogatories not relating to proper magnitude BBE.
All questions within scope of proper discovery Certificate of
Bvc encl
MORSE, A K Coulee Region Energy Coalition 80/11/21 3pp
07084-041
- P Operating license stage documents & correspondence
- 7908240206 Clarifies changes in review responsibility for Generic
Item 8-24 SEP branch will review purge isolation matter
REEVES, E A Operating Reactors Branch 1 (Pre 791030). 79/07/27,
1p. 00781 001.
- 8011303034 Ltr to all licensees of operating plants, applicants for CLs
& holders of CPs re preliminary clarification of TMI action
plan requirements Provides summary listing of all approved
TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05. 209pp
- 8011390129 Forwards request for addl info re bypass & reset of
engineered safety features
CRUTCHFIELD, D Operating Reactors Branch 5. 80/09/22. 4pp
06999 213
- 8011303042 Forwards Amend 21 to License DPR-45 & notice of issuance &
availability
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/23. 3pp.
06998 294
- 8011303049 Amend 21 to License DPR-45, adding license condition to
include Commission-approved safeguards contingency plan.
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/09/23 2pp.
06998:297.
- 8011303052 Notice of issuance & availability of Amend 21 to License
DPR-45.
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/23 2pp.
06998 299
- 8011390112 Submits list of topics that should be added to 791116
listing for deletion from SEP review Revised list of DBE
accident & transient groups applicable to BWRs encl.
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/26. 5pp
06999:207
- 8011304046 Ltr to all licensees of operating plants & applicants for
CLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs. Info needed by 801101.
EISENHUT, D G Division of Licensing 80/10/01. 5pp.
- 8011390564 Forwards NRC comments re 790814 proposed Tech Specs amend
long-term scram sys reliability IE Bulletin 80-17 required
mods to assure adequate short-term performance Info should
be submitted within 25 days.
CRUTCHFIELD, D Operating Reactors Branch 5. 80/10/01. 77pp
06978:004.
- 8011390237 Ltr to all BWR licensees requesting info on plans to assure
long-term scram sys reliability IE Bulletin 80-17 required
mods to assure adequate short-term performance Info should
be submitted within 25 days.
EISENHUT, D G Division of Licensing. 80/10/01. 2pp.

DOCKETED ITEMS

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp.

8011240070 Forwards order for mod of License DPR-45 re environ qualification of safety-related electrical equipment (SEP Topic III-12) Revised Tech Specs also encl
CRUICKFIELD, D Operating Reactors Branch 5 80/10/24 3pp
07038 275

--8011240076 Order for mod of license re environ qualification of safety-related electrical equipment Compliance w/Div of Operating Reactors guidelines or NUREG-0588 required by 820630 Complete records must be available by 801201
EISENHUT, D O Division of Licensing 80/10/24 6pp 07038 278

--8011240081 Revised Tech Spec pages per 801024 order for mod of license re environ qualification of safety-related electrical equipment
* Division of Licensing 80/10/24 3pp 07038 284

8011040179 Responds to NRC 801001 ltr re environ qualification of electrical equipment No tests scheduled
LINDER, F Dairyland Power Cooperative 80/10/29 1p 06884 267

8011170039 Informs that 800508 submittal in response to NRC 800215 ltr forwarding guidelines for evaluating environ qualification of Class IE electrical equipment in operating reactors is unsatisfactory & should be revised
CRUICKFIELD, D Operating Reactors Branch 5 80/10/29 2pp
06976-381

8011210440 Forwards request for addl info generated from review of "Asymmetric LOCA Loading," WCAP-9628 & 9748, dtd Nov 1979 & June 1980, respectively
LAINAS, G C Assistant Director for Safety Assessment 80/10/29 2pp

8011040410 Forwards balance of info re environ qualification of electrical equipment in response to NRC 800919 order.
LINDER, F Dairyland Power Cooperative 80/10/31 6pp. 01756 001

8011210004 Advises of delay in completion of SEP Topic XVI, Tech Specs, until completion of all SEP topic reviews & integrated safety assessment. Delay will allow evaluation of current Tech Specs w/proposed changes resulting from reviews
CRUICKFIELD, D Operating Reactors Branch 5 80/11/05 2pp
07033 183

Q Inspection reports, IE Bulletins & correspondence

8011060281 Forwards IE Insp Rept 50-409/80-08 on 800826-28 No noncompliance noted
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/09/17 2pp 06911 237

--8011060286 IE Insp Rept 50-409/80-08 on 800826-28 No noncompliance noted Major areas inspected environ protection & confinement measurements programs
GRANT, W B, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/09/17 6pp 06911 239

8011180099 Forwards IE Insp Rept 50-409/80-09 on 800801-31 & notice of violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/02 2pp 06985 108

--8011180104 Notice of violation from insp on 800801-31
* Region 3, Chicago, Office of the Director 80/09/30 2pp
06985 110

--8011180114 IE Insp Rept 50-409/80-09 on 800801-31 Noncompliance noted Failure to accomplish operations review committee review & approval of facility change & failure to provide two manual valves on exposed piping
FORNEY, H L, BRANCH, M W, STREETER, J F. Region 3, Chicago, Office of the Director 80/09/30 6pp 06985 112

8011260367 Forwards IE Insp Rept 50-409/80-11 on 800901-30 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/13 2pp 07072 296

--8011260375 IE Insp Rept 50-409/80-11 on 800901-30 No noncompliance noted Major areas inspected operational safety, surveillance, maint, followup action on IE bulletins & LERs.
FORNEY, H L, BRANCH, M W, RIDGWAY, K R. Region 3, Chicago, Office of the Director 80/10/13. 6pp 07072 298

8011070252 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/24 1p. 06924 239

8011190009 Updates NRC 800903 ltr re site access of Region 3 personnel New badges are currently being issued Interim questions re inspector identification should be directed to Region 3 ofc Badge examples encl
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/28 3pp 06999 148

8011200017 Forwards IE Insp Rept 50-409/80-12 on 801009-10 No noncompliance noted
HIND, J A Region 3, Chicago, Safeguards Branch 80/11/03 2pp
07020 195

--8011200022 IE Insp Rept 50-409/80-12 on 801009-10 No noncompliance noted Major areas inspected protected area physical barriers, detection aids, security plan & power supply. Details withheld (ref 10CFR2 790)
PIRTLE, O L. Region 3, Chicago, Office of the Director. HIND, J A Region 3, Chicago, Safeguards Branch 80/10/28 1p 07020 197.

8011190639 Act receipt of 801028 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/80-05.
HIND, J A Region 3, Chicago, Safeguards Branch. 80/11/04 1p
07001 227

--8011190647 Responds to NRC 800930 ltr re violations noted in IE Insp Rept 50-409/80-05 Corrective actions withheld (ref 10CFR2 790).
LINDER, F. Dairyland Power Cooperative. 80/10/28. 1p 07001 228

R Periodic operating reports & related correspondence

8011170502 Forwards monthly operating rpt for Oct 1980
LINDER, F Dairyland Power Cooperative 80/11/10 1p 06975 075.

--8011170503 Monthly operating rpt for Oct 1980
GOODMAN, L S Dairyland Power Cooperative 80/11/06 13pp
06975 076

S Reportable occurrences, LERs & related correspondence

8011180684 RO 80-11 on 801110, at commencement of 1980 refueling outage, plant cooldown rate exceeded 150 F/hr at five points on reactor vessel Cause not stated Max change over 1-h period did not exceed 150 F Facsimile LER encl
LINDER, F. Dairyland Power Cooperative 80/11/12 3pp 06991 272

8011250523 RO 80-12 on 801117, visual insp of fuel assemblies 2-37 & 2-50 revealed possible fuel cladding degradation Investigation continuing
LINDER, F Dairyland Power Cooperative 80/11/18 3pp 07068 108

V Operator Examinations

8011120340 Responds to NRC 800731 ltr re interim criteria for shift staffing Continuous presence of senior operator in control room & addl short-term relief operator is not required
LINDER, F Dairyland Power Cooperative 80/10/29 5pp 06951 349.

DOCKET 80-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05. 209pp

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D O. Division of Licensing. 80/10/01 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D O Division of Licensing 80/10/06. 6pp

8011030497 Forwards addl info requested in NRC 800909 ltr re DYWIDAG threadbar sys Approval of sys requested by 801201 to allow for use in structures scheduled for const beginning B10301 Lead time required to get needed matls & train splicers
RHODE, O K Niagara Mohawk Power Corp 80/10/28 20pp 06872 325

8011040421 Responds to NRC 801001 request for info re environ qualification tests to be conducted on facility equipment info will be submitted by 801231
RHODE, O K Niagara Mohawk Power Corp 80/10/30 1p 06874 184

8011070465 Forwards "Geologic Investigation - Radwaste Thrust Structure"
RHODE, O K Niagara Mohawk Power Corp 80/10/31 1p 06922 045

--8011070469 "Geologic Investigation - Radwaste Thrust Structure"
+ Niagara Mohawk Power Corp 04707-022-19 80/10/31 800pp 06922 046

8011250369 Forwards addl info required for cooling tower rept review, per NRC 800909 request. Oversize drawing available in Central Files
RHODE, O K Niagara Mohawk Power Corp 80/11/21 11pp 07065 353

F Security, medical, emergency & fire protection plans

8011170021 Forwards facility emergency planning info for placement in LPDR, w/o encl
SQUIDER, J L Division of Rules and Records 80/11/04 1p 06978-268

H General correspondence

8011040408 Requests FI Dialik name be added to svc lists for all matters re facilities, BNL & transport of nuclear matls in NY
BIALIK, E I New York, State of 80/10/31 1p

G Inspection reports, IE Bulletins & correspondence

8011060537 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" IEB 79-01B & suppl did 800229, not previously transmitted, also encl. No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/30 1p 06910-222

8011070267 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06921 260

8011140080 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators" No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06963 338

8011140625 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp" No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06963 253

DOCKET 30-412 BEAVER VALLEY POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements. Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp.

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp.

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" w/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011030581 Responds to NRC 801001 request for addl info re environ qualification of safety-related equipment info to be available on 801201 due to magnitude of effort
MOGLEVER, E J Duquesne Light Co 80/10/29 1p 06835 064

F Security, medical, emergency & fire protection plans

8011180337 Forwards facility emergency planning info for placement in LPDR w/o encl
SQUIDER, J L Division of Rules and Records 80/11/04 1p 06991 164

G Adjudicatory correspondence

8011060196 Responds to 800919 ltr re approval for transfer of interest for security purposes Arrangement re proposed const trust to finance OH Edison does not require application or approval.
REIS, E J Hearing Branch 3 80/11/04 2pp. 06912 092

G Inspection reports, IE Bulletins & correspondence

8011060543 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" IEB 79-01B & suppl did 800229, not previously transmitted, also encl. No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/30 1p 06912 359.

8011060644 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2" No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06909 329

8011070265 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06921 292

8011140139 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators." No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06968 229

8011170893 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp" No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06981 225

B Reportable occurrences, LERs & related correspondence

8011140407 Forwards Interim Rept 2 re Significant Deficiency 80-03, concerning linear indications in g1b gusset welds in reactor vessel structural support Q1ba & g1b gussets will be removed & replaced. Final rept scheduled for 810715
MOGLEVER, E J Duquesne Light Co 80/11/13 12pp. 06962 348

8011180603 Interim deficiency rept re inferior rung welds on cable tray fittings first reported on 801015 All tray tees & crosses not yet installed Welds presently installed will either be repaired or replaced to ensure structural adequacy
MOGLEVER, E J Duquesne Light Co 80/11/14 3pp. 06992 117

8011190304 Significant Deficiency Rept 80-05, originally reported on 801015, re inferior welds on cable tray fittings. Procedure for repair of deficient fittings being developed Final rept will be submitted by 810130
MOGLEVER, E J Duquesne Light Co 80/11/14 3pp 07000 032

8011230321 Significant Deficiency Rept 80-06, originally reported on 801029, re 3-inch motor operated valve gate valves in safety injection & chemical & vol control sys Deficiency being investigated Interim rept will be issued 810601.
MOGLEVER, E J Duquesne Light Co 80/11/20 4pp 07036 075.

DOCKET 30-413 CATAWBA NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements. Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp.

DOCKETED ITEMS

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101 EISENHUT, D O Division of Licensing 80/10/01 3pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl EISENHUT, D O Division of Licensing 80/10/06 6pp.

8011040481 Forwards list re equipment which will undergo environ qualification tests, to be conducted within next two yrs, in response to NRC 801001 request PARKER, W D Duke Power Co 80/10/31 3pp

M. Antitrust correspondence

8011070316 Advises that no basis exists to conclude that participation in Unit 1 by NC Electric Membership Corp & Saluda River Electric Cooperative constitutes violation of antitrust laws. No hearing re transfer of ownership necessary LITVACK, S M Justice, Dept of 80/10/29 2pp 06924:273

801110704 Ack receipt of ltr opposing sale of nuclear power station to NC Electric Membership Corp Ltr has been forwarded to DOJ re antitrust proceeding. SALTZMAN, J Utility Finance Branch (formerly Antitrust & Indemnity) 80/10/30 1p. 06947 352

8011170042 Forwards Atty General 801029 ltr providing addl antitrust advice re CP application Ltr will be published in FR. SALTZMAN, J Utility Finance Branch (formerly Antitrust & Indemnity) 80/11/06 1p 06978:269

G. Inspection reports, IE Bulletins & correspondence

8011040799 Ack receipt of 800926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-17 & 50-414/80-17 MURPHY, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/17 1p 06885 006.

--8011040322 Responds to NRC 800829 ltr re violations noted in IE Insp Repts 50-413/80-17 & 50-414/80-17 Corrective actions Procedure 427 issued re process control requirements for ASME Class A, B & C welds PARKER, W D. Duke Power Co 80/09/26 4pp 06885 007

--8011040304 Forwards IE Insp Repts 50-413/80-17 & 50-414/80-17 on 800721-25 & notice of violation. MURPHY, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/08/29 2pp 06885 011

--8011040306 Notice of violation from insp on 800721-25, "Region 2, Atlanta, Office of the Director. 80/08/28 2pp. 06885:013

--8011040310 IE Insp Repts 50-413/80-17 & 50-414/80-17 on 800721-25. Noncompliance noted. Use of undersize pipe to flange socket welds OIRARD, E H Region 2, Atlanta, Office of the Director. HERDT, A R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/28 2pp 06885 015.

8011040064 Ack receipt of IE Insp Repts 50-413/80-25 & 50-414/80-25 on 800908-12 No proprietary info PARKER, W D Duke Power Co 80/10/26 1p. 06884 290

--8011040068 Forwards IE Insp Repts 50-413/80-25 & 50-414/80-25 on 800908-12 No noncompliance noted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/01 2pp. 06884 291

--8011040073 IE Insp Repts 50-413/80-25 & 50-414/80-25 on 800908-12 No noncompliance noted Major areas inspected: responses to nonconforming items; unresolved items; IE Bulletin 80-19, containment dome & reactor coolant piping welding work RAUSCH, J K, VANHOORN, P K Region 2, Atlanta, Office of the Director. BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/30 3pp 06884 293.

8011170685 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required. O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/10/24 1p. 06976 238.

8011170362 Ack receipt of IE Insp Repts 50-413/80-26 & 50-414/80-26 No proprietary info PARKER, W D Duke Power Co 80/10/29 1p 06976 323.

--8011170565 Forwards IE Insp Repts 50-413/80-26 & 50-414/80-26 on 800915-19 No noncompliance noted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/10 2pp 06976 324

--8011170568 IE Insp Repts 50-413/80-26 & 50-414/80-26 on 800915-19 No noncompliance noted Major areas inspected RCPB piping, safety-related piping, containment structural steel & matl storage BLAKE, J Region 2, Atlanta, Office of the Director HERDT, A E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/10 3pp 06976 326

8011210768 Clarifies 801020 ltr disagreeing w/IE Circular 80-21 re directly supervised refueling operations Senior operator should have freedom to determine location needing most attention PARKER, W D Duke Power Co 80/11/03 1p 07029 128

8011260423 Suppl 801016 acknowledgement ltr re receipt of util 800811 ltr informing NRC of steps taken to correct violations noted in IE insp repts. Action noted in Paragraph b of IE 801016 ltr remains outstanding MURPHY, C E Region 2, Chicago, Reactor Construction & Engineering Support Branch 80/11/12 1p 07075 170.

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements EISENHUT, D O Division of Licensing 80/09/03 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101 EISENHUT, D O Division of Licensing 80/10/01 3pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl EISENHUT, D O Division of Licensing. 80/10/06 6pp.

8011040481 Forwards list re equipment which will undergo environ qualification tests, to be conducted within next two yrs, in response to NRC 801001 request. PARKER, W D. Duke Power Co 80/10/31 3pp

M Antitrust correspondence

8011070316 Advises that no basis exists to conclude that participation in Unit 1 by NC Electric Membership Corp & Saluda River Electric Cooperative constitutes violation of antitrust laws No hearing re transfer of ownership necessary LITVACK, S M Justice, Dept of 80/10/29 2pp 06924 273

8011170042 Forwards Atty General 801029 ltr providing addl antitrust advice re CP application. Ltr will be published in FR. SALTZMAN, J Utility Finance Branch (formerly Antitrust & Indemnity). 80/11/06 1p. 06978:269

G. Inspection reports, IE Bulletins & correspondence

8011040799 Ack receipt of 800926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-17 & 50-414/80-17. MURPHY, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/17 1p 06885 006

--8011040322 Responds to NRC 800829 ltr re violations noted in IE Insp Repts 50-413/80-17 & 50-414/80-17 Corrective actions: Procedure 427 issued re process control requirements for ASME Class A, B & C welds. PARKER, W D Duke Power Co. 80/09/26 4pp. 06885 007.

--8011040304 Forwards IE Insp Repts 50-413/80-17 & 50-414/80-17 on 800721-25 & notice of violation MURPHY, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/08/29 2pp 06885:011.

DOCKETED ITEMS

211

--8011040306 Notice of violation from insp on 800721-25
* Region 2, Atlanta, Office of the Director 80/08/28 2pp
06885 013

--8011040310 IE Insp Repts 50-413/80-17 & 50-414/80-17 on 800721-25
Noncompliance noted use of undersize pipe to flange socket
weld.
GIRARD, E.H. Region 2, Atlanta, Office of the Director HERDT, A.R.
Region 2, Atlanta, Reactor Construction & Engineering Support
Branch 80/08/28 3pp 06885 015

8011040064 Ack receipt of IE Insp Repts 50-413/80-25 & 50-414/80-25, on
800908-12 No proprietary info
PARKER, W.O. Duke Power Co 80/10/20 1p 06884 290

--8011040068 Forwards IE Insp Repts 50-413/80-25 & 50-414/80-25 on
800908-12 No noncompliance noted
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/10/01 2pp 06884 291

--8011040073 IE Insp Repts 50-413/80-25 & 50-414/80-25 on 800908-12 No
noncompliance noted Major areas inspected responses to
nonconforming items, unresolved items, IE Bulletin 80-19,
containment dome & reactor coolant piping welding work
RAUSCH, J.K., VANDOOORN, P.K. Region 2, Atlanta, Office of the
Director BRYANT, J.C. Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 80/09/30 3pp 06884 293

8011170685 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ
Qualification of Class 1E Equipment " No written response
required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/24.
1p

8011170562 Ack receipt of IE Insp Repts 50-413/80-26 & 50-414/80-26.
No proprietary info
PARKER, W.O. Duke Power Co. 80/10/29 1p. 06976-323.

--8011170565 Forwards IE Insp Repts 50-413/80-26 & 50-414/80-26 on
800915-19 No noncompliance noted
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/10/10 2pp 06976 324.

--8011170568 IE Insp Repts 50-413/80-26 & 50-414/80-26 on 800915-19 No
noncompliance noted Major areas inspected: RCPB piping,
safety-related piping, containment structural steel & metal
storage
BLAKE, J. Region 2, Atlanta, Office of the Director. HERDT, A.E.
Region 2, Atlanta, Reactor Construction & Engineering Support
Branch. 80/10/10 3pp. 06976.326

8011210768 Clarifies 801020 ltr disagreeing w/IE Circular 80-21 re
directly supervised refueling operations Senior operator
should have freedom to determine location needing most
attention.
PARKER, W.O. Duke Power Co. 80/11/03 1p.

8011260423 Suppl 801016 acknowledgement ltr re receipt of util 800811
ltr informing NRC of steps taken to correct violations noted
in IE insp repts. Action noted in Paragraph b of IE 801016
ltr remains outstanding.
MURPHY, C.E. Region 2, Chicago, Reactor Construction & Engineering
Support Branch. 80/11/12 1p.

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TH1 action
plan requirements. Provides summary listing of all approved
TH1-2 related requirements
EISENHUT, D.Q. Division of Licensing. 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs info needed by 801101.
EISENHUT, D.Q. Division of Licensing. 80/10/01. 3pp

8011100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports " W/o encl.
EISENHUT, D.Q. Division of Licensing. 80/10/06 6pp.

8011030741 Notification of 801119 & 20 meetings w/util in Port Gibson,
MS to discuss overall project status & detailed project
schedule & to observe const activities in progress.
MARTORE, J.A. Licensing Branch 3. 80/10/24. 6pp 06860.127

8011170576 Requests description re licensee program to improve hydrogen
control capability to cope w/significant amounts of hydrogen
in excess of those considered in code
TEDESCH, R.L. Assistant Director for Licensing 80/10/30 1p
06911-001.

8011250267 Forwards "Summary of Environ Protection Program re Const of
Grand Gulf Nuclear Station for 6 Months Ending Oct 1980 "
MCGAUGHY, J. Mississippi Power & Light Co 80/11/03 3pp
07032 341

--8011250270 "Summary of Environ Protection Program re Const of Grand
Gulf Nuclear Station for 6 Months Ending Oct 1980 "
* Mississippi Power & Light Co 80/11/03 2pp 07032 342

8011280064 Forwards Amend 44 to application for OLs, consisting of
responses to NRC questions, miscellaneous refinements of
design info & revised hydrodynamic required response
spectra, Oversize drawings encl
MCGAUGHY, J.P. Mississippi Power & Light Co 80/11/26 2pp
07076 010

--8011280067 Amend 44 to application for OLs, responding to NRC questions
re FSAR & miscellaneous refinements of design info
MCGAUGHY, J.P. Mississippi Power & Light Co 80/11/20 2pp
07076 012

C Utility Environmental Report (ER), amends & correspondence

8011190588 Forwards request for addl info re operability of Ramney well
sys, as part of continuing NRC environ rept
TEDESCH, R.L. Assistant Director for Licensing 80/11/10 4pp
06976 205.

F. Security, medical, emergency & fire protection plans

8011060174 Notification of 801030 meeting w/util in Bethesda, MD to
discuss util approach to emergency planning requirements
Date changed from 801021
MARTORE, J.A. Licensing Branch 3 80/10/07 3pp 06912 326.

8011030735 Notification of 801119-21 meeting w/util & Bechtel Power
Corp in Port Gibson, MS to review fire protection
MARTORE, J.A. Licensing Branch 3 80/10/24 4pp 06860 124

8011170038 Notification of date & time change of 801203-05 meeting
w/util & Bechtel to review facility for fire protection
MARTORE, J.A. Licensing Branch 3 80/11/07 3pp 06981 308

8011180401 Forwards revised physical security plan. Plan withheld
(ref 10CFR2 770)
MCGAUGHY, J.P. Mississippi Power & Light Co 80/11/13. 2pp
06992-158.

H General correspondence

8011040317 Responds to 800602 ltr re lack of community input to
emergency planning informs of new regulations & requirements
for classifying & declaring emergency Suggests communication
w/FEMA & other local organizations
DENTON, H.R. Office of Nuclear Reactor Regulation, Director
80/10/20 2pp. 06885 032

--8011040323 Suggests that more details be afforded Miller concern re
lack of citizen participation in formulation of evacuation
plans
KETCHEN, E.O. Office of the Executive Legal Director. 80/09/23
3pp. 06885 034

--8011040326 Expresses concern re lack of citizen input into planning
process surrounding evacuation plan
MILLER, J. Claiborne County Citizens for Safe Energy 80/06/02
2pp. 06885:037

K Utility Final Safety Analysis Report (FSAR) & amends

8011280064 Forwards Amend 44 to application for OLs, consisting of
responses to NRC questions, miscellaneous refinements of
design info & revised hydrodynamic required response
spectra, Oversize drawings encl.
MCGAUGHY, J.P. Mississippi Power & Light Co 80/11/26. 2pp
07076:010.

--8011280067 Amend 44 to application for OLs, responding to NRC questions
re FSAR & miscellaneous refinements of design info.
MCGAUGHY, J.P. Mississippi Power & Light Co. 80/11/20. 2pp.
07076 012

DOCKETED ITEMS

--B011283069 Amend 44 to FSAR
* Mississippi Power & Light Co 80/11/30 1600pp 07076.014

--B011280070 "P & I Diagram Suppression Pool Make-up Sys"
* Bechtel Corp 9645 80/08/22 1p

--B011280072 "P & I Diagram Control Room Heating, Ventilation & Air
Conditioning Sys"
* Bechtel Corp 9645 80/03/04 1p

--B011280074 "P & I Diagram RHR Sys"
* Bechtel Corp 9645 80/09/05 1p

--B011280076 "P & I Diagram RHR Sys"
* Bechtel Corp 9645 80/09/05 1p.

G Inspection reports, IE Bulletins & correspondence

B011260392 Forwards IE Insp Repts 50-416/80-22 & 50-417/80-12 on
B00702-05 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch. 80/10/08 2pp 07072 317

--B011260396 IE Insp Repts 50-416/80-22 & 50-417/80-12 on B00702-05 No
noncompliance noted Major areas inspected licensee
identified items & inspector followup items
OIBBONS, T D Region 2, Atlanta, Office of the Director
CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch. 80/10/08 3pp 07072 319

B011060107 Responds to IE Bulletin 80-20 No Westinghouse W-2 control
switches w/spring return to neutral position used in safety-
related areas. Thirty manhours expended for review
DALE, L F Mississippi Power & Light Co 80/10/15 1p 06912.214

B011170781 Completes response to IE Bulletin 80-08 Forwards list of
pipe sizes & mats, welds needing repair or replacement &
description of defects No further action required
DALE, L F Mississippi Power & Light Co 80/10/15 14pp
06978 304

B011170267 Completes review & evaluation of IE Bulletin 80-19, Revision
1 Station has not utilized mercury-wetted relays in logic
matrix of reactor protection sys No further action required
Approx 20 manhours expended on bulletin
DALE, L F Mississippi Power & Light Co 80/10/21 2pp 06968.350

B011100424 Requests 60-day extension so OE may complete evaluation of
NBSB portions of station affected by IE Bulletin 80-16
Partial response submitted on B00827
DALE, L F Mississippi Power & Light Co 80/10/27 1p. 06929 294

B011200438 Ack receipt of B01013 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-416/80-19
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/11/05 1p 07020 124

--B011200446 Responds to NRC B00711 ltr re violation noted in IE Insp
Rept 50-416/80-19. Corrective actions bolting on pumps
retorqued using certified multipliers.
MCGAUGHY, J P Mississippi Power & Light Co. 80/10/13. 2pp
07020 125

--B011200451 Forwards IE Insp Rept 50-416/80-19 on B00812-15 & notice of
violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/09/11 2pp 07020 127

--B011200456 Notice of violation from insp on B00812-15
* Region 2, Atlanta, Office of the Director 80/09/10 1p
07020 129.

--B011200460 IE Insp Rept 50-416/80-19 on B00812-15 Noncompliance noted
failure to provide calibr & control procedures for torque
wrench multipliers
AND, W P Region 2, Atlanta, Office of the Director. HERDT, A R.
Region 2, Atlanta, Reactor Construction & Engineering Support
Branch. 80/09/10 4pp 07020 130

B011140064 Final deficiency rept re use of uncertified torque wrench
multipliers noted in IE Insp Rept 50-416/80-19 & first
reported on B01007 Torque wrench multipliers were certified
& all affected equipment retorqued Rept is not Part 21
MCGAUGHY, J P Mississippi Power & Light Co 80/11/07 2pp
06963.343

B Reportable occurrences, LERs & related correspondence

B011030620 Part 21 rept re deficient switch on Rosemount Model 510 DV
trip/calibr units & Model 1152 pressure transmitters,
reported on B00327 Field disposition instructions issued to
return units for repair
MCGAUGHY, J P Mississippi Power & Light Co 80/10/22. 4pp.
06850 097

B011030497 Interim deficiency rept re Reactor Controls, Inc issuance of
drawings prior to verification of design adequacy
Investigation continuing to determine effects & safety &
reportability under 10CFR50.55e & 10CFR21.
MCGAUGHY, J P Mississippi Power & Light Co 80/10/27 2pp
06872 312

B011060700 Part 21 rept re electroschwitch malfunctions, reported on
B00702 Switches showed contact & indication malfunctions
during sys testing. Cause undetermined by vendor Final rept
will be filed by B10219.
MCGAUGHY, J P. Mississippi Power & Light Co 80/10/28 4pp
06914 337

B011140102 Interim deficiency rept originally reported on B00702 re
contact & indication malfunctions of Electro switches OE to
determine corrective action Final rept expected by B10219.
MCGAUGHY, J P Mississippi Power & Light Co 80/10/28 3pp
06960.328

B011190410 Part 21 Interim Rept 2 re Rosemount Model 1151A pressure
transmitters reported on B00411 Supplier still conducting
investigation into application of transmitters in NBSB sys.
Final rept by B10218
MCGAUGHY, J P Mississippi Power & Light Co 80/10/30 3pp
06916 001

B011120335 Interim deficiency rept re defective link rod assembly on
standby diesel generators supplied by Transamerica Delaval,
Inc. Initially reported on B01003 No potential problem exists
on Unit I engines Unit II engines will be inspected
MCGAUGHY, J P Mississippi Power & Light Co. 80/11/03 2pp
06952.021

B011140001 Deficiency rept re Limitorque valve operator malfunctions. No
stem protectors have been found to cause valve malfunctions
Valve testing continuing. Final rept will be submitted by
B10117
MCGAUGHY, J P Mississippi Power & Light Co 80/11/03 2pp
06961.226

B011120350 Second interim deficiency rept re potential failure of
anchor bolts supplied by Hilti Fastening Sys, Inc. Initially
reported on B00814. Manufacturer is conducting tests to
determine cause Final rept will be provided by B10320
MCGAUGHY, J P Mississippi Power & Light Co. 80/11/04 2pp
06952 019

B011140071 Interim deficiency rept re incorrectly crimped ITE Imperial
control circuitry terminations in engineered safety feature
4 16 Kv bus, reported B00703 Investigation not complete
Preliminary indications show operation is still safe
MCGAUGHY, J P Mississippi Power & Light Co. 80/11/06 3pp
06963.340.

B011140111 Second interim deficiency rept re linear indications on
Guyon Alloys, Inc couplings used in Class I & II
applications, originally reported on B00811. Plant can still
operate safely
MCGAUGHY, J P Mississippi Power & Light Co 80/11/06 2pp
06968.266

B011140064 Final deficiency rept re use of uncertified torque wrench
multipliers noted in IE Insp Rept 50-416/80-19 & first
reported on B01007. Torque wrench multipliers were certified
& all affected equipment retorqued Rept is not Part 21
MCGAUGHY, J P Mississippi Power & Light Co 80/11/07. 2pp
06963 343

B011180686 Second interim deficiency rept re standby diesel generator
jacket water cooler thermostatic valve fracture Cause not
stated Magnetic particle exam performed on remaining valve
Final rept will be submitted by B10205
MCGAUGHY, J P. Mississippi Power & Light Co 80/11/10 2pp
06991 277.

B011180502 Second status rept re installation of expansion anchors for
conduit hangers, instrument process tubing & air supply
supports. Investigation completed Final deficiency rept will
be provided by B10310.
MCGAUGHY, J P. Mississippi Power & Light Co. 80/11/11 2pp.
06988.321.

DOCKETED ITEMS

213

801180492 Third status rept re indications revealed during liquid penetrant examination of inner bore region of N4-A feedwater nozzle on reactor pressure valve Results of repair work being evaluated Final rept to be submitted by 810315
MCGAUGHY, J P Mississippi Power & Light Co 80/11/12 2pp
06988 323

801190523 Interim deficiency rept to PRD-80/63, originally reported on 801015, re ventilation sys VLK air extractor structural inadequacy. Vane assembly sagging being investigated Investigation to be completed & rept submitted by 810312
MCGAUGHY, J P Mississippi Power & Light Co 80/11/14 2pp
07000 025

8011230466 Second interim deficiency rept re procedural violation in cutting rebar, initially reported on 800602 Constructor issued stop work order Method to evaluate unlogged cut rebar is being developed Final rept will be provided by 810801
MCGAUGHY, J P Mississippi Power & Light Co 80/11/17 3pp.
07068 237

DOCKET 80-417 GRAND GULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for GLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D O Division of Licensing 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for GLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports" W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011030741 Notification of 801119 & 20 meetings w/util in Port Gibson, MS to discuss overall project status & detailed project schedule & to observe const activities in progress.
MARTORE, J A Licensing Branch 3 80/10/24 6pp. 06860 127

801170576 Requests description re licensee program to improve hydrogen control capability to cope w/significant amounts of hydrogen in excess of those considered in code
TEDESCO, R L Assistant Director for Licensing 80/10/30, 1p
06911 001

8011250267 Forwards "Summary of Environ Protection Program re Const of Grand Gulf Nuclear Station for 6 Months Ending Oct 1980"
MCGAUGHY, J P Mississippi Power & Light Co. 80/11/03 3pp
07052 341.

--8011250270 "Summary of Environ Protection Program re Const of Grand Gulf Nuclear Station for 6 Months Ending Oct 1980"
* Mississippi Power & Light Co 80/11/03 2pp 07052 342

C Utility Environmental Report (ER), amends & correspondence

801190588 Forwards request for addl info re operability of Ranney well sys, as part of continuing NRC environ rept
TEDESCO, R L Assistant Director for Licensing 80/11/10 4pp.
06976 205.

F Security, medical, emergency & fire protection plans

8011060174 Notification of 801030 meeting w/util in Bethesda, MD to discuss util approach to emergency planning requirements Date changed from 801021
MARTORE, J A Licensing Branch 3 80/10/07 3pp 06912 326

8011030735 Notification of 801119-21 meeting w/util & Bechtel Power Corp in Port Gibson, MS to review fire protection.
MARTORE, J A Licensing Branch 3. 80/10/24. 4pp 06860 124.

801170038 Notification of date & time change of 801203-05 meeting w/util & Bechtel to review facility for fire protection
MARTORE, J A Licensing Branch 3. 80/11/07 3pp 06981 308.

8011804901 Forwards revised physical security plan Plan withheld (ref 10CFR2 790)
MCGAUGHY, J P Mississippi Power & Light Co 80/11/13 2pp
06972 158

H General correspondence

8011040317 Responds to 800602 ltr re lack of community input to emergency planning informs of new regulations & requirements for classifying & declaring emergency Suggests communication w/FEMA & other local organizations
DENIGAN, H R Office of Nuclear Reactor Regulation, Director 80/10/20 2pp 06885 032

--8011040323 Suggests that more details be afforded Miller concern re lack of citizen participation in formulation of evacuation plans
KETCHEN, E O Office of the Executive Legal Director 80/09/23 3pp 06885 034

--8011040326 Expresses concern re lack of citizen input into planning process surrounding evacuation plan
MILLER, J Claiborne County Citizens for Safe Energy 80/06/02 2pp 06885 037

K Utility Final Safety Analysis Report (FSAR) & amends

8011280064 Forwards Amend 44 to application for GLs, consisting of responses to NRC questions, miscellaneous refinements of design info & revised hydrodynamic required response spectra. Oversize drawings encl
MCGAUGHY, J P Mississippi Power & Light Co 80/11/26 2pp
07076 010.

--8011280067 Amend 44 to application for GLs, responding to NRC questions re FSAR & miscellaneous refinements of design info
MCGAUGHY, J P Mississippi Power & Light Co 80/11/20 2pp
07076 012

--8011280069 Amend 44 to FSAR.
* Mississippi Power & Light Co 80/11/30 1400pp 07076 014

--8011280072 "P & I Diagram Control Room Heating, Ventilation & Air Conditioning Sys"
* Bechtel Corp 9648 80/03/04 1p

G Inspection reports, IE Bulletins & correspondence

8011260392 Forwards IE Insp Repts 80-416/80-22 & 80-417/80-12 on 800902-05. No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/08 2pp 07072 317

--8011260396 IE Insp Repts 80-416/80-22 & 80-417/80-12 on 800902-05. No noncompliance noted Major areas inspected licensees identified items & inspector followup items
QIBBONS, T D Region 2, Atlanta, Office of the Director
CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/08 3pp 07072 319

8011060107 Responds to IE Bulletin 80-20 No Westinghouse W-2 control switches w/spring return to neutral position used in safety-related areas. Thirty manhours expended for review
DALE, L F Mississippi Power & Light Co 80/10/15 1p 06912 214

801170281 Completes response to IE Bulletin 80-08 Forwards list of pipe sizes & matls, welds needing repair or replacement & description of defects. No further action required
DALE, L F Mississippi Power & Light Co 80/10/15. 14pp
06978 304

801170267 Completes review & evaluation of IE Bulletin 80-19, Revision 1 Station has not utilized mercury-wetted relays in logic matrix of reactor protection sys No further action required
Approx 20 manhours expended on bulletin
DALE, L F Mississippi Power & Light Co 80/10/21 2pp 06968 350

801100424 Requests 60-day extension so OE may complete evaluation of NSSB portions of station affected by IE Bulletin 80-16.
Partial response submitted on 800827
DALE, L F Mississippi Power & Light Co 80/10/27 1p. 06929 294.

801140064 Final deficiency rept re use of uncertified torque wrench multipliers noted in IE Insp Rept 80-416/80-19 & first reported on 801007 Torque wrench multipliers were certified & all affected equipment retorqued Rept is not Part 21.
MCGAUGHY, J P Mississippi Power & Light Co. 80/11/07 2pp

DOCKETED ITEMS

S Reportable occurrences, LERs & related correspondence

8011030620 Part 21 rept re deficient switch on Rosemount Model 510 DU trip/calibr units & Model 1152 pressure transmitters, reported on 800327 Field disposition instructions issued to return units for repair
MCOAUGHY, J.P. Mississippi Power & Light Co 80/10/22 4pp
06960,097

8011030457 Interim deficiency rept re Reactor Controls, Inc issuance of drawings prior to verification of design adequacy
Investigation continuing to determine effects & safety & reportability under 10CFR50.55a & 10CFR21
MCOAUGHY, J.P. Mississippi Power & Light Co 80/10/27 2pp
06872 312

8011040700 Part 21 rept re electroschwitch malfunctions, reported on 800702 Switches showed contact & indication malfunctions during sys testing Cause undetermined by vendor, Final rept will be filed by 810219
MCOAUGHY, J.P. Mississippi Power & Light Co 80/10/28 4pp
06914 337

8011140102 Interim deficiency rept originally reported on 800702 re contact & indication malfunctions of Electro switches OE to determine corrective action Final rept expected by 810219
MCOAUGHY, J.P. Mississippi Power & Light Co 80/10/28 3pp.
06960 328

8011190410 Part 21 Interim Rept 2 re Rosemount Model 1151A pressure transmitters reported on 800411 Supplier still conducting investigation into application of transmitters in NSSB sys
Final rept by 810218
MCOAUGHY, J.P. Mississippi Power & Light Co 80/10/30 3pp.
06916, 001

801120335 Interim deficiency rept re defective link rod assembly on standby diesel generators supplied by Transamerica Deleval, Inc, initially reported on 801003 No potential problem exists on Unit 1 engines Unit 1 engines will be inspected.
MCOAUGHY, J.P. Mississippi Power & Light Co 80/11/03 2pp
06952, 021

8011140001 Deficiency rept re Limitorque valve operator malfunctions. No stem protectors have been found to cause valve malfunctions
Valve testing continuing Final rept will be submitted by 810117.
MCOAUGHY, J.P. Mississippi Power & Light Co 80/11/03 2pp
06961 226

801120350 Second interim deficiency rept re potential failure of anchor bolts supplied by Hilti Fastening Sys, Inc, initially reported on 800814 Manufacturer is conducting tests to determine cause Final rept will be provided by 810520
MCOAUGHY, J.P. Mississippi Power & Light Co 80/11/04 2pp.
06952, 019

8011140071 Interim deficiency rept re incorrectly crimped ITE Imperial control circuitry terminations in engineered safety feature 4 16 Kv bus, reported 800703. Investigation not complete
Preliminary indications show operation is still safe.
MCOAUGHY, J.P. Mississippi Power & Light Co 80/11/06 3pp.
06963 340

8011140111 Second interim deficiency rept re linear indications on Guyan Alloys, Inc couplings used in Class I & II applications, originally reported on 800811 Plant can still operate safely.
MCOAUGHY, J.P. Mississippi Power & Light Co 80/11/06 2pp.
06968 266

8011140064 Final deficiency rept re use of uncertified torque wrench multipliers noted in IE Insp Rept 50-416/80-19 & first reported on 801007 Torque wrench multipliers were certified & all affected equipment retorqued Rept is not Part 21.
MCOAUGHY, J.P. Mississippi Power & Light Co. 80/11/07 2pp.
06963, 343

8011180486 Second interim deficiency rept re standby diesel generator jacket water cooler thermostatic valve fracture. Cause not stated. Magnetic particle exam performed on remaining valve.
Final rept will be submitted by 810205
MCOAUGHY, J.P. Mississippi Power & Light Co. 80/11/10. 2pp.
06991, 277

8011180502 Second status rept re installation of expansion anchors for conduit hangers, instrument process tubing & air supply supports. Investigation completed Final deficiency rept will be provided by 810310.
MCOAUGHY, J.P. Mississippi Power & Light Co 80/11/11 2pp.
06988, 321

8011180492 Third status rept re indications revealed during liquid penetrant examination of inner bore region of N4-A feedwater nozzle on reactor pressure valve Results of repair work being evaluated Final rept to be submitted by 810313
MCOAUGHY, J.P. Mississippi Power & Light Co 80/11/12 2pp.
06988-325

8011190923 Interim deficiency rept to PRD-80/63, originally reported on 801015, re ventilation sys VLK air extractor structural inadequacy Vane assembly sagging being investigated
Investigation to be completed & rept submitted by 810312
MCOAUGHY, J.P. Mississippi Power & Light Co. 80/11/14 2pp.
07000 025

8011230466 Second interim deficiency rept re procedural violation in cutting rebar, initially reported on 800602 Constructor issued stop work order Method to evaluate unlogged cut rebar is being developed Final rept will be provided by 810801.
MCOAUGHY, J.P. Mississippi Power & Light Co. 80/11/17 3pp
07068 257

DOCKET 50-423 HILLSTONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D O Division of Licensing. 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101
EISENHUT, D O. Division of Licensing. 80/10/01. 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

F Security, medical, emergency & fire protection plans

8011170007 Forwards facility emergency planning info for placement LPDR W/o encl
BOUDER, J.L. Division of Rules and Records 80/11/04 1p.
06978-245

G Inspection reports, IE Bulletins & correspondence

8011060545 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " IEB 79-018 & suppl dtd 800229, not previously transmitted, also encl No written response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/09/30. 1p 06914 132

8011060746 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/24 1p 06914-345.

8011070326 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/24 1p. 06922, 021

8011140063 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/31. 1p. 06968, 245

8011170087 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/31. 1p. 06981, 220

Reportable occurrences, LERs & related correspondence

011050063 Ack receipt of 800829 interim deficiency rept re failures in diesel generator assemblies Rept will be reviewed & evaluated.
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/24 1p 06896-297

-8011050219 Interim Deficiency Rept 3 re failures in diesel generator assemblies Injection pumps on engines have been replaced, rocker arms reworked & placed in satisfactory condition & lubricating oil header redesigned.
COUNSIL, W.O., FOSTER, E.R. Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/29 3pp 06896-298

Operator Examinations

011040158 Responds to NRC 800731 ltr re interim criteria for shift staffing Util commits to having two licensed senior reactor operators, two licensed reactor operators & min of two auxiliary operators at each operating reactor by 820701
COUNSIL, W.O. Northeast Utilities 80/10/22. 6pp

DOCKET 50-424 ALVIN W. VOOTLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D.O. Division of Licensing. 80/09/05 209pp

011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D.O. Division of Licensing. 80/10/01. 5pp

011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D.O. Division of Licensing 80/10/06 6pp.

011060458 Advises that info re environ qualification of safety-related equipment will not be available until 801201.
EHRENSPERGER, W. Georgia Power Co 80/10/30. 1p 06915-306.

B Inspection reports, IE Bulletins & correspondence

0111210139 Forwards IE Insp Repts 50-424/80-13 & 50-425/80-13 on 800915-18 No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/08. 2pp 07037-144.

--8011210145 IE Insp Repts 50-424/80-13 & 50-425/80-13 on 800915-18. No noncompliance noted Major areas inspected: RCPB piping, safety-related piping & general const activities.
CROWLEY, B.R. Region 2, Atlanta, Office of the Director.
HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/08. 8pp 07037-146

0111260422 Forwards IE Insp Repts 50-424/80-12 & 50-425/80-12 on 800909-11. No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/09 2pp. 07072-349.

--8011260427 IE Insp Repts 50-424/80-12 & 50-425/80-12 on 800909-11. No noncompliance noted. Major areas inspected: licensee identified items, IE bulletins, inspector followup items & QA audits.
HUNT, M.D. Region 2, Atlanta, Office of the Director. BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/08. 4pp. 07072-351.

B. Reportable occurrences, LERs & related correspondence

8007240182 Final Part 21 rept re potential deficiency in Bechtel Power Corp pipe support design Corrective actions, pipe support design issue for const suspended pending preparation, approval & issue of new embed plate capacity tables.
LEX, B.L. Bechtel Power Corp. (subs. of Bechtel Corp.). 80/07/07. 7pp. 05986-214.

8011250335 Final deficiency rept, originally submitted on 800814 re defective bolting malts supplied by Southern Bolt & Fastener Co. Util determined item not reportable deficiency
Southern Co Svcs Inc 801114 ltr to util encl
DUTTON, D. Georgia Power Co 80/11/17 2pp 07055-240

DOCKET 50-425 ALVIN W. VOOTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D.O. Division of Licensing 80/09/05. 209pp

8011100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D.O. Division of Licensing 80/10/01 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D.O. Division of Licensing 80/10/06 6pp.

8011060458 Advises that info re environ qualification of safety-related equipment will not be available until 801201
EHRENSPERGER, W. Georgia Power Co 80/10/30 1p 06915-306.

B. Inspection reports, IE Bulletins & correspondence

8011210139 Forwards IE Insp Repts 50-424/80-13 & 50-425/80-13 on 800915-18 No noncompliance noted
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/08 2pp 07037-144

--8011210145 IE Insp Repts 50-424/80-13 & 50-425/80-13 on 800915-18. No noncompliance noted Major areas inspected: RCPB piping, safety-related piping & general const activities.
CROWLEY, B.R. Region 2, Atlanta, Office of the Director.
HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/08 8pp 07037-146

8011260422 Forwards IE Insp Repts 50-424/80-12 & 50-425/80-12 on 800909-11 No noncompliance noted
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/09. 2pp 07072-349.

--8011260427 IE Insp Repts 50-424/80-12 & 50-425/80-12 on 800909-11. No noncompliance noted. Major areas inspected: licensee identified items, IE bulletins, inspector followup items & QA audits.
HUNT, M.D. Region 2, Atlanta, Office of the Director. BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/08 4pp 07072-351

B. Reportable occurrences, LERs & related correspondence

8007240182 Final Part 21 rept re potential deficiency in Bechtel Power Corp pipe support design Corrective actions, pipe support design issue for const suspended pending preparation, approval & issue of new embed plate capacity tables
LEX, B.L. Bechtel Power Corp. (subs. of Bechtel Corp.). 80/07/07. 7pp 05986-214.

8011250335 Final deficiency rept, originally submitted on 800814 re defective bolting malts supplied by Southern Bolt & Fastener Co. Util determined item not reportable deficiency.
Southern Co Svcs Inc 801114 ltr to util encl
DUTTON, D. Georgia Power Co 80/11/17. 2pp 07055-240

DOCKET 50-437 FLOATING NUCLEAR PLANT

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D.O. Division of Licensing 80/09/05 209pp.

DOCKETED ITEMS

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101 EISENHUT, D O Division of Licensing 80/10/01 3pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl EISENHUT, D O Division of Licensing 80/10/06 6pp

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8011005354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101 EISENHUT, D O Division of Licensing 80/10/01 3pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl EISENHUT, D O Division of Licensing 80/10/06 6pp

8011140428 Forwards Vols 1 & 2, "Bellefonte Nuclear Plant Preoperational Aquatic Monitoring Rept, 1974-79 " EL-ASHRY, M T Tennessee Valley Authority 80/11/06 1p 04966 314

--8011140434 Vol 1, "Bellefonte Nuclear Plant Preoperational Aquatic Monitoring Rept, 1974-79 " BROQU, R N, MEINERT, D L, WADE, D C Tennessee Valley Authority HR(70)-40-2-80 1 V1 80/10/31 217pp 04966 315

--8011140438 Vol 2, "Bellefonte Nuclear Plant Preoperational Aquatic Monitoring Rept, 1974-79 " BROQU, R N, MEINERT, D L, WADE, D C Tennessee Valley Authority HR(70)-40-2-80 1 V2 80/10/31 360pp 04967 164

8011250357 Advises that response to NRC 800421 request for info on Category I masonry walls will be addressed in response to PSAR Question 210 28 MILLS, L M Tennessee Valley Authority 80/11/20 1p 07056 121

F Security, medical, emergency & fire protection plans

8011030347 Forwards addl info & revisions to security personnel training & qualification plans Info withheld (ref 10CFR2 790) MILLS, L M Tennessee Valley Authority 80/10/27 1p

G Inspection reports, IE Bulletins & correspondence

801170687 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24 1p

8011200405 Ack receipt of 800827 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-12 & 50-439/80-12 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/03 1p 07020 072

--8011200411 Forwards revised response to NRC 800730 ltr re violations noted in IE Insp Repts 50-438/80-12 & 50-439/80-12 Corrective actions pipes cleaned, capped & will be in full compliance by 801114 MILLS, L M Tennessee Valley Authority 80/10/14 7pp 07020 073

--8011200417 Confirms 800925 meeting in Knoxville, TN to discuss IE Insp Repts 50-438/80-12 & 50-439/80-12 on 800616-20 & evaluation identified in util 800827 ltr O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/11 1p 07020 080

--8011200422 Responds to NRC 800730 ltr re violations noted in IE Insp Repts 50-438/80-12 & 50-439/80-12 Corrective actions pipes capped in compliance w/General Const Spec 0-29M MILLS, L M Tennessee Valley Authority 80/08/27 8pp 07020 081.

--8011200425 Forwards IE Insp Repts 50-438/80-12 & 50-439/80-12 on 800616-20 & notice of violation MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/30 1p 07020 087

--8011200427 Notice of violation from Insp on 800616-20 * Region 2, Atlanta, Office of the Director 80/07/25 3pp 07020 091

--8011200430 IE Insp Repts 50-438/80-12 & 50-439/80-12 on 800616-20 Noncompliance noted failure to follow procedure for storage & protection of permanent const matl COLEY, J L Region 2, Atlanta, Office of the Director HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/25 7pp 07020 094

S Reportable occurrences, LERs & related correspondence

8011060688 Part 21 rept re 480-volt MCC control transformer fuses, reported on 800808 Awaiting assessment by vendor, Gould-Brown Boveri Next rept by 810116 MILLS, L M Tennessee Valley Authority 80/10/24 2pp 04914 333

8011050472 First interim deficiency rept re socket weld misalignment on essential air sys welds failed to meet specs & procedures & are being evaluated to determine whether they satisfy seismic Category I loading requirements MILLS, L M Tennessee Valley Authority 80/10/29 2pp 06897 258

8011070389 First interim deficiency rept re main steam line analysis trips input error Areas of proper application, placement & timing of forcing functions questioned Steam hammer analysis under re-evaluation MILLS, L M Tennessee Valley Authority 80/10/31 2pp 04921 050

8011190781 Part 21 rept re Borg Warner 3-inch motor operated gate valves Valve failure to close completely caused by lack of proper guiding & high bearing stress between gates & seats Next rept to be submitted 810213 MILLS, L M Tennessee Valley Authority 80/11/06 3pp 04946 120.

8011210448 Part 21 rept re differential pressure indicators on air cleanup units, initially reported on 800801 Util working w/CFI Nuclear to resolve deficiency, MILLS, L M Tennessee Valley Authority 80/11/10 2pp. 02227 001

801180488 Final interim deficiency rept originally reported on 800805 re RCB pump cases out of level B&W level tolerance of 0 125 inches exceeded on two of four RCB pump casings B&W review noted that out-of-tolerance pump cases are usable as is MILLS, L M Tennessee Valley Authority 80/11/12 2pp 04988 168

V Operator Examinations

8011140325 Forwards info describing operator training & qualification programs which comply w/criteria addressed in 800328 ltr to all power reactor applicants & licensees MILLS, L M Tennessee Valley Authority 80/11/10 8pp

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements EISENHUT, D O. Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101 EISENHUT, D O Division of Licensing 80/10/01 3pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl, EISENHUT, D O. Division of Licensing 80/10/06 6pp.

8011140428 Forwards Vols 1 & 2, "Bellefonte Nuclear Plant Preoperational Aquatic Monitoring Rept, 1974-79"
EL-ASHRY, M T Tennessee Valley Authority 80/11/06 1p 06966 314

--8011140434 Vol 1, "Bellefonte Nuclear Plant Preoperational Aquatic Monitoring Rept, 1974-79"
BROWN, R N, MEINERT, D L, WADE, D C Tennessee Valley Authority
NR(70)-40-2-80 1 V1 80/10/31 217pp 06966 313

--8011140438 Vol 2, "Bellefonte Nuclear Plant Preoperational Aquatic Monitoring Rept, 1974-79"
BROWN, R N, MEINERT, D L, WADE, D C Tennessee Valley Authority
NR(70)-40-2-80 1 V2 80/10/31 360pp 06967 164

8011250357 Advises that response to NRC 800421 request for info on Category I masonry walls will be addressed in response to FBAR Question 210 28
MILLS, L M Tennessee Valley Authority 80/11/20 1p 07056 121

F Security, medical, emergency & fire protection plans

8011030367 Forwards addl info & revisions to security personnel training & qualification plans info withheld (ref 10CFR2.790).
MILLS, L M Tennessee Valley Authority 80/10/27 1p

Q Inspection reports, IE Bulletins & correspondence

8011170687 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24 1p 06976 234

8011200405 Ack receipt of 800827 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-12 & 50-439/80-12
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/03 1p 07020 072

--8011200411 Forwards revised response to NRC 800730 ltr re violations noted in IE Insp Repts 50-438/80-12 & 50-439/80-12
Corrective actions pipes cleaned, capped & will be in full compliance by 801114
MILLS, L M Tennessee Valley Authority 80/10/14 7pp 07020 073

--8011200417 Confirms 800925 meeting in Knoxville, TN to discuss IE Insp Repts 50-438/80-12 & 50-439/80-12 on 800616-20 & evaluation identified in util 800827 ltr
O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/09/11 1p 07020 080

--8011200422 Responds to NRC 800730 ltr re violations noted in IE Insp Repts 50-438/80-12 & 50-439/80-12 Corrective actions: pipes capped in compliance w/General Const Spec Q-29M
MILLS, L M Tennessee Valley Authority 80/08/27 8pp 07020 081

--8011200425 Forwards IE Insp Repts 50-438/80-12 & 50-439/80-12 on 800616-20 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/07/30 1p 07020 089

--8011200427 Notice of violation from insp on 800616-20, + Region 2, Atlanta, Office of the Director 80/07/25 3pp 07020 091

--8011200430 IE Insp Repts 50-438/80-12 & 50-439/80-12 on 800616-20 Noncompliance noted failure to follow procedure for storage & protection of permanent const matl
COLEY, J L Region 2, Atlanta, Office of the Director HERDT, A R, Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/25 7pp 07020, 094

B Reportable occurrences, LERs & related correspondence

8011060688 Part 21 rept re 480-volt MCC control transformer fuses, reported on 800808 Awaiting assessment by vendor, Gould-Brown Boveri Next rept by 810116
MILLS, L M Tennessee Valley Authority 80/10/24 2pp 06914 333.

8011030472 First interim deficiency rept re socket weld misalignment on essential air sys welds Welds failed to meet specs & procedures & are being evaluated to determine whether they satisfy seismic Category I loading requirements.
MILLS, L M Tennessee Valley Authority, 80/10/29, 2pp. 06897 258.

8011070389 First interim deficiency rept re main steam line analysis tripe input error Areas of proper application, placement & timing of forcing functions questioned Steam hammer analysis under re-evaluation
MILLS, L M Tennessee Valley Authority 80/10/31 2pp 06921 050

8011190281 Part 21 rept re Borg Warner 3-inch motor operated gate valves Valve failure to close completely caused by lack of proper guiding & high bearing stress between gates & seats
Next rept to be submitted 810213
MILLS, L M Tennessee Valley Authority 80/11/06 3pp 06996 120

8011130381 Third interim deficiency rept re welding of structural annulus floor framing Util finalizing records search to identify welding insps Checks will be made to determine nature of deficiency Next rept will be sent 810220
MILLS, L M Tennessee Valley Authority 80/11/07 2pp 06959 220

8011210448 Part 21 rept re differential pressure indicators on air cleanup units, initially reported on 800801 Util working w/CTI Nuclear to resolve deficiency
MILLS, L M Tennessee Valley Authority 80/11/10 2pp 02227 001

V Operator Examinations

8011140325 Forwards info describing operator training & qualification programs which comply w/criteria addressed in 800328 ltr to all power reactor applicants & licensees
MILLS, L M Tennessee Valley Authority 80/11/10 8pp

DOCKET 80-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

8011060054 Forwards NRC position re application of cladding swelling & rupture models for LOCA analyses Requests supplemental calculations described in encl & schedule for response
TEDESCH, R L Assistant Director for Licensing 80/10/17 3pp 06911 161

8011070464 Responds to NRC 801001 ltr re environ qualification of safety-related equipment Environ qualifications have been delegated to individual vendors List of equipment undergoing qualification testing encl
OROSEUP, G W Cleveland Electric Illuminating Co 80/10/31 2pp. 06924 360

8011260097 Responds to question re documents on microfiche raised during NRC presentation at 800708 Records Mgt Association Symposium Authorized person must ascertain that document is latest revision
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/04 2pp. 07075 332

8011210283 Requests detailed info re free standing steel containment including layout & fabrication drawings, penetration locations & matl properties test repts by 801128
TEDESCH, R L Assistant Director for Licensing 80/11/05 2pp 07030 120

C Utility Environmental Report (ER), amends & correspondence

8011210700 Forwards environ rept for acceptance review Review tentatively scheduled to begin in Feb 1981 w/completion in Apr 1981. W/o encl.
HOUSTON, M D, Licensing Branch 2 FIN A-211B, 80/10/15 1p 07029 142.

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

- 8011040113 Forwards IE Insp Repts 50-440/80-13 & 50-441/80-12 on 800730-0801 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/30 2pp 06912 201
- 8011060133 IE Insp Rept 50-440/80-13 & 50-441/80-12 on 800730-0801 No noncompliance noted Major areas inspected licensee & contractor procedures, QA design control documents & records re reactor coolant loop piping installation
WILLIAMS, C C, KONKLIN, J E, KEY, W J Region 3, Chicago, Office of the Director 80/08/28 9pp 06912 203
- 8011260335 Forwards IE Insp Repts 50-440/80-15 & 50-441/80-14 on 800819-22 & notice of violation.
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/12 2pp 07072 269
- 8011260339 Notice of violation from insp on 800819-22
* Region 3, Chicago, Office of the Director 80/09/10 1p 07072 271
- 8011260348 IE Insp Repts 50-440/80-15 & 50-441/80-14 on 800819-22 Noncompliance noted housekeeping conditions in anchor bolt area of reactor pressure vessel out of control
ERB, C M Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/10 4pp 07072 272.
- 8011260354 Forwards IE Insp Rept 50-440/80-18 on 800827-29 & notice of violation
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/12 2pp 07072 282.
- 8011260357 Notice of violation from insp on 800827-29
* Region 3, Chicago, Office of the Director 80/09/11 1p 07072 284
- 8011260364 IE Insp Rept 50-440/80-18 on 800827-29 Noncompliance noted bead width of Weld 6 on Isometric Drawing 1-E22-5 & Weld 6 on Drawing 1-E12-32 exceeded procedure requirement.
LEE, E W K Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/11 6pp 07072 283
- 8011030084 Forwards IE Insp Repts 50-440/80-16 & 50-441/80-15 on 800801-31 & notice of violation
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/18 2pp 06857 159
- 8011030088 Notice of violation from insp on 800801-31
* Region 3, Chicago, Office of the Director 80/09/17 1p 06857 161
- 8011030093 IE Insp Repts 50-440/80-16 & 50-441/80-15 on 800801-31 Noncompliance noted inadequate review of fire dampers
HUGHES, J, WILLIAMS, C C Region 3, Chicago, Office of the Director 80/09/17 15pp 06857 162
- 8011060242 Forwards IE Insp Repts 50-440/80-17 & 50-441/80-16 on 800826-28 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/18 2pp 06911 176
- 8011060251 IE Insp Repts 50-440/80-17 & 50-441/80-16 on 800826-28 No noncompliance noted Major areas inspected status of ASME code compliance activities & licensee actions re review of IE bulletins & circulars
KONKLIN, J E, WILLIAMS, C C Region 3, Chicago, Office of the Director 80/09/17 5pp 06911 198
- 011105337 Forwards IE Insp Repts 50-440/80-14 & 50-441/80-13 on 800819-21 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/10/04 2pp 06975 075
- 8011170541 Notice of violation from insp on 800819-21.
* Office of Inspection & Enforcement, Office of the Director. 80/10/02 1p, 06975 097
- 8011170544 IE Insp Repts 50-440/80-14 & 50-441/80-13 on 800819-21 Noncompliance noted failure to conduct noise surveys semiannually
* Region 3, Chicago, Office of the Director. 80/10/02 1p, 06975 098
- 8011230067 Forwards IE Insp Repts 50-440/80-22 & 50-441/80-20 on 800929-1002 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/20 2pp 07056 235
- 8011230072 IE Insp Repts 50-440/80-22 & 50-441/80-20 on 800929-1002 No noncompliance noted Major areas inspected nondestructive examination procedures, personnel certifications, equipment & review of radiographs
WARD, K D Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/17 12pp 07056 237
- 8011230049 Forwards IE Insp Repts 50-440/80-19 & 50-441/80-17 on 800902-30 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/23 2pp 07056 212
- 8011230053 IE Insp Repts 50-440/80-19 & 50-441/80-17 on 800902-30 No noncompliance noted Major areas inspected safety-related const activities including welding of safety-related fluid piping sys
HUGHES, J, WILLIAMS, C C Region 3, Chicago, Office of the Director 80/10/22 10pp 07056 214
- 8011070260 Forwards Suppl 3 to IE Bulletin 79-018, "Environ dualification of Class IE Equipment " No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/24 1p 06924 231
- 8011040191 Ack receipt of 801018 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-15 & 50-441/80-14
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/28 1p 06884 336
- 8011040194 Responds to NRC 800912 ltr re violations noted in IE Insp Repts 50-440/80-15 & 50-441/80-14 Corrective actions removal of water & debris & subsequent maint completed
DAVIDSON, D R Cleveland Electric Illuminating Co 80/10/15 2pp 06884 337
- 8011280235 Forwards IE Insp Repts 50-440/80-23 & 50-441/80-21 on 801007-10 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/26 2pp 07083 305
- 8011280237 IE Insp Repts 50-440/80-23 & 50-441/80-21 on 801007-10 No noncompliance noted Major areas inspected safety-related electrical work activities & QA records
LEE, R L Region 3, Chicago, Office of the Director HAYES, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/27 5pp 07083 307
- 8011190467 Ack receipt of 801022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-16 & 50-441/80-15
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/03 1p, 06998 102.
- 8011190472 Responds to NRC 800918 ltr re violations noted in IE Insp Repts 50-440/80-16 & 50-441/80-15 Corrective actions notes added to diagrams to identify that fire dampers are exception to safety-related classification
DAVIDSON, D R Cleveland Electric Illuminating Co 80/10/22 2pp, 06998 103
- 8011210444 Ack receipt of 801027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-14 & 50-441/80-13
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/12 1p 07029 197
- 8011210447 Responds to NRC 801006 ltr re violations noted in IE Insp Repts 50-440/80-14 & 50-441/80-13 Corrective actions noise surveys will be made semiannually by nuclear test section of nuclear engineering.
DAVIDSON, D R Cleveland Electric Illuminating Co 80/10/27 2pp 07029 198.
- G Reportable occurrences, LERs & related correspondence
- 8011200238 Ack receipt of 800929 interim deficiency rept re Cutler Hammer motor control ctrs.
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/17 1p 07019 356

8011070406 Interim deficiency rept re mfg defect in DeLaval standby diesel generators, Models DSRV12, DSRV16 & DSRV20 built before 800201 (ref DeLaval 800919 Part 21 rept) Possibly caused by defective link rod Final rept will be submitted by 801201
DAVIDSON, D.R. Cleveland Electric Illuminating Co. 80/11/03. 2pp
06924 338

801140043 Interim deficiency rept originally reported on 801010 re qualification testing of Hilti-Kwik bolts Nonconformance Rept CGA 144, Revision 1, documents problem & ensures proper tracking & closeout. Evaluation planned upon test completion
DAVIDSON, D.R. Cleveland Electric Illuminating Co. 80/11/06. 3pp
06960 331.

801180491 Interim deficiency rept originally reported on 801006 re problem w/stainless steel cladding in suppression pools. Clad matl possibly sensitized during normalizing process. Licensee evaluating problem Final rept will be submitted by 810301
DAVIDSON, D.R. Cleveland Electric Illuminating Co. 80/11/12 3pp
06988 170.

DOCKET 80-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for GLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D.Q. Division of Licensing. 80/09/05. 209pp.

801100486 Ltr to all licensees of operating plants & applicants for GLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D.Q. Division of Licensing. 80/10/01. 5pp.

801100837 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports." W/o encl
EISENHUT, D.Q. Division of Licensing 80/10/06 6pp.

801100054 Forwards NRC position re application of cladding swelling & rupture models for LOCA analyses. Requests supplemental calculations described in encl & schedule for response.
TEDESCO, R.L. Assistant Director for Licensing. 80/10/17 3pp.
06911:161.

8011070464 Responds to NRC 801001 ltr re environ qualification of safety-related equipment. Environ qualifications have been delegated to individual vendors List of equipment undergoing qualification testing encl.
GRUBER, O.W. Cleveland Electric Illuminating Co. 80/10/31. 2pp
06924, 340.

8011240099 Responds to question re documents on microfiche raised during NRC presentation at 800908 Records Mgt Association Symposium. Authorized person must ascertain that document is latest revision.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/04 2pp 07075, 332.

8011210753 Requests detailed info re free standing steel containment including layout & fabrication drawings, penetration locations & matl properties test repts by 801128.
TEDESCO, R.L. Assistant Director for Licensing. 80/11/05. 2pp.
07030; 120.

C Utility Environmental Report (ER), amends & correspondence

8011210700 Forwards environ rept for acceptance review Review tentatively scheduled to begin in Feb 1981 w/completion in Apr 1981. W/o encl.
HOUSTON, M.D. Licensing Branch 2 FIN A-2118. 80/10/15. 1p.
07029; 142

D Inspection reports, IE Bulletins & correspondence

8011060119 Forwards IE Insp Repts 50-440/80-13 & 50-441/80-12 on 800730-0801. No noncompliance noted
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/08/30 2pp. 06912:201.

--8011060133 IE Insp Rept 50-440/80-13 & 50-441/80-12 on 800730-0801. No noncompliance noted Major areas inspected: licensee & contractor procedures, QA design control documents & records re reactor coolant loop piping installation.
WILLIAMS, C.C., KONKLIN, J.E., KEY, W.J. Region 3, Chicago, Office of the Director. 80/08/28. 9pp 06912:203.

8011260335 Forwards IE Insp Repts 50-440/80-13 & 50-441/80-14 on 800819-22 & notice of violation
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/09/12 2pp 07072 269

--8011260339 Notice of violation from insp on 800819-22
* Region 3, Chicago, Office of the Director 80/09/10 1p
07072 271

--8011260348 IE Insp Repts 50-440/80-13 & 50-441/80-14 on 800819-22 Noncompliance noted housekeeping conditions in anchor bolt area of reactor pressure vessel out of control
ERB, C.M. Region 3, Chicago, Office of the Director
DANIELSON, D.H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/10. 4pp 07072 272

8011030084 Forwards IE Insp Repts 50-440/80-16 & 50-441/80-15 on 800801-31 & notice of violation
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/18 2pp 06897 159

--8011030088 Notice of violation from insp on 800801-31
* Region 3, Chicago, Office of the Director 80/09/17. 1p.
06897 161

--8011030093 IE Insp Repts 50-440/80-16 & 50-441/80-15 on 800801-31 Noncompliance noted. Inadequate review of fire dampers.
HUQES, J., WILLIAMS, C.C. Region 3, Chicago, Office of the Director 80/09/17 13pp 06897 162.

8011060242 Forwards IE Insp Repts 50-440/80-17 & 50-441/80-16 on 800826-28 No noncompliance noted
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/18 2pp. 06911:196

--8011060251 IE Insp Repts 50-440/80-17 & 50-441/80-16 on 800826-28 No noncompliance noted Major areas inspected status of ASME code, compliance activities & licensee actions re review of IE bulletins & circulars
KONKLIN, J.E., WILLIAMS, C.C. Region 3, Chicago, Office of the Director 80/09/17. 3pp 06911 198

801170537 Forwards IE Insp Repts 50-440/80-14 & 50-441/80-13 on 800819-21 & notice of violation.
DAVIS, A.B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/10/06 2pp 06973 093

--801170541 Notice of violation from insp on 800819-21
* Office of Inspection & Enforcement, Office of the Director 80/10/02 1p. 06973 097

--801170544 IE Insp Repts 50-440/80-14 & 50-441/80-13 on 800819-21 Noncompliance noted. Failure to conduct noise surveys semiannually
* Region 3, Chicago, Office of the Director. 80/10/02. 1p.
06973 098

8011250067 Forwards IE Insp Repts 50-440/80-22 & 50-441/80-20 on 800929-1002. No noncompliance noted
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/20 2pp. 07056:233

--8011250072 IE Insp Repts 50-440/80-22 & 50-441/80-20 on 800929-1002. No noncompliance noted. Major areas inspected. nondestructive examination procedures, personnel certifications, equipment & review of radiographs.
WARD, K.D. Region 3, Chicago, Office of the Director.
DANIELSON, D.H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/17 12pp 07056, 237

8011250049 Forwards IE Insp Repts 50-440/80-19 & 50-441/80-17 on 800902-30. No noncompliance noted.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/23 2pp 07056 212

--8011250053 IE Insp Repts 50-440/80-19 & 50-441/80-17 on 800902-30 No noncompliance noted Major areas inspected safety-related const activities including welding of safety-related fluid piping sys
HUQES, J., WILLIAMS, C.C. Region 3, Chicago, Office of the Director 80/10/22 10pp. 07056 214.

8011070260 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required.
KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/10/24. 1p. 06924 251.

DOCKETED ITEMS

8011040191 Ack receipt of 801015 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-440/80-15 & 80-441/80-14
 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/28. 1p 06884 356

--8011040194 Responds to NRC 800912 ltr re violations noted in IE Insp Repts 80-440/80-15 & 80-441/80-14. Corrective actions: removal of water & debris & subsequent maint completed
 DAVISON, D R Cleveland Electric Illuminating Co. 80/10/15. 2pp 06884 357

8011280235 Forwards IE Insp Repts 80-440/80-23 & 80-441/80-21 on 801007-10 No noncompliance noted
 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/28 2pp 07083 305

--8011280237 IE Insp Repts 80-440/80-23 & 80-441/80-21 on 801007-10 No noncompliance noted Major areas inspected: safety-related electrical work activities & QA records.
 LEE, R L Region 3, Chicago, Office of the Director HAYES, D. W. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/27 3pp 07083 307

8011190467 Ack receipt of 801022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-440/80-16 & 80-441/80-15
 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/03 1p 06998 102

--8011190472 Responds to NRC 800918 ltr re violations noted in IE Insp Repts 80-440/80-16 & 80-441/80-15 Corrective actions: notes added to diagrams to identify that fire dampers are exception to safety-related classification
 DAVISON, D R Cleveland Electric Illuminating Co. 80/10/22 2pp. 06998 103

8011210444 Ack receipt of 801027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-440/80-14 & 80-441/80-13
 DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/11/12. 1p 07029 197.

--8011210447 Responds to NRC 801006 ltr re violations noted in IE Insp Repts 80-440/80-14 & 80-441/80-13 Corrective actions: noise surveys will be made semiannually by nuclear test section of nuclear engineering
 DAVISON, D R Cleveland Electric Illuminating Co. 80/10/27 2pp. 07029 198

B. Reportable occurrences, LERs & related correspondence

8011200238 Ack receipt of 800929 interim deficiency rept re Cutler-Hammer motor control ctrs
 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/17 1p 07019 356.

8011070406 Interim deficiency rept re mfg defect in DeLaval standby diesel generators, Models D8RV12, D8RV16 & D8RV20 built before 800201 (ref DeLaval 800919 Part 21 rept) Possibly caused by defective link rod. Final rept will be submitted by 801201
 DAVISON, D R Cleveland Electric Illuminating Co. 80/11/03. 2pp. 06924 358.

8011140043 Interim deficiency rept originally reported on 801010 re qualification testing of Hilti-Kwik bolts Nonconformance Rept CQA 164, Revision 1, documents problem & ensures proper tracking & closeout Evaluation planned upon test completion.
 DAVISON, D R Cleveland Electric Illuminating Co. 80/11/06. 3pp. 06960 331

8011180491 Interim deficiency rept originally reported on 801006 re problem w/ stainless steel cladding in suppression pools Clad matl possibly sensitized during normalizing process. Licensee evaluating problem Final rept will be submitted by 801201.
 DAVISON, D. R Cleveland Electric Illuminating Co. 80/11/12 3pp 06988 170

DOCKET 80-443 SEABROOK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8011170314 Responds to NRC 801001 ltr re environ qualification of safety-related equipment. Majority of safety-related equipment has been tested exclusive of vibration testing. All tests should be completed by Feb 1981 Summary encl.
 DEVENCENTI, J. Public Service Co. of New Hampshire. 80/11/05. 2pp. 06960 001

8011190371 Forwards Amend 41 to DL application Amend relates to applicant request for reinstatement of prior authorization for transfer from CT Light & Power Co to Fitchburg Gas & Electric Light Co.
 RITSHER, J. A. Ropes & Gray. 80/11/18 1p 07006 209.

--8011190378 Amend 41 to application for DL requesting partial transfer of ownership from CT Light & Power Co to Fitchburg Gas & Electric Light Co Certificate of Svc & applicant general info encl.
 MERRILL, D. N. Public Service Co. of New Hampshire. 80/11/10 13pp 07006 220

--8011190383 Order approving Montaup Electric Co acquisition of 1% interest in project from PSC of NH Fitchburg Gas & Electric Light Co acquisition of percentages of interest in project
 POTE, D. R., BDNBALL, J. N., SPRADUE, G. R. Massachusetts, State of. 80/10/30 303pp 07006 223.

--8011190396 Order directing consolidation of instant petitions for further hearing, investigation & consideration w/ petition docketed as DPH 20035
 POTE, D. R., BDNBALL, J. N., SPRADUE, G. R. Massachusetts, State of. 79/06/28 13pp 07007 168

F. Security, medical, emergency & fire protection plans

8011180321 Forwards facility emergency planning info for placement in LPDR. W/o encl.
 BOUDER, J. L. Division of Rules and Records. 80/11/04. 1p 06991 159.

G. Adjudicatory correspondence

8011030552 Informs that 800630 ltr will be considered as request for order suspending or revoking facility CPs re petition on behalf of Seacoast Anti-Pollution League, requesting relief based on concerns re emergency planning. Notice encl.
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 80/10/21 2pp. 06873 010

--8011030557 Notice of denial to review 800211 HR Denton decision per 2, 205 re RA Beckus petition on behalf of Seacoast Anti-Pollution League, requesting relief based on concerns re emergency planning & severe accident considerations.
 CASE, E. G. Office of Nuclear Reactor Regulation, Director. 80/10/21. 2pp 06873 013

8011040392 Motion to suspend const re Commission 800925 order to reopen record for addl seismic hazards evidence. Burden of proof falls on applicant to issue seismic reanalysis & demonstrate safety of continuing const w/ Certificate of Svc.
 WEISS, E. R., JORDAN, W. B. New England Coalition on Nuclear Pollution. 80/10/29. 8pp 06873 247.

8011040409 Order directing applicants to advise Board of current const status & future work schedule re bldgs & components affected by Commission remand, in response to New England Coalition on Nuclear Pollution motion for CP suspension
 BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 80/10/30 1p 06873 267

8011040448 Responds to 801013 ltr re desire to testify at hearings. Explains controversy of emergency planning issues.
 LEBBY, R. P. Antitrust Division. 80/10/31. 2pp 06873 286.

8011050177 Request to honor encl MA Chinnery 801023 desire to be called as ASLB witness. Board should provide assistance to Trifunac re points of testimony Responds to applicant & NRC procedural points.
 WEISS, E. R., JORDAN, W. B. New England Coalition on Nuclear Pollution. 80/10/31 7pp 06899 037.

8011240354 Requests, on behalf of util, that new general counsel, DP Cameron, be added to svc list
 RITSHER, J. A. Ropes & Gray. 80/11/03. 1p 07049 092

8011280003 Requests that name of util general counsel, DPO Cameron, be added to svc list.
 RITSHER, J. A. Ropes & Gray. 80/11/03 1p 07083 337.

8011100451 Memorandum & order granting New England Coalition on Nuclear Pollution request to call M. Trifunac as ASLB witness. Denies similar request re MA Chinnery Prepared testimony shall be filed by 801216 Evidentiary hearing shall start on 801406
 BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 80/11/06. 8pp. 06929 313.

DOCKETED ITEMS

2

801100425 Forwards Aug 1980 NUREG/CR-1582, Vols 2 & 3. "Seismic Hazard Analysis, Solicitation of Expert Opinion," prepared by TERA Corp. W/o encl.
LESBY, R.P. Hearing Branch 3 80/11/06 1p 06940:357

801101006 Response in opposition to New England Coalition on Nuclear Pollution motion to suspend const Virginia Petroleum Jobbers test provides no basis for suspension. Balancing of equities favors denial of motion. Certificate of Bvc encl.
DIGNAN, T.O., QAD, R.K. Public Service Co. of New Hampshire
DIGNAN, T.O., Ropes & Gray. 80/11/13 11pp 06998:341

--801101018 Affidavit submitting three charts showing present status of safety-related structures & completion of design. Certificate of Bvc encl.
DEVINGENTIS, J. Yankee Atomic Electric Co 80/11/12 6pp 06998:332.

801100340 Forwards response to motion to suspend const. Notice of appearance & Certificate of Bvc encl.
LIPELES, M.I. Massachusetts, State of 80/11/13. App 07018:167.

--801100341 Response to Intervenor New England Coalition on Nuclear Pollution motion to suspend const of facility. Supports motion w/ limitations to structures potentially affected by remain.
BECKER, S.K., LIPELES, M.I. Massachusetts, State of. 80/11/13. 6pp. 07018:171.

801100746 Brief in opposition to New England Coalition on Nuclear Pollution petition to suspend const. Continuation of const activities will not foreclose const alternatives if structural engineering mode determined necessary.
LESBY, R.P. Antitrust Division 80/11/18. 14pp. 07003:285.

--801100751 Affidavit re continuation of const activities at site. Continuation over next six months will not foreclose const alternatives if seismic-related engineering mode required. Certificate of Bvc encl.
KNIIGHT, J.P. Assistant Director for Components & Structures Engineering. 80/11/18 4pp. 07003:301.

8011230690 Forwards "Seismic Hazard Analysis," NUREG/CR-1582, Vols 2 & 3 to E Weiss on behalf of M Chinnery W/o encl.
LESBY, R.P. Antitrust Division 80/11/21. 1p. 07068:209

I. Financial information.

801100371 Forwards Amend 41 to DL application. Amend relates to applicant request for reinstatement of prior authorization for transfer from CT Light & Power Co to Fitchburg Gas & Electric Light Co.
RITBHER, J.A. Ropes & Gray. 80/11/18. 1p. 07006:209.

--801100378 Amend 41 to application for DL requesting partial transfer of ownership from CT Light & Power Co to Fitchburg Gas & Electric Light Co. Certificate of Bvc & applicant general info encl.
MERRILL, D.N. Public Service Co. of New Hampshire. 80/11/10 13pp. 07006:220.

--801100383 Order approving Montaup Electric Co acquisition of 1% interest in project from PSC of NH Fitchburg Gas & Electric Light Co acquisition of percentages of interest in project.
POTE, D.R., BONBALL, J.N., SPRAQUE, O.R. Massachusetts, State of. 80/10/30. 303pp. 07006:225

--801100396 Order directing consolidation of instant petitions for further hearing, investigation & consideration w/petition docketed as DPH 20035
POTE, D.R., BONBALL, J.N., SPRAQUE, O.R. Massachusetts, State of. 79/06/28. 13pp. 07007:168.

G. Inspection reports, IE Bulletins & correspondence

801100344 Forwards IE Insp Repts 80-443/80-09 & 80-444/80-09 on 800804-0905 No noncompliance noted.
CARLBON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/26. 2pp. 06929:238

--801100353 IE Insp Repts 80-443/80-09 & 80-444/80-09 on 800804-0905, No noncompliance noted. Major areas inspected piping erection & pipe support welding activities, structural steel erection, component support welding & storage.
CERNE, A.C. Region 1, Philadelphia, Office of the Director.
MCQUAGHY, R.W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/09/25. 12pp. 06929:240.

801100638 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/24 1p 06909:313

8011070330 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/24. 1p 06922:02b

801140116 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/31 1p. 06963:359

801170563 Forwards IE Info Notice 80-39, "Malfunction of Bolensoid Valves Hfg by Valcor Engineering Corp." No written response is required
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 80/10/31. 1p 06979:209

S. Reportable occurrences, LERs & related correspondence

801140403 Interim deficiency rept re defective cooling tower concrete beams, initially reported on 801008. Testing is in process to determine if significant deficiency exists & will be completed by 801216.
DEVINGENTIS, J. Public Service Co. of New Hampshire 80/11/06 1p 06962:347

DOCKET 80-444 SEABROOK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

801120314 Responds to NRC 801001 ltr re environ qualification of safety-related equipment. Majority of safety-related equipment has been tested exclusive of vibration testing. All tests should be completed by Feb 1981 Summary encl.
DEVINGENTIS, J. Public Service Co. of New Hampshire. 80/11/05 2pp. 06960:001.

801100371 Forwards Amend 41 to DL application. Amend relates to applicant request for reinstatement of prior authorization for transfer from CT Light & Power Co to Fitchburg Gas & Electric Light Co
RITBHER, J.A. Ropes & Gray. 80/11/18 1p. 07006:209

--801100378 Amend 41 to application for DL requesting partial transfer of ownership from CT light & Power Co to Fitchburg Gas & Electric Light Co Certificate of Bvc & applicant general info encl.
MERRILL, D.N. Public Service Co. of New Hampshire 80/11/10. 13pp. 07006:220.

--801100383 Order approving Montaup Electric Co acquisition of 1% interest in project from PSC of NH Fitchburg Gas & Electric Light Co acquisition of percentages of interest in project.
POTE, D.R., BONBALL, J.N., SPRAQUE, O.R. Massachusetts, State of. 80/10/30. 303pp 07006:225.

--801100396 Order directing consolidation of instant petitions for further hearing, investigation & consideration w/petition docketed as DPH 20035
POTE, D.R., BONBALL, J.N., SPRAQUE, O.R. Massachusetts, State of. 79/06/28 13pp. 07007:168

F Security, medical, emergency & fire protection plans

801180321 Forwards facility emergency planning info for placement in LPRR W/o encl.
SOUDER, J.L. Division of Rules and Records 80/11/04. 1p. 06991:157

G. Adjudicatory correspondence

8011030552 Informs that 800630 ltr will be considered as request for order suspending or revoking facility CPs re petition on behalf of Seacoast Anti-Pollution League, requesting relief based on concerns re emergency planning Notice encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 80/10/21. 2pp. 06873:010.

DOCKETED ITEMS

--8011030557 Notice of denial to review 800211 HR Denton decision per 2 205 re RA Backus petition on behalf of Seacoast Anti-Pollution League requesting relief based on concerns re emergency planning & severe accident considerations
CASE, E.O. Office of Nuclear Reactor Regulation, Director
80/10/21 2pp 06873 013

8011040392 Motion to suspend const re Commission 800925 order to reopen record for addl seismic hazards evidence Burden of proof falls on applicant to issue seismic reanalysis & demonstrate safety of continuing const w/ Certificate of Bvc
WEIBS, E.R. JORDAN, W.S. New England Coalition on Nuclear Pollution
WEIBS, E.R. Sheldon, Harmon & Weiss 80/10/29 8pp. 06873:247

8011040409 Order directing applicants to advise Board of current const status & future work schedule re bldgs & components affected by Commission remand, in response to New England Coalition on Nuclear Pollution motion for CP suspension
BISHOP, C.J. Atomic Safety and Licensing Appeal Panel 80/10/30.
1p 06873 267

8011040448 Responds to 801013 ltr re desire to testify at hearings Explains controversy of emergency planning issues.
LESSBY, R.P. Antitrust Division 80/10/31 2pp 06873:286

8011050177 Request to honor encl MA Chinnery 801023 desire to be called as ASLB witness Board should provide assistance to Trifunac re points of testimony Responds to applicant & NRC procedural points.
WEIBS, E.R. JORDAN, W.S. New England Coalition on Nuclear Pollution.
WEIBS, E.R. Sheldon, Harmon & Weiss 80/10/31 7pp 06899:057.

8011240354 Requests, on behalf of util, that new general counsel, DP Cameron, be added to svc list
RITSHER, J.A. Ropes & Gray 80/11/05. 1p 07049 092

8011280003 Requests that name of util general counsel, DPO Cameron, be added to svc list.
RITSHER, J.A. Ropes & Gray. 80/11/05. 1p 07083 357

801100451 Memorandum & order granting New England Coalition on Nuclear Pollution request to call M Trifunac as ASLB witness. Denies similar request re MA Chinnery Prepared testimony shall be filed by 810216 Evidentiary hearing shall start on 810406.
BISHOP, C.J. Atomic Safety and Licensing Appeal Panel. 80/11/06.
6pp. 06929 313

801100625 Forwards Aug 1980 NUREG/CR-1582, Vols 2 & 3, "Seismic Hazard Analysis, Solicitation of Expert Opinion," prepared by TERA Corp w/o encl
LESSBY, R.P. Hearing Branch 3 80/11/06 1p 06940 357.

8011190106 Response in opposition to New England Coalition on Nuclear Pollution motion to suspend const Virginia Petroleum Jobbers test provides no basis for suspension Balancing of equities favors denial of motion, Certificate of Bvc encl
DIGNAN, T.O. GAD, R.K. Public Service Co of New Hampshire
DIGNAN, T.O. Ropes & Gray 80/11/13 11pp 06998:341

--8011190118 Affidavit submitting three charts showing present status of safety-related structures & completion of design, Certificate of Bvc encl
DEVINGENTIS, J. Yankee Atomic Electric Co. 80/11/12 6pp
06998 352

8011200340 Forwards response to motion to suspend const, Notice of appearance & Certificate of Bvc encl
LIFELES, M.I. Massachusetts, State of 80/11/13. 4pp. 07018.167

--8011200341 Response to Intervenor New England Coalition on Nuclear Pollution motion to suspend const of facility. Supports motion w/ limitations to structures potentially affected by remand.
BECKER, S.K. LIFELES, M.I. Massachusetts, State of 80/11/13
6pp 07018:171

8011190746 Brief in opposition to New England Coalition on Nuclear Pollution petition to suspend const Continuation of const activities will not foreclose const alternatives if structural engineering mods determined necessary
LESSBY, R.P. Antitrust Division 80/11/18 16pp. 07003.285

8011190751 Affidavit re continuation of const activities at site. Continuation over next six months will not foreclose const alternatives if seismic-related engineering mods required. Certificate of Bvc encl
JOHT, J.P. Assistant Director for Components & Structures Engineering. 80/11/18 4pp 07003:301

8011250690 Forwards "Seismic Hazard Analysis," NUREG/CR-1582, Vols 2 & 3 to E Weiss on behalf of M Chinnery w/o encl
LESSBY, R.P. Antitrust Division 80/11/21 1p 07068.209

Q Inspection reports, IE Bulletins & correspondence

801100344 Forwards IE Insp Repts 50-443/80-09 & 50-444/80-09 on 800804-0903 No noncompliance noted
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/26 2pp 06929 238

--801100355 IE Insp Repts 50-443/80-09 & 50-444/80-09 on 800804-0903 No noncompliance noted Major areas inspected piping erection & pipe support welding activities, structural steel erection, component support welding & storage
CERNI, A.C. Region 1, Philadelphia, Office of the Director.
MCQUAGHY, R.W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/25 12pp 06929.240

8011060638 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
ORIER, B.H. Region 1, Philadelphia, Office of the Director.
80/10/24. 1p 06909:313

8011070330 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director
80/10/24 1p 06922 029.

8011140116 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director.
80/10/31. 1p. 06965:399

8011170663 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
ORIER, B.H. Region 1, Philadelphia, Office of the Director.
80/10/31 1p 06979 209

S. Reportable occurrences, LERs & related correspondence

8011140403 Interim deficiency rept re defective cooling tower concrete beams, initially reported on 801008 Testing is in process to determine if significant deficiency exists & will be completed by 810216
DEVINGENTIS, J. Public Service Co of New Hampshire. 80/11/06 1p 06962.347.

DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA, UNIT 1

A. Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of THF action plan requirements Provides summary listing of all approved THF-2 related requirements
EISENHUT, D.O. Division of Licensing 80/09/03 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D.O. Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " w/o encl
EISENHUT, D.O. Division of Licensing 80/10/06 6pp.

8011030219 Recommends preliminary assessment of Unit 1 control room to identify significant human factors & instrumentation problems per NUREG-0694 requirements Detailed review per NUREG-0660 will be required at later date
TEDESCO, R.L. Assistant Director for Licensing. 80/10/15 3pp
06855:218

8011030208 Forwards request for addl info required to complete evaluation re application for OLs, FSAR should be amended to include requested info Response should be provided within 6 wks.
TEDESCO, R.L. Assistant Director for Licensing. 80/10/16 12pp.
06857 142

8011030287 Forwards addl electrical instrumentation & control drawings to assist in plant review Drawings available on aperture cards in PDR
GARY, R. J Texas Utilities Generating Co 80/10/28 3pp
06861.200

8011140458 Forwards response to NRC 800818 request for addl info re piping analysis Drawings available in Central Files only
BCHMIDT, H C Texas Utilities Services, Inc 80/10/29 200pp
06966 003

8011040535 Forwards schedule for environ qualification tests for Class IE equipment to be conducted within next two yrs for safety-related equipment, in response to NRC 801001 ltr
BCHMIDT, H C Texas Utilities Services, Inc 80/10/31 4pp
06873 109

8011200419 Notification of 801118 meeting w/uttl in Bethesda, MD to discuss uttl mgt structure & technical resources for routine operations
BURWELL, B. B Licensing Branch 2 80/11/05 4pp 07020.105

8011170224 Forwards proprietary & nonproprietary versions of slides used in Westinghouse proposal for addressing inadvertent boron dilution event at Facility Application for withholding & affidavit encl
ANDERSON, T M Westinghouse Electric Corp, PWR Systems Div.
80/11/07 11pp 06968 295

8011180494 Forwards initial responses to Instrumentation & Control Sys Branch second round questions, 8032 75-8032 1102. Responses will be retransmitted in Amend 13 to FSAR
GARY, R. J Texas Utilities Generating Co 80/11/10. 78pp
06988.327.

8011250202 Responds to 801009 request for info re species under Endangered Species Act threatened or endangered by facilities. No listed or proposed species would be affected by proposed action
HOLSTENHULNE Interior, Dept of, Fish & Wildlife Service 80/11/14 1p 07068:315.

8011250326 Forwards "HFE Preliminary Assessment of Comanche Peak Unit 1 Control Room," in response to NRC 801015 request Copies will be provided to NRC human factors review team for use in preparation for 801208-12 site visit
GARY, R. J Texas Utilities Generating Co 80/11/20. 1p 07052 232

--8011250331 "HFE Preliminary Assessment of Comanche Peak Unit 1 Control Room " Oversize control room layout drawing encl
BIRD, R. D., WARD, B. M Texas Utilities Generating Co ESTES, R L Texas Utilities Services, Inc 80/11/17. 30pp 07052:253

C. Utility Environmental Report (ER), amends & correspondence

8011260444 Ack receipt of 800912 ltr re addl info for environ review
Reviews need for clarification of encl issues.
TEDESCO, R. L Assistant Director for Licensing 80/11/14 5pp.
07074.242.

D. Adjudicatory correspondence

8011050072 Notice that ASLB plans to consolidate intervening parties, Association of Community Organizations for Reform Now, Citizens Association for Sound Energy & Citizens for Fair Util Regulation each to be lead party for contentions
DEALE, V. B. Atomic Safety and Licensing Board Panel 80/10/31 1p.
06897 269.

8011040211 Several rulings on applicants' & intervenors' objections to ASLB 800616 order & on miscellaneous motions Citizens for Fair Util Regulation opposition to applicants' objections & motion for extension of time denied
DEALE, V. B. Atomic Safety and Licensing Board Panel 80/10/31. 13pp. 06912 068.

8011050432 Response in support of Citizens Association for Sound Energy 801014 request for extension until 801117 to supply answers to applicant motion to compel No ASLB action required re CASE motion to have NRC issuances provided to mini-LPDR.
ROTHSCHILD, H U Hearing Branch 1 80/11/03 6pp. 06898-200.

--8011050434 Forwards NRC issuances for Jan & Feb 1980 Complete set of 1978 & 1979 monthly issuances will be sent shortly. W/o encl. Certificate of Svc encl
SOUDEK, J. L. Division of Rules and Records. 80/10/29. 3pp
06898:206.

8011200293 Forwards ALAB-613, in response to ASLB request W/o encl
STEPHEN, C R Docketing & Services Branch 80/11/17 1p
07021 318

8011240499 Dismisses Citizens Association for Sound Energy conditional motion to compel applicant answers to first set of interrogatories
DEALE, V. B Atomic Safety and Licensing Board Panel. 80/11/17 4pp
07047 022

8011240513 Grants extension of time to 801201 for Citizens Association for Sound Energy to respond to motion to compel Also permits applicants to withdraw, modify or affirm 800718 motion to compel by 801208
DEALE, V. B Atomic Safety and Licensing Board Panel 80/11/17 4pp
07047 014

8011250583 Comments responding to ASLB 801031 plans for consolidation of parties Supports designation of lead intervenor for certain limited purposes Certificate of Svc encl
TURN, B Hearing Branch 1 80/11/20 5pp 07068 358

8011280019 Request for separate intervenor status Citizens Association for Sound Energy should not be consolidated w/other parties Costs & burdens incurred by consolidation far outweigh benefits. Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 80/11/20 11pp
07084 029

8011280024 Request for appointment of Citizens Association for Sound Energy as lead party for consolidated Contentions 22, 23, 24 & 5. In alternative, CASE should be granted separate intervenor status. Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 80/11/20. 5pp
07084 044

8011280036 Response in opposition to plans for consolidation of parties on Contentions 4 & 5 Citizens for Fair Util Regulation does not have same interest as other intervenors Other parties would not adequately represent CPUR. W/Certificate of Svc
FOULKE, R. L, HART, J Citizens for Fair Utility Regulation 80/11/20. 4pp 07084 079.

8011280065 Comments supporting consolidation of parties on Contentions 4, 5, 9, 23, 22((f)) & 24(a) ASLB should designate intervenor as lead party for each remaining contention Consolidation should be for all purposes. W/Certificate of Svc
REYNOLDS, N B, MORIN, H. A Texas Utilities Generating Co. REYNOLDS, N B Debevoise & Liberman 80/11/20 13pp 07084 107

8011280002 Order denying Citizens Association for Sound Energy 801002 motion for protection. Request not specific CASE has until 801201 to respond to referenced interrogatories
DEALE, V. B Atomic Safety and Licensing Board Panel 80/11/21 6pp.
07083:351

8011280031 Order dismissing Citizens for Fair Util Regulation appeal of ALAB-621 which rejected Contention 4B Appeal unauthorized by rules of practice due to interlocutory nature
BISHOP, C J Atomic Safety and Licensing Appeal Panel. 80/11/24 2pp 07084.096.

M Antitrust correspondence

801100396 Responds to uttl 801105 motion for clarification of ASLB 801024 order & ltr to ASLB Disagrees w/uttl understanding of order & intends to provide witness summaries indicated
POIRIER, M. R Spiegel & McDiarmid 80/11/06. 2pp 06928 068.

801140514 Order denying Houston Lighting & Power 801105 motion for clarification of ASLB 801024 order Procedural matters suspended until determination of necessity of evidentiary hearing made by ASLB.
MILLER, M E. Atomic Safety and Licensing Board Panel 80/11/10 3pp. 06963:114

801140542 Comments in opposition to settlement proposing license conditions Combination suggested makes cost prohibitive due to imposition of addl burden in violation of Sherman Act Certificate of Svc encl.
SPIEGEL, G, LANDSMAN, R M Brownsville, TX. SPIEGEL, G Spiegel & McDiarmid. 80/11/12 9pp. 06962:002.

8011260007 Confirms 801120 telcon granting extension until 801203 to file reply briefs Ltr is in lieu of formal motion
CHANANIA, F. D Antitrust Division 80/11/20 1p. 07075 289.

DOCKETED ITEMS

1 Inspection reports, IE Bulletins & correspondence

101140347 Ack receipt of IE Insp Repts 50-445/80-13 & 50-446/80-13 No proprietary info.
GARY, R J Texas Utilities Generating Co 80/08/20 1p 06965 202

01140355 Ack receipt of IE Insp Repts 50-445/80-17 & 50-446/80-17 No proprietary info.
GARY, R J Texas Utilities Generating Co 80/08/27 1p 06965 204

01100102 Forwards IE Insp Repts 50-445/80-18 & 50-446/80-18 on 800801-31 & notice of violation
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/19 2pp 06930 289.

801100106 Notice of violation from Insp on 800801-31.
* Region 4, Dallas, Office of the Director. 80/09/18 1p.
06930 291

801100116 IE Insp Repts 50-445/80-18 & 50-446/80-18 on 800801-31
Noncompliance noted undersized welds in safety-related piping sys not properly reported per 10CFR50 55(e).
TAYLOR, R O, GILBERT, L D, CROSSMAN, W A Region 4, Dallas, Office of the Director 80/09/18 10pp 06930 292

11210751 Forwards notice of violation from IE Insp Repts 50-445/80-20 & 50-446/80-20 on 800917 Insp repts to be issued in near future
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/24 2pp 07029 115

3011210760 Notice of violation from Insp on 800917 Noncompliance noted welds in four components not sufficiently free from coarse ripples, grooves, overlap, abrupt ridges & valleys
* Region 4, Dallas, Office of the Director 80/09/24 1p
07029 117

1040668 Forwards IE Insp Repts 50-445/80-21 & 50-446/80-21 on 100908-12 No noncompliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/26 2pp 06976 005

011040674 IE Insp Repts 50-445/80-21 & 50-446/80-21 on 800908-12 No noncompliance noted Major areas inspected: safety-related const activities pertaining to installation, Insp & documentation of safety-related electrical cables
MARTIN, L E, JOHNSON, A R, CROSSMAN, W A Region 4, Dallas, Office of the Director 80/09/26 3pp 06976 007

1070052 Forwards Suppl 2 to IE Bulletin 79-018, "Environment of Class IE Equipment" No written response required
FRITZ, K V Region 4, Dallas, Office of the Director 80/09/30 1p
06920 001

060797 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting" No written response required
FRITZ, K V Region 4, Dallas, Office of the Director 80/10/10 06909 054

210621 Forwards IE Insp Repts 50-445/80-20 & 50-446/80-20 during Sept 1980 & notice of deviation
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/10/21 2pp 07029 267

11210624 Notice of deviation from Insp during Sept 1980
* Region 4, Dallas, Office of the Director 80/10/20 1p
07029 269

11210631 IE Insp Repts 50-445/80-20 & 50-446/80-20 during Sept 1980 Noncompliance noted unsuitable weld surface & incorrect design of pressurizer spray sys control valve piping.
TAYLOR, R O, CROSSMAN, W A Region 4, Dallas, Office of the Director 80/10/20 7pp 07029 270

40361 Ack receipt of IE Insp Repts 50-445/80-21 & 50-446/80-21 No proprietary info.
Y. R J. Texas Utilities Generating Co 80/10/22 1p 06965 203

30052 Forwards Suppl 3 to IE Bulletin 79-018, "Environment of Class IE Equipment" No written response required
FRITZ, K V Region 4, Dallas, Office of the Director 80/10/24 06938 179.

8011170029 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2" No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/27 1p 06981 300

8011170609 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators" No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/10/31 1p. 06976 347

8 Reportable occurrences, LERs & related correspondence

801100102 Forwards IE Insp Repts 50-445/80-18 & 50-446/80-18 on 800801-31 & notice of violation
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/19 2pp 06930 289

--801100116 IE Insp Repts 50-445/80-18 & 50-446/80-18 on 800801-31.
Noncompliance noted undersized welds in safety-related piping sys not properly reported per 10CFR50 55(e)
TAYLOR, R O, GILBERT, L D, CROSSMAN, W A Region 4, Dallas, Office of the Director 80/09/18 10pp 06930 292

8011030985 Final deficiency repts re Plastics 7122 lining in svc water sys piping. Condition is not reportable per 10CFR50 55e
Supporting documentation available at plant site.
GARY, R J Texas Utilities Generating Co 80/10/29 1p 06861 139

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA, UNIT 2

A Application/construction stage documents & correspondence

8011030334 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011030219 Recommends preliminary assessment of Unit 1 control room to identify significant human factors & instrumentation problems per NUREG-0694 requirements Detailed review per NUREG-0660 will be required at later date
TEDESCO, R L Assistant Director for Licensing 80/10/15 3pp
06895 218

8011030208 Forwards request for addl info required to complete evaluation re application for DLs FSAR should be amended to include requested info Response should be provided within 6 wks.
TEDESCO, R L Assistant Director for Licensing 80/10/16 12pp
06897 142

8011030287 Forwards addl electrical instrumentation & control drawings to assist in plant review Drawings available on aperture cards in PDR
GARY, R J Texas Utilities Generating Co 80/10/28 3pp
06861 200

8011140458 Forwards response to NRC 800818 request for addl info re piping analysis Drawings available in Central Files only.
SCHMIDT, H C Texas Utilities Services, Inc. 80/10/29 200pp.
06966 003

8011040535 Forwards schedule for environ qualification tests for Class IE equipment to be conducted within next two yrs for safety-related equipment in response to NRC 801001 ltr
SCHMIDT, H C Texas Utilities Services, Inc 80/10/31 4pp
06873 109

8011200419 Notification of 801118 meeting w/util in Bethesda, MD to discuss util mgt structure & technical resources for routine operations.
BURRELL, B B. Licensing Branch 2 80/11/03 4pp. 07020 103.

DOCKETED ITEMS

BO1170224 Forwards proprietary & nonproprietary versions of slides used in Westinghouse proposal for addressing inadvertent boron dilution event at facility Application for withholding & affidavit encl
ANDERSON, T M Westinghouse Electric Corp , PWR Systems Div
BO/11/07 11pp. 06968 295

BO1180494 Forwards initial responses to Instrumentation & Control Sys Branch second round questions, 0032.75-0032 1102 Responses will be retransmitted in Amend 13 to FSAR
GARY, R J Texas Utilities Generating Co BO/11/10 78pp
06988 327

BO11250202 Responds to BO1009 request for info re species under Endangered Species Act threatened or endangered by facilities No listed or proposed species would be affected by proposed action
WOLSTENHULME Interior, Dept of, Fish & Wildlife Service BO/11/14 1p 07068 315

C Utility Environmental Report (ER), amends & correspondence

BO11260044 Ack receipt of BO0912 ltr re addl info for environ review. Review reveals need for clarification of encl issues
TEDESCO, R L Assistant Director for Licensing. BO/11/14 5pp
07074 242

G Adjudicatory correspondence

BO11030072 Notice that ASLB plans to consolidate intervening parties: Association of Community Organizations for Reform Now; Citizens Association for Sound Energy & Citizens for Fair Util Regulation; each to be lead party for contentions.
DEALE, V B Atomic Safety and Licensing Board Panel. BO/10/31 1p 06897 269

BO11060211 Several rulings on applicants' & intervenors' objections to ABLR BO0616 order & on miscellaneous motions. Citizens for Fair Util Regulation opposition to applicants' objections & motion for extension of time denied
DEALE, V B Atomic Safety and Licensing Board Panel BO/10/31. 13pp 06912 068

BO11050432 Response in support of Citizens Association for Sound Energy BO1014 request for extension until BO1117 to supply answers to applicant motion to compel No ASLB action required re CAFE motion to have NRC issuances provided to mini-LPDR
ROTHSCHILD, M U Hearing Branch 1. BO/11/03. 6pp. 06898.200

--BO11050434 Forwards NRC Issuances for Jan & Feb 1980 Complete set of 1978 & 1979 monthly issuances will be sent shortly w/o encl Certificate of Svc encl
SOUDER, J L Division of Rules and Records. BO/10/29. 3pp. 06898.206

BO11200295 Forwards ALAB-613, in response to ASLB request w/o encl.
STEPHENS, C. R. Docketing & Services Branch BO/11/17. 1p. 07021.318

BO11240499 Dismisses Citizens Association for Sound Energy conditional motion to compel applicant answers to first set of interrogatories.
DEALE, V B Atomic Safety and Licensing Board Panel BO/11/17. 4pp. 07047 022

BO11240513 Grants extension of time to BO1201 for Citizens Association for Sound Energy to respond to motion to compel. Also permits applicants to withdraw, modify or affirm BO0918 motion to compel by BO1208
DEALE, V B Atomic Safety and Licensing Board Panel BO/11/17. 4pp. 07047 014

BO11250583 Comments responding to ASLB BO1031 plans for consolidation of parties Supports designation of lead intervenor for certain limited purposes Certificate of Svc encl
TURK, S. Hearing Branch 1. BO/11/20 3pp 07068:338.

BO11280019 Request for separate intervenor status. Citizens Association for Sound Energy should not be consolidated w/other parties. Costs & burdens incurred by consolidation far outweigh benefits Certificate of Svc encl.
ELLIS, J Citizens Association for Sound Energy BO/11/20. 11pp. 07084:029

BO11280024 Request for appointment of Citizens Association for Sound Energy as lead party for consolidated Contentions 22, 23, 24 & 3. In alternative, CAFE should be granted separate intervenor status Certificate of Svc encl
ELLIS, J. Citizens Association for Sound Energy BO/11/20. 5pp. 07084 044.

BO11280036 Response in opposition to plans for consolidation of parties on Contentions 4 & 5 Citizens for Fair Util Regulation does not have same interest as other intervenors Other parties would not adequately represent CFUR W/Certificate of Svc
FOURIE, R L , HART, J Citizens for Fair Utility Regulation BO/11/20 4pp. 07084 079

BO11280055 Comments supporting consolidation of parties on Contentions 4, 5, 9, 23, 22(f) & 24(a). ASLB should designate intervenor as lead party for each remaining contention Consolidation should be for all purposes. W/Certificate of Svc
REYNOLDS, N B , HORIN, W. A Texas Utilities Generating Co
REYNOLDS, N B Debevoise & Liberman BO/11/20 13pp. 07084:107.

BO11280092 Order denying Citizens Association for Sound Energy BO1002 motion for protection Request not specific CAFE has until BO1201 to respond to referenced interrogatories
DEALE, V B Atomic Safety and Licensing Board Panel BO/11/21 6pp. 07083 351

BO11280051 Order dismissing Citizens for Fair Util Regulation appeal ALAB-621 which rejected Contention 4B Appeal unauthorized by rules of practice due to interlocutory nature.
BISHOP, C J Atomic Safety and Licensing Appeal Panel. BO/11/24 2pp. 07084 096

M. Antitrust correspondence

BO11100396 Responds to util BO1105 motion for clarification of ASLB BO1024 order & ltr to ASLB. Disagrees w/util understanding of order & intends to provide witness summaries indicated.
POIRIER, M. R Spiegel & McDiarmid BO/11/06 2pp. 06928 068.

BO11140514 Order denying Houston Lighting & Power BO1105 motion for clarification of ASLB BO1024 order. Procedural matters suspended until determination of necessity of evidentiary hearing made by ASLB.
MILLER, M E. Atomic Safety and Licensing Board Panel BO/11/10. 3pp. 06963 114

BO11140542 Comments in opposition to settlement proposing license conditions. Combination suggested makes cost prohibitive due to imposition of addl burden in violation of Sherman Act. Certificate of Svc encl
SPIEGEL, G., LANDSMAN, R. M. Brownsville, TX SPIEGEL, G Spiegel & McDiarmid BO/11/12 98pp 06962 002

BO11260007 Confirms BO1120 telcon granting extension until BO1203 to file reply briefs Ltr is in lieu of formal motion
CHANANIA, F. D. Antitrust Division. BO/11/20. 1p 07075.289

G Inspection reports, IE Bulletins & correspondence

BO11140367 Ack receipt of IE Insp Repts 50-445/80-15 & 50-446/80-15, N proprietary info
GARY, R J Texas Utilities Generating Co. BO/08/20. 1p. 06965.20

BO11140355 Ack receipt of IE Insp Repts 50-445/80-17 & 50-446/80-17 N proprietary info
GARY, R J Texas Utilities Generating Co BO/08/27 1p 06965.20

BO1100102 Forwards IE Insp Repts 50-445/80-18 & 50-446/80-18 on BO0801-31 & notice of violation
SEIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. BO/09/19. 2pp 06930 289

--BO1100106 Notice of violation from insp on BO0801-31
* Region 4, Dallas, Office of the Director BO/09/18 1p. 06930 291.

--BO11100116 IE Insp Repts 50-445/80-18 & 50-446/80-18 on BO0801-31 Noncompliance noted: undersized welds in safety-related piping sys not properly reported per 10CFR50.55(a)
TAYLOR, R. G , GILBERT, L. D., CRISSEMAN, W A Region 4, Dallas, Office of the Director. BO/09/18. 10pp 06930 292

BO11210751 Forwards notice of violation from IE Insp Repts 50-445/80- & 50-446/80-20 on BO0917 Insp repts to be issued in near future.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. BO/09/24. 2pp 07029.115.

--BO11210760 Notice of violation from insp on BO0917 Noncompliance noted: welds in four components not sufficiently free from coarse ripples, grooves, overlap, abrupt ridges & valleys.
* Region 4, Dallas, Office of the Director BO/09/24 1p 07029:117

DOCKETED ITEMS

8011040648 Forwards IE Insp Repts 50-445/80-21 & 50-446/80-21 on 800908-12 No noncompliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/26 2pp 06876 005

--8011040674 IE Insp Repts 50-445/80-21 & 50-446/80-21 on 800908-12 No noncompliance noted Major areas inspected safety-related const activities pertaining to installation, insp & documentation of safety-related electrical cables
MARTIN, L E, JOHNSON, A R, CROSSMAN, W A Region 4, Dallas, Office of the Director 80/09/26 3pp 06876 007

8011070062 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/09/30 1p 06920 001

8011060757 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/10 1p 06909 054

8011210621 Forwards IE Insp Repts 50-445/80-20 & 50-446/80-20 during Sept 1980 & notice of deviation
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/10/21 2pp 07029 267

--8011210624 Notice of deviation from insp during Sept 1980
* Region 4, Dallas, Office of the Director 80/10/20 1p 07029 267

--8011210631 IE Insp Repts 50-445/80-20 & 50-446/80-20 during Sept 1980 Noncompliance noted unsuitable weld surface & incorrect design of pressurizer spray sys control valve piping
TAYLOR, R G, CROSSMAN, W A Region 4, Dallas, Office of the Director 80/10/20 7pp 07029 270

8011140361 Ack receipt of IE Insp Repts 50-445/80-21 & 50-446/80-21 No proprietary info
GARY, R J Texas Utilities Generating Co 80/10/22 1p 06965 203.

8011130052 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/24 1p 06958 179

8011170029 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/27 1p 06981 300

8011170609 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/31 1p 06976 347

S Reportable occurrences, LERs & related correspondence

8011100102 Forwards IE Insp Repts 50-445/80-18 & 50-446/80-18 on 800801-31 & notice of violation
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/19 2pp 06930 289

--8011100116 IE Insp Repts 50-445/80-18 & 50-446/80-18 on 800801-31 Noncompliance noted undersized welds in safety-related piping sys not properly reported per 10CFR50 55(e).
TAYLOR, R G, HALL, R E Region 4, Dallas, Office of the Director 80/09/18 10pp

8011030585 Final deficiency rept re Plasite 7122 lining in svc water sys piping Condition is not reportable per 10CFR50 55(e).
Supporting documentation available at plant site
GARY, R J Texas Utilities Generating Co 80/10/29 1p 06861 139.

DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 2

A Application/construction stage documents & correspondence

8011260265 Advises that Ofc of Controller has been notified to issue invoice for balance of fee for NRC review of CP application withdrawn on 800709.
MILLER, W D License Fee Management Branch 80/11/10. 1p 07074 148

S Reportable occurrences, LERs & related correspondence

8011070454 Final deficiency rept re Agastat relay bases Each Agastat relay base of type in question in five GE supplied panels will be modified by insertion of micarta spacer under relay base
HINES, E Detroit Edison Co 80/11/03 2pp 06924 363

DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3

A Application/construction stage documents & correspondence

8011260265 Advises that Ofc of Controller has been notified to issue invoice for balance of fee for NRC review of CP application withdrawn on 800709.
MILLER, W D License Fee Management Branch 80/11/10 1p 07074 148

S Reportable occurrences, LERs & related correspondence

8011070494 Final deficiency rept re Agastat relay bases Each Agastat relay base of type in question in five GE supplied panels will be modified by insertion of micarta spacer under relay base
HINES, E Detroit Edison Co 80/11/03. 2pp 06924 363

DOCKET 50-454 BYRON STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O. Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01 5pp

8011100357 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl.
EISENHUT, D O Division of Licensing 80/10/06 6pp.

8011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201
ABEL, J S Commonwealth Edison Co 80/10/31 1p

8011100389 Forwards page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments
TRAMM, T R Commonwealth Edison Co 80/11/05 2pp

F Security, medical, emergency & fire protection plans

8011050428 Forwards draft public info package re emergency preparedness for facilities Package has been distributed to States of IL, IA & WI for comment Requests NRC comment by 801121
DELGROD, E L Commonwealth Edison Co. 80/11/03 8pp

Q Adjudicatory correspondence

8011250323 Forwards request per 10CFR2 206 & 2 202, on behalf of Rockford, IL League of Women Voters, re CP mod Also forwards affidavit of engineers RB Hubbard & GC Minor Requests prompt response, due to urgency of matter.
CHERRY, M M Cherry, M M /Cherry, Flynn & Kanter 80/11/21. 1p 07052 131

--8011250327 Request per 10CFR2 206 & 2.202 for mod of CP license until resolution of all outstanding safety issues presently applicable to facility Proof of svc encl
CHERRY, M M League of Women Voters of Rockford, IL. CHERRY, M M. Cherry, M M /Cherry, Flynn & Kanter 80/11/21 4pp 07052 132.

--8011250333 Affidavit of RB Hubbard & GC Minor re mod of CP license until resolution of all outstanding safety problems presently applicable to facility Supporting exhibit encl.
MINOR, G C, HUBBARD, R B MHS Technical Associates CHERRY, M M. League of Women Voters of Rockford, IL. 80/11/21 114pp 07052 136

K Utility Final Safety Analysis Report (FSAR) & amends

8011030531 Forwards Amend 2B to FSAR, consisting of amend to application for CPs & DLs
NAUGHTON, W F Commonwealth Edison Co 80/10/31 4pp 06855:271

--8011030544 Amend 2B to FSAR
* Commonwealth Edison Co 80/10/30 300pp. 06855:273

801120365 Forwards affidavit certifying that distribution of FSAR Amend 2B made per Encl 1 of NRC 781028 ltr
TRAHM, T R Commonwealth Edison Co 80/11/06 2pp. 06952:031.

G Inspection reports, IE Bulletins & correspondence

7904040038 IE Insp Rept 50-373/79-10, 50-374/79-04, 50-434/79-04 & 50-435/79-04 on 790119, 790203 & 06 No noncompliance noted
Major areas inspected tendon sys performance tests & proposed Inryco, Inc tendon performance program
* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/02/23 4pp. 03133:271

8011060560 Responds to NRC 800815 ltr re const rework noted in IE Insp Repts 50-434/80-13, 50-435/80-12, 50-436/80-07 & 50-437/80-07.
Program initiated to determine extent & causes for rework in six general areas.
REED, C. Commonwealth Edison Co. 80/09/22, 2pp. 06916:220.

8011200074 Forwards IE Insp Repts 50-434/80-18 & 50-435/80-17 on 800915-16, 19 & 22-23 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/10/16 2pp. 07020:297

--8011200076 Notice of violation from Insp on 800915-16, 19 & 22-23.
* Region 3, Chicago, Office of the Director. 80/10/15, 1p 07020:299.

--8011200085 IE Insp Repts 50-434/80-18 & 50-435/80-17 on 800915-16, 19 & 22-23 Noncompliance noted: no daily checklists filed in permanent records for these dates & area of erosion approx 2 ft deep found near northwest corner.
PHILLIPS, C J, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/10/15 6pp. 07020:300

8011070146 Forwards response, provided in Bargent & Lundy Engineers 790611 ltr to util, to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves mfg by Valen Engineering Corp." Check valve weights correct & have been used in piping analysis.
MERWIN, J. T. Commonwealth Edison Co. 80/10/17, 6pp.

8011070285 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
KEPLER, J Q Region 3, Chicago, Office of the Director. 80/10/24, 1p

8011030104 Ack receipt of 801015 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-434/80-09, 50-435/80-09, 50-436/80-04 & 50-437/80-04.
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/28, 1p. 06897:270.

--8011030110 Responds to NRC 800610 & 18 ltrs re violations noted in IE Insp Repts 50-434/80-09, 50-435/80-09, 50-436/80-04 & 50-437/80-04 Corrective actions re supplier study & technical assessment will be submitted by 801215.
ABEL, J B Commonwealth Edison Co 80/10/15 1p. 06897:271

8011030118 Ack receipt of 801017 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-434/80-12 & 50-435/80-11
FIORELLI, Q. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/29 1p. 06897:272

--8011030123 Responds to NRC 800916 ltr re violation noted in IE Insp Repts 50-434/80-12 & 50-435/80-11 Corrective actions re emergency diesel generator design will be submitted by 801029
ABEL, J B Commonwealth Edison Co. 80/10/17, 1p 06897:273.

8011280204 Ack receipt of 801027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-434/80-12 & 50-435/80-11.
KEPLER, J. Q. Region 3, Chicago, Office of the Director. 80/11/18, 1p. 07082:357

--8011280206 Responds to NRC 800710 ltr re violations noted in IE Insp Repts 50-434/80-12 & 50-435/80-11 Corrective actions cooling water supply to emergency diesel generators considered by util in conformance w/intent of 10CFR50
ABEL, J B Commonwealth Edison Co 80/10/27 3pp 07082:358

DOCKET 50-435 BYRON STATION, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp.

8011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201.
ABEL, J B. Commonwealth Edison Co 80/10/31 1p

8011000389 Forwards page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments
TRAHM, T.R. Commonwealth Edison Co. 80/11/03, 2pp.

F Security, medical, emergency & fire protection plans

8011030428 Forwards draft public info package re emergency preparedness for facilities Package has been distributed to States of IL, IA & WI for comment. Requests NRC comment by 801121
DELEGORGE, L O Commonwealth Edison Co. 80/11/03 8pp

G Adjudicatory correspondence

8011250323 Forwards request per 10CFR2 206 & 2 202, on behalf of Rockford, IL League of Women Voters, re CP mod. Also forwards affidavit of engineers RB Hubbard & QC Minor Requests prompt response, due to urgency of matter.
CHERRY, M H Cherry, M H./Cherry, Flynn & Kanter. 80/11/21 1p. 07052:131

--8011250327 Request per 10CFR2 206 & 2 202 for mod of CP license until resolution of all outstanding safety issues presently applicable to facility Proof of svc encl.
CHERRY, M M League of Women Voters of Rockford, IL. CHERRY, M M. Cherry, M. M./Cherry, Flynn & Kanter 80/11/21 4pp. 07052:132

--8011250333 Affidavit of RB Hubbard & QC Minor re mod of CP license until resolution of all outstanding safety problems presently applicable to facility. Supporting exhibit encl.
MINOR, O C, HUBBARD, R B MHB Technical Associates, CHERRY, M M. League of Women Voters of Rockford, IL. 80/11/21 114pp. 07052:136.

K Utility Final Safety Analysis Report (FSAR) & amends

8011030531 Forwards Amend 2B to FSAR, consisting of amend to application for CPs & DLs
NAUGHTON, W F. Commonwealth Edison Co 80/10/31. 4pp. 06855:271.

--8011030544 Amend 2B to FSAR
* Commonwealth Edison Co 80/10/30 300pp. 06855:273.

801120365 Forwards affidavit certifying that distribution of FSAR Amend 2B made per Encl 1 of NRC 781028 ltr
TRAHM, T R Commonwealth Edison Co 80/11/06 2pp 06952:031.

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

7904040038 IE Insp Rept 50-373/79-10, 50-374/79-04, 50-454/79-04 & 50-453/79-04 on 790119, 790209 & 04 No noncompliance noted. Major areas inspected tendon sys performance tests & proposed Inryco, Inc tendon test program.
* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/02/23 4pp

801060560 Responds to NRC 800815 ltr re const rework noted in IE Insp Repts 50-454/80-13, 50-455/80-12, 50-456/80-07 & 50-457/80-07. Program initiated to determine extent & causes for rework in six general areas.
REED, C Commonwealth Edison Co 80/08/22 2pp 06916, 220

8011200074 Forwards IE Insp Repts 50-454/80-18 & 50-455/80-17 on 800915-16, 19 & 22-23 & notice of violation.
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch, 80/10/16 2pp 07020:297.

--8011200076 Notice of violation from insp on 800915-16, 19 & 22-23.
* Region 3, Chicago, Office of the Director 80/10/15, 1p, 07020 297.

--8011200085 IE Insp Repts 50-454/80-18 & 50-455/80-17 on 800915-16, 19 & 22-23 Noncompliance noted, no daily checklists filed in permanent records for three dates & area of erosion approx 2 ft deep found near northwest corner.
PHILLIPS, C J, PAPERIELLO, C J, Region 3, Chicago, Office of the Director 80/10/15 6pp, 07020 300

801070146 Forwards response provided in Bargent & Lundy Engineers 790411 ltr to util, to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves mfg by Velan Engineering Corp." Check valve weights correct & have been used in piping analysis.
MERWIN, J T Commonwealth Edison Co 80/10/17, 6pp

801070285 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
KEPPLER, J G Region 3, Chicago, Office of the Director, 80/10/24 1p

801050104 Ack receipt of 801015 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/80-09, 50-455/80-09, 50-456/80-04 & 50-457/80-04.
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/28 1p, 06897 270

--801050110 Responds to NRC 800610 & 18 ltrs re violations noted in IE Insp Repts 50-454/80-09, 50-455/80-09, 50-456/80-04 & 50-457/80-04. Corrective actions re supplier study & technical assessment will be submitted by 801215.
ABEL, J B Commonwealth Edison Co, 80/10/15 / 1p 06897, 271.

801050118 Ack receipt of 801017 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-454/80-12 & 50-455/80-11.
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch, 80/10/29 1p 06897 272.

--801050123 Responds to NRC 800915 ltr re violation noted in IE Insp Repts 50-454/80-12 & 50-455/80-11. Corrective actions re emergency diesel generator design will be submitted by 801029.
ABEL, J B Commonwealth Edison Co 80/10/17 1p, 06897 273.

8011280204 Ack receipt of 801027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/80-12 & 50-455/80-11.
KEPPLER, J G Region 3, Chicago, Office of the Director, 80/11/18, 1p 07082, 357.

--8011280206 Responds to NRC 800710 ltr re violations noted in IE Insp Repts 50-454/80-12 & 50-455/80-11. Corrective actions: cooling water supply to emergency diesel generators considered by util in conformance w/intent of 10CFR50.
ABEL, J B, Commonwealth Edison Co 80/10/27 3pp, 07082:358.

DOCKET 80-456 BRAIDWOOD STATION, UNIT 1

A Application/Construction stage documents & correspondence

8011090354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D G, Division of Licensing, 80/09/03 209pp.

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D G Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl.
EISENHUT, D G Division of Licensing 80/10/06 6pp.

8011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201.
ABEL, J B Commonwealth Edison Co 80/10/31, 1p

801100389 Forwards page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments.
TRAMM, T R Commonwealth Edison Co 80/11/03, 2pp

C Utility Environmental Report (ER), amends & correspondence

801110563 Addresses discrepancy between NRC FEB & util operating stage environ rept, identified in IE Insp Repts 50-456/80-09 & 50-457/80-08. Preoperational radiological monitoring will begin 2 yrs prior to commercial operation.
TRAMM, T R Commonwealth Edison Co 80/10/31 1p, 06950:060.

D NRC Draft/Final Environmental Statements, suppl & correspondence

801110563 Addresses discrepancy between NRC FEB & util operating stage environ rept, identified in IE Insp Repts 50-456/80-09 & 50-457/80-08. Preoperational radiological monitoring will begin 2 yrs prior to commercial operation.
TRAMM, T R Commonwealth Edison Co 80/10/31 1p 06950:060

F Security, medical, emergency & fire protection plans

801050428 Forwards draft public info package re emergency preparedness for facilities. Package has been distributed to States of IL, IA & WI for comment. Requests NRC comment by 801121.
DELGROUE, L G, Commonwealth Edison Co 80/11/03, 8pp

K Utility Final Safety Analysis Report (FSAR) & amends

801030531 Forwards Amend 2B to FSAR, consisting of amend to application for CPs & DLs.
NAUGHTON, W F Commonwealth Edison Co 80/10/31 4pp 06855 271.

--801030544 Amend 2B to FSAR.
* Commonwealth Edison Co 80/10/30 300pp, 06855, 275.

801120365 Forwards affidavit certifying that distribution of FSAR Amend 2B made per Encl 1 of NRC 78102B ltr.
TRAMM, T R Commonwealth Edison Co 80/11/06, 2pp 06952 031

G Inspection reports, IE Bulletins & correspondence

801060560 Responds to NRC 800815 ltr re const rework noted in IE Insp Repts 50-454/80-13, 50-455/80-12, 50-456/80-07 & 50-457/80-07. Program initiated to determine extent & causes for rework in six general areas.
REED, C Commonwealth Edison Co 80/08/22, 2pp 06916:220

801060305 Forwards IE Insp Repts 50-456/80-10 & 50-457/80-09 on 800904 & 03 No noncompliance noted.
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/02 2pp 06911:293.

--801060311 IE Insp Rept 50-456/80-10 & 50-457/80-09 on 800904 & 03 No noncompliance noted. Major areas inspected site tour & review of previous insp findings.
SCHREIBER, E R, WILLIAMS, C C Region 3, Chicago, Office of the Director 80/10/02, 3pp 06911 295

801170734 Forwards IE Insp Repts 50-456/80-11 & 50-457/80-10 on 800909-10 & notice of violation.
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch, 80/10/03 2pp 06981, 276.

--801170738 Notice of violation from insp on 800909-10.
* Region 3, Chicago, Office of the Director, 80/09/30, 1p 06981:278.

DOCKETED ITEMS

229

--801170742 IE Insp Repts 50-456/80-11 & 50-457/80-10 on 800909-10
Noncompliance noted improper storage of safety-related components.
ERB, C M Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/30 App 06981 279

801170942 Forwards IE Insp Repts 50-456/80-09 & 50-457/80-08 on 800917-19 & 23 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/10/09 2pp 06978 180

--801170945 Notice of violation from insp on 800917-19 & 23
* Region 3, Chicago, Office of the Director 80/10/08 1p 06978:182.

--801170947 IE Insp Repts 50-456/80-09 & 50-457/80-08 on 800917-19 & 23
Noncompliance noted, radiological environ monitoring program not begun in Jul 1979 No daily or weekly environ monitoring checks performed
PHILLIPS, M P, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/10/08 7pp 06978:183

8011070146 Forwards response, provided in Sargent & Lundy Engineers 790611 ltr to util, to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves mfg by Velan Engineering Corp." Check valve weights correct & have been used in piping analysis.
MERWIN, J T Commonwealth Edison Co 80/10/17. 6pp.

8011070285 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/24. 1p.

8011050104 Ack receipt of 801015 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/80-09, 50-455/80-09, 50-456/80-04 & 50-457/80-04
FIORELLI, Q. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/28 1p 06897:270

--8011050110 Responds to NRC 800610 & 18 ltrs re violations noted in IE Insp Repts 50-454/80-09, 50-455/80-09, 50-456/80-04 & 50-457/80-04 Corrective actions re supplier study & technical assessment will be submitted by 801215
ABEL, J S Commonwealth Edison Co. 80/10/15 1p 06897:271.

801110563 Addresses discrepancy between NRC FEB & util operating stage environ rept, identified in IE Insp Repts 50-456/80-09 & 50-457/80-08, Preoperational radiological monitoring will begin 2 yrs prior to commercial operation
TRAMM, T R. Commonwealth Edison Co 80/10/31. 1p

8011210767 Ack receipt of 801031 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/80-09 & 50-457/80-08
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/13. 1p 07029 124

--8011210769 Responds to NRC 801009 ltr re violations noted in IE Insp Repts 50-456/80-09 & 50-457/80-08 Corrective actions, daily checks resumed on 800923 to ensure approval & required repts will be filed
ABEL, J B. Commonwealth Edison Co 80/10/31 3pp. 07029:125.

DOCKET 50-457 BRAIDWOOD STATION, UNIT 2

A. Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05. 209pp.

801100496 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D O. Division of Licensing 80/10/01. 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " N/e encl
EISENHUT, D O Division of Licensing 80/10/06. 6pp.

8011040394 Informs NRC that info re environ qualification tests to be conducted within next 2 yrs on equipment used or to be used in facilities will be provided by 801201
ABEL, J S Commonwealth Edison Co 80/10/31 1p

8011100389 Forwards page 2-6 of Topical Rept CE-1-A, "QA Program," revised per other previous QA program commitments
TRAMM, T R Commonwealth Edison Co 80/11/05 2pp

C Utility Environmental Report (ER), amends & correspondence

801110563 Addresses discrepancy between NRC FEB & util operating stage environ rept, identified in IE Insp Repts 50-456/80-09 & 50-457/80-08 Preoperational radiological monitoring will begin 2 yrs prior to commercial operation
TRAMM, T R Commonwealth Edison Co 80/10/31. 1p 06950 060.

D. NRC Draft/Final Environmental Statements, supplis & correspondence

801110563 Addresses discrepancy between NRC FEB & util operating stage environ rept, identified in IE Insp Repts 50-456/80-09 & 50-457/80-08 Preoperational radiological monitoring will begin 2 yrs prior to commercial operation
TRAMM, T R Commonwealth Edison Co. 80/10/31 1p

F Security, medical, emergency & fire protection plans

8011050428 Forwards draft public info package re emergency preparedness for facilities Package has been distributed to States of IL, IA & WI for comment Requests NRC comment by 801121
DELGROUSE, L. O. Commonwealth Edison Co. 80/11/03 8pp

K Utility Final Safety Analysis Report (FSAR) & amends

8011030531 Forwards Amend 2B to FSAR, consisting of amend to application for CPs & OLs.
NAUGHTON, W F Commonwealth Edison Co. 80/10/31. 4pp.

--8011030544 Amend 2B to FSAR
* Commonwealth Edison Co 80/10/30 300pp

8011120365 Forwards affidavit certifying that distribution of FSAR Amend 2B made per Encl 1 of NRC 78102B ltr
TRAMM, T R. Commonwealth Edison Co 80/11/06 2pp.

Q Inspection reports, IE Bulletins & correspondence

8011060560 Responds to NRC 800813 ltr re const rework noted in IE Insp Repts 50-454/80-13, 50-455/80-12, 50-456/80-07 & 50-457/80-07 Program initiated to determine extent & causes for rework in six general areas
REED, C Commonwealth Edison Co 80/09/22 2pp.

8011060305 Forwards IE Insp Repts 50-456/80-10 & 50-457/80-09 on 800904 & 05 No noncompliance noted.
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/02. 2pp 06911:293

--8011060311 IE Insp Rept 50-456/80-10 & 50-457/80-09 on 800904 & 05, No noncompliance noted Major areas inspected site tour & review of previous insp findings
SCHWEIBINZ, E R, WILLIAMS, C C. Region 3, Chicago, Office of the Director. 80/10/02. 3pp 06911:295

8011170734 Forwards IE Insp Repts 50-456/80-11 & 50-457/80-10 on 800909-10 & notice of violation
FIORELLI, Q. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/03. 2pp. 06981 276

--8011170738 Notice of violation from insp on 800909-10.
* Region 3, Chicago, Office of the Director 80/09/30 1p. 06981:278.

--8011170742 IE Insp Repts 50-456/80-11 & 50-457/80-10 on 800909-10. Noncompliance noted, improper storage of safety-related components
ERB, C M Region 3, Chicago, Office of the Director.
DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/30 App 06981:279.

8011170942 Forwards IE Insp Repts 50-456/80-09 & 50-457/80-08 on 800917-19 & 23 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/10/09. 2pp. 06978:180.

DOCKETED ITEMS

--801170949 Notice of violation from insp on 800917-19 & 23
* Region 3, Chicago, Office of the Director 80/10/08 1p
06978 182

--801170947 IE Insp Repts 50-456/80-07 & 50-457/80-08 on 800917-19 & 23
Noncompliance noted radiological environ monitoring program
not begun in Jul 1979 No daily or weekly environ monitoring
checks performed
PHILLIPS, M P, PAPERIELLO, C J Region 3, Chicago, Office of the
Director 80/10/08 7pp 06978 183

8011070146 Forwards response provided in Bargent & Lundy Engineers
790611 ltr to util, to IE Bulletin 79-04, "Incorrect Weights
for Swing Check Valves mfg by Velan Engineering Corp " Check
valve weights correct & have been used in piping analysis
HERWIN, J T Commonwealth Edison Co 80/10/17 6pp

8011070285 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " No written response
required
KEPLER, J G. Region 3, Chicago, Office of the Director 80/10/24
1p

8011050104 Ack receipt of 801015 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-454/80-09,
50-455/80-09, 50-456/80-04 & 50-457/80-04
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/10/29 1p

--8011050110 Responds to NRC 800610 & 18 ltrs re violations noted in IE
Insp Repts 50-454/80-09, 50-455/80-09, 50-456/80-04 &
50-457/80-04 Corrective actions re supplier study &
technical assessment will be submitted by 801215
ABEL, J B Commonwealth Edison Co 80/10/15 1p

801110763 Addresses discrepancy between NRC FES & util operating
stage environ rept, identified in IE Insp Repts 50-456/80-09
& 50-457/80-08 Preoperational radiological monitoring
will begin 2 yrs prior to commercial operation
TRAMM, T R. Commonwealth Edison Co 80/10/31 1p

8011210747 Ack receipt of 801031 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-456/80-09 &
50-457/80-08
DAVIS, A B. Region 3, Chicago, Fuel Facility & Materials Safety
Branch 80/11/13 1p 07029 124

--8011210769 Responds to NRC 801009 ltr re violations noted in IE Insp
Repts 50-456/80-09 & 50-457/80-08 Corrective actions: daily
checks resumed on 800923 to ensure approval & required repts
will be filed
ABEL, J B Commonwealth Edison Co 80/10/31 3pp 07029 125.

DOCKET 50-458 RIVER BEND STATION, UNIT 1

A. Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TMI action
plan requirements. Provides summary listing of all approved
TMI-2 related requirements
EISENHUT, D O. Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs Info needed by 801101
EISENHUT, D O. Division of Licensing 80/10/01 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D O. Division of Licensing 80/10/06 6pp

H General correspondence

8011060073 FOIA request for repts & correspondence re choice &
actuality of facility becoming BWR
KRAUSE, L. Affiliation Unknown 80/10/08. 2pp. 06914 154.

8011060066 Responds to FOIA request for repts & correspondence re
choice & actuality of facility becoming BWR NRC has no
documents re reactor selection PSAR, SER, environ rept & draft
& final EIS are available in LPDRs
FELTON, J. M. Division of Rules and Records. 80/10/31. 1p
06914 153.

Q Inspection reports, IE Bulletins & correspondence

8011200098 Forwards IE Mgt Meeting Rept 50-458/80-10 on 800917 in Baton
Rouge, LA re regional evaluation of licensee performance
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/10/08 1p 07020 344

--8011200102 IE Mgt Meeting Rept 50-458/80-10 on 800917. Areas discussed,
evaluation of licensee performance re enforcement history &
const deficiencies
SEYFRIT, K V, CROSSMAN, W A Region 4, Dallas, Office of the
Director SEIDLE, W C Region 4, Dallas, Reactor Construction &
Engineering Support Branch 80/10/03 10pp 07020 345

8011060765 Forwards IE Info Notice 80-36, "Failure of Steam Generator
Support Bolting " No written response required.
SEYFRIT, K V. Region 4, Dallas, Office of the Director 80/10/10
1p 06909 064

801130044 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " No written response
required
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/10/24
1p 06958 171

8011170925 Forwards IE Info Notice 80-37, "Containment Cooler Leaks &
Reactor Cavity Flooding at Indian Point Unit 2 " No written
response required
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/10/27
1p 06981 296

8011170619 Forwards IE Circular 80-23, "Potential Defects in Beloit
Power Sys Emergency Generators " No written response
required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/31
1p. 06977 280

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs
& holders of CPs re preliminary clarification of TMI action
plan requirements. Provides summary listing of all approved
TMI-2 related requirements
EISENHUT, D O. Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for
OLs & holders of CPs requesting info re environ
qualification tests to be conducted on safety-related
equipment within next two yrs Info needed by 801101.
EISENHUT, D O. Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding
summary of 800827 meeting re guidance from Unresolved
Safety Issue A-12, "Potential for Low Fracture Toughness &
Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D O. Division of Licensing 80/10/06 6pp

H General correspondence

8011060073 FOIA request for repts & correspondence re choice &
actuality of facility becoming BWR
KRAUSE, L. Affiliation Unknown 80/10/08. 2pp 06914 154

8011060066 Responds to FOIA request for repts & correspondence re
choice & actuality of facility becoming BWR. NRC has no
documents re reactor selection PSAR, SER, environ rept & draft
& final EIS are available in LPDRs
FELTON, J. M. Division of Rules and Records 80/10/31 1p
06914 153

Q Inspection reports, IE Bulletins & correspondence

8011060765 Forwards IE Info Notice 80-36, "Failure of Steam Generator
Support Bolting " No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/10/10.
1p 06909 064

801130044 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " No written response
required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/24
1p 06958 171.

801170025 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2" No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/27
1p 06981 296

801170419 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators" No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/31
1p 06977 280

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lameellar Tearing on Component Supports" W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

8011070444 Informs that info requested in NRC 800731 ltr re environ qualification of safety-related equipment will be submitted by 801201
RENEBERGER, D L Washington Public Power Supply System 80/11/07
1p 06919 193

G Inspection reports, IE Bulletins & correspondence

801190449 Ack receipt of 800918 ltr informing NRC of addl steps taken to correct violations noted in IE insp on 800429-0502
SPENCER, J S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/10/07 1p 06998 089

--801190451 Responds to NRC 800904 ltr re violations noted in IE insp Identified condition is isolated case & not basis for generic concern
RENEBERGER, D L Washington Public Power Supply System 80/09/18 3pp 06998 090

--801190453 Ack receipt of 800813 ltr informing NRC of steps taken to correct violations noted in IE insp on 800429-0502 Addl info required
SPENCER, J S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/09/04 1p 06998 093

--801190455 Responds to NRC 800711 ltr re violations noted in IE insp Corrective actions training sessions held to reiterate requirements for performance of addl work on hangers & issuance of proper documentation
FERGUSON, R L Washington Public Power Supply System 80/08/13 8pp 06998 094

8011060773 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting" No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/10 1p 06909 083

801130029 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/24 1p 06958 078

8011200105 Forwards IE Mgt Meeting Repts 50-460/80-12, 50-513/80-12, 50-508/80-11 & 50-509/80-11 on 801009 No noncompliance noted
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/29 2pp 07021 001

--8011200117 IE Mgt Meeting Repts 50-460/80-12, 50-513/80-12, 50-508/80-11 & 50-509/80-11 on 801009 No noncompliance noted Major areas discussed enforcement; IE bulletins & insp program
ENGELKEN, R H, HAYNES, R C, BISHOP, T W Region 5, San Francisco, Office of the Director 80/10/29 3pp 07021 003

--8011200129 Discusses 800905 regional evaluation review board meeting re enforcement, IE bulletins & insp programs Licensee performance needs improvement in PSAR commitments translated into specs & spec codes translated into work procedures
HAYNES, R C, BISHOP, T W, KIRSCH, D F Region 5, San Francisco, Office of the Director 80/10/03 14pp 07021 005

--8011200135 Discusses 800905 regional evaluation review board meeting re enforcement, IE bulletins & insp programs Licensee performance warrants improvement in assuring preparation adequate prior to start of safety-related work
HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch KIRSCH, D F, HAIST, D P Region 5, San Francisco, Office of the Director 80/10/02 12pp 07021 020

801170649 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators" No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/31 1p 06976 262

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lameellar Tearing on Component Supports" W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

801190014 Advises that Baldwin Associates has been authorized to remove arc strike on valve 1B21-F011A, per Nonconformance Rept 3623 Repair plan, procedures & related documents will be available for review at site
SPENCER, J S Illinois Power Co 80/10/13 1p 06996 274

8011070318 Forwards updated distribution list for suppl & amends to FSAR, environ rept & general info
BUCKLEY, B C Licensing Branch 3 80/10/15 4pp 06919 312

8011040257 Confirms NRC plans for 801028 meeting at corporate ofcs in Decatur, IL re facility regulatory performance
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/12 1p 06873 353

8011200203 Informs that util is planning repairs consisting of disc/guide bar alignment
SPENCER, J S Illinois Power Co 80/10/23 1p 07021 299

8011030196 Notification of 801105 meeting w/util in Clinton, IL re in situ info concerning design & layout of piping sys
GRIMES, C I Licensing Branch 3 80/10/24 3pp 06857 260

8011030185 Notification of 801112-14 meeting w/util in Clinton, IL re status of const completion
GRIMES, C I Licensing Branch 3 80/10/27 4pp 06857 254

8011040485 Responds to 801001 ltr re environ qualification of safety-related equipment Equipment description & sys where equipment installed included in FSAR Tables 3.10 & 3.11 Tests will be performed in vendor shop or by subcontractor
MULLER, O E Illinois Power Co 80/10/31 1p 06877 163

C Utility Environmental Report (ER), amends & correspondence

8011070318 Forwards updated distribution list for suppl & amends to FSAR, environ rept & general info
BUCKLEY, B C Licensing Branch 3 80/10/15 4pp 06919 312

801120484 Comments on environ rept per area fish & wildlife resource Biological monitoring programs, baseline studies & control of soil erosion by plantings & buffer strips satisfactorily completed. Bottomland timber loss should be mentioned
GROUTAGE, T M Interior, Dept of, Fish & Wildlife Service 80/11/02 2pp 06951 026

DOCKETED ITEMS

G Adjudicatory correspondence

8011030211 Petition to intervene as interested state in OL proceedings States interest & reserves right to submit issues to be litigated Certificate of Svc & notice of filing encl WILLIAMS, P. L. FAHNER, T. C., SEKULER, S. Illinois, State of 80/10/29 7pp 06899 087

8011050473 Informs of Bloomington-Normal chapter of Prairie Alliance request for public hearing Requests right to intervene in issuance of DLs for facilities FR notice has not been posted in library for public insp URIKH, J. Prairie Alliance 80/10/29 1p 02319 196

8011060319 Petition to intervene & request for hearing States interest, standing & issues to be litigated re impact of unresolved safety matters, adequacy of radwaste transportation & results of human errors Affidavits encl FOV, J., SCHMART, J., SAKELSON, A. Prairie Alliance 80/10/29 7pp 02319 196

8011170902 Notice of filings re responses to State of IL, Prairie Alliance & Bloomington-Normal Chapter petitions to intervene FAZIO, P. V. Illinois Power Co FAZIO, P. V. Schiff, Hardin & Waite 80/11/10 1p 06978 121

--8011170905 Response in opposition to Prairie Alliance petition to intervene & request for hearing Petition failed to raise aspect not fully & conclusively resolved in CP proceedings Certificate of Svc encl FAZIO, P. V., ZABEL, S. A. Illinois Power Co FAZIO, P. V. Schiff, Hardin & Waite 80/11/10 8pp 06978 122

8011170913 Response to State of IL petition to intervene Urges denial if no other interventions are permitted Effect of const & operation on electrical power rate charges not sufficient for standing Certificate of Svc encl FAZIO, P. V., ZABEL, S. A. Illinois Power Co FAZIO, P. V. Schiff, Hardin & Waite 80/11/10 6pp 06978 155

8011190046 Response in support of Prairie Alliance petition to intervene re standing Ruling on adequacy of petition premature prior to submittal of contentions KARMAN, M. Hearing Branch 2 80/11/18 3pp 06999 324

--8011190050 Response in support of State of IL 801029 petition to intervene if hearing held KARMAN, M. Hearing Branch 2 80/11/18 1p 06999 327

--8011190055 Response in opposition to Bloomington-Normal Prairie Alliance 801029 petition to intervene Limited appearance may be granted Notice of appearance & Certificate of Svc encl KARMAN, M. Hearing Branch 2 80/11/18 6pp 06999 328

K Utility Final Safety Analysis Report (FSAR) & amends

8011070318 Forwards updated distribution list for supplis & amends to FSAR, environ rept & general info BUCKLEY, B. C. Licensing Branch 3 80/10/15 4pp 06919 312

8011200248 Forwards Amend 1 to Clinton 1 & 2 FSAR Instructions for updating FSAR encl Revision status sheets & 470 oversize drawings available in Central Files only KOCH, L. J. Illinois Power Co 80/11/17 2pp 07022 242

--8011200254 Amend 1 to Clinton 1 & 2 FSAR, updating Section 1 7 drawings, process & instrumentation diagrams, & revising Chapter 7 * Illinois Power Co 80/11/14 1,200pp 07022 244

Q Inspection reports, IE Bulletins & correspondence

8011200700 Forwards IE Insp Rept 50-461/80-19 on 800915-19 & notice of violation FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/07 2pp 07021 260

--8011200206 Notice of violation from insp on 800915-19 * Region 3, Chicago, Office of the Director 80/10/06 1p 07021 262

--8011200214 IE Insp Rept 50-461/80-19 on 800915-19, Noncompliance noted, travelers completed w/o welders identification & weld matl heat/lot number WESTCOTT, H. M., LEE, R. L., KNOP, R. C. Region 3, Chicago, Office of the Director 80/10/06 8pp 07021 263

8011250281 Forwards IE Insp Rept 50-461/80-20 on 800902 & 22-30 & notice of violation FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/10 2pp 07056 307

--8011250283 Notice of violation from insp on 800902 & 22-30 * Region 3, Chicago, Office of the Director 80/10/07 1p 07056 311

--8011250286 IE Insp Rept 50-461/80-20 on 800902 & 22-30, Noncompliance noted approx 2,000 temporary attachments welded to drywell wall liner & primary containment liner w/o required controls LIVERMORE, H. H., KNOP, R. C. Region 3, Chicago, Office of the Director 80/10/07 6pp 07056 312

8011070314 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required KEPLER, J. O. Region 3, Chicago, Office of the Director 80/10/24 1p 06922 001

8011190479 Ack receipt of 801024 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/80-17 FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/05 1p 06998 105

--8011190483 Responds to NRC 800911 ltr re violations noted in IE Insp Rept 50-461/80-17 Corrective actions design criteria & project instruction issued to define & control engineering verification program KOCH, L. J. Illinois Power Co 80/10/24, 1p 06998 106

B Reportable occurrences, LERs & related correspondence

8011030558 Interim deficiency rept re suspect cracking in hardware Fittings Preliminary tensile tests & onsite visual insp of stock hardware conducted Midland/Ross Super Strut Co revised production methods to increase bend radius in fittings. GERSTNER, W. C. Illinois Power Co 80/10/22 2pp 06855 037

8011030470 Final deficiency rept re inadequate instructions & procedures for const welding of temporary & permanent nonsafety attachments New procedure BAP 2 21 developed & temporary attachments removed KOCH, L. J. Illinois Power Co 80/10/24 3pp 01756, 001

8011040539 Advises that final deficiency rept re thin-walled elbow will be filed in early Dec 1980 KOCH, L. J. Illinois Power Co 80/10/28 1p 06873, 108

8011170268 Ack receipt of 801020 interim deficiency rept re inadequate const controls & electrical raceway hanger installation FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/30 1p 06981 242

8011170228 Ack receipt of 801024 final deficiency rept re welding of permanent & temporary nonsafety attachments to safety-related structures & components FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/03 1p 06988, 354

8011170254 Ack receipt of 801022 interim deficiency rept re suspect cracking in certain hardware for electrical hangers supplied by Midland/Ross Super Strut FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch, 80/11/03 1p 06981 239

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements, Provides summary listing of all approved TH1-2 related requirements EISENHUT, D. O. Division of Licensing 80/09/05 209pp

8011100486 Ltr to all licensees of operating plants & applicants for CLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101 EISENHUT, D. O. Division of Licensing 80/10/01 5pp.

8011100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl EISENHUT, D. O. Division of Licensing, 80/10/06 6pp.

DOCKETED ITEMS

21

BO11070318 Forwards updated distribution list for suppl & amends to
FSAR; environ rept & general info
BUCKLEY, B. C Licensing Branch 3 80/10/15 4pp 06919 312

BO11040485 Responds to 801001 ltr re environ qualification of safety-
related equipment Equipment description & sys where
equipment installed included in FSAR Tables 3 10 & 3 11
Tests will be performed in vendor shop or by subcontractor
WULLER, G E Illinois Power Co 80/10/31 1p 06877 163

C Utility Environmental Report (ER), amends & correspondence

BO11070318 Forwards updated distribution list for suppl & amends to
FSAR; environ rept & general info
BUCKLEY, B C Licensing Branch 3 80/10/15 4pp 06919 312

BO11120484 Comments on environ rept per area fish & wildlife resources
Biological monitoring programs, baseline studies & control of
soil erosion by plantings & buffer strips satisfactorily
completed Bottomland timber loss should be mentioned.
GROUTAOE, T M Interior, Dept of, Fish & Wildlife Service 80/11/03
2pp 06931 026

D Adjudicatory correspondence

BO11050211 Petition to intervene as interested state in OL proceedings
States interest & reserves right to submit issues to be
litigated. Certificate of Svc & notice of filing encl
WILLMAN, P L, FAHNER, T C, BEKULER, S Illinois, State of 80/10/29
7pp. 06899 087

BO11050493 Informs of Bloomington-Normal chapter of Prairie Alliance
request for public hearing Requests right to intervene in
issuance of OLs for facilities FR notice has not been
posted in library for public insp
URISH, J Prairie Alliance 80/10/29 1p 02319 196

BO11060219 Petition to intervene & request for hearing. States interest,
standing & issues to be litigated re impact of unresolved
safety matters, adequacy of radwaste transportation & results
of human errors Affidavits encl
FOY, J, SCHWART, J, SAMELSON, A Prairie Alliance 80/10/29 7pp
02319 196

BO11170902 Notice of filings re responses to State of IL, Prairie
Alliance & Bloomington-Normal Chapter petitions to
intervene.
FAZIO, P V Illinois Power Co FAZIO, P V Schiff, Hardin & Waite
80/11/10. 1p 06978 121

--BO11170906 Response in opposition to Prairie Alliance petition to
intervene & request for hearing Petition failed to raise
aspect not fully & conclusively resolved in CP proceedings
Certificate of Svc encl
FAZIO, P V, ZABEL, S A Illinois Power Co FAZIO, P V Schiff,
Hardin & Waite. 80/11/10 8pp 06978 122

BO11170913 Response to State of IL petition to intervene Urges denial
if no other interventions are permitted Effect of const &
operation on electrical power rate charges not sufficient
for standing. Certificate of Svc encl
FAZIO, P V, ZABEL, S A Illinois Power Co FAZIO, P V Schiff,
Hardin & Waite 80/11/10 6pp 06978 195

BO11190046 Response in support of Prairie Alliance petition to
intervene re standing Ruling on adequacy of petition
premature prior to submittal of contentions
KARHAN, M. Hearing Branch 2 80/11/18 3pp 06999 324

--BO11190050 Response in support of State of IL 801029 petition to
intervene if hearing held.
KARHAN, M. Hearing Branch 2 80/11/18 1p 06999 327.

--BO11190055 Response in opposition to Bloomington-Normal Prairie
Alliance 801029 petition to intervene Limited appearance may
be granted. Notice of appearance & Certificate of Svc encl.
KARHAN, M. Hearing Branch 2 80/11/18 6pp 06999 328

K Utility Final Safety Analysis Report (FSAR) & amends

BO11070318 Forwards updated distribution list for suppl & amends to
FSAR; environ rept & general info.
BUCKLEY, B C Licensing Branch 3. 80/10/15 4pp 06919 312

BO11200748 Forwards Amend 1 to Clinton 1 & 2 FSAR Instructions for
updating FSAR encl. Revision status sheets & 470 oversize
drawings available in Central Files only
KOCH, L J. Illinois Power Co. 80/11/17 2pp 07022 242

--BO11200254 Amend 1 to Clinton 1 & 2 FSAR, updating Section 1 7 drawings
process & instrumentation diagrams, & revising Chapter 7
* Illinois Power Co 80/11/14 1,200pp 07022 244

O Inspection reports, IE Bulletins & correspondence

BO11070314 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ
Qualification of Class IE Equipment " No written response
required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/24
1p 06922 001

BO11190479 Ack receipt of 801024 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 80-461/80-17
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/03 1p 06998 105

DOCKET 80-465 RINGHALS, UNIT 3

A Application/Construction stage documents & correspondence

BO11200409 Submits application to amend export license extending date
from 810201 to Dec 31, 2020 & doubling value of export
HERSCH, M. M Westinghouse Electric Corp 80/10/31 1p. 07020 102

DOCKET 80-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

O Adjudicatory correspondence

BO11100623 Forwards util 800904 ltr to Congressman Brooks re cost of
unwarranted delay for hearing on CP application. Urges
assistance to have NRC cease benign neglect of nuclear
projects
BRDOKS, J House of Rep 80/10/20 4pp 06940 353.

BO11050157 Order directing JF Doherty to inform ASLB whether or not
800730 motion to subpoena Read rept is withdrawn Doherty
801022 motion for extension until 801115 to respond to
motions for summary disposition granted
WOLFE, B J Atomic Safety and Licensing Board Panel 80/10/30 2pp
06897 300

BO11050194 Response in opposition to JF Doherty 801022 second request
for indefinite extension to suppl responses re motions for
summary judgment on Contentions 5, 15, 33 & 48 Inability to
obtain info due to lack of diligence W/Certificate of Svc
CULP, R H, COPELAND, J O. Houston Lighting & Power Co CULP, R H
Lewenstein, Newman, Reis, Axelrad & Toll 80/10/30 5pp 06899 065

BO11050412 Response in opposition to JF Doherty 801013 motions to file
direct testimony on TX PIRO contentions & to consolidate
rejected Contention 1 w/recently admitted contention re
effects of low level radiation Certificate of Svc encl
BLACK, R. L. Hearing Branch 1 80/11/03 13pp 06898 187

BO11060180 Response in opposition to TX PIRO 801008 motion for summary
disposition of contentions re barge slip, cooling lake,
alternative sources & technical qualifications Assertions
w/o evidentiary basis W/contentions & Certificate of Svc
BLACK, R. L. Hearing Branch 3 80/11/03 22pp 06912 125

BO11070240 Advises that JM Scott ltr postmarked 800926 will be sent to
Commission Secretary for appropriate consideration re
interim policy statement. Class 9 comments will not be
considered for response due to bearing on CP litigation
SHAPAR, H K Office of the Executive Legal Director. 80/11/05 5pp.
06911 001.

BO11140093 Motion to compel info & documents used by TX PIRO for
preparation of A Sanson 790416 deposition Requests response
to encl 791212 & 801013 ltrs re qualification & opinions of
identified witnesses W/proposed order & Certificate of Svc
BIDDLE, C T., NEWMAN, J R Houston Lighting & Power Co BIDDLE, C. T
Baker & Botts 80/11/06 13pp 06963 178

BO11170244 Response to W Schuessler second set of interrogatories &
requests for production of documents Describes discussions
w/Austin County, TX Sheriff Dept re evacuation analysis
W/affidavit, prof qualifications & Certificate of Svc
RASKIN, D B, COPELAND, J O Houston Lighting & Power Co RASKIN, D B.
Lewenstein, Newman, Reis, Axelrad & Toll 80/11/06 15pp 06982 011

BO11140493 Response to W Schuessler request for addl answers to first
set of interrogatories Applicant is not in possession of
data analyzing hypothetical significant offsite radiological
releases Certificate of Svc encl
RASKIN, D B., COPELAND, J O Houston Lighting & Power Co RASKIN, D. B.
Lewenstein, Newman, Reis, Axelrad & Toll 80/11/10. 7pp 06963 065

DOCKETED ITEMS

801180147 Motion to compel intervenors Cumings, Griffith, Johnston & Lerner response to 801022 first set of interrogatories
Complies w/ASLB 801003 order requiring info about unresolved discovery matters by 801114 W/Certificate of Svc
COPELAND, J O , NEWMAN, J R Houston Lighting & Power Co
COPELAND, J O Baker & Botts 80/11/10 4pp 06987 203

801140511 Response in opposition to JF Doherty 801015 motion seeking admission of Contention 50 re jet pump cracking in reactor coolant circulation sys Contention will broaden issue & may impact on hearing schedule Certificate of Svc encl
BLACK, R L Hearing Branch 3 80/11/12 8pp 06983 105

801170908 Order directing NRC applicant & intervenor Marrack to present evidence re impact upon migratory waterfowl re Marrack Contention 2(c) Rules on TX PIRQ Contentions 1,2,4, 5,7, AB & A12 Dismisses intervenor Potthoff
LINENBERGER, O , WOLFE, B J Atomic Safety and Licensing Board Panel
80/11/13 25pp 06978 130

801190166 Responds to ASLB 801003 memorandum & order No unresolved matters except various motions presently before ASLB
BLACK, R L Hearing Branch 3 80/11/14 1p 06998 203

801190176 Rept per ASLB 801003 memorandum & order requesting submittal of unresolved matters for 801202 rehearing conference, by 801114 No problems of authenticity re evidential documents Certificate of Svc encl
NEWMAN, J R , COPELAND, J O Houston Lighting & Power Co NEWMAN, J R Lowenstein, Neuman, Reis, Axelrad & Toll 80/11/14 7pp 06978 225

801190188 Order correcting Line 7, Page 24 of ASLB 801113 order ruling on environ contentions Line should read "design, a 193,840 acre (306 sq mi) marine biomass farm could produce annually the "
WOLFE, B J Atomic Safety and Licensing Board Panel. 80/11/14 1p, 06998 242

8011210422 Advises that applicant has identified NUREG-0594, "Occupational Radiation Exposure at Commercial Nuclear Power Reactors 1978," as document to be used in prepared testimony addressing TX PIRQ Addl Contention 21
BIDDLE, C T Baker & Botts 80/11/17 1p 07035.112

801280004 Appeals ASLB initial ruling on Contention 6 ASLB erred in ruling marine biomass farm not viable & reasonable alternative Certificate of Svc encl
POTTHOFF, F H Affiliation Unknown, 80/11/17 3pp 06915 001

801240502 Responds to 801030 ltr to S Bohinski informing that correspondence re hearing schedule for Allens Creek proceeding has not been received Name is now on applicable svc list to receive notices
BLACK, R L Hearing Branch 1 80/11/18 1p 07047 021.

801280010 Order ruling on JF Doherty & TX PIRQ contentions. Doherty Contention 1 not admitted Amended petition to intervene & 12 TX PIRQ contentions also not admitted Doherty Contention 50 may be filed out of time
LINENBERGER, O , WOLFE, B J Atomic Safety and Licensing Board Panel.
80/11/20, 12pp 07084 007

801280012 Order directing applicant to submit list of environ contentions & Board questions sequentially presenting case in chief at evidentiary hearing
WOLFE, B J Atomic Safety and Licensing Board Panel 80/11/21 2pp, 07084 019

801280037 Order scheduling environ phase of evidentiary hearing on 810112 Limited appearance statements will be taken 810112-13 w/evidence presented by parties following
WOLFE, B J Atomic Safety and Licensing Board Panel 80/11/25 2pp 07084 083

H General correspondence

8010240404 Comments on new interim policy on Class 9 accidents & rulemaking on reactor siting criteria re facilities
Commission should direct ASLB to include Class 9 accidents in suppl to EIS
SCOTT, J Affiliation Unknown 80/10/22 1p 01726.332

DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

G Adjudicatory correspondence

8011210422 Advises that applicant has identified NUREG-0594, "Occupational Radiation Exposure at Commercial Nuclear Power Reactors 1978," as document to be used in prepared testimony addressing TX PIRQ Addl Contention 21
BIDDLE, C T Baker & Botts 80/11/17 1p. 07035.112

DOCKET 50-471 PILGRIM NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing, 80/10/01, 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

G Adjudicatory correspondence

8009190299 Responds to FOIA request for 13 documents listed in bibliography of NUREG-0625, "Rept of Siting Policy Task Force " Documents 6-8 & 13 are available in PDR Forwards remaining documents
FELTON, J M Division of Rules and Records 80/09/04 1p.

--8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features
MINOQUE, R B Office of Standards Development, Director, SECY-79-362 79/06/04 7pp

--8009190630 Requests that encl, "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards,
SCINTO, J F. Hearings Division 79/04/04 16pp.

8011230031 Forwards J Levine affidavit re X/Q analysis
GODDARD, R J Hearing Branch 2, 80/11/19, 1p 07056.191

--8011230032 Affidavit re analysis of short-term relative concentration for DBE described in Section 2.3.4 of June, 1975 SER. Since use of X/Q value in SER produced acceptable doses, use of direction dependent method does not alter conclusion
LEVINE, J, Accident Evaluation Branch, 80/11/19 5pp 07056.192.

DOCKET STN-30-482 WOLF CREEK GENERATING STATION

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D G Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D G Division of Licensing 80/10/06 6pp

801100027 Summary of 801007-10 meeting w/utls re completion dates of plants, site visits & forecasted fuel load dates
STARK, R H. Licensing Branch 1 80/10/30 8pp 0692B, 347

M Antitrust correspondence

8011250287 Forwards addl antitrust info, in response to NRC 800708 ltr. Util correspondence w/City of Garrettsville, OH; City of Oshtemo, MI; Board of Public Utilities & Spiegel & McDiarmid encl.
KOESTER, O L Kansas Gas & Electric Co 80/11/14 102pp.
07035, 001.

Q Inspection reports, IE Bulletins & correspondence

801170550 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " No piping sys has been found containing Youngstown matls w/hoop stress equal to or greater than 85% ASME code allowable
SEIKEN, B J Standardized Nuclear Unit Power Plant System 80/08/20 2pp 06975, 105

8011200029 Ack receipt of 800904 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-482/80-14.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/09/15 1p 07020 221

--8011200034 Responds to NRC 800806 ltr re violations noted in IE Insp Rept 50-482/80-14 Corrective actions GC retraining sessions have been scheduled
KOESTER, O L Kansas Gas & Electric Co. 80/09/04 2pp 07020 222

801170720 Forwards IE Insp Rept 50-482/80-14 on 800801-0905 & notice of violation Notice already forwarded by 800806 ltr
SEIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/10/09 2pp 06977 343

--801170727 IE Insp Rept 50-482/80-14 on 800801-0905 Noncompliance noted. Failure to follow procedures & instructions re rebar installation for dome placement, Lift 7.
VANDEL, T E, OBERG, C R, CROSSMAN, W A Region 4, Dallas, Office of the Director 80/10/08 8pp 06977, 345

801106076B Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting." No written response required
BEYFRIT, K V. Region 4, Dallas, Office of the Director 80/10/10. 1p 06909, 075

801120126 Forwards IE Insp Rept 50-482/80-19 on 800930-1001. No noncompliance noted.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/10/10. 2pp. 07056, 264.

--801120132 IE Insp Rept 50-482/80-19 on 800930-1001 No noncompliance noted. Major areas inspected, safety-related concrete placement of reactor containment bldg dome
TAPIA, J I., CROSSMAN, W A. Region 4, Dallas, Office of the Director HALL, R E Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/10/10. 2pp. 07056, 266.

801130040 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
BEYFRIT, K V. Region 4, Dallas, Office of the Director 80/10/24. 1p. 06958, 135.

801170023 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2 " No written response required
BEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/27 1p 06981 292

801170623 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
BEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/31 1p 06977 27B

S Reportable occurrences, LERs & related correspondence

801170194 Interim rept re potential deficiency in nuclear coating in reactor bldg Bechtel presently reviewing coating procedures
Suppl to rept expected by 801101
KOESTER, O L Kansas Gas & Electric Co 80/08/25 1p 06981 344

801120582 Interim deficiency rept re loose bushing condition in sway struts furnished by ITT Grinnell & Bergen Patterson Three Bergen Patterson & 9 ITT Grinnell sway struts are affected
Vendors will examine & Bechtel will make safety review
KOESTER, O L Kansas Gas & Electric Co 80/08/29. 2pp 06953, 343

801140618 Final rept re 2-inch 90 degree elbows, mfg by Capital Mfg Co Presence of shallow forging seam is not detrimental to fitting matl Condition not reportable per 10CFR50.35e
KOESTER, O L Kansas Gas & Electric Co 80/08/29 1p 06965 347

8011040321 Interim deficiency rept re undersized socket welds All deficient welds identified will be repaired Future insp of welds will include 360 degree criteria including entire weld circumference.
KOESTER, O L Kansas Gas & Electric Co 80/10/30 7pp 06884, 244.

801120497 Clarifies corrective actions indicated in 800724 generic rept re defective pipe support sway struts All struts are being checked for tightness at Corner & Lada facility prior to shipment
SEIKEN, B J Standardized Nuclear Unit Power Plant System 80/11/07. 2pp 06953, 106

DOCKET STN-30-483 CALLOWAY PLANT, UNIT 1

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D G Division of Licensing. 80/09/05. 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D G Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D G. Division of Licensing 80/10/06 6pp

801100027 Summary of 801007-10 meeting w/utls re completion dates of plants, site visits & forecasted fuel load dates
STARK, R H Licensing Branch 1 80/10/30. 8pp 0692B 347

8011200353 Forwards review of environ questions generated by ANL. Some questions address fossil plants & some are CP related & not relevant to DL stage W/o encl
STARK, R H. Licensing Branch 1. 80/11/12 1p 07019, 002

8011260038 Forwards clarification of FR notice of receipt of application for facility DL notice of consideration of issuance of facility DL & notice of opportunity for hearing.
YOUNGBLOOD, B J. Licensing Branch 1 80/11/14 2pp. 07074, 236

--8011260041 Clarification of notice of receipt of application for facility DL, consideration of issuance of facility DL & notice of opportunity for hearing.
BOURNIA, A. Licensing Branch 1. 80/11/14 4pp. 07074, 238

DOCKETED ITEMS

C Utility Environmental Report (ER), amends & correspondence

801170033 Notification of 80118-20 site visit w/ANL, MD Dept of Natural Resources, MD Dept of Conservation & Util in preparation for review of environ rept
STARK, R M Licensing Branch 1 80/11/07 5pp 06981.314.

F Security, medical, emergency & fire protection plans

8011060305 Informs that submittal date for guard training & qualification plan has been changed to 810501 from 801101. Delay is due to recent schedule changes postponing fuel loading by 6 months
BRYAN, J K Union Electric Co 80/10/28 1p 06915.295

G. Adjudicatory correspondence

801100283 Response stating no objection to JO Reed 801023 amended petition to intervene demonstrating standing. Reserves right to contest 801023 outlined contentions. Certificate of Svc encl
BERNSTEIN, D L, BAXTER, T A, CHARNOFF, Q Union Electric Co. 80/11/05 5pp 06929 086

801130301 Response in support of JO Reed 801022 amended petition to intervene & request for hearing. Petitioner Contentions 3 & 4 should be admitted & request for free copying & svc must be granted. Certificate of Svc encl
LEBBY, R P Hearing Branch 3 80/11/10 14pp. 06958 298

801180139 Response in opposition to Coalition for Environ. St Louis Region: Missourians for Safe Energy, Crowded Alliance & K Drey 801023 addendum to 800923 joint petition to intervene. No new info presented re palpable harm. Certificate of Svc encl
BERNSTEIN, D L, CHARNOFF, Q Union Electric Co. BERNSTEIN, D L, Shaw, Pittman, Potts & Trowbridge 80/11/10 7pp 06987 196

8011280026 Response in opposition to NRC 801110 response to JO Reed amended petition to intervene. NRC should review Contention 2 in light of change in 10CFR30.33(g) re emergency plans. Certificate of Svc encl.
REED, J Q. Affiliation Unknown 80/11/18 4pp 07084 049

G. Inspection reports, IE Bulletins & correspondence

801170550 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe." No piping sys has been found containing Youngstown matls w/ hoop stress equal to or greater than 85% ASME code allowable
BEIKEN, B J Standardized Nuclear Unit Power Plant System. 80/08/20 2pp 06973.105

801170198 Forwards IE Insp & Meeting Rept 50-483/80-14 on 800410.0529, 0610-12, 0806 & 14. No noncompliance noted
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/09/16 2pp. 06979 275

--801170204 IE Insp & Meeting Rept 50-483/80-14 on 800410.0529, 0610-12, 0806 & 14. No noncompliance noted. Major areas discussed, until 780310 submittal re acceptability of embedded plates.
GALLAGHER, E J Region 3, Chicago, Office of the Director.
HAYES, D W, FIGURELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/03 10pp 06979.277.

--801170212 Summarizes responses to NRC questions re util embed rept. Responses will be subj of 800529 meeting. Supporting documentation encl
SCHWELL, D F Union Electric Co 80/05/23 14pp 06979.288

--801170221 Forwards Blue-700, Daniel Intl Corp 800529 telcon sheet & QC Procedures QCP-507, Revision 5 in response to 800529 request for addl input to questions re embed rept.
SCHWELL, D F Union Electric Co. 80/06/19 7pp. 06979.302.

--801170227 Detailed procedures for, "Test Program to Evaluation Welds of Anchor Rods & Studs to Embedded Plates," Revision 2.
PARIKH, K Bechtel Power Corp (subs of Bechtel Corp). 80/08/05. 9pp. 06979 309

--801170232 "Welds of Anchor Rods & Studs to Embedded Plates," interim rept.
PARIKH, K. Bechtel Power Corp. (subs of Bechtel Corp). 80/08/27, 25pp. 06979 318

801180379 Forwards IE Insp Rept 50-483/80-22 on 800818-20 & notice of violation.
FIGURELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/29. 2pp. 06989.167

--801180386 Notice of violation from insp on 800818-20
* Region 3, Chicago, Office of the Director 80/09/22. 2pp. 06989.169.

--801180391 IE Insp Rept 50-483/80-22 on 800818-20. Noncompliance noted: failure to identify safety-related rip-rap; failure to perform necessary soil tests & failure to indoctrinate & train craft personnel
LANDSMAN, R B, SCHAPKER, J F Region 3, Chicago, Office of the Director HAYES, D W Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/22 8pp 06989.171.

801100297 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director. 80/10/24. 1p 06921 324

B Reportable occurrences, LERs & related correspondence

801120497 Clarifies corrective actions indicated in 800724 generic rept re defective pipe support sway struts. All struts are being checked for tightness at Corner & Lada facility prior to shipment
BEIKEN, B J. Standardized Nuclear Unit Power Plant System. 80/11/07. 2pp 06953.106

801190291 Amended deficiency rept re Bergen-Paterson pipe support strut w/mechanical shock arrester having insufficient clearances to permit specified angular movement. Vendor determined addl delivered assemblies are deficient
BRYAN, J K Union Electric Co 80/11/14 1p. 06996.236.

DOCKET BYN-30-484 TYRONE ENERGY PARK, UNIT 1G Adjudicatory correspondence

8011060244 Order declining deferral of Tyrone permit revocation & denying Dakota Commissions' 800711 request for hearing. Chairman Ahearne & Commissioners Hendrie, Gillsky & Bradford separate opinions encl
CHILK, B J Office of the Secretary of the Commission. 80/10/30 8pp 06911.203.

801180015 Petition for reconsideration of Commission 801103 order denying ND & SD Commissions' request for deferral of CP revocation. Urges intervention & hearing based on restatement of interest, injury in fact & standing. W/Certificate of Svc.
FRANCIS, F E South Dakota, State of ADRAQNA, J. M. North Dakota, State of FRANCIS, F E Spiegel & McDiarmid. 80/11/13 23pp. 06985 216

T. Hearing transcripts on non-antitrust matters

801110569 Transcript of 801031 Affirmation Session 80-48 re SECY-A-146 & Byron Unit 1.
* Commissioners 80/10/31 6pp. 06949.324.

DOCKET BYN-30-485 STERLING POWER PROJECT NUCLEAR, UNIT 1H General correspondence

8011040384 Informs of changes in organizational structure per FE Drake retirement as board chairman & chief executive officer. Corporate organization chart, effective 801001, encl
MAIER, J. E. Rochester Gas & Electric Corp. 80/10/29. 2pp. 06880.176.

G Inspection reports, IE Bulletins & correspondence

8011060665 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/10/24 1p. 06914.297.

8011070232 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/10/24. 1p. 06924.212.

801140124 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/10/31. 1p. 06968.219.

DOCKETED ITEMS

23

801170843 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
ORIER, B H Region 1, Philadelphia, Office of the Director.
80/10/31 1p 06979 222

DOCKET STN-30-486 CALLOWAY PLANT, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 4pp.

801100027 Summary of 801007-10 meeting w/utls re completion dates of plants, site visits & forecasted fuel load dates.
STARK, R M Licensing Branch 1 80/10/30 8pp. 06928 347.

8011200353 Forwards review of environ questions generated by ANL Some questions address fossil plants & some are CP related & not relevant to OL stage W/o encl
STARK, R M Licensing Branch 1 80/11/12 1p. 07019 002

8011260038 Forwards clarification of FR notice of receipt of application for facility OL/notice of consideration of issuance of facility OL & notice of opportunity for hearing
YOUNGBLOOD, B J Licensing Branch 1. 80/11/14 2pp 07074 236.

--8011260041 Clarification of notice of receipt of application for facility OL/consideration of issuance of facility OL & notice of opportunity for hearing
BOURNIA, A. Licensing Branch 1 80/11/14 4pp 07074.238.

F Security, medical, emergency & fire protection plans

8011060505 Informs that submittal date for guard training & qualification plan has been changed to 810501 from 801101 Delay is due to recent schedule changes postponing fuel loading by 6 months
BRYAN, J K Union Electric Co 80/10/28 1p. 06915 295

G Adjudicatory correspondence

801100283 Response stating no objection to JO Reed 801023 amended petition to intervene demonstrating standing Reserves right to contest 801023 outlined contentions. Certificate of Svc encl.
BERNSTEIN, D L., BAXTER, T A., CHARNOFF, G Union Electric Co.
80/11/05 5pp. 06929 086

801130301 Response in support of JO Reed 801022 amended petition to intervene & request for hearing. Petitioner Contentions 3 & 4 should be admitted & request for free copying & svc must be granted Certificate of Svc encl.
LEBBY, R P. Hearing Branch 3. 80/11/10 14pp 06958.278.

801180139 Response in opposition to Coalition for Environ. St Louis Region, Missourians for Safe Energy, Graudad Alliance & K Drey 801023 addendum to 800925 joint petition to intervene. No new info presented re palpable harm. Certificate of Svc encl
BERNSTEIN, D L., CHARNOFF, G Union Electric Co BERNSTEIN, D L Shaw, Pittman, Potts & Trowbridge 80/11/10. 7pp. 06987.196

8011280026 Response in opposition to NRC 801110 response to JO Reed amended petition to intervene NRC should review Contention 2 in light of change in 10CFR50.33(g) re emergency plans. Certificate of Svc encl
REED, J O. Affiliation Unknown 80/11/18. 4pp 07084 049.

G Inspection reports, IE Bulletins & correspondence

801170550 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " No piping sys has been found containing Youngstown matls w/hoop stress equal to or greater than 85% ASME code allowable
SEIKEN, S J Standardized Nuclear Unit Power Plant System 80/08/20 2pp. 06975 105

8011070297 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
KEPLER, J O. Region 3, Chicago, Office of the Director. 80/10/24 1p 06921 324

S Reportable occurrences, LERs & related correspondence

801120497 Clarifies corrective actions indicated in 800724 generic rept re defective pipe support sway struts All struts are being checked for tightness at Corner & Lada facility prior to shipment
SEIKEN, S J Standardized Nuclear Unit Power Plant System 80/11/07 2pp 06953 106.

DOCKET STN-30-488 PERKINS NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D O. Division of Licensing. 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D O. Division of Licensing 80/10/01. 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D O. Division of Licensing 80/10/06 8pp.

8011040481 Forwards list re equipment which will undergo environ qualification tests, to be conducted within next two yrs, in response to NRC 801001 request
PARKER, W O. Duke Power Co. 80/10/31 3pp.

G Adjudicatory correspondence

8011060187 Exceptions & notice of appeal from ASLB 800222 partial initial decision approving alternate site analysis. Uncontradicted evidence of water defect was disregarded by ASLB Certificate of Svc encl
PFEFFERKORN, W. Pfefferkorn & Cooley, P A. 80/10/28 27pp 06912 098.

8011280041 Request for extension until 801231 to file brief supporting 801028 exceptions due to heavy case load Certificate of Svc encl
MCQARRY, J M Duke Power Co MCQARRY, J M Debevoise & Liberman. 80/11/24. 4pp 07084 085

8011280059 Notice of availability of procedural assistance in adjudicatory licensing proceedings, published in 800723 FR. In order to qualify for aid, intervenor must submit statement showing need to ASLB
BOMERB, E S. Atomic Safety and Licensing Board Panel. 80/11/24. 1p. 07084 102

G Inspection reports, IE Bulletins & correspondence

801170678 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 80/10/24. 1p. 06976 242.

DOCKETED ITEMS

DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011040481 Forwards list re equipment which will undergo environ qualification tests, to be conducted within next two yrs, in response to NRC 801001 request
PARKER, W O Duke Power Co 80/10/31 3pp

G Adjudicatory correspondence

8011060187 Exceptions & notice of appeal from ASLB 800222 partial initial decision approving alternate site analysis Uncontradicted evidence of water defect was disregarded by ASLB Certificate of Svc encl
PFEFFERKORN, W Pfefferkorn & Cooley, P A 80/10/28 27pp.
06912 098

8011280041 Request for extension until 801231 to file brief supporting 801028 exceptions due to heavy case load Certificate of Svc encl
MCGARRY, J M Duke Power Co MCGARRY, J M Debovoise & Liberman 80/11/24 4pp 07084 085

8011280059 Notice of availability of procedural assistance in adjudicatory licensing proceedings, published in 800725 FR in order to qualify for aid, intervenor must submit statement showing need to ASLB
BOWERS, E S Atomic Safety and Licensing Board Panel 80/11/24 1p
07084 102

G Inspection reports, IE Bulletins & correspondence

801170678 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24 1p 06976 242

DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8011040481 Forwards list re equipment which will undergo environ qualification tests, to be conducted within next two yrs, in response to NRC 801001 request
PARKER, W O Duke Power Co 80/10/31 3pp

G Adjudicatory correspondence

8011060187 Exceptions & notice of appeal from ASLB 800222 partial initial decision approving alternate site analysis Uncontradicted evidence of water defect was disregarded by ASLB Certificate of Svc encl
PFEFFERKORN, W Pfefferkorn & Cooley, P A 80/10/28 27pp
06912 098

8011280041 Request for extension until 801231 to file brief supporting 801028 exceptions due to heavy case load Certificate of Svc encl
MCGARRY, J M Duke Power Co MCGARRY, J M Debovoise & Liberman, 80/11/24 4pp 07084 085

8011280059 Notice of availability of procedural assistance in adjudicatory licensing proceedings, published in 800725 FR in order to qualify for aid, intervenor must submit statement showing need to ASLB
BOWERS, E S Atomic Safety and Licensing Board Panel 80/11/24 1p
07084 102

G Inspection reports, IE Bulletins & correspondence

801170678 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/10/24 1p 06976 242

DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing, 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D O. Division of Licensing 80/10/01. 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D O. Division of Licensing 80/10/06 6pp

8011040481 Forwards list re equipment which will undergo environ qualification tests, to be conducted within next two yrs, in response to NRC 801001 request
PARKER, W O Duke Power Co 80/10/31 3pp

G Inspection reports, IE Bulletins & correspondence

801170678 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
O'REILLY, J P. Region 2, Atlanta, Office of the Director, 80/10/24. 1p

8011260423 Suppl 801016 acknowledgement ltr re receipt of util 800811 ltr informing NRC of steps taken to correct violations noted in IE insp repts. Action noted in Paragraph b of IE 801016 ltr remains outstanding.
MURPHY, C E Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/12 1p

DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D O Division of Licensing, 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D O. Division of Licensing 80/10/01. 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl.
EISENHUT, D O Division of Licensing, 80/10/06. 6pp.

8011040481 Forwards list re equipment which will undergo environ qualification tests, to be conducted within next two yrs, in response to NRC 801001 request.
PARKER, W. O. Duke Power Co 80/10/31. 3pp.

G. Inspection reports, IE Bulletins & correspondence

801170678 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/10/24. 1p.

8011260423 Suppl 801016 acknowledgement ltr re receipt of util 800811 ltr informing NRC of steps taken to correct violations noted in IE insp repts. Action noted in Paragraph b of IE 801016 ltr remains outstanding
MURPHY, C E Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/12 1p

DOCKET STN-90-493 CHEROKEE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D. G. Division of Licensing 80/10/01 5pp

801100937 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl.
EISENHUT, D. G. Division of Licensing 80/10/06 6pp

8011040481 Forwards list re equipment which will undergo environ qualification tests, to be conducted within next two yrs. in response to NRC 801001 request
PARKER, W Q Duke Power Co 80/10/31 3pp.

G. Inspection reports, IE Bulletins & correspondence

801170678 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24. 1p

8011260423 Suppl 801016 acknowledgement ltr re receipt of util 800811 ltr informing NRC of steps taken to correct violations noted in IE insp repts. Action noted in Paragraph b of IE 801016 ltr remains outstanding
MURPHY, C E Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/12 1p.

DOCKET STN-90-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D G Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D G Division of Licensing. 80/10/01 5pp.

801100937 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl.
EISENHUT, D. G. Division of Licensing 80/10/06 6pp.

8011030535 Requests that encl preserve insp & testing requirements to ensure snubber operability be included in licensing process & be implemented at facility
TEDESCO, R L Assistant Director for Licensing 80/10/17. 4pp. 06873.006

8011040603 Confirms discussion w/DO Barker re addl auxiliary feedwater sys safety-related welding. Concurs w/util 801017 plan to re-examine & repair welding NRC must review field welding involving greater than 3/4-inch thickness.
BEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/10/22. 2pp 06873:161.

801120587 Requests branch review of util 800228 request for clarification of NRC request to delete emergency boration sys. Util presently plans other use of space designated for emergency boration sys. Early resolution desired
SCHWENGER, A. Licensing Branch 2 80/10/30. 2pp. 06953:339.

8011040173 Forwards response to NRC 800924 request for revised QA program description & response to specific questions
OPREA, O W Houston Lighting & Power Co 80/10/31 4pp 06877 016

--8011040178 QA program during design & const
* Houston Lighting & Power Co 80/10/31 36pp 06877 020

--8011040183 QA program during design & const
* Brown & Root Corp (subs of Halliburton Corp) 80/10/31 91pp 06877 057

--8011040188 Responds to public meeting 800819 request for util analysis & response to Bechtel recommendations. Specific responses encl
OPREA, O W Houston Lighting & Power Co 80/09/24 7pp 06877 148

8011060562 Informs that licensee in process of having vendors/suppliers contacted to obtain requested info re environ qualification tests on safety-related equipment, per 801023 request. Info will be submitted by 801129
BARKER, D Q Houston Lighting & Power Co 80/10/31 2pp 06912 255

801120348 Updates 801002 request for restart of limited complex safety-related concrete activities. Current projected placement dates for previously identified placements encl
OPREA, O W Houston Lighting & Power Co 80/11/03 5pp 06952 014

8011200551 Notifies that util 801031 revised QA program for installation, insp & testing of structural concrete is satisfactory for const of facilities
TEDESCO, R L Assistant Director for Licensing 80/11/04 2pp 0701B 200

801190466 Notification of 80118 meeting w/util & Brown & Root Corp in Houston, TX to discuss status of engineering design.
BELL, D. Licensing Branch 2 80/11/12. 3pp 06996:197

O Adjudicatory correspondence

8011040310 Requests names of inspectors who supplied info re harassment at facility & names of employees responsible for harassment & intimidation. Related correspondence.
MILLER, B A Citizens Concerned About Nuclear Power, Inc. 80/10/28. 1p 06873:136

8011040530 Submits change of address & lists individuals authorized to speak in intervention process
EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/10/28. 1p. 06873 113.

8011050489 Requests name of company hired for testing backfill for stability & relationship to util, Brown & Root or any other facility affiliates
EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/10/29 1p 06899:055

8011060234 Requests V Stello closed door statement re order to show cause. Related correspondence
EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/10/29. 1p 06911:195

8011050440 Requests const deficiency repts missing from files. Related correspondence
EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/10/30. 1p. 06899.036.

801180108 Responds to intervenor 801030 request for documents. Util correspondence w/NRC re const deficiencies available in LPDR in San Antonio, TX. Certificate of Svc encl.
HUDBON, T B Baker & Botts 80/11/06 4pp 06987:184

801180041 Forwards proposed suppl to statement of issues agreed upon between applicant & NRC
BORDENICK, B M Hearing Branch 3 80/11/14 3pp 06987.176

801190185 Response requesting extension until 801208 to substantively respond to Citizens Concerned About Nuclear Power requests for info. States desire to provide info despite intervenor noncompliance w/provisions. Certificate of Svc encl
BORDENICK, B. M. Hearing Branch 3 80/11/17 4pp 06998 243.

8011250588 Notice of withdrawal from proceeding effective 801119. Certificate of Svc encl
SINKIN, B A Citizens Concerned About Nuclear Power, Inc. 80/11/18. 2pp. 07069.004.

DOCKETED ITEMS

K Utility Final Safety Analysis Report (FSAR) & amends

801190305 Forwards Amend 13 to FSAR
OPREA, G W Houston Lighting & Power Co 80/11/17 6pp 06997 018

--801190308 Amend 13 to FSAR
* Houston Lighting & Power Co 80/11/17 130pp 06997 024

M Antitrust correspondence

8011060467 Forwards motion for clarification of ASLB 801024 order re Public Util Board of Brownsville, TX obligation to file summaries of testimony Parties wishing to respond to motion should submit pleadings by 801104
BOUKNIGHT, J A Lowenstein, Neuman, Reis, Axelrad & Toll 80/11/05 2pp 06911 330

--8011060469 Motion requesting clarification of ASLB 801024 decision by directing Public Util Board of Brownsville, TX to file summaries of testimony
BOUKNIGHT, J A Houston Lighting & Power Co BOUKNIGHT, J A Lowenstein, Neuman, Reis, Axelrad & Toll 80/11/05 8pp 06911.332

801100396 Responds to util 801105 motion for clarification of ASLB 801024 order & ltr to ASLB Disagrees w/util understanding of order & intends to provide witness summaries indicated
FOIRIER, M R Spiegel & McDiarnid 80/11/06 2pp 06928 068

801140514 Order denying Houston Lighting & Power 801105 motion for clarification of ASLB 801024 order. Procedural matters suspended until determination of necessity of evidentiary hearing made by ASLB
MILLER, M E Atomic Safety and Licensing Board Panel 80/11/10 3pp. 06963 114

801190202 Request for documents directed to NRC re meetings w/Houston Lighting & Power & Brown & Root on issue of inadequate mgt
EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/11/11. 1p 06998 277

801140542 Comments in opposition to settlement proposing license conditions Combination suggested makes cost prohibitive due to imposition of addl burden in violation of Sherman Act Certificate of Svc encl
SPIEGEL, G, LANDSMAN, R M Brownsville, TX SPIEGEL, G Spiegel & McDiarnid 80/11/12 7dpp 06962 002

8011260007 Confirms 801120 telcon granting extension until 801203 to file reply briefs Ltr is in lieu of formal motion
CHANANHA, F D Antitrust Division 80/11/20 1p 07075 289.

Q Inspection reports, IE Bulletins & correspondence

801100172 Forwards IE Insp Repts 50-498/80-23 & 50-499/80-23 on 800801-31 No noncompliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/19 2pp 06930 329

--801100184 IE Insp Repts 50-498/80-23 & 50-499/80-23 on 800801-31. No noncompliance noted Major areas inspected independent insp during site tours, followup insp re noncompliances, unresolved matters & show cause order items
PHILLIPS, H S, CROSSMAN, W A Region 4, Dallas, Office of the Director 80/09/12 3pp 06930 331

801100109 Forwards IE Insp Repts 50-498/80-18 & 50-499/80-18 on 800723-26 & notice of violation
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/09/19 2pp 06930 312

--801100118 Notice of violation from insp on 800723-26
* Region 4, Dallas, Office of the Director 80/09/16 3pp. 06930 314

--801100157 IE Insp Repts 50-498/80-18 & 50-499/80-18 on 800723-26 Noncompliance noted Quality Const Procedure AQ40 KPCCP-3 did not provide methods for assuring traceability of field installed items to documentation
PHILLIPS, H S, CROSSMAN, W A Region 4, Dallas, Office of the Director 80/09/16 12pp 06930 317

8011200063 Forwards IE Insp Repts 50-498/80-14 & 50-499/80-14 on 800605-06, 18-20 & 24-26 No noncompliance noted
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/10/09. 2pp 07020.273

--8011200096 IE Insp Repts 50-498/80-14 & 50-499/80-14 on 800605-06, 18-20 & 24-26 No noncompliance noted Major areas inspected Allegations that some Brown & Root subcontract surveillance records were falsified
HERR, R K, DRISKILL, D D Region 4, Dallas, Office of the Director
CROSSMAN, W A Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/24 14pp 07020 275

8011060761 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/10 1p 06907 068

8011030535 Requests that encl preservice insp & testing requirements to ensure snubber operability be included in licensing process & be implemented at facility
TEDESCO, R L Assistant Director for Licensing 80/10/17 4pp 06873 006

8011260195 Forwards IE Investigation Repts 50-498/80-22 & 50-499/80-22 No noncompliance noted
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/10/17 2pp 07071 341

--8011260197 IE Investigation Repts 50-498/80-22 & 50-499/80-22 on 800729 Major areas inspected allegations re competency of piping sys designers, supervisors & contractors Allegations unsubstantiated
DRISKILL, D D, SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/10 6pp 07071.343

8011280208 Forwards IE Investigation Repts 50-498/80-29 & 50-499/80-29 on 800924 No noncompliance noted
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/17 1p 07083 015

--8011280212 IE Investigation Repts 50-498/80-29 & 50-499/80-29 on 800924. No noncompliance noted Major areas inspected, allegation that contractor allows drug use by employees, thus affecting quality of work at site
DRISKILL, D D, DIOALOMA, T L, SEYFRIT, K V, Region 4, Dallas, Office of the Director 80/10/17 4pp. 07083 016

8011030598 Responds to IE Insp Repts 50-498/80-18 & 50-499/80-19 re failure to develop appropriate procedures to assure traceability of embed matl & failure to respond to B&R audits Compliance will be affected 801130
OPREA, G W Houston Lighting & Power Co 80/10/23 5pp 06855 076.

801130037 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/24 1p 06938 131

801170031 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2." No written response required.
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/10/27 1p 06981-304

801170611 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/10/31. 1p 06976-348.

8011210753 Ack receipt of 801023 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/80-18 & 50-499/80-18
SEIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/11/12. 1p 07029 118.

--8011210763 Responds to NRC 800919 ltr re violations noted in IE Insp Repts 50-498/80-18 & 50-499/80-18 Corrective actions, QC inspectors now required to verify embeds that are Category I prior to concrete placement
OPREA, G W Houston Lighting & Power Co. 80/10/23 5pp. 07029.119

B Reportable occurrences, LERs & related correspondence

801120637 Second interim deficiency rept re nonconforming backfill matl located around power block Next rept will be submitted by 801205
OPREA, G W Houston Lighting & Power Co. 80/09/23 3pp 06950-319.

801190630 Second interim deficiency rept re min/max soil density tests on essential cooling water backfill reported on 800620 Effort to correct nonconformance still in progress Next rept will be submitted by 801217
OPREA, O W Houston Lighting & Power Co 80/09/23 3pp 07001 224

8011030583 Interim deficiency rept re beam to column connection design in reactor containment bldg On 781025, certain loads, load combinations, stresses & design inputs improperly applied in structural steel framing design Reanalysis is continued
OPREA, O W Houston Lighting & Power Co 80/10/24 6pp 06855 065

801120341 Interim deficiency rept re breakdown in quality program for procurement cycle of purchased mats & equipment Activities associated w/investigative review detailed & vendor control program verified
OPREA, O W Houston Lighting & Power Co 80/10/31 16pp 06951 354

801120362 Fourth interim deficiency rept re matl control of ASTM-A325 structural steel bolts, initially reported on 800617 Util has experienced delays in obtaining documentation for installed bolts Next rept will be provided by 801222
OPREA, O W Houston Lighting & Power Co 80/11/05 4pp 06952 027

801180622 Interim deficiency rept re reactor cavity ventilation design, initially reported on 801017 Alternatives are being evaluated, including redesign of reactor cavity seal plate Next rept will be forwarded by 801227
OPREA, O W Houston Lighting & Power Co 80/11/11 6pp 06991.240

T. Hearing transcripts on non-antitrust matters

8011260188 Transcript of 801119 hearing in Houston, TX Pp 197-347
* Atomic Safety and Licensing Board Panel 80/11/19 190pp.
07069 012

DOCKE1 BTH-50-499 SOUTH TEXAS PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011030535 Requests that encl preservice insp & testing requirements to ensure snubber operability be included in licensing process & be implemented at facility
TEDESCO, R L Assistant Director for Licensing 80/10/17 4pp 06873 006.

8011040603 Confirms discussion w/DG Barker re addl auxiliary feedwater sys safety-related welding. Concurs w/util 801017 plan to re-examine & repair welding NRC must review field welding involving greater than 3/4-inch thickness.
BEYFRIT, K V Region 4, Dallas, Office of the Director. 80/10/22 2pp 06875.161

801120587 Requests branch review of Util 800228 request for clarification of NRC request to delete emergency boration sys Util presently plans other use of space designated for emergency boration sys Early resolution desired.
SCHWENGER, A Licensing Branch 2 80/10/30 2pp 06953 339.

8011040173 Forwards response to NRC 800924 request for revised QA program description & response to specific questions
OPREA, O W Houston Lighting & Power Co. 80/10/31 4pp. 06877 016

--8011040178 QA program during design & const
* Houston Lighting & Power Co 80/10/31 36pp. 06877.020.

--8011040183 QA program during design & const.
* Brown & Root Corp (subs of Halliburton Corp.). 80/10/31. 91pp. 06877.057

--8011040188 Responds to public meeting 800819 request for util analysis & response to Bechtel recommendations Specific responses encl
OPREA, O W Houston Lighting & Power Co 80/09/24 7pp 06877 148

8011060562 Informs that licensee in process of having vendors/suppliers contacted to obtain requested info re environ qualification tests on safety-related equipment, per 801023 request Info will be submitted by 801029
BARKER, D O Houston Lighting & Power Co 80/10/31 2pp 06912 255

801120348 Updates 801002 request for restart of limited complex safety-related concrete activities Current projected placement dates for previously identified placements encl
OPREA, O W Houston Lighting & Power Co 80/11/03 5pp 06952 014

8011200951 Notifies that util 801031 revised QA program for installation, insp & testing of structural concrete is satisfactory for const of facilities
TEDESCO, R L Assistant Director for Licensing 80/11/04 2pp 07018 200

801190466 Notification of 801118 meeting w/util & Brown & Root Corp in Houston, TX to discuss status of engineering design
SEL, B D Licensing Branch 2 80/11/12 3pp 06996 197

O Adjudicatory correspondence

8011040510 Requests names of inspectors who supplied info re harassment at facility & names of employees responsible for harassment & intimidation Related correspondence
MILLER, B A Citizens Concerned About Nuclear Power, Inc 80/10/28 1p. 06873 136

8011040530 Submits change of address & lists individuals authorized to speak in intervention process
EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/10/28 1p 06873 113

8011050489 Requests name of company hired for testing backfill for stability & relationship to util, Brown & Root or any other facility affiliates
EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/10/29 1p. 06899 095

8011060234 Requests V Stello closed door statement re order to show cause Related correspondence
EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/10/29 1p 06911 195

8011050440 Requests const deficiency repts missing from files Related correspondence
EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/10/30 1p 06899 036

801180108 Responds to intervenor 801030 request for documents Util correspondence w/NRC re const deficiencies available in LPDR in San Antonio, TX Certificate of Svc encl
HUOBON, T B Baker & Botts 80/11/06 4pp 06987 184

801180041 Forwards proposed suppl to statement of issues agreed upon between applicant & NRC
BORDENICK, B M Hearing Branch 3 80/11/14 3pp 06987 176

801190185 Response requesting extension until 801208 to substantively respond to Citizens Concerned About Nuclear Power requests for info States desire to provide info despite intervenor noncompliance w/provisions Certificate of Svc encl
BORDENICK, B M Hearing Branch 3 80/11/17 4pp 06998 243

8011250988 Notice of withdrawal from proceeding effective 801117 Certificate of Svc encl
SINKIN, B A Citizens Concerned About Nuclear Power, Inc 80/11/18 2pp 07069 004

K Utility Final Safety Analysis Report (FSAR) & amends

801190305 Forwards Amend 13 to FSAR
OPREA, O W Houston Lighting & Power Co 80/11/17 6pp 06997 018.

--801190308 Amend 13 to FSAR
* Houston Lighting & Power Co 80/11/17 130pp 06997 024

DOCKETED ITEMS

M Antitrust correspondence

8011060457 Forwards motion for clarification of ASLB 801024 order re Public Util Board of Brownsville, TX obligation to file summaries of testimony Parties wishing to respond to motion should submit pleadings by 801106
 BOUKNIGHT, J A Lowenstein, Neuman, Reis, Axelrad & Toll 80/11/05 2pp. 06911 330

--8011060469 Motion requesting clarification of ASLB 801024 decision by directing Public Util Board of Brownsville, TX to file summaries of testimony
 BOUKNIGHT, J A Houston Lighting & Power Co BOUKNIGHT, J A Lowenstein, Neuman, Reis, Axelrad & Toll 80/11/05 8pp 06911 332

8011100396 Responds to util 801105 motion for clarification of ASLB 801024 order & ltr to ASLB Disagrees w/util understanding of order & intends to provide witness summaries indicated
 RIRIER, M R Spiegel & McDiarmid 80/11/06 2pp

8011140514 Order denying Houston Lighting & Power 801105 motion for clarification of ASLB 801024 order Procedural matters suspended until determination of necessity of evidentiary hearing made by ASLB
 MILLER, M E Atomic Safety and Licensing Board Panel 80/11/10. 3pp

8011190202 Request for documents directed to NRC re meetings w/Houston Lighting & Power & Brown & Root on issue of inadequate mgt
 EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/11/11. 1p 06998 277

8011140542 Comments in opposition to settlement proposing license conditions Combination suggested makes cost prohibitive due to imposition of addl burden in violation of Sherman Act Certificate of Bvc encl
 SPIEGEL, O Brownsville, TX LANDSHAW, R M Spiegel & McDiarmid 80/11/12 98pp

8011260007 Confirms 801120 telcon granting extension until 801203 to file reply briefs Ltr is in lieu of formal motion
 CHANANIA, F D Antitrust Division 80/11/20 1p.

Q Inspection reports, IE Bulletins & correspondence

8011100172 Forwards IE Insp Repts 50-498/80-23 & 50-499/80-23 on 800801-31 No noncompliance noted
 SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/15 2pp 06930 329

--8011100185 IE Insp Repts 50-498/80-23 & 50-499/80-23 on 800801-31 No noncompliance noted Major areas inspected independent insp during site tours, followup insp re noncompliances, unresolved matters & show cause order items
 PHILLIPS, H S, CROSSMAN, W A Region 4, Dallas, Office of the Director 80/09/12 3pp 06930 331

8011100109 Forwards IE Insp Repts 50-498/80-18 & 50-499/80-18 on 800723-26 & notice of violation
 SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/19 2pp 06930 312

--8011100118 Notice of violation from insp on 800723-26
 * Region 4, Dallas, Office of the Director 80/09/16 3pp 06930 314

--8011100157 IE Insp Repts 50-498/80-18 & 50-499/80-18 on 800723-26. Noncompliance noted Quality Const Procedure A040 KPCCP-3 did not provide methods for assuring traceability of field installed items to documentation
 PHILLIPS, H S, CROSSMAN, W A Region 4, Dallas, Office of the Director 80/09/16 12pp 06930 317

8011200063 Forwards IE Insp Repts 50-498/80-14 & 50-499/80-14 on 800605-06 18-20 & 24-26 No noncompliance noted
 SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/09 2pp 07020-273

--8011200096 IE Insp Repts 50-498/80-14 & 50-499/80-14 on 800605-06. 18-20 & 24-26 No noncompliance noted Major areas inspected: allegations that some Brown & Root subcontract surveillance records were falsified
 HEFAR, R K, DRISKILL, D D Region 4, Dallas, Office of the Director. CROSSMAN, W A Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/24 14pp 07020 275

8011060761 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting" No written response required
 SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/10. 1p. 06909 068

8011030535 Requests that encl preservice insp & testing requirements to ensure snubber operability be included in licensing process & be implemented at facility
 TEDESCO, R L Assistant Director for Licensing 80/10/17 4pp

8011260193 Forwards IE Investigation Repts 50-498/80-22 & 50-499/80-22. No noncompliance noted
 SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/17. 2pp 07071 341

--8011260197 IE Investigation Repts 50-498/80-22 & 50-499/80-22 on 800729 Major areas inspected allegations re competency of piping sys designers, supervisors & contractors. Allegations unsubstantiated
 DRISKILL, D D, SEYFRIT, K V Region 4, Dallas, Office of the Director 80/10/10 6pp 07071 343

8011280208 Forwards IE Investigation Repts 50-498/80-29 & 50-499/80-29 on 800924 No noncompliance noted.
 SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/10/17 1p. 07083-015

--8011280212 IE Investigation Repts 50-498/80-29 & 50-499/80-29 on 800924 No noncompliance noted Major areas inspected allegation that contractor allows drug use by employees, thus affecting quality of work at site.
 DRISKILL, D. D., DIGALONA, T L., SEYFRIT, K. V Region 4, Dallas, Office of the Director 80/10/17 4pp. 07083-016

8011030598 Responds to IE Insp Repts 50-498/80-18 & 50-499/80-19 re failures to develop appropriate procedures to assure traceability of embed matl & failure to respond to B&R audits. Compliance will be effected 801130
 OPREA, O W Houston Lighting & Power Co. 80/10/23. 5pp 06855.076.

8011130037 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." No written response required
 SEYFRIT, K V. Region 4, Dallas, Office of the Director 80/10/24. 1p. 06958 151.

8011170031 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2" No written response required
 SEYFRIT, K V. Region 4, Dallas, Office of the Director 80/10/27. 1p 06981-304

8011170611 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators" No written response required
 SEYFRIT, K V. Region 4, Dallas, Office of the Director. 80/10/31 1p. 06976 345.

8011210733 Ack receipt of 801023 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/80-18 & 50-499/80-18
 SEIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/12 1p. 07029 118.

--8011210763 Responds to NRC 800919 ltr re violations noted in IE Insp Repts 50-498/80-18 & 50-499/80-18 Corrective actions QC inspectors now required to verify embeds that are Category I prior to concrete placement
 OPREA, O W Houston Lighting & Power Co 80/10/23. 3pp. 07029 119

S Reportable occurrences, LERs & related correspondence

801120637 Second interim deficiency rept re nonconforming backfill matl located around power block Next rept will be submitted by 801205.
 OPREA, O W Houston Lighting & Power Co. 80/09/23 3pp. 06950.319.

8011190630 Second interim deficiency rept re min/max soil density tests on essential cooling water backfill reported on 800620 Effort to correct noncompliance still in progress. Next rept will be submitted by 801217.
 OPREA, O W Houston Lighting & Power Co 80/09/23. 3pp. 07001.224.

8011030583 Interim deficiency rept re beam to column connection design in reactor containment bldg. On 781025, certain loads, load combinations, stresses & design inputs improperly applied in structural steel framing design. Reanalysis is continued
 OPREA, O W Houston Lighting & Power Co 80/10/24. 6pp. 06855-065.

801120341 Interim deficiency rept re breakdown in quality program for procurement cycle of purchased matls & equipment. Activities associated w/investigative review detailed & vendor control program verified.
 OPREA, O W Houston Lighting & Power Co. 80/10/31. 16pp 06951-354.

DOCKETED ITEMS

801120362 Fourth interim deficiency rept re matl control of ASTM-A325 structural steel bolts, initially reported on 800617 Util has experienced delays in obtaining documentation for installed bolts. Next rept will be provided by 810122.
OPREA, G W Houston Lighting & Power Co 80/11/05 4pp. 06952 027

801120522 Interim deficiency rept re reactor cavity ventilation design, initially reported on 801017 Alternatives are being evaluated, including redesign of reactor cavity seal plate. Next rept will be forwarded by 810127.
OPREA, G W Houston Lighting & Power Co 80/11/11 6pp. 06991-240

T Hearing transcripts on non-antitrust matters

801126018B Transcript of 801119 hearing in Houston, TX. Pp 197-347.
* Atomic Safety and Licensing Board Panel 80/11/19. 150pp
07069 012

DOCKET 80-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8011210704 Requests submittal of formal withdrawal of application & info describing current status of onsite activities re LNAs including any plans to redress site. Info should be provided within 30 days.
YOUNGBLOOD, B J Licensing Branch 1 80/11/13 1p. 07032:319

8011210615 Advises of 800124 & 29 ltrs to NRC withdrawing Central Area Power Coordinating Group joint application for OLs. Requests that NRC take prompt action to make withdrawal effective.
CROUSE, R P. Toledo Edison Co 80/11/17 1p 07029:152

G. Adjudicatory correspondence

8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREG-0625, "Rept of Siting Policy Task Force." Documents 6-B & 13 are available in PDR. Forwards remaining documents.
FELTON, J M Division of Rules and Records. 80/09/04 1p.

--8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features.
MINGOUE, R. B. Office of Standards Development, Director
SECY-79-362 79/06/04. 7pp.

--8009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards.
SCINTO, J F. Hearings Division 79/04/04. 16pp

DOCKET 80-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8011210704 Requests submittal of formal withdrawal of application & info describing current status of onsite activities re LNAs including any plans to redress site. Info should be provided within 30 days.
YOUNGBLOOD, B J Licensing Branch 1 80/11/13. 1p. 07032:319

8011210615 Advises of 800124 & 29 ltrs to NRC withdrawing Central Area Power Coordinating Group joint application for OLs. Requests that NRC take prompt action to make withdrawal effective.
CROUSE, R. P. Toledo Edison Co. 80/11/17 1p 07029:152

G. Adjudicatory correspondence

8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREG-0625, "Rept of Siting Policy Task Force." Documents 6-B & 13 are available in PDR. Forwards remaining documents.
FELTON, J. M. Division of Rules and Records. 80/09/04. 1p.

--8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features.
MINGOUE, R. B. Office of Standards Development, Director.
SECY-79-362 79/06/04 7pp.

--8009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards.
SCINTO, J. F. Hearings Division. 79/04/04 16pp.

DOCKET 80N-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OL & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D G Division of Licensing. 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OL & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D G Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl.
EISENHUT, D G Division of Licensing 80/10/06 6pp

8011070444 Informs that info requested in NRC 800731 ltr re environ qualification of safety-related equipment will be submitted by 801201.
RENNBERGER, D L Washington Public Power Supply System 80/11/07. 1p 06919 193

G. Inspection reports, IE Bulletins & correspondence

8011060773 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting." No written response required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 80/10/10 1p 06909:083

801130029 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 80/10/24 1p 06938 078

801200105 Forwards IE Mgt Meeting Repts 80-460/80-12, 80-513/80-12, 80-508/80-11 & 80-509/80-11 on 801009. No noncompliance noted.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 80/10/29 2pp. 07021:001

--801200117 IE Mgt Meeting Repts 80-460/80-12, 80-513/80-12, 80-508/80-11 & 80-509/80-11 on 801009. No noncompliance noted. Major areas discussed enforcement, IE bulletins & insp program.
ENGELKEN, R H, HAYNES, R C, BISHOP, T W Region 5, San Francisco Office of the Director 80/10/29 3pp. 07021 003.

--801200129 Discusses 800905 regional evaluation review board meeting re enforcement, IE bulletins & insp programs. Licensee performance needs improvement in PSAR comments translated into specs & spec codes translated into work procedures.
HAYNES, R. C., BISHOP, T. W., KIRSCH, D F. Region 5, San Francisco, Office of the Director 80/10/03 14pp. 07021.006.

--801200135 Discusses 800905 regional evaluation review board meeting re enforcement, IE bulletins & insp programs. Licensee performance warrants improvement in assuring preparation adequate prior to start of safety-related work.
HAYNES, R. C. Region 5, San Francisco, Reactor Construction & Engineering Support Branch KIRSCH, D F., HAIST, D. P. Region 5, Francisco, Office of the Director 80/10/02 12pp. 07021:020.

801170649 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Bys Emergency Generators." No written response required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 80/10/31. 1p 06976:262.

DOCKET 80N-50-509 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OL & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D. G. Division of Licensing 80/09/05. 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OL & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D. G. Division of Licensing 80/10/01 5pp.

DOCKETED ITEMS

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011070444 Informs that info requested in NRC 800731 ltr re environ qualification of safety-related equipment will be submitted by 801201
RENSBERGER, D L Washington Public Power Supply System 80/11/07 1p

G Inspection reports, IE Bulletins & correspondence

80110607/3 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting" No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/10 1p

801130029 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/24 1p

8011200105 Forwards IE Mgt Meeting Repts 50-460/80-12, 50-513/80-12, 50-508/80-11 & 50-509/80-11 on 801009 No noncompliance noted
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/29 2pp

--8011200117 IE Mgt Meeting Repts 50-460/80-12, 50-513/80-12, 50-508/80-11 & 50-509/80-11 on 801009 No noncompliance noted Major areas discussed: enforcement, IE bulletins & insp program
ENGELKEN, R H, TOTHA, D, HAIST, D P Region 5, San Francisco, Office of the Director 80/10/29 3pp

--8011200129 Discusses 800905 regional evaluation review board meeting re enforcement, IE bulletins & insp programs Licensee performance needs improvement in PSAR commitments translated into specs & spec codes translated into work procedures
HAYNES, R C, TOTHA, D Region 5, San Francisco, Office of the Director 80/10/03 14pp

--8011200135 Discusses 800905 regional evaluation review board meeting re enforcement, IE bulletins & insp programs Licensee performance warrants improvement in assuring preparation adequate prior to start of safety-related work
HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch BISHOP, T W Region 5, San Francisco, Office of the Director 80/10/02 12pp.

8011170649 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators" No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/31 1p

DOCKET 80-513 WPPSS NUCLEAR PROJECT, UNIT 4

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing. 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" W/o encl.
EISENHUT, D O Division of Licensing 80/10/06 6pp.

8011070444 Informs that info requested in NRC 800731 ltr re environ qualification of safety-related equipment will be submitted by 801201
RENSBERGER, D L Washington Public Power Supply System. 80/11/07. 1p.

G Inspection reports, IE Bulletins & correspondence

8011190449 Ack receipt of 800918 ltr informing NRC of addl steps taken to correct violations noted in IE insp on 800429-0502
SPENCER, O S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/10/09 1p 06998 089

--8011190451 Responds to NRC 800904 ltr re violations noted in IE insp Identified condition is isolated case & not basis for generic concern.
RENSBERGER, D L Washington Public Power Supply System 80/09/18. 3pp 06998 090

--8011190453 Ack receipt of 800813 ltr informing NRC of steps taken to correct violations noted in IE insp on 800429-0502 Addl info required
SPENCER, O S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/09/04 1p. 06998 093

--8011190455 Responds to NRC 800711 ltr re violations noted in IE insp Corrective actions training sessions held to reiterate requirements for performance of addl work on hangers & issuance of proper documentation
FERGUSON, R L Washington Public Power Supply System. 80/08/13. 8pp 06998 094

80110607/3 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting" No written response required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/10 1p

801130029 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/24 1p

8011200105 Forwards IE Mgt Meeting Repts 50-460/80-12, 50-513/80-12, 50-508/80-11 & 50-509/80-11 on 801009 No noncompliance noted
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/29 2pp 07021 001

--8011200117 IE Mgt Meeting Repts 50-460/80-12, 50-513/80-12, 50-508/80-11 & 50-509/80-11 on 801009 No noncompliance noted Major areas discussed: enforcement, IE bulletins & insp program.
ENGELKEN, R H, HAYNES, R C, BISHOP, T W Region 5, San Francisco, Office of the Director 80/10/29 3pp 07021 003

--8011200129 Discusses 800905 regional evaluation review board meeting re enforcement, IE bulletins & insp programs Licensee performance needs improvement in PSAR commitments translated into specs & spec codes translated into work procedures
HAYNES, R C, BISHOP, T W, KIRSCH, D F. Region 5, San Francisco, Office of the Director 80/10/03 14pp 07021 006.

--8011200135 Discusses 800905 regional evaluation review board meeting re enforcement, IE bulletins & insp programs Licensee performance warrants improvement in assuring preparation adequate prior to start of safety-related work
HAYNES, R C. Region 5, San Francisco, Reactor Construction & Engineering Support Branch KIRSCH, D F, HAIST, D P. Region 5, San Francisco, Office of the Director. 80/10/02 12pp. 07021 020.

8011170649 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/31 1p

DOCKET 80-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D O. Division of Licensing 80/10/01. 5pp.

DOCKETED ITEMS

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D Q Division of Licensing 80/10/06 6pp

Q Adjudicatory correspondence

8011190167 Third status rept per ASLB 800721 order. Proposed findings of fact & conclusions of law will be filed by 801202 Chairman. Ahearns has not responded to applicant 800930 ltr re allocation of NRC resources Certificate of Svc encl
BORDENICK, B M Hearing Branch 3 80/11/17 4pp 06998 204

8011280061 Notice of availability of procedural assistance in adjudicatory licensing proceedings, published in 800725 FR in order to qualify for aid, intervenor must submit statement showing need to ASLB
BOWERS, E S Atomic Safety and Licensing Board Panel 80/11/24 1p 07084 106.

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D Q Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D. Q. Division of Licensing 80/10/01 3pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D. Q. Division of Licensing 80/10/06 6pp

Q Adjudicatory correspondence

8011190167 Third status rept per ASLB 800721 order. Proposed findings of fact & conclusions of law will be filed by 801202 Chairman. Ahearns has not responded to applicant 800930 ltr re allocation of NRC resources Certificate of Svc encl
BORDENICK, B. M. Hearing Branch 3. 80/11/17 4pp 06998 204.

8011280061 Notice of availability of procedural assistance in adjudicatory licensing proceedings, published in 800725 FR in order to qualify for aid, intervenor must submit statement showing need to ASLB.
BOWERS, E S. Atomic Safety and Licensing Board Panel 80/11/24 1p. 07084 106.

DOCKET 50-516 JAMESPORT NUCLEAR STATION, UNIT 1

Q Adjudicatory correspondence

8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREG-0625, "Rept of Siting Policy Task Force." Documents 6-8 & 13 are available in PDR. Forwards remaining documents
FELTON, J M Division of Rules and Records 80/09/04. 1p

--8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features.
MINOQUE, R B Office of Standards Development, Director. SECY-79-362 79/06/04. 7pp.

--8009190630 Requests that encl, "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards
SCINIO, J. F. Hearings Division 79/04/04. 16pp.

Q Inspection reports, IE Bulletins & correspondence

8011060531 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment." IEB 79-01B & suppl dtd 800229, not previously transmitted, also encl. No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/09/30. 1p. 06911:352.

8011060636 Forwards IE Info Notice 80-37, "Containment Cooler Leaks Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/10/24 1p 06909 309

8011070241 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06924 227

8011140147 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06948 231

8011140613 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p 06963 247

DOCKET 50-517 JAMESPORT NUCLEAR STATION, UNIT 2

Q Adjudicatory correspondence

8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREG-0625, "Rept of Siting Policy Task Force." Documents 6-8 & 13 are available in PDR. Forwards remaining documents
FELTON, J M Division of Rules and Records 80/09/04 1p.

--8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features.
MINOQUE, R B Office of Standards Development, Director SECY-79-362 79/06/04 7pp

--8009190630 Requests that encl, "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards
SCINIO, J F Hearings Division 79/04/04 16pp

Q Inspection reports, IE Bulletins & correspondence

8011060531 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " IEB 79-01B & suppl dtd 800229, not previously transmitted, also encl. No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/30 1p 06911 352

8011060636 Forwards IE Info Notice 80-37, "Containment Cooler Leaks Reactor Cavity Flooding At Indian Point Unit 2 " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06909 309

8011070241 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/24 1p 06924 227

8011140147 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/31 1p. 06948 231

8011140613 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/10/31 1p 06963 247

DOCKET 50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D Q Division of Licensing 80/09/05 209pp

DOCKETED ITEMS

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

801070306 Application to amend CPPR-150, CPPR-151, CPPR-152 & CPPR-153, modifying aquatic const effects monitoring program Class III & Class I fees will be forwarded
MILLS, L M Tennessee Valley Authority 80/10/31 2pp 06925 062

0 Inspection reports, IE Bulletins & correspondence

801170687 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24 1p 06976 234

5 Reportable occurrences, LERs & related correspondence

801140096 Third interim deficiency rept originally reported on 800314 re cracks in reactor pressure vessel shield wall Cracks to be repaired after OE approves recommended disposition & repair procedure. Final rept expected by 80101
MILLS, L M Tennessee Valley Authority 80/10/03, 1p 06963 227.

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05, 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp.

801070306 Application to amend CPPR-150, CPPR-151, CPPR-152 & CPPR-153, modifying aquatic const effects monitoring program Class III & Class I fees will be forwarded
MILLS, L M Tennessee Valley Authority 80/10/31 2pp 06925 062.

0 Inspection reports, IE Bulletins & correspondence

801170687 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/10/24, 1p.

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing, 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing, 80/10/01, 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

801070306 Application to amend CPPR-150, CPPR-151, CPPR-152 & CPPR-153, modifying aquatic const effects monitoring program Class III & Class I fees will be forwarded
MILLS, L M Tennessee Valley Authority 80/10/31 2pp 06925 062

0 Inspection reports, IE Bulletins & correspondence

801170687 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24 1p

DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp.

801070306 Application to amend CPPR-150, CPPR-151, CPPR-152 & CPPR-153, modifying aquatic const effects monitoring program, Class III & Class I fees will be forwarded.
MILLS, L M Tennessee Valley Authority 80/10/31 2pp

0 Inspection reports, IE Bulletins & correspondence

801170687 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/10/24 1p

DOCKET STN-50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8010270291 Summarizes recent finding of possible capable fault on Cable Mountain, WA
TUBTUS, P B Geosciences Branch 80/09/02 2pp 03661 200.

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing, 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06, 6pp.

DOCKET STN-90-523 SKAQIT NUCLEAR POWER PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8010270791 Summarizes recent finding of possible capable fault on Cable Mountain, WA
TUBTUB, P B Geosciences Branch, 80/09/02 2pp 03661 200.

8011030354 Ltr to all licensees of operating plants, applicants for QLS & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O Division of Licensing 80/09/03 209pp

801100486 Ltr to all licensees of operating plants & applicants for QLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O, Division of Licensing, 80/10/01 3pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports," W/o encl
EISENHUT, D O, Division of Licensing 80/10/06, 6pp.

DOCKET STN-90-528 PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for QLS & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT, D O, Division of Licensing, 80/09/03, 209pp.

801100486 Ltr to all licensees of operating plants & applicants for QLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT, D O, Division of Licensing 80/10/01, 3pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports," W/o encl
EISENHUT, D O Division of Licensing, 80/10/06, 6pp.

8011060986 Notification of caseload forecast panel 801028-30 meeting w/util in Buckeye, AZ & at site Agenda encl
KERRIQAN, J, Licensing Branch 3, 80/10/17, 6pp 06914 156.

8011190389 Notification of 801105 meeting w/util in Bethesda, MD to discuss guidelines & schedule for addl independent design review meetings.
KERRIQAN, J Licensing Branch 3, 80/11/04 3pp 06996 194.

8011200350 Summary of 801028-30 meeting w/util in Buckeye, AZ to discuss facility const status, Meeting agenda & attendee list encl.
KERRIQAN, J Licensing Branch 3, 80/11/06 7pp 07019 010.

8011180448 Requests review of RETRAN computer code developed under sponsorship of EPRI. Util will use RETRAN for analysis of reactor transients Development of RETRAN capability scheduled to begin in early 1981
WOODS, T O, Arizona Public Service Co, 80/11/10 1p 06988 165.

G. Adjudicatory correspondence

8011140563 Urges submittal of contentions in compliance w/ASLB 801023 order. Addl copy of order will be provided.
MCGURREN, H J Hearing Branch 3 80/11/12 1p, 06963 218.

8011230019 Notifies of agreement reached between L Hourihan, NRC & applicants re schedule for filing contentions & responses Agreement orally adopted by ASLB on 801112. Contentions will be filed by 801121 & responses by 801209
MCGURREN, H J, Hearing Branch 1, 80/11/19, 2pp 07056 187.

G Inspection reports, IE Bulletins & correspondence

8010240079 Responds to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " No suby relays used in reactor protective sys at facilities
VAN BRUNT, E E Arizona Public Service Co 80/09/02 1p 06795 156.

8011060758 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No written response required
ENGELKFF, R H Region 5, San Francisco, Office of the Director 80/10/10 1p 06909 058

8011030356 Forwards IE Insp Repts 80-528/80-14, 80-529/80-14 & 80-530/80-14 on 800804-29 No noncompliance noted
SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/10/15 2pp 06899 307

--8011030360 IE Insp Rept 80-528/80-14, 80-529/80-14 & 80-530/80-14 on 800804-29, No noncompliance noted Major areas inspected storage units, piping & equipment preservation
VORDERBRUEGGEN Region 5, San Francisco, Office of the Director
HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/10/15 3pp 06899 307.

801130024 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
ENGELKFF, R H Region 5, San Francisco, Office of the Director 80/10/24 1p 06958 074

8011170628 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
ENGELKFF, R H Region 5, San Francisco, Office of the Director 80/10/31 1p 06977 276

B Reportable occurrences, LERs & related correspondence

801120373 Final deficiency rept re Borg-Warner motor-operated gate valve failure to close under operating conditions Caused by inadequate guiding of valve gate Valves will be reworked by 80101 Unit 3 valve design change planned
VAN BRUNT, E E Arizona Public Service Co 80/10/31, 9pp, 06953 082

801120477 Final deficiency rept re potential motor shaft breakage in six Comp, Inc hydrogen monitors Necessary action being taken to have equipment reworked per supplier recommendation prior to sys startup
VAN BRUNT, E E Arizona Public Service Co 80/10/31 3pp 06953 097.

8011170570 Final rept of deficiency re possible inadvertent defeat of mechanical interlock device on battery charger cabinet which could close both breakers Power Conversion Products provided design fix which will be incorporated prior to startup
VAN BRUNT, E E Arizona Public Service Co 80/11/05 3pp 06977 308

8011170577 Final deficiency rept re cable splice on non-Class IE single conductor, 350 KCMIL, 600 volt power cable from Rockbestos Reel A-47B Actions implemented to assure that only qualified Rockbestos power cable utilized for Class IE circuits
VAN BRUNT, E E Arizona Public Service Co 80/11/05, 3pp 06977 294

8011170575 Final deficiency rept re reinforcing steel shown in Drawings 13-C-2GS-108 & 115 not accurately reflecting actual design. Analysis of containment initiated & results show shell-basemat within allowable stress limits
VAN BRUNT, E E Arizona Public Service Co 80/11/06, 9pp 06977 299

T. Hearing transcripts on non-antitrust matters

8010270462 Forwards transcript of 800821 & 22 sys review in Phoenix, AZ re facility auxiliary feedwater sys.
VAN BRUNT, E E Arizona Public Service Co 80/10/17, 1p.

--8010270468 Transcript of Auxiliary Feedwater Sys Review Board 800821 & 22 review in Phoenix, AZ re facility auxiliary feedwater sys Vol 1 of 11, Pp 1-181
* Arizona Public Service Co, 80/08/22, 187pp.

DOCKETED ITEMS

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D Q Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D Q Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D Q Division of Licensing 80/10/06 6pp

8011060586 Notification of caseload forecast panel 801028-30 meeting w/util in Buckeye, AZ & at site Agenda encl
KERRIGAN, J Licensing Branch 3 80/10/17 6pp 06914 156

801190389 Notification of 801105 meeting w/util in Bethesda, MD to discuss guidelines & schedule for addl independent design review meetings
KERRIGAN, J Licensing Branch 3 80/11/04 3pp 06996 194

8011200350 Summary of 801028-30 meeting w/util in Buckeye, AZ to discuss facility const status Meeting agenda & attendee list encl
KERRIGAN, J Licensing Branch 3 80/11/06 7pp 07019 010

801180448 Requests review of RETRAN computer code developed under sponsorship of EPRI Util will use RETRAN for analysis of reactor transients Development of RETRAN capability scheduled to begin in early 1981
WOODS, T Q Arizona Public Service Co 80/11/10 1p 06988 165.

G Adjudicatory correspondence

801140563 Urges submittal of contentions in compliance w/ASLB 801023 order Addl copy of order will be provided
MCQUINN, H J Hearing Branch 3 80/11/12 1p 06963 218

8011250019 Notices of agreement reached between L Hourihan, NRC & applicants re schedule for filing contentions & responses Agreement orally adopted by ASLB on 801113 Contentions will be filed by 801121 & responses by 801209
MCQUINN, H J Hearing Branch 1 80/11/19 2pp 07056 187

G Inspection reports, IE Bulletins & correspondence

8010240079 Responds to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " No subj relays used in reactor protective sys at facilities
VAN BRUNT, E E Arizona Public Service Co 80/09/02 1p 06795 156

8011060758 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No written response required
ENDELKEN, R H Region 3, San Francisco, Office of the Director 80/10/10 1p 06909 058

8011050356 Forwards IE Insp Repts 50-528/80-14, 50-529/80-14 & 50-530/80-14 on 800804-29 No noncompliance noted
SPENCER, O S Region 3, San Francisco, Reactor Construction & Engineering Support Branch 80/10/15 2pp 06899 307.

--8011050360 IE Insp Rept 50-528/80-14, 50-529/80-14 & 50-530/80-14 on 800804-29 No noncompliance noted Major areas inspected storage units, piping & equipment preservation
VORDERBRUGGEN, Region 3, San Francisco, Office of the Director HAYNES, R C Region 3, San Francisco, Reactor Construction & Engineering Support Branch 80/10/15 3pp 06899 309

801133024 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required
ENDELKEN, R H Region 3, San Francisco, Office of the Director, 80/10/24 1p 06958 074

801170628 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
ENDELKEN, R H Region 3, San Francisco, Office of the Director 80/10/31 1p 06977 276

S Reportable occurrences, LERs & related correspondence

801120373 Final deficiency rept re Borg-Warner motor-operated gate valve failure to close under operating conditions Caused by inadequate guiding of valve gate Valves will be reworked by 80101 Unit 3 valve design change planned
VAN BRUNT, E E Arizona Public Service Co 80/10/31 9pp 06953 082

801120477 Final deficiency rept re potential motor shaft breakage in six Consip, Inc hydrogen monitors Necessary action being taken to have equipment reworked per supplier recommendation, prior to sys startup
VAN BRUNT, E E Arizona Public Service Co 80/10/31 3pp 06953 097

801170575 Final deficiency rept re reinforcing steel shown in Drawings 13-C-ZCS-108 & 115 not accurately reflecting actual design Analysis of containment initiated & results show shell-basemat within allowable stress limits
VAN BRUNT, E E Arizona Public Service Co 80/11/06 9pp 06977 299

T Hearing transcripts on non-antitrust matters

8010270462 Forwards transcript of 800821 & 22 sys review in Phoenix, AZ re facility auxiliary feedwater sys
VAN BRUNT, E E Arizona Public Service Co 80/10/17 1p.

--8010270468 Transcript of Auxiliary Feedwater Sys Review Board 800821 & 22 review in Phoenix, AZ re facility auxiliary feedwater sys Vol 1 of 11 Pp 1-181
* Arizona Public Service Co 80/08/22 187pp

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D Q Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D Q Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT, D Q Division of Licensing 80/10/06 6pp

8011060586 Notification of caseload forecast panel 801028-30 meeting w/util in Buckeye, AZ & at site Agenda encl
KERRIGAN, J Licensing Branch 3 80/10/17 6pp 06914, 156.

801190389 Notification of 801105 meeting w/util in Bethesda, MD to discuss guidelines & schedule for addl independent design review meetings
KERRIGAN, J Licensing Branch 3 80/11/04 3pp 06996 194

8011200350 Summary of 801028-30 meeting w/util in Buckeye, AZ to discuss facility const status Meeting agenda & attendee list encl
KERRIGAN, J Licensing Branch 3 80/11/06 7pp 07019 010

801180448 Requests review of RETRAN computer code developed under sponsorship of EPRI Util will use RETRAN for analysis of reactor transients Development of RETRAN capability scheduled to begin in early 1981.
WOODS, T. Q. Arizona Public Service Co 80/11/10, 1p 06988:165

G Adjudicatory correspondence

801140563 Urges submittal of contentions in compliance w/ASLB 801023 order Addl copy of order will be provided
MCQUINN, H J Hearing Branch 3 80/11/12 1p 06963, 218

DOCKETED ITEMS

249

8011250019 Notifies of agreement reached between L. Hourihan, NRC & applicants re schedule for filing contentions & responses. Agreement orally adopted by ASLB on 801113. Contentions will be filed by 801121 & responses by 801209.
MCOURREN, H J Hearing Branch 1 80/11/19 2pp 07056 187

G. Inspection reports, IE Bulletins & correspondence

8010240079 Responds to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E." No subj relays used in reactor protective sys at facilities.
VAN BRUNT, E E Arizona Public Service Co 80/09/02 1p 06795:156

8011060758 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting." No written response required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/10 1p 06909 058

8011050356 Forwards IE Insp Repts 80-528/80-14, 80-529/80-14 & 80-530/80-14 on 800804-29 No noncompliance noted.
SPENCER, O S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/10/13 2pp 06899:307

--8011050360 IE Insp Rept 80-528/80-14, 80-529/80-14 & 80-530/80-14 on 800804-29 No noncompliance noted. Major areas inspected: storage units, piping & equipment preservation.
VORDERBRUEGGEN, Region 5, San Francisco, Office of the Director
HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/10/13 3pp 06899 307

8011130024 Forwards Suppl 3 to IE Bulletin 79-018, "Environment Qualification of Class IE Equipment." No written response required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/24 1p 06958 074

8011170628 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/31 1p 06977:276

S. Reportable occurrences, LERs & related correspondence

8011120477 Final deficiency rept re potential motor shaft breakage in six Consip, Inc hydrogen monitors. Necessary action being taken to have equipment reworked per supplier recommendation prior to sys startup.
VAN BRUNT, E E Arizona Public Service Co 80/10/31 5pp 06953 097

8011170575 Final deficiency rept re reinforcing steel shown in Drawings 13-C-208-10B & 11S not accurately reflecting actual design. Analysis of containment initiated & results show shell-basemat within allowable stress limits.
VAN BRUNT, E E Arizona Public Service Co 80/11/06 9pp 06977:299

T. Hearing transcripts on non-antitrust matters

8010270462 Forwards transcript of 800821 & 22 sys review in Phoenix, AZ re facility auxiliary feedwater sys.
VAN BRUNT, E E Arizona Public Service Co 80/10/17 1p

--8010270468 Transcript of Auxiliary Feedwater Sys Review Board 800821 & 22 review in Phoenix, AZ re facility auxiliary feedwater sys. Vol I of II Pp 1-181.
* Arizona Public Service Co 80/08/22 187pp

DOCKET STN-50-533 RINCHALS NUCLEAR POWER STATION, UNIT 4

A. Application/construction stage documents & correspondence

8011200407 Submits application to amend export license extending date from 810301 to Dec 31, 2021 & increasing value of export.
HERSCH, M M Westinghouse Electric Corp 80/10/31 1p 07020 101

DOCKET STN-50-535 CASSAR-6

J. Insurance & indemnity information

8011030430 Forwards Endorsement 113 to NELIA Policy NF-34.
CORREA, M A Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div. 80/10/28 2pp 06855 094

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

B. Utility Preliminary Safety Analysis Report, amends

8011070416 Forwards Amend 57 to PSAR.
COPELAND, R L Energy, Dept of, Clinch River Breeder Reactor Plant 80/11/07 4pp 06918 271

--8011070417 Amend 57 to PSAR.
* Energy, Dept of, Clinch River Breeder Reactor Plant 80/11/07 200pp 06918 275

8011180630 Forwards affidavit confirming distribution of Amend 57 to PSAR to designated local public officials & representatives of EPA.
COPELAND, R L Energy, Dept of, Clinch River Breeder Reactor Plant 80/11/13 2pp 06991 246

8011280047 Forwards Amend 58 to PSAR.
COPELAND, R L Energy, Dept of, Clinch River Breeder Reactor Plant 80/11/26 1p 07084 194

--8011280048 Amend 58 to PSAR.
* Energy, Dept of, Clinch River Breeder Reactor Plant 80/11/26 350pp 07084 202

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D O Division of Licensing 80/09/05 209pp

8011200257 Forwards request for addl info re safety-related concrete areas, critical biological shielding locations & concrete repair work. Verbal exchange may be more convenient.
FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/29 2pp 07020 003

--8011200261 Submits list of info previously requested & requests addl info as result of meetings w/other consultants.
HAMM, R C, PARME, A L Hamm Engineers, Inc 80/09/05 3pp 07020 005

--8011200264 Forwards request for addl info re nondestructive testing supplementing 800903 request.
HAMM, R C, PARME, A L Hamm Engineers, Inc 80/09/10 3pp 07020 008

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101.
EISENHUT, D O Division of Licensing 80/10/01 3pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl.
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011200011 Responds to NRC 800515 ltr re graduated rescission of 790815 order. Items identified in app which are prerequisite to const resumption completed. Upon NRC review Items B 7, C 3, D 3, E 1 & E 3, util will request order be lifted.
SHIELDS, B W Public Service Co of Indiana, Inc 80/10/30 2pp 07015:354

8011200052 Ack receipt of 801001 ltr requesting voluntary submittal of info re environ qualification of safety-related equipment. Response will be submitted by 810101.
SHIELDS, B W Public Service Co of Indiana, Inc 80/10/31 1p 07020 268

8011210741 Ack receipt of 801107 ltr requesting further partial rescission of 790815 order. Authorizes firms to commence receipt insp in contracted disciplines.
STELLER, V Office of Inspection & Enforcement, Office of the Director. 80/11/13 5pp 07027:106

DOCKETED ITEMS

--8011210754 Ack receipt of 800515 ltr re 790815 graduated rescission of order Specific activities accomplished adjustment of QA programs & comprehensive audits Requests NRC perform evaluations of adjusted receipt insp programs
SHIELDS, S W Public Service Co of Indiana, Inc 80/11/07 2pp
07029 111

--8011210759 Informs that Region 3 has concluded that vendors can carry out receipt insp properly Recommends resumption of activities Draft ltr authorizing activity encl
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/07 2pp 07029 113

8011250413 Forwards Revision 1 to SL-3753, "Evaluation of In-Place Concrete " W/o encl
SHIELDS, S W Public Service Co of Indiana, Inc 80/11/17 1p
07036 097

H General correspondence

801140335 Requests carbon copies of correspondence be sent to
WM Petro
SHIELDS, S W Public Service Co of Indiana, Inc. 80/11/07 1p
06962 341

G Inspection reports, IE Bulletins & correspondence

8011260372 Forwards IE Insp Repts 50-546/80-33 & 50-547/80-33 on 800910-12 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/23 2pp 07072 304

--8011260378 IE Insp Repts 50-546/80-33 & 50-547/80-33 on 800910-12 No noncompliance noted Major areas inspected unresolved items from previous insp. GA, GC & work procedures involving receipt storage handling
NEIBLER, J H, WILLIAMS, C C Region 3, Chicago, Office of the Director 80/09/22 5pp 07072 306

8011040297 Forwards IE Insp Repts 50-546/80-34 & 50-547/80-34 on 800917-19 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/02 2pp 06884 359

--8011040300 IE Insp Repts 50-546/80-34 & 50-547/80-34 on 800917-19 No noncompliance noted Major areas inspected licensee action re insp of installed Category 1 structural steel implemented per 790815 stop work order
KONKLE, J E, WILLIAMS, C C Region 3, Chicago, Office of the Director 80/09/30 5pp 06885 001

8011040305 Forwards IE Insp Repts 50-546/80-32 & 50-547/80-32 on 800908-10 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/02 2pp 06885 020

--8011040309 IE Insp Repts 50-546/80-32 & 50-547/80-32 on 800908-10 No noncompliance noted Major areas inspected site tour & review of previous insp findings
SCHNEIBINZ, E R, WILLIAMS, C C Region 3, Chicago, Office of the Director 80/10/02 4pp 06885 022

8011200548 Forwards IE Insp Repts 50-546/80-04 & 50-547/80-04 on 800123-30, 0201-08, 0617-30 & 0703-11 & notice of violation
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/15 2pp 01741 019

--8011200550 Notice of violation from insp on 800123-30, 0201-08, 0617-30 & 0703-11
* Region 3, Chicago, Office of the Director 80/09/26 2pp
01741 019

--8011200553 IE Insp Repts 50-546/80-04 & 50-547/80-04 on 800123-30, 0201-08, 0617-30 & 0703-11 Noncompliance noted personnel signing or initialing records for other personnel
FOSTER, J E, HAWKINS, F C, NORELIUS, C E Region 3, Chicago, Office of the Director 80/09/26 40pp 01741-019

--8011200554 Transcript of JE Henry 790620 statement, afternoon session, in Madison, IN Pp 1-53 W/supporting documentation
HENRY, J E United States Testing Co, Inc. 79/06/20 110pp
01741-019

801100047 Forwards IE Insp Repts 50-546/80-35 & 50-547/80-35 on 800922-25 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/17 2pp 06929 034

--801100054 IE Insp Repts 50-546/80-35 & 50-547/80-35 on 800922-25 No noncompliance noted Major areas inspected status of Verification Program SPP-11, review of Verification Programs SPP-4, SPP-B & SPP-12 & review of safety storage
ERB, C H, CORDERO, Z C Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/16 5pp 06929 036

8011250057 Forwards IE Insp Repts 50-546/80-36 & 50-547/80-36 on 801006-09 No noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/21 2pp 07056 224

--8011250062 IE Insp Repts 50-546/80-36 & 50-547/80-36 on 801006-09 No noncompliance noted Major areas inspected Const Verification Program SPP-13, Category 1 concrete constituent mats & embedded metals records review
O'ALLAGHER, E J Region 3, Chicago, Office of the Director, HAYES, D W Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/20 9pp 07056 226

8011070304 Forwards Suppl 3 to IF Bulletin 79-018, "Environment Qualification of Class IE Equipment " No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/24 1p 06921 336

8011170168 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME BA-312, Type 304 Stainless Steel Pipe " Requests extension until 801215 to respond to bulletin
SHIELDS, S W Public Service Co of Indiana, Inc 80/10/31 1p
06982 001

8011260416 Forwards IE Investigation Repts 50-546/79-08 & 50-547/79-08 on 790622, 23-29, 0707, 11-13 & 17-20 No noncompliance noted Notes rept will receive expedited proprietary review
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/10 2pp 07073 001

--8011260424 IE Investigation Repts 50-546/79-08 & 50-547/79-08 on 790622, 23-29, 0707, 11-13 & 17-20 Major areas insp allegations of improper repair of concrete structures & concealment of nonconforming concrete areas
FOSTER, J E, HAWKINS, F C, WILLIAMS, C C Region 3, Chicago, Office of the Director 79/08/09 19pp 07073 003

--8011260429 Statement of 790508 appearance in Madison, IN re const deficiencies Pp 1-23
CUTSHELL, C E Affiliation Unknown 79/05/08 23pp 07073 022

S Reportable occurrences, LERs & related correspondence

8011030683 Ack receipt of 800902 interim deficiency rept re ability of structural contractor QA program to assure that design changes were incorporated into const activities.
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/23 1p 06873 039

--8011030686 Second interim deficiency rept re ability of structural contractor QA program to assure design changes were incorporated into const activities Design change issue is still unresolved Final rept to be submitted by 801101
SHIELDS, S W Public Service Co of Indiana, Inc 80/09/02 1p, 06873 040

8011200250 Ack receipt of 800929 interim deficiency rept re incorrect weld filler used in safety-related pipe spool pieces.
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/17 1p 07020 001

8011030584 Forwards attachments to 801017 fuel deficiency repts re use of concrete expansion anchors to install temporary piping & defective Carbo-Zinc 11 primer coating on polar cranes
SHIELDS, S W Public Service Co of Indiana, Inc. 80/10/27, 11pp, 01756 001

801120049 Ack receipt of 801014 final deficiency rept re Westinghouse Type W-2 switches.
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/27 1p 06953 004

801120417 Ack receipt of 801017 final deficiency rept re documentation packages for Westinghouse supplied mats missing quality records
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/29, 1p 06953 007,

801190303 Ack receipt of 801024 Interim deficiency rept re welds on cable tray hangers
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/31 1p 06916 001

801190726 Ack receipt of 801023 Interim deficiency rept re substitution of certain matls for those allowed by spec for stainless steel liner work
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/31 1p 06916 001

801100398 Forwards schedule indicating when final deficiency repts will be submitted Schedule addresses items reported prior to 800101, for which final rept dates have not been previously identified
SHIELDS, S W Public Service Co of Indiana, Inc 80/11/03 2pp 06928 334

801100477 Final deficiency rept re ability of contractor GA program to assure that design changes were incorporated into const activities Insp verified that changes were incorporated Item determined not reportable per 10CFR50.55e
SHIELDS, S W Public Service Co of Indiana, Inc 80/11/03 2pp 06928 008

8011200137 PNO-III-80-209 on 801107, Region 3 was informed by Louisville, KY, newspaper reporter that grand jury re alleged coverup of defective concrete at site had convened & subsequently announced no indictment would be issued.
SCHWEIBINZ, E ; WILLIAMS, C. ; FIORELLI, G Region 3, Chicago, Office of the Director 80/11/07 1p 07021 279

801190533 Interim deficiency rept, originally reported on 800509, re centrifugal charging pumps operation during high energy line rupture Westinghouse currently evaluating potential mods
Final rept to be available by 810201
SHIELDS, S W Public Service Co of Indiana, Inc. 80/11/14 1p 06999:362

8011230454 Interim deficiency rept re defects in welds on cable tray hangers initially reported on 800925 Addl evaluation of weld deficiencies is in progress Evaluation results & corrective action will be provided in final rept by 810301
SHIELDS, S W Public Service Co of Indiana, Inc 80/11/19 2pp 07068 255

8011230289 Final deficiency rept re 800919 notification of installation of approx 600 safety-related component supports w/o procedural controls. Reinsp determined no corrective action necessary. Issue not reportable per 10CFR50.55e
SHIELDS, S W Public Service Co of Indiana, Inc 80/11/20 2pp 07056:139.

T. Hearing transcripts on non-antitrust matters

8011240493 Transcript of 800617 interview of J Henry in Louisville, KY
Pg 1-242
* Commissioners 80/06/17 242pp 07047 042

8011200348 Forwards IE Insp Repts 50-546/80-04 & 50-547/80-04 on 800123-30, 0201-08, 0617-30 & 0703-11 & notice of violation
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/15 2pp 01741 019

--8011200354 Transcript of JE Henry 790620 statement, afternoon session, in Madison, IN Pg 1-53 W/supporting documentation
HENRY, J E United States Testing Co, Inc. 79/06/20 110pp. 01741 019

8011260416 Forwards IE Investigation Repts 50-546/79-08 & 50-547/79-08 on 790622, 25-29, 0707, 11-13 & 17-20 No noncompliance noted Notes rept will receive expedited proprietary review.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/10, 2pp. 07073, 001

--8011260429 Statement of 790808 appearance in Madison, IN re const deficiencies. Pg 1-23
CUTBELL, C E Affiliation Unknown 79/05/08 23pp. 07073 022

DOCKET BTN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8011030354 Ltr to all licensees of operating plants, applicants for OLS & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements.
EISENHUT, D O. Division of Licensing 80/09/05 209pp

8011200257 Forwards request for addl info re safety-related concrete areas, critical biological shielding locations & concrete repair work Verbal exchange may be more convenient
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/27 2pp 07020 093

--8011200261 Submits list of info previously requested & requests addl info as result of meetings w/other consultants
HAMM, R C ; PARME, A L Hamm Engineers, Inc 80/09/05 3pp 07020 005

--8011200264 Forwards request for addl info re nondestructive testing supplementing 800903 request
HAMM, R C ; PARME, A L Hamm Engineers, Inc 80/09/10 3pp 07020 008

801100486 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100937 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports " W/o encl
EISENHUT, D O Division of Licensing 80/10/06 6pp

8011200011 Responds to NRC 800515 ltr re graduated rescission of 790815 order Items identified in app which are prerequisite to const resumption completed Upon NRC review Items D 7, C 3, D 3, E 1 & E 3, until will request order be lifted
SHIELDS, S W Public Service Co of Indiana, Inc 80/10/30 2pp 07015 354

8011200352 Ack receipt of 801001 ltr requesting voluntary submittal of info re environ qualification of safety-related equipment Response will be submitted by 810101
SHIELDS, S W Public Service Co of Indiana, Inc 80/10/31, 1p 07020 268

8011210741 Ack receipt of 801107 ltr requesting further partial rescission of 790815 order Authorizes firms to commence receipt insp in contracted disciplines
STELL, O V Office of Inspection & Enforcement, Office of the Director 80/11/13 5pp 07029 106

--8011210754 Ack receipt of 800515 ltr re 790815 graduated rescission of order. Specific activities accomplished adjustment of QA programs & comprehensive audits Requests NRC perform evaluations of adjusted receipt insp programs
SHIELDS, S W Public Service Co of Indiana, Inc 80/11/07 2pp 07029 111

--8011210759 Informs that Region 3 has concluded that vendors can carry out receipt insp properly Recommends resumption of activities Draft ltr authorizing activity encl
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/07 2pp 07029 113

8011250413 Forwards Revision 1 to SL-3753, "Evaluation of In-Place Concrete " W/o encl
SHIELDS, S W Public Service Co of Indiana, Inc 80/11/17 1p 07056 097

H General correspondence

8011140395 Requests carbon copies of correspondence be sent to WM Petros.
SHIELDS, S W Public Service Co of Indiana, Inc 80/11/07 1p 06962:341.

O Inspection reports, IE Bulletins & correspondence

8011260372 Forwards IE Insp Repts 50-546/80-33 & 50-547/80-33 on 800910-12. No noncompliance noted
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/23 2pp 07072 304

--8011260378 IE Insp Repts 50-546/80-33 & 50-547/80-33 on 800910-12 No noncompliance noted Major areas inspected unresolved items from previous insp, QA, QC & work procedures involving receipt storage handling
McIBLER, J H ; WILLIAMS, C C Region 3, Chicago, Office of the Director 80/09/22 5pp 07072 306

8011040297 Forwards IE Insp Repts 50-546/80-34 & 50-547/80-34 on 800917-19 No noncompliance noted.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/02 2pp 06984 359

DOCKETED ITEMS

- 8011040300 IE Insp Repts 50-546/80-34 & 50-547/80-34 on 800917-19 No noncompliance noted. Major areas inspected licensee action re insp of installed Category 1 structural steel implemented per 790815 stop work order
KONKLIN, J E, WILLIAMS, C C. Region 3, Chicago, Office of the Director 80/09/30 5pp 06885 001
- 8011040303 Forwards IE Insp Repts 50-546/80-32 & 50-547/80-32 on 800908-10 No noncompliance noted
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/02 2pp 06885 020
- 8011040309 IE Insp Repts 50-546/80-32 & 50-547/80-32 on 800908-10 No noncompliance noted. Major areas inspected site tour & review of previous insp findings
SCHWEIBINZ, E R, WILLIAMS, C C. Region 3, Chicago, Office of the Director 80/10/02 4pp 06885 022
- 8011200548 Forwards IE Insp Repts 50-546/80-04 & 50-547/80-04 on 800123-30, 0201-08, 0617-30 & 0703-11 & notice of violation
KEPPLER, J O. Region 3, Chicago, Office of the Director 80/10/15 2pp 01741 019.
- 8011200550 Notice of violation from insp on 800123-30, 0201-08, 0617-30 & 0703-11.
+ Region 3, Chicago, Office of the Director 80/09/26 2pp.
01741 019
- 8011200553 IE Insp Repts 50-546/80-04 & 50-547/80-04 on 800123-30, 0201-08, 0617-30 & 0703-11. Noncompliance noted, personnel signing or initiating records for other personnel
FOSTER, J E, HAWKINS, F C, NDRELIUS, C E. Region 3, Chicago, Office of the Director 80/09/26 40pp 01741 019
- 8011200554 Transcript of JE Henry 790620 statement, afternoon session, in Madison, IN Pp 1-33 W/supporting documentation
HEPNEY, J E. United States Testing Co, Inc 79/06/20 110pp.
01741 019.
- 801100047 Forwards IE Insp Repts 50-546/80-35 & 50-547/80-35 on 800922-25 No noncompliance noted.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/17 2pp 06929 034.
- 801100054 IE Insp Repts 50-546/80-35 & 50-547/80-35 on 800922-25 No noncompliance noted. Major areas inspected status of Verification Program SPP-11, review of Verification Programs SPP-4, SPP-8 & SPP-12 & review of safety storage
ERB, C H, CORDERO, Z C. Region 3, Chicago, Office of the Director DANIELSON, D H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/16 5pp. 06929 036.
- 8011250057 Forwards IE Insp Repts 50-546/80-36 & 50-547/80-36 on 801006-09 No noncompliance noted
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/21 2pp 07056 224
- 8011250062 IE Insp Repts 50-546/80-36 & 50-547/80-36 on 801006-09. No noncompliance noted. Major areas inspected. Const Verification Program SPP-13, Category 1 concrete constituent matls & embedded metals records review
QALLAHER, E J. Region 3, Chicago, Office of the Director HAYES, D W. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/20 9pp 07056 226.
- 8011070304 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required
KEPPLER, J O. Region 3, Chicago, Office of the Director 80/10/24 1p 06921 336
- 801170168 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Requests extension until 801215 to respond to bulletin
SHIELDS, B W. Public Service Co of Indiana, Inc. 80/10/31 1p. 06982 001.
- 8011260416 Forwards IE Investigation Repts 50-546/79-08 & 50-547/79-08 on 790622, 25-29, 0707, 11-13 & 17-20. No noncompliance noted. Notes re: will receive expedited proprietary review
KEPPLER, J O. Region 3, Chicago, Office of the Director 80/11/10. 2pp 07073 001.
- 8011260424 IE Investigation Repts 50-546/79-08 & 50-547/79-08 on 790622, 25-29, 0707, 11-13 & 17-20. Major areas insp: allegations of improper repair of concrete structures & concealment of nonconforming concrete areas
FOSTER, J E, HAWKINS, F C, WILLIAMS, C C. Region 3, Chicago, Office of the Director. 79/08/09 17pp 07073 003.
- 8011260429 Statement of 790308 appearance in Madison, IN re const deficiencies Pp 1-23
CUTBELL, C E. Affiliation Unknown 79/09/08 23pp 07073 022
- 8 Reportable occurrences, LERs & related correspondence
- 8011030683 Ack receipt of 800902 interim deficiency re: ability of structural contractor GA program to assure that design changes were incorporated into const activities
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/23 1p 06873 039
- 8011030686 Second interim deficiency re: ability of structural contractor GA program to assure design changes were incorporated into const activities. Design change issue is still unresolved. Final re: to be submitted by 801101
SHIELDS, B W. Public Service Co of Indiana, Inc 80/09/02 1p. 06873 040
- 8011200250 Ack receipt of 800929 interim deficiency re: incorrect weld filler used in safety-related pipe spool pieces
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/17 1p 07020 001
- 8011030584 Forwards attachments to 801017 fuel deficiency re: use of concrete expansion anchors to install temporary piping & defective Carbo-Zinc 11 primer coating on polar cranes
SHIELDS, B W. Public Service Co of Indiana, Inc 80/10/27 11pp. 01736 001
- 801120049 Ack receipt of 801014 final deficiency re: Westinghouse Type W-Z switches
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/27 1p 06953 004
- 801120417 Ack receipt of 801017 final deficiency re: documentation packages for Westinghouse supplied matls missing quality records
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/29 1p 06953 007
- 801190303 Ack receipt of 801024 interim deficiency re: welds on cable tray hangers
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/31 1p. 06916 001
- 801190726 Ack receipt of 801023 interim deficiency re: substitution of certain matls for those allowed by spec for stainless steel liner work
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/31 1p 06916 001
- 801100298 Forwards schedule indicating when final deficiency repts will be submitted. Schedule addresses items reported prior to 800101, for which final re: dates have not been previously identified
SHIELDS, B W. Public Service Co of Indiana, Inc 80/11/03 2pp. 06928 334
- 801100477 Final deficiency re: re: ability of contractor GA program to assure that design changes were incorporated into const activities. Insp verified that changes were incorporated. Item determined not reportable per 10CFR50.55e
SHIELDS, B W. Public Service Co of Indiana, Inc. 80/11/03 2pp. 06928 008.
- 8011200137 PNO-III-80-209 on 801107. Region 3 was informed by Louisville, KY, newspaper reporter that grand jury re: alleged coverup of defective concrete at site had convened & subsequently announced no indictment would be issued
SCHWEIBINZ, E, WILLIAMS, C., FIORELLI, O. Region 3, Chicago, Office of the Director 80/11/07 1p 07021 279.
- 801190533 Interim deficiency re: originally reported on 800509, re: centrifugal charging pumps operation during high energy line rupture. Westinghouse currently evaluating potential mode. Final re: to be available by 810201
SHIELDS, B W. Public Service Co of Indiana, Inc 80/11/14 1p. 06999 362
- 8011250454 Interim deficiency re: re: defects in welds on cable tray hangers initially reported on 800925. Addl evaluation of weld deficiencies is in progress. Evaluation results & corrective action will be provided in final re: by 810301
SHIELDS, B W. Public Service Co of Indiana, Inc. 80/11/19 2pp. 07068 235.

8011250289 Final deficiency rept re 800919 notification of installation of approx 600 safety-related component supports w/o procedural controls. Reinsp determined no corrective action necessary. Issue not reportable per 10CFR30.55e. SHIELDS, B. W. Public Service Co. of Indiana, Inc. 80/11/20. 2pp. 07056:139

T. Hearing transcripts on non-antitrust matters

8011240493 Transcript of 800617 interview of J. Henry in Louisville, KY. Pp 1-242. * Commissioners. 80/06/17. 242pp. 07047:042

8011200548 Forwards IE Insp Repts 50-546/80-04 & 50-547/80-04 on 800123-30, 0201-08, 0617-30 & 0703-11 & notice of violation. KEPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/15. 2pp.

--8011200554 Transcript of J.E. Henry 790620 statement, afternoon session, in Madison, IN. Pp 1-53. W/supporting documentation. HENRY, J. E. United States Testing Co., Inc. 79/06/20. 110pp.

8011260416 Forwards IE Investigation Repts 50-546/79-08 & 50-547/79-08 on 790622, 25-29, 0707, 11-13 & 17-20. No noncompliance noted. Notes rept will receive expedited proprietary review. KEPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/10. 2pp.

--8011260429 Statement of 790508 appearance in Madison, IN re const deficiencies. Pp 1-23. CUTBELL, C. E. Affiliation Unknown. 79/05/08. 23pp.

DOCKET 50-548 FORT CALHOUN STATION, UNIT 2

G. Adjudicatory correspondence

8011190156 Forwards util request for withdrawal of application for CP & termination of proceedings held in abeyance since Oct 1978. VOIGT, H. H. LeBoeuf, Lamb, Leiby & MacRae. 80/11/14. 1p. 06998:197.

--8011190163 Request for withdrawal of application for CP w/o prejudice to right for future applications. Urges continuation of withholding confidential documents submitted by util from public disclosure Certificate of BvC encl. BHALL, L. C. Omaha Public Power District. 80/11/13. 3pp. 06998:200

DOCKET BTN-50-553 PHIPPS BEND NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements. EISENHUT, D. G. Division of Licensing. 80/09/05. 209pp.

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101. EISENHUT, D. G. Division of Licensing. 80/10/01. 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl. EISENHUT, D. G. Division of Licensing. 80/10/06. 6pp.

G. Inspection reports, IE Bulletins & correspondence

801170687 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24. 1p.

B. Reportable occurrences, LERs & related correspondence

801140079 Interim deficiency rept originally reported on 801003 re longitudinal cracks in US Steel carbon steel piping purchased from Ouyon Alloys. Util, US Steel & Ouyon Alloys will meet onsite for piping evaluation. Final rept by 810202. MILLS, L. M. Tennessee Valley Authority. 80/11/03. 2pp. 06960:324.

801140557 Part 21 rept re US Steel pipe w/longitudinal cracks. Piping has not been installed in any sys or component that is to function under pressure. Final rept will be submitted by 810202.

MILLS, L. M. Tennessee Valley Authority. 80/11/03. 3pp. 06911:001.

801180551 Interim deficiency rept originally reported on 801014 re embedded plates w/o heat traceability. Number of embedded plates w/o traceability will be determined. Affected plates to be chipped out of auxiliary bldg walls. MILLS, L. M. Tennessee Valley Authority. 80/11/13. 2pp. 06988:250.

DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements. EISENHUT, D. G. Division of Licensing. 80/09/05. 209pp.

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101. EISENHUT, D. G. Division of Licensing. 80/10/01. 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl. EISENHUT, D. G. Division of Licensing. 80/10/06. 6pp.

G. Inspection reports, IE Bulletins & correspondence

801170687 Forwards Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/24. 1p.

B. Reportable occurrences, LERs & related correspondence

801140079 Interim deficiency rept originally reported on 801003 re longitudinal cracks in US Steel carbon steel piping purchased from Ouyon Alloys. Util, US Steel & Ouyon Alloys will meet onsite for piping evaluation. Final rept by 810202. MILLS, L. M. Tennessee Valley Authority. 80/11/03. 2pp. 06960:324.

801140557 Part 21 rept re US Steel pipe w/longitudinal cracks. Piping has not been installed in any sys or component that is to function under pressure. Final rept will be submitted by 810202. MILLS, L. M. Tennessee Valley Authority. 80/11/03. 3pp. 06911:001.

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

A. Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TMI action plan requirements. Provides summary listing of all approved TMI-2 related requirements. EISENHUT, D. G. Division of Licensing. 80/09/05. 209pp.

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101. EISENHUT, D. G. Division of Licensing. 80/10/01. 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl. EISENHUT, D. G. Division of Licensing. 80/10/06. 6pp.

G. Adjudicatory correspondence

801180378 FOIA request for OE "Reed Rept." HUNN, B. D. Affiliation Unknown. 79/02/23. 1p. 06991:187.

801180288 FOIA request for OE "Reed Rept." & related abstracts. ORRIS, L. H. United Press International. 79/08/16. 1p. 06986:029.

DOCKETED ITEMS

8011040438 Advises that release of OE Reed rept is deferred until seven days after Federal District Court Nov hearing on OE action to enjoin proposed release
BICKHIT,L Office of the General Counsel 80/10/29 1p
06873 284

8011070018 Addendum to Commission 801009 decision, CLI-80-35, providing JM Hendrie & PA Bradford separate statements re retention of OE Reed rept, for inclusion in decision
CHILK,B J Office of the Secretary of the Commission 80/11/04 9pp. 06924 275

8011180247 Supplis 800116 response to FOIA request for OE "Reed Rept." & excerpt re 27 safety-related issues Forwards Commission memo re release of rept Rept cannot be released pending resolution of claims W/o encl
FELTON,J M Division of Rules and Records 80/11/14 1p
06913.001

--8011180279 Excerpt from Joint Committee on Atomic Energy 760218-23-24 & 0302-04 hearings in Washington, DC Page 1,493.
* Congress (Joint & Rotating Committees, etc). 76/03/04. 2pp.
06913:001

8011180286 Supplis 790816 response to FOIA request for OE "Reed Rept " Provides current status of rept Forwards Commission memo re release of rept Rept cannot be released pending resolution of claims.W/o encl Commission memo
FELTON,J M. Division of Rules and Records 80/11/14 1p
06986 028.

8011180296 Supplis 790329 response to FOIA request for OE "Reed Rept " Provides current status of rept Forwards Commission memo re rept release.Rept cannot be released pending resolution of claims.W/o encl Commission memo
FELTON,J M. Division of Rules and Records 80/11/14 1p
06986 026.

8011180306 Supplis 791119 response to FOIA request for OE "Reed Rept " Provides current status of rept Forwards Commission memo re rept release.Rept cannot be released pending resolution of claims.W/o encl Commission memo
FELTON,J M Division of Rules and Records. 80/11/14 1p
06991 154

8011180376 Supplis 790323 response to FOIA request for OE "Reed Rept " Provides current status of rept Forwards Commission memo re rept release Rept cannot be released pending resolution of claims
FELTON,J M Division of Rules and Records. 80/11/14 1p.
06991:186.

8011250071 Advises of latest developments in litigation re release of Reed rept.OE action transferred from Washington,DC to IL NRC may not disclose rept until IL court decides pending case Decision not expected until early 1981
BICKHIT,L Office of the General Counsel 80/11/18 ap
07056 189.

--8011250027 Order transferring Civil Action 80-2659 to US District Court for Central District of IL Reed rept may not be released pending disposition.
ROBINSON U.S. District Court, District of Columbia 80/10/31.
1p. 07056.190

General correspondence

801120405 Petitions govt representatives to promote use of solar & wind-powered energy & phase out operation of nuclear plants as quickly as possible
MACEE,L Affiliation Unknown 80/10/21 1p 06956 250

8011240290 Petition urging support for wide use of solar & wind power, & phasing out of nuclear power plants,especially Black Fox, as soon as possible.
HALL,D Affiliation Unknown. 80/10/21. 19pp 07049 330

DOCKET BTN-80-557 BLACK FOX STATION, UNIT 2

Application/construction stage documents & correspondence

801030354 Ltr to all licensees of operating plants,applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT,D O Division of Licensing 80/09/05. 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs Info needed by 801101
EISENHUT,D O Division of Licensing 80/10/01 5pp

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl
EISENHUT,D O Division of Licensing 80/10/06 6pp

O Adjudicatory correspondence

8011040438 Advises that release of OE Reed rept is deferred until seven days after Federal District Court Nov hearing on OE action to enjoin proposed release
BICKHIT,L Office of the General Counsel 80/10/29 1p
06873 284.

8011070018 Addendum to Commission 801009 decision, CLI-80-35, providing JM Hendrie & PA Bradford separate statements re retention of OE Reed rept, for inclusion in decision
CHILK,B J Office of the Secretary of the Commission 80/11/04 9pp 06924 275

8011250021 Advises of latest developments in litigation re release of Reed rept.OE action transferred from Washington,DC to IL NRC may not disclose rept until IL court decides pending case.Decision not expected until early 1981
BICKHIT,L Office of the General Counsel 80/11/18 ap
07056.189

--8011250027 Order transferring Civil Action 80-2659 to US District Court for Central District of IL Reed rept may not be released pending disposition.
ROBINSON U.S. District Court, District of Columbia 80/10/31
1p. 07056.190

H General correspondence

801120405 Petitions govt representatives to promote use of solar & wind-powered energy & phase out operation of nuclear plants as quickly as possible
MACEE,L Affiliation Unknown. 80/10/21 1p 06956.250.

8011240290 Petition urging support for wide use of solar & wind power, & phasing out of nuclear power plants,especially Black Fox, as soon as possible
HALL,D Affiliation Unknown 80/10/21 19pp 07049.330

DOCKET 80-564 NUCLEAR FUELS RECOVERY & RECYCLE CENTER

O Adjudicatory correspondence

8011040382 Responds to 801013 ltr transmitting J Courtney request for resumption of QESMO proceeding.Comments will be taken into account in NRC review re proceeding.
KAMMERER,G. Office of Congressional Affairs 80/10/22 1p

DOCKET BTN-80-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants,applicants for OLs & holders of CPs re preliminary clarification of TMI action plan requirements Provides summary listing of all approved TMI-2 related requirements
EISENHUT,D O Division of Licensing. 80/09/05 209pp.

801100486 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs. Info needed by 801101
EISENHUT,D.O Division of Licensing 80/10/01. 5pp.

801100537 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " W/o encl.
EISENHUT,D.O Division of Licensing 80/10/06. 6pp

DOCKETED ITEMS

2

G Inspection reports, IE Bulletins & correspondence

8011260418 Forwards IE Insp Repts 50-566/80-15 & 50-567/80-15 on 800908-11 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/09 2pp 07072 342

--8011260421 IE Insp Repts 50-566/80-15 & 50-567/80-15 on 800908-11 No noncompliance noted Major areas inspected receiving insp, storage, preventive maint, concrete activities, const status & QA audits
THOMAS, M Region 2, Atlanta, Office of the Director
CANTRELL, F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/08 5pp 07072 344

8011170687 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment," No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24 1p.

B. Reportable occurrences, LERs & related correspondence

8011190737 Part 21 rept re structural steel framing for control bldg Rework of fillet welds has been performed by vendor representatives & items now comply w/contract spec requirements. Audit will be completed by 801201.
MILLS, L M. Tennessee Valley Authority 80/11/05, 3pp 07001 184

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8011050354 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs re preliminary clarification of TH1 action plan requirements Provides summary listing of all approved TH1-2 related requirements
EISENHUT, D O Division of Licensing 80/09/05 209pp

801100486 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs requesting info re environ qualification tests to be conducted on safety-related equipment within next two yrs info needed by 801101
EISENHUT, D O Division of Licensing 80/10/01 5pp

801100937 Ltr to all power reactor licensees & applicants forwarding summary of 800827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports," W/o encl.
EISENHUT, D O Division of Licensing 80/10/06 6pp

G Inspection reports, IE Bulletins & correspondence

8011260418 Forwards IE Insp Repts 50-566/80-15 & 50-567/80-15 on 800908-11, No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/10/09 2pp 07072.342

--8011260421 IE Insp Repts 50-566/80-15 & 50-567/80-15 on 800908-11 No noncompliance noted Major areas inspected receiving insp, storage, preventive maint, concrete activities, const status & QA audits.
THOMAS, M. Region 2, Atlanta, Office of the Director
CANTRELL, F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/08 5pp 07072 344

8011170687 Forwards Suppl 3 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24. 1p.

B. Reportable occurrences, LERs & related correspondence

8011190737 Part 21 rept re structural steel framing for control bldg Rework of fillet welds has been performed by vendor representatives & items now comply w/contract spec requirements. Audit will be completed by 801201
MILLS, L.M. Tennessee Valley Authority, 80/11/05, 3pp 07001:184

DOCKET STN-50-580 ERIE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8011260761 Advises that Ofc of Controller has been notified to issue invoice for balance of fee for NRC review of CP application withdrawn on 800123
MILLER, W.D. License Fee Management Branch 80/11/10 1p 07074 146

DOCKET STN-50-581 ERIE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8011260761 Advises that Ofc of Controller has been notified to issue invoice for balance of fee for NRC review of CP application withdrawn on 800123
MILLER, W.D. License Fee Management Branch 80/11/10 1p 07074 146

DOCKET STN-50-592 PALO VERDE NUCLEAR STATION, UNIT 4

A Application/construction stage documents & correspondence

8011260269 Advises that Ofc of Controller has been notified to issue invoice for balance of fee for NRC review of CP application withdrawn on 790824
MILLER, W.D. License Fee Management Branch 80/11/10 1p 07074 150

DOCKET STN-50-593 PALO VERDE NUCLEAR STATION, UNIT 5

A Application/construction stage documents & correspondence

8011260269 Advises that Ofc of Controller has been notified to issue invoice for balance of fee for NRC review of CP application withdrawn on 790824
MILLER, W.D. License Fee Management Branch 80/11/10 1p 07074 150

DOCKET STN-50-596 NEW HAVEN, UNIT 1

G Adjudicatory correspondence

8011050164 Certifies svc of motion to terminate proceeding on 801016
SPINDEL, N W New York State Electric & Gas Corp SPINDEL, N W Huber, Magill, Lawrence & Farrell 80/10/16 6pp. 06897 306

8011050441 Response stating no objection to NY State Electric & Gas Corp & util motion to terminate CP proceeding Certificate of Svc encl
MOORE, J.E. Hearing Branch 2. 80/11/03 5pp 06898 209

8011140040 Order dismissing license application for nuclear fueled generation station at New Haven or Stuyvesant sites Proceeding terminated
WENNER, B., PARIS, D.H., JORDAN, W.H. Atomic Safety and Licensing Board Panel 80/11/06 2pp 06961 342

DOCKET STN-50-597 NEW HAVEN, UNIT 2

G Adjudicatory correspondence

8011050164 Certifies svc of motion to terminate proceeding on 801016
SPINDEL, N W New York State Electric & Gas Corp SPINDEL, N W Huber, Magill, Lawrence & Farrell. 80/10/16 6pp 06897 306

8011050441 Response stating no objection to NY State Electric & Gas Corp & util motion to terminate CP proceeding Certificate of Svc encl
MOORE, J.E. Hearing Branch 2. 80/11/03 5pp. 06898 209

8011140040 Order dismissing license application for nuclear fueled generation station at New Haven or Stuyvesant sites Proceeding terminated.
WENNER, B., PARIS, D.H., JORDAN, W.H. Atomic Safety and Licensing Board Panel. 80/11/06 2pp 06961.342

DOCKETED ITEMS

DOCKET 50-599 CARROLL FACILITY I

A. Application/construction stage documents & correspondence

8011190503 Notifies that review of preliminary geologic data & field insp shows Carroll County site adequate for const of nuclear facility
MORRIS, R H Interior, Dept of, Geological Survey 80/11/03 1p.
06999 147

O Adjudicatory correspondence

8011100228 Advises that Commission has declined review of ALAB-601 which will become final agency action by 801104 PA Bradford separate views re impact of early site review encl.
CHILK, S J Office of the Secretary of the Commission 80/11/05 2pp 06929 065

DOCKET 50-600 CARROLL FACILITY II

A. Application/construction stage documents & correspondence

8011190503 Notifies that review of preliminary geologic data & field insp shows Carroll County site adequate for const of nuclear facility
MORRIS, R H Interior, Dept of, Geological Survey 80/11/03 1p
06999 147

O Adjudicatory correspondence

8011100228 Advises that Commission has declined review of ALAB-601 which will become final agency action by 801104 PA Bradford separate views re impact of early site review encl.
CHILK, S J Office of the Secretary of the Commission 80/11/05 2pp 06929 065

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

8011030009 Forwards DOE rept, RFP-3110, "Transuranic (TRU) Waste Mgt Program," re acceptance of commercial TRU waste TRU wastes exceeding 10 nanoCuries/g are no longer acceptable for disposal at operating shallow land disposal sites.
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 80/10/10 5pp 06997 021

--8011030017 "US DOE Acceptance of Commercial Transuranic Waste " TABOAS, A L, BENNETT, W S, BROWN, C M Rockwell International Corp, Energy Systems Div 80/02/29, 30pp, 06857 026

-8011030022 Forwards transuranic (TRU) waste packaging criteria now used at DOE sites for retrievable storage of DOE TRU waste When Federal repository becomes operational, DOE will accept all NRC TRU waste requiring isolation.
MEYERS, S Energy, Dept of 80/04/14, 4pp 06857 036

-8011030024 "Criteria for Packaging Transuranic Waste for Receipt at INEL Radwaste Mgt Complex Offsite Generated Waste," Revision 1
Energy, Dept. of IDQ-10074 R1 79/08/31 35pp 06857 060

8011240018 Confirms arrangements for 801112 meeting to discuss item of noncompliance & related issues involving shipment of spent fuel cast in Jul 1980.
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/11/10, 1p 07039 254

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP

8011060422 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) R/Loss of Offsite Power " Emergency line verification performed by telephone representative Directive requiring NRC notification was issued
REMLEY, H E Rockwell International Corp, Energy Systems Div 80/08/15 3pp 06909 040

8011030045 Forwards IE Insp Rept 70-0025/80-08 on 800722-25, No noncompliance noted
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch, 80/09/18 2pp 06857 096.

--8011030047 IE Insp Rept 70-0025/80-08 on 800722-25 No noncompliance noted Major areas inspected health, safety & radiation svcs organization, changes & mods, internal review & audit
COOLEY, H J, THOMAS, R D, BOOK, H E Region 5, San Francisco Fuel Facility & Materials Safety Branch 80/09/16 8pp 06857 129

8011030009 Forwards DOE rept, RFP-3110, "Transuranic (TRU) Waste Mgt Program," re acceptance of commercial TRU waste TRU wastes exceeding 10 nanoCuries/g are no longer acceptable for disposal at operating shallow land disposal sites
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 80 5pp

8011060812 Forwards IE Insp Rept 70-0025/80-09 on 801006-10 No noncompliance noted Encl withheld (ref 10CFR2 790)
NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 80/10/28 2pp 06909 132

DOCKET 70-0027 BABCOCK & WILCOX CO

8011060179 Ack receipt of 800902 ltr providing assurance that B&W has sufficient capital to cover decommissioning costs
PAGE, R Q Uranium Recovery Licensing Branch 80/09/30 1p 06915 326

8011200529 Forwards IE Insp Rept 70-0027/80-16 on 800923-26 No noncompliance noted.
KENNA, W B Region 2, Atlanta, Safeguards Branch 80/10/14 1p 07020 161

--8011200534 IE Insp Rept 70-0027/80-16 on 800924-26 No noncompliance noted Major areas inspected nuclear criticality safety, safety committees, operations & procedure control
CORVELL, O P, WRAY, J R Region 2, Atlanta, Office of the Director KAHN, E J B Region 2, Atlanta, Safeguards Branch 80/10/14 5p 07020 162

8011240569 Notifies of IE 801111 site visit to review groundwater monitoring data & to assess adequacy of groundwater monitoring program Question guide encl
STCHUR, J P Region 2, Atlanta, Office of the Director 80/11/04 3pp 07049 083

DOCKET 70-0033 TEXAS INSTRUMENTS, INC

8011030305 Confirms & documents 800925 agreement w/NRC re extension of deadline for reconciliation of 800827 physical inventory Extension permits further investigation of natl balance & item control area records to be completed by 801001
SCHWENSBFIR, R Texas Instruments, Inc 80/09/25 1p, 06861 203

8011140536 Revises License Condition 2.1 of Amend MFP-1 to License 8NM-23 re fundamental nuclear matl control plan
PARTLOW, J Q Material Control Licensing Branch 80/10/31 1p 06963 006

8011280194 Discusses planned mods to emergency notification sys & health physics network NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys.
ORIER, B H Region 1, Philadelphia, Office of the Director 80/11/14 2pp 07083 296

DOCKET 70-0048 WESTINGHOUSE ELECTRIC CORP.

8010020739 Submits corporate info applicable to encl list of licensees Forwards Annual Financial Rept 1979
DIPIAZZA, R P Westinghouse Electric Corp 80/09/04 5pp

--8010020745 Annual Financial Rept 1979
Westinghouse Electric Corp 80/01/30 51pp 03616 203

8011030009 Forwards DOE rept, RFP-3110, "Transuranic (TRU) Waste Mgt Program," re acceptance of commercial TRU waste TRU wastes exceeding 10 nanoCuries/g are no longer acceptable for disposal at operating shallow land disposal sites
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 80/10/10 5pp.

DOCKET 70-0135 BABCOCK & WILCOX CO

8011050317 Forwards IE Insp Rept 70-0135/80-17 on 800618-20 No noncompliance noted
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/04, 2pp 06900 214

--8011050521 IE Insp Rept 70-0135/80-17 on 800618-20 No noncompliance noted Major areas inspected outstanding items audits, blue bldg, dosimetry, source inventory & leak test, whole body count & instrument calibr
CLEMONS, P Region 1, Philadelphia, Office of the Director
KNAPP, J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/27 5pp 04900-216

8011070534 Forwards IE Insp Rept 70-0135/80-26 on 800825-27 No noncompliance noted
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/09/19 2pp 06925 173

--8011070537 IE Insp Rept 70-0135/80-26 on 800825-27 No noncompliance noted Major areas inspected residual U holdup Details withheld (ref 10CFR2 790)
COHEN, I, SUMMERS, R Region 1, Philadelphia, Office of the Director
JOYNER, J H Region 1, Philadelphia, Safeguards Branch 80/09/18 1p 06925 173

8011060179 Ack receipt of 800902 ltr providing assurance that B&W has sufficient capital to cover decommissioning costs
PAGE, R O Uranium Recovery Licensing Branch 80/09/30 1p 06915 326

8011210280 Forwards IE Insp Repts 70-0135/80-24 & 70-0364/80-21 on 800804-29 No noncompliance noted
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/09/30 2pp 07030 129

--8011210297 IE Insp Repts 70-0135/80-24 & 70-0364/80-21 on 800804-29 No noncompliance noted Major areas inspected: matl control & accounting, physical security & health & industrial safety Portions withheld (ref 10CFR2 790)
KUSHNER, W L Region 1, Philadelphia, Office of the Director
JOYNER, J H Region 1, Philadelphia, Safeguards Branch 80/09/26 8pp 07030 131

8011070541 Ack receipt of 800829 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/80-21 & 70-0364/80-17
MARTIN, W O Region 1, Philadelphia, Safeguards Branch, 80/10/09 1p 06925-176

--8011070546 Responds to NRC 800807 ltr re violations noted in IE Insp Repts 70-0135/80-21 & 70-0364/80-17 Corrective actions withheld (ref 10CFR2 790)
AUSTIN, M A Babcock & Wilcox Co 80/08/29 1p 06925 177

--8011070592 Forwards IE Insp Repts 70-0135/80-21 & 70-0364/80-17 on 800602-0704 & notice of violation Notice of violation withheld (ref 10CFR2 790)
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/08/07 2pp 06925-178

--8011070558 IE Insp Repts 70-0135/80-21 & 70-0364/80-17 on 800602-0704 Noncompliance noted Failure to advise NRC of mods to structure of item control area for high enriched U Details withheld (ref 10CFR2 790)
KUSHNER, W L Region 1, Philadelphia, Office of the Director
JOYNER, J H Region 1, Philadelphia, Safeguards Branch 80/08/04 8pp 06925-180

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC

8011070348 Forwards responses to info request sheets comprising part of App 1, Revision 0 of NPS physical safeguards plan, per 800904 ltr. Remainder of app will be forwarded by 801117 Encl withheld (ref 10CFR2 790)
MICHEL, C J Nuclear Fuel Services, Inc (subs. of Getty Oil Co.), 80/11/03 1p 06918-126

801180088 Expresses strong opposition to NRDC effort to remove NPS plant from Erwin, TN.
GAINES, W J Tennessee, State of 80/10/06 1p 06916-001

8011240399 Forwards IE Insp Rept 70-0143/80-28 on 800818-22 No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 80/10/09 1p 07072-325

--8011260407 IE Insp Rept 70-0143/80-28 on 800818-22 No noncompliance noted Major areas inspected: airborne effluent monitoring, environ air sampling & soil decontamination.
MILLSAP, W J Region 2, Atlanta, Office of the Director
OTSBUN, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 80/10/06 5pp 07072-326

8011030009 Forwards DOE rept, RFP-3110, "Transuranic (TRU) Waste Mgt Program," re acceptance of commercial TRU waste TRU wastes exceeding 10 nanoCuries/g are no longer acceptable for disposal at operating shallow land disposal sites
CUMMINGHAM, R E Division of Fuel Cycle & Material Safety 80/10/10 5pp

8011050048 Responds to NRC 800929 ltr re rept entitled, "Technical Assessment of Inventory Differences at NPS, Jan 1978-Mar 1980" Rept does not contain proprietary info
MANBER, W C Nuclear Fuel Services, Inc (subs. of Getty Oil Co) 80/10/10 1p 06896-295

8011030272 Forwards IE Insp Rept 70-0143/80-32 on 800922-24 No noncompliance noted
KENNA, W B Region 2, Atlanta, Safeguards Branch 80/10/15 2pp 06857 210

--8011030275 IE Insp Rept 70-0143/80-32 on 800922-24 No noncompliance noted Major areas inspected physical barriers, access controls & testing & maint Details withheld (ref 10CFR2 790)
TOSIN, W J, HOWELL, J C Region 2, Atlanta, Office of the Director
MCQUIRE, D R Region 2, Atlanta, Safeguards Branch 80/10/14 1p 06857-212

8011060370 Transcript of 801017 briefing by IE on rept on NPS-Erwin in Washington, DC Pp 1-79 Briefing notes encl
* Commissioners 80/10/17 100pp 06910-002

--8011060376 "Technical Assessment of Inventory Differences at Nuclear Fuel Svcs," Jan 1978-Mar 1980
* Region 2, Atlanta, Safeguards Branch 80/10/17 120pp 06910-084

8011100514 Grants license condition to Amend MPP-1 of License 8NM-124, for determining U inventory difference Approval is contingent on submittal of supplemental info
BURNETT, R F Division of Safeguards 80/10/23 2pp 06931 219

8011040525 Opposes NRDC action to relocate NPS
EDWARDS, W E Nuclear Fuel Services, Inc (subs. of Getty Oil Co) 80/10/24 1p 06873 114

8011130377 Ack receipt of 800922 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-23
KENNA, W B Region 2, Atlanta, Safeguards Branch 80/10/27 1p 06937-001

--8011130387 Responds to NRC 800902 ltr re violations noted in IE Insp Rept 70-0143/80-23 Corrective actions withheld (ref 10CFR2 790)
MANBER, W C Nuclear Fuel Services, Inc (subs. of Getty Oil Co) 80/09/22 1p 06937-002

--8011130392 Forwards IE Insp Rept 70-0143/80-23 on 800624-0804 & notice of violation
KENNA, W B Region 2, Atlanta, Safeguards Branch, 80/09/02 2pp 06937-003

--8011130398 Notice of violation from insp on 800624-0804
* Region 1, Philadelphia, Office of the Director 80/08/29 1p 06937-003

--8011130405 IE Insp Rept 70-0143/80-23 on 800624-0804 Noncompliance noted, health & safety procedure not followed which resulted in fire in auxiliary cleaning room Portions withheld (ref 10CFR2 790)
LEE, T D Region 1, Philadelphia, Office of the Director
GILLESPIE, F P Region 1, Philadelphia, Safeguards Branch, 80/08/29 5pp 06937 006

8011060409 Confirms 801023 telcon that correction of item 5 of Deviation B has been rescheduled for 801015 due to delay in delivery of two level controllers
MANBER, W C Nuclear Fuel Services, Inc (subs. of Getty Oil Co.) 80/10/29 1p 06910 001

8011210360 Ack receipt of IE Insp Rept 70-0143/80-28 No proprietary info.
MANBER, W C Nuclear Fuel Services, Inc (subs. of Getty Oil Co.) 80/10/29 1p 07030-133

8011040497 Forwards Revision 19 page change to physical protection plan, Page 13 Changes submitted per 10CFR70 32 & upgrade mods. No fees applicable to 10CFR170 required. Encl withheld (ref 10CFR2 790)
MICHEL, C J Nuclear Fuel Services, Inc (subs. of Getty Oil Co) 80/10/30 1p 06877-144

DOCKETED ITEMS

801120296 RD on 800929, U-234 concentration on scrubber stack of Bldg 233 exceeded insoluble concentration of 10CFR20, App B, Table 1 for seven consecutive days. Facility shut down. Plant will be restarted sequentially. Air sample info encl. MANBER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 80/10/30 4pp, 06952 078

8011040408 Requests FI Bialik name be added to svc lists for all matters re facilities, BNL & transport of nuclear matts in NY
BIALIK, E I New York, State of 80/10/31 1p

8011070432 Forwards "Bldg 302/3 Stack Sampling Sys Evaluation," in response to NRC 800918 request
MANBER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 80/10/31 1p 06910 001

--8011070435 "Bldg 302/3 Stack Sampling Sys Evaluation"
* Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 80/10/31 9pp 06910 001

8011250007 Notifies of IE 801120 site visit to review groundwater monitoring data & to assess adequacy of groundwater monitoring program. Question guide encl.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/11/04 3pp 07052-358

801120295 Advises that consulting svcs were obtained from manufacturer of bldg 302/303 roof scrubber, as committed to in 800918 meeting. Analysis of scrubbing sys w/vendor comments encl.
MANBER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 80/11/03 5pp 06932 082

801170147 Notifies that no addl fee will be necessary re review of Revision 17 to physical security plan
MILLER, W D License Fee Management Branch 80/11/05 1p, 06981 361

801120531 Forwards Revision 19 to ref sections of fundamental nuclear matl control plan. Revision 19 withheld (ref 10CFR2.790). Encl destroyed.
HENSLEY, M D Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/11/06 1p 06953 347

801170907 Addl response to FOIA request for documents re NRC consideration of facility licensing & transcripts re closed Commission meetings. Forwards App A & B documents. Documents partially withheld (ref FOIA Exemptions 3 & 4).
FELTON, J M Division of Rules and Records 80/11/06 4pp 06971 001

801170918 Staff requirements memo re Commission 790920 meeting on facility Commission discussed desirability of requesting early FBI involvement in current NRC investigation of inventory difference at facility. Lists NRC requests.
CHILK, S J Office of the Secretary of the Commission 79/09/21 1p

801170928 Staff requirements memo re Commission 790919 meeting on facility Commission discussed results of physical inventory conducted in Aug 1979 & status of current NRC investigation of reported inventory discrepancy. Lists NRC requests.
CHILK, S J Office of the Secretary of the Commission, 79/09/21, 1p

801170935 Staff requirements memo re Commission 790927 meeting on facility Commission discussed current status of inventory difference investigation & agreed that FBI should be requested to participate in investigation.
CHILK, S J Office of the Secretary of the Commission 79/09/27, 1p.

801170943 Provides alternatives for Commission policy on safeguards regulations of highly enriched U activities at facility. Recommends approval of Alternative D info partially withheld (ref FOIA Exemptions 3 & 4).
DIRCKS, W J Office of Nuclear Material Safety & Safeguards SECY-79-650 79/12/11 12pp

801170948 Recommends that Commission approve highly enriched U activities at facility for single operating period following implementation of safeguards improvements outlined in SECY-79-650. Info partially withheld (ref FOIA Exemption 3).
DIRCKS, W J Office of Nuclear Material Safety & Safeguards SECY-79-650A 80/01/02 4pp

1200510 Ack receipt of IE Insp Rept 70-0143/80-31 on 800827-29 & 0714-15. No proprietary info.
MANBER, W C Nuclear Fuel Services, Inc (subs. of Getty Oil Co.) 0/11/06 1p 07020 146

--8011200515 Forwards IE Insp Rept 70-0143/80-31 on 800827-29 & 0714-15. No noncompliance noted.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/21 1p 07020 147

--8011200519 IE Insp Rept 70-0143/80-31 on 800827-29 & 0714-15. No noncompliance noted. Major areas inspected: confirmatory measurements & radiation surveys of contaminated adjacent railroad.
SHUM, E Y, MCPHAIL, P C Region 2, Atlanta, Office of the Director, 018504, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/21 13pp 07020 148

801180567 Forwards corrective actions taken or to be taken in response to NRC 801024 ltr containing IE Insp Rept 70-0143/80-29. Encl withheld (ref 10CFR2.790).
MANBER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 80/11/12 1p 06992 123

DOCKET 70-0162 LUCIUS PITKIN, INC

801110006 Amend 1 to SNM-137, decreasing possession limit of U-235 & changing expiration date to 810930.
PAGE, R D Uranium Fuel Licensing Branch 80/10/27 2pp 06943 207.

--801110010 Safety evaluation supporting Amend 1 to SNM-137, reducing possession limit of U-235, be approved.
SODOR, A L, CROW, W T Uranium Fuel Licensing Branch 80/10/27, 7pp 06943, 209

DOCKET 70-0182 NAVY, DEPT OF

8011260028 Ack receipt of 801009 ltr informing NRC of steps taken to correct violation noted in IE insp of Licenses 19-02891-05 & SNM-155 on 800827-28.
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/27 1p 07070 333

--8011260035 Responds to NRC 800915 ltr re violation noted in IE insp of Licenses 19-02891-05 & SNM-155 on 800827-28. Corrective actions: records of dose calibr linearity incorporated into permanent record book & duct work under hoods modified.
HORDAN, J T National Naval Medical Center Bethesda, MD, 80/10/09 1p 07070 334

--8011260037 Discusses IE insp of Licenses 19-02891-05 & SNM-155 on 800827-28 & forwards notice of violation.
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/13 2pp, 07070 335.

--8011260040 Notice of violation from insp on 800827-28. Noncompliance noted: failure to maintain records of dose calibr linearity tests.
* Region 1, Philadelphia, Fuel Facility & Materials Safety Branch, 80/09/13 1p 07070 337.

DOCKET 70-0261 SCHLUMBERGER TECHNOLOGY CORP

8011260066 Discusses insp of Licenses SNM-239, 06-00807-01 & 06-00807-02 on 800929-30 & forwards notice of violation.
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/24 2pp 07074, 247

--8011260068 Notice of violation from insp on 800929-30.
* Region 1, Philadelphia, Office of the Director 80/10/24, 1p 07074 249.

DOCKET 70-0267 NUCLEAR SCIENCE & TECHNOLOGY FACILITY AT SUNY

801180168 Forwards renewed License SNM-273 & safety evaluation.
PAGE, R D Uranium Fuel Licensing Branch 80/11/04, 1p 06987-236.

--801180173 Safety evaluation approving merger of Licenses SNM-273 & SNM-723 into one license, SNM-273.
SODOR, A L, CROW, W T Uranium Fuel Licensing Branch, 80/11/04, 7pp 06987 237.

--801180182 Matl/Byproduct License SNM-273 for State Univ of NY at Buffalo authorizing use of U-235 & Pu.
CROW, W T Uranium Fuel Licensing Branch 80/11/04, 11pp, 06987 244

DOCKETED ITEMS

25

--801180185 Extends appreciation for hospitality to AL Boong during trip to State Univ of NY, Buffalo & encl copy of trip rept
Revised renewal application due by 800731.
CROW, W T. Uranium Fuel Licensing Branch 80/07/02. 1p
06987.235

--801180192 Summary of 800619 trip to State Univ of NY at Buffalo to discuss license application
BOOKER, A L. Uranium Fuel Licensing Branch. 80/07/02. 3pp.
06987.236

DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO

8004070383 Ack receipt of 800205 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0364/79-80.
SMITH, G H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/27. 1p 04527.301

--8004070401 IE Insp Rept 70-0364/79-80 on 791128-29 Noncompliance noted: Improper survey procedures for box gloves & air samples
CLEMONS, P. E., CROCKER, H W. Region 1, Philadelphia, Office of the Director 80/01/11 9pp 04527.309.

801130321 Forwards IE Insp Rept 70-0364/80-23 on 800825-29 No noncompliance noted.
MARTIN, W. O. Region 1, Philadelphia, Safeguards Branch. 80/09/16. 2pp. 06958.317

--801130329 IE Insp Rept 70-0364/80-23 on 800825-29. No noncompliance noted. Major areas inspected records & repts on shipping & receiving. Details withheld (ref 10CFR2.790)
RATTA, A D, WOLTER, E F. Region 1, Philadelphia, Office of the Director. JOYNER, J H. Region 1, Philadelphia, Safeguards Branch. 80/09/15. 1p 06958.319.

8011060179 Ack receipt of 800902 ltr providing assurance that B&W has sufficient capital to cover decommissioning costs.
PAGE, R O. Uranium Recovery Licensing Branch 80/09/30 1p.
06915.325.

8011210280 Forwards IE Insp Repts 70-0135/80-24 & 70-0364/80-21 on 800804-29 No noncompliance noted
MARTIN, W. O. Region 1, Philadelphia, Safeguards Branch. 80/09/30. 2pp. 07030.129

--8011210297 IE Insp Repts 70-0135/80-24 & 70-0364/80-21 on 800804-29 No noncompliance noted Major areas inspected. matl control & accounting, physical security & health & industrial safety. Portions withheld (ref 10CFR2.790).
KUSHNER, W L. Region 1, Philadelphia, Office of the Director. JOYNER, J H. Region 1, Philadelphia, Safeguards Branch. 80/09/26. 8pp. 07030.131

8011070541 Ack receipt of 800829 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/80-21 & 70-0364/80-17.
MARTIN, W. O. Region 1, Philadelphia, Safeguards Branch. 80/10/09. 1p 06925.176

--8011070546 Responds to NRC 800807 ltr re violations noted in IE Insp Repts 70-0135/80-21 & 70-0364/80-17. Corrective actions withheld (ref 10CFR2.790).
AUSTIN, M A. Babcock & Wilcox Co. 80/08/29. 1p. 06925.177.

--8011070552 Forwards IE Insp Repts 70-0135/80-21 & 70-0364/80-17 on 800602-0704 & notice of violation. Notice of violation withheld (ref 10CFR2.790).
MARTIN, W. O. Region 1, Philadelphia, Safeguards Branch. 80/08/07. 2pp. 06925.178.

--8011070558 IE Insp Repts 70-0135/80-21 & 70-0364/80-17 on 800602-0704. Noncompliance noted failure to advise NRC of mods to structure of item control area for high enriched U Details withheld (ref 10CFR2.790).
KUSHNER, W L. Region 1, Philadelphia, Office of the Director. JOYNER, J H. Region 1, Philadelphia, Safeguards Branch. 80/08/04. 8pp 06925.180.

8011030009 Forwards DOE rept, RFP-3110, "Transuranic (TRU) Waste Mgt Program," re acceptance of commercial TRU waste. TRU wastes exceeding 10 nanoCuries/g are no longer acceptable for disposal at operating shallow land disposal sites.
CUNNINGHAM, R E. Division of Fuel Cycle & Material Safety 80/10/10. 5pp. 06897.021

801100425 Forwards comments on licensee 800829 revised fundamental nuclear matl control plan for Pu decommissioning W/o encl.
PARTLOW, J O. Material Control Licensing Branch. 80/10/22. 1p. 06931.271

8011210325 Ack receipt of response to IE Bulletin 80-15 re possible loss of emergency notification sys Response was not submitted under oath of affirmation Required oath must be submitted within 10 days
ORIER, B H. Region 1, Philadelphia, Office of the Director 80/10/23. 1p. 07030.142

8011280210 Discusses planned mods to emergency notification sys & health physics network NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys
ORIER, B H. Region 1, Philadelphia, Office of the Director 80/11/14. 2pp 07083.301.

DOCKET 70-0371 UNITED NUCLEAR CORP

801130341 Forwards IE Insp Rept 70-0371/80-13 on 800818 & 20-22 No noncompliance noted
MARTIN, W O. Region 1, Philadelphia, Safeguards Branch 80/09/16. 2pp. 06958.352

--801130348 IE Insp Rept 70-0371/80-13 on 800818 & 20-22 No noncompliance noted. Major areas inspected security plan & organization & physical barriers Details withheld (ref 10CFR2.790)
MADDEN, W. Region 1, Philadelphia, Office of the Director DEVLIN, J W. Region 1, Philadelphia, Safeguards Branch 80/09/12. 1p 06958.354.

8011210331 Ack receipt of response to IE Bulletin 80-15 re possible loss of emergency notification sys Response was not submitted under oath of affirmation Required oath must be submitted within 10 days.
ORIER, B H. Region 1, Philadelphia, Office of the Director. 80/10/23 1p. 07030.143

801180006 Forwards revised License Condition 2.1 of Amend MPP-1 to BNM-36B, incorporating new pages re fundamental nuclear matl control plan License Condition 3.2 requirements have been deleted
PARTLOW, J O. Material Control Licensing Branch 80/10/29. 5pp. 06986.083.

801190607 Amend 13 to License BNM-36B, authorizing vault storage of packaged recovered U.
PAGE, R O. Uranium Fuel Licensing Branch 80/10/31. 2pp 06996.224

--801190613 Safety evaluation recommending issuance of Amend 13 to License BNM-36B, authorizing vault storage of packaged recovered U.
STEVENSON, R L, CROW, W T. Uranium Fuel Licensing Branch. 80/10/31 2pp 06996.226

801180875 Amend MPP-1 to License BNM-36B, exempting Condition 3.1 requirements to that licensee. Upon receipt of shipment of three tamper-safed drums of BNM, may measure U & U-235 content only
PARTLOW, J O. Material Control Licensing Branch 80/11/03 1p. 06991.344

8011250080 Revised Amend MPP-1 of License BNM-36B, adding condition to allow receipt & storage of three tamper-safed drums of BNM.
PARTLOW, J O. Material Control Licensing Branch. 80/11/03 1p. 07088.290

8011280197 Discusses planned mods to emergency notification sys & health physics network NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys
ORIER, B H. Region 1, Philadelphia, Office of the Director. 80/11/14 1p 07083.278

DOCKET 70-0398 COMMERCE, DEPT. OF

8011070528 Forwards IE Insp Rept 70-0398/80-03 on 800827-29. No noncompliance noted.
SMITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/09/15 2pp. 06925.166.

--8011070532 IE Insp Rept 70-0398/80-03 on 800827-29. No noncompliance noted. Major areas inspected ventilation, smear surveys, annual rept, procedures, environ monitoring, liquid waste, source leak test & instruments.
CLEMONS, P. Region 1, Philadelphia, Office of the Director. KNAPP, P J. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/09/15. 5pp. 06925.168

DOCKETED ITEMS

DOCKET 70-0372 MONSANTO RESEARCH CORP

8011030009 Forwards DOE rept, RFP-3110, "Transuranic (TRU) Waste Mgt Program," re acceptance of commercial TRU waste TRU wastes exceeding 10 nanoCuries/g are no longer acceptable for disposal at operating shallow land disposal sites
CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety 80/10/10 5pp

DOCKET 70-0687 UNION CARBIDE CORP

8011080923 Advises that fee re approval of 801022 bypass route to spent fuel route originally approved in Feb 1980 will be assessed upon completion of review
WEISS, J.D. License Fee Management Branch 80/10/30 1p 06991 236

DOCKET 70-0698 WALTZ MILL SITE, WESTINGHOUSE ELECTRIC CORP

8010020739 Submits corporate info applicable to encl list of licensees. Forwards Annual Financial Rept 1979
DIPIAZZA, R.P. Westinghouse Electric Corp. 80/09/04, 5pp

--8010020745 Annual Financial Rept 1979
* Westinghouse Electric Corp 80/01/30, 5pp 03616 203

DOCKET 70-0734 GENERAL ATOMIC CO

8011060366 Forwards replacement summary page of IE Insp Rept 70-0734/80-09 on 800908-12, including insp team signatures
NORDEHAUG, L.R. Region 5, San Francisco, Safeguards Branch 80/10/09, 1p 06910 266

--8011060371 Replacement summary page to IE Insp Rept 70-0734/80-09 on 800908-12
NORDEHAUG, L.R. Region 5, San Francisco, Safeguards Branch
BROCK, B.L., KOBORI, L. Region 5, San Francisco, Office of the Director 80/10/09 1p 06910 267

DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO

801110741 Forwards Summary of a 771202 meeting re postulated Verona fault, 771209 NRC ltr to US Geological Survey requesting info on surface faulting Requests course of action planned to resolve surface faulting issue
SCHMIDT, A. Operating Reactors Branch 1 (Pre 790623) 77/12/14 2pp

--7812190026 Show Cause Order requiring that, upon completion of present operating cycle on 771027, the Gen Elec Test Reactor be placed & maintained safely in cold shutdown condition
Comments for OETR 771202 meeting encl
CASE, E.O. Office of Nuclear Reactor Regulation, Director, 77/10/24, 13pp

8011030009 Forwards DOE rept, RFP-3110, "Transuranic (TRU) Waste Mgt Program," re acceptance of commercial TRU waste TRU wastes exceeding 10 nanoCuries/g are no longer acceptable for disposal at operating shallow land disposal sites
CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety 80/10/10 5pp

DOCKET 70-0820 UNITED NUCLEAR CORP

8008130675 Responds to 800702 ltr re radionuclides found in groundwater under licensee property at Wood River Junction, RI Licensee is responsible for cost of decontaminating property IE will inspect facility during decommissioning process.
DIRCKS, W.J. Office of the Executive Director for Operations 80/07/29, 4pp 03266 155

8011100329 Forwards IE Insp Rept 70-0820/80-15 on 800827-28. No noncompliance noted
MARTIN, W.O. Region 1, Philadelphia, Safeguards Branch, 80/09/23 2pp. 06929 213

--8011100348 IE Insp Rept 70-0820/80-15 on 800827-28. No noncompliance noted. Major areas inspected: decommissioning activities
Details withheld (ref 10CFR2 790).
BISSETT, P.H., HOLLODY, D.J. Region 1, Philadelphia, Office of the Director
JOYNER, J.H. Region 1, Philadelphia, Safeguards Branch, 80/09/18 1p 06929 213.

8011030078 Immediate Action Ltr 80-35, confirms 801001 telcon commitments re lagoon sludge packaging requirements Company will not make radioactive matl shipments before taking preventative actions re presence of free-standing liquids
ORIER, B.H. Region 1, Philadelphia, Office of the Director 80/10/01, 1p 06895 143

8011210338 Ack receipt of response to IE Bulletin 80-15 re possible loss of emergency notification sys Response was not submitted under oath of affirmation Required oath must be submitted within 10 days
ORIER, B.H. Region 1, Philadelphia, Office of the Director 80/10/23 1p 07030 154

8011060266 PND-1-80-139C on 801028, Region 1 inspectors completed insp on contents of six trailers carrying low level radwaste in boxes & 55 gallon drums from United Nuclear Corp, Wood River Junction, RI Five containers out of 143 found leaking
KINNEY, W.W., BOREB, R.J. Region 1, Philadelphia, Office of the Director 80/10/28 1p 06911 167

801100049 Addl response to FOIA request, on behalf of Concerned Citizens of RI, for four categories of info re Facility NRC action has been completed on request.
FELTON, J.M. Division of Rules and Records 80/11/05, 1p 06928 250

8011240454 PND-1-80-164 on 801112, meeting held between NRC, State of RI, local citizens & reporter from Providence Journal to organize public meeting to discuss United Nuclear Corp radioactive matls shipping & decommissioning activities
KINNEY, W.W., CROCKER, H.W., SMITH, G.H. Region 1, Philadelphia, Office of the Director 80/11/13 2pp 07039 260

8011280201 Discusses planned mods to emergency notification sys & health physics network. NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys
ORIER, B.H. Region 1, Philadelphia, Office of the Director 80/11/14 2pp 07083 299

DOCKET 70-0824 BASCOCK & WILCOX CO

8011060179 Ack receipt of 800902 ltr providing assurance that B&W has sufficient capital to cover decommissioning costs
PAGE, R.Q. Uranium Recovery Licensing Branch 80/09/30 1p.

8011030009 Forwards DOE rept, RFP-3110, "Transuranic (TRU) Waste Mgt Program," re acceptance of commercial TRU waste TRU wastes exceeding 10 nanoCuries/g are no longer acceptable for disposal at operating shallow land disposal sites
CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety, 80/10/10 5pp 06897 021

8011100517 Revises Amend MPP-1 to License SNM-778, changing License Condition 2 1 re fundamental nuclear matl control plan.
PARTLOW, J.O. Material Control Licensing Branch 80/10/24 1p 06931 232

DOCKET 70-0882 COLUMBIA UNIV

8011250110 Forwards IE Insp Rept 70-0882/80-01 on 800806 & notice of violation
MARTIN, W.O. Region 1, Philadelphia, Safeguards Branch, 80/08/29, 2pp. 07056 249

--8011250114 Notice of violation from insp on 800806
* Region 1, Philadelphia, Office of the Director 80/08/27 1p. 07056 251

--8011250121 IE Insp Rept 70-0882/80-01 on 800806. Noncompliance noted. matl status repts not submitted every six months per requirement
COHEN, I., ZIBULSKY, H. Region 1, Philadelphia, Office of the Director, JOYNER, J.H. Region 1, Philadelphia, Safeguards Branch, 80/08/27 4pp. 07056 252

8011170259 Ack receipt of 800627, 0718, 0813 & 0919 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0882/78-01 & 70-0882/80-01.
MARTIN, W.O. Region 1, Philadelphia, Safeguards Branch 80/10/10 1p. 06968 323

--8011170266 Responds to NRC 800829 ltr re violations noted in IE Insp Rept 70-0882/80-01 Corrective actions forwarded in 800627 ltr to BH Orier.
LQRIO, P.M. Columbia Univ 80/09/19, 1p. 06968 324.

DOCKETED ITEMS

261

--8011170275 Apologizes for delay in answering NRC 800613 ltr re IE Insp Rept 70-0882/78-01 Requests in future that all ltrs be addressed to PM Lorio w/copies to JM Harding & PD Carter
CARTER, P D Columbia Univ 80/07/18 2pp 06968 325

--8011170278 Responds to NRC 800613 ltr re violations noted in IE Insp Rept 70-0882/78-01 Missing U-233 foils are probably disposed of in West Valley NY burial site
LORIO, P M Columbia Univ 80/08/13 2pp 06968 327.

--8011170284 Responds to NRC 800613 ltr re violations noted in IE Insp Rept 70-0882/78-01 Corrective actions source properly labeled & missing U-233 foils will be located Itemized source matl inventory encl w/o encl
LORIO, P M Columbia Univ 80/06/27 2pp 06968 329

--8011170288 Ack receipt of 800505 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0882/78-01. Complete physical inventory must be made to locate missing matl Evaluation of compliance encl
ORFIER, B H Region 1, Philadelphia, Office of the Director 80/06/13 4pp 06968 331

--8011170297 Responds to NRC 800331 ltr re violations noted in IE Insp Rept 70-0882/78-01. Corrective actions returned neutron source to engineering terrace & searching for lost matl Statement of source matl inventory encl.
LORIO, P M Columbia Univ 80/05/05 3pp 06968 335.

--8011170305 Requests response to 790204 ltr re IE Insp Rept 70-0882/78-01.
MARTIN, W J Region 1, Philadelphia, Safeguards Branch 80/03/31 1p. 06968 338

--8011170309 Forwards IE Insp Rept 70-0882/78-01 on 781130-1201 & notice of violation
MARTIN, W J Region 1, Philadelphia, Safeguards Branch. 79/02/06. 2pp 06968 339

--8011170314 Notice of violation from insp on 781130-1201
* Region 1, Philadelphia, Office of the Director 79/02/06 2pp 06968 341.

--8011170322 IE Insp Rept 70-0882/78-01 on 781130-1201 Noncompliance noted, source not stored in authorized area, annual source matl inventory not submitted & leak tests of U-233 foils not performed
JOVIER, J H Region 1, Philadelphia, Office of the Director
MARTIN, W J Region 1, Philadelphia, Safeguards Branch. 79/02/06 7pp 06968 343

DOCKET 70-0923 CIMARRON FACILITY, KERR-MCBEE CORP

8011280714 Discusses planned mods to emergency notification sys & health physics network equipment NRC will pay for installation of output jacks for adding one-way speakers to sys w/o encl health physics network manual
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/11/19 2pp 07083 303.

DOCKET 70-0997 WESTINGHOUSE ELECTRIC CORP

8010020739 Submits corporate info applicable to encl list of licensees Forwards Annual Financial Rept 1979
DIFIAZZA, R. P. Westinghouse Electric Corp 80/09/04. 5pp.

--8010020745 Annual Financial Rept 1979
* Westinghouse Electric Corp. 80/01/30. 51pp 03616 203

DOCKET 70-1027 ATOMIC ENERGY OF CANADA, CHALK RIVER NUCLEAR LAB

8002110367 Responds to 790927 ltrs requesting approval of routes for shipment of spent fuel from Chalk River Lab, via Ogdenburg, NY, to DOE Savannah River Plant Route approved. Route changed to bypass bridge w/weight limitation
MCCORRLE, G W Physical Security Development Branch. 79/12/05 2pp. 01946:126

DOCKET 70-1092 UNITED NUCLEAR CORP.

8010270112 Forwards May 1980 summary rept, "Aerial Radiologic Survey of United Nuclear Facility."
BORES, R. J. Region 1, Philadelphia, Office of the Director. 80/09/25. 1p. 06810 173.

--8010270115 "Aerial Radiological Survey of United Nuclear Facility," summary rept
MUELLER, J R, HAHN, H F E020, Inc WAMD-011 80/09/05 4pp 06810 174

8011200342 Forwards addendum to May 1980 summary rept, "Aerial Radiological Survey of United Nuclear Facility."
BORES, R J Region 1, Philadelphia, Office of the Director. 80/10/24 1p 07018 177

--8011200343 Addendum to "Aerial Radiological Survey of United Nuclear Facility"
* E020, Inc WAMD-011 ADD 80/10/24 5pp 07018 178

DOCKET 70-1100 COMBUSTION ENGINEERING, INC.

8011070484 Ack receipt of 800930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1100/80-05 & 30-03754/80-02
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/15 1p 06925 124

--8011070489 Responds to NRC 800904 ltr re violations noted in IE Insp Repts 70-1100/80-05 & 30-03754/80-02 Corrective actions: radiological control committee organized
LICHTENBERGER Combustion Engineering, Inc, C-E Minerals Div 80/09/30 1p. 06925 125

--8011070494 Forwards IE Insp Repts 70-1100/80-05 & 30-03754/80-02 on 800709-11 & notice of violation
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/04 2pp 06925 126

--8011070499 Notice of violation from insp on 800709-11.
* Region 1, Philadelphia, Office of the Director. 80/08/28 1p. 06925 128

--8011070505 IE Insp Repts 70-1100/80-05 & 30-03754/80-02 on 800709-11. Noncompliance noted failure to institute radiological control committee
CLEMONS, P Region 1, Philadelphia, Office of the Director
KNAPP, P J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/28 7pp 06925 129

DOCKET 70-1113 GENERAL ELECTRIC CO

8011060607 Ack receipt of Waste Packaging Insp Rept 15000039/80-15 on 800727-0801 No proprietary info
KAPLAN, A L General Electric Co, Nuclear Energy Products Div 80/10/07 1p. 06909 268

--8011060613 Forwards Waste Packaging Insp Rept 15000039/80-15 on 800727-0801. No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 2pp 06909 269

--8011060620 Waste Packaging Insp Rept 15000039/80-15 on 800727-0801. No noncompliance noted Major areas inspected: licensee-shipper vehicle for compliance w/shipping paper requirements, radiation levels & removable contamination
MACARTHUR, T C, POTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/16 8pp 06909 271.

8011060215 Ack receipt of IE Insp Rept 70-1113/80-16 on 800908-12 & approves NRC intention to withhold rept (ref 10CFR2 790).
KAPLAN, A L General Electric Co., Nuclear Energy Products Div 80/10/09 1p 06909 159

8011250002 Notices of IE 801117-18 site visit to review groundwater monitoring data & to assess adequacy of groundwater monitoring program Question guide encl
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/11/04 3pp. 07052 355

8011240511 Forwards summary of 801021 meeting in Atlanta. QA re activities authorized by License BNM-1097.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/11/06. 3pp 07047 018

8011200477 Ack receipt of 801031 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1113/80-17.
KENNA, W B. Region 2, Atlanta, Safeguards Branch. 80/11/12. 1p. 07020 141.

DOCKETED ITEMS

8011200481 Responds to NRC 800926 ltr re violations noted in IE Insp Rept 70-1113/80-17 Corrective actions withheld (ref 10CFR2 790)
KAPLAN, A L General Electric Co 80/10/31 1p 07020 142

8011200485 Forwards IE Insp Rept 70-1113/80-17 on 800908-11 Details & notice of violation withheld (ref 10CFR2 790).
KENNA, W B Region 2, Atlanta, Safeguards Branch. 80/09/26 2pp 07020 143

8011200489 IE Insp Rept 70-1113/80-17 on 800908-11. Noncompliance noted failure to include matl discarded as liquid effluents during matl balance period in limit of error calculation
Details withheld (ref 10CFR2 790)
JONES, D. W Region 2, Atlanta, Office of the Director. KAHLE, J B Region 2, Atlanta, Safeguards Branch 80/09/26 1p. 07020 145

CKET 70-1143 WESTINGHOUSE ELECTRIC CORP

10020739 Submits corporate info applicable to encl list of licensees
Forwards Annual Financial Rept 1979
PIAZZA, R. P Westinghouse Electric Corp. 80/09/04 5pp

8010020745 Annual Financial Rept 1979.
* Westinghouse Electric Corp 80/01/30 51pp 03616 203

11100359 Ack receipt of 800930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1143/80-10 & 30-06134/80-01.
SMITH, O. H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/10/09 1p. 06929 252

801100387 Responds to NRC 800904 ltr re violations noted in IE Insp Repts 70-1143/80-10 & 30-06134/80-01 Corrective actions instructed employees on termination repts. Future repts will be checked for completeness
MOORE, J B Westinghouse Electric Corp 80/09/30 3pp 06929 253

801100456 Forwards IE Insp Repts 70-1143/80-10 & 30-06134/80-01 & on 800723-25 & notice of violation
SMITH, O. H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/04 2pp 06929 256

801100457 Notice of violation from insp on 800723-25
* Region 1, Philadelphia, Office of the Director. 80/08/29 1p 06929 258

801100460 IE Insp Repts 70-1143/80-10 & 30-06134/80-01 on 800723-25. Noncompliance noted: required termination repts & required exposure info not submitted.
CLEMONS, P Region 1, Philadelphia, Office of the Director.
KNAPP, P. J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/29. 7pp 06929 259

1030009 Forwards DOE rept, RFP-3110, "Transuranic (TRU) Waste Mgt program." re acceptance of commercial TRU waste TRU wastes exceeding 10 nanoCuries/g are no longer acceptable for disposal at operating shallow land disposal sites
KUNNINGHAM, R E Division of Fuel Cycle & Material Safety 80/10/10. 5pp.

1280191 Discusses planned mods to emergency notification sys & health physics network NRC will pay for installation of output jacks to provide capability for adding one-way speakers to sys
RIER, B. H Region 1, Philadelphia, Office of the Director. 0/11/14 2pp. 07083 294

CKET 70-1151 WESTINGHOUSE ELECTRIC CORP

1030368 Forwards addl info to support 800407 request for amend to license SNM-1107, authorizing use of SNM in advanced waste treatment process Encl supersedes, in entirety, info transmitted by 800407 application
PIAZZA, R. P. Westinghouse Electric Corp 80/04/24 6pp 06671 294.

1020739 Submits corporate info applicable to encl list of licensees
Forwards Annual Financial Rept 1979
PIAZZA, R. P. Westinghouse Electric Corp 80/09/04. 5pp

11020745 Annual Financial Rept 1979.
* Westinghouse Electric Corp 80/01/30. 51pp. 03616 203.

801110165 Ack receipt of 800929 ltr re IE Insp 70-1151/80-25 on 800902-04
FOSTER, H Westinghouse Electric Corp 80/10/17 1p 06943 342

8011240591 Notifies of IE 801114 site visit to review groundwater monitoring data & to assess adequacy of groundwater monitoring program Question guide encl
STORR, J. P. Region 2, Atlanta, Office of the Director 80/11/04 3pp. 07049 089

8011180299 Ack receipt of 800630 ltr re extension of existing waste storage bldg Const covered by environ rept & may be conducted w/o license amend
PAGE, R O Uranium Fuel Licensing Branch 80/11/05 1p 06989 150

8011240431 Notifies of refund due from fee re Amend & to License SNM-1107.
MILLER, W O License Fee Management Branch 80/11/14 1p 07049 073

DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP

8011030039 Forwards DOE rept, RFP-3110, "Transuranic (TRU) Waste Mgt Program." re acceptance of commercial TRU waste TRU wastes exceeding 10 nanoCuries/g are no longer acceptable for disposal at operating shallow land disposal sites.
KUNNINGHAM, R E Division of Fuel Cycle & Material Safety. 80/10/10. 5pp

8011280214 Discusses planned mods to emergency notification sys & health physics network equipment NRC will pay for installation of output jacks for adding one-way speakers to sys W/o encl health physics network manual.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/19 2pp 07083 303.

DOCKET 70-1201 UF & CONVERSION FACILITY, BABCOCK & WILCOX CO

8011060179 Ack receipt of 800902 ltr providing assurance that B&W has sufficient capital to cover decommissioning costs
PAGE, R O Uranium Recovery Licensing Branch. 80/09/30 1p

8011040030 Ack receipt of 801009 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1201/80-11
KENNA, W B Region 2, Atlanta, Safeguards Branch 80/10/21 1p 06884 055.

--8011040036 Responds to NRC 800919 ltr re violations noted in IE Insp Rept 70-1201/80-11. Corrective actions addl personnel safety training instituted re need to maintain integrity of water baffling.
ZEFF, R W Babcock & Wilcox Co., Nuclear Material Div 80/10/09 2pp 06884 056

--8011040039 Forwards IE Insp Rept 70-1201/80-11 on 800826-29 & notice of violation
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 80/09/19 2pp. 06884 058

--8011040044 Notice of violation from insp on 800826-29.
* Region 2, Atlanta, Office of the Director 80/09/19 1p 06884 060

--8011040051 IE Insp Rept 70-1201/80-11 on 800826-29 Noncompliance noted failure to maintain baffling in place around svc water piping in pelletizing area
CORYELL, O. P Region 2, Atlanta, Office of the Director
KAHLE, J B Region 2, Atlanta, Safeguards Branch 80/09/19. 5pp 06884 061

8011240589 Notifies of IE 801112 site visit to review groundwater monitoring data & to assess adequacy of groundwater monitoring program Question guide encl
STORR, J. P. Region 2, Atlanta, Office of the Director. 80/11/04. 3pp. 07049 086

DOCKET 70-1207 NAVY, DEPT OF

8011180309 Confirms 801029 telcon re renewal application for License SNM-1147. License shall remain in effect until application for renewal of license finally determined
CROW, W T Uranium Fuel Licensing Branch. 80/11/05. 1p. 06989 151.

DOCKETED ITEMS

263

DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO , INC

8011060377 Forwards Amend MPP-2 to License SNM-1257 re physical protection requirements for SNM of low strategic significance
MCCORKLE, O W Physical Security Licensing Branch 80/09/12 2pp
06910 300

8011030100 Provides notarized 800707 ltr in response to WJ Cooley 800922 telcon informing that ltr had not been signed under oath or affirmation as required by IE Bulletin 80-13
EBTEY, H P Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/09/22 3pp 06837 129

8011030009 Forwards DOE rept, RFP-3110, "Transuranic (TRU) Waste Mgt Program," re acceptance of commercial TRU waste. TRU wastes exceeding 10 nanoCuries/g are no longer acceptable for disposal at operating shallow land disposal sites
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 80/10/10 5pp

8011000074 Addl response to FOIA request for documents re License ISNM-79005 from Exxon Nuclear Corp Forwards Apps A & B documents App A documents partially withheld confidential business info (ref FOIA Exemption 4 & 10CFR2 790)
FELTON, J M Division of Rules and Records 80/11/04, 4pp
06931 277

--801100096 Discusses procedures for safeguarding licensed SNM &/or security measures for physical protection of licensed facility. DOE & NRC nuclear matl transaction rept encl info withheld (ref 10CFR2 790)
SCHNEIDER, R A Exxon Nuclear Co , Inc (subs of Exxon Corp.) 80/06/27, 12pp

DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO.

8011030171 Response in opposition to State of IL 801015 motion to stay proceedings Requests permission to submit revised schedule by 801113, to make necessary changes & additions required under 10CFR72. Certificate of Bvc encl
SZHAJAKOWSKI, R , ROONEY, M A General Electric Co SZHAJAKOWSKI, R Mayer, Brown & Platt, 80/10/30 3pp, 06897 329

8011060432 Forwards GE 801023 ltr re physical security plan - Morrison operation Related correspondence
ROONEY, M A Mayer, Brown & Platt 80/10/30 2pp 06911 327

--8011060433 Forwards changes to physical security plan - Morris operation. Encl withheld per 10CFR2 790
DAWSON, D M General Electric Co 80/10/23 1p, 06911 329

8011050410 Request to file reply to Rorem 801024 response to GE 801009 motion for sanctions Rorem reply contained inaccuracies & implications
SZHAJAKOWSKI, R , General Electric Co, SZHAJAKOWSKI, R, Mayer, Brown & Platt, 80/10/31, 1p 06898 181.

--8011050411 Response in opposition to Rorem 801024 reply to GE 801009 motion for sanctions Motion for sanctions should be granted & Rorem should be dismissed from proceeding for disregard of ABLB orders & schedules Certificate of Bvc encl
SZHAJAKOWSKI, R , General Electric Co SZHAJAKOWSKI, R Mayer, Brown & Platt 80/10/31 5pp 06898 182.

801110587 Response in opposition to State of IL 801015 petition for hearing & consolidation re application for license amend Application will be withdrawn by 801114 due to mootness arising from 10CFR72 promulgation Certificate of Bvc encl.
SZHAJAKOWSKI, R , ROONEY, M A General Electric Co SZHAJAKOWSKI, R Mayer, Brown & Platt, 80/11/05 4pp, 06946 231.

8011000430 Response stating no objection to GE 801031 motion to reply re GE requests for sanctions against Rorem et al & State of IL Adheres to NRC 801029 response to GE motions for sanctions Certificate of Bvc encl
ROTHSCHILD, M U Hearing Branch 1, 80/11/07, 3pp 06929 310

801180037 Request to enter schedule for resumption of proceeding re State of IL 801030 motion to stay. Proposes 810112 for revisions of BAR, 810226 for amends to contentions & 810319 for responses thereto. Certificate of Bvc encl.
SZHAJAKOWSKI, R , ROONEY, M A General Electric Co SZHAJAKOWSKI, R Mayer, Brown & Platt, 80/11/13 3pp 06987 173

801190016 Forwards 801112 FR notice of 10CFR72 issuance per NRC commitment made in 801003 motion to set aside schedule for summary disposition.
BACHMANN, R O Hearing Branch 1, 80/11/14, 21pp, 06916 001.

DOCKET 70-1327 UF & CONVERSION FACILITY, ALLIED GENERAL NUCLEAR

8011040382 Responds to 801013 ltr transmitting J Courtney request for resumption of OESMO proceeding Comments will be taken into account in NRC review re proceeding
KAMMERER, C Office of Congressional Affairs 80/10/22 1p

DOCKET 70-1432 RECYCLE FUELS PLANT, WESTINGHOUSE ELECTRIC CORP

8010020739 Submits corporate info applicable to encl list of licensees Forwards Annual Financial Rept 1979
DIPIAZZA, R P Westinghouse Electric Corp 80/09/04 5pp

--8010020745 Annual Financial Rept 1979
* Westinghouse Electric Corp 80/01/30 51pp 03616 203

8011040382 Responds to 801013 ltr transmitting J Courtney request for resumption of OESMO proceeding Comments will be taken into account in NRC review re proceeding
KAMMERER, C Office of Congressional Affairs 80/10/22 1p

DOCKET 70-1470 VET ADMIN HOSP LOS ANGELES, CA

8011060205 IE Insp Findings & Licensee Ack dtd 800904 of License SNM-1440 Insp findings no items of noncompliance found
FONO, F T Region 5, San Francisco, Office of the Director 80/09/04 1p 06912 066

DOCKET 70-1503 WESTINGHOUSE R&D CENTER, WESTINGHOUSE ELECTRIC CORP

8010020739 Submits corporate info applicable to encl list of licensees Forwards Annual Financial Rept 1979
DIPIAZZA, R P Westinghouse Electric Corp 80/09/04 5pp

--8010020745 Annual Financial Rept 1979
* Westinghouse Electric Corp 80/01/30 51pp 03616 203

DOCKET 70-1810 WESTINGHOUSE ELECTRIC

8010020739 Submits corporate info applicable to encl list of licensees. Forwards Annual Financial Rept 1979
DIPIAZZA, R P Westinghouse Electric Corp 80/09/04 5pp

--8010020745 Annual Financial Rept 1979
* Westinghouse Electric Corp 80/01/30 51pp, 03616 203

DOCKET 70-1821 PLUT PROD FACIL , ALLIED GENERAL NUCLEAR SERVICES CORP

8011040382 Responds to 801013 ltr transmitting J Courtney request for resumption of OESMO proceeding Comments will be taken into account in NRC review re proceeding
KAMMERER, C Office of Congressional Affairs 80/10/22 1p

DOCKET 70-1840 GENERAL ELECTRIC CO

8011260238 Amend 3 to import license for GE extending expiration date to 840101.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/11/19 1p 07071 397

DOCKET 70-1966 TENNESSEE VALLEY AUTHORITY

801130010 Amend 1 to License SNM-1526, revising Item B A to allow possession of 10,000 g U-235, enriched to max of 10% U-235
PAGE, R G Uranium Fuel Licensing Branch 80/10/28 1p 06957 051

--801130013 Approves until 800926 application for Amend 1 of License SNM-1526 to allow possession of 10,000 g U-235, enriched to max of 10% U-235
STEVENSON, R L , CROW, W T Uranium Fuel Licensing Branch, 80/10/28 1p 06957 052

DOCKETED ITEMS

DOCKET 70-2116 LAWRENCE GENERAL HOSP LAWRENCE

801130177 Ack receipt of 800924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-01874/80-01 & 70-2116/80-01
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/08 1p 03727 058

--801130181 Responds to NRC 800902 ltr re violations noted in IE Insp Repts 30-01874/80-01 & 70-2116/80-01 Corrective actions documentation of dose calibrator checks is current. Personnel instructed to wear gloves when handling radioactive matl
NOYCE, A W Lawrence General Hosp Lawrence, MA 80/09/24 1p 03727 059

--801130184 Discusses IE Insp Repts 30-01874/80-01 & 70-2116/80-01 on 800723 & forwards notice of violation
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/02 2pp, 03727 060

--801130190 Notice of violation from insp on 800723 Noncompliance noted: daily checks of dose calibrator not performed after 800714
Gloves not worn routinely by nuclear medicine personnel while handling radioactive matl
* Region 1, Philadelphia, Office of the Director 80/09/02, 1p, 03727 062

DOCKET 70-2172 WESTINGHOUSE ELECTRIC CORP

8011260442 Application by Westinghouse to amend license extending validity until 830101
HERSCH, M M Westinghouse Electric Corp. 80/11/03 1p, 07073 096

DOCKET 70-2304 MEDICAL COLLEGE OF PENNSYLVANIA

801120011 Ack receipt of 800926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-03022/80-01, 30-12998/80-01 & 70-2304/80-01
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/14 1p 06952 148

--801120015 Responds to NRC 800908 ltr re violations noted in IE Insp Repts 30-03022/80-01, 30-12998/80-01 & 70-2304/80-01 Corrective actions: no unauthorized personnel to handle active matl; monthly surveys conducted in all labs
CLIFFORD, M C Medical College of Pennsylvania & Hosp. Philadelphia, PA 80/09/26, 1p 06952:149

--801120022 Discusses IE Insp Repts 30-03022/80-01, 30-12998/80-01 & 70-2304/80-01 on 800731 & forwards notice of violation.
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/08 2pp 06952, 150

--801120027 Notice of violation from insp on 800731 Noncompliance noted: individual worked w/20 mCi tritiated thymidine methyl prior to authorization No routine lab surveys performed since Apr 1980.
* Region 1, Philadelphia, Office of the Director 80/09/08 1p, 06952:152

DOCKET 70-2313 NUCLEAR FUEL SERVICES

8011040560 Forwards "Fifty-Eighth Quarterly Rept for Jul-Sept 1980," Replacement pages for last two repts also encl.
DUCKWORTH, J P Nuclear Fuel Services, Inc., West Valley Reprocessing Plant, 80/10/27 1p 06873, 297

--8011040567 "Fifty-Eighth Quarterly Rept for Jul-Sept 1980," * Nuclear Fuel Services, Inc., West Valley Reprocessing Plant, 80/10/27 11pp, 06873, 298

--8011040578 Forwards 57th quarterly rept for Apr-June 1980 (replacement pages) w/o encl
DUCKWORTH, J P Nuclear Fuel Services, Inc., West Valley Reprocessing Plant 80/07/18 1p, 06873, 307

801120313 Forwards info in response to NRC request for documentation of licensee actions re each concern identified in 800918 mgt meeting at Erwin plant. Info withheld (ref 10CFR2.790).
TAYLOR, C W Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.), 80/11/07, 1p, 06956:264

DOCKET 70-2314 GENERAL ELECTRIC CO

8011260242 Requests extension of export license expiration dates to 840101
WILSON, B D General Electric Co 80/11/13 1p 07071 361

DOCKET 70-2623 MCQUIRE SPENT FUEL POOL, DUKE POWER CO

8011050143 Order denying Carolina Environ Study Group 801006 motion to reopen record & rejecting NRC 801027 motion for extension re spent fuel transshipments
HILLER, M E Atomic Safety and Licensing Board Panel 80/10/31 2pp

8011060395 Initial decision denying until 780309 application for amend of SNM license authorizing transshipment of spent nuclear fuel from Oconee for storage in McGuire Initial decision shall constitute final action 45 days from issuance
HARD, C H Atomic Safety and Licensing Board Panel 80/10/31 103pp

8011070020 Notice of reconstitution of ASLB in license amend proceeding, consisting of AS Rosenthal, Chairman & JH Duck & RS Salzman, members
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 80/11/03 1p

801130310 Exceptions to ASLB 801031 initial decision due to errors in findings re application of segmentation decisions, inadequacy of NRC EIA & onsite spent fuel storage installation as preferred alternative w/certificate of Svc
KETCHEN, E O Hearing Branch 4 80/11/10 5pp 06958 312

801140504 Exceptions to ASLB 801031 initial decision which denied trans-shipment of spent nuclear fuel from Oconee to McGuire for storage purposes. Cites 28 ASLB errors. Certificate of Svc encl
MCQUARRY, J M Duke Power Co. 80/11/10 16pp.

DOCKET 70-2860 SOUTH CAROLINA ELECTRIC & GAS CO

8011060185 Amend 1 to License SNM-1834 changing expiration date to 820930 or upon conversion of CPPR-94 to OL
PADEER, O Uranium Recovery Licensing Branch 80/10/08 1p 06915 325

DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP POWER SYSTEMS

8011050002 Forwards addl info re facility environ rept requested in NRC 800610 ltr Addl distribution of info has been completed per NRC 800806 instructions.
DIPIAZZA, R P Westinghouse Electric Corp. 80/09/23, 1p, 02319 196

--8011050005 Forwards addl info supporting facility environ rept in response to NRC 800610 request
DIPIAZZA, R P Westinghouse Electric Corp 80/09/23, 1p 02319:196

--8011050010 Forwards addl info re environ rept in response to NRC 800610 ltr Info represents state-of-project estimates available at current level of facility planning & design.
CELLIER, F Westinghouse Electric Corp. 80/07/08 33pp 02319:196

--8011050016 "AL Nuclear Fuel Fabrication Plant Site Aquatic & Terrestrial Annual Summary Rept," Info re environ rept encl
NELSON, J L, WIESE, J H, BLYE, R W, R&M Consultants, Inc. 79/12/31, 300pp 02319 196

--8011050017 "Groundwater Resources of Autauga County, AL: Reconnaissance Rept,"
SCOTT, J C, Interior, Dept. of, JONES, W B Alabama, State of, 80/11/07, 100pp, 02319, 196

801120210 Joint motion for substitution of C Donelson for DL Allred as named intervenor Urges withdrawal of Allred to benefit of parties & public interest Certificate of Svc encl.
ALLRED, D L, DONELSON, C, Affiliation Unknown. 80/11/09, 5pp 06981:345

801180118 Petition to intervene in lieu of DL Allred States interest & good cause Affidavit & Certificate of Svc encl
DONELSON, C, Affiliation Unknown. 80/11/10 6pp 06987:188

DOCKETED ITEMS

26

8011200307 Forwards intervenor DL Allred 801001 addl proposed contentions re Westinghouse application for SNM license w/o encl
TURK;B E Hearing Branch 1 80/11/18 1p 01741 019

8011240184 Forwards 801010 ltr from JO Davis, NRC NMSS, to DL Allred, petitioner for leave to intervene w/o encl
TURK;B Hearing Branch 1 80/11/18 1p 07042 361

DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY

8011040191 Informs of approving fuel storage physical security plan submitted in 800529 ltr & as amended in 800814 & 29 ltrs. License will be amended to include license condition Plan must be fully implemented 30 days after receipt of ltr
MCCORKLE, O W Physical Security Development Branch 80/09/24 1p 06919 324

DOCKET 70-2913 TENNESSEE VALLEY AUTHORITY

801190707 Amend 2 to License SNM-1863, authorizing use of high density spent fuel storage racks for storage of new fuel assemblies
PAGE;R O Uranium Fuel Licensing Branch 80/10/31 1p 06996:232

--801190755 Safety evaluation recommending issuance of Amend 2 to License SNM-1863, permitting use of high density spent fuel storage racks for storage of new fuel assemblies
STEVENSON, R L ; CROW, W T Uranium Fuel Licensing Branch 80/10/31 2pp 06996.233

DOCKET 70-2936 MISSISSIPPI POWER & LIGHT CO

801190125 Submits review schedule for util 801001 application to amend license to permit possession & use of in-core detectors & receipt, storage, insp & transport of SNM
KETZLACH, N Uranium Fuel Licensing Branch 80/11/04 1p 06999-212

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0003 EXXON NUCLEAR CO , INC

801120618 Forwards XN-NF-439, Revision 2, QA program
NILSON, R Exxon Nuclear Co., Inc (subs of Exxon Corp), 80/10/10 1p 06993:183

--801120622 Revision 2 to QA program
* Exxon Nuclear Co., Inc (subs of Exxon Corp) XN-NF-439 R2 80/10/07 38pp 06993 184

8011230659 Forwards QA program approval for radioactive matl package
MACDONALD, C E Transportation Branch 80/11/17, 1p, 07068 207

--8011250664 QA program approval for radioactive matl package, 0003, Revision 1.
MACDONALD, C E Transportation Branch 80/11/17 1p 07068 208.

DOCKET 71-0018 NUCLEAR ASSURANCE CORP

801180768 Forwards Revision 1 to QA program, in response to NRC 800904 request for addl info
JOHNSON, C.R. Nuclear Assurance Corp 80/10/07 1p. 06991 318

--801180772 Revision 1 to QA program
* Nuclear Assurance Corp 80/10/07 22pp 06991 319

DOCKET 71-0024 HITTMAN NUCLEAR & DEVELOPMENT CORP

801180762 Forwards QA manual for cask use Requests that QA program be revised accordingly Also requests that conditions of program approval allow certain QA program changes w/o prior NRC approval.
ROWE, B B. Hittman Nuclear & Development Corp. (subs Hittman Corp.), 80/11/04, 2pp. 06985 123

--801180770 QA manual for cask use.
* Hittman Nuclear & Development Corp. (subs Hittman Corp.) HNDC-C-200 80/10/20 91pp 06985-123

DOCKET 71-0102 SOURCE PROD & EQUIP CO , INC

8011050546 Forwards request for addl info to be submitted in 30 days for review of 800929 application re approval of QA program
MACDONALD, C E Transportation Branch 80/10/21 2pp 06901 294

DOCKET 71-0112 NAVY, DEPT OF

801180493 Notifies that QA approval can be terminated. Radioisotope thermoelectric generators are no longer licensed
HENDRIX, G Navy, Dept of, Naval Facilities Engineering Command 80/10/29 1p 06913 001

DOCKET 71-0121 NEUTRON PRODUCTS, INC

801100245 Forwards Revision 4 of QA program, providing list of changes made to previously submitted Revision 3
SHEDIRA, C Neutron Products, Inc 80/10/17 3pp 06931:105

--801100249 Revision 4 of QA program
SHEDIRA, C ; RANBOHOF, J.A Neutron Products, Inc 80/10/16 15pp 06931:108

801170582 Forwards QA program approval for radioactive matl package
MACDONALD, C E. Transportation Branch. 80/10/31 1p. 06978 248

--801170584 QA program approval for radioactive matl package, 0121, Revision 1
MACDONALD, C E. Transportation Branch 80/10/31 1p. 06978:249

DOCKET 71-0164 MASSACHUSETTS INSTITUTE OF TECHNOLOGY

801170581 Forwards request for addl info to complete review of QA program
MACDONALD, C E Transportation Branch. 80/10/31, 3pp. 06978:245

DOCKET 71-0198 NUCLEAR FUEL SERVICES, INC

801120631 Forwards QA program for operations.
CLARK, J R. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co) 80/10/27, 1p 06993:028

DOCKET 71-0248 MONSANTO RESEARCH CORP

801100145 Forwards Pages 6 & 10 to Revision 5 of QA manual, NPD-BTD-001, which improves administration of QA program Requests expeditious approval.
TAYLOR, R R Monsanto Research Corp. 80/10/21 2pp 06931 140

--801100150 Revision 5 to QA manual, changing Pages 6 & 10
* Monsanto Research Corp. NPD-BTD-001 R5. 80/10/17. 2pp 06931 142

8011030226 Forwards QA program approval for radioactive matl package, Revision 2
MACDONALD, C E Transportation Branch 80/10/27 1p. 06857-229

--8011030232 QA program approval for radioactive matl package, 0248, Revision 2
MACDONALD, C E Transportation Branch 80/10/27 1p 06857:230

DOCKET 71-0325 CONSUMERS POWER CO

8011210602 Requests registration as user of Model 3364
HOFFMAN, D P. Consumers Power Co. 80/11/17 1p 07029.159.

DOCKET 71-0371 MODEL NNFD-10, UNIFIED NUCLEAR CORP.

8011070621 Forwards Addendum 1 to 800818 QA program.
DE GUZMAN, A S Navy, Dept. of 80/10/06 1p 06921 036.

--8011070623 Addendum 1 to QA program (organizational chart)
* Navy, Dept. of 80/10/06 1p. 06921-037.

DOCKETED ITEMS

8011120648 Forwards addl info for inclusion in QA program
SMITH, R H Navy, Dept of 80/10/22 1p 06953-270

--801120651 Forwards addl info for inclusion in QA program
DE GUZMAN, A S Navy, Dept of, Electronics Systems Engineering
Center, SC 80/10/06 1p 06953-271

--801120654 Revised organizational chart for QA program
+ Navy, Dept of, Electronics Systems Engineering Center, SC
80/10/06 1p 06953-272

DOCKET 71-0382 INTERIOR, DEPT OF, GEOLOGICAL SURVEY

801120657 Forwards revised QA Program for shipments of radioactive
materials in response to NRC 800929 ltr
RUSLING, D H, HARRANZING, A Interior, Dept of, Geological Survey
80/10/20 1p 03719-316

--801120661 Revised QA program for shipments of radioactive materials.
+ Interior, Dept of, Geological Survey 80/10/20. 12pp.
03719:317

801130081 Forwards QA program approval for radioactive matl package.
Revision 0
MACDONALD, C E Transportation Branch 80/11/05 1p 06957-312

--801130085 QA program approval for radioactive matl package 0382.
Revision 0
MACDONALD, C E Transportation Branch 80/11/05 1p 06957:313.

DOCKET 71-0395 NAVY, DEPT OF, NAVAL FACILITIES ENG. COMMAND

801180423 Forwards QA program approval for radioactive matl package.
Revision 0
MACDONALD, C E Transportation Branch. 80/11/05. 1p 06989-195.

--801180429 QA program approval for radioactive matl package 0395.
Revision 0
MACDONALD, C E Transportation Branch. 80/11/05 1p 06989-196

DOCKET 71-0397 TELEPHONE ENERGY SYSTEMS

8011050233 Forwards QA program approval for radioactive matl package
MACDONALD, C E Transportation Branch 80/10/14 1p 06912-320

--8011060240 QA program approval for radioactive matl package 0397.
Revision 0
MACDONALD, C E Transportation Branch 80/10/14 1p 06912-321.

DOCKET 71-0398 TEXAS A&M UNIV

8011030069 Submits QA program for shipping packages of unirradiated &
irradiated fuels Shipment to begin no later than Jan 1981
RANKALL, J D Texas A & M Univ 80/10/02. 1p. 06857-112

--8011030070 QA program for shipping packages.
* Texas A & M Univ 80/10/31 6pp 06857-113

8011210743 Forwards request for addl info re QA program for approval of
radioactive matl package
MACDONALD, C E. Transportation Branch 80/11/14 3pp. 07029:103.

DOCKET 71-0399 NORTH CAROLINA, STATE OF

8011030082 Forwards QA program for NC Dept of Transportation, Div of
Highways, Mats & Tests Unit
WAGNER, F T North Carolina, State of. 80/10/02 1p. 06857-121

--8011030089 QA program Organization chart encl
RUBISILL, G D North Carolina, State of. 80/06/30 5pp
06857:122

DOCKET 71-0400 NAVY, DEPT OF

801180407 Forwards QA program approval for radioactive matl package.
Revision 0
MACDONALD, C E Transportation Branch. 80/11/05 1p 06989-195

--801180415 QA program approval for radioactive matl package 0400.
Revision 0
MACDONALD, C E Transportation Branch 80/11/05 1p. 06989-188

DOCKET 71-9026 MODEL 8C-48-220, ATCOR, INC

801180367 Notification of registration as user of Model CNS-14-190.
MACDONALD, C E Transportation Branch 80/11/06 1p 06989-186

8011200771 Notification of registration as user of Models CNS
14-190, 6244 & HW-1005
MACDONALD, C E Transportation Branch 80/11/06 1p 07020-012

DOCKET 71-9059 MODEL URANY NIT-TNK, NUCLEAR FUEL SERVICES, INC

8011040566 Application for renewal of Certificate of Compliance 5039,
5442 & 6273 for Models Urany NIT-TNK, LA-36 & 48X, F, A, Y,
respectively
MICHEL, C J Nuclear Fuel Services, Inc. (subs of Getty Oil Co).
80/10/14 1p 06875-157

DOCKET 71-5086 MODEL UNC-2600, GENERAL ATOMIC CO.

801100294 Requests term, "drop forged lug," be discontinued in all
NRC-DDT shipping container terminology. Term is unnecessary
when bolt & ring are low carbon steel & attachment weld of
ring is only good workmanship Lug can be made commercially
KIRK, W F. United Nuclear Corp., Naval Products Div. 80/09/25 1p
06931-299

801100502 Comments on license 800925 ltr re deletion of drop forged
lugs requirement in Certificate of Compliance 5086. Submittal
fails to address type of closure ring proposed or
capability to meet code criteria for Model UNC-2600
MACDONALD, C E Transportation Branch 80/10/22 1p 06931-213

DOCKET 71-5442 MODEL LA-36, BABCOCK & WILCOX CO.

8011040566 Application for renewal of Certificate of Compliance 5039,
5442 & 6273 for Models Urany NIT-TNK, LA-36 & 48X, F, A, Y,
respectively
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co).
80/10/14 1p 06875-157

DOCKET 71-5768 MODEL BB-250-2, COMBUSTION ENGINEERING CO., INC.

8010240369 Consolidated application for renewal of Certificate of
Compliance 5768, authorizing use of BB-250-2 shipping
container Check to cover fee will be forwarded under
separate cover. Oversize drawings encl.
AUSTIN, M A Babcock & Wilcox Co., Nuclear Material Div 80/09/26
37pp 06808-188

DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CO

8011200705 Responds to 800725 ltr requesting addl info on GE Model 1500
shipping container Revised pages of BAR will be submitted
801031.
CUMMINGHAM, G E General Electric Co., Nuclear Energy Products Div.
80/10/14. 2pp 07021-271.

801100497 Approves 800922 request for registration as user of Model
GE-1500 Registration for Model F-168 packaging has been
denied
MACDONALD, C E Transportation Branch. 80/10/23 1p. 06931:210

801170883 Forwards Revision 6 to Certificate of Compliance 5939 for
Model GE-1500
MACDONALD, C E. Transportation Branch 80/10/31 2pp. 06979-270

--801170888 Certificate of Compliance 5939, Revision 6, for Model GE-1500
MACDONALD, C E Transportation Branch 80/10/31 3pp. 06979:272.

DOCKET 71-5980 MODEL GE-600, GENERAL ELECTRIC CO

801110822 Application for amend of Certificate of Compliance 5980,
changing max quantity of matl per package
CUMMINGHAM, G E. General Electric Co. 80/10/08 4pp. 06948-021.

DOCKETED ITEMS

267

DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR SYSTEMS, INC

8011200271 Notification of registration as user of Models CNS 14-190, 6244 & HN-1005
MACDONALD, C E Transportation Branch 80/11/06 1p 07020 012

DOCKET 71-6273 MODEL 48X, F. A. Y. ALLIED-GENERAL NUCLEAR SERVICES

8011040566 Application for renewal of Certificates of Compliance 5039, 5442 & 4273 for Models Urayu NIT-TNK, LA-36 & 48X, F. A. Y. respectively
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co.)
80/10/14 1p 06875 157

801180045 Forwards Revision 4 to Certificate of Compliance 6273 for Models 48A, 48X, 48F & 48Y
MACDONALD, C E Transportation Branch 80/11/06 2pp 06992 005

--801180846 Certificate of Compliance 4273, Revision 4, for Models 48A, 48X, 48F & 48Y
MACDONALD, C E Transportation Branch 80/11/06 3pp 06992 007

DOCKET 71-6294 MODEL UNC-2901, COMBUSTION ENGINEERING, INC.

8011200399 Notification of registration as user of Model UNC-2901.
MACDONALD, C. E. Transportation Branch. 80/11/06, 1p 07020 031

DOCKET 71-6386 MODEL 235R001, ENERGY, DEPT. OF

801190768 Forwards Revision 6 to Certificate of Compliance 6386 for Model 235R001
MACDONALD, C. E. Transportation Branch 80/11/07 1p 07001 187

--801190772 Certificate of Compliance 6386, Revision 6 for Model 235R001
MACDONALD, C. E. Transportation Branch 80/11/07, 4pp, 07001:186.

DOCKET 71-6400 MODEL: SUPER TIGER, WESTINGHOUSE ELECTRIC CORP

801120053 Application to amend Certificate of Compliance 6400, authorizing limited use for shipment of waste to Richland, WA & granting exemption from external pressure requirement
AUSTIN, M. A. Babcock & Wilcox Co., Nuclear Material Div. 80/10/17, 3pp. 06731:190

DOCKET 71-6568 MODEL LL-60-150, TVA

801180489 Application to amend Certificate of Compliance 6568 for TVA Model LL-60-150, clarifying weight limit of 12,500 lb
MILLS, L M Tennessee Valley Authority. 80/10/23 1p. 06991:230.

8011030201 Forwards Revision 2 to Certificate of Compliance 6568 for Model LL-60-150
MACDONALD, C. E. Transportation Branch. 80/10/24 2pp. 06857:234.

--8011030207 Certificate of Compliance 6568, Revision 2, for Model LL-60-150.
MACDONALD, C. E. Transportation Branch 80/10/24, 3pp. 06857:234.

DOCKET 71-6581 MODEL 51032-1 & 1A, EXXON NUCLEAR CO., INC.

801120618 Forwards XN-NF-439, Revision 2, QA program.
NILSON, R. Exxon Nuclear Co., Inc (subs. of Exxon Corp.), 80/10/10, 1p. 06953:183

--801120622 Revision 2 to QA program.
* Exxon Nuclear Co., Inc (subs. of Exxon Corp.), XN-NF-439 R2
80/10/07, 38pp, 06953:184.

801140532 Notifies that no addl fee is required for review of 790619 application for revision of Certificate of Compliance 6581.
MILLER, W. Q. License Fee Management Branch. 80/10/29, 1p. 06963:008.

DOCKET 71-6601 MODEL LL-50-100, CHEM-NUCLEAR SYSTEMS, INC

801190692 Requests registration as user of Certificate of Compliance 6601 for Model CNS 8-120
HAYNES, J O Southern California Edison Co 80/10/21 1p 06996 228

DOCKET 71-6679 MODEL 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO

801190602 Requests consolidated BAR for Model Half Super Tiger within 30 days.
MACDONALD, C E Transportation Branch 80/10/28 1p 06953.179

DOCKET 71-6698 MODEL NFB-4, NUCLEAR FUEL SERVICES, INC

8011070338 Application for amend to Revision 11 to Certificate of Compliance 6698, changing Paragraph 14 re assessment of stability of Model NAC-1 inner cavity. Chi-square test description encl
JOHNSON, C R Nuclear Assurance Corp 80/10/06 5pp 06919 319

--8011070350 Forwards graphs showing results of sensitivity of chi-square test as applied to Model NAC-1D. Chi-square test is capable of detecting cavity configuration changes representative of buckling.
JOHNSON, C R Nuclear Assurance Corp 80/10/02 2pp 06919:324.

--8011070355 Requests comment on draft application for amend of Certificate of Compliance 6698, replacing Paragraph 14 re spent fuel shipping cask inner cavity Chi-square test description encl.
JOHNSON, C R. Nuclear Assurance Corp. 80/09/30 6pp. 06919:326

8011060354 Forwards Revision 12 to Certificate of Compliance 6698, for Model NFB-4.
MACDONALD, C. E. Transportation Branch. 80/10/17 3pp. 06912:297.

--8011060362 Revision 12 to Certificate of Compliance 6698, for Model NFB-4
MACDONALD, C. E. Transportation Branch 80/10/17. 8pp. 06912:300.

801110632 Application to amend Revision 11 to Certificate of Compliance 6698, requiring periodic cask cavity measurements to verify cavity dimension conformance to Drawing E10080, Sheet 1, Revision 19
JOHNSON, C R. Nuclear Assurance Corp. 80/10/17 2pp 06944:338.

801190017 Application for renewal of Certificate of Compliance 6698: Revision 12 Check encl
JOHNSON, C R Nuclear Assurance Corp. 80/10/22, 1p. 06996 273

DOCKET 71-6722 MODEL: BS-33-180, TENNESSEE VALLEY AUTHORITY

801170132 Application for extension to Certificate of Compliance 6722 for Model BS-33-180
MILLS, L. M Tennessee Valley Authority. 80/10/28 1p 06981:362

DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC

8010220042 Application for Revision 7 to Certificate of Compliance 9010, to permit use of alternate personnel barrier arrangement. Revised pages & drawings & fee encl
DIXON, G N. NL Industries, NL Nuclear Div. 80/09/29, 9pp.

--8010220055 "Nat'l Lead Industries 1/2 Cask & Trailer, General Arrangement," Sheet 1
* NL Industries, NL Nuclear Div 80/09/24 1p.

--8010220071 "Nat'l Lead Industries 1/2 Cask & Trailer, General Arrangement," Sheet 2
* NL Industries, NL Nuclear Div 80/09/24, 1p.

801100770 Requests registration as user of Model NLI 1/2, Certificate of Compliance 9010
DAWSON, D. M. General Electric Co. 80/10/13, 1p. 06931:302.

DOCKETED ITEMS

DOCKET 71-9019 MODEL BU-7, GENERAL ELECTRIC CO

8011050197 Application for Mod 1 to Amend T-16 of application for Certificate of Compliance 9019 for Model GE BU-7, Refs to Drawing 11201592 revised
KAPLAN, A L General Electric Co, Nuclear Energy Products Div.
80/10/06 4pp 06909 154

--8011060204 "ASM Shipping Container Model BU-7,"
PADILLA, R General Electric Co, Nuclear Energy Products Div
80/10/06 1p 06909 158

DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO

8011190026 Requests registration as user of Certificate of Compliance 9044 for Model GE-1600
HAYNES, J. G Southern California Edison Co. 80/10/21 1p
06999 157

8011180003 Requests registration as user of Model CNSI 1-130.
SMEHIRA, C Neutron Products, Inc 80/10/28 1p. 06991 233

DOCKET 71-9057 MODEL: FPD 100, GENERAL ATOMIC CO

8011030213 Forwards Revision 2 to Certificate of Compliance 9037 for Model FPD-100.
MACDONALD, C E. Transportation Branch. 80/10/24 1p. 06897 231.

--8011030220 Certificate of Compliance 9037, Revision 2, for Model FPD-100.
MACDONALD, C E Transportation Branch 80/10/24. 2pp. 06897 232.

DOCKET 71-9070 MODEL N-55, ENERGY DEPT OF

8011100135 Forwards Revision 2 to application for Certificate of Compliance for Model N-55 App included re qualification drop test rept on hypothetical accident conditions for model
HANSSEN, L J Nuclear Packaging, Inc. 80/10/10 1p 06931 144.

--8011100139 Revision 2 to application for Certificate of Compliance for Model N-55
* Nuclear Packaging, Inc 80/10/10. 57pp 06931 145

8011260334 Forwards Revision 3 to Certificate of Compliance 9070 for Model N-55
MACDONALD, C E Transportation Branch. 80/11/14 2pp 07072 264.

--8011260340 Certificate of Compliance 9070, Revision 3, for Model N-55.
MACDONALD, C E Transportation Branch 80/11/14. 3pp 07072 266.

DOCKET 71-9074 MODEL: AP-100, ANEFCO, INC

8011170585 Notifies that Model ANEFCO AP-100 will be used for delivery of radioactive matl under Certificate of Compliance 9074.
FAV, C W Wisconsin Electric Power Co. 80/10/06 1p. 06979 208

DOCKET 71-9086 MODEL: HN-100 SERIES 1, HITTMAN NUCLEAR & DEVELOPMENT

8010310152 Application for Revision 3 of Certificate of Compliance 9086, changing drawings to reflect critical features of Model HN-100, Series 1 Lists of changes to drawings & addendum to SAR & fee encl
MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp). 80/10/07. 3pp 06868 001

--8010310162 Revision 1 to Addendum 1 of "SAR for HN-100, Series 1 Redwaste Shipping Cask"
* Hittman Nuclear & Development Corp (subs Hittman Corp.).
80/09/02 28pp 06868 006

DOCKET 71-9089 MODEL NH-100 B, HITTMAN NUCLEAR & DEVELOPMENT CORP

8011050018 Requests registration as user of Model NH-100 B.
ZULLA, B S. Power Authority of the State of New York. 80/10/06. 1p.
06893 360.

8011200271 Notification of registration as user of Models CNS 14-190, 6244 & HN-1005
MACDONALD, C E Transportation Branch 80/11/06 1p. 07020 012

DOCKET 71-9091 MODEL: 30 A, GENERAL ELECTRIC CO

8011180010 Forwards NRC 800513 notification of registration as user of Models 30A & 30B.
MCDONALD, Z D Transportation Branch 80/11/03 1p 06915 001.

--8011180013 Notification of registration as user of Models 30A & 30B in response to 800904 request
MACDONALD, Z D Transportation Branch. 80/05/13.
1p. 06915 001

DOCKET 71-9094 MODEL: CNSI-14-195-H, CHEM-NUCLEAR SYSTEMS, INC.

8011190032 Requests registration as user of Certificate of Compliance 9094 for Model CNSI-14-195-H.
HAYNES, J. G Southern California Edison Co 80/10/21. 1p
06999 161

DOCKET 71-9132 MODEL T-3, NUCLEAR PACKAGING, INC

8011040027 Forwards Revision 4 to "SAR for FFTF Fuel Pin Shipping Cask, Model T-3," providing generic statement re allowable limits for radiation source, fissile reactivity & density of fissile matl.
BINCHUK, J. D. Nuclear Packaging, Inc. 80/08/25 2pp. 06885 042.

--8011040029 "SAR for FFTF Fuel Pin Shipping Cask, Model T-3"
* Nuclear Packaging, Inc. 80/08/25. 44pp. 06885 044.

DOCKET 71-9136 MODEL: GE 9136, GENERAL ELECTRIC CO.

8011240438 Notifies of refund due from review fee for 790927 application to transport hoods & glove boxes containing low level solid radioactive matl
HILLER, W G. License Fee Management Branch 80/11/14 1p.
07049 074

DOCKET 71-9141 MODEL 900 TYPE B, TECHNICAL OPERATIONS, INC.

8011070628 Requests registration as user of Model 900.
VENEGAS, M. Venegas Industrial Testing Laboratories, Inc 80/10/06.
1p 06921 038.

8011200356 Notification of registration as user of Model 900.
MACDONALD, C E Transportation Branch. 80/11/06. 1p. 07020 050.

NONDOCKETED ITEMS

10GFR COMMISSION MEETING RECORDS

8010220274 Transcript of 800903 meeting re low power OL in Washington DC Pp 1-58
 * Commissioners 80/09/03 60pp 06778.171.

--8010220282 NUREG-0117 DRAFT
 Draft Suppl 4 to SER, NUREG-79/034, for facility Draft OL
 encl
 * Office of Nuclear Reactor Regulation, Director 80/09/28,
 177pp 06778.232

801030294 Transcript of 801021 meeting to discuss & vote on fire protection program in Washington, DC Pp 1-53 W/supporting documentation
 * Commissioners 80/10/21, 66pp 06865.043.

801030334 Commission determination dtd 801014 releasing transcript of Commission 790807 meeting, afternoon session re FY81 budget Pp 1-77
 * Commissioners. 79/08/07, 82pp 06865.140

801030025 Transcript of NRC 801028 meeting in Washington, DC re briefing on clarification on TMI action plan requirements Pp 1-87
 * Commissioners 80/10/28 90pp, 06897.111.

--801050028 Forwards summary listings of written comments received on 800705 preliminary clarification of TMI action plan requirements ltr, NRC response & impact on clarification package compiled by NUREG-0660 task action plan.
 BENTON, H. R. Office of Nuclear Reactor Regulation, Director, 80/10/24 19pp, 06897.201.

801050030 Transcript of NRC 801027 meeting in Washington, DC to discuss & vote on fire protection program Pp 1-43
 * Commissioners. 80/10/24, 43pp 06894.124.

--801050034 Forwards draft fire protection rule & statement of considerations proposed by NRC, revised pages, proposed immediately effective rule & possible subsection on tolling of specified completion on schedule
 BENTON, H. R. Office of Nuclear Reactor Regulation, Director, 80/10/24, 107pp, 06894.170

801050586 Transcript of 801030 briefing on criteria for emergency offsite facilities Pp 1-87
 * Commissioners 80/10/30 89pp 06892.267.

801050590 Transcript of 801030 Affirmation Session 80-47, Pp 1-2
 * Commissioners. 80/10/30 4pp 06893.013.

--801050592 BECY-80-486A
 Recommends 30-day extension of current relief from pat-down searches at power reactors to allow for Commission consideration of revised search procedures. Draft FR notice encl.
 DAVIS, J. O. Office of Nuclear Material Safety & Safeguards, 80/10/28 6pp, 06893.017

801070033 Transcript of NRC 801028 meeting in Washington, DC re OE, AIF & EPRI presentations on ATWS, Pp 1-71. Viewgraph presentations by DC Gibbs & GB Lellouche encl.
 * Commissioners. 80/10/28, 113pp 06924.060.

--801070041 Requests participation at Commissioners meeting when NRC position paper re ATWS is discussed. Proposed requirements in NUREG-0460, Vol 4 not necessary, considering BWR capability to mitigate using existing equipment & modified sys
 SHERWOOD, O. O. General Electric Co., Nuclear Energy Products Div, MFN-101-80, 80/08/21, 1p, 06924.178.

--801070047 Responds to 800521 ltr requesting participation in forthcoming Commission discussion of NRC position paper re ATWS Full discussion may require several sessions Schedule & time allotted for participation will be forwarded
 CHILK, S. J. Office of the Secretary of the Commission 80/07/08 1p 06924.179

--801070071 Extends invitation to OE, EPRI & AIF for participation in NRC 801028 open meeting in Washington, DC re ATWS Commission expects that participants will arrange allocation of available time.
 CHILK, S. J. Office of the Secretary of the Commission 80/10/23 1p 06924.182

--801070077 Extends invitation to OE, EPRI & AIF participation in NRC 801028 open meeting in Washington, DC re ATWS Commission expects that participants will arrange allocation of available time.
 CHILK, S. J. Office of the Secretary of the Commission 80/10/23 1p 06924.183

--801070078 Invites OE, EPRI & AIF participation in NRC 801028 open meeting in Washington, DC re ATWS Commission expects that participants will arrange allocation of available time
 CHILK, S. J. Office of the Secretary of the Commission. 80/10/23, 1p 06924.184

--801070085 Comments on proposed rulemaking to amend 10CFR50 re ATWS events & NUREG-0460 Issue can be resolved on fair & equitable basis, but w/o plant mods & schedule requirements recommended in BECY-80-409
 SHERWOOD, O. O. General Electric Co., Nuclear Energy Products Div MFN-183-80 80/10/24 8pp 06924.185.

801070613 Transcript of Affirmation Session 80-46 on 801023 in Washington, DC to discuss BECY-80-384A re fees for withdrawn CPs & OLs
 * Commissioners. 80/10/23 6pp, 06924.052.

801110031 Staff requirements memo informing of NRC requirements approved at 801023 Affirmation Session 80-46 in Washington, DC.
 CHILK, S. J. Office of the Secretary of the Commission. MB01023 80/10/27 2pp, 06944.102.

801110574 Transcript of 801031 meeting w/industry groups working on control room design questions in Washington, DC Pp 1-44
 Presentation by S Howell before NRC on 801031 encl
 * Commissioners 80/10/31 58pp, 06949.234

801120085 Transcript of 801103 Affirmation Session 80-49 re UCB policy statement in Washington, DC Pp 1-3
 * Commissioners. 80/11/03, 5pp, 06953.313.

801120089 Transcript of 800807 closed meeting in Washington, DC re Westinghouse turbine disc cracking, Pp 1-75.
 * Commissioners. 80/08/07, 76pp, 07015.267

--801120084 Commission determination releasing portions of transcript of 800807 closed meeting in Washington, DC re Westinghouse turbine disc cracking
 CHILK, S. J. Office of the Secretary of the Commission 80/11/07 1p, 07015.266.

8011200445 Forwards notice of Commission meetings during wk of 801013 to be published in 801015 FR.
 CHILK, S. J. Office of the Secretary of the Commission. 80/10/10, 1p 07018.239

--8011200452 Notice of Commission meetings during wk of 801013. Meetings re discussion of potential litigation & other responses to TMI-2 developments on 801006 & discussion of mgt-organization on 801009 were not held
 MAOER, H. Office of the Secretary of the Commission. 80/10/08 1p 07018.240.

NONDOCKETED ITEMS

8011200457 Forwards notice of Commission meetings during wks of 800929 & 1006 to be published in 801008 FR
CHILK, S J Office of the Secretary of the Commission 80/10/06.
1p 07018 237

--8011200461 Notice of Commission meetings during wks of 800929 & 1006
THEED, R M Office of the Secretary of the Commission. 80/10/03
1p. 07018 238

8011210008 Transcript of 801110 public meeting in Washington, DC re
inclusion of steam generator transients as Unresolved
safety issue Pp 1-39
* Commissioners. 80/11/10 42pp 07030 200

8011210185 Transcript of 801110 public meeting in Washington, DC re
ATWS policy Pp 1-34
* Commissioners. 80/11/10 56pp 07029 334

--8011210191 Offers critique for consideration re NRC position on ATWS
at 801028 briefing
HANRAHAN, E J Office of Policy Evaluations 80/11/07 8pp
07030 028

--8011210208 Forwards revised draft FR notice to SECY-80-409 re proposed
rulemaking to amend 10CFR50 on ATWS events Substitutes limit
on radioactivity source term as acceptance criteria for
radiological consequences
HINDQUE, R B. Office of Standards Development, Director 80/11/07
35pp 07030 036

8011210687 Forwards notice of Commission meetings during wk of 801006
in Washington, DC
CHILK, S J Office of the Secretary of the Commission. 80/10/03
1p. 07029 143

--8011210694 Notice of 801009 Commission meeting in Washington, DC
MAGEE, W Office of the Secretary of the Commission. 80/10/02
1p 07029 144.

8011240472 Transcript of 801114 public meeting in Washington, DC re
investigation of containment flooding event at Indian Point
2 & restart of Indian Point 3 Pp 1-156
* Office of Inspection & Enforcement, Office of the Director
80/11/14 156pp

--8011240486 SECY-A-80-179
Discusses proposed footnote re procedural issues for ASLP
to follow, due to investigative nature of proceeding
BICKWIT, L Office of the General Counsel 80/11/13 16pp

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

8008180461 Discusses ACRS Subcommittee on Regulatory Activities 800806
review of Revision 2 to Reg Guide 1.97 Reg guide not
endorsed by Committee due to need for clarification
Instrument classifications should be more explicit
PLESSET, M S ACRS - Advisory Committee on Reactor Safeguards
80/08/13. 3pp 06397 318.

8011030377 Transcript of Subcommittee on Transportation of Radioactive
Mats 801029 meeting in Washington, DC re review of
transportation certification process for package design.
Pp 1-136 Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 80/10/29
176pp. 06899:336

801110643 Transcript of 247th general meeting on 801106 in Washington,
DC, Pp 1-144 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 80/11/06.
185pp 06945-337

801110648 Transcript of Subcommittee on Regulatory Activities 801103
meeting in Washington, DC Pp 1-270, W/supporting
documentation.
* ACRS - Advisory Committee on Reactor Safeguards 80/11/07
360pp. 06948 231.

801130093 Notice of ACRS proposed meetings.
HOYLE, J. C. Office of the Secretary of the Commission 80/09/12.
5pp. 06938:258

801130097 Notice of ACRS Subcommittee on Safety Philosophy, Technology
& Criteria 800903 meeting in Washington, DC to review NRC
general approach to developing licensing requirements
HOYLE, J. C. Office of the Secretary of the Commission. 80/09/16.
2pp. 06937-354

801130100 Notice of procedures to be followed for ACRS meetings.
HOYLE, J. C. Office of the Secretary of the Commission 80/10/01
5pp 06937 356

801130102 Notice of ACRS Subcommittee on Waste Mgt 801003 meeting in
Washington, DC
HOYLE, J. C. Office of the Secretary of the Commission 80/09/12
2pp 06937.361

801130106 Notice of ACRS Subcommittee on Advanced Reactors 801008
meeting in Washington, DC to discuss proposals & schedules
for future subcommittee activities & role in development
of safety & research goals
HOYLE, J. C. Office of the Secretary of the Commission 80/09/16
2pp 06938 255

801130116 Notice of change of time & location for ACRS Subcommittee on
Advanced Reactor 801008 meeting in Washington, DC to discuss
proprietary info
HOYLE, J. C. Office of the Secretary of the Commission. 80/09/26
2pp 06937-317

801130120 Revised notice of ACRS 801009 & 10 meeting to discuss
nuclear power plant safety & regulation
HOYLE, J. C. Office of the Secretary of the Commission 80/09/26.
4pp 06937 319

801130147 Notice of ACRS Subcommittee on Extreme External Phenomena
801008 meeting in Washington, DC to discuss status of NRC
review of need for seismic qualification of auxiliary
feedwater sys.
HOYLE, J. C. Office of the Secretary of the Commission 80/09/16
2pp 06937 323.

801130151 Notice of ACRS Subcommittee on ECCS meeting on 801022-23 in
ID Falls, ID to review data from LOFT & semiscale programs on
reactor coolant pump trip
HOYLE, J. C. Office of the Secretary of the Commission 80/09/30.
2pp. 06938 264

801130157 Draft notice of ACRS 801009-11 meeting in Washington, DC
to discuss ACRS role in regulatory process
HOYLE, J. C. Office of the Secretary of the Commission. 80/10/31
7pp. 06938, 266

801140643 Schedule & outline of 247th ACRS 801106-08 meeting in
Washington, DC to discuss generic issues applicable to LWRs.
* ACRS - Advisory Committee on Reactor Safeguards 80/10/27. 4pp.
06963 265.

801180094 Summary of ACRS 245th meeting on 800904-06 in Washington, DC
Items considered included problems re hydraulic scram sys in
BWRs & proposed rept to Commission on quantitative risk
criteria.
PLESSET, M S ACRS - Advisory Committee on Reactor Safeguards
80/09/22 3pp 06987 323

801180101 Summary of ACRS 246th meeting on 801009-11 in Washington, DC
Items considered included rept on quantitative risk
acceptance criteria & proposed fire protection rule
PLESSET, M S ACRS - Advisory Committee on Reactor Safeguards.
80/10/27 3pp 06987-326

801190141 Schedule & outline of 246th ACRS meeting on 801009-11 in
Washington, DC
* ACRS - Advisory Committee on Reactor Safeguards. 80/09/30 4pp.
06999-219

801190344 Comments on 247th meeting on 801106-08 re Reg Guide 1.97,
Revision 2, "Instrumentation for Light-Water-Cooled Nuclear
Power Plants to Assess Plant & Environs Conditions During
& Following Accident."
PLESSET, M, BENDER, M ACRS - Advisory Committee on Reactor
Safeguards 80/11/10. 2pp 06999.360

801190374 Recommends addl research before commitment to specific sys
re nuclear data link Sys interface w/reactor instrumentation
may decrease reliability, as evidence that reactor sys is not
adversely affected has not been clearly demonstrated
PLESSET, M S ACRS - Advisory Committee on Reactor Safeguards
80/11/12 1p 06999 355.

801190376 Comments on Commissioner Gilinsky 801002 memo re format of
findings in ACRS repts on license applications in response
to request, ACRS conclusions have positive value, taking into
account variety of factors, including comparisons.
PLESSET, M S ACRS - Advisory Committee on Reactor Safeguards.
80/11/12 1p. 06996:190.

8011210060 Transcript of ACRB Subcommittee on Radwaste Mgt 801113 meeting in Washington, DC re proposed rulemaking on storage & disposal of nuclear waste & 1982 research budget for waste mgt Pp 1-167
* ACRB - Advisory Committee on Reactor Safeguards 80/11/13 181pp 07031 005

8011240055 Transcript of Subcommittee on Radwaste Mgt 801114 hearing in Washington, DC re proposed 1982 budget for research in disposal & storage of nuclear waste Pp 168-237
* ACRB - Advisory Committee on Reactor Safeguards 80/11/14 189pp 07039 060

8011240061 Transcript of Fluid Dynamic Subcommittee 801113 hearing in Burlingame, CA re nucleoside passive containment sys Pp 1-155
* ACRB - Advisory Committee on Reactor Safeguards 80/11/13 155pp 07040 064

8011260187 Transcript of ACRB Subcommittee on LERs 801120 meeting in Washington, DC Pp 1-276 Supporting documentation encl
* ACRB - Advisory Committee on Reactor Safeguards 80/11/20 500pp 07069 192

8011260189 Transcript of ACRB Subcommittee on Class 9 Accidents 801121 meeting in Washington, DC re NRC research program on degraded core cooling & rulemaking procedures Pp 1-63
* ACRB - Advisory Committee on Reactor Safeguards 80/11/21 79pp 07073:007

COMMISSION NRC COMMISSIONERS

8009100073 Discusses 800527 testimony by V Boyer, until senior vice president, re emergency planning NRC met w/Boyer on 800630 Boyer has committed to assuring that all until mgt levels have sincere commitment to effective emergency measures
AHEARNE, J F Commissioners 80/08/20 1p 06517 004

8010020403 Responds to 800727 ltr re available NRC expertise to assess adequacy of safety-related const at facility NRC has adequate in-house expertise to competently carry out effective insp program at facility
AHEARNE, J F Commissioners 80/09/02 2pp. 0361B 198.

8010290005 Requests Commission approval of encl clarification & changes to 800905 ltr & encl setting forth complete listing of TH1-related requirements approved for implementation Ltr & encls will be published as NUREG-0737 upon approval
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/10/22 10pp

--8010290014 Forwards comments on clarification of TH1 action plan requirements in response to 800905 ltr & 800926 meeting w/ NRC Long-term training requirements should be directly germane to job requirements of position
CLAYTON, F L Alabama Power Co 80/10/06 4pp. 06827.341

--8010290019 Forwards generic comments of BWR owner's group on NRC 800905 ltr re preliminary clarification of TH1 action plan requirements. Plant-unique comments are being transmitted via separate submittals
WATERS, D. B. Carolina Power & Light Co 80/10/08 16pp 06828.005.

8011070066 Weekly info rept for wk ending 801024
REHM, T A Office of the Executive Director for Operations 80/10/29. 34pp 06920 003

801110578 Responds to 800611 ltr re providing info to intervenors admitted to NRC proceedings info re specific facilities is routinely placed in LPDR near facility & in NRC PDR, Washington, DC.
AHEARNE, J F Commissioners 80/10/27 3pp 03719 253

--801110584 Requests info on NRC procedures for supplying intervenors w/ info & scheduling & recording of meetings
UDALL, M House of Rep., Interior & Insular Affairs. 80/06/11. 1p. 03719 255.

801120098 Accepts proposal to establish formal agreement for mutual exchange of info & cooperation on nuclear, radiological & security matters re American made plants. JD Lafleur nominated as US liaison to implement ltr of agreement.
AHEARNE, J F Commissioners 80/10/15. 1p 06953 242

801120108 Approves 810402 tentative date & arrangements for Spring forum on nuclear power, submitted in 800916 ltr Visit may include overnight stay
HENDRIE, J M Commissioners. 80/10/20. 1p. 06953 249

--801120113 Act receipt of 800909 ltr indicating willingness to participate in Spring forum Proposes 810402 tentative date & arrangements
WILLIAMS, B L Austin College 80/09/16 2pp 06953 246

801140653 Weekly info rept for wk ending 801031
REHM, T A Office of the Executive Director for Operations. 80/11/03 29pp 06963 284

801170426 Ack receipt of State Planning Council on Radwaste Mgt 800917 comments on proposed rule 10CFR60 re disposal of high level radwastes in geologic repositories NRC analysis of comments will be publicly available
AHEARNE, J F Commissioners 80/10/23 1p 06975 131

--801170437 Forwards State Planning Council on Radwaste Mgt comments on proposed rule 10CFR60 re disposal of high level radwastes in geologic repositories Effective means for participation of State, local & tribal govts urged
RILEY, R W Affiliation Unknown 80/09/17 8pp 06975 132

801170587 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p 06996 068

--801170588 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p 06996 069

--801170591 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p 06996 070

--801170592 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p 06996 071

--801170594 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20. 1p 06996 072

--801170596 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20. 1p 06996 073

--801170598 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p 06996 074.

--801170600 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p 06996 075

--801170602 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p 06996 076

--801170604 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p 06996 077

--801170606 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20. 1p 06996 078

--801170607 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners, 80/10/20 1p 06996 079

--801170608 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p. 06996 080

NONDOCKETED ITEMS

27

--B011170838 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p 06996 117

--B011170841 Forwards draft NUREG-0725, "Public Info Circular for Shipments of Irradiated Reactor Fuel " Document will be made available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p 06996 118

--B011170847 NUREG-0725 DRAFT
Draft "Public Info Circular for Shipments of Irradiated Reactor Fuel "
* Commissioners. 80/09/30 50pp 06996 119

B011170793 Memorandum of understanding between NRC & FEMA to define relationship in connection w/response to potential or actual radiological emergency
MACY, J W Federal Emergency Management Agency AHEARNE, J F Commissioners 80/10/22 7pp 06979 213

B011180198 Expresses appreciation for hospitality during trip to Copenhagen
HENDRIE, J M Commissioners 80/10/27 1p 06987 261

B011180201 Expresses appreciation for hospitality during trip to Loviisa
HENDRIE, J M Commissioners 80/10/27 1p 06987 262

B011180202 Expresses appreciation for hospitality during trip to Loviisa
HENDRIE, J M Commissioners 80/10/27 1p 06987 263

B011180208 Expresses appreciation for hospitality during trip to Copenhagen
HENDRIE, J M Commissioners 80/10/27 1p 06987 264

B011180211 Expresses appreciation for hospitality during trip to Vienna, for IAEA general conference
HENDRIE, J M Commissioners 80/10/27 1p 06987 265

B011180214 Expresses appreciation for hospitality during trip to Dampierre
HENDRIE, J M Commissioners 80/10/28 1p 06987 266

B011180218 Expresses appreciation for hospitality during trip to Helsinki.
HENDRIE, J M Commissioners 80/10/28 1p 06987 267

B011180220 Expresses appreciation for hospitality during trip to France
HENDRIE, J M Commissioners 80/10/28 1p 06987 268.

B011180223 Expresses appreciation for hospitality during trip to London
HENDRIE, J M Commissioners 80/10/29 1p. 06987 269

B011180225 Expresses appreciation for hospitality during trip to Harwell.
HENDRIE, J M Commissioners 80/10/29 1p 06987 270

B011180228 Expresses appreciation for hospitality during trip to Harwell.
HENDRIE, J M Commissioners 80/10/29 1p 06987 271

B011180231 Expresses appreciation for hospitality during trip to Bounreay facility
HENDRIE, J M Commissioners 80/10/29 1p. 06987 272.

B011180233 Expresses appreciation for hospitality during trip to Helsinki
HENDRIE, J M Commissioners 80/10/27 1p 06987 273.

B011180238 Expresses appreciation for hospitality during trip to London.
HENDRIE, J M Commissioners 80/10/27 1p 06987 274

B011180242 Expresses appreciation for hospitality during trip to Copenhagen
HENDRIE, J M Commissioners. 80/10/27 1p 06989 092.

B011180246 Expresses appreciation for hospitality during trip to Paris.
HENDRIE, J M Commissioners. 80/10/27 1p. 06989 093.

B011180254 Expresses appreciation for hospitality during trip to Loviisa nuclear station
HENDRIE, J M Commissioners 80/10/27 1p 06989 094

B011180255 Expresses appreciation for hospitality during trip to Paris
HENDRIE, J M Commissioners 80/10/27 1p 06989 095

B011180269 Forwards NRC comments on QAO rept re NRC plans addressing regulatory deficiencies highlighted by TMI accident. W/o encl
AHEARNE, J F Commissioners 80/10/29 1p 06989 096

--B011180274 Forwards NRC comments on QAO rept re NRC plans addressing regulatory deficiencies highlighted by TMI accident W/o encl
AHEARNE, J F Commissioners 80/10/29 1p 06989 097

--B011180277 Forwards NRC comments on QAO rept re NRC plans addressing regulatory deficiencies highlighted by TMI accident W/o encl
AHEARNE, J F Commissioners 80/10/29 1p 06989 098

--B011180282 Forwards NRC comments on QAO rept re NRC plans addressing regulatory deficiencies highlighted by TMI accident W/o encl
AHEARNE, J F Commissioners 80/10/29 1p 06989 099.

--B011180285 Forwards NRC comments on QAO rept re NRC plans addressing regulatory deficiencies highlighted by TMI accident W/o encl
AHEARNE, J F Commissioners 80/10/29 1p 06989 100.

--B011180289 Forwards NRC comments on QAO rept re NRC plans addressing regulatory deficiencies highlighted by TMI accident W/o encl.
AHEARNE, J F Commissioners 80/10/29 1p 06989 101

--B011180293 Forwards NRC comments on QAO rept re NRC plans addressing regulatory deficiencies highlighted by TMI accident W/o encl
AHEARNE, J F Commissioners. 80/10/29 1p 06989 102

--B011180301 Forwards NRC comments on QAO rept re NRC plans addressing regulatory deficiencies highlighted by TMI accident
AHEARNE, J F Commissioners 80/10/29 2pp 06989 103

B011180326 Discusses B00911 memo re new safety concepts for future const Further efforts focusing on new reactor design not advisable due to lack of expressed interest by industry
DIRCKS, W J Office of the Executive Director for Operations 80/10/24. 2pp 06992 039

--B011180329 Forwards Ope of Nuclear Reactor Research input to "New Safety Concepts for Future Const " Requests response
MURLEY, T E Division of Reactor Safety Research 80/09/22 3pp 06992 061

B011210165 Weekly info rept for wk ending B01107
REIM, T A Office of the Executive Director for Operations 80/11/13 40pp 07037 177

B011210210 Expresses appreciation for hospitality during trip to Paris & opportunity to visit EdF facilities at Dampierre
HENDRIE, J M Commissioners 80/10/27 1p 07030 101

B011210234 Informs that JM Hendrie will meet w/IH Bonnenberg in Washington, DC in early Dec
HENDRIE, J M Commissioners 80/10/31 1p 07030 104

--B011210242 Ack receipt of B00820 ltr expressing intention to present paper & requests meeting during first wk of Dec
BONNENBERG, H Bonnenberg & Drescher Ingenieurgesellschaft MBH 80/10/20 1p 07030 105

CONTRACT NRC CONTRACTS AND MODIFICATIONS

B011030110 Notification of contract execution, Mod 1 to "Evaluation of Efficiency & Effectiveness of Eleven Mgt & Program Analysis Mgt Info Products." Contractor, TRW Energy Sys Planning Div
WIGGINS, E Administrative Contracts Branch NRC-25-80-312. 80/09/17 1p. 06937 193

NONDOCKETED ITEMS

- 8011030115 Mod 1, revising delivery schedule for "Evaluation of Efficiency & Effectiveness of Eleven Mgt & Program Analysis Mgt Info Products " awarded to Hawley, C W TRW, Inc., Energy Systems Planning Div. MATTIA, M J Administrative Contracts Branch NRC-28-80-312 80/09/17 3pp 06857 194
- 8011030436 Notification of contract execution, Mod 9 to "Geophysical Investigation of Anna, OH Earthquake Region," awarded to Univ of MI JACOBS, A Research Contracts Branch FIN B-5345 NRC-04-76-192 80/10/17 1p 06857 014
- 8011030438 Mod 9, modifying Article III re govt property, to "Geophysical Investigation of Anna, OH Earthquake Region " awarded to MATTHEWS, C W Michigan, Univ of MORTON, K V Research Contracts Branch FIN B-5345 NRC-04-76-192 80/10/17 2pp 06857 015.
- 8011030440 Notification of contract execution, Mod 3 to "Nuclear Energy Ctr Workshops " Contractor Mitre Corp HAIRSTON, C Technical Assistance Contracts Branch NRC-02-75-127 80/10/16 1p 06857 017
- 8011030443 Mod 3, deobligating funds to "Nuclear Energy Ctr Workshops " awarded to MAHONEY, R C Mitre Corp DOUGHERTY, D J Technical Assistance Contracts Branch NRC-02-75-127 80/10/16 1p 06857 018
- 8011040170 Notification of contract execution "Subscription Svc," awarded to FH Faxon Co, Inc LEBOW, C D Administrative Contracts Branch NRC-10-80-669 80/10/17 1p 02319 196
- 8011040174 Contract: "Subscription Svc," awarded to FH Faxon Co, Inc * F W Faxon Co, Inc MATTIA, M J Administrative Contracts Branch NRC-10-80-669 80/10/17 7pp 02319 196.
- 8011060294 Notification of contract execution, Mod 1 to "Conversion of Microfilm Cartridges into 8 1/2-Inch x 11-Inch Paper Copies " Contractor Small Business Administration Subcontractor Automated Datatron, Inc WLOONINS, E Administrative Contracts Branch. NRC-10-78-409, 80/10/16 1p 06911 286
- 8011060296 Mod 1, deobligating funds under contract for "Conversion of Microfilm Cartridges into 8 1/2-Inch x 11-Inch Paper Copies " awarded to TUNSTALL, J E Small Business Administration MATTIA, M J Administrative Contracts Branch MARKS, C E Automated Datatron, Inc NRC-10-78-409 80/10/16 2pp 06911 287
- 8011000331 Notification of contract execution, "Establishing Critical Elements & Performance Stds," awarded to USDA Graduate School COLEMAN, R Administrative Contracts Branch NRC-10-B1-363 80/10/30 1p 06929 146.
- 8011000335 Contract. "Establishing Critical Elements & Performance Stds," awarded to USDA Graduate School * Agriculture, Dept. of MATTIA, M J Administrative Contracts Branch NRC-10-B1-363 80/10/30, 12pp 06929 147
- 801120640 Notification of contract execution, Mod 5 to "Consulting on Foreign Countries' Code Development Programs," Contractor P8 Andersen. WOLLETT, B A Research Contracts Branch FIN B-6300, NRC-04-79-177 80/10/29 1p 06950 322
- 801120644 Mod 5, providing continued work scope & funding, to "Consulting on Foreign Countries' Code Development Programs " awarded to ANDERSEN, P B P B Andersen MORTON, K V Research Contracts Branch. FIN B-6300 NRC-04-79-177, 80/10/29 3pp 06950 323
- 801120677 Notification of contract execution, Mod 1 to "Aeromagnetic Survey of Parts of Northeast AR," Contractor AR Geological Commission. BRODERO, B Research Contracts Branch FIN B-6790 NRC-04-79-213, 80/10/29, 1p 03720 256
- 801120681 Mod 1, extending period of performance from 800930 to 810101, to "Aeromagnetic Survey of Parts of Northeast AR " awarded to WILLIAMS, N F Arkansas, State of MORTON, K V Research Contracts Branch. FIN B-6790 NRC-04-79-213 80/10/29, 1p 03720 257
- 801140579 Notification of contract execution: "Technical Assistance to Working Group on Commission Waste Mgt Basis for Confidence Proceeding (Re Safe Waste Disposal)," awarded to Teknekron Research, Inc FLEENOR, C M Administrative Contracts Branch. FIN B-1314 NRC-19-81-491 80/10/28 1p 06963 219.
- 801140586 Contract "Technical Assistance to Working Group on Commission Waste Mgt Basis for Confidence Proceeding (Re Safe Waste Disposal)," awarded to Teknekron Research, Inc COHEN, S Teknekron, Inc PERLMAN, J Administrative Contracts Branch FIN B-1314, NRC-19-81-491 80/10/28 5pp 06963 220
- 801170105 Notification of contract execution, Mod 1 to "Classified Safeguards Program " Contractor ORI, Inc COLEMAN, R Administrative Contracts Branch NRC-10-80-369 80/10/31 1p 06976 318
- 801170113 Mod 1, deleting administrative requirement incumbent upon contractor to "Classified Safeguards Program " awarded to ORI, Inc MATTIA, M J Administrative Contracts Branch NRC-10-80-369 80/10/31 1p 06976 319.
- 801170129 Notification of contract execution "Technical Assistance to Support NRC IE Technical Personnel in Investigation of Incidents," awarded to Parameter, Inc BAIRDEN, L Research Contracts Branch FIN B-1013 NRC-05-80-251 80/10/23 1p 06981 338.
- 801170140 Contract: "Technical Assistance to Support NRC IE Technical Personnel in Investigation of Incidents," awarded to Parameter, Inc LOFV, R Parameter, Inc MORTON, K V Research Contracts Branch FIN B-1013 NRC-05-80-251 80/10/23 5pp 06981 339
- 801170360 Notification of contract execution, Mod 2 to "Transfer of Multi-Channel Tapes to 30 Minute Cassettes " Contractor Dictaphone Corp. WLOONINS, E J Administrative Contracts Branch NRC-10-79-398, 80/11/03 1p 06972 345
- 801170364 Mod 2, deobligating unliquidated balance of funds to "Transfer of Multi-Channel Tapes to 30 Minute Cassettes," awarded to CARTIER, B J Dictaphone Corp MATTIA, M J Administrative Contracts Branch NRC-10-79-398 80/11/03 2pp 06972 346
- 801170772 Notification of contract execution "Radiological Evaluation of Burial Grounds," awarded to Radiation Mgt Corp HAIRSTON, C Technical Assistance Contracts Branch FIN B-6901-0 NRC-02-80-034 80/08/13 1p 06915 001
- 801170777 Solicits offer to enter into ltr contract re "Radiological Evaluation of Burial Grounds," per NRC-02-80-034, DOUGHERTY, D J, Technical Assistance Contracts Branch NRC-02-80-034 80/08/13, 3pp 06915 001
- 801170781 Contract "Radiological Evaluation of Burial Grounds" awarded to Radiation Mgt Corp BRONSON, F L Radiation Management Corp DOUGHERTY, D J Technical Assistance Contracts Branch FIN B-6901-0 NRC-02-80-034 80/08/13 17pp 06915 001
- 801170787 Notification of contract execution, Mod 8 to "Technical Assistance in Reviewing Original Seismic Design Bases & Design Bases for Operating Plants," Contractor, NM Newark HAIRSTON, C Technical Assistance Contracts Branch, NRC-03-78-150, 80/10/07 1p 06968 268.
- 801170795 Mod 8, modifying scope of work, to "Technical Assistance in Reviewing Original Seismic Design Bases & Design Base for Operating Plants " awarded to NEWMARK, N M N. M. Newark Consulting Engineering Services. HALMAN, E L, Technical Assistance Contracts Branch NRC-03-78-150 80/09/30, 3pp 06968 269
- 801180062 Notification of contract execution: "Arbitration Hearing - Examine Facts in Employee Grievance, Hold Hearing, Make Written Rept W/Final & Binding Decision," awarded to J Stone FLEENOR, C M Administrative Contracts Branch NRC-10-81-361 80/11/03, 1p 06992 299
- 801180066 Contract: "Arbitration Hearing - Examine Facts in Employee Grievance, Hold Hearing, Make Written Rept W/Final & Binding Decision," awarded to J Stone STONE, J, Stone, J, (Arbitrator), PERLMAN, J Administrative Contracts Branch. NRC-10-81-361, 80/11/03 6pp 06992 300.
- 801180196 Notification of contract execution, Mod 1 to "Technical Assistance to Working Group on Commission Waste Mgt Basis for Confidence Proceeding (Re Safe Waste Disposal)" awarded to Teknekron Research, Inc FLEENOR, C M Administrative Contracts Branch. FIN B-1314, NRC-19-81-491, 80/10/28, 1p 06987 259.

--801180203 Mod 1, extending period of contract, to "Technical Assistance to Working Group on Commission Waste Mgt Basis for Confidence Proceeding (re Safe Waste Disposal) " * Teisberg, Inc. PERLMAN, J. Administrative Contracts Branch FIN B-1314 NRC-19-81-491 80/10/28 1p 06987 260

801180199 Responds to FOIA request for proposal submitted by Technology Development of CA, Inc in response to NRC-04-80-215 Forwards nonproprietary version of proposal FELTON, J. M. Division of Rules and Records. 80/11/13, 1p, 06987 305

--801180210 Nonproprietary response to NRC-04-80-215, "Development of Nuclear Reactor Plant Data Bank " Applicant proposes development of data bank structure that can accommodate all info required for safety analysis of LWR sys * Shannon & Wilson, Inc 80/04/11 23pp.

801180825 Notification of contract execution, Mod 4 to "Summary Discussion of Several Institutional Issues Re Establishment Under NRC Auspices of Security Force to Safeguard Special Matis Within US " Contractor Princeton Univ HAIRSTON, C. Technical Assistance Contracts Branch NRC-02-76-156 80/10/06. 1p 06988 252.

--801180841 Mod 4, closing out contract, to "Summary Discussion of Several Institutional Issues Re Establishment Under NRC Auspices of Security Force to Safeguard Special Matis Within US " SINFIOALLI, A. J. Princeton Univ. DOUGHERTY, D J Technical Assistance Contracts Branch. NRC-02-76-156. 80/10/06. 1p 06988 253.

801200188 Notification of contract execution, Mod 13 to "Document Control Sys " Contractor, Tera Advanced Sys Corp. LEBOW, C. D. Administrative Contracts Branch NRC-10-78-580 80/11/10. 2pp. 07021 240

--801200194 Mod 13, defining 800725 Mod 10, to "Document Control Sys. " FELTON, R. W. Tera Corp MATTIA, M J Administrative Contracts Branch NRC-10-78-580. 80/11/10. 3pp. 07021 241

801210006 Notification of contract execution, Mod 5 to "Career Counseling " Contractor, Binder, Elster, Mendelson & Wheeler, Inc. MCGOWAN, E. J. Administrative Contracts Branch. NRC-10-79-387 80/11/10. 1p 07030 198.

--801210013 Mod 5, increasing ceiling amount, to "Career Counseling. " * Binder, Elster, Mendelson & Wheeler, Inc NRC-10-79-387 80/11/10. 1p. 07030 199.

801210027 Notification of contract execution, Mod 8 to "Analysis of Fission Transport & Disposition Within LWRs Under Assumed Accident Conditions " Contractor Battelle Columbus Labs. BROMBERG, B. Research Contracts Branch. FIN A-4078. NRC-04-76-293-0 80/11/04. 1p. 07030 354.

--801210037 Mod 8, providing no cost extension, to "Analysis of Fission Transport & Disposition Within LWRs Under Assumed Accident Conditions " LUTE, F. J. Battelle Memorial Institute, Columbus Laboratories MORTON, K. V. Research Contracts Branch. FIN A-4078. NRC-04-76-293-0. 80/11/04 1p 07030 355.

801210072 Notification of contract execution, Mod 3 to "Add'l Logistical Support for Stanislaus Nuclear Project, Unit 1, Antitrust Hearings " Contractor: PO&E. COLEMAN, R. Administrative Contracts Branch. NRC-10-78-604. 80/11/10. 1p 07031 209

--801210104 Mod 3, extending period of performance, to "Add'l Logistical Support for Stanislaus Nuclear Project, Unit 1, Antitrust Hearings. " BENTON, R. P. Pacific Gas & Electric Co. MATTIA, M. J. Administrative Contracts Branch. NRC-10-78-604 80/11/10. 1p, 07031 210.

801230673 Notification of contract execution. "Newspaper Clipping Bvc. " awarded to Press Intelligence, Inc. FLYNN, M. J. Administrative Contracts Branch. NRC-10-81-357. 80/10/31. 1p. 02227 001.

--801230680 Solicitation, offer & award of "Newspaper Clipping Bvc. " to Press Intelligence, Inc. JOHNS, J. M. Press Intelligence, Inc MATTIA, M. J. Administrative Contracts Branch. NRC-10-81-357 80/10/31. 4pp. 02227 001

801230699 Notification of contract execution, Mod 1 to "Study & Review of Issues Concerning Equal Employment Opportunity at NRC. " Contractor CRC Education & Human Development, Inc. MEDROW, L. X. Administrative Contracts Branch FIN B-1325 NRC-03-80-502 80/11/10 1p 07068 249

--801230702 Mod 1, extending period of performance, revising time of delivery & increasing total cost of contract, to "Study & Review of Issues Concerning Equal Employment Opportunity at NRC. " OGDON, A. K. CRC Education & Human Development, Inc. MATTIA, M. J. Administrative Contracts Branch FIN B-1325 NRC-03-80-502 80/11/10 3pp 07068 250

801260001 Notification of contract execution, Mod 4 to "Union Carbide Uravan Mill Tailings Evaluation " Contractor Geotechnical Engineers, Inc. HAIRSTON, C. FIELDER, J. Technical Assistance Contracts Branch FIN B-6926 NRC-02-79-055 80/10/21. 1p 07075 185

--801260003 Mod 4, extending period of performance, to "Union Carbide Uravan Mill Tailings Evaluation " CASTRO, O. Geotechnical Engineers, Inc. DOUGHERTY, D J. Technical Assistance Contracts Branch FIN B-6926 NRC-02-79-055 80/10/21. 1p 07075 186

801260131 Notification of contract execution, Mod 1 to "Word Processing Svcs " Contractor Automated Correspondence Sys. Inc. COLEMAN, R. Administrative Contracts Branch NRC-10-80-702 80/11/13 1p 07074 290.

--801260136 Mod 1, providing add'l funding to continue effort, to "Word Processing Svcs. " * Automated Correspondence Systems, Inc. MATTIA, M. J. Administrative Contracts Branch. NRC-10-80-702. 80/11/13 2pp. 07074 291

DISCLOSURE FINANCIAL DISCLOSURE INFORMATION

801130094 Notifies that exemption from requirements of 10CFR 735-21 is granted interest in Union Carbide Corp pension fund will not affect integrity of svcs to NRC. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 80/10/23. 1p 06956 352

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

7910010092 Forwards data sheets for Portsmouth, VA to Savannah River, SC transport route. Info partially withheld (ref FOIA Exemption 4). BLACK, H. Physical Security Licensing Branch 79/07/05. 10pp

8004080069 Advises that route for transport of AECL spent fuels from Ogdensburg, NY to Dunbarton, NC must be changed due to local ordinance in Ogdensburg, NY. Proposes alternate route STUKENBROEKER NL Industries, NL Nuclear Div. 15807 80/03/11 2pp. 04529 255

8005130284 Notice of violation from insp on 781211-14 * Region 3, Chicago, Office of the Director. 79/02/01. 2pp.

8005140305 Appeals denial of FOIA request for info concerning NL Industries & route & radioactive content of proposed Canadian spent fuel shipments REBNIKOFF, M. Sierra Club. 80/04/11. 1p. 04954 281

8005270337 Responds to FOIA request for 9 categories of documents re radwaste shipments scheduled to enter US through Portsmouth, VA Info partially withheld: safeguarding procedures & security measures (ref FOIA Exemption 4). FELTON, J. M. Division of Rules and Records 80/05/16. 4pp.

--8005270692 Notifies that shipment of irradiated HTR fuel from Sweden is scheduled to arrive in Portsmouth, VA on 800208 aboard Atlantic Bomp. Provides details re shipper, receiver & carrier. Dates & times withheld (ref FOIA Exemption 4). RAVENSCROFT, N. Edlow International Co 15481. 80/02/04. 2pp

8006020268 Discusses 800417 meeting between representatives of Turbine Generator Disc Integrity Task Force & NRC re task force position on Category A units scheduled for insp. STIEDE, W. L. Commonwealth Edison Co. 80/05/27 1p. 05158 055.

8006030286 Forwards comments on NUREG-0460, Vol 4, re ATWS for LWRs. Committee on Reactor Licensing & Safety disagrees w/proposed resolution based on design requirements. Q1888, D. C. Atomic Industrial Forum. 80/05/27. 12pp. 05166 300.

NONDOCKETED ITEMS

- 8006300549 Responds to appeal of partial denial of FOIA request for NL Industries most recent approved spent fuel route plan. Appeal is denied. Info partially withheld surface transportation routes (ref FOIA Exemption 4 & 10CFR2.790).
DIRCKS, W. J. Office of the Executive Director for Operations
80/06/18 1p 05532 345
- 8007280343 Discusses IE Insp of Licenses 12-02752-03 & 08 on 800625-26 & forwards notice of violation.
KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 80/07/21 2pp 03019 348
- 8007280369 Notice of violation form insp on 800625-26 Noncompliance noted prescription doses & teletherapy treatments given w/o authorization & individuals receiving excess whole body exposure not properly notified.
* Region 3, Chicago, Office of the Director 80/07/21 4pp. 03019 330
- 8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREG-0625, "Rept of Biting Policy Task Force." Documents 6-8 & 13 are available in PDR. Forwards remaining documents.
FELTON, J. M. Division of Rules and Records 80/09/04 1p
- 8009190587 BECY-79-362
Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features.
MANGOUER, R. B. Office of Standards Development, Director. 79/06/04, 7pp
- 8011030127 Responds to FOIA request for documents re analyses of LERs for reactors which concerned assessment for determining precursors to core melt accidents. Final publication of ORNL/NUREG/NSIC-182 will be forwarded.
FELTON, J. M. Division of Rules and Records 80/10/29 1p 06855 186
- 8011030140 Forwards 800930 FOIA request & ORNL response NRC project leader is GE Edison, Div of Sys & Reliability Research.
COTTRELL, W. B. Oak Ridge National Laboratory. 80/10/08. 1p 06855 189.
- 8011030133 FOIA request for documents re analyses of LERs for reactors which concerned assessment for determining precursors to core melt accidents. WB Cottrell 801008 response encl.
DILLEHAY, W. Critical Mass Energy Project 80/09/30 2pp. 06855 187
- 8011030168 Responds to FOIA request for first record located containing info identifying date & authority by which NRC employee discarded 760324 issue of Weekly Highlights publication. Rept was destroyed before request was made.
FELTON, J. M. Division of Rules and Records 80/10/24 2pp. 06855 195.
- 8011030174 FOIA request for first record located containing info identifying date & authority by which NRC employee discarded 760324 issue of Weekly Highlights publication.
POWER, D. F. Affiliation Unknown 80/10/01 2pp. 06855 197
- 8011030195 Responds to FOIA request for nonproprietary version of winning proposal submitted in response to NRC RFP RS-08D-80-016. Forwards proposal.
FELTON, J. M. Division of Rules and Records. 80/10/28. 1p. 06855 216.
- 8011030216 Responses to NRC questions re proposal submitted in response to RFP RS-08D-80-016, "Disease Incidence Rates from Occupational Exposure to Hazardous Substances."
* Battelle Memorial Institute, Columbus Laboratories 80/09/10, 13pp
- 8011030225 Nonproprietary response to RFP RS-08D-80-016, "Disease Incidence Rates from Occupational Exposure to Hazardous Substances." Describes technical approach of project & mgt organization.
* Battelle Memorial Institute, Columbus Laboratories. RS-08D-80-016 80/05/19 73pp
- 8011030206 FOIA request for nonproprietary version of winning proposal submitted in response to NRC RFP RS-08D-80-016.
O'BRIEN, T. Rand Corp 80/09/30 1p. 06855:217.
- 8011030227 Responds to FOIA request for MJ Reaves 730104 ltr to RD Nininger & RD Nininger ltr to AR Matheson. Request has been forwarded to DOE for response. MJ Reaves 730104 ltr encl.
FELTON, J. M. Division of Rules and Records. 80/07/29. 1p. 06855:210
- 8011030233 Forwards MD Grant 800722 FOIA request. Requests response w/o encl.
FELTON, J. M. Division of Rules and Records 80/07/29 1p. 06855:211.
- 8011030247 Responds to request for current data re commercial purchases of natural U. Provides info re firm U concentrate purchase commitments & USOB being supplied for specific reactors.
REAVES, M. J. Gulf Energy & Environmental Systems 31478 79/01/04 3pp 06855 213
- 8011030239 FOIA request for MJ Reaves 730104 ltr to RD Nininger & RD Nininger ltr to AR Matheson.
GRANT, M. D. Pepper Hamilton & Sheets 80/07/22 1p 06855 212
- 8011030250 Responds to FOIA request for info re charges of hazardous practices against Rockwell Intl Corp/Rockwell Hanford Operations in storage & disposal of radwaste. Forwards App A documents. DOE may be contacted for addl info.
FELTON, J. M. Division of Rules and Records 80/10/22 2pp. 06855 221
- 8011030263 Extends invitation to testify on 791211 before Subcommittee on Environ & Public Works re federal nuclear waste mgt program. Requests responses to listed questions.
HART, M. D. Senate, Environment & Public Works 79/11/27. 2pp
- 8011030270 Notifies of 791211 tentative waste hearing before Senate Subcommittee on Environ & Public Works. NRC licensing of DOE facilities will be principle topic w/transportation of waste & away-from-reactor storage as secondary topics.
KAMMERER, C. Office of Congressional Affairs. 79/11/27 1p.
- 8011030273 Transcript of 791211 testimony before Senate Subcommittee on Environ & Public Works in Washington, DC re federal waste mgt program.
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards. 79/12/11 4pp
- 8011030254 FOIA request for info re charges of hazardous practices against Rockwell Intl Corp/Rockwell Hanford Operations in storage & disposal of radwaste.
RHYNE, S. W. Mullin, Connor & Rhyme 80/10/01. 2pp. 06855.223.
- 8011060109 FOIA request for info re radiation levels of plant environs & dump sites & radiation levels in nine listed places.
KASS, A. W. Affiliation Unknown. 80/10/13 1p 06914:357.
- 8011070545 Responds to FOIA request for all records re License 13-02752-03. Forwards documents listed in App A. Document B partially withheld, name of individual exposed to radiation (ref FOIA Exemption 6).
FELTON, J. M. Division of Rules and Records 80/10/31. 3pp
- 8011070556 Matl/Byproduct License 13-02752-03 for IN Univ is amended in its entirety per 790523 application. Amend 47 authorizes use of Groups I-VI byproduct matls, Xe-133, Au-198, I-125, tritium, Cs-137, Sr-90 & Am-241.
BOHYER, J. E. Licensing Management Branch 79/08/21. 6pp
- 8011070566 Matl/Byproduct License 13-02752-03 for IN Univ is amended per 800710 application. Amend 49 revises Condition 25, authorizing possession & use of matl described in Items 6, 7 & 8 of license in accordance w/790523 application.
COOPER, J. W. Licensing Management Branch. 80/09/17. 1p.
- 8011070568 IE Insp Rept 30-09792/80-01 on 800625. Noncompliance noted teletherapy treatments given w/o supervision of authorized user.
SCHULTZ, W. H. Region 3, Chicago, Office of the Director. 80/07/10 15pp
- 8011070572 IE Insp Rept 30-01690/80-01 on 800625. Noncompliance noted: failure to maintain training records, failure to perform dose calibrator constancy checks & four physicians doing brachy therapy did not have permits.
SCHULTZ, W. H. Region 3, Chicago, Office of the Director. 80/07/17 13pp.
- 8011070575 IE Insp Rept 30-01690/79-01 on 790201. Noncompliance noted: byproduct matl stored in area which lacks constant surveillance & immediate license control. Byproduct storage area was not posted w/radiation caution symbol & words.
PAUL, R. A., FAGLIARDI, J. A. Region 3, Chicago, Office of the Director. 79/03/05 6pp.
- 8011070590 Discusses IE Insp of Licenses 13-02752-03, 13-02752-08 & BUC-1217 on 800620-22 & forwards notice of violation.
ALLAN, J. M. Region 3, Chicago, Office of the Director. 77/07/26 2pp

NONDOCKETED ITEMS

277

- 8011070596 Notice of violation from insp on 800620-22
* Region 3, Chicago, Office of the Director 30-09792/77-01
77/07/24 1p
- 8011070582 IE insp Rept 30-01690/77-01 on 770620-22 Noncompliance
noted: two eye applicators containing nominal 50 & 100 mCi
8r-90 were not tested for leakage between 751120-761122.
DICEY, B B Region 3, Chicago, Office of the Director. 77/07/14
16pp.
- 8011070400 Discusses IE insp of Licenses 13-02752-03 & 13-02752-08 on
740813-15 & forwards description of violations Noncompliance
noted: no evaluations made of byproduct matl concentrations
released to unrestricted areas Draft insp findings encl.
KEPPLER, J O. Region 3, Chicago, Office of the Director 74/09/25.
24pp
- 8011070406 Discusses licensee health physics radiological safety
program Program has shown great improvement since previous
insp. Info partially withheld. name of individual exposed to
radiation (ref FOIA Exemption 6) W/supporting documentation.
MORETTI, E J Atomic Energy Commission 71/05/19 15pp
- 8011070410 Discusses IE insp of License 13-02752-03 on 700421-23 &
forwards notice of noncompliance
ORIER, B.H. Atomic Energy Commission. 70/06/12. 1p
- 8011070584 Notice of violation from insp on 700421-23 Supporting
documentation encl.
MARITTI, E J. Atomic Energy Commission. 70/06/12 19pp.
- 8011070551 FOIA request for all records re License 13-02752-03.
LAUDIG, B Rynearson & Laudig 80/08/25. 1p 06925/037.
- 8011070418 Responds to FOIA request for specifics & map of routes for
transportation of spent nuclear fuel as noted in 801025 NY
Times article. Forwards NUREG-0725, showing NRC approved spent
fuel shipment routes & Announcement 80-191. W/o encls.
FELTON, J.M. Division of Rules and Records. 80/11/05. 1p.
06921/033.
- 8011070623 FOIA request for specifics & map of routes for
transportation of spent nuclear fuel as noted in encl
801025 NY Times article
GROSSMAN, K Island Closeup News Service 80/10/25 2pp.
06921/034.
- 801100019 Responds to FOIA request for IE insp repts re Pharmatopex,
Inc facilities in Washington, DC & Detroit, MI. Forwards
documents listed in App A W/o encls
FELTON, J.M. Division of Rules and Records 80/11/04. 2pp
06928/244.
- 801100026 FOIA request for IE insp repts re Pharmatopex, Inc facilities
in Washington, DC & Detroit, MI.
MCDONALD, D D Nuclear Pharmacy, Inc 80/09/29. 1p 06928/246.
- 801100033 Responds to FOIA request for PSAR or PBIR & records re
design, siting &/or consideration of Taiwan Power Nuclear
Units 7 & 8. NRC has no documents equivalent to PSAR or PBIR
re foreign facilities. Forwards PA Bradford 801010 memo.
FELTON, J.M. Division of Rules and Records. 80/11/04 1p
06928/247
- 801100041 Requests legal basis for staff position that NRC may act on
license application prior to time contract is awarded.
Response required by 801031.
BRADFORD, P.A. Commissioners. 80/10/10 1p
- 801100036 FOIA request for PSAR or PBIR & records re design, siting &/
or consideration of Taiwan Power Nuclear Units 7 & 8
NERENBERG, A L. Center for Development Policy. 80/10/17 2pp
06928/248.
- 801100034 Responds to FOIA request for winning proposal submitted in
response to RFP RS-REB-80-192 Forwards nonproprietary
version of RS-REB-80-192, "Effective Peak Acceleration for
Nuclear Power Plant Design."
FELTON, J.M. Division of Rules and Records. 80/11/03. 1p
06931/260.
- 801100077 Forwards suppl to 800519 proposal for RS-REB-80-192,
"Effective Peak Acceleration for Nuclear Power Plant
Design " Includes response summaries for questions posed at
800804 meeting. Info partially withheld (ref 10CFR2.790).
1DR189, I.M. Woodward-Clyde Consultants, Inc. 80P213B. 80/08/14.
8pp.
- 801100083 Forwards nonproprietary technical proposal in response to
RFP RS-REB-80-192 "Effective Peak Acceleration for Nuclear
Power Plant Design."
1DR189, I.M. Woodward-Clyde Consultants, Inc 80P213B 80/05/19
1p
- 801100094 Nonproprietary response to RFP RS-REB-80-192, "Effective
Peak Acceleration for Nuclear Power Plant Design " Objective
is to develop recommendations for methods for selecting
design response spectra to characterize foundation motion
* Woodward-Clyde Consultants, Inc RS-REB-80-192 80/05/19
72pp
- 801100063 FOIA request for winning proposal submitted in response to
RFP RS-REB-80-192, "Effective Peak Acceleration for Nuclear
Power Plant Design "
WILLIAMS, D John A. Blume & Associates, Engineers (subs URS Corp.)
80/10/16 1p. 06931/261
- 801100074 Addl response to FOIA request for documents re License
18NM-79005 from Exxon Nuclear Corp. Forwards Apps A & B
documents. App A documents partially withheld. Confidential
business info (ref FOIA Exemption 4 & 10CFR2.790)
FELTON, J.M. Division of Rules and Records 80/11/04 4pp
- 801100082 Discusses confidential business info. A Kraft 800403 memo to
R Nilson re shipper-receiver data for Biblis B XN-1 encl
Info withheld (ref 10CFR2.790)
NILSON, R Exxon Nuclear Co., Inc (subs of Exxon Corp.).
80/05/08. 5pp
- 801100086 Discusses confidential business info Info withheld (ref
10CFR2.790).
NILSON, R. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
80/05/20. 1p
- 801100112 Responds to 800908 & 20 requests for approval of procedures
for determination of receivers values for U hexafluoride
from foreign suppliers Proposed procedures are acceptable.
Info withheld (ref 10CFR2.790 & FOIA Exemption 4)
PARTLOW, J.Q. Material Control Licensing Branch 80/05/22. 2pp.
- 801100123 Lists additions & revisions to NMEB review section &
coordination statement re proposed License 18NM-79005 for
import of low enriched U from USSR
SHERR, T.B. Material Control & Accountability Development Branch.
79/04/06 1p.
- 801100541 Responds to FOIA request for documents re spent radioactive
fuel routes passing through CO. Forwards NUREG-0725 showing
NRC-approved routes for shipment of spent nuclear reactor
fuel & NRC Announcement 80-191 W/o encls
FELTON, J.M. Division of Rules and Records 80/10/31. 1p.
06931/233
- 801100573 FOIA request for documents re spent radioactive fuel routes
passing through CO.
EKBROM, A L Business Organized for a Safe Society 80/10/06. 1p.
06931/234
- 801101038 Responds to FOIA request for memo between NRC & predecessor
agencies concerning processing of reactor fuel at United
Nuclear Recovery Bys since 1972 NRC has no records subj to
request.
FELTON, J.M. Division of Rules and Records. 80/11/06. 1p.
06943/121.
- 801101032 FOIA request for memo between NRC & predecessor agencies
concerning processing of reactor fuel at United Nuclear
Recovery sys since 1972
VERRECCHIA, P Rhode Island Public Interest Research Group.
80/10/08. 1p. 06943/122.
- 801101039 Responds to appeal of denial of FOIA request for info re
route for spent fuel shipments from Chalk River, Canada to
SC. Grants appeal Forwards previously withheld five pages.
DIRCKS, W.J. Office of the Executive Director for Operations
80/11/07 1p 06945/097
- 8011010340 "Road Transportation Routes - Ogdensburg, NY to Savannah
River, SC."
* Commissioners. 80/11/07 11pp
- 801104061 Addl response to FOIA request for radiation levels of plant
environs & dump sites & radiation levels in nine listed
places. NRC has no further info or documents subj to request.
Addl info may be sought from EEOG, Inc & EPA.
FELTON, J.M. Division of Rules and Records. 80/11/10 1p.
06963/314

NONDOCKETED ITEMS

801170907 Addl response to FOIA request for documents re NRC consideration of facility licensing & transcripts re closed Commission meetings Forwards App A & B documents. Documents partially withheld (ref FOIA Exemptions 3 & 4)
FELTON, J. M. Division of Rules and Records. 80/11/06. 4pp

--801170943 SECY-79-650

Provides alternatives for Commission policy on safeguards regulations of highly enriched U activities at facility
Recommends approval of Alternative D. Info partially withheld (ref FOIA Exemptions 3 & 4).
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards 79/12/11 12pp.

--801170948 SECY-79-650A

Recommends that Commission approve highly enriched U activities at facility for single operating period following implementation of safeguards improvements outlined in SECY-79-650 Info partially withheld (ref FOIA Exemption 3)
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards 80/01/02 4pp.

801180032 Responds to FOIA request for all NRC documents re 800919 titan missile silo explosion in Damascus, AR. NRC has no documents suby to request. Nuclear weapons activities fall under jurisdiction of DOE & DOD.
FELTON, J. M. Division of Rules and Records. 80/11/04. 1p. 06986 123

801180038 FOIA request for all NRC documents re 800919 titan missile silo explosion in Damascus, AR.
WELLS, G. Z. Berman & Olanque. 80/10/16 1p. 06986 124.

801180057 Responds to FOIA request for listing of all commercial & military spent fuel routes in IN. Forwards App A summarizing requested commercial routes. No info available re military spent fuel routes
FELTON, J. M. Division of Rules and Records. 80/11/05. 2pp. 06984 192

801180061 FOIA request for listing of all commercial & military spent fuel routes in IN
CAMERON, D. M. Indiana Public Interest Research Group, Inc. 80/08/06. 1p. 06984 194

801180159 Responds to FOIA request for winning proposal in response to RFP-RES-80-214 "Evaluation of Ecosystem Simulation Models as Tools for Assessment of Power Plant Impact on Fish Populations." Forwards nonproprietary version of proposal.
FELTON, J. M. Division of Rules and Records. 80/11/12. 1p. 06987 293

--801180165 Nonproprietary response to RFP RS-RES-80-214, "Evaluation of Ecosystem Simulation Models as Tools for Assessment of Power Plant Impacts on Fish Population." Proposed research will compare & evaluate current aquatic simulation models
SHWARTZMAN, G. L., CHAPMAN, D. O. Washington Univ. of RS-RES-80-214. 80/04/22 49pp

--801180171 Forwards mods to technical & cost proposal submitted in response to RFP RS-RES-80-214, "Evaluation of Ecosystem Simulation Models as Tools for Assessment of Power Plant Impact on Fish Populations."
BALDWIN, D. R., SHWARTZMAN, G. Washington Univ. of, 80/09/04. 3pp.

801180161 FOIA request for winning proposal submitted in response to RFP RS-RES-80-214, "Evaluation of Ecosystem Simulation Models as Tools for Assessment of Power Plant Impact on Fish Populations."
MOORE, S. F. Resource Management Associates. 80/10/21. 1p. 06987 294

801180199 Responds to FOIA request for proposal submitted by Technology Development of CA, Inc in response to NRC-04-80-215 Forwards nonproprietary version of proposal.
FELTON, J. M. Division of Rules and Records. 80/11/13. 1p. 06987 305.

--801180210 Nonproprietary response to NRC-04-80-215, "Development of Nuclear Reactor Plant Data Bank." Applicant proposes development of data bank structure that can accommodate all info required for safety analysis of LWR sys.
* Shannon & Wilson, Inc. 80/04/11 25pp

801180204 FOIA request for proposal submitted by Technology Development of CA, Inc in response to NRC-04-80-215, "Development of Nuclear Reactor Plant Data Bank."
MCQUEEN, D. J. Shannon & Wilson, Inc. 80/10/20. 1p. 06987 306.

801180272 FOIA request for OE "Reed Rept" & excerpt re 27 safety-related issues
BRAUN, M. Affiliation Unknown 80/01/22. 1p. 06986 025.

801180347 Responds to FOIA request for winning proposal in response to RFP RS-RES-80-214, "Assessing Usefulness of Simulation Models in Determining Impact of Nuclear Power Plants on Fish Populations." Forwards nonproprietary version W/O encl.
FELTON, J. M. Division of Rules and Records 80/11/13 1p 06991 165

801180354 FOIA request for winning proposal submitted in response to RFP RS-RES-80-214, "Assessing Usefulness of Simulation Models in Determining Impact of Nuclear Power Plants on Fish Populations."
SIEMENS, W. D. Martin Marietta Corp 80/10/27 1p 06991 166.

801180360 Responds to FOIA request for proposal submitted by Woodward-Clyde Consultants under RFP RS-RES-80-192, "Effective Peak Acceleration for Nuclear Power Plant Design." Forwards nonproprietary version of proposal W/O encl.
FELTON, J. M. Division of Rules and Records. 80/11/14. 1p. 06991 176

801180369 FOIA request for proposal submitted by Woodward-Clyde Consultants under RFP RS-RES-80-192, "Effective Peak Acceleration for Nuclear Power Plant Design."
HART, R. B. Sierra Geophysics, Inc 80/11/07. 1p. 06991 177.

GEN TEC IS GENERIC TECHNICAL ISSUES

801180382 Responds to 800820 request re status of Task action plan A-44 in light of ASLAB decision re St Lucia 2 Longer term portions of plan involve extensive use of reliability & risk assessment studies
DIRCKS, W. J. Office of the Executive Director for Operations. ALAB-603 80/09/26 2pp 06865 112

--801180381 Task action plan A-44, "Station Blackout."
* Office of Nuclear Regulatory Research, Director 80/09/26. 21pp 06865 114.

801180060 Notification of 80112 meeting w/EPRI in Bethesda, MD to discuss program for resolution of unresolved safety issues A-12 fracture toughness issue.
SNAIDER, R. P. Generic Issues Branch 80/10/17. 1p. 06929 331

IE INSPECTION AND ENFORCEMENT

8006190085 IE Info Notice 80-36, "Failure of Steam Generator Support Bolting."
* Office of Inspection & Enforcement, Office of the Director. 80/09/10 0.

800820248 IE Bulletin 79-01 Suppl 3, "Environ Qualification of IE Equipment."
* Office of Inspection & Enforcement, Office of the Director 80/10/24. 2pp. 06996 065.

801160272 PNO-IV-80-38 on 801023, fire occurred at Mineral Exploration U Mill final product processing area. Portion of mill was still under const & had processed no matl. Fire caused by welding operations
BROWN, G. D. Region 4, Dallas, Office of the Director. 80/10/24. 1p. 06911 166

801110364 PNO-I-80-158 on 801029, during testing of new hose reel connection, hose reel isolation valve leaked approx 900 gallons of fresh water. No damage found
KENNY, T. J. Region 1, Philadelphia, Office of the Director. 80/10/30. 1p.

801110371 PNO-I-80-160 on 801103, approx 8,000 gallons of non-radioactive svc water spilled on containment floor. Svc water leaking from isolation valve, SHN44-1, backed up through fan cooler 22 & flowed from open flange spool piece.
GREENMAN, E. Region 1, Philadelphia, Office of the Director. 80/11/04. 1p

801110376 PNO-I-80-159 on 801031, during full power operation, Target Rock relief valve opened & failed to reseat. Manual scram was initiated & reactor is being cooled down via main condenser. Valve reclosed at 340 psi w/reactor stable. Cause unknown
JOHNSON, J. Region 1, Philadelphia, Office of the Director. 80/10/31. 1p.

801140370 PNO-TM1-80-050 on 801104, fire discovered in trailer on Unit 2 side of site. Trailer located outside protected area, but inside owner-controlled fences approx 20 yards from onsite NRC complex. Trailer sustained heavy smoke & water damage.
CONTE, R. J. NRC Three Mile Island Task Force. 80/11/07. 2pp. 06960 340

NONDOCKETED ITEMS

279

801190058 PNA-80-37 on 801114, State of OR informed NRC that individual attempted to sell radium needles to proprietor of Ardwerks Guns & Trade Ctr, Bend, OR. States of OR, NV, CA, ID & WA will issue notice to all radium licensees for inventory. LUBENAU, J. O., BOLLINO, L. A. Office of State Programs, Director 80/11/17, 1p 07001:294

801190068 PNA-80-38, on 801117, State of AL informed NRC that state licensee had reported technetium generator Mo-99 breakthrough during first elution on 801117. Generator was Squibb Model 1330 calibr 801115 Generator pulled from svc. LUBENAU, J. O., KENDIG, J. F. Office of State Programs, Director 80/11/17, 1p 07001:293

8011240459 PND-I-80-165 on 801116, during Startup, 0.5 Ci release occurred. Increases in recombiner room & roof vent radioactivity monitors noted w/ slight increase in air ejector exhaust pressure. Caused by blown loop seal. COHILL, L. C. Region 1, Philadelphia, Office of the Director 80/11/17, 1p

8011240468 PND-I-80-166 on 801116, plant emergency declared upon receipt of radiation alarm during transfer of spent resin from deborating ion exchanger. Caused by partially open discharge valve. Max noble gas release was 9% of limit. MCCABE, E. C. Region 1, Philadelphia, Office of the Director, 80/11/17, 1p.

8011250535 PND-I-80-167 on 800929, State of NJ Dept of Environ Protection received ltr from citizen complaining of radioactive contamination along Route 17, Rochella, Park, NJ. Th-232 & Ra-226 confirmed in 801008 & 20 soil samples. KINNEHAN, J. Region 1, Philadelphia, Office of the Director, 80/11/17 2pp, 07068:272

8011250542 PND-I-80-168 on 801117, reactor tripped due to low steam pressure signal. Caused by placing wrong channel in trip when intermittent fault became evident on another instrument. Outage expected to last two days for reborator & repairs. MCCABE, E. C. Region 1, Philadelphia, Office of the Director, 80/11/17, 1p

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

8011030147 Forwards response to 800909 request for recommendations re areas in which Hydrology Committee can contribute to NRC. Suggested areas of contribution include coordination of storm surge data collection programs & modeling effort. DIRCKSE, W. J. Office of the Executive Director for Operations 80/10/15, 4pp 06855:190

--8011030151 Requests recommendations re areas in which Hydrology Committee can contribute to NRC hydrologic engineering needs. MARTIN, G. R. U. S. Water Resources Council 80/09/09, 1p, 06855:194.

8011060035 Responds to 800917 ltr re initial actions for public safety during severe nuclear power plant accidents. NRC position favors sheltering rather than evacuation while accident severity is being assessed. GRIMES, B. K. Emergency Preparedness Program Office, 80/10/03, 2pp, 06911:193.

--8011060040 Requests info re NRC position on initial action for public safety during severe nuclear power accidents. ELLEMAN, D. Affiliation Unknown 80/09/17, 1p, 06911:194.

8011060342 Approves proposed Tech Spec re draft radiation protection plan guide & concurs w/ plan to issue guide for public comment. BROWHOLT, D. J. Quality Assurance Branch, 80/09/29 1p 06916:211

8011060546 Responds to 800718 request for comments on AGAP-1, Edition 3, "HATO GC Sys Requirements for Industry." Substantive & editorial/clarification comments encl. HAASB, W. P. Quality Assurance Branch 80/09/30 3pp 06916:212

8011060778 Forwards IE Info Notice 80-36 "Failure of Steam Generator Support Bolting" & draft copy of transmittal letter. MCSELEY, N. C. Division of Reactor Operations Inspections, 80/10/09, 1p.

8011070298 Forwards Nov 1980 update of cases pending before ABLP, ASLAP & Commission. CHRISTENBURY, E. Hearings Division 80/11/03, 27pp, 06919:282.

8011070359 Ack receipt of 800903 ltr requesting NRC support of workshop between aerospace & electrical power communities. Meeting proposed for 801020 in Silver Spring, MD. MURLEY, T. E. Office of Nuclear Regulatory Research, Director 80/10/13, 3pp 06919:332

--8011070362 Requests NRC support of workshop between aerospace & electrical power communities. Agenda encl. BARTEN, B. O. American Institute of Aeronautics & Astronautics 004058, 80/09/03 3pp 06919:335

801100287 Forwards research results utilization form for RIL 91, "ACFR Experiments on Prompt-Burnt Energetics w/ Fresh U Carbide Fuel." KNIGHTON, O. H. Research & Standards Coordination Branch 80/10/17, 2pp 06931:300

801120534 Advises that field engineering serviceman is scheduled to go to job site in Dec 1980. Questions raised will be answered after site visit. AXELROD, L. R. Kay-Ray, Inc. 80/11/03, 1p 06953:346.

801120594 Confirms 801003 telcon re pat down searches & protection against insider threats. Concurs w/ Commission papers re searches. Recommends that proposed amendments to code include credit record checks re applicants for security positions. MILLER, J. R. Standardization & Special Projects Branch 80/10/29 1p 06953:032

801140541 Confirms 801031 telcon re licensing requirements for proposed export of 44 primary sys control valves to India. Dept of Commerce is licensing authority for export of general purpose valves. DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80/11/06 1p 06963:007

8011170127 Responds to 800905 ltr to DOE requesting info re exposures to electromagnetic fields associated from transmission lines. No substantiated data indicates adverse effects by electric fields at power line frequencies. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/11/03 2pp, 06915:001

--8011170137 Forwards MB Wentzell 800905 ltr re exposure to electromagnetic fields associated from transmission lines. Requests response DOE response encl. WEBSTER, E. Energy, Dept of 80/09/29 4pp 06915:001

8011170316 Confirms 800826 telcon that Dept of Commerce is appropriate licensing authority for valves described in vendor 800316 application to export Class 1500 psi steam pressure reducing valves to India. DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80/10/31, 1p 06968:360

8011200237 Forwards info re licensing actions completed during Oct 1980. Lists manpower utilization statistics for 801004-1101. ROBERTSON, Z. R. Equipment Qualification Branch 80/11/05 3pp, 07019:340

8011210066 Reviews unsolicited proposal "Demonstration of Reactor Emergency Noble Gas Recovery Sys." from Science Applications, Inc. Proposed effort would not contribute to agency mission & should not be funded. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/11/05, 2pp 07031:185.

--8011210073 Forwards unsolicited proposal "Demonstration of Reactor Emergency Noble Gas Recovery Sys." from Science Applications, Inc. Advises of questions to consider in review. Requests prompt response w/o encl. COLEMAN, H. E. Contract Policy Branch, 80/06/25 3pp 07031:187

8011240077 Forwards list of licensing actions completed during Oct 1980. BENARDY, V. Chemical Engineering Branch 80/11/04 4pp, 02227:001

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

8006030286 Forwards comments on NUREG-0480, Vol 4, re ATHB for LHRs. Committee on Reactor Licensing & Safety disagrees w/ proposed resolution based on design requirements. QIBER, D. C. Atomic Industrial Forum, 80/03/27, 12pp 05166:300

8010020486 Forwards comments on Essex Rept, "Human Engineering Guide to Control Room Evaluation." NUREG/CR-1580. FLANAGAN, G. F. Oak Ridge National Laboratory, 80/09/25, 7pp, 03610:201

NONDOCKETED ITEMS

8010220274 Transcript of 800903 meeting re low power OL in Washington
DC Pp 1-58
* Commissioners 80/09/03 60pp 06778 171

--8010220282 NUREG-0117 DRFT
Draft Suppl 4 to SER, NUREG-75/034, for facility. Draft OL
encl
* Office of Nuclear Reactor Regulation, Director 80/08/28
177pp. 06778 232.

8010230019 NUREG/CR-1394
"Diffusion Near Bldgs as Determined From Atmospheric Tracer
Experiments."
SAGENDORF, J F, RICKS, N R, START, O E Commerce, Dept of, National
Oceanographic & Atmospheric Administration FIN B-3690
NRC-03-79-132 80/09/30 30pp Available at GPO 06791:298

8010290005 Requests Commission approval of encl clarification & changes
to 800905 ltr & encl setting forth complete listing of
TMI-related requirements approved for implementation Ltr &
encls will be published as NUREG-0737 upon approval.
BENTON, H R Office of Nuclear Reactor Regulation, Director
80/10/22 10pp

--8010290014 Forwards comments on clarification of TMI action plan
requirements in response to 800905 ltr & 800926 meeting w/
NRC. Long-term training requirements should be directly
pertinent to job requirements of position
CLAYTON, F L Alabama Power Co 80/10/06 4pp. 06827 341

--8010290019 Forwards generic comments of BWR owner's group on NRC
800905 ltr re preliminary clarification of TMI action plan
requirements. Plant-unique comments are being transmitted
via separate submittals
WATERS, D B Carolina Power & Light Co 80/10/08 16pp
06828-005

8010300044 Notice of issuance & availability for public comment of
proposed rulemaking to 10CFR50 re acceptance criteria for
deviations from SRP
CHILK, S J Office of the Secretary of the Commission 80/10/03
7pp 06855 106

8010300252 NUREG/CR-1591
"Combined SAFE/SNAP Approach to Safeguards Evaluation"
ENGEL, D, CHAPMAN, L D. Sandia Laboratories GRANT, F H Pritsker &
Associates, Inc FIN A-1060 SAND80-0329 80/08/31 22pp.
Available at NTIS 06897 278

801030428 NUREG/CR-1154 V1 N03
"BWR Blowdown Emergency Core Cooling Fifteenth Quarterly
Progress Rept." Jul-Sept 1979
MURALIDHARAN, R General Electric Co, Nuclear Energy Products Div
NRC-04-76-215 GEAP-21304-15 80/10/31 50pp Available at NTIS
06897 319

801030429 NUREG-0735
"Plan for Developing Safety Goal"
* Office of Policy Evaluations. 45FR71023 80/10/31 30pp
Available at NTIS 06857 294

801030480 NUREG/CR-1275
"Annotated Bibliography on Transportation & Handling of
Radioactive Metals - 3"
HEISKELL, M M Oak Ridge National Laboratory FIN B-0126
ORNL/NUREG/NSIC. 80/09/30 160pp 01756 001

801030488 NUREG/CR-1376
"Risk Methodology for Geologic Disposal of Radwaste
Distributed Velocity Method of Solving Convective-Dispersion
Equation."
CAMPBELL, J E, LONGSHINE, D E, REEVES, M Sandia Laboratories.
FIN-1192 SAND80-0717 80/07/31 74pp. 06860 211.

801030495 NUREG/CR-1509
"LWR Safety Research Program," quarterly rept, Apr-June 1980
BERMAN, M Sandia Laboratories, FIN A-1019 SAND80-1304. 80/08/31
114pp 06860 281

801030510 NUREG-0584 R2 DRFT
"Assuring Availability of Funds for Decommissioning Nuclear
Facilities," draft Revision 2
WOOD, R S Office of Nuclear Reactor Regulation, Director 80/10/31.
80pp 06861 239

801030515 NUREG/CR-1642
"Site-Dependent Response at E1 Centro, CA Accelerograph
Station Including Soil/Structure Interaction Effects"
* Shannon & Wilson, Inc * Agabian Associates FIN B-3015.
NRC-04-76-200 80/10/31 164pp 06861:318

801030647 NUREG-0090 V3 N01
"Rept to Congress on Abnormal Occurrences, Jan-Mar 1980"
* Office of Management and Program Analysis 80/09/30 38pp
06863 124.

801030659 NUREG/CR-1560
"Structural Uncertainty in Seismic Risk Analysis - Seismic
Safety Margins Research Program"
HASSELMAN, T K, SIMONIAN, S B Lawrence Livermore Laboratory. FIN
A-0130 UCRL-13218 80/10/31 145pp 06862 265

801030664 NUREG/CR-1670 V1
"Use of Process Monitoring Data for Nuclear Matl
Accounting," summary rept, Vol 1
BROUN, R J, SMITH, B W, BRIDE, D W. Battelle Memorial Institute,
Pacific Northwest Laboratory FIN B-2213 PNL-3396 80/10/31
32pp 06861 212

801040342 NUREG/CR-0983 V9
"Advanced Reactor Safety Research Combined Quarterly Rept,"
Oct 1978 - Mar 1979, Vol 9
* Sandia Laboratories SAND79-1566 80/08/31 306pp 06874 204

801040555 Forwards revised draft of introduction section to NUREG-
0096 Redundancy has been removed & discussion has been
added re philosophy behind facilities Sections on safety
parameter display sys & technical support ctr revised
PRESTON-SMITH, PETERSON, R Pacific Gas & Electric Co. 80/10/30
9pp 06873 310

801050025 Transcript of NRC 801028 meeting in Washington, DC re
briefing on clarification of TMI action plan requirements
Pp 1-87
* Commissioners 80/10/28 90pp 06897:111

--801050028 Forwards summary listings of written comments received on
800905 preliminary clarification of TMI action plan
requirements ltr. NRC response & impact on clarification
package compiled by NUREG-0660 task action plan
BENTON, H R Office of Nuclear Reactor Regulation, Director
80/10/24 19pp 06897:201

801050166 Comments on NUREG-0696, "Functional Criteria for Emergency
Response Facilities"
DISE, D P Niagara Mohawk Power Corp 45FR54708 034 80/10/10
9pp 06898:336

801050185 Comments on NUREG-0696, "Functional Criteria for Emergency
Response Facilities" Emergency involving functional
interfaces & authorities has not been adequately defined
SHIELDS, S W Public Service Co of Indiana, Inc 45FR54708 033
80/10/06 10pp 06899:001

801050523 NUREG-0435 V2 N03
"Research Project Control Sys (RPCS)," status summary rept
for data as of 800915, Vol 2, Number 3
* Office of Nuclear Regulatory Research, Director 80/09/15
200pp 06902 305

801050526 NUREG/CR-1572 V12
"Advanced Reactor Safety Research," Vol 12, quarterly rept
for Oct-Dec 1979
* Sandia Laboratories FIN A-1016. SAND80-1072 80/09/30 225pp.
Available at NTIS 06900 223

801050532 NUREG-0304 V5 N01
"Regulatory & Technical Repts," Vol 5, Number 1 compilation
for Jan-Mar 1980.
OLIU, W E, MCKENZIE, L., ARAOON, R Office of Administration
80/10/31 200pp. Available at NTIS 06901 062

801050544 NUREG/CR-1718
"Analysis of Linear & Nonlinear Instability Phenomena in
Heated Channels."
ACHARD, J L, DREW, D A, LAHEY, R T Rensselaer Polytechnic Inst FIN
B-6461 80/10/31 110pp Available at NTIS 06893:031

801050554 NUREG/CR-1711
"MARCH (Meltdown Accident Response Characteristics) Code
Description & User Manual."
HOOTON, R O., AVCI, M I, Battelle Memorial Institute, Columbus
Laboratories FIN A-4067 BNL-2064 80/10/31 200pp Available
at NTIS 06893:142

801050568 NUREG-0724
"Problems in Modeling of Small Break LQCA"
ZUBER, N Division of Reactor Safety Research. 80/10/31. 90pp.
Available at NTIS 06901:206

NONDOCKETED ITEMS

28

- 8011060353 BECY-80-440
Informs of status of min qualification guidelines for nuclear plant staffing Guidelines list procedures that will be required to maintain safe operation & communications
DENTON, H R Office of Nuclear Reactor Regulation, Director
80/09/19 2pp 06910 231
- 8011060359 NUREG-0731 DRAFT
"Guidelines for Util Mgt Structure & Technical Resources," draft rept
* Office of Nuclear Reactor Regulation, Director 80/09/19
32pp 06910 234
- 8011060553 Submits guidance on reassessment of secondary review responsibility assignments for SRP revisions Revised sections should document review process so that integrated review can be tracked from branch to branch Example encl
SCHROEDER, F Division of Safety Technology 80/10/10 5pp
06916 215
- 8011060664 NUREG-0580 V9 N04
"Regulatory Licensing Data for Decisions," status summary rept, Vol 9, Number 4
* Division of Licensing 80/10/17 130pp Available at NTIS
#6 00, 06916 016
- 8011070033 Transcript of NRC 801028 meeting in Washington, DC re GE, AIF & EPRI presentations on ATWS Pp 1-71 Videograph presentations by DC Gibbs & GS Lellouche encl
* Commissioners 80/10/28 113pp 06924 060
- 8011070041 Requests participation at Commissioners meeting when NRC position paper re ATWS is discussed. Proposed requirements in NUREG-0460, Vol 4 not necessary, considering BWR capability to mitigate using existing equipment & modified sys.
SHERWOOD, O O General Electric Co, Nuclear Energy Products Div
MFN-101-80 80/03/21 1p 06924 178
- 8011070047 Responds to 800521 ltr requesting participation in forthcoming Commission discussion of NRC position paper re ATWS Full discussion may require several sessions Schedule & time allotted for participation will be forwarded
CHILK, S J Office of the Secretary of the Commission 80/07/08
1p, 06924 179
- 8011070071 Extends invitation to GE, EPRI & AIF for participation in NRC 801028 open meeting in Washington, DC re ATWS Commission expects that participants will arrange allocation of available time
CHILK, S J Office of the Secretary of the Commission 80/10/23
1p 06924 182
- 8011070077 Extends invitation to GE, EPRI & AIF participation in NRC 801028 open meeting in Washington, DC re ATWS Commission expects that participants will arrange allocation of available time
CHILK, S J Office of the Secretary of the Commission 80/10/23
1p 06924 183
- 8011070078 Invites GE, EPRI & AIF participation in NRC 801028 open meeting in Washington, DC re ATWS Commission expects that participants will arrange allocation of available time
CHILK, S J Office of the Secretary of the Commission 80/10/23,
1p 06924 184
- 8011070085 Comments on proposed rulemaking to amend 10CFR50 re ATWS events & NUREG-0460. Issue can be resolved on fair & equitable basis, but w/o plant mods & schedule requirements recommended in BECY-80-409
SHERWOOD, O O General Electric Co, Nuclear Energy Products Div
MFN-183-80 80/10/24 8pp 06924 185
- 8011070080 Notification of 801112 meeting w/Westinghouse to discuss new emergency procedure guideline & compliance of current emergency procedures guidelines in meeting requirements of Item I C 1 of TMI task action plan
STEGEL, B L Procedures & Test Review Branch NUREG-0660 80/10/24
2pp 06920 048
- 8011070090 Comments by ConServ on NUREG/CR-1580, "Human Engineering Guide to Control Room Evaluation." Use of document to produce backfitting designs can be dangerous.
BARGENT, T D Affiliation Unknown 80/10/13, 3pp 06925 026.
- 8011070095 Comments by Whitston Associates on NUREG/CR-1580, "Human Engineering Guide to Control Room Evaluation." Goals cannot be realized on basis of document
GLIVER, J A Affiliation Unknown 80/09/23 6pp 06925 029.
- 8011070101 Forwards comments on NUREG/CR-1580, "Human Engineering Guide to Control Room Evaluation." Rept has potential for useful applications in evaluation & design of control rooms
ANDERSON, T M Westinghouse Electric Corp NS-TMA-2315 80/09/26
6pp 06925 035
- 8011070107 Comments on NUREG/CR-1580, "Human Engineering Guide to Control Room Evaluation." Document does not adequately provide guidance needed by individual utilities for human factors review of existing control rooms
PARKER, W O Duke Power Co 80/09/29 13pp 06925 041
- 8011070333 Discusses basis for statement in NUREG/CR-1280 that utilities assert their training & qualification program is adequate because they have not had TMI-type accident
COLLINS, F F Operator Licensing Branch 80/10/20 2pp 06919 317
- 801100113 Forwards comments by JL Seminars on NUREG/CR-1580, "Human Engineering Guide to Control Room Evaluation." Most comments expressed during 801002-03 workshop in Atlanta, GA are covered in 800926 ltr
PACK, R W Institute of Nuclear Power Operations 80/10/15 21pp
06930 001
- 801100202 Comments on NUREG-0630, "Cladding Swelling & Rupture Models for LCA Analysis." Introduction lacks clear description of clad deformation processes in bundle geometry.
HANNAFORD, J United Kingdom 79/12/10 4pp 06916 001.
- 801100256 Comments by ENTOR Corp on NUREG/CR-1580, "Human Engineering Guide to Control Room Evaluation." Document does not address major concern re sensory overload on operators when plant goes into upset condition
PIELAK, H W Affiliation Unknown, 80/09/15 2pp 06916 001
- 801100259 Comments on NUREG/CR-1580, "Human Engineering Guide to Control Room Evaluation." No comment Response time is too short for any realistic comment Objects to draft & method of asking for public comment
FECHTER, J V Honeywell, Inc 80/09/24 2pp 06931 304.
- 801100265 Comments on NUREG/CR-1580, "Human Engineering Guide to Control Room Evaluation." No comment Requests extension of time for response
HANS, L F Institute of Electrical & Electronic Engineers 9/80-42
80/09/16 1p 06931 303
- 801100463 NUREG/CR-1498
"Population Dose Commitments Due to Radioactive Releases from Nuclear Power Plant Sites in 1977"
BAKER, D A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2243 PNL-3324 80/10/31, 120pp 06940 138
- 801100466 NUREG/CR-1526 V2
"Physics of Reactor Safety," quarterly rept, Apr-June 1980, Vol 2
* Argonne National Laboratory FIN A-2015 ANL-80-84 80/08/31
70pp Available at NTIS 06941 142
- 801100471 NUREG/CR-1742
"Steam-Water Mixing & Two-Phase Hydrodynamics Program-Task 4," quarterly progress rept, Jan-Mar 1980
BEDEV, A, FLANIGAN, L J, LIU, J S K Battelle Memorial Institute, Columbus Laboratories FIN A-4048 BNL-2045 80/10/31 91pp
Available at NTIS 06940 253
- 801110008 Comments by Lund Consulting, Inc on NUREG/CR-1580, "Human Engineering Guide to Control Room Evaluation." Guidelines have apparent lack of interdisciplinary approach to problem
HECHT, L O Affiliation Unknown 80/09/26 7pp 06944 106
- 801110051 Comments by AF Meyer & Associates, Inc on NUREG/CR-1580, "Human Engineering Guide to Control Room Evaluation." Document presently has problems from practical use viewpoint
MEYER, A F Affiliation Unknown 80/09/18 2pp 06944 100
- 801110056 Comments on NUREG/CR-1580, "Human Engineering Guide to Control Room Evaluation." Document stresses design deficiencies, whereas positive aspect of control room evaluation is to assure effective performance design
JACOBS, B B Stone & Webster Engineering Corp, 80/09/26 2pp
06944 098
- 801110162 Forwards comments on proposed rules 10CFR50.51 & 100 re siting criteria & NUREG-0625, "Rept of Siting Policy Task Force." Criteria should substantially support using existing sites to meet additional nuclear needs
MILLS, L M Tennessee Valley Authority, 45FR50350 063 80/10/21,
6pp.

NONDOCKETED ITEMS

- 801110617 NUREQ-0540 V2 N07
"Title List of Documents Made Publicly Available," Vol 2.
Number 7, for Jul 1980
* Office of Administration 80/07/31 550pp Available at NTIS.
\$4 30 06915.001
- 8011120414 Submits general & specific comments on draft NUREQ/CR-1580.
"Human Engineering Guide to Control Room Evaluation" All
design review factors specified in NUREQ-0460 not addressed.
Precise checklist selection criteria needs definition
BUCHHOLZ, R H General Electric Co, Nuclear Energy Products Div
MFN-184-80 80/11/06 5pp 06952 125
- 8011120632 NUREQ/CR-1713
"Upper Plenum Dump During Reflood."
ORIFFITH, P Massachusetts Institute of Technology SUDD, Y Japan
FIN 8-7229. 80/10/31 80pp Available at NTIS 06951 028
- 8011120668 Requests FR publication for encl notice of issuance of
NUREG-0468, Suppl 1, "Mark II Containment Lead Plant
Program Load Evaluation & Acceptance Criteria"
SCHROEDER, F Division of Safety Technology 80/10/16 1p
06953-022
- 8011130194 Notices of comments received on NUREQ/CR-1580, "Human
Engineering Guide to Control Room Evaluation," as of
801029 Forwards comments for placement in PDR AIF, Bechtel
Power Corp & Comm E6 comments encl
FROELICH, R W Human Factors Engineering Branch 80/10/30 2pp
06957 053
- 8011130204 Forwards comments on NUREQ/CR-1580, "Human Engineering Guide
to Control Room Evaluation" Vol 1 should focus on scope &
objectives of human factors review rather than specific
organizational structure & methodology
HONELL, S H Atomic Industrial Forum. 80/10/20 4pp. 06957-055
- 8011130211 Forwards comments on NUREQ/CR-1580, "Human Engineering Guide
to Control Room Evaluation" Rept lacks distinction in
application of guidelines & backfit requirements to safety-
related & nonsafety-related equipment & tasks
DELGORDOE, L O Commonwealth Edison Co 80/09/29 101pp
06957 061
- 8011140158 NUREQ/CR-1724
"Proceedings of CBNI Specialists Meeting on Nuclear Aerosols
in Reactor Safety," preliminary rept.
* Oak Ridge National Laboratory FIN B-0121 ORNL/NUREG/TM-4.
80/10/31 600pp 06982-290
- 8011140176 NUREQ/CR-1618
"Water Reactor Safety Research Div. Quarterly Progress Rept."
Apr - June 1980
KOUTS, H. J. C., YATO, W. Y., ABUAF, N Brookhaven National Laboratory
FIN A-3014 BNL-NUREG-51255 80/08/31 61pp. Available at NTIS.
06964 212
- 8011140184 NUREQ/CR-1154 V1 N04
"BWR Blowdown Emergency Core Cooling 16th Quarterly Progress
Rept," Oct-Dec. 1979, Vol 1, Number 4.
CARUSO, S General Electric Co * Electric Power Research
Institute * Commissioners NRC-04-76-215 GEAP-21304-16
80/10/31. 44pp Available at NTIS 06964 322
- 8011140191 NUREQ/CR-1686 V1
"Feasibility & Cost/Benefit of Advanced Safeguards for
Control of Nuclear Matl In-Process," summary rept, Sept 1979-
Aug 1980, Vol 1
GLANCY, J., BORCONOVI, Q., DONELSON, S Science Applications, Inc FIN
B-6930, BA101580-343LW 80/10/31 65pp Available at NTIS
06964 139.
- 8011140200 NUREQ/CR-1187
"Lower Plenum Voiding," topical rept.
ROTHER, F H, SAM, R O Creare, Inc. FIN A-4070 CREARE TN-310
80/10/31. 35pp Available at NTIS. 06964 278
- 8011140282 NUREQ/CR-1654
"Nuclear Reactor Safety," quarterly progress rept for Jan-
Mar 1980.
STEVENSON, K Q, JACKSON, J. F., VIOIL, J C Los Alamos Scientific
Laboratory FIN A-7014 LA-8494-PR 80/08/31. 82pp 06964 057.
- 8011140309 NUREQ-0738
"Investigations of Reported Plant & Animal Health Effects in
TMI Area"
GEARS, O. E., LA ROCHE, Q Commissioners SMITH, D. Environmental
Protection Agency EPA 600/4-80-04 80/10/31 34pp. Available at
NTIS 06965-043.
- 8011140320 NUREQ/CR-1727
"Experiment Data Rept for Semiscale Mod-3 Small Break Test
Series (Tests 8-SB-P3 & 8-SB-P4)"
SACKETT, K E, CLEGG, L B, EQ&O Idaho, Inc FIN A-6038 EQQ-2063
80/10/31 31pp Available at NTIS. 06964 001
- 8011140324 NUREQ/CR-1653
"Critical Experiments on Low-Enriched U Oxide Sys
W/H/U=1 25"
GOEBEL, O R, OH, I, ROTHE, R E Rockwell International Corp FIN
A-1036 RFP-3129 80/10/31 41pp Available at NTIS 06965 082
- 8011140601 NUREQ/CR-1619
"Physical Protection of Nuclear Facilities," quarterly
progress rept for Apr-June 1980
CHAPMAN, L D Sandia Laboratories FIN A-1060 SAND80-1741
80/09/30 19pp Available at NTIS. 06963 322.
- 8011140603 NUREQ/CR-1266 V1
"Technology, Safety & Costs of Decommissioning Ref U Fuel
Fabrication Plant," Vol 1, main rept
ELDER, H K, BLAHNIK, D E, Battelle Memorial Institute, Pacific
Northwest Laboratory FIN B-2036 80/10/31 235pp. Available at
NTIS 06982 032
- 8011140669 NUREQ/CR-1646
"Bibliography of Microfiched Foreign Repts Distributed Under
NRC Reactor Safety Research Foreign Technical Exchange
Program, 1979"
QUEENER, D S Oak Ridge National Laboratory. FIN B-0126
ORNL/NUREG/NSIC 80/10/31 123pp Available at NTIS 06911:001
- 8011170393 NUREQ/CR-1692
"Flow Regime Identification & Void Fraction Measurement
Techniques in Two-Phase Flow"
VINGE, M A, LAHEY, R T Rensselaer Polytechnic Inst FIN B-7272
80/10/31 535pp 06980 001
- 8011170529 NUREQ/CR-1617
"Advanced Reactor Safety Research Div." quarterly progress
rept Apr-June 1980
ROMANO, A J Brookhaven National Laboratory FIN A-3015.
BNL-NUREG-51254 80/07/31 93pp 06971 008
- 8011170554 NUREQ/CR-1266 V2 APP
"Technology, Safety & Costs of Decommissioning Ref U Fuel
Fabrication Plant," Vol 2, Apps
ELDER, H. K., BLAHNIK, D E, Battelle Memorial Institute, Pacific
Northwest Laboratory FIN B-2036. 80/10/31 225pp 06972.122
- 8011170563 NUREQ/CR-1623
"Study of Film Boiling, Quench & Rewet Phenomena During High
Pressure Power Cooling Mismatch Testing."
GURNERSON, F S, DUNPHY, P S EQ&O Idaho, Inc. FIN A-6041 EQQ-2052
80/10/31 95pp 06976 147.
- 8011170587 Forwards draft NUREQ-0725, "Public Info Circular for
Shipments of Irradiated Reactor Fuel" Document will be made
available to public on 801024
AHEARNE, J F Commissioners 80/10/20 1p. 06976-068
- 8011170847 NUREQ-0725 DRAFT
Draft "Public Info Circular for Shipments of Irradiated
Reactor Fuel"
* Commissioners 80/09/30 50pp 06976 119
- 8011170613 NUREQ/CR-1693
"Evaluation of Isotope Migration - Land Burial, Water
Chemistry at Commercially Operated Low Level Radwaste
Disposal Sites," quarterly progress rept Apr-June 1980
CZYSCINSKI, K S, WEISS, A J Brookhaven National Laboratory FIN
A-3042 BNL-NUREG-51263. 80/08/31 40pp. 06976.279.
- 8011170661 NUREQ/CR-1615
"Solid Angle & Surface Density as Criticality Parameters."
THOMAS, J T Oak Ridge National Laboratory FIN B-0419.
ORNL/NUREG/CBD/ 80/10/31 146pp. 06973 191
- 8011170674 NUREQ/CR-1454 V1
"Reactor Safety Research Programs," quarterly rept Jan-Mar
1980, Vol 1
HAGEN, C M, Battelle Memorial Institute, Pacific Northwest
Laboratory FIN B-2101 PNL-3380-1 V1. 80/10/31. 117pp.
06971 244
- 8011170688 NUREQ/CR-1177 V13
"LWR Safety Research Program," Vol 13, quarterly rept
Jul-Sept 1979
BERMAN, M Sandia Laboratories FIN A-1019. SAND79-2290 80/09/30.
176pp Available at NTIS 06973 001

- 8011170497 NUREG/CR-0568
"Thermostructural Response of Advanced Reactor Cell Liners,"
STONE, C. H., GARTLING, D. K. Sandia Laboratories FIN A-1054
80/08/31 43pp Available at NTIS 06971 147
- 8011170712 NUREG/CR-1743
"Steam-Water Mixing & Sys Hydrodynamics Program - Task 4,"
quarterly progress rept Apr-June 1980
BEOEV, A., FLANIGAN, L. J., COLLIER, R. P. Battelle Memorial Institute,
Columbus Laboratories FIN A-4048 BMI-2067 80/10/31 46pp
Available at NTIS 06971 100
- 8011170721 NUREG-0688
"Computerized Reactor Pressure Vessel Matls Info Sys."
STROBNIDER, J., MONSERRATE, C., KENWORTHY, L. D. Office of Nuclear
Reactor Regulation, Director 80/10/31 130pp Available at NTIS
06972 001.
- 8011170730 NUREG/CR-1571
"Evaluating Strength & Ductility of Irradiated Zircaloy, Task
5," quarterly progress rept Jul-Sept 1979
LOWRY, L. M., MARKWORTH, A. J., PERRIN, J. B. Battelle Memorial Institute,
Columbus Laboratories FIN A-4068 BMI-2057 80/10/31. 62pp
06971.184
- 8011180221 Comments on NUREG/CR-1580, "Human Engineering Guide to
Control Room Evaluation." Checklists, which should form basic
document for public review & comment, are missing. Precise
selection criteria need to be defined as development method
PANKRATZ, D. R. General Electric Co. DRP-80-14. 80/09/26 4pp.
06992 285.
- 8011180454 Comments on draft NUREG-0731, "Guidelines for Util Mgt
Structure & Technical Resources." Sept 1980. Figure 1 not
consistent w/characteristics of plant staff organization.
Distinct functional areas must be clearly defined
LOWRY, R. C. Affiliation Unknown. 80/11/12. 1p 06988:166
- 8011190070 NUREG/CR-1699
"Modes of Circulation in Inverted U-Tube Array
w/Condensation"
CALIA, C., GRIFFITH, P. Massachusetts Institute of Technology. FIN
B-7229. 80/10/31 101pp 07004 242
- 8011190080 NUREG/CR-1764
"Review of Staffing Requirements for Near-Term OL
Facilities."
PRICE, H., WALLACE, P., BAUMAN, M. Bio-Tec, Inc FIN B-7502
80/10/31 67pp. 07005:065.
- 8011190081 NUREG/CR-1753
"Application of Linear Propagation of Errors to Fuel Rod
Temp & Stored Energy Calculations."
CUMMINGHAM, M. E., OLSEN, A. R., LANNING, D. D. Battelle Memorial
Institute, Pacific Northwest Laboratory. FIN B-2043. PNL-3539.
80/10/31. 104pp. Available at NTIS 07004:142
- 8011190085 NUREG/CR-1603
"Evaluation of Cracking in Feedwater Piping Adjacent to
Steam Generators in Nine PWR Plants"
GOLDBERO, A., STREIT, R. D., SCOTT, R. O. Lawrence Livermore Laboratory.
FIN A-0255 UCRL-5300. 80/10/31 191pp 07003 305
- 8011190096 NUREG/CR-1722
"Interim Rept on Systematic Errors in Nuclear Power Plants.
Seismic Safety Margins Research Program"
MOIENI, P., APOSTOLAKIS, G. California, Univ. of, Los Angeles.
CUMMINGHAM, O. E. Lawrence Livermore Laboratory FIN A-0126.
UCRL-15274 80/10/31. 77pp Available at NTIS 07004:352.
- 8011190183 NUREG/CR-1758
"Safeguards for High Level Waste Repositories," final
rept, Feb 1979-Sept 1980.
STODDARD, J., HARRIS, L., WALKUSH, J. Science Applications, Inc FIN
B-4376-7 80/10/31 100pp Available at NTIS.
07005 341.
- 8011190215 NUREG-0737
"Clarification of TMI Action Plan Requirements."
* Office of Nuclear Reactor Regulation, Director. 80/11/30. 150pp.
Available at NTIS. 07003:027
- 8011190374 Recommends addl research before commitment to specific sys
re nuclear data link. Sys interface w/reactor instrumentation
may decrease reliability, as evidence that reactor sys is not
adversely affected has not been clearly demonstrated.
PLESSET, M. B. ACRB - Advisory Committee on Reactor Safeguards.
80/11/12 1p 06999:353.
- 8011190506 Forwards notice of issuance & availability of NUREG/CR-1636,
"Util Mgt & Technical Resources," for FR publication
CHILK, B. J. Office of the Secretary of the Commission 80/10/16
1p 07001 178
- 8011190509 FR notice of issuance & availability of NUREG/CR-1636, "Util
Mgt & Technical Resources"
VASSALLO, D. B. Licensee Qualifications Branch 80/10/09. 2pp
07001 179
- 8011190693 NUREG/CR-1669
"Biological Characterization of Radiation Exposure & Dose
Estimates for Inhaled U Milling Effluents," annual progress
rept for Mar 1979-Mar 1980
EIDSON, A. F. Inhalation Toxicology Research Institute. * Lovelace
Biomed & Environmental Research Institute FIN A-1222 LMF-76
80/10/31. 43pp Available at NTIS 07005 137
- 8011190696 NUREG/CR-1673
"Critical Excitation Method for Calculating Earthquake
Effects on Nuclear Plant Structures. Assessment Study"
BEROSIAN, B., BARBELA, M., DRENICK, R. F. Burns & Roe Co. FIN B-6220
80/10/31 185pp Available at NTIS 07005 173
- 8011190703 NUREG/CR-0849 VI N02
"Safeguards Matl Control & Accounting Program," quarterly
rept for Jan-Mar 1980, Vol 1, Number 2
POGOLO, A. J., DUNN, D. R. Lawrence Livermore Laboratory FIN A-0115
UCRL-52715-B0-2 80/10/31. 28pp Available at NTIS 07005 315
- 8011190708 NUREG/CR-1775
"Environ Assessment of Consumer Products Containing
Radioactive Matl"
BUCKLEY, D. W., BELANGER, R., MARTIN, P. E. Science Applications, Inc
FIN B-0280 80/10/31. 350pp. Available at NTIS.
07007 181
- 8011190709 NUREG/CR-1588
"Potential Crush Loading of Radioactive Matl Packages in
Highway, Rail & Marine Accidents"
COLTON, J. D., ROMANDER, C. M. SRI International FIN B-6124
80/10/31 153pp Available at NTIS. 07008:198
- 8011210038 Comments on NUREG-0660, re NRC action plan Requirements
should be prioritized. Backfitting policy should be
developed for both operating plants & plants under const.
SULLIVAN, T. J. Consumers Power Co 45FR306130003 80/10/31 1p
07033 173
- 8011210052 Comments by San Francisco Neighborhood Legal Assistance
Foundation on NUREG-75/087 requiring licensees & applicants
to document all deviations from SRP NRC needs to devise
workable proposal which reviews all plants for safety.
BOROEN, D. Affiliation Unknown 80/10/28 2pp 07033:169
- 8011210185 Transcript of 801110 public meeting in Washington, DC, re
ATWS policy. Pp 1-84.
* Commissioners 80/11/10 56pp 07029 334
- 8011210191 Offers critique for consideration re NRC position on ATWS
at 801020 briefing
HANRAHAN, E. J. Office of Policy Evaluations 80/11/07 8pp
07030 028.
- 8011210208 Forwards revised draft FR notice to SECY-80-409 re proposed
rulemaking to amend 10CFR30 on ATWS events. Substitutes limit
on radioactivity source term as acceptance criteria for
radiological consequences
MINDQUE, R. B. Office of Standards Development, Director 80/11/07
35pp. 07030:036
- 8011210264 NUREG/CR-1721
"Computer Code Development for Pipe Whip & Impact Analysis,
Progress Rept for Yr 1"
POWELL, O. H. Lawrence Livermore Laboratory ROW, B. O., HOLLINGS, J. O.
California, Univ. of, Berkeley. FIN A-0136 UCRL-15273. 80/11/30
212pp. Available at NTIS. 07035:118
- 8011210287 Forwards comments on NUREG-0660, "NRC Action Plan as Result
of TMI-2 Accident." Schedules should recognize advantages
of maximizing power plant availability by consideration of
individual plant refueling schedules
SHIELDS, S. W. Public Service Co of Indiana, Inc. 45FR30613 002
80/10/28 5pp 07032 303
- 8011210592 Expresses appreciation for NRC cooperation extended to
Interorganizational Advisory Committee re NUREG-0634 &
response to proposed changes. Requests revisions to NUREG-
0696 to clarify NRC role in offsite emergency operations.
MANCUSO, F. Connecticut, State of. 80/11/12 2pp. 07034:004

NONDOCKETED ITEMS

- 8011240067 NUREQ-0707
"Methodology for Calculating Residual Radioactivity Levels Following Decommissioning"
ECKERMANN, K. F., YOUNG, M. W. Division of Siting, Health & Safeguards Standards 80/10/31 61pp Available at NTIS 07038:211
- 8011240085 NUREQ-0739
"Approach to Quantitative Safety Goals for Nuclear Power Plants."
* ACRS - Advisory Committee on Reactor Safeguards. 80/10/31 154pp. 07039:263.
- 8011240100 NUREQ/CR-1778
"Advanced Reactor Accident Delineation Assessment." Final rept. Nov 1978 - Dec 1979
CATTON, I. I., DHIR, V. K., KASTENBERG, W. E. California, Univ. of, Los Angeles FIN B-3004-9 80/10/31, 157pp Available at NTIS 07042:048
- 8011240101 NUREQ/CR-1761
"Survey of Proposed Functional Requirements for Disturbance Analysis & Surveillance Sys."
BIBES, W. H., OH, C. B., KNIGHT, P. F. Oak Ridge National Laboratory. FIN B-0438 ORNL/NUREG/TM-3 80/10/31. 32pp 07042:312
- 8011240420 NUREQ-0857
"Analysis of Comments on 10CFR72"
REISENHEAVER, D. Fuel Process Systems Standards Branch 80/11/30. 450pp. Available at NTIS 07045:170
- 8011240428 NUREQ/CR-1559
"Transient Critical Heat Flux & Blowdown Heat Transfer Studies"
LEUNG, J. C. Argonne National Laboratory FIN A-2026. ANL-80-53. 80/09/31 148pp. Available at NTIS 07044:266
- 8011240436 NUREQ-0020 V4 NIO
Grey book: "Operating Units Status Rept," Vol 4, Number 10, data as of 800930.
* Office of Management and Program Analysis 80/10/31. 150pp
- 8011240440 NUREQ/CR-1627
"Heavy-Section Steel Technology Program," quarterly progress rept for Apr-June 1980
WHITHAM, G. D., BRYAN, R. H. Oak Ridge National Laboratory FIN B-0119. ORNL/NUREG/TM-4. 80/10/31 61pp. Available at NTIS. 07049:176
- 8011250041 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 & on NUREQ-0683 re decontamination & disposal.
Indicates that public cannot look to NRC for protection
BRIGGS, I. J. Roswell Park Memorial Institute 43FR67018 O&O 80/11/03 10pp. 07055:126.
- 8011250282 Forwards comments on NUREQ/CR-1580, "Human Engineering Guide to Control Room Evaluation." Procedure to complete form for each discrepancy appears unwieldy Checklists should yield same result.
TAUBER, H. Detroit Edison Co EF2-51,214. 80/10/30. 3pp 07052:350
- 8011250362 Comments on draft NUREQ-0731, "Guidelines for Util Mgt Structure & Technical Resources." Personnel qualification requirements too prescriptive & restrictive. Does not support issuance until outstanding issues raised are resolved
UTLEY, E. E. Carolina Power & Light Co. NC-80-1727 80/11/20 5pp. 07068:128.
- 8011260163 Describes program & schedule for response to NUREQ-0737, item II K.3 30 re possible upgrade of LOCA analytical model
Vendor will justify acceptability of current model in written rept by 820101.
BUCHHOLZ, R. H. General Electric Co MFN-202-80. 80/11/18. 2pp. 07074:077.
- 8011260266 NUREQ/CR-1723
"Nonlinear Sensitivity & Uncertainty Analysis in Support of Blowdown Heat Transfer Program"
RONE, Y., BIERKE, M. A., CACUCI, D. G. Oak Ridge National Laboratory. FIN B-0125. ORNL/NUREG/TM-4. 80/11/30. 37pp Available at NTIS. 07072:107.
- 8011260307 NUREQ/CR-1712
"Steam Generator Flow Instability Modeling"
HSIA, D., GRIFFITH, P. Massachusetts Institute of Technology. FIN A-4060. NRC-04-74-232. 80/10/31 135pp. Available at NTIS. 07073:221.
- 8011260454 NUREQ/CR-1710 V2
"Computerized Process Control Sys for ORR-PBF Irradiation Experiment, Part 2. Mathematical Basis & Computer Implementation of Temp Control Algorithm," Vol 2
MILLER, L. F. Oak Ridge National Laboratory. FIN B-0415. ORNL/NUREG/TM-4 80/11/30 62pp Available at NTIS. 07074:005.
- 8011280132 Forwards comments on NUREQ-0811 re DES on U milling & criteria for U mill tailings & const of major plants.
LANO, E. A. Atomic Industrial Forum. 80/10/24. 71pp 07083:036.
- 8011280231 NUREQ/CR-1644
"Response of 6-Inch Nuclear Power Plant Valve to Dynamic Excitation"
MABRI, B. F., STOTT, B. J. Southern California, Univ of FIN B-5976. 80/10/31. 100pp. Available at NTIS. 07080:346
- 8011280232 NUREQ/CR-1774
"Aerosol Measurements & Modeling for Fast Reactor Safety," annual rept for FY79.
QIEBEKE, J. A., LEE, K. W., JORDAN, H. Battelle Memorial Institute, Columbus Laboratories FIN A-4063 BMI-2060 80/10/31. 95pp. Available at NTIS. 07080:167.
- 8011280233 NUREQ-0540 V2 NOB
"Title List of Documents Made Publicly Available," Aug 1980
Vol 2, Number 8
* Office of Administration 80/08/31 434pp Available at NTIS. 06915:001.
- ORO CORRESPONDENCE WITH OTHER ORGANIZATIONS
- 7906180095 Reg Guide 1.8 Revision 2 distribution list. Requests addl comments.
MINGOUE, R. B. Office of Standards Development, Director. 79/05/21. 1p.
- 8010020486 Forwards comments on Essex Rept, "Human Engineering Guide to Control Room Evaluation," NUREQ/CR-1380
FLANAGAN, G. F. Oak Ridge National Laboratory. 80/09/25 7pp. 03610.201
- 801060471 Outlines revised std format & content of site characterization for high level waste geologic repositories
Draft will be prepared during wk of 800908.
ODLER, K. R. Division of Siting, Health & Safeguards Standards 80/09/09 2pp 06914:349.
- 801060790 Advises that IE Info Notice 80-36, "Failure of Steam Generator Support Bolting," was sent to listed licensees on 801010.
PAPPAS, H. Region 3, Chicago, Office of the Director. 80/10/14 2pp. 06909:099
- 801070079 Advises that Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" was sent to listed licensees on 801001.
PAPPAS, H. Region 3, Chicago, Office of the Director. 80/10/06. 2pp. 06920:045
- 801100215 "LWR In-Plant Measurement Program," informal monthly progress rept for Aug 1980.
HANDLER, J. W. EQ&O Idaho, Inc FIN A-6075 80/09/19 4pp
- 801100226 Forwards std order for DOE work, "Source Term Measurements," issued to INEL
ARSENAULT, F. J. Division of Safeguards, Fuel Cycle & Environmental Research. FIN A-6075 80/10/14 1p. 06931:133.
- 801100232 Std order for DOE work, "Source Term Measurements," issued to INEL
ARSENAULT, F. J. Division of Safeguards, Fuel Cycle & Environmental Research FIN A-6075-1. 80/10/16 3pp 06931:134
- 801120085 Transcript of 801103 Affirmation Session 80-49 re UCS policy statement in Washington, DC. Pp 1-3
* Commissioners. 80/11/03 5pp 06953:313.
- 801130003 Advises that IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding at Indian Point Unit 2," was sent to listed licensees on 801024.
PAPPAS, H. Region 3, Chicago, Office of the Director. 80/10/28. 2pp. 06987:249.
- 801130005 Advises that Suppl 3 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," was sent to listed licensees on 801027.
PAPPAS, H. Region 3, Chicago, Office of the Director. 80/10/28. 2pp. 06997:254.

NONDOCKETED ITEMS

801130074 Response to 800815 ltr by listing NRC actions taken to improve capability to respond to natl emergencies & utilize FEMA special facility resources. Addl improvements & maint of existing programs planned.
DIRCKB, W. J. Office of the Executive Director for Operations.
80/10/24, 1p. 06986:350

--801130082 Comments on NRC 800731 ltr notifying of decision not to participate in REX-80 BRAVO exercise, involving sabotage to vital defense resource installations. NRC emergency function activities will be simulated.
CAHMF, A. Federal Emergency Management Agency. 80/08/15 1p.
06986:351

801140140 Advises that IE Circular 80-22, "Confirmation of Employee Qualifications," was sent to listed licensees on 801002.
PAPPAS, H. Region 3, Chicago, Office of the Director 80/10/07.
2pp 06963:212.

801170793 Memorandum of understanding between NRC & FEMA to define relationship in connection w/response to potential or actual radiological emergency.
MACV, J. W. Federal Emergency Management Agency. ANEARN, J. F. Commissioners 80/10/22, 7pp. 06979:213

801180303 Forwards statement of NRC/FEMA interfacing responsibilities re assessment of states' emergency plans, in response to 801007 request for input to OAG evaluation.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director.
80/10/15, 2pp. 06986:030.

--801180319 Requests statement of NRC/FEMA interfacing responsibilities re assessment of states' emergency plans for OAG evaluation of federal programs.
BARRY, L. W. Office of the Controller. 80/10/07, 1p. 06986:032.

--801180333 Forwards annual rept on mgt improvement initiatives in response to 800619 memo & OMB Circular A-117.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
80/06/30, 26pp. 06986:033

PR PROPOSED RULE

800910022B SECY-80-392

Requests Commission approval of final rulemaking deleting 10CFR20.304 re burial of small quantities of radionuclides. Value impact assessment & rept justification for deletion of 10CFR20.304 & proposed FR notice deleting 20.304 encl.
MINDQUE, R. B. Office of Standards Development, Director 80/08/21.
17pp. 03518:083

--800910022B Value impact assessment & rept justification for deletion of 10CFR20.304 re burial of small quantities of radionuclides. Deletion would result in improved records re amounts & locations of buried radioactive matl.
HICKEY, J. W. Sit. & Environ. Stds. Br (formerly Environ. Prot. Stds. Br.). 80/08/21, 32pp. 03518:097

8011030044 Notice of issuance & availability for public comment of proposed rulemaking to 10CFR50 re acceptance criteria for deviations from BRP.
CHILK, B. J. Office of the Secretary of the Commission. 80/10/03, 7pp. 06855:106.

8011030058 Comments on proposed rules 10CFR50.51 & 100 re mod of policy & regulatory practice governing siting of nuclear power reactors. Requests 30-day extension to respond to proposed rule.
BARBER, R. W. Energy, Dept. of. 80/10/15, 1p. 06857:095

8011030063 Comments on proposed rule 10CFR50 re fire protection programs for nuclear power plants operating prior to 790101. Supports fire protection measures.
KEARNEY, J. J. Edison Electric Institute. 45FR36082 054, 80/10/15, 3pp. 01756:001.

8011030065 Forwards 801010 ltr sent to FEMA commenting on proposed rules 10CFR50 & 70 re review & approval of state & local radiological emergency plans & preparedness.
KEARNEY, J. J. Edison Electric Institute. 45FR55402 001, 80/10/10, 3pp. 06857:109.

8011030071 SECY-77-461
Presents proposed policy statement to clarify role of emergency planning in siting & licensing plants. Provides proposed limited rule change to 10CFR50, App. E. Recommends approval of encl policy. Analysis & assessment encl.
MINDQUE, R. B. Office of Standards Development, Director. 77/08/29, 35pp.

--8011030073 Concurs w/770824 draft Commission paper re current policy emergency planning & licensing of nuclear power plants. Submits addl language explaining ongoing events of interest to states.
RYAN, R. Q. Office of State Programs, Director 77/08/26 2pp

--8011030073 Concurs w/770824 draft Commission paper re current policy emergency planning & licensing of nuclear power plants. Submits addl language explaining ongoing events of interest to states.
RYAN, R. Q. Office of State Programs, Director. 77/08/29, 2pp.
06872:245.

8011030109 Notice of issuance & availability for public comment of proposed rule to amend 10CFR20 re disposal of biomedical & aqueous wastes.
CHILK, B. J. Office of the Secretary of the Commission. 80/10/02, 11pp. 06855:146.

--8011030114 Preliminary value/impact assessment of proposed amends to 10CFR20 for disposal of biomedical & aqueous wastes. Recommends FR publication of proposed amends for public comment.
* Office of the Secretary of the Commission. 80/10/02, 29pp
06855:137.

8011040015 Comments by Oakland County Medical Soc on proposed rule 10CFR33 re NRC rules on radiation misadministrations. Present rules should be suspended while seeking alternative plan.
BAUMANN, B. B. Affiliation Unknown 45FR31701 001, 80/10/01 1p.
06884:073.

8011040017 Advises recipients of proposed rules 10CFR2 & 60, et al, the comment Number 33 of PR-60 should be Number 36 of PR-2, et al. Comment Number 33 of PR-60 will not be used again.
* Docketing & Services Branch. 45FR31393, 80/10/07, 1p.
06884:072

8011040018 Advises recipients of proposed rules 10CFR50.51 & 100 that comments numbered 29, 46 & 56 were miscoded. Subj numbers will not be used again.
* Docketing & Services Branch. 45FR50350, 80/10/07, 1p
06884:071.

8011050030 Transcript of NRC 801027 meeting in Washington, DC to discuss & vote on fire protection program. Pp 1-43.
* Commissioners. 80/10/24 45pp. 06894:124

--8011050034 Forwards draft fire protection rule & statement of considerations proposed by NRC, revised pages, proposed immediately effective rule & possible subsection on tolling of specified completion on schedules.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 80/10/24, 107pp. 06894:170.

8011050057 Suggestions as to nature & scope of further proceedings. Joins w/State of IL 801006 suggestions.
LINDHOLM, R. H. Missouri, State of. 80/10/30, 1p 06897:267.

8011050153 Comments by NUBAC, Inc on proposed rule 10CFR2 re policy & procedure for enforcement actions to be codified as App C. Series of definitions pertinent to policy should be incorporated into final version.
LUMB, R. F. Affiliation Unknown. 45FR66754 001 80/10/23 1p
06898:349.

8011050163 Comments by NJ Dept of Environ Protection on proposed rule 10CFR50.51 & 100 re revision of reactor siting criteria & back force.
SCHWIDT, L. New Jersey, State of. 45FR50350 062 80/10/10 6pp.
06898:350.

8011050165 Comments on NUREG-0696, "Functional Criteria for Emergency Response Facilities."
DISE, D. P. Niagara Mohawk Power Corp 45FR54708 034 80/10/10, 5pp. 06898:355.

8011050180 Comments on proposed rule 10CFR35 re decision to require mandatory reporting of all radiopharms & that physicians must use FDA approved drug strictly in accord w/manufacture packages insert.
BAHMONG, J. H. Affiliation Unknown. 45FR31701 002, 80/09/26 2pp
06898:361.

8011050185 Comments on NUREG-0696, "Functional Criteria for Emergency Response Facilities." Emergency involving functional interfaces & authorities has not been adequately defined.
SHLESB, B. H. Public Service Co. of Indiana, Inc 45FR54708 033, 80/10/06, 10pp. 06899:001.

NONDOCKETED ITEMS

8011050189 Comments on proposed rule 10CFR50 re Tech Specs Format should be revised to three levels of importance immediate action requirements, less immediate action requirements & design bases & administrative commitments
RENNERGER, D. L. Washington Public Power Supply System 45FR45916 032. 80/10/20 5pp 06899 011

8011050202 Comments by College of Physicians & Surgeons of Columbia Univ on proposed rule 10CFR20 re disposal of certain low level wastes. Supports rule
ROBBI, H. H. Affiliation Unknown 45FR67018 006 80/10/22 1p 06899 018

8011050213 Comments by IN Univ Medical Ctr on proposed rule 10CFR20 re exempting scintillation cocktail containing small concentrations of tritium & C-14 Urges swift implementation of proposed rule.
HINNFIELD, S. Affiliation Unknown 45FR67018 001 80/10/17 1p. 06899 046

8011050217 Comments on proposed rule 10CFR20 re disposal of certain low level wastes Supports rule
SURPRENANT, E. L. Affiliation Unknown 45FR67018 003 80/10/17. 1p. 06899 047

8011050220 Comments on proposed rule 10CFR20 wording should be included in body of text to indicate that regulation does not relieve licensees from complying w/other applicable regulations of federal, state & local agencies
LEWIS, L. Affiliation Unknown 45FR67018 002 80/10/20 1p 06899 048

8011050224 Comments on proposed rule 10CFR20 re NRC proposal to remove most restrictions on disposal of liquid scintillation media & animal carcasses. Rule will have major positive economic impact w/o effect on health of citizens.
EVENS, R. O. Washington Univ Medical Center St Louis, MO 45FR67018 003. 80/10/21. 1p. 06899 049.

8011050230 Forwards OA & CH Rau ltr commenting on proposed rule 10CFR20 allowing labs & hosps to dispose of certain radioactive waste into drains & sewage sys Ltr should be accepted for public comment record on rule
WINN, L. House of Rep 45FR67018 004 80/10/21 3pp. 02319 196

8011050236 Comments on proposed rule 10CFR20 re stds for protection against radiation permitting licensees greater leeway in disposing of liquid scintillation media & animal carcasses Opposes rule
PRELERNIK, W. L. Affiliation Unknown. 45FR67018 007. 80/10/22 1p 06899 050.

8011050239 Comments on proposed rule 10CFR20 re disposal of low level radwastes. Concentration units for liquid scintillation waste are in mCi per milliliter
DICEY, B. B. Michigan, Univ of. 45FR67018 008 80/10/20 3pp 06899 051.

8011050251 Comments on proposed rule 10CFR50 re three options for resuming issuance of CPs Option 1 should be implemented for CP application currently on file & backfit requirements of NUREG-0660.
ROHLEY, C. W. Affiliation Unknown. 45FR65247 001 80/10/20. 2pp. 06899 019

8011060034 Forwards notice of proposed rulemaking re 10CFR30.32.70 & 130 which establishes exemptions from licensing & regulatory requirements for persons using Tc-99 or low enriched U in smelted alloys W/o encl
MINOQUE, R. B. Office of Standards Development, Director. 80/10/17 3pp.

8011060408 ORNL/E18-156/V1
"Selected Annotated Bibliography of Studies re Isolation of Nuclear Wastes." Vol 1.
HYDER, L. K., FORE, C. S., VAUGHAN, N. D. Oak Ridge National Laboratory ORNL/E18-156/V1 80/09/30 500pp Available at NTIS. 06910 001

8011060412 ORNL/E18-133/V2
"Low Level Radwaste Technology, Selected Annotated Bibliography." Vol 2
ORE, C. S., VAUGHAN, N. D., HYDER, L. K. Oak Ridge National Laboratory ORNL/E18-133/V2 80/10/31 310pp Available at NTIS 06910:001.

1070324 Ltr to all matl licensees & addressees advising that NRC is considering amend of regulations to permit greater leeway in disposing liquid scintillation media & animal carcasses containing tritium or C-14
UNNINGHAM, R. E. Division of Fuel Cycle & Material Safety 5FR67018. 80/10/10 4pp 06910:001.

8011000438 Motion to strike part of Scientists & Engineers for Secure Energy 801006 pleading re suggestions as to record Evaluation of issues not authorized in present stage of rulemaking W/Certificate of Svc.
BIALIK, E. I., ABRAMS, R. New York, State of 80/11/03 7pp. 06929 324

8011000616 Motion for withdrawal of NRC 801001 request for Quotation RS-NMS-81-032. "Technical Support for Conference Rulemaking Proceeding" Participants must approve & comment on document issued w/o prior notice Certificate of Svc encl
BIALIK, E. I., ABRAMS, R. New York, State of 80/11/03 11pp 06916:001

8011000650 Comments on proposed rule 10CFR20 re disposal of radwastes. Rule will benefit public by reducing costs incurred by hosps & biomedical research inst
REBA, R. C. George Washington Univ Medical Center Wash DC 45FR67018 013. 80/10/23 1p. 06944 097

8011000662 Comments on proposed rule 10CFR20 re radwaste disposal Supports rule
BATES, H. R. Vet Admin Hosp Wash, D C 45FR67018 014 80/10/24 1p 06944 096

8011000666 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing H-3 & C-14 into sewer sys Establishing de minimus level eliminates transportation costs
CULVER, C. Vet. Admin Medical Center Ann Arbor, MI. 45FR67018 015. 80/10/21 2pp 06944 094

801100070 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing H-3 & C-14
SIEGEL, B. A. Washington Univ. Medical Center St. Louis, MO 45FR67018 016. 80/10/27 1p 06944 093

801100074 Comments on proposed rule 10CFR20 re disposal of specific wastes Wastes should be expanded to include medium, general trash, gloves, disposable protective garb, absorbent paper & other combustible matl
HAIRR, G. M. Environmental Protection Agency. 45FR67018 017 80/10/27. 1p 06944 092.

801100081 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing H-3 & C-14 Rule represents acceptable & responsible approach.
HCCRACKEN, R. C. Vet. Admin Hosp. Bronx, NY. 45FR67018 018 80/10/27 1p 06944 091

801100086 Comments on proposed rule 10CFR20 re disposal of radwastes by release to sewage sys Disposal method poses no risk to health or safety of public & would conserve waste burial capacity.
RAJWAN, R. Q. Ohio State Univ 45FR67018 019. 80/10/27. 2pp 06944 089.

801100092 Comments by Interex Corp on proposed rule 10CFR20 re disposal of low level tritium & C-14 Sewer sys disposal of liquid scintillation waste has resulted in contamination of water sources Change should not be adopted.
ROSENBERG, J. Affiliation Unknown 45FR67018 020 80/10/28. 1p. 06944 088

8011010122 Comments on proposed rule 10CFR2. "Proposed General Statement of Policy & Procedure for Enforcement Actions" Statement should give equal weight to backgrounded, training & supervision of mgt & operations staff.
DAVENS, E. Affiliation Unknown 45FR66754 004 80/10/31 2pp 06913:001.

8011010130 Comments on proposed rule 10CFR20 re disposal of liquid scintillation vials & animal carcasses containing H-3 & C-14 Rule will prolong lifetime of burial sites & decrease disposal costs
TRIPODES, J. O., NABOR, W. O. California, Univ of, Los Angeles 45FR67018 009 80/10/21. 1p 06944 087

8011010136 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & contaminated animal carcasses. Supports rule. Suggests issuance of reg guide describing acceptable disposal methods.
STRACCI, F. P. Union Carbide Corp 45FR67018 010 80/10/24 1p 06944 086.

8011010144 Comments by MT Dept of HEW on proposed rule 10CFR20 re disposal of radwastes containing H-3 & C-14. Changes will reduce & simplify work involved in disposing of radwastes & substantially reduce vol of waste shipped out for burial
BERGMAN, R. K. Montana, State of. 45FR67018 011 80/10/23 1p. 06944 085

NONDOCKETED ITEMS

801110150 Comments on proposed rule 10CFR20 re disposal of C-14 Rule should not be limited to liquid scintillation media & animal carcasses
WEATHERBEE, L. Vet. Admin. Medical Center Ann Arbor, MI 45FR67018 012 80/10/22 1p 06944 084

801110162 Forwards comments on proposed rules 10CFR50.51 & 100 re siting criteria & NUREG-0429, "Rept of Siting Policy Task Force " Criteria should substantially support using existing sites to meet addl nuclear needs
MILLER, L. M. Tennessee Valley Authority 45FR50350 063. 80/10/21 4pp 06915 001

801110177 Comments on proposed rule 10CFR2 re general statement of policy & procedure for enforcement actions Use of Roman numerals is confusing
ZIMMERMAN, S. R. Affiliation Unknown 45FR66754 002 80/10/22 1p 06918 001

801110184 Comments on Proposed rule 10CFR2 re proposed general statement of policy & procedures for enforcement actions. Opposes implementation of rules w/o clarification of regulations of which bureaucracy has jurisdiction
PEEPLES, W. P. Gulf Nuclear, Inc 45FR66754 003 80/10/29 3pp 06944 081.

801110192 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedure for enforcement actions Bone rewording is needed
MATTINGOE, J. J. Sacramento Municipal Utility District. 45FR66754 005 80/10/30. 1p. 06944 080

801110201 Comments on proposed rules 10CFR50.51 & 100 re siting policies. Supports congressional intent of establishing new siting guidelines Requests that NRC include siting impact evaluation w/new siting criteria developed under program
EDWARDS, D. W. Yankee Atomic Electric Co 45FR50350 065 80/10/28 3pp 06949 224

801110210 Forwards comments on proposed rules 10CFR50.51 & 100 re mod of policy & regulatory practice governing siting of nuclear power reactors.
EMERY, R. C. Housing & Urban Development, Dept. of 45FR50350 064. 80/10/23. 7pp 06949 227.

801110199 Response in opposition to introduction of NRC 801001 NRC RFO RS-NMH-B1-032 re reliance on outside consultants Urges that Scientists & Engineers for Secure Energy 801006 filing be stricken & 801016 contract cancelled H/Certificate of Bvc
WEISS, E. R., JORDAN, W. B. Natural Resources Defense Council
WEISS, E. R. New England Coalition on Nuclear Pollution 80/11/07 12pp 06946 267.

801110611 Motion by CA Energy Commission & CA Dept of Conservation in opposition to NRC 801001 FRQ RS-NMH-B1-032 re reliance on outside consultants Priority must be given to participants' filings in present rulemaking Certificate of Bvc encl
VARANINI, E. E., GREW, P. C. California, State of 80/11/05 9pp. 06945 328.

801110640 Responds to Item 1a of 800630 memo discussing BECY-80-153, re proposed rulemaking on reactor siting Requested site evaluations will be included in SERs for applicable CP & OL applications. Related matl encl.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/09/05. 15pp 06945 070

8011120086 Comments on proposed rule 10CFR20, "Stds for Protection Against Radiation." Supports regulation All solvents should be included.
BRIQUET, H. C. Indiana Univ 45FR67018 025. 80/10/23 1p 06953 312.

8011120088 Comments by Mary Hitchcock Memorial Hosp on proposed rule 10CFR20, "Stds for Protection Against Radiation " Supports rule.
FILIMONOV, A. Affiliation Unknown. 45FR67018 027 80/10/29 1p. 06953 311.

8011120090 Comments by IN State Board of Health on proposed rule 10CFR20 re radwaste disposal. Supports changes that would treat liquid scintillation vials & animal tissues as normal wastes.
STOCKS, H. Indiana, State of. 45FR67018 028 80/10/29 1p. 06953 310.

8011120091 Comments by IN State Board of Health on proposed rule 10CFR20. Supports changes that would treat most liquid scintillation vials & animal tissue as normal wastes
KONOPINSKI, V. J. Indiana, State of. 45FR67018 029. 80/10/29. 1p. 06953 309.

8011120094 Comments on proposed rule 10CFR20 re radwaste disposal Radiation hazard is less than chemical & pathogenic hazards which workers are exposed to in packaging matl for shipment & burial
MCCLROY, N. L. American Association of Physicists in Medicine 45FR67018 024 80/10/30 1p 06953 308

8011120099 Comments on proposed rule 10CFR20 re radwaste disposal Decreases monies spent for burial sites Reduces risk of accidental leakage during shipment
COOK, S. A. Cleveland Clinic Cleveland, OH 45FR67018 022 80/10/2 1p 06953 307

8011120106 Comments on proposed rule 10CFR20 re dumping of 480,000 cubic ft of low level radwaste Rule shows govt disregard for citizens
CONNELLY, O. Affiliation Unknown 45FR67018 021. 80/10/26 3pp 06916 001

8011120110 Comments on proposed rule 10CFR20 re radwaste disposal Negligible environ & individual radiological impact demonstrates viability of action w/o compromising general public welfare
MOORE, R., LOPRESTI, D. A., MAB, P. J. Hartford Hosp Hartford, CT 45FR67018 023 80/10/22 1p 06953 291.

8011120121 Comments by Veterans Administration Medical Ctr, Chicago, I on proposed rule 10CFR20 re radwaste disposal Rules should be extended to include "bacter" vials containing less than 2 mCi C-14 per vial & animals containing 1-125, 1-131 & P-32.
HENDERSON, W. J. Affiliation Unknown. 45FR67018 026 80/10/27 1p 06953 305

8011120124 Comments on proposed rule 10CFR20 re disposal of trace amounts of H-3 & C-14 Supports rule
COX, E. C. Princeton Univ 45FR67018 030 80/10/30 1p 06953 304

8011120131 Comments by American Board of Nuclear Medicine on proposed rule 10CFR20, "Stds for Protection Against Radiation " Rule maintains safety of disposal & relieves medical community of unnecessary stringent regulations.
ROSS, J. F. Affiliation Unknown 45FR67018 031 80/10/28 1p 06953 304

8011120135 Comments on proposed rule 10CFR20, re radwaste disposal Rule will alleviate high cost of shipping large vol of low level radwastes Supports rule
HENDEE, W. R. Society of Nuclear Medicine. 45FR67018 036 80/10/ 1p 06953 303

8011120140 Comments by Boehringer Ingelheim, Ltd on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing H-3 or C-14 Supports rule
KEIRNS, J. J. Affiliation Unknown 45FR67018 032. 80/10/30. 1p. 06953 302

8011120153 Comments on proposed rule 10CFR20 re low level radwaste disposal. Rule reduces low level radwaste problems from both burial site & generators of radwaste.
RICHARD, M. Indiana Univ Medical Center Indianapolis, IN 45FR6 033. 80/10/20 2pp 06953 300

801112015B Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tracer levels of tritium or C-14 Rule should include other matls to avoid separating solutions containing other isotopes.
MUSE, L. A. Georgia, Univ. of. 45FR67018 034. 80/10/30 2pp 06953 298

8011120162 Comments by Radiation Safety Engineering on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses Rule should be modified to include all solid radioactive matls based on isotope radiotoxicity
METZGER, R. L. Affiliation Unknown 45FR67018 035 80/10/29 2p 06953 296.

8011120167 Comments on proposed rule 10CFR20 re disposal of low level C-14 & H-3 wastes. Rule should be extended to include C-14 labeled culture media which contains no more than 2 mCi.
Supports rule
BOLARI, A. J. Michigan, Univ. of. 45FR67018 037 80/10/27. 2pp 06953 294.

8011120172 Comments on proposed rule 10CFR20 re disposal of liquid scintillation vials & animal carcasses as nonradwaste Consideration should be given to ways to apply concept to other wastes such as paper & gloves.
WEGST, W. California, Univ. of. Los Angeles 45FR67018 038. 80/10/29. 1p. 06953 293.

NONDOCKETED ITEMS

- 801120170 Comments on proposed rule 10CFR20 re stds for protection against radiation Opposes rule
BUHREVER, K J Affiliation Unknown 45FR67018 039 80/10/30 1p.
06953 292
- 801130291 Comments on proposed rules 10CFR21, 19, 20, 21, 30, 40, 51, 60 & 70 re development of geologic repositories for disposal of radwastes.
COOK, N O California, Univ of, Berkeley 44FR70408 019 80/02/28 2pp
- 801140579 Notification of contract execution. "Technical Assistance to Working Group on Commission Waste Mgt Basis for Confidence Proceeding (Re Safe Waste Disposal)," awarded to Teknekron Research, Inc
PLEENOR, C M Administrative Contracts Branch. FIN 8-1314
NRC-19-81-491 80/10/28 1p 06963 219
- 801140586 Contract "Technical Assistance to Working Group on Commission Waste Mgt Basis for Confidence Proceeding (Re Safe Waste Disposal)," awarded to Teknekron Research, Inc
COHEN, S Teknekron, Inc PERLMAN, J Administrative Contracts Branch FIN 8-1314. NRC-19-81-491. 80/10/28 5pp 06963 220.
- 801170231 Response in support of State of NY motion urging withdrawal of requests for quotations which allow evaluation of record by unknown consultants NRC explanation required Certificate of Src encl
MUCHNICKI, E D Ohio, State of 80/11/10. 6pp 06982 026
- 801170426 Ack receipt of State Planning Council on Radwaste Mgt 800917 comments on proposed rule 10CFR60 re disposal of high level radwastes in geologic repositories. NRC analysis of comments will be publicly available
AHEARNE, J F. Commissioners 80/10/23 1p 06975: 131
- 801170437 Forwards State Planning Council on Radwaste Mgt comments on proposed rule 10CFR60 re disposal of high level radwastes in geologic repositories. Effective means for participation of State, local & tribal govts urged.
RILEY, R W Affiliation Unknown 80/09/17 8pp 06975: 132
- 01170695 Forwards FR notice of proposed rulemaking & DEB re exemption of Tc-99 & low enriched U as residual contamination in smelted alloys Comment period ends 801211 for proposed rule & 801242 for DEB W/o encl
MINDOUE, R B. Office of Standards Development, Director 45FR70874 80/10/28 1p 06972.348
- 801170701 Forwards DEB, NUREG-0518, re proposed rulemaking to exempt from licensing requirements smelted alloys containing residual Tc-99 & low enriched U. FEB will be prepared & forwarded after comment period ends
MALARD, J C Transportation & Product Standards Branch 45FR70874 80/10/23 2pp 06972.349
- 1180022 Requests findings & other info needed for MN Environ Quality Board to monitor rulemaking proceeding re radwaste storage & disposal Board 800918 order encl
BENNER, R Minnesota, State of 80/10/31 3pp 06985 239.
- 1180028 Forwards DOE replies to WI State officials indicating that Document ONWI-80 does not reflect DOE position re rulemaking proceeding on storage & disposal of radwaste. Certificate of Src encl
IRDWIN, O Energy, Dept of 80/11/06 18pp 06987: 155
- 1180196 Notification of contract execution, Mod 1 to "Technical assistance to Working Group on Commission Waste Mgt Basis for Confidence Proceeding (re Safe Waste Disposal)"
contractor: Teknekron Research, Inc
LEENOR, C M Administrative Contracts Branch FIN 8-1314
RC-19-81-491 80/10/28 1p 06987: 259
- D1180203 Mod 1, extending period of contract, to "Technical Assistance to Working Group on Commission Waste Mgt Basis for Confidence Proceeding (re Safe Waste Disposal)"
* Teknekron, Inc. PERLMAN, J Administrative Contracts Branch
FIN 8-1314 NRC-19-81-491 80/10/28 1p 06987.260
- 190038 Responds to 800808 request for info for NRDC lawsuit alleging 1978 amendments to 10CFR21. There is no valid reason for extending 10CFR21 to commercial grade components used in clean facilities LER list forwarded
NTON, H R Office of Nuclear Reactor Regulation, Director
10/9/15 3pp. 06999 165
- 801190045 Requests LER examples for NRDC lawsuit challenging 1978 amendments to 10CFR21 Defense wishes to determine if application of 10CFR21 to suppliers of commercial-grade items would forestall component defects Brief excerpt encl
ETLPERIN, S Office of the General Counsel 80/08/08 12pp 06999: 168
- 801190275 Motion in support of State of NY 801103 motion for withdrawal of NRC quotation requests for working group in rulemaking proceeding re radwaste storage & disposal
OLSON, J F, BENECHAL, M E Minnesota, State of 80/11/12 1p 06999 348
- 801200361 SECY-78-044
Discusses issuance of proposed effective amend to 10CFR50 App E re emergency plans for production & utilization facilities Requests approval of proposed amend Draft FR notice & congressional ltr encl
MINDOUE, R B Office of Standards Development, Director 78/01/25 14pp 07018 290
- 801200369 Comments on proposed issuance of effective amend to 10CFR50 App E re emergency plans for production & utilization facilities Second sentence needs mod if concept of generic protective action zones is adopted Concurs w/rule change
RYAN, R Q Office of State Programs, Director 77/12/09. 3pp 07018 304
- 801200372 Provides clarification of one point in response to comment on proposal re implementing certain study group recommendations on improving nuclear power plant licensing
Intervenor should be invited to attend local meetings
BRADFORD, P A Commissioners 78/01/24 3pp 07018 308
- 801200383 SECY-78-044A
Discusses issuance of proposed effective amend to 10CFR50 App E re emergency planning outside low population zone Requests approval of proposed amend. Draft FR notice & congressional ltr encl
MINDOUE, R D Office of Standards Development, Director. 78/05/30 17pp. 07018 241
- 801200388 Comments on proposed issuance of effective amend to 10CFR50 App E re emergency plans for production & utilization facilities Second sentence needs mod if concept of generic protective action zones is adopted Concurs w/rule change
RYAN, R Q Office of State Programs, Director 77/12/09 3pp. 07018: 261
- 801200391 Comments on issuance of proposed effective amend to 10CFR50 App E re emergency plans for production & utilization facilities Problems w/amend re fuel cycle facilities will as 10CFR100 limits are not used Provides addl paragraph
SMITH, C V Office of Nuclear Material Safety & Safeguards 77/12/19 1p 07018 266
- 801200395 Comments on proposed effective amend to 10CFR50 App E re emergency planning requirements outside reactor low population zone. Proposal should be modified to incorporate several changes Proposal, as is, would not amend 10CFR100
KELLEY, J L Office of the General Counsel 78/02/14. 6pp 07018: 268
- 801200402 Comments on Ofc of General Counsel objections to issuance of proposed effective amend to 10CFR50 App E re emergency planning requirements outside reactor low population zone Recommends incorporation of SRP
SHAPAR, H K Office of the Executive Legal Director 78/03/02 11pp 07018: 275.
- 801210007 Comments on proposed rule 10CFR50 re proposed licensing requirements for pending CP & mfg license applications. Rule is premature & unnecessary
LEWIS, M I Affiliation Unknown 45FR65247 003 80/11/07 5pp 02227 001
- 801210011 Comments on proposed rule 10CFR2 re enforcement action policy Severity level concept of violation is confusing Fines should be leveled as last resort after appropriate warnings have been made
BOYD, R M Georgia Institute of Technology 45FR66754 006 80/11/04 1p. 07033 178
- 801210014 Comments on proposed rule 10CFR50 for pending CP & mfg license applications Unclear whether Option 3 could lead to granting of new CP before rulemaking on siting is final.
ROTHLEBERGER Interior, Dept. of. 45FR65247 002 80/11/05 1p 07033 177.

NONDOCKETED ITEMS

289

8011210026 Comments on proposed rule 10CFR2 re notice of public meetings on NRC enforcement policy NRC should postpone planned schedule of meeting for six months
HUBER, S A SAHCL, Stan A Huber Consultants, Inc 45FR6754 007 80/11/03 2pp 07033 175

8011210045 Supplis 801031 comment on proposed rule 10CFR2 re general statement of policy & procedure for enforcement actions.
Forwards NY Sunday Times 801102 illustration of point made in previous ltr re "incident" at Indian Point
DAVENS, E Affiliation Unknown 45FR6754 004 80/11/04 2pp 07033 171

8011210060 Transcript of ACRS Subcommittee on Radwaste Mgt 801113 meeting in Washington, DC re proposed rulemaking on storage & disposal of nuclear waste & 1982 research budget for waste mgt Pp 1-167
* ACRS - Advisory Committee on Reactor Safeguards 80/11/13 181pp 07031 005

8011210121 Forwards notice of "NRC Enforcement Policy - Public Meetings" to be published in 801017 FR
CHILK, B J Office of the Secretary of the Commission 80/10/14 1p 07032 325

--8011210128 Forwards "NRC Enforcement Policy - Public Meetings" For transmittal to Ofc of FR for publication
THOMPSON, D Office of Inspection & Enforcement, Office of the Director 80/10/14 1p 07032 326.

--8011210141 Notice of dates & locations of public meetings re NRC enforcement policy
THOMPSON, D Office of Inspection & Enforcement, Office of the Director 80/10/14 3pp 07032 327

8011210305 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Rule is appropriate & should be extended to low level dry waste
EVRAETS, J C California, Univ of, Los Angeles, 45FR67018 040 80/10/31 1p 07032 298

8011210309 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Provision could be extended to almost any beta &/or photon emitting radionuclides w/o affecting radiation safety.
THOMAS, J H Pennsylvania, Univ of 45FR67018 043 80/10/30. 2pp. 07032 296

8011210317 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Supports rule
BYERS, B Washington, Univ of 45FR67018 045 80/10/31 1p 07032 295

8011210321 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Change constitutes major improvement in effective waste mgt Supports rule
HODDER, D T Proctor & Gamble Co 45FR67018 050. 80/10/31. 2pp 07032-293

8011210327 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Rule should include biological samples removed from carcasses, such as blood & urine
NELP, W B, Washington, Univ of 45FR67018 044 80/11/03 1p 07032.292

8011210333 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 NRC should consider extending concept to include other low level dry radwaste & liquid radwaste
KLOEFFINO, R J, San Jose State Univ 45FR67018 051 80/11/03 1p. 07032 291

8011210339 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Rule should be extended for other solid low level wastes such as column or thin layer chromatography media
SCHNEIDER, P B Massachusetts, Univ of, Medical School. 45FR67018 049 80/11/03. 1p. 07032-290.

8011210346 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Alleviates waste disposal problems w/little or no adverse environ impact
MATTOX, A Brandeis Univ. 45FR67018 047. 80/11/03. 2pp 07032 288.

8011210353 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Supports rule
CRABTREE, R E Affiliation Unknown 45FR67018 046 80/11/06 1p 07032 287

8011210656 Comments by AZ Radiation Regulatory Agency on proposed rule 10CFR20 re changes of regulations on disposal of radwaste from medical research. De minimus levels for other isotopes should be considered.
TEDFORO, C F Arizona, State of 45FR67018 048 80/10/31 3p 07029 145

8011240194 Motion requesting that Commission withdraw all requests for quotation & cancel contracts re solicitation of technical support for Working Group of NRC staff Also joins NRDC-New England Coalition on Nuclear Pollution 801107 motion
O'NEILL, J P Affiliation Unknown 80/11/14 1p 02227 001

8011240420 NUREG-0857
"Analyses of Comments on 10CFR72 "
REISENHEAVER, D Fuel Process Systems Standards Branch 80/11/30 450pp Available at NTIS. 07045.170

8011240421 Forwards summary of public comments re criteria in 10CFR140 for determining extraordinary nuclear occurrences
PETERSON, H T Office of Standards Development, Director 80/11/07 12pp 07049 040.

8011250041 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 & on NUREG-0483 re decontamination & disposal
Indicates that public cannot look to NRC for protection
BROSB, I J, Roswell Park Memorial Institute 45FR67018 060 80/11/03 10pp 07055.126.

8011250048 Comments by American Hosp Association on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Rule should be included in rule Supports rule.
FLANAGAN, R J Affiliation Unknown 45FR67018 061 80/11/04 2pp 07055:124.

8011250070 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule should be extended to include solid wastes, specifically animal bedding, at same levels Supports rule
NORTON, M E Texas, Univ of, Cancer Center 45FR67018 063 80/11/03 1p. 07056 179

8011250076 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Rule should include waste experimental plant materials Supports rule
MARSHALL, P E, Michigan, Univ of 45FR67018 064 80/11/03 1p 07056 178

8011250082 Comments by Boehringer Ingelheim, Ltd on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Rule would be helpful in R&D aspects of biomedical research Supports rule.
JAKUBOWSKI, C W Affiliation Unknown 45FR67018 065 80/11/06 1p. 07056 177

8011250086 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
KUCHELAPATI, R, Princeton Univ. 45FR67018 066 80/11/06 1p 07056 176.

8011250091 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Similar case can be made for other radionuclides such as I-125, Cr-51, Ce-141 & Br-85 Supports rule
SLABACK, L A Defense, Dept. of, Defense Nuclear Agency 45FR67018 067 80/11/07 1p. 07056 175

8011250113 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Poses no significant risk to public health & safety & will mitigate disposal problem Rule should be adapted
WOOLFENDEN, J M, Arizona, Univ. of 45FR67018 069 80/11/06. 1p 07056:156.

8011250120 Comments by State of UT, Dept of Health on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14. Supports rule.
HASQIN, J D Utah, State of. 45FR67018 068 80/11/03. 1p 07056:155.

NONDOCKETED ITEMS

8011250124 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Supports rule
O'SHAUGHNESSY Affiliation Unknown 45FR6701B 070 80/11/10 1p
07056 154

8011250125 Comments on proposed rules 10CFR30.51 & 100 re reactor siting Type & power of reactor, inherent characteristics, containment & protective sys. should be taken into account when considering proposed location
GAUNT, J United Kingdom 45FR30330 066 80/11/06 2pp.
07056 145

8011250133 Comments on proposed rule 10CFR20 re disposal of liquid tritium & C-14 wastes generated by biomedical research. Local incineration is more preferable solution, if properly monitored Supports rule
FOLK, W R Michigan, Univ of 45FR6701B 071 80/11/04 1p
07056 153

8011250139 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Questions if rule includes other glassware exposed to low radioactive liquids Supports rule
PRICE, A R Michigan, Univ of. 45FR6701B 072 80/11/06 1p
07056 152

8011250146 Comments by State of IN Board of Health on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Supports rule
HERT, O M Indiana, State of 45FR6701B 073, 80/11/07 1p
07056 151

8011250154 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Supports rule
SPITZNAGLE, L A Maryland, Univ of, Baltimore 45FR6701B 074, 80/11/05 1p 07056-149

8011250160 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Rule will reduce costs & free considerable space in limited areas available in open burial grounds.
D'AMARA, R E Rochester Univ. of 45FR6701B 075 80/11/05 1p
07056 148

8011250169 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Protests rule
IRELAND, C D Affiliation Unknown 45FR6701B 076 80/11/08 1p
02227 001

11260004 Request for stay of effectiveness of App E to 800811 final rule on emergency planning requiring 15-minute notification of all within exposure pathway EPZ pending DC Court of Appeals review Certificate of Svc encl
BROWNE, R C Duke Power Co BROWNE, R C Debevoise & Liberman 80/11/12 19pp. 07075 246

8011260009 Affidavit re cost util will incur if 15-minute warning requirement is not stayed Prof qualifications encl
TUCKER, H B Duke Power Co. 80/11/03 App 07075.26D

1260095 Forwards summary of public comments received on code criteria for determining extraordinary nuclear occurrence. Comments include Public Citizen Litigation Group & Critical Mass Energy Project petition.
EVERSON, H T Radiological Health Standards Branch 80/11/07, 2pp 07071 325.

1260165 Request for reconsideration of App E to 800811 final rule on emergency planning requiring 15-minute notification of all within exposure pathway EPZ Requests hearing to address ques & stay of rule effectiveness Certificate of Svc encl
OWNE, R C Duke Power Co. BROWNE, R C Debevoise & Liberman 7/11/12 11pp 01741 019

11260172 Forwards WR Stratton, AP Malinauskas & DO Campbell 800814 ltr questioning NRC assumptions re post-accident iodine release. Requests review & comment Excerpts of 800814 public hearing in Washington, DC encl
ICKLESIMER, H Fuel Behavior Branch 80/09/05 32pp 01741 019

80401 Comments on proposed rule 10CFR20 re disposal of low level 4 & tritium wastes. Supports rule
CKSON, R.P. Michigan, Univ. of, Medical School 45FR6701B 079, 11/04 1p 07075 321.

8011260408 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Rule will effect 20% reduction in hosp current cost for disposal Supports rule
FEARS, J R Vet Admin Hosp Hines, IL 45FR6701B 080 80/11/06 1p 07075 322

8011260412 Forwards comments on proposed rule 10CFR20 re disposal of liquid scintillation waste containing tritium or C-14 Proposed change is excellent but level should be changed to 0.02 uCi/g instead of 0.05 uCi/g
WALKER, J Affiliation Unknown 45FR6701B 081 80/11/10 6pp
07075 323

8011260415 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14
RYBKIENICH, D P CIBA-GEIGY Corp. 45FR6701B 082 80/11/07 2pp
07075 329

8011260417 Comments on proposed rule 10CFR20 re disposal of low level radwaste Supports rule
ELY, R L Research Triangle Institute 45FR6701B 083, 80/11/10, 1p 07075 330

8011260420 Comments on proposed rule 10CFR20 re disposal of liquid scintillation media & animal carcasses containing tritium & C-14 Supports rule.
BOTT, J V Affiliation Unknown 45FR6701B 084 80/11/05 1p
07075.331

PRM PETITION FOR RULEMAKING

8011120577 Comments on petition for rulemaking 71-8 requesting exemption from requirement that licensee possess all documents in application when using package Recommends denial of petition
HENRY, J J Transportation & Product Standards Branch 45FR39519 80/10/30 2pp 06915 001

8011190038 Responds to 800808 request for info for NRDC lawsuit challenging 1978 amends to 10CFR21. There is no valid reason for extending 10CFR21 to commercial grade components used in nuclear facilities LER list forwarded
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/09/15, 0pp 06999 165.

--8011190045 Requests LER examples for NRDC lawsuit challenging 1978 amends to 10CFR21 Defense wishes to determine if application of 10CFR21 to suppliers of commercial-grade items would forestall component defects Brief excerpt encl.
EILPERIN, S Office of the General Counsel 80/08/08, 12pp. 06999 168.

8011200488 Forwards OA Co filing of petition for rulemaking 30-57 to be published in 801014 FR
CHILK, S J Office of the Secretary of the Commission 80/10/08 1p 07017 276.

8011260095 Forwards summary of public comments received on code criteria for determining extraordinary nuclear occurrence. Comments include Public Citizen Litigation Group & Critical Mass Energy Project petition
PETERSON, H T Radiological Health Standards Branch, 80/11/07 12pp. 07071 325

PROJ PROJECTS - PREDOCKET LICENSING

8011030665 Responds to NRC 800805 ltr inviting comment on proposed amend to 10CFR70 State of NM has no written comment
WOLFF, T A New Mexico, State of 80/08/26, 1p / 06873 038

8011040021 Comments on proposed amend to 10CFR71 requiring advance notification to state governors of transportation of nuclear waste to, through or across state boundaries Supports rule
DUNKLEBERGER, J New York, State of, 80/08/27 2pp. 06884 067.

8011040024 Comments on Appropriation Authorization Act, Section 301, requiring that state governors receive notification prior to radwaste shipments. Notification should take place two working days before waste shipment.
PARENT, C D Affiliation Unknown 80/10/29, 2pp 02319 196

8011040026 Comments by OR DOE on proposed amends to 10CFR71. Supports requirement for notification of state prior to radwaste shipments exceeding Type A quantities. Std notification form should be designed & used
FRANK, L Oregon, State of 80/08/22, 2pp 06884 067.

8011040028 Comments by ND State Health Dept on proposed amend to 10CFR71. Words "&/or his designee(s)" should be added following "governor" as individuals to be notified
HUNT, D.K. North Dakota, State of 80/08/28 1p 06884-066

8011040169 Comments by CA Dept of Health Svcs on proposed amend to 10CFR71: route & stopover details requirement should be incorporated into amend
WARD, J.D. California, State of 80/08/26 1p 06874-033.

8011040222 Comments on proposed amend to 10CFR71 re advance notification of radwaste shipments. Supports amend.
BROWN, J.Y. Kentucky, State of 80/08/29 1p 06874-043.

8011040227 Comments by GA Dept of Human Resources re advance notification to state governors of nuclear waste shipments. Agrees w/new rule. State rules on transportation of hazardous mats encl.
BIMANIS, A. Georgia, State of 80/08/21 9pp 06874-035.

8011040231 Comments by ID Dept of Health & Welfare on proposed amend to 10CFR71 requiring prior notification to state governors of radwaste shipments. Intent of regulation is ambiguous.
FUNDERBURG, R.D. Idaho, State of 80/08/13 1p. 06874-034.

8011040235 Comments by SC Dept of Health & Environ Control on proposed amend to 10CFR71 requiring that state governors receive prior notification of radwaste shipments.
HEALY, H.O. South Carolina, State of 80/08/22 2pp. 06874-032

8011040242 Comments by NV Dept of Human Resources re notification of state governors prior to radwaste shipments. Disagrees w/concept that Type A quantities of radioactive matl could never pose significant health hazard
DIBBIO, R.R. Nevada, State of 80/08/20 2pp. 06874-030.

8011050121 Comments by State of KS Dept of Health & Environ on proposed amend to 10CFR71. Suggests program involving state matl licensing agencies, emergency response agencies & traffic control could be developed.
ALLEN, O.W. Kansas, State of 80/08/13 2pp. 06898-344

8011050140 Comments by State of AZ Radiation Regulatory Agency on proposed amend to 10CFR71 re advance notification to state governors of radwaste shipments. Routing info should also be included. Supports rule
TEOFORD, C.F. Arizona, State of 80/08/18 1p. 06898-346.

8011050145 Comments on Section 301 of S.B. 562 requiring that state governors receive prior notification of radwaste shipments. Governors should be included in routing decision & be notified quarterly of low level waste shipments
STONEY, K. Affiliation Unknown, 80/08/02 2pp 02319-196.

8011050168 Stipulation re PQ&E 780428 request for production of documents directed to CA Dept of Water Resources. Production shall not constitute waiver of objection to possible admissibility at hearing. Certificate of BVC encl.
MEISS, R.L. Pacific Gas & Electric Co. STRUMHABER California, State of 80/10/28 14pp. 06897-315

8011050282 Comments by Salinas for Alternative to Nuclear Energy re amend to Authorization Act requiring that state governors receive prior notification of radwaste shipments. Requests notification include routing, date & time of day & matl.
GRUWER, M., VINT, J., GROTER, C. Affiliation Unknown, 80/08/13 2pp 02319-196.

8011070051 Reports results of investigation conducted per 800315-17 conference re alleged PQ&E transfer of relevant documents to warehouse storage to avoid discovery. Substantial evidence of intentional & improper conduct does not exist.
GOLDBERG, J.R. Antitrust Division ISSUANCES A. 80/11/03 3pp. 06924-318

801110812 Forwards final EIS on U milling. W/o encl.
MCCONNAUGHAY Maryland, State of 17693 80/10/21 1p. 06947-361.

801110816 Ack receipt of final OEIS on U milling. Review will be completed within 32 days.
ROEBCH, R.M. Ohio, State of 17694. 17694. 80/10/21 1p. 06948-020

801120527 Ack receipt of final EIS on U milling. Project will have no effect on properties under control of WA State Parks & Recreation Commission.
HEISER, D.W. Washington, State of 17745 80/10/20 1p. 06953-036

801120629 Offers no negative comments on EIS on U milling
HAYHARD, N. Delaware, State of 17737 80/10/23 1p 06953-037

801120671 Ack receipt of final OEIS on U milling. Review period of 30 days has been assigned
OINMAN, R.A. New Jersey, State of 17693 80/10/15 1p 06953-024

801120678 Ack receipt of final OEIS on U milling. Results of review will be submitted by 801115
* Georgia, State of 17692 80/10/15 1p. 06953-025

801170548 Forwards "Pretest Predictions for FFTF Reactor & Primary Loop Transient Natural Circulation Test from 5% Power."
CARLISLE, C.B. Energy, Dept of 80/11/10 2pp 06979-018

--801170549 Procedure TS-31-SA008, Part 1, "Pretest Predictions for FFTF Reactor & Primary Loop Transient Natural Circulation Test from 5% Power"
NUTT, W.T., HECK, F.M., ADDITION, S.L. Hanford Engineering Development Laboratory, 80/11/03 22pp. 06979-020.

--801170552 Test Spec TS-31-SA008, Revision 4, "Transient Natural Circulation Test"
KNECHT, W.L., NUTT, W.T., HECK, F.M. Hanford Engineering Development Laboratory, 80/11/06 80pp. 06979-042.

--801170556 HEDL-SA-1919FP
Speech entitled "FFTF Primary Bys Transition to Natural Circulation from Low Reactor Power," presented at specialists' 800228-29 meeting re decay heat removal & natural convection in fast breeder reactors.
NUTT, W.T., ADDITION, S.L. Hanford Engineering Development Laboratory, BOUCHEY, O.D. Energy, Dept. of 80/02/29 17pp. 06979-123.

--801170561 TC-177B
"Pretest Predictions of Thermal & Hydraulic Responses of Fuelled Open Test Assemblies to 5% Power Natural Circulation FFTF Plant Startup Test."
JOHNSON, H.O. Hanford Engineering Development Laboratory, 80/08/31 61pp. 06979-140.

801180162 Forwards BW Shackelford 801022 deposition taken by NRC. Examination & signature of deponent requested. W/o encl.
VOGLER, B.M. Antitrust Division. ISSUANCES A. 80/11/13 1p 06987-220.

8011210072 Notification of contract execution, Mod 3 to "Add1 Logistical Support for Stanislaus Nuclear Project, Unit 1, Antitrust Hearings." Contractor: PQ&E.
COLEMAN, R. Administrative Contracts Branch, NRC-10-7B-604, 80/11/10 1p. 07031-209.

--8011210104 Mod 3, extending period of performance, to "Add1 Logistical Support for Stanislaus Nuclear Project, Unit 1, Antitrust Hearings."
BENTON, R.P. Pacific Gas & Electric Co. MATTIA, M.J. Administrative Contracts Branch, NRC-10-7B-604, 80/11/10 1p. 07031-210.

8011280132 Forwards comments on NUREG-0311 re DEB on U milling & criteria for U mill tailings & const of major plants.
LANE, E.A. Atomic Industrial Forum, 80/10/24 71pp. 07083-036.

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

801170807 Updated Part 21 rept re performance of add1 interference checking of all sizes of vendor Part 2341/modifed 2540, Sizes -8, -15 & -120 assemblies contain potential interference which may hinder function of unit
BECKSTED, W.F. Bergen-Patterson Pipe Support Corp. 80/10/29 2pp 06981-283.

PT9 10CFR, PART 9 -

8007280363 Discusses IE insp of Licenses 12-02752-03 & 06 on 800625-26 & forwards notice of violation.
KEPPLER, J.O. Region 3, Chicago, Office of the Director, 80/07/21 2pp 03019-348.

--8007280369 Notice of violation form insp on 800625-26. Noncompliance noted: prescription doses & teletherapy treatments given w/o authorization & individuals receiving excess whole body exposure not properly notified.
* Region 3, Chicago, Office of the Director, 80/07/21 4pp. 03019-350.

NONDOCKETED ITEMS

QA999 QUALITY ASSURANCE INSPECTIONS

- 8011040080 Ack receipt of 800919 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900505/80-02
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/10/20
ip. 06884.296
- 8011040085 Responds to NRC 800818 ltr re deviation noted in QA Program Insp Rept 99900505/80-02 Corrective actions for future contracts on IE bulletin work, 791220 formal compliance support program will be applied.
TENZER,B E Ebasco Services, Inc (subs of Enserch Corp)
80/09/15. 2pp 06884.297
- 8011040087 Forwards QA Program Insp Rept 99900505/80-02 on 800721-25 & notice of deviation
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/08/18.
2pp 06884.299
- 8011040091 Notice of deviation from insp on 800721-25,
* Region 4, Dallas, Office of the Director 80/09/15 2pp
06884.301
- 8011040096 QA Program Insp Rept 99900505/80-02 on 800721-25.
Noncompliance noted, procedures developed for St Lucie Unit 1 re IE Bulletin 79-14 were inadequate & not approved until work was virtually completed.
COSTELLO,J R, AQUEE,J R, HALE,C J Region 4, Dallas, Vendor Inspection Branch IEB-79-14. 80/08/15 10pp. 06884.303.
- 8011040097 Forwards QA Program Insp Rept 99900509/80-04 on 800806-07, No noncompliance noted
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 80/08/21.
ip 06884.313
- 8011040103 QA Program Insp Rept 99900509/80-04 on 800806-07 No noncompliance noted, Major areas inspected, allegation of employing unqualified individual
HERR,R.K., SEYFRIT,K.V. Region 4, Dallas, Office of the Director.
80/08/18 6pp. 06884.314.
- 8011040105 Ack receipt of 800528 ltr & two undated ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900255/80-01.
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/10/20.
ip 06884.320.
- 8011040110 Responds to NRC 800822 ltr re deviation noted in QA Program Insp Rept 99900255/80-01 Corrective actions completed except Deviation B for which manual revision will be issued by Dec 1980
JENKINS,B. Pacific Scientific, Kin-Tech Div. 80/08/22. 1p
06884.321
- 8011040113 Ack receipt of 800528 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900255/80-01 Addl info re completion dates needed in 20 days
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch. 80/08/22
ip. 06884.322
- 8011040118 Responds to NRC 800627 ltr re deviation noted in QA Program Insp Rept 99900255/80-01 Corrective actions customer requirement will be incorporated & Tech Specs will be reviewed in detail to control purchase orders.
JENKINS,B Pacific Scientific, Kin-Tech Div 80/06/27 3pp
06884.323.
- 8011040125 Ack receipt of 800528 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900255/80-01 Addl info re corrective actions to prevent recurrence needed in 20 days.
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/06/27.
ip. 06884.324
- 8011040131 Responds to NRC 800305 ltr re deviation noted in QA Program Insp Rept 99900255/80-01 Corrective actions, new procedure to identify location of thermocouples & pieces implemented & approved by contractor
JENKINS,B. Pacific Scientific, Kin-Tech Div. 80/03/28 2pp.
06884.327
- 8011040135 Forwards QA Program Insp Rept 99900255/80-01 on 800204-08 & notice of deviation.
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/03/05
2pp. 06884.329.
- 8011040138 Notice of deviation from insp on 800204-08
* Region 4, Dallas, Office of the Director 80/03/04 2pp
06884.331
- 8011040148 QA Program Insp Rept 99900255/80-01 on 800204-08 Noncompliance noted QA holdpoint had been bypassed on mfg outline & heat treatment chart trace not identified w/individual piece.
ROBERDS,H.W., HUNNICUTT,D M Region 4, Dallas, Vendor Inspection Branch 80/03/04 5pp 06884.333
- 8011040153 Forwards QA Program Insp Rept 99900114/80-02 on 800812-13, No noncompliance noted
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/09/10
2pp 06884.338
- 8011040156 QA Program Insp Rept 99900114/80-02 on 800812-13 No noncompliance noted Major areas inspected action on previous insp findings, review of QA organization/program & testing of completed products
SUTTON,J H, WHITEBELL,D E Region 4, Dallas, Vendor Inspection Branch 80/09/08. 7pp 06884.340.
- 8011040231 Ack receipt of 800926 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900509/80-03
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch IEB-79-14.
80/10/23 1p 06912.001
- 8011060239 Responds to NRC 800827 ltr re deviation noted in QA Program Insp Rept 99900509/80-03 Corrective actions remaining IE Bulletin 79-14 items shall be expedited re identification of potential overstress condition for piping
KELLY,R.B. Stone & Webster Engineering Corp IEB-79-14
80/09/26 3pp 06912.002
- 8011060245 Forwards QA Program Insp Rept 99900509/80-03 on 800804-08 & notice of deviation.
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch. 80/08/27.
2pp 06912.005.
- 8011060247 Notice of deviation from insp on 800804-08
* Region 4, Dallas, Vendor Inspection Branch IEB-79-14
80/08/27. 1p 06912.007
- 8011060252 QA Program Insp Rept 99900509/80-03 on 800804-08. Noncompliance noted Procedure STF-3 for IE Bulletin 79-14 related work not adequate re sys operability & prompt notification
COSTELLO,J.R., COMPTON,R.M., HALE,C.J. Region 4, Dallas, Vendor Inspection Branch IEB-79-14. 80/08/27 7pp. 06912.008
- 8011060256 Ack receipt of 801009 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 99900003/80-02.
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch. 80/10/23.
ip. 06911.211
- 8011060262 Responds to NRC 800910 ltr re deviations noted in QA Program Insp Rept 99900003/80-02 Corrective actions Procedure 70-33 revised & requirement re storage of nonconforming channels on separate app revised
LEES,E.A General Electric Co. 80/10/09. 3pp 06911.212
- 8011060267 Forwards QA Program Insp Rept 99900003/80-02 on 800819-22 & notice of deviation
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch. 80/09/10.
2pp. 06911.215.
- 8011060269 Notice of deviation from insp on 800819-22.
* Region 4, Dallas, Office of the Director. 80/09/08 1p
06911.217
- 8011060278 QA Program Insp Rept 99900003/80-02 on 800819-22 Noncompliance noted, nonconforming channels not segregated & insp repts not attached per Procedure 70-33.
MCNEILL,H M., WHITEBELL,D.E. Region 4, Dallas, Vendor Inspection Branch. 80/09/08 6pp 06911.218
- 8011060287 Forwards QA Program Insp Rept 99900080/80-01 on 800811-14. No noncompliance noted
POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/09/15.
2pp 06911.233
- 8011060289 QA Program Insp Rept 99900080/80-01 on 800811-14. No noncompliance noted. Major areas inspected: action on previous insp findings, mfg process control, welding control & followup on deficiency repts
OLLER,R.E., BARNES,I Region 4, Dallas, Vendor Inspection Branch. 80/09/12. 11pp 06911.255.

NONDOCKETED ITEMS

293

8011060293 Ack receipt of 800929 ltr re GA Program Insp Rept 9990060/80-02 Returns GA manual & badge used during insp POTAPDVB,U Region 4, Dallas, Vendor Inspection Branch 80/10/17 1p 06911:271

--8011060297 Ack receipt of NRC 800925 ltr re GA Program Insp Rept 9990060/80-02 No proprietary info ABRUZZO,U Target Rock Corp GCL 80-270 80/09/29 1p 06911:272.

--8011060301 Forwards GA Program Insp Rept 9990060/80-02 on 800908-10. No noncompliance noted. POTAPDVB,U Region 4, Dallas, Vendor Inspection Branch 80/09/23, 2pp 06911:273

--8011060307 GA Program Insp Rept 9990060/80-02 on 800908-10 No noncompliance noted. Major areas inspected: applicable codes & stds re design & document control, design computer program verification & welding procedure spec KELLEY, W.D., WHITESELL, D.E. Region 4, Dallas, Vendor Inspection Branch 80/09/19 11pp. 06911:275

8011060313 Forwards GA Program Insp Rept 99900711/80-02 on 800818-21. No noncompliance noted POTAPDVB,U Region 4, Dallas, Vendor Inspection Branch 80/09/18, 2pp 06911:298

--8011060318 GA Program Insp Rept 99900711/80-02 on 800818-21 No noncompliance noted Major areas inspected applicable codes & stds, GA manual review & control for special processes HUNTER, V.H., WHITESELL, D.E. Region 4, Dallas, Vendor Inspection Branch. 80/09/16, 7pp. 06911:300

8011060314 Forwards GA Program Insp Rept 99900289/80-03 on 800813. No noncompliance noted POTAPDVB,U Region 4, Dallas, Vendor Inspection Branch 80/09/12 2pp 06911:307

--8011060321 GA Program Insp Rept 99900289/80-03 on 800813 No noncompliance noted. Major areas inspected review of representative documents & procedures re potential deficiencies WHITESELL, D.E. Region 4, Dallas, Vendor Inspection Branch. 80/09/08 8pp 06911:309

8011060326 Forwards GA Program Insp Rept 99900025/80-03 on 800818-20. No noncompliance noted POTAPDVB,U Region 4, Dallas, Vendor Inspection Branch 80/09/12, 2pp. 06911:319.

--8011060332 GA Program Insp Rept 99900025/80-03 on 800818-20. No noncompliance noted Major areas inspected review & evaluation of reported radiographic deficiencies of welds on nuclear piping assemblies. ROBERDB, H.W., BARNES, I. Region 4, Dallas, Vendor Inspection Branch 80/09/08, 3pp 06911:321

8011060387 Ack receipt of 800820 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900510/80-01 POTAPDVB,U Region 4, Dallas, Vendor Inspection Branch. 80/10/17, 1p. 06914:138.

--8011060392 Forwards revised response to deviation noted in GA Program Insp Rept 99900510/80-01. Corrective actions: memo issued clarifying requirements for proper drawing certification. CURRANE, R A United Engineers & Constructors, Inc. (subs. of Raytheon Co). 80/08/20, 2pp. 06914:139.

801110021 Forwards attachment to GA Program Insp Rept 99900509/80-04 on 800804-07. SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/08/23, 1p. 06944:104.

--801110098 Attachment to GA Program Insp Rept 99900509/80-04 on 800804-07. Discusses 800823 telcon in which EF Haslam provided addl info re Page 4 of draft investigation rpt which contained incorrect employee info. * Region 4, Dallas, Office of the Director. 80/08/23 1p. 06944:103.

801130327 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02 1p. 06938:320

801130331 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02, 1p. 06938:323.

801130333 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/10/02 1p 06938:326

801130335 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02 1p 06938:343

801130337 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/10/02, 1p 06938:346

801130339 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/10/02 1p 06938:349

801130342 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/10/02 1p. 06938:353.

801130345 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02, 1p. 06938:358

801130349 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02, 1p 06960:285.

801130353 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02, 1p. 06960:289

801130357 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/10/02 1p. 06960:296.

801130360 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02, 1p. 06960:299.

801130364 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02, 1p 06960:302

801130366 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02 1p 06960:305

801130370 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02, 1p. 06960:308

801130373 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/10/02 1p. 06960:311.

801130376 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/10/02, 1p. 06960:314.

801130380 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02, 1p. 06938:360

801130383 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02, 1p. 06937:336

801130386 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 80/10/02, 1p. 06937:339.

NONDOCKETED ITEMS

- 8011130390 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/10/02
1p. 06957.342
- 8011130393 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/10/02.
1p. 06957.345
- 8011130397 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/10/02
1p. 06957.348
- 8011170101 Forwards GA Program Insp Rept 99900066/80-01 on 800904-05
No noncompliance noted
POTAPQV8, U. Region 4, Dallas, Vendor Inspection Branch. 80/09/25.
2pp. 06970.355.
- 8011170107 GA Program Insp Rept 99900066/80-01 on 800904-05. No noncompliance noted. Major areas inspected: review & evaluation of reported below min wall thickness condition in bend in feedwater sys piping assembly
BARNES, I. Region 4, Dallas, Vendor Inspection Branch. 80/09/24.
4pp. 06970.357.
- 8011170116 Forwards GA Program Insp Rept 99900056/80-01 on 800728-0801
No noncompliance noted
POTAPQV8, U. Region 4, Dallas, Vendor Inspection Branch. 80/08/25.
2pp. 06981.258
- 8011170124 GA Program Insp Rept 99900056/80-01 on 800728-0801 No noncompliance noted. Major areas inspected: action on previous insp findings; review of vendor activities; internal audits & welder qualifications.
OLLER, R. E., BARNES, I. Region 4, Dallas, Vendor Inspection Branch. 80/08/22. 13pp. 06981.260
- 8011170369 Ack receipt of 801016 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900002/80-02.
POTAPQV8, U. Region 4, Dallas, Vendor Inspection Branch. 80/11/05.
1p. 06975.157.
- 8011170374 Responds to NRC 800922 ltr re deviation noted in GA Program Insp Rept 99900002/80-02 Corrective actions: simulated tack welds to locking discs made per spec requirements.
LICHTENBERGER Combustion Engineering, Inc. NGA 80-013. 80/10/16.
2pp. 06975.158.
- 8011170378 Forwards GA Program Insp Rept 99900002/80-02 on 800909-12 & notice of deviation.
POTAPQV8, U. Region 4, Dallas, Vendor Inspection Branch. 80/09/22.
2pp. 06975.160
- 8011170382 Notice of deviation from insp on 800909-12.
* Region 1, Philadelphia, Office of the Director. 80/09/19. 1p. 06975.162.
- 8011170388 GA Program Insp Rept 99900002/80-02 on 800909-12. Deviation noted: some tack welding of grid cage assemblies was not fully controlled
MCNEILL, W. M., WHITEBELL, D. E. Region 4, Dallas, Vendor Inspection Branch. 80/09/19. 6pp. 06975.163
- 8011170763 Forwards GA Program Insp Rept 99900722/80-01 on 800623-24 & notice of deviation.
POTAPQV8, U. Region 4, Dallas, Vendor Inspection Branch. 80/07/18.
2pp. 06978.335.
- 8011170766 Notice of deviation from insp on 800623-24.
* Region 4, Dallas, Office of the Director. 80/07/15. 1p. 06978.337
- 8011170771 GA Program Insp Rept 99900722/80-01 on 800623-24
Noncompliance noted: master checklist revised to conform w/data on process & cost cards; for new orders w/o changing revision designation or having revision reviewed.
KELLEY, W. D., WHITEBELL, D. E. Region 4, Dallas, Vendor Inspection Branch. 80/07/15. 9pp. 06978.338
- 8011170833 Ack receipt of 800930 ltr informing NRC of steps taken to correct deviation & violation noted in GA Program Insp Rept 99900284/80-01.
POTAPQV8, U. Region 4, Dallas, Vendor Inspection Branch. 80/10/28.
1p. 06978.224.
- 8011170840 Responds to NRC 800904 ltr re deviation noted in GA Program Insp Rept 99900284/80-01 Corrective actions: position of mfg engineer filled on 800801 & instruments/products change notices approved on 800808
LEBLANC, J. V. Sigma Instruments, Inc. International Instruments Div. 80/09/30. 7pp. 06978.225
- 8011170845 Forwards GA Program Insp Rept 99900284/80-01 on 800805-07 & notice of deviation & violation
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/09/04.
2pp. 06978.232
- 8011170850 Notice of violation from insp on 800805-07
* Region 4, Dallas, Vendor Inspection Branch. 80/08/29. 1p. 06978.234
- 8011170852 Notice of deviation from insp on 800805-07
* Region 4, Dallas, Vendor Inspection Branch. 80/08/29. 3pp. 06978.235
- 8011170858 GA Program Insp Rept 99900284/80-01 on 800805-07
Noncompliance noted: practices re unresolved items not consistent w/corrective action response ltr.
FOSTER, W. E., BARNES, I. Region 4, Dallas, Vendor Inspection Branch. 80/08/29. 7pp. 06978.238
- 8011170842 Ack receipt of 800922 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900717/80-01.
POTAPQV8, U. Region 4, Dallas, Vendor Inspection Branch. 80/10/28.
1p. 06979.224
- 8011170848 Responds to NRC 800731 ltr re deviation noted in GA Program Insp Rept 99900717/80-01 Corrective actions: accept/reject status of each line entry on setup & run sample instruction sheet can be determined by circled discrepant dimensions
QUODDY, P. R. Square D Co., Electromagnetic Industries. 80/09/22. 12pp. 06979.225.
- 8011170853 Forwards GA Program Insp Rept 99900058/80-01 on 800625-27 & notice of deviation.
POTAPQV8, U. Region 4, Dallas, Vendor Inspection Branch. 80/08/05.
2pp. 06979.236
- 8011170856 Notice of deviation from insp on 800625-27.
* Region 4, Dallas, Office of the Director. 80/07/31. 2pp. 06979.238.
- 8011170861 GA Program Insp Rept 99900058/80-01 on 800625-27.
Noncompliance noted: audits not performed; ultrasonic test equipment not recalibr & personnel continued to use equipment past recalibr date.
KELLEY, W. D., WHITEBELL, D. E. Region 4, Dallas, Vendor Inspection Branch. 80/07/31. 10pp. 06979.240.
- 8011170862 Ack receipt of 801003 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900228/80-01.
POTAPQV8, U. Region 4, Dallas, Vendor Inspection Branch. 80/10/28.
1p. 06979.250.
- 8011170868 Responds to NRC 800903 ltr re deviation noted in GA Program Insp Rept 99900228/80-01. Corrective actions: Work Instruction CV-0040 written to delineate interface control sys operation at CV-1 & CV-2.
ROGERS, J. E. Kerite Co. (subs. of Harvey Hubbell, Inc.). 80/10/03.
4pp. 06979.251.
- 8011170872 Forwards GA Program Insp Rept 99900228/80-01 on 800819-21 & notice of deviation.
POTAPQV8, U. Region 4, Dallas, Vendor Inspection Branch. 80/09/03.
2pp. 06979.255.
- 8011170875 Notice of deviation from insp on 800819-21
* Region 4, Dallas, Office of the Director. 80/08/29. 3pp. 06979.257.
- 8011170879 GA Program Insp Rept 99900228/80-01 on 800819-21.
Noncompliance noted: operation of interface controls of Continuous Vulcanizing Lines 1 & 2 not prescribed by formal instructions, procedures or drawings.
FOSTER, W. E., BARNES, I. Region 4, Dallas, Vendor Inspection Branch. 80/08/29. 10pp. 06979.260.
- 8011180313 Ack receipt of 800930 & 1013 ltrs informing NRC of steps taken to correct deviation noted in GA Program Investigation Rept 99900727/80-01.
POTAPQV8, U. Region 4, Dallas, Vendor Inspection Branch. 80/11/03.
2pp. 06989.152.

--801180320 Suppls 800930 ltr re deviation noted in GA Program Investigation Rept 99900727/80-01 Corrective actions under remaining employed is properly requalified & certified.
ZALB, A.M. Keene Corp Ray Prook Div 80/10/13 2pp 06989 154.

--801180327 Responds to NRC 800922 ltr re deviation noted in GA Program Investigation 99900727/80-01 Points out that absence of evidence of deliberate intent re falsification of records should be part of insp rept
ZALB, A.M. Keene Corp Ray Prook Div 80/09/30 1p 06989 156.

--801180332 Forwards GA Program Investigation Rept 99900727/80-01 on 800827-28. No noncompliance noted
POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch. 80/09/22 1p 06989 157

--801180340 GA Program Investigation Rept 99900727/80-01 on 800826-28 No noncompliance noted Major area investigated allegations that mgt personnel falsified welder qualifications
HERR, R.K. Region 4, Dallas, Office of the Director
WHITEBELL, D.E., POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 80/09/12, 8pp 06989, 158

REG00 REGULATORY GUIDES

7904180093 Reg Guide 1.8 Revision 2 distribution list Requests addl comments.
MINOQUE, R.B. Office of Standards Development, Director 79/05/21 1p.

8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREG-0425. "Rept of Siting Policy Task Force." Documents 4-B & 13 are available in PDR Forwards remaining documents.
FELTON, J.M. Division of Rules and Records 80/09/04 1p.

--8009190587 SECY-79-362
Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features
MINOQUE, R.B. Office of Standards Development, Director. 79/06/04, 7pp.

801103060 Comments on draft Reg Guide OH 710-4, "Health Physics Surveys in U Mill"
SHELLEY, W.J. Kerr-McGee Corp 80/10/08 3pp. 06837, 106

8011030661 Forwards comments on draft Reg Guide RS 110-5, "Nuclear Power Plant Simulators for Use in Operator Training."
CRANE, P.A. Pacific Gas & Electric Co. 80/10/01. 2pp. 06873, 036

8011030671 Comments on draft Reg Guide OH 941-4, "Info Relevant to Ensuring That Occupational Radiation Exposures at U Mills Will be ALARA"
HERBLOFF, L.W. Rocky Mountain Energy Co ESD 80-1077. 80/09/30, 2pp. 06873, 044.

8011030676 Comments on proposed Revision 1 to Reg Guide 1.23 re onsite meteorological info.
FREDERICK, L.C. Public Service Co. of New Hampshire 80/10/03. 2pp. 06873, 046

8011030697 Comments on draft Reg Guides OH 710-4 & OH 941-4, "Health Physics Surveys in U Mills" & "Info Relevant to Ensuring That Occupational Radiation Exposures at U Mills Will be ALARA," respectively.
HERBLOFF, L.W. Rocky Mountain Energy Co ESD 80-1076. 80/09/30 2pp. 06872 361.

8011060061 Forwards for publication, FR notice of issuance of Reg Guide 10.8, Revision 1.
MINOQUE, R.B. Office of Standards Development, Director. 80/10/21. 1p. 03708, 316

801110648 Transcript of Subcommittee on Regulatory Activities 801105 meeting in Washington, DC Pg 1-270, w/supporting documentation.
* ACRB - Advisory Committee on Reactor Safeguards. 80/11/05. 360pp. 06948, 231.

801120025 Forwards second proposed Revision 3 to Reg Guide 1.33 & Draft 4 to ANS 3.2, as agreed in 801010 meeting on GA policies, w/o encls.
HAAB, W.P. Quality Assurance Branch. 80/10/27. 1p. 06951, 108.

801120182 Submits supplemental comments on draft Reg Guide OH 710-4, "Health Physics Surveys in U Mills"
* American Mining Congress. 80/11/03. 3pp 06953, 285.

801120186 Comments on draft Reg Guide FP 818-4, "Std Format & Content of License Applications (including Environ Repts) For In-Situ U Solution Extraction" Rule inappropriate re development of in-situ U leach project
* American Mining Congress 80/10/29 7pp 06953, 281.

801120192 Comments on Reg Guide 1.23, "Meteorological Programs in Support of Nuclear Power Plants."
OAT, U Oak Ridge National Laboratory 80/10/01 2pp 06953 279.

801120318 Comments on draft Reg guide OH 710-4, "Health Physics Surveys in U Mills" Bioassay results from mill w/routine contamination at levels in guide would be routinely high Rubber gloves rather than surgical gloves, should be used
COOK, L.M. Chevron Industries, Inc; Chevron Resources Co Div. 80/10/21 1p 06956 261

801120322 Comments on Draft 3 of Revision 2 to Reg Guide 1.97. Instruments to measure Type C & E variables for environs monitoring are readily available Perimeter monitoring sys will be installed at PWRs within 2 months
KROON, J.C. Reuter-Stokes, Inc 80/10/28 2pp 06956 259

801120327 Forwards comments on draft Reg Guide OH 905-4 & value/impact statements, "Calibr & Error Limits of Air Sampling Instruments for Total Vol of Air Sampled," ANSI std on calibr may be necessary.
LOONIS, J.B. Sargent & Lundy, Inc 80/10/24. 2pp 06956, 257

801190199 Modified Draft 3 of Revision 2 to Reg Guide 1.97. "Instrumentation for Light-Water-Cooled Nuclear Plants to Assess Plant & Environs Conditions During & Following Accident"
HINTZ, A.S. Reactor Systems Standards Branch. 80/11/06. 58pp 06999, 238

801190344 Comments on 247th meeting on 801104-08 re Reg Guide 1.97, Revision 2. "Instrumentation for Light-Water-Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident"
PLESSET, M. BENDER, M. ACRB - Advisory Committee on Reactor Safeguards. 80/11/10 2pp 06999 360.

8011200465 Forwards notice of issuance of second proposed Revision 2 to Reg Guide 1.8.
CHILK, S.J. Office of the Secretary of the Commission 80/10/08. 1p. 07018, 233

--8011200470 Notice of issuance & availability of second proposed Revision 2 to Reg Guide 1.8
ARLOTTO, C.A. Division of Engineering Standards 80/09/30. 3pp. 07018, 234.

8011210062 Submits followup to 801024 telcon commenting on Draft 3 of Revision 2 to Reg Guide 1.97 re environs radioactivity-exposure rates. Restates that instruments to measure Type C & E variables for environs monitoring are readily available.
KROON, J.C. Reuter-Stokes, Inc 80/10/28 2pp. 07033, 167

8011210077 Comments on Draft 3 of Revision 2 to Reg Guide 1.97. "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident."
LOONIS, J.B. Sargent & Lundy, Inc 80/10/31 4pp 07033, 163

8011210092 Comments on draft Revision 1 to Reg Guide 1.23 re meteorological programs Printouts programmed per formats in Tables B-1, B-2 & B-3. Forwards suggestions that would make data more useful.
WOODARD, K. Pickard, Lowe & Garrick 80/10/30 3pp. 07032, 347.

8011210099 Comments on Draft 3 of Revision 2 to Reg Guide 1.97. "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident."
COX, E.L. Black & Veatch 80/11/04. 1p 07032, 346.

8011210102 Forwards comments on Draft 3 of Revision 2 to Reg Guide 1.97 re instrumentation to assess plant & environs following nuclear power plant accident. Overall clarity has been improved.
SAVAGE, M.R. Ohio State Univ. 80/11/04. 5pp. 07032, 341.

8011210109 Comments on Draft 3 of Revision 2 to Reg Guide 1.97. "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident." Time phases in ANS 4.5 should not be ignored.
KASPER, A.R. Affiliation Unknown. 80/10/31. 2pp. 07029, 129.

NONDOCKETED ITEMS

8011210115 Forwards comments on draft Reg Guide DH 941-4, "Info re Ensuring That Occupational Exposures at U Mills Will Be ALARA." NRC should recognize that type & size of operation will have effect on ALARA program
BUCOS, L A American Mining Congress 80/11/12 10pp 07032 331.

8011210292 Forwards comments on draft Revision 1 to Reg Guide 1.23, "Meteorological Programs in Support of Nuclear Power Plants"
ABEL, J S Commonwealth Edison Co. 80/11/10 3pp 07032.300

8011240096 Responds to 800917 task initiation request to revise original EM 014-4, re control room habitability, to include radiological guidance Request inappropriate due to present availability of sufficient guidance
BENTON, H R Office of Nuclear Reactor Regulation, Director 80/11/10 1p 07049 146

8011250103 Responds to 800811 ltr commenting on proposed Revision 2 to Reg Guide 1.97 Suggestion re accident monitoring instrumentation has been incorporated into guide
WENZINGER, E C Reactor Systems Standards Branch 80/11/07 1p. 07068.291.

8011260443 Second proposed Revision 3 to Reg Guide 1.33, "QA Program Requirements (Operation)"
* Reactor Systems Branch 80/09/22 62pp 07073 097

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

8011040082 Revisions to interim rept, "Power-Cooling-Mismatch Test Series; Test PCN-7 Equation of State," experimental data
SPARKS, D T Idaho National Engineering Laboratory. TFBP-TR-311. 79/02/28 14pp 06874 102

8011040247 LTR 10-15 RB
"Hydrogen Production & Control During LOCA & Loss-of-Coolant Experiment"
ANDERSON, B S Idaho Nuclear Corp LTR 10-15 RB 74/03/05 20pp. 06874.010

8011050537 "FRAP-TS Review of Thermal & Mechanical Analysis & Performance," topical rept for Sept 1980.
BEIFFERT, S L, APPELHANS, A D Energy, Dept of, Idaho Operations Office. FIN A-6041 EQO-TFBP-5230 80/09/30. 82pp. 06902.107

8011050541 "Best Estimate Prediction for LOFT Nuclear Experiments L6-1, L6-2, L6-3 & L6-5," experiment prediction analysis rept.
KEELER, C D Energy, Dept of, Idaho Operations Office FIN A-6048 EQO-LOFT-5161 80/10/31 124pp 06902 188.

8011050573 "Physical Protection of Nuclear Facilities," informal quarterly progress rept for Jul-Sept 1980
CHAPMAN, L D Sandia Laboratories FIN A-1060 SAND80-2428 80/10/10 10pp 06901.302

8011050578 "Div of Reactor Safety Research ORNL Programs," monthly highlights rept for Sept 1980
MYHATT, F R Oak Ridge National Laboratory. FIN B-0413 80/10/10. 46pp. 06902 029

8011050583 "Steam Generator Tube Rupture Iodine Transport Mechanisms," monthly progress rept for Sept 1980
DENNING, R S Battelle Memorial Institute, Columbus Laboratories. NRC-04-76-293 80/10/14. 6pp. 06902 078

8011060077 "Analysis of Hypothetical Accidents Resulting in Core Meltdown," monthly progress rept for Sept 1980.
DENNING, R S, CYBULSKI, P., BAYBUTT, P Battelle Memorial Institute, Columbus Laboratories FIN A-4067. 80/10/14 9pp. 06912.244

8011060084 "Unavailability of Offsite Power at Nuclear Power Plants," preliminary assessment rept
MONNIE, D I Energy, Dept. of, Idaho Operations Office FIN A-6048C. EQO-EA-5256 80/10/31. 14pp 06912.231

8011000206 "Investigation of Ventilation Component Response to Large Pressure Pulses," informal monthly progress rept for Jul 1980
OREGORY, W S Los Alamos Scientific Laboratory. FIN A-7028. 80/09/17 3pp 06931 137

8011000215 "LWR In-Plant Measurement Program," informal monthly progress rept for Aug 1980
HANDLER, J W, EQ&O Idaho, Inc. FIN A-6075. 80/09/19. 4pp.

--8011000226 Forwards std order for DOE work, "Source Term Measurements," issued to INEL
ARSENAULT, F J Division of Safeguards, Fuel Cycle & Environmental Research FIN A-6075 80/10/16 1p 06931 133

--8011000232 Std order for DOE work, "Source Term Measurements," issued to INEL.
ARSENAULT, F J Division of Safeguards, Fuel Cycle & Environmental Research FIN A-6075-1 80/10/16 3pp 06931 134

8011100002 BNL-NUREG-28403
"Scoping Study of Alternatives for Managing Waste Containing Chelating Decontamination Chemicals"
PREMUZIC, E T, MANAKTALA, H K Brookhaven National Laboratory FIN A-3158 BNL-NUREG-28403 80/09/30 54pp 06944 113

801120057 Informal ltr progress rept for Sept 1980 for "Safeguards for Proliferation Resistant Fuels"
CADWELL, J Brookhaven National Laboratory FIN A-3221 80/10/02 3pp 06953.327.

801120070 Summary of 801006 meeting w/Battelle Columbus Labs to review progress of research contract to investigate transport of iodine under steam generator tube rupture conditions
Proposed computer code presented. Agenda encl
AKSTULEWICZ, F Accident Evaluation Branch 80/10/29 3pp 06951 124

801120683 "Safeguards for Proliferation Resistant Fuels," monthly progress rept for Aug 1980
CADWELL, J J Brookhaven National Laboratory. FIN A-3221. 80/10/02. 3pp. 06953.033

801130138 "Summary of Nuclear Plant Safety-Related Pump & Valve Engineering & Failure Data," informal rept
NARETTO, C J, DECKER, G R, WINSTON, O B Energy, Dept of, Idaho Operations Office FIN A-6407 EQO-EA-5253 80/10/31 90pp 02227.001

801130144 LO-31-79-051
"Performance Evaluation of LOFT Steam Generator & Air Cooled Condenser During Power Range Test"
TOWNSEND, W C EQ&O Idaho, Inc. RE-A-79-047 80/10/12 44pp 06959.001

801130153 "Quick-Look Rept on LOFT Nuclear Experiments L6-1, L6-2 & L6-3," preliminary data analysis rept.
REEDER, D L Energy, Dept of, Idaho Operations Office FIN A-6048 EQO-LOFT-5270 80/10/31. 71pp. 06959.044.

801130236 "Quick-Look Rept on LOFT Nuclear Experiment L3-5/L3-5A," preliminary data analysis rept.
ADAMS, J P, EQ&O Idaho, Inc FIN A-6048 EQO-LOFT-5242. 80/10/31 55pp. 06957 160.

801130246 "H88T Thermal-Shock Program," quick-look rept
CHEVERTON, R D Oak Ridge National Laboratory FIN B-0119. TSP-1007 80/10/09. 26pp. 06957.213.

801130252 "LWR Pressure Vessel Irradiation Surveillance Dosimetry Program," bimonthly status ltr for Aug-Sept 1980
PRESTON, C C., MCCLROY, W N Hanford Engineering Development Laboratory. 8053621 80/10/16. 10pp. 06957 239

801170776 "Technology & Costs of Termination Surveys Associated w/Decommissioning of Nuclear Facilities," monthly progress rept for Sept 1980
WITHERSPOON, J., HOLLOWAY, C F Oak Ridge National Laboratory FIN A-9042 ORNL/HASRD-99 80/09/30 3pp 06978 347.

801170780 "Dosimetry & Biotransport Models to Implement ALARA," quarterly progress rept for Jul-Sept 1980.
KOECHER, D C., MCDOWELL-BOYER, RYAN, M T Oak Ridge National Laboratory FIN B-0188 ORNL/HASRD-97 80/10/13 5pp 06978.350

801170785 "Nuclear Power Plant Design Concepts for Sabotage Protection Program," informal quarterly rept for Jul-Sept 1980.
ERICSON, D M Sandia Laboratories. FIN A-3221. 80/10/30. 4pp 06978.353

801170789 "Safeguards Analysis for Byproduct Matls & Small Quantities of SNM," monthly progress rept for Sept 1980.
CHESTER, R O., RANDOLPH, M L Oak Ridge National Laboratory FIN B-6108. ORNL/HASRD-98. 80/10/13 6pp. 06981.245

801170797 "Forecasting Electricity Demand by State & by Util Svc Area," progress rept for Aug-Sept 1980
CHERN, W S Oak Ridge National Laboratory. FIN B-0190-B. ORNL/ED/EAS-80 80/10/13. 5pp. 06977.358.

NONDOCKETED ITEMS

297

BO1170855 "Nondestructive Examination Evaluation Support," monthly progress rept for Sept 1980
SMITH, J. H. Oak Ridge National Laboratory FIN B-0233
ORNL/HCD/NEES-B 80/10/13 4pp 06977 349

BO1180079 "LWR Pressure Vessel Irradiation Surveillance Dosimetry Program," bimonthly status ltr for June-Jul 1980
PRESTON, C. C., MCCLROY, W. H. Hanford Engineering Development Laboratory 8052760 80/08/21 10pp 06987:312

BO1180538 "Threadfin Shad Impingement Population Response," quarterly progress rept Apr-June, 1980.
VAN WINKLE, W., MCLEAN, R. D. Oak Ridge National Laboratory FIN B-0406 80/11/13 5pp 06989 266

BO1180766 "Sediment & Radionuclide Transport in Rivers Transport Modeling," quarterly rept Apr-June, 1980.
* Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2294 80/11/13 5pp

BO1180787 "Sediment & Radionuclide Transport in Rivers Field Sampling Program," quarterly progress rept, Apr-June, 1980
* Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2275 80/11/13 5pp 06992 026

BO1190367 Forwards monthly repts for Jan-Oct 1980
DANAPATHY, B. Michigan, Univ of 80/11/13 20pp 07000-005

BO11200124 "LOFT Experiment Operating Spec Non-Loss-of-Coolant Experiment Baseline Test Series L6," Revision 1
JORDAN, R. P., HARVEGO, J. H., BOLBRIG, C. W. EQ&O Idaho, Inc L-4472 80/10/09, 34pp. 07022 189

BO11200345 "Physical Protection of Nuclear Facilities," informal monthly progress rept for Sept 1980
CHAPMAN, L. D. Sandia Laboratories FIN A-1060 80/10/17, 5pp 07018 183

BO11240458 "LOFT," monthly progress rept for Sept 1980.
KAUFMAN, N. C. Energy, Dept of, Idaho Operations Office FIN A-6048 EQO-LOFT-5276 80/10/31 104pp 07048 151.

BO11240466 "Survivability Study for Drag Bodies & Densitometer Source UPTF Using RELAP4/HOD6 Code"
LIN, J. C. Energy, Dept of, Idaho Operations Office. FIN A-6100 EQO-CAAP-5277, 80/10/31 34pp 07048 117

BO11260022 "Evaluation of Docket Files of Terminated Licenses," monthly progress rept for Sept 1980
HOLDWAY, C. F., WITHERSPOON, J. Oak Ridge National Laboratory. FIN A-9085-7 ORNL/HASRD-96 80/09/30 21pp 07074 214

BO11260260 "Definition of Parameters for Major Accidents at Waste Solidification & Spent Fuel Storage Facilities," informal monthly progress rept for Sept 1980
FREDERICK, E. J. Oak Ridge National Laboratory FIN B-0425 80/10/15 3pp 07072-104

BO11260317 "Physical Protection of Nuclear Facilities," informal monthly progress rept for Oct 1980
CHAPMAN, L. D. Sandia Laboratories. FIN A-1060, 80/11/14 4pp 07072 217.

BO11260323 "Environ Assessments of Fuel Cycle Facilities," monthly progress rept for Sept 1980
ZITTEL, H. E. Oak Ridge National Laboratory. FIN B-0279, ORNL/ED/EIS-138 80/09/30, 5pp 07072-221

REVIEW GRP NRC RESEARCH REVIEW GROUPS

BO11030691 Summary of BO1003 fire protection review group meeting in Bethesda, MD re preliminary replication fire test plan
FEIT, R. Division of Reactor Safety Research, 80/10/20, 10pp, 06873:026

BO11040634 Forwards matls & papers presented at BO0916 seminar on proposed guidelines for review of methodology to precondition or age equipment for DBA qualification testing
MURLEY, T. E. Office of Nuclear Regulatory Research, Director 80/10/22, 31pp. 06875 269.

BO11070092 Summary of Surveillance & Noise Diagnostics Research Review Group BO0922 meeting in Bethesda, MD re results from NRC sponsored research in FY80 agenda
FARMER, W. B. Division of Reactor Safety Research, 80/10/10 5pp, 06920-030.

--BO11070135 "Automated Machinery Diagnostics," presented at 25th Intl Instrumentation Symposium on 790507-10 in Anaheim, CA
FRAREY, J. L. Shaker Research Corp 79/09/10 16pp 06920 195

--BO11070142 "Experiences W/On-Line Diagnostic Instrumentation in Nuclear Power Plants"
GOPAL, R., GIARAMITARD, W., SMITH, J. R. Westinghouse Electric Corp 80/09/22 16pp 06920 211

BO11240088 Forwards summary of Fire Protection Review Group meeting on BO1103 in Bethesda, MD re Sandia Fire protection research program
FEIT, R. Fire Protection Review Group 80/11/13 5pp 07049:140

RM RULEMAKING

BO11040382 Responds to BO1013 ltr transmitting J Courtney request for resumption of OESHD proceeding Comments will be taken into account in NRC review re proceeding
KAMMERER, C. Office of Congressional Affairs 80/10/22 1p

BO11240161 Decision CLI-80-37, accepting proposed traditional clearance program to grant access to or control over ENM, Bradford dissenting visus & Ahearns, Gilinsky & Hendrie separate visus encl.
CHILW, B. J. Office of the Secretary of the Commission, CLI-80-37 80/11/17, 28pp 07041:104.

SECY POSITION PAPERS BEFORE THE COMMISSION

BO09100225 SECY-80-392
Requests Commission approval of final rulemaking deleting 10CFR20.304 re burial of small quantities of radionuclides. Value impact assessment & rept justification for deletion of 10CFR20.304 & proposed FR notice deleting 20.304 encl
MINGOUE, R. B. Office of Standards Development, Director 80/08/21 17pp 0351B 083

--BO09100228 Value impact assessment & rept justification for deletion of 10CFR20.304 re burial of small quantities of radionuclides
Deletion would result in improved records re amounts & locations of buried radioactive matl
HICKEY, J. W. Sit & Environ Stds Br (formerly Environ. Prot Stds Br) 80/08/21 32pp 0351B.097

BO09190299 Responds to FOIA request for 15 documents listed in bibliography of NUREG-0625, "Rept of Biting Policy Task Force." Documents 6-B & 13 are available in PDR Forwards remaining documents
FELTON, J. M. Division of Rules and Records, 80/09/04, 1p.

--BO09190387 SECY-79-362
Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features
MINGOUE, R. B. Office of Standards Development, Director, 79/06/04, 7pp

BO09290477 Discusses proposed exchange of info between US & Mexico
Proposes establishment of procedures to effect exchange & designated coordinator to prepare procedures for implementation.
BELLG, R. Mexico 80/07/30 5pp 03596-155

BO09290528 SECY-80-409
Replacement Pages 3, 4, 8 & 9 of Encl B of SECY-80-409.
* Office of Standards Development, Director 80/09/11 4pp 03596:335

BO10200608 Forwards replacement pages to SECY-80-409, proposed rulemaking re ATNS events Encl B, Page 4 & Encl H, Pages 7-9 encl
* Office of the Secretary of the Commission, 80/09/17, 1p 03643.107.

BO10220338 SECY-80-423
Informs Commission of progress of NRC review of responses to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" Bimonthly status rept encl.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director STELLG, V. Office of Inspection & Enforcement, Office of the Director IE8-79-01B, 80/09/11 18pp 03560-001

NONDOCKETED ITEMS

8010220457 SECY-80-453

Informs receipt of Edlow Intl Co. as agent for Govt of India, application for license to export low enriched U to India Executive Branch action not anticipated in near future.

SHEA, J. R. Office of International Programs, Director 80/10/03
1p 03650 167

8010300009 SECY-80-459

Forwards Executive Branch position on two pending export license applications involving HAWK-II & HFR-Patten reactors in West Germany & The Netherlands, respectively.

SHEA, J. R. Office of International Programs, Director 80/10/07
1p 01796 001.

8010300493 SECY-80-451A

Summarizes status of proposed license to export medium enriched U to Federal Republic of Germany. Recommends license be issued.

SHEA, J. R. Office of International Programs, Director. 80/10/09
3pp 03689 007

8010300071 SECY-77-461

Presents proposed policy statement to clarify role of emergency planning in siting & licensing plants. Provides proposed limited rule change to 10CFR50, App E. Recommends approval of encl policy Analysis & assessment encl.

HINDOQUE, R. B. Office of Standards Development, Director 77/08/29.
35pp 06067 349.

--8011030075 Concurs w/770824 draft Commission paper re current policy on emergency planning & licensing of nuclear power plants.

Submits addl language explaining ongoing events of interest to states.
RYAN, R. Q. Office of State Programs, Director 77/08/29 2pp
06872 265

--8011030075 Concurs w/770824 draft Commission paper re current policy on emergency planning & licensing of nuclear power plants.

Submits addl language explaining ongoing events of interest to states.
RYAN, R. Q. Office of State Programs, Director. 77/08/26 2pp.

8011050990 Transcript of 801030 Affirmation Session 80-47, Pp 1-2.

* Commissioners 80/10/30, 4pp. 06893 013.

--8011050592 SECY-80-486A

Recommends 30-day extension of current relief from shut-down searches at power reactors to allow for Commission consideration of revised search procedures. Draft FR notice encl.

DAVIS, J. Q. Office of Nuclear Material Safety & Safeguards, 80/10/28 4pp 06893 017

8011060353 SECY-80-440

Informs of status of min qualification guidelines for nuclear plant staffing. Guidelines list procedures that will be required to maintain safe operation & communications.

DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 80/09/19, 2pp 06910 231

--8011060359 NUREG-0731 DRFT

"Guidelines for Util Mgt Structure & Technical Resources," draft rept

* Office of Nuclear Reactor Regulation, Director. 80/09/19, 32pp 06910:234.

8011060666 SECY-80-485

Informs of progress re review of IE Bulletin 79-01B responses. Bimonthly status rept re environ qualification of electrical equipment for period ending 801001 encl.

DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1EB-79-01B 80/10/24 12pp 06941 210.

8011200079 SECY-80-367

Informs Commission of results of investigation re possible release of proprietary qualification on Class IE electrical equipment & discusses establishment of nuclear industry equipment clearinghouse.

DENTON, H. R. Office of Nuclear Reactor Regulation, Director 79-01B, 80/08/06 4pp 06951, 186

801120687 SECY-78-011B

Informs Commission of NRC 780205-1B visit to USSR re exchange of info & cooperation in nuclear endeavors. NRC should sign arrangement to cooperate w/USBR in exchange of LNR safety info w/supporting documentation.

LAFLUE, J. D. Office of International Programs, Director STELLO, V. Office of Inspection & Enforcement, Office of the Director. 78/03/21. 63pp 06914:001

8011140656 SECY-80-487

Informs Commission of Executive Branch response on pending application for license to export fuel to West Germany. Requests Commission advice re info that should be included in analysis.

SHEA, J. R. Office of International Programs, Director 80/10/29
1p. 06963:011

--8011140668 Executive Branch position re Transnuclear Inc application

for license to export 3 409 kg U-235, enriched to max of 45.4% to West Germany. License should be granted Ltr of assurance encl.

NOGENZ, L. V. State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/10/17, 3pp. 06963 012

--8011140679 Forwards Transnuclear, Inc application for license to

export SNM to West Germany. Requests views on whether proposed export meets applicable criteria in Atomic Energy Act of 1954.

DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80/08/29 1p 06963 018

--8011140684 Application by Transnuclear, Inc for license to export 7 508

kg U, enriched to max of 45.4%, to West Germany. End use statement encl.

* Transnuclear, Inc NUK-339 80-180 80/08/25, 2pp 06963.019

--8011140690 Forwards application for license to export 7 508 kg U,

enriched to max of 45.4% to West Germany w/o encl.

MATSON, V. Transnuclear, Inc. 80-180/01 80/08/25 1p
06963:021

801170907 Addl responses to FOIA request for documents re NRC

consideration of facility licensing & transcripts re closed Commission meetings. Forwards App A & B documents. Documents partially withheld (ref FOIA Exemptions 3 & 4).

FELTON, J. H. Division of Rules and Records 80/11/06, 4pp

--801170943 SECY-79-650

Provides alternatives for Commission policy on safeguards regulations of highly enriched U activities at facility. Recommends approval of Alternative D info partially withheld (ref FOIA Exemptions 3 & 4).

DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards 79/12/11 12pp

--801170948 SECY-79-650A

Recommends that Commission approve highly enriched U activities at facility for single operating period following implementation of safeguards improvements outlined in SECY-79-650. Info partially withheld (ref FOIA Exemption 3).

DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards, 80/01/02, 4pp

8011900010 SECY-80-493

Forwards, for info of Commission, 801009 applications for C-E to export two PHRs, initial cores & three reloads each, to Taiwan GE & Westinghouse have also applied for licenses to supply same reactors, cores & reloads.

SHEA, J. R. Office of International Programs, Director 80/11/03
1p. 03739 065.

8011200358 SECY-78-111

Discusses current accident evaluation practices in siting & licensing of nuclear power plants. Lists results of current accident evaluation practices. Accident analysis, site evaluation & other related info encl.

HINDOQUE, R. B. Office of Standards Development, Director 78/02/22, 49pp 0701B 311

8011200361 SECY-78-044

Discusses issuance of proposed effective amend to 10CFR50 App E re emergency plans for production & utilization facilities. Requests approval of proposed amend. Draft FR notice & congressional ltr encl.

HINDOQUE, R. B. Office of Standards Development, Director. 78/01/29, 14pp. 0701B, 290

--8011200369 Comments on proposed issuance of effective amend to 10CFR50

App E re emergency plans for production & utilization facilities. Second sentence needs mod if concept of generic protective action zones is adopted. Concurs w/rule change.

RYAN, R. Q. Office of State Programs, Director 77/12/09 3pp.
0701B:304.

--8011200372 Provides clarification of one point in response to comment

on proposal re implementing certain study group recommendations on improving nuclear power plant licensing. Interveners should be invited to attend local meetings.

BRADFORD, P. A. Commissioners. 78/01/24 3pp. 0701B:308.

8011200383 SECY-78-044A

Discusses issuance of proposed effective amend to 10CFR50
App E re emergency planning outside low population zone
Requests approval of proposed amend. Draft FR notice &
congressional ltr encl
MINOQUE, R B Office of Standards Development, Director 78/05/30
17pp 07018 241

--8011200388 Comments on proposed issuance of effective amend to 10CFR50

App E re emergency plans for production & utilization
facilities Second sentence needs mod if concept of generic
protective action zones is adopted Concurrs w/rule change
RYAN, R O Office of State Programs, Director 77/12/09 3pp
07018 261

--8011200391 Comments on issuance of proposed effective amend to 10CFR50

App E re emergency plans for production & utilization
facilities Problems w/amend re fuel cycle facilities will
as 10CFR100 limits are not used Provides addl paragraph
SMITH, C V Office of Nuclear Material Safety & Safeguards.
77/12/19 1p 07018 266

--8011200395 Comments on proposed effective amend to 10CFR50 App E re

emergency planning requirements outside reactor low
population zone Proposal should be modified to incorporate
several changes. Proposal, as is, would not amend 10CFR100
KELLEY, J L Office of the General Counsel. 78/02/14 6pp
07018 268

--8011200402 Comments on Ofc of General Counsel objections to issuance of

proposed effective amend to 10CFR50 App E re emergency
planning requirements outside reactor low population zone
Recommends incorporation of BRP
BHAPAR, H K Office of the Executive Legal Director 78/03/02
11pp 07018 273

8011210008 Transcript of 801110 public meeting in Washington, DC re

Inclusion of steam generator transients as unresolved
safety issue Pp 1-39
* Commissioners 80/11/10. 42pp 07030 200

8011240472 Transcript of 801114 public meeting in Washington, DC re

Investigation of containment flooding event at Indian Point
2 & restart of Indian Point 3 Pp 1-156.
* Office of Inspection & Enforcement, Office of the Director.
80/11/14 156pp

--8011240484 SECY-A-80-179

Discusses proposed footnote re procedural issues for ABLP
to follow, due to investigative nature of proceeding
BICKMIT, L. Office of the General Counsel 80/11/13. 16pp.

STATE PROO STATE PROGRAMS

8011030095 Responds to NRC 800908 ltr forwarding comments on CD Dept

of Health radioactive matls regulatory program. Joy Mfg
Co license will be reviewed. Supervisory personnel will
conduct field evaluations of inspectors
HAZLE, A. J. Colorado, State of. 80/09/26. 2pp. 06857 127.

8011030465 Responds to NRC 800805 ltr inviting comment on proposed

amend to 10CFR70. State of NM has no written comment
WOLFF, T A New Mexico, State of 80/08/26 1p /. 06873.038

8011040021 Comments on proposed amend to 10CFR71 requiring advance

notification to state governors of transportation of nuclear
waste to, through or across state boundaries. Supports rule.
DUNKLEBERGER, J. New York, State of 80/08/27 2pp. 06884.069.

8011040026 Comments by OR DOE on proposed amends to 10CFR71. Supports

requirement for notification of state prior to radwaste
shipments exceeding Type A quantities Std notification
form should be designed & used.
FRANK, L Oregon, State of 80/08/22 2pp. 06884.067.

8011040028 Comments by ND State Health Dept on proposed amend to

10CFR71 Words "s/or his designee(s)" should be added
following "governor" as individuals to be notified.
MCUNT, D K North Dakota, State of. 80/08/28. 1p 06884.066.

8011040141 Comments by CA Dept of Health Svcs on proposed amend to

10CFR71 route & stopover details requirement should be
incorporated into amend
WARD, J O. California, State of 80/08/26. 1p. 06874.055.

8011040222 Comments on proposed amend to 10CFR71 re advance

notification of radwaste shipments. Supports amend.
BROWN, J Y. Kentucky, State of. 80/08/29. 1p. 06874.045.

8011040227 Comments by GA Dept of Human Resources re advance
notification to state governors of nuclear waste shipments
Agrees w/new rule State rules on transportation of
hazardous matls encl.
SIMANIS, A Georgia, State of 80/08/21 9pp 06874 035.

8011040231 Comments by ID Dept of Health & Welfare on proposed amend to
10CFR71 requiring prior notification to state governors of
radwaste shipments Intent of regulation is ambiguous
FUNDERSBURG, R D Idaho, State of 80/08/13 1p 06874 034

8011040235 Comments by SC Dept of Health & Environ Control on proposed
amend to 10CFR71 requiring that state governors receive
prior notification of radwaste shipments
SHEALY, H O South Carolina, State of 80/08/22 2pp 06874 032

8011040242 Comments by NV Dept of Human Resources re notification of
state governors prior to radwaste shipments. Disagrees
w/concept that Type A quantities of radioactive matl could
never pose significant health hazard
DIBIBIO, R R Nevada, State of 80/08/20 2pp 06874 030

8011050121 Comments by State of KB Dept of Health & Environ on proposed
amend to 10CFR71 Suggests program involving state matls
licensing agencies, emergency response agencies & traffic
control could be developed
ALLEN, O W Kansas, State of 80/08/19. 2pp. 06898.344

8011050140 Comments by State of AZ Radiation Regulatory Agency on
proposed amend to 10CFR71 re advance notification to
state governors of radwaste shipments Routing info should
also be included Supports rule
TEDFORD, C F Arizona, State of 80/08/19 1p. 06898.344

8011060309 Responds to 800909 ltr re license review, field evaluation of
inspectors & procedures for enforcement actions. License for
Joy Mfg Co will be reviewed Supervisory personnel will
conduct field evaluations of inspectors.
HAZLE, A J Colorado, State of 80/09/26 2pp 06911.317.

8011060478 Summarizes contract award amounts & semiannual repts
submitted by Agreement States under U Mill Tailings
Radiation Control Act
YOUNG, F W Assistant Director for Program Development. 80/11/03
2pp. 06916 208

--8011060479 Forwards revisions to RFPAs for grants to Agreement States
under U Mill Tailings Radiation Control Act W/o encl
RYAN, R O Office of State Programs, Director. 80/06/09. 1p
06916.210

801110583 Forwards State of MI "Radioactive Matl Transportation
Surveillance. Fourth Quarterly Progress Rpt, June-Aug 1980."
JANINEK, M Office of State Programs, Director NRC-06-77-051.
80/10/27 1p 06944.335

--801110586 "Radioactive Matl Transportation Surveillance: Fourth
Quarterly Progress Rpt, June-Aug 1980."
* Michigan, State of. NRC-06-77-051 80/08/31 21pp
06944.337

801110595 Forwards State of IL transportation surveillance program
quarterly progress repts for 800307-0607 & 800607-0907
JANINEK, M Office of State Programs, Director. 80/10/24 2pp
06945.088

--801110602 Submits fourth quarter transportation surveillance program
rept for 800307-0607.
NEUMELO, M Illinois, State of 80/06/30. 3pp. 06945.090.

--801110607 Submits first quarter transportation surveillance program
rept for 800607-0907.
NEUMELO, M Illinois, State of 80/10/08. 2pp. 06944.360.

801120561 Confirms NRC comments re regulatory program review for U
milling & administrative aspects of radiation control
program License should be amended immediately to require
biassay program.
LUBENAU, J O Assistant Director for State Agreements Programs.
80/10/27. 2pp. 06953.251

--801120565 Confirms 801003 discussion re results of NRC review &
evaluation of NM Environ Improvement Div radiation control
program Responsibilities for tailings dam insp should be
clearly defined.
KERR, O W Office of State Programs, Director 80/10/27. 2pp.
06953.253

NONDOCKETED ITEMS

801120690 Ack receipt of 801017 ltr re actions to improve program for regulation of agreement matl Actions will be reviewed during NRC visit in Dec 1980
KERR, O W Office of State Programs, Director. 80/10/31. 1p.
06953 238

801140312 Forwards State of MD transportation surveillance program first quarterly progress rept for 800606-0906
JANINEK, M Office of State Programs, Director 80/10/31 2pp.
06962, 315

--801140313 Forwards State of MD transportation surveillance program first quarterly progress rept for 800606-0906.
MCQUADE, J E Maryland, State of NRC-06-80-679. 80/10/17. 22pp
06962 317

801170528 Forwards State of WA transportation surveillance program fourth quarterly progress rept for 800610-0909
JANINEK, M Office of State Programs, Director 80/10/24 2pp.
06979, 001

--801170530 Forwards State of WA transportation surveillance program fourth quarterly progress rept for 800610-0909.
ORONEMYER, E L Washington, State of. 80/10/10 1p. 06979:003.

--801170534 Forwards State of WA transportation surveillance program fourth quarterly progress rept for 800610-0909
BTRDNO, T R Washington, State of 80/10/15. 14pp. 06979, 004

801180303 Forwards statement of NRC/FEMA interfacing responsibilities re assessment of states' emergency plans, in response to 801007 request for input to QAD evaluation
DENTON, H R Office of Nuclear Reactor Regulation, Director. 80/10/15 2pp 06986:030.

--801180319 Requests statement of NRC/FEMA interfacing responsibilities re assessment of states' emergency plans for QAD evaluation of federal programs
BARRY, L W Office of the Controller. 80/10/07. 1p. 06986:032

801190038 PNA-80-37, on 801114, State of OR informed NRC that individual attempted to sell radium needles to proprietor of Ardvarke Guns & Trade Ctr. Send OR States of OR, NV, CA, ID & WA will issue notice to all radium licensees for inventory
LUBENAU, J O, BOLLING, L A Office of State Programs, Director. 80/11/17. 1p. 07001:294

801190068 PNA-80-38, on 801117, State of AL informed NRC that state licensee had reported technetium generator Mo-99 breakthrough during first elution on 801117 Generator was Squibb Model 1930 calibr 801115 Generator pulled from svc
LUBENAU, J O, WENDT, J F Office of State Programs, Director 80/11/17 1p 07001 293

801200361 SECY-76-044
Discusses issuance of proposed effective amend to 10CFR50 App E re emergency plans for production & utilization facilities. Requests approval of proposed amend. Draft FR notice & congressional ltr encl.
HINDOUE, R B Office of Standards Development, Director. 78/01/25. 14pp. 07018, 290.

--801200369 Comments on proposed issuance of effective amend to 10CFR50 App E re emergency plans for production & utilization facilities. Second sentence needs mod if concept of generic protective action zones is adopted. Concurs w/rule change.
RYAN, R O Office of State Programs, Director. 77/12/09 3pp.
07018:304

801200383 SECY-76-044A
Discusses issuance of proposed effective amend to 10CFR50 App E re emergency planning outside low population zone Requests approval of proposed amend. Draft FR notice & congressional ltr encl.
HINDOUE, R B Office of Standards Development, Director. 78/03/30. 17pp. 07018, 241.

801200388 Comments on proposed issuance of effective amend to 10CFR50 App E re emergency plans for production & utilization facilities. Second sentence needs mod if concept of generic protective action zones is adopted. Concurs w/rule change.
RYAN, R O Office of State Programs, Director 77/12/09. 3pp.
07018, 261.

80120592 Expresses appreciation for NRC cooperation extended to Interorganizational Advisory Committee re NUREG-0654 & response to proposed changes. Requests revisions to NUREG-0654 to clarify NRC role in offsite emergency operations.
MANCUSO, F. Connecticut, State of. 80/11/12. 2pp 07034:004.

801280149 Comments on advance FR notice of proposed general statement of policy. "Evaluation of Agreement State Radiation Control Programs." Technical qualifications of personnel could be improved through increased training & salary upgrading
TEDFORD, C F Arizona, State of 80/10/22 2pp 07083, 284.

801280173 Comments on advance FR notice of proposed general statement of policy. "Evaluation of Agreement State Radiation Control Programs." Personnel topics need further evaluation
STEELE, K E. Nebraska, State of 80/10/02. 4pp 07083, 286

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

8006020748 Discusses 800417 meeting between representatives of Turbine Generator Disc Integrity Task Force & NRC re task force position on Category A units scheduled for insp
STIEDE, W L Commonwealth Edison Co 80/03/27. 1p. 05158:035.

8008260408 Forwards proprietary & nonproprietary responses to NRC Partial Question Set 1 on WCAP-9401 & 9402. "Verification Testing & Analyses of Westinghouse 17X17 Optimized Fuel Assembly." Applications & affidavits for withholding encl
ANDERSON, T M Westinghouse Electric Corp NS-TMA-2293. 80/08/22. 18pp. 06412:144

801030183 Ack receipt of 800307 comments for use in Commission consideration of inerting requirements of BWR containments Vendor should submit new info to proposed interim rule. Chronology encl.
DIRCKS, W J. Office of the Executive Director for Operations 80/10/15 3pp 06855:204.

--801030191 Comments on BWR Mark I & II containment inerting Inerting containments is unnecessary & counterproductive to BWR safety.
BRAY, A P General Electric Co. 80/03/07 3pp 06855, 207.

801030446 Approves of Revision 14 to CE-1-A, QA program.
HAASS, W P Quality Assurance Branch. 80/10/01 2pp 06857:019.

801030513 Forwards App A, "Hafnium" & App B "Aluminum Oxide/Boron Carbide Pellets" to WCAP-9179 Revision 1 (proprietary) & WCAP-9224 (nonproprietary). "Properties of Fuel & Core Component Matls." Application & affidavit encl
ANDERSON, T M Westinghouse Electric Corp, PWR Systems Div NS-TMA-2322 80/10/24. 8pp 06861, 140.

--801030521 WCAP-9224 APP A
Nonproprietary version of App A, "Hafnium"
* Westinghouse Electric Corp., PWR Systems Div 80/10/24 8pp.
06861 148

--801030530 WCAP-9224 APP B
Nonproprietary version of App B, "Aluminum Oxide/Boron Carbide Pellets"
* Westinghouse Electric Corp., PWR Systems Div 80/10/24 9pp.
06861:156

801040296 Forwards "Mark I Containment Program Vent Sys Compressibility Effects on Mark I Pool Swell." Rept concludes that previous subscale test results are conservative for existing Mark I conditions.
BUCHHOLZ, R H General Electric Co., Nuclear Energy Products Div. RHB-042-80. 80/06/04 1p. 06878:059.

--801040232 NEDO-24778
"Mark I Containment Program Vent Sys Compressibility Effects on Mark I Pool Swell" Prepared for GE
IANNI, P W, WADE, O E. Alcorn, BONE001B 80/03/31. 6Bpp
06878:060

801040580 Notifies that defective mounting was found on Fisher Type 846 electropneumatic transducer for use in vendor NSSB. Specific application was not reportable under 10CFR50.55b. All safety-related mountings will be inspected prior to use.
TAYLOR, J H Babcock & Wilcox Co. 80/10/27 1p. 06873:073

801050443 Forwards proprietary & nonproprietary test repts describing operational cycling normal & abnormal temp & humidity testing & seismic qualification testing of reactor trip switchgear per commitments made in WCAP-8587.
ANDERSON, T M. Westinghouse Electric Corp. NS-TMA-2309 80/09/30. 10pp. 06897:031.

--801050445 WCAP-8587-E20A B2
Nonproprietary version of "Equipment Qualification Test Rept: Reactor Trip Switchgear: Operational Cycling & Normal & Abnormal Temp & Humidity Testing."
FAUST, C E, VALICH, M. Westinghouse Electric Corp. 80/09/30. 18pp. 06897, 041.

NONDOCKETED ITEMS

301

- B011080449 WCAP-B5B7-E208
Nonproprietary version of "Equipment Qualification Test
Rept Reactor Trip Switchgear Seismic Qualification Testing "
FAUST,C.E. , TANG,D.T. , VALICH,M. Westinghouse Electric Corp
80/09/30 34pp 06897 059
- B011080452 EGDP-ESE-20 R2
"Equipment Qualification Data Package Reactor Trip
Switchgear - DS-416 Circuit Breakers "
ANDERSON,T.M. Westinghouse Electric Corp , Nuclear Energy Systems
80/09/30 18pp 06897 093
- B011060925 Forwards list of addl info needed to complete review of
B00321 Topical Rept 80-67459, "Performance of York Model 299
Type 3Q Demister/Moisture Separator in Removing Droplets in
Air-Stream Dispersion "
TEDESCO,R.L. Assistant Director for Licensing 80/10/22 3pp
02319 196
- B011060955 Forwards proprietary version of "Analytical Model for LOCA
Water Jet in Mark II Containments (Ring Vortex Model) "
Affidavit encl Rept withheld (ref 10CFR2.790)
BUCHHEIDZ,R.H. General Electric Co. , Nuclear Energy Products Div
MFN-184-80 80/10/27 5pp 06911 142
- B011070080 Notification of B01112 meeting w/Westinghouse to discuss new
emergency procedure guideline & compliance of current
emergency procedures guidelines in meeting requirements of
Item I.C.1 of TMI task action plan
SIGEL,B.L. Procedures & Test Review Branch. NUREG-0660 80/10/24.
2pp 06920 048
- B011100409 Forwards request for addl info re SL-TR-1A,Revision 4,QA
program List of reg guides referenced in introduction must
be revised,QA coordinating committee objectives must be
restated.
HAASB,H.P. Quality Assurance Branch 80/10/24 4pp. 06931.262
- B011100414 Forwards "Exxon Nuclear Co Plant Transient Simulator Code
for Evaluation of Abnormal Transients for Jet Pump BWRs "
Rept suppl B00531 Revision 1 submittal,Exxon rept
available in Central Files only w/JN Morgan affidavit
OWSLEY,O.F. Exxon Nuclear Co. , Inc (subs of Exxon Corp.),
GFO.147.80 80/11/03. 4pp 06931 282
- B01110461 Forwards proprietary & nonproprietary revisions to
CENPD-193, "Evaluation of Uncertainty in Nuclear Power
Peaking Measured By Self-Powered,Fixed In-Core Detector
Sys." Proprietary info withheld (ref 10CFR2.790)
SCHERER,A.E. C-E Power Systems. LD-80-048. 80/09/04 5pp.
06946.291.
- B011110469 CENPD-193-NP R1A
Nonproprietary version,Revision 1-NP-A of "Evaluation of
Uncertainty in Nuclear Power Peaking Measured By
Self-Powered,Fixed In-Core Detector Sys. "
JONGBON,A. , TERNEY,W.B. , CRUMP,M.W. C-E Power Systems. 80/03/31.
450pp 06946.296.
- B011110745 Forwards topical rept evaluations for NEDE-24057,
NEDE-24057-1 & NEDE-24057-2, "Assessment of Reactor
Internals Vibration in BWR/4 & BWR/5 Plants. "
TEDESCO,R.L. Assistant Director for Licensing. 80/10/28. 2pp
06947.356.
- B011110754 Topical rept evaluations of NEDE-24057,NEDE-24057-1 &
NEDE-24057-2, "Assessment of Reactor Internals Vibration in
BWR/4 & BWR/5 Plants." Repts are acceptable.
Mechanical Engineering Branch. 80/08/31. 18pp. 06948.001.
- B011120345 Forwards Revision 2 of NEDO-11209-04A,QA program
Acknowledgement form only encl.
LOWE,D.C. General Electric Co 80/11/04 2pp. 06952.012.
- B011120491 Informs that CENPD-79, "C-E Pellet/Clad Thermal Conductance
Model" has been reviewed & determined to contain no
proprietary info.Rept should be redesignated "downgraded,
nonproprietary "
SCHERER,A.E. Combustion Engineering, Inc. ID-80-039. 80/11/06
1p 06953:351.
- B011120546 Forwards samples of types of new regulatory requirements
reviewed or under review by Safety Program Evaluation
Branch,Contractor support in area of cost estimates is under
consideration by NRC,H/o encl.
BAER,R.L. Safety Program Evaluation Branch. 80/10/23. 3pp
06953:248.
- B011140002 Forwards corrections to XN-NF-77-57,Suppl 1,"Exxon Nuclear
Power Distribution Control for PWRs,Phase 2," June 1979
Revisions do not change intent of related PDC-2 procedure
but clarify requirements
OWSLEY,O.F. Exxon Nuclear Co. , Inc (subs of Exxon Corp.)
GFO 150.80 80/11/04. 3pp 06961 223.
- B011140060 Notifies of organizational changes & planned changes
within Water Reactor Divs.
ANDERSON,T.M. Westinghouse Electric Corp. PAS-PTH-80-585
80/10/28 2pp 06963:345
- B011170121 Notifies of billing cost re review of Revision 9 to
CPC-1-A,QA program manual.Invoice will be sent under
separate cover
MILLER,W.D. License Fee Management Branch. 80/11/05 1p.
06978.262
- B011170141 Notifies of billing cost re review of FGTPN-7B,QA for AISC
nuclear quality certification program Invoice will be sent
under separate cover
MILLER,W.D. License Fee Management Branch 80/11/05 1p
06981:360
- B011170495 Forwards model updates to RELAP4-EM/ENC28B,per NRC 760715
procedure,Updates for large break calculations
insignificant.Changes which affect small break calculational
results will be submitted at later date.
OWSLEY,O.F. Exxon Nuclear Co. , Inc. (subs of Exxon Corp.)
GFO.148.80 80/11/04. 8pp. 06977:335
- B011180009 Forwards proprietary vendor 791220 & B00130 ltrs re low
pressure turbine discs,Ltrs withheld (ref 10CFR2.790).
VAROA,S.A. Operating Reactors Branch 1. 80/09/05 2pp 06986:094.
- B011180236 Forwards summary of organizational changes in engineering &
const.Revisions will be incorporated in CPC-1A.
HOFFMAN,D.P. Consumers Power Co 80/11/14 2pp 06988:242
- B011180258 Forwards BAW-10146, "Determination of Min Required Tube Wall
Thickness for 177-FA Once-Through Steam Generators " Rept
presents generic wall thinning allowance upon which tube
plugging requirements would be based for steam generators.
TAYLOR,J.H. Babcock & Wilcox Co 80/11/11 1p 06985.282
- B011180262 BAW-10146
"Determination of Min Required Tube Wall Thickness for 177-
FA Once-Through Steam Generators."
Babcock & Wilcox Co 80/10/31. 105pp 06985 283
- B011180869 Notifies of payment due for review of organizational changes
to WCAP-8370,Revision 7A,QA plan.
MILLER,W.D. License Fee Management Branch 80/11/06 1p
06991:343
- B011190206 Notifies of change in reload license analyses re mislocated
bundle accident basis for change withheld (ref 10CFR2.790).
Affidavit for withholding encl.
ENGEL,R.E. General Electric Co MFN-199-80 80/11/14. 6pp
07000:033.
- B011200308 Modifies assessment of proprietary info re RH Buchholz
101003 nonproprietary version of B00905 CDYN submittal
Forwards corrected Tables 1-3 & 1-4 re analysis of
(DeltaCPPR/ICPR).Table 1-3 withheld (ref 10CFR2.790).
BUCHHEIDZ,R.H. General Electric Co. MFN 192-80. 80/11/06 4pp.
07022.091
- B011210176 Forwards request for addl info needed for completion of
review for AECC-2-P, "Radwaste Vol Reduction Sys. "
TEDESCO,R.L. Division of Licensing. 80/11/10. 3pp. 07031.357.
- B011210316 Forwards proprietary Amend 9 to NEDE-24011-P-A-i, "Generic
Reload Fuel Application."
ENGEL,R.E. General Electric Co. MFN-196-80. 80/11/17. 2pp.
07035:033.
- B011210505 Forwards Westinghouse owners group guidelines for recovery
from inadequate core cooling,utilizing WCAP-9753,WCAP-9744 &
WCAP-9762 as analytical bases.
JURGENSEN,R.W. Westinghouse Operating Plants Owners Group 09-44.
80/11/10. 63pp. 07034:227.
- B011240144 Forwards nuclear characteristic tables for new fuel bundle
design in NEDE-24011-P-A-i,Amend 9,Tables 1-5 & affidavit
withheld (ref 10CFR2.790).Affidavit not encl.
ENGEL,R.E. General Electric Co MFN-197-80. 80/11/14. 1p.
07046:320.

NONDOCKETED ITEMS

8011240188 Forwards "Interim All Volatile Treatment Guidelines," "Overall Direction All Volatile Treatment Guidelines" & "Steam Side Water Chemistry Control Specs" in response to NRC 800826 request for info
ANDERSON, T M Westinghouse Electric Corp. NS-TMA-233B, 80/11/07, 14pp 07066.001.

--8011240192 "Steam Side Water Chemistry Control Specs"
DUHANE, R, BECK, N I, PERRY, D T Westinghouse Electric Corp. 75/01/31 132pp. 07066.015

8011250246 Forwards NEDO-24615, Vols 1, 2 & 3, "Mark 1 Containment Program, 1/4 Scale Pressure Suppression Pool Swell Test Program Supplemental Plant Unique Tests - Task Numbers 3, 4/10.1." Proprietary version, NEDO-24615-P was submitted
BUCHHOLZ, R H General Electric Co RHB-041-80 80/10/09 1p 07053.001.

--8011250252 NEDO-24615 V1
Vol 1 of "Mark 1 Containment Program, 1/4 Scale Pressure Suppression Pool Swell Test Program Supplemental Plant Unique Tests - Task Numbers 3, 4/10.1"
HUMPHREY, J M, WADE, G E, IANNI, P M General Electric Co 80NED023, 80/06/30, 50pp 07053.002

--8011250292 NEDO-24615 V2
Vol 2 of "Mark 1 Containment Program, 1/4 Scale Pressure Suppression Pool Swell Test Program Supplemental Plant Unique Tests - Task Numbers 3, 4/10.1"
HUMPHREY, J M, WADE, G E, IANNI, P M General Electric Co 80NED023, 80/06/30 379pp. 07053.083

--8011250294 NEDO-24615 V3
Vol 3 of "Mark 1 Containment Program, 1/4 Scale Pressure Suppression Pool Swell Test Program Supplemental Plant Unique Tests - Task Numbers 3, 4/10.1"
HUMPHREY, J M, WADE, G E, IANNI, P M General Electric Co 80NED023 80/06/30 120pp.

8011250503 Forwards Revision 2 of NEDO-11209-04A w/errata & addenda sheets for updating Nuclear Energy Business Group BWR GA program. Revision identifies organizational structure & describes GA program in effect as of 801001.
ANDERSON, G J General Electric Co 80/10/23, 1p. 07054.309.

--8011250508 NEDO-11209-04A RA
Revision 2 to Nuclear Energy Business Group BWR GA program w/errata & addenda sheets.
BREED, A General Electric Co 80/10/31, 50pp 07054.312.

8011250686 Forwards proprietary version of WCAP-9693, "Investigation of Feedwater Line Cracking in PWRs," June 1980 Nonproprietary version will be provided 801210 Proprietary version withheld (ref 10CFR2790).
ANDERSON, T M Westinghouse Electric Corp NS-TMA-2327 80/11/10 1p. 07053.119.

8011260074 Submits response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power" Insp of sys performed by plant maint personnel w/telephone representatives on 800626. Administrative directive issued.
AUSTIN, M A Babcock & Wilcox Co, Nuclear Material Div IES-80-15, 80/11/06 2pp. 07071.309

8011260163 Describes program & schedule for response to NUREG-0737, Item 11.K 3.30 re possible upgrade of LOCA analytical model. Vendor will justify acceptability of current model in written rept by 820101.
BUCHHOLZ, R H General Electric Co MFN-202-80 80/11/18, 2pp. 07074.077.

8011280023 Forwards topical rept "RWR-1 TM Radwaste Vol Reduction Sys." for approval. Affidavit for withholding proprietary version encl Proprietary version available in Central Files only.
KANNARD, J R Newport News Industrial Corp (subs of Newport News Shipbuilding & Dry Dock Co.) OBO/NRC/80-802 80/11/25, 4pp. 07084.123.

--8011280027 EI/NNI-77-7-NP
"RWR-1 TM Radwaste Vol Reduction Sys."
* Newport News Industrial Corp. (subs of Newport News Shipbuilding & Dry Dock Co.). 80/10/31, 150pp.

WASTE MGT NUCLEAR WASTE MANAGEMENT

801110175 Forwards application for special use permit for Hansen project tailings disposal area w/o encl.
THOMPSON, M A Cyprus Mines Corp. 17674, 80/10/16, 1p 06943.347

801110196 Forwards solid waste disposal rept, Sept 1980
JONES, R K Union Carbide Corp 17678 80/10/19, 43pp. 06915.001

8011120647 Ack receipt of request for NRC comment on three documents
Dawn Mining Co response to NRC environ assessment of below-grade tailings mgt plan matches data NRC supplied to State of WA
SCARANO, R A Uranium Recovery Licensing Branch 80/10/23 1p 06933.269

8011180483 Forwards Acres American, Inc response to question raised during 800924 meeting re Uranium tailings, Phase IIB w/o encl
KAGETSU, T J Union Carbide Corp. 17759 80/10/22 1p. 06991.222.

8011180498 Forwards corrected mylar copies of Figures 1 & 3-6 from 800529 transmittal re characterization of landslide potential for three cell option w/o encls
BURANEK, D W A Wahler & Associates, Inc 17789 80/10/21 1p 06991.232

8011210212 Order granting extension until 801024 for addl comments to hearing record re Gulf Mineral Resources Co application for discharge plan & radioactive materials license
CLAYTON, C L New Mexico, State of 17761 80/10/22, 1p 07035.035.

8011280177 Responds to NRC questions re tailings disposal area. Specific retention of Hansen Pit tailings will be between 13X & 38X of total vol Picnic Tree tailings will retain fluid between 30% & 40% of total vol
THOMPSON, M A Cyprus Mines Corp 17803 80/10/31, 4pp. 07083.290.

XPORTLIC EXPORT AND IMPORT LICENSES

8004080069 Advises that route for transport of AECL spent fuels from Ogdensburg, NY to Dunbarton, NC must be changed due to local ordinance in Geneva, NY. Proposes alternate route
STUKENBROEKER, NL Industries, NL Nuclear Div. 15807 80/03/11 2pp. 04529.255

8010280457 SECY-80-453
Informs of receipt of Edlow Intl Co, as agent for Govt of India, application for license to export low enriched U to India. Executive Branch action not anticipated in near future
SHEA, J R Office of International Programs, Director 80/10/03 1p 03650.167.

8010300009 SECY-80-459
Forwards Executive Branch position on two pending export license applications involving KNK-II & HFR-Petten reactors in West Germany & The Netherlands, respectively
SHEA, J R Office of International Programs, Director. 80/10/07 1p 01756.001.

8010300080 Amend 2 to license for Hoke, Inc. extending expiration date from 801001 to 850101.
DEVINE, J B Assistant Director for Export/Import & International Safeguards. 1132 80/10/28 1p. 06857.157

8010300085 Amend 3 to license for Westinghouse, extending expiration date from 801231 to Dec 31, 2013
DEVINE, J B Assistant Director for Export/Import & International Safeguards. FE-20040, 80/10/28 1p 06857.158

8010300091 Amend 4 to license for Hoke, Inc. extending expiration date from 801231 to 850630
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/10/28 1p 01756.001.

8010300096 Executive Branch position re Westinghouse application for license amend to export 904 micrograms Cf-252 contained in four sealed sources to Taiwan. Amend should be issued.
GURIN, M A State, Dept of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs 80/10/24, 2pp 06857.177.

801030104 Requests Executive Branch position re Westinghouse application for license to export nuclear equipment to Indonesia, w/o encl license
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/10/28, 1p. 06857.179.

801030106 Application by Sigma Chemical Co for license to export compounds containing deuterium, equivalent to 10.0 kg of deuterium oxide liquid over 2-yr period, to Australia
STERN, W C Sigma Chemical Co (subs. of Sigma-Aldrich Corp.), D-55, 80/10/13, 1p. 06857.132

NONDOCKETED ITEMS

303

8011030112 License for Coordination Council for North American Affairs to export 4,000 kg heavy water to Taiwan
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/10/14 2pp 01756 001

8011030119 Forwards application by Westinghouse for license to export radiation surveillance capsules to South Korea
HERSCH, M M Westinghouse Electric Corp ILS-003 80/10/23 1p 06857 239

--8011030124 Application by Westinghouse for license to export six radiation capsules to South Korea
HERSCH, M M Westinghouse Electric Corp. ILS-003 80/10/23 1p 06857 240

8011030122 Forwards application for license to export 1 0 kg deuterium, in 5 0 kg deuterium oxide, to Venezuela
EDELSTEIN, B Aldrich Chemical Co., Inc (subs of Sigma-Aldrich Corp.) 80/10/03 1p 06867 355

--8011030126 Application by Aldrich Chemical Co for license to export 1 0 kg deuterium, in 5 0 kg deuterium oxide, to Venezuela
EDELSTEIN, B Aldrich Chemical Co., Inc. (subs of Sigma-Aldrich Corp.) 20/80 80/10/03 1p 06867 356

8011030131 Application by Mitsui & Co, Inc for license to export Zircaloy 2 & Zircaloy 4 tube shells to Japan
TAKAH, K Mitsui & Co., Ltd 136175 80/10/10 2pp 01756-001

8011030175 License for Edlow Intl Co to export 0.031 g U-235, contained in 2 g U, to Japan.
DEVINE, J B Assistant Director for Export/Import & International Safeguards SHIB1118-2971-B. 80/10/16 2pp 06857 133

8011030178 License for QE to export 0.639 kg U-235 & 0 0262 kg Pu in 17 metal clad experimental & prototype fuel rods, to Taiwan
DEVINE, J B Assistant Director for Export/Import & International Safeguards BDW-79223. 80/10/10 2pp 01756-001

8011030328 Amend i to license for Transnuclear, Inc changing form of matl from U hexafluoride to U metal.
DEVINE, J B Assistant Director for Export/Import & International Safeguards MISC 321 80-073 80/10/27 1p 01756.001.

8011030342 License for Edlow Intl Co as agent for Meridian Enterprises to export 1.763 kg U-235, enriched to 10% w/o max, to Taiwan
DEVINE, J B Assistant Director for Export/Import & International Safeguards IH-2 80/10/27 2pp 01756 001

8011030431 Advises Executive Branch to change Item 20 on license to export, from 740 kg of U-235 to 370 kg
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/10/27. 1p. 06857 012.

8011050055 Application for Amend i to License X8NM-1362, to include Transnuclear Omh of West Germany as other intermediate consignee
MATSON, V. Transnuclear, Inc. 78-222/01 80/10/14. 1p 06896:296.

8011050464 Application by Sigma Chemical Co for license to export 10 kg deuterium oxide liquid to New Zealand.
STERN, W C. Sigma Chemical Co (subs of Sigma-Aldrich Corp.). D-96 80/10/20 1p 06898 223

8011050466 Application by Westinghouse for license to export five compensated ionization chambers to France
POCHAL, W F Westinghouse Electric Corp ZE-20293. 80/10/16. 1p 06898.224

8011050468 Forwards application for license to export 30 kg natural enrichment U dioxide powder to Italy.
WILSON, B D. General Electric Co. BDW 80 112 80/10/21 1p 06898 285

--8011050476 Application by QE for license to export 30 kg natural enrichment U dioxide powder to Italy
WILSON, B D General Electric Co BDW 80 112. 80/10/21 1p 06898-286.

8011060273 Discusses findings re Transnuclear, Inc application for license to import 1.591 kg U, enriched to max 88.1% U-235, from Canada. Recommends issuance of license
MOORE, R N Office of International Programs, Director. 80/10/23 1p 03710:264

--8011060279 License for Transnuclear, Inc to import 1 591 kg U, enriched to max 88.1% U-235, from Canada
DEVINE, J B Office of International Programs, Director 80/10/23 2pp 03710 265

8011060303 Executive Branch position re Transnuclear, Inc application for license to export 3 409 kg of U-235 enriched to max 4 5% to West Germany
NOSENZO, L V State, Dept. of 80/10/17 1p 06912 314

8011060308 Executive Branch position re Westinghouse application for license to export 564 MW electric PWR to Korea
NOSENZO, L V State, Dept of 80/10/16 2pp 06912 313

8011060330 Executive Branch position re Chase Brass & Copper Co, Inc application for license to export zirconium-niobium coolant tubes to Romania
NOSENZO, L V State, Dept of 80/10/16. 2pp 06912-311

8011060336 Executive Branch position re QA Co application for license to export control rod elements, drives, ion & fission chambers & electronic equipment to West Germany
NOSENZO, L V State, Dept of 80/10/16 2pp 06911.324.

8011060345 Forwards application by Exxon Nuclear, Inc for license to export 7,000 kg U, containing 225 kg U-235, to West Germany.
HANSEN, L E Exxon Nuclear Co., Inc. (subs of Exxon Corp.), 80/10/02. 1p 02319.176.

--8011060349 Application by Exxon Nuclear Co, Inc for license to export 7,000 kg U, containing 225 kg U-235, to West Germany.
HANSEN, L E Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 80/10/02 2pp 02319:176

8011060348 Executive Branch position re Chase Brass & Copper Co, Inc application for license to export zirconium-niobium coolant tubes to Romania
NOSENZO, L V. State, Dept of 80/10/16. 2pp. 06912:309.

8011060355 Forwards application by Transnuclear, Inc for license to export 10.794 kg U, containing 367 kg U-235, to Belgium
MATSON, V. Transnuclear, Inc 80-206/01 80/10/06 1p. 06910:001

--8011060360 Application by Transnuclear, Inc for license to export 10.794 kg U, containing 367 kg U-235, to Belgium End use statement encl
MATSON, V Transnuclear, Inc. 80-206/01 TNP-3 80/10/06 3pp. 06910.001.

8011060398 Forwards application by Exxon Nuclear Co, Inc for license to export 2,670 kg U, containing 76 kg U-235, to West Germany.
HANSEN, L E Exxon Nuclear Co., Inc (subs. of Exxon Corp.), 80/10/02 1p 06910.001

--8011060402 Application by Exxon Nuclear Co, Inc for license to export 2,670 kg U, containing 76 kg U-235, to West Germany
HANSEN, L E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 80/10/02 1pp 06910:001.

8011060332 License for Mitsui & Co to export 101.853 lb Zircaloy-2 & Zircaloy-4 tube shells to Japan.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 136175. 80/10/30 1pp. 02319:196

8011060534 License for Aldrich Chemical Co to export 5 kg deuterium oxide to South Korea
DEVINE, J B Assistant Director for Export/Import & International Safeguards. 22/80 80/10/29 1pp 06910.001

8011060536 License for Mitsubishi Corp to export 500 mCi Cf-252 to Japan
DEVINE, J B Assistant Director for Export/Import & International Safeguards 64-7479-80 80/10/30. 2pp. 06910:001.

8011060538 Executive Branch position re QA Co application for license to export \$200,000 worth of replacement parts to Indonesia Ltr of assurance encl License should be granted.
NOSENZO, L V. State, Dept of. Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 80/10/16 3pp. 06911:358.

8011060540 License for Sigma Chemical Co to export 10 kg deuterium oxide to Australia.
DEVINE, J B Assistant Director for Export/Import & International Safeguards D-55 80/10/30 2pp 06910:001.

NONDOCKETED ITEMS

- 8011040544 Executive Branch position re GE application for license amend to increase amount of SNM export to Taiwan Ltr of assurance encl Amend should be granted
QUINN, M. A. State Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/10/24 4pp 06915 262
- 8011040547 Requests Executive Branch position re Transnuclear, Inc application for license to export SNM to West Germany
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80/10/29 1p 06909 279
- 8011040550 Requests Executive Branch position re Transnuclear, Inc application for license to export SNM to West Germany
DEVINE, J. B. Office of International Programs, Director 80/10/29 1p 06909 284
- 8011040686 Requests Executive Branch position re Westinghouse application for license to export Np-237 to South Korea w/o encl application
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80/10/29 1p 06914:332
- 8011040789 Requests Executive Branch position re Teledyne Isotopes application for license to export 2.9 kg depleted U to China as part of TLD dosimeter w/o encl application
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80/10/31 1p. 06909 097
- 8011040792 Requests Executive Branch position re C-E applications for licenses to export two power reactors, initial cores & three reloads each to Taiwan w/o encl applications
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80/10/30 1p. 06909:098
- 8011040796 Executive Branch position re QA Co application for license to export one research reactor to Malaysia Ltr of assurance encl License should be granted
NGSENZO, L. V. State Dept of, Bureau of Oceans & Internatl. Environ & Scientific Affairs 80/10/29 27pp 06909 108
- 8011070083 Confirms 801030 telcon re request by ultimate consignee to transport involved matl as promptly as possible
HANSON, L. E. Exxon Nuclear Co., Inc (subs of Exxon Corp) 80/10/30 1p 06910:001
- 8011070088 Amend 1 to Monsanto Research Corp export license adding New Zealand to list of approved countries
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80/10/31 1p 06910 001.
- 8011070093 License for GE to export 200 kg natural U as U dioxide powder & pellets to Canada
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards BDN 80106 80/10/31 2pp 06910 001
- 8011070099 License for Transnuclear, Inc to export 10,794 kg U, containing 367 kg U-235, to Belgium
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80-206/01 TNP-3 80/10/31 2pp 06910 001
- 8011070105 Application by General Motors Corp for license to export ball bearing screw assemblies used in refueling sys that loads & unloads fuel elements into reactor to Canada
* General Motors Corp. 83352-3 80/10/20 1p 06920.238.
- 8011070109 Application by Edlow Intl Co for license to export 270 kg U-235, contained in 8,558 kg U, to Japan
HARMON, D. W. Edlow International Co UES JA 13. 80/10/27 1p 06920 239.
- 8011070113 Forward application to export 792 kg U-235, contained in 28,380 kg U, to Japan.
BAIKI, T. Mitsui & Co (U S A), Inc (Subs of Mitsui & Co ,Ltd) 80/10/29 1p 06920 240
- 8011070120 Application by Mitsui & Co (USA) for license to export 792 kg U-235, contained in 28,380 kg U, to Japan
TAMA, K. Mitsui & Co (U S A), Inc (Subs of Mitsui & Co ,Ltd.). MBK-F5-R4 80/10/29 1p. 06920:241
- 1070303 Forwards application for license for minor nuclear export re of assurance required.
VINE, J. B. Assistant Director for Export/Import & International Safeguards 80/10/17 1p 06921:029.
- 100018 License for Carpenter Technology Corp to export 480 pieces caloxy-4 fuel channels to Italy
VINE, J. B. Assistant Director for Export/Import & International Safeguards. JDB 14135. 80/11/03. 1p 06916 001
- 801100022 License for QA Co to export miscellaneous specially designed parts & components for use in nuclear reactor to Italy
Export of assembled pressure vessels, primary coolant pumps or control rods not authorized
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards IEL-2012 80/11/03 1p 06916 001
- 801100033 Responds to FOIA request for PSAR or PSIR & records re design, siting &/or consideration of Taiwan Power Nuclear Units 7 & 8 NRC has no documents equivalent to PSAR or PSIR re foreign facilities Forwards PA Bradford 801010 memo
FELTON, J. M. Division of Rules and Records. 80/11/04 1p 06928 247
- 801100041 Requests legal basis for staff position that NRC may act on license application prior to time contract is awarded
Response required by 801031
BRADFORD, P. A. Commissioners 80/10/10 1p
- 801100123 Lists additions & revisions to NMBS review section & coordination statement re proposed License ISNM-79005 for import of low enriched U from USSR
SHERR, T. B. Material Control & Accountability Development Branch 79/04/06 1p
- 801100392 Forwards license application for Teledyne Isotopes to export source matl to China
EAGLESDON, D. Teledyne Isotopes 80/10/24 1p 06929.291
- 801100395 Application by Teledyne Isotopes for license to export 2 U-238 calibr plates contained in wood case to China
* Teledyne Isotopes 80/10/24 2pp 06929 292
- 801110202 License for Aldrich Chemical Co to export 5 kg deuterium oxide to Venezuela
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 20/80 80/10/30 2pp. 06915 001
- 801110206 License for TX Nuclear Div to export 1 g Pu-238 to Norway
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 760013 80/10/30 2pp 06915 001
- 801110212 Forwards license application for Mitsui & Co (USA), Inc to export SNM to Japan
BAIKI, T. Mitsui & Co (U S A), Inc (Subs. of Mitsui & Co ,Ltd) 80/10/27 1p 06944.042
- 801110221 Application by Mitsui & Co (USA), Inc for license to export 5,429 kg U, containing 146 kg U-235, to Japan
TAMA, K. Mitsui & Co. (U S A), Inc. (Subs of Mitsui & Co ,Ltd.) MBK-F5-R4(A) 80/10/27 1p 06944 043
- 801110657 Notifies that there are no matl changed circumstances associated w/application from those at issuance of
XSNM-1674 License may be issued
MOORE, R. N. Assistant Director for Export/Import & International Safeguards 80/10/30 1p 06948 229
- 801110665 Notifies that there are no matl changed circumstances associated w/application from those existing at issuance of
XSNM-1672. License may be issued
MOORE, R. N. Assistant Director for Export/Import & International Safeguards 80/10/30. 1p 06948.230
- 801110672 Letter of assurance re Transnuclear, Inc application to export 0.016 kg U-235 to France
MARCHAL, J. European Communities, Commission of 80/10/22 1p 06944 362.
- 801110678 Letter of assurance re GE application to export 200 kg U oxide powder to Canada
CARROTHERS, W. D. Canada 15-2-C33 80/10/15 1p 06944:357
- 801110691 Ltr of assurance re Seasmal Transport Corp application for license to export 72.5 g Pu contained in 172 Pu stds & 316 66155 g U-235 contained in 580 g total U, to Belgium.
MARCHAL, J. European Communities, Commission of. 80/10/22 1p 06947.341
- 801110697 Ltr of assurance re Transnuclear, Inc application for license to export 367 kg U-235 contained in 10,794 kg U, to Belgium
MARCHAL, J. European Communities, Commission of 80/10/22 1p 06947 342
- 801110703 Notifies that Aldrich Chemical Co license to export deuterium oxide to South Korea, was issued w/o customary 15-day waiting period
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80/10/28 1p 06947:351.

NONDOCKETED ITEMS

305

801110749 Ltr of assurance re application for license to export 833 kg U-235, enriched to max 3.95%, to Japan Tokyo Power Co, Inc appointed authorized person
HIYABAYASHI, M Japan 80/10/07 1p 06947 353

801110718 Ltr of assurance re Transnuclear, Inc application for license to export 533 kg U-235, contained in 15,900 kg total U & 0.0335 kg U-235, contained in 1.0 kg total U, to West Germany
MARCHAL, J European Communities, Commission of 80/10/22 1p. 06947 354

801110735 Notifies that there are no matl changed circumstances associated w/application from those existing at issuance of license XSNM-1657 License may be issued
MOORE, R N Assistant Director for Export/Import & International Safeguards 80/10/30 1p 06947 355

801110778 Application by C-E Power Sys for license to export nuclear fuel loadings, to Taiwan
WEST, J M C-E Power Systems 80/10/09 4pp 06948 009.

801110801 Application by C-E Power Sys for license to export two NSSS, to Taiwan
WEST, J M C-E Power Systems 80/10/09 3pp 06948:016

801110809 Application, on behalf of Union Carbide Corp, for amend of XSNM-1995 changing max enrichment to 93.15%
BUTENKOT, A Transnuclear, Inc. 80/10/08 1p 06948 019

801110821 License for Transnuclear, Inc to export 572 mCi Cf-252 in cermet pellet form to West Germany
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80-134/01 80/11/05, 2pp 06915.001

801110823 Application for license to export initial nuclear fuel loadings, containing 177 fuel assemblies, to Taiwan
WEST, J M C-E Power Systems 80/10/09 4pp 06948:025.

8011120002 Letter of assurance re OA Co application to export 862 g U-235 to Italy.
MARCHAL, J European Communities, Commission of. 80/10/22 1p. 06953 177

8011120035 Informs of Commission approval of Amend 7 to Boeing Co license to export depleted U to Angola per SECY-80-446 Discusses considerations in approving amend & stipulations that were made in connection w/amend
CHILK, S J Office of the Secretary of the Commission 880-446 80/10/27 1p. 06953:273

8011120037 Forwards Executive Branch response on pending export license application requiring Commission review Requests final review as soon as possible to facilitate early response to forthcoming action paper.
SHEA, J R Office of International Programs, Director. 80/10/28. 1p 06953:332

8011120430 Requests written confirmation of fabricators involved in mfg of highly enriched U to assist in review of export license applications to West Germany
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 80/10/31 1p

8011120692 License for Westinghouse to export one proportional counter, Model WL 23770, to West Germany
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/11/05 1p 06916.001

801113008B Application by Isotope Products Labs for license to export curium oxide solid to West Germany.
HELM, K B. Isotope Products Laboratories 8135 80/11/04. 1p. 06958.257

8011130092 License for OA Co to export miscellaneous specially designed or prepared parts & components to Indonesia.
DEVINE, J B Assistant Director for Export/Import & International Safeguards. IEL-1192. 80/11/05 1p 02227:001

8011130412 License for Mitsui & Co (USA), Inc to export 813 kg U-235, contained in 29,648 kg U, to Japan.
DEVINE, J B Assistant Director for Export/Import & International Safeguards. MBK-F3-R6 80/11/04. 2pp 02227.001.

801114018B License for Transnuclear, Inc to export 533 kg U-235, contained in 15,900 kg U & 0.0335 kg U-235, contained in 1.0 kg U, to West Germany.
DEVINE, J B Assistant Director for Export/Import & International Safeguards. RBV 348 80-203/. 80/11/04. 2pp. 06911:001.

8011140192 License for Transnuclear, Inc to export 0.016 kg U-235, contained in 1.840 kg U, to France
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80-184/01 TNY-3 80/11/04 2pp. 06911 001.

8011140247 License for OA Co to export 0.862 kg U-235, contained in 4.334 kg U, to Italy.
DEVINE, J B Assistant Director for Export/Import & International Safeguards IEL-2013 80/11/04 2pp. 06911 001

8011140255 Amend 1 to OE license, increasing amount of export from 0.25 kg U-235, contained in 2.5 kg U, to 0.90 kg U-235, contained in 4.5 kg U
DEVINE, J B Assistant Director for Export/Import & International Safeguards BDW 79186. 80/11/04 1p 06911 001

8011140261 Forwards Exxon Nuclear Co 801030 ltr advising that ultimate consignee would like matl to be exported as soon as possible H/o encl.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/11/04 1p 06960 279

8011140449 Forwards Byron Jackson Pump Div application for license to export components to India Same equipment was authorized for export under expired License XCOM-0203 Requests review H/o encl.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/11/03 1p. 06962 361.

8011140547 Forwards Edlow Intl Co 801031 mailgram re end uses for proposed re-export of C/F-252 source to India H/o encl.
DEVINE, J B Assistant Director for Export/Import & International Safeguards. 80/11/06 1p. 06963:008.

8011140656 SECY-80-487
Informs Commission of Executive Branch response on pending application for license to export fuel to West Germany Requests Commission advice re info that should be included in analysis
SHEA, J R Office of International Programs, Director 80/10/29. 1p 06963 011

--8011140668 Executive Branch position re Transnuclear, Inc application for license to export 3.409 kg U-235, enriched to max of 45.4%, to West Germany. License should be granted Ltr of assurance encl.
NOSENZO, L V State, Dept of, Bureau of Ocean & Internatl Environ & Scientific Affairs 80/10/17 3pp. 06963 012

--8011140679 Forwards Transnuclear, Inc application for license to export ENM to West Germany. Requests views on whether proposed export meets applicable criteria in Atomic Energy Act of 1954
DEVINE, J B Assistant Director for Export/Import & International Safeguards. 80/08/29. 1p 06963 018

--8011140684 Application by Transnuclear, Inc for license to export 7.508 kg U, enriched to max of 45.4%, to West Germany End use statement encl.
* Transnuclear, Inc NUK-339 80-180 80/08/25. 2pp 06963 019.

--8011140690 Forwards application for license to export 7.508 kg U, enriched to max of 45.4%, to West Germany H/o encl
MAYBON, V. Transnuclear, Inc 80-180/01 80/08/25 1p 06963:021

8011140663 Forwards application for license to export single reloads of low enriched U fuel. Ltr of assurance required H/o application
DEVINE, J B Assistant Director for Export/Import & International Safeguards. 80/11/04 1p. 06963 313

8011140667 Forwards application for license to export single reloads of low enriched U fuel. Ltr of assurance required. H/o application.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/11/04 1p. 06962.360

8011170085 Forwards Byron Jackson Pump Div application for license to export tandem type mechanical seal cartridge, specially prepared for use in coolant pumps, to India
NORTON, J F Borg-Warner Corp. Byron Jackson Pump Div. 80/10/27 1p 06915:001.

--8011170090 Application by Byron Jackson Pump Div for license to export tandem type mechanical seal cartridge, specially prepared for use in coolant pumps, to India.
NORTON, J F Borg-Warner Corp. Byron Jackson Pump Div. 781 V 2814. 80/10/27 1p. 06915.001

NONDOCKETED ITEMS

- 801170120 Amend 1 to license for CA Co to add Bandung II Reactor as another ultimate consignee & increase quantity of matl authorized for export from 1 943 kg U to 4 478 kg U enriched to 19.9 w/o U-235
DEVINE, J B Assistant Director for Export/Import & International Safeguards IEL-1159 80/11/03 1p 06911 001
- 801170759 License for Transnuclear, Inc to export 2 951 kg U-235, contained in 6 5 kg U to West Germany
DEVINE, J B Assistant Director for Export/Import & International Safeguards (NUK-337) 80-16 80/11/07 2pp 06978 333
- 801170812 Executive Branch position re Delegation of Commission of European Communities & Transnuclear, Inc applications for licenses to export 56 624 kg U enriched to 93.3% to West Germany Ltrs of assurance encl. Licenses should be granted
NOSENZ, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/11/03 6pp. 06981 286
- 801170863 Recommends issuance of license to Transnuclear, Inc, authorizing import of 500 g U, enriched to 8.0% as U dioxide pellets, from Belgium Proposed import represents no change to previous imports
MOORE, R N Office of International Programs, Director 80/10/08 1p 06979 355
- 801180012 Requests ltr of assurance that export license application will be suby to terms & conditions of Agreement for Cooperation Application not encl
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/10/28 1p 06986:096
- 801180149 Amend 1 to license for Edlow Intl Co extending expiration date from 810701 to 840701
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/11/10, 2pp 06987 207
- 801180781 Requests expeditious processing of license to export 25 microgram Cm-244 to West Germany. Matl ready for shipment
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/11/06 1p 06915:001
- 801180784 License for Isotope Products Labs to export 25.0 microgram Cm-244, as oxide, to West Germany
DEVINE, J B Office of International Programs, Director W/D 8135 80/11/06 2pp 06915:001
- 801180801 Forwards Executive Branch response re pending application for license to export research reactor to Malaysia & ancillary application Requests review W/o encl
SHEA, J R Office of International Programs, Director 80/11/05 1p 06991 340
- 801180864 Forwards revised application for license to export Zircaloy-4 & hafnium components for installation in ATUCHA CNA-2 reactor in Argentina
MOZNIAK, D R Carpenter Technology Corp 80/10/10 1p. 06992 021.
- 801180866 Revised Application by Carpenter Technology Corp for license to export Zircaloy-4 & hafnium reactor components to Argentina
* Carpenter Technology Corp 80/10/10, 4pp. 06992 022
- 801180876 Forwards ltrs written to Executive Branch re request for export license to ship Cf-252 neutron source to BARC in India
TAYLOR, R R Monsanto Co. 80/10/29, 3pp 06991 359
- 801190010 BECY-80-493
Forwards, for info of Commission, 801007 applications for C-E to export two PHWRs, initial cores & three reloads each, to Taiwan GE & Westinghouse have also applied for licenses to supply same reactors, cores & reloads.
SHEA, J R Office of International Programs, Director. 80/11/03 1p
- 801190666 Informs that NRC has not completed licensing action on export license application XSNM-1700 for low enriched U to Switzerland for QC audit. Ack receipt of 800821 assurance ltr from embassy. Final action delayed
SHEA, J R Office of International Programs, Director 80/11/04 1p 03742 207
- 801190670 Requests amend to export license extending expiration date three yrs.
HARMON, D. Edlow International Co 80/10/31 1p. 06916 001.
- 801190675 Forwards export license application for low enriched U fuel. Ltr of assurance required. W/o encl
DEVINE, J B Assistant Director for Export/Import & International Safeguards. 80/11/04, 1p 07001:235.
- 8011200171 Forwards application for export license for minor nuclear export Ltr of assurance required. W/o encl
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/11/10 1p 07021 226
- 8011200213 Ltr of assurance re GE application for license to export 30 kg natural enrichment U dioxide powder to Italy
MARCHAL, J European Communities, Commission of. 80/11/05 1p 07019 351
- 8011200362 Forwards application for license to export primary sources to South Korea
HERSCH, M M Westinghouse Electric Corp ILS-011 80/11/05 1p 07020.052
- 8011200366 Application by Westinghouse for license to export two primary source rods, each containing max 125 mCi Cf-252, for total max 470 micrograms to South Korea
HERSCH, M M Westinghouse Electric Corp, ILS-011 80/11/05 1p 07020 053
- 8011200370 Forwards application for license to export Zirconium tubes to United Kingdom
HERSCH, M M Westinghouse Electric Corp ILS-012 80/11/06 1p 07020.054
- 8011200373 Application by Westinghouse for license to export 1,600 pieces Zirconium-4 tubes to United Kingdom
HERSCH, M M Westinghouse Electric Corp ILS-012 80/11/06 1p 07020 055
- 8011200404 Submits application for license to import 76 kg U-235, contained in 2,000 kg U, from Italy
WILSON, B D. General Electric Co BDW 80115 80/11/07 2pp. 07020 070
- 801120020 License for GE to export 30 kg natural U as U dioxide power to Italy
DEVINE, J B Assistant Director for Export/Import & International Safeguards BDW-80112, 80/11/10 2pp 07030 352
- 8011200442 License for Transnuclear, Inc to export 2,799 kg U-235, contained in 3 kg U to West Germany
DEVINE, J B Assistant Director for Export/Import & International Safeguards NUK-328 80-033/ 80/11/10 2pp 02227.001.
- 801120047 License for Sigma Chemical Co to export 10 kg deuterium oxide to New Zealand
DEVINE, J B Assistant Director for Export/Import & International Safeguards. D-56 80/11/12, 2pp 07030:358
- 801120053 Submits application by Radiation Mgt Corp for license to export two power range detector assemblies, Model WL-236, & addl miscellaneous nuclear equipment to South Korea.
O'MALLEY, T E Radiation Management Corp 80/11/05 2pp. 02227:001.
- 801120054 License for Westinghouse to export five compensated ionization chambers, Model WL23944, to France.
DEVINE, J B Assistant Director for Export/Import & International Safeguards ZE-20293 80/11/12, 1p. 07030 360
- 801120082 Requests Executive Branch position re Transnuclear, Inc application for license to export SNM to West Germany. W/o encl 801024 application
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/11/10, 1p 07031.211
- 801120088 Requests Executive Branch position re Westinghouse application for license to export Cf-252 sources to South Korea W/o encl 801105 application
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/11/12 1p. 07031 212
- 801120091 Application by Aldrich Chemical Co, Inc for license to export 1 kg deuterium in 5 kg deuterium oxide to Venezuela
EDELSTEIN, B Aldrich Chemical Co, Inc (subs of Sigma-Aldrich Corp.) 23/80, 80/11/04, 1p 07037 081
- 801120096 Application by Sigma Chemical Co for license to export equivalent of 10 kg deuterium oxide liquid over two-yr period to Canada
* Sigma Chemical Co (subs of Sigma-Aldrich Corp). D-57 80/11/10, 1p 07037.082.
- 801120101 Forwards application for license to export 15,048 kg U, containing 802 kg U-235, to Japan. End use statement encl.
SHIMA, B. Mitsubishi International Corp. (subs. of Mitsubishi Corp.) HBA-5480-10 80/10/21, 5pp. 07037.083.

NONDOCKETED ITEMS

307

--801121011 Application by Mitsubishi Intl Corp for license to export 15,048 kg U, containing 502 kg U-235, to Japan
e Mitsubishi International Corp (subs of Mitsubishi Corp).
HBA-5480-10. 80/10/21 1p 07037 087

801121016 Application by Transnuclear, Inc for license to export 2,002 mCi Cf-252 as cermet wire & Pd-Cf203 wire in bare form to France.
BUTENQ, T A Transnuclear, Inc TNP 356 80-238/ 80/11/04 1p 07037 090

8011210122 Executive Branch position re Edlow Intl application for license to export 117,319 kg U, in form of U-308, to West Germany Ltr of assurance encl License should be granted
NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/11/07 3pp 07037 091

8011210130 Executive Branch position re OA Co application for license to export 959 g U-235, contained in 1,372 g U, to Yugoslavia, License should be granted
NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/11/09 30pp 02227:001

8011210135 Requests mod to 801031 application, revising expiration date from 810101 to 860101, monetary value & scope of package
HERSCH, M M Westinghouse Electric Corp ILS-013 80/11/10, 1p, 07037:143.

8011210147 Approves Westinghouse request for license to export zirconium tubing to United Kingdom. License issued w/o 15-day waiting period
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/11/10 1p 07032:323

--8011210150 License for Westinghouse to export zirconium tubing to United Kingdom
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80/11/10 1p 07032:324.

8011240038 Advises that NRC has not completed licensing action on application to export highly enriched U to West Germany
Favorable Executive Branch views were received on 800903
Final action expected in near future.
SHEA, J. R. Office of International Programs, Director 80/11/05 1p, 07039:256.

8011240205 Application by Sandvik Special Metals Corp for license to export 40 pieces Sandvik Zr-4 Caterpillar thimble tube, totalling 50 lbs, to Japan
NICKLAUS, J W Sandvik Special Metals Corp 80/11/13, 1p 07042 360.

8011240411 Forwards application for renewal of License XB-4357 Amend 2 w/requested life of 10 yrs
EVRAETS, J. C. California, Univ. of, Los Angeles 80/11/04, 2pp 07049:114

--8011240416 Application by UCLA for license to export 1 Ci tritium at no more than 10 mCi per shipment for 10 years.
EVRAETS, J. C. California, Univ. of, Los Angeles 80/11/03, 1p 07049:116

8011250711 Forwards Executive Branch responses to pending applications for export licenses. Final review requested to facilitate early response to forthcoming action papers w/o encls
SHEA, J. R. Office of International Programs, Director. 80/11/17, 1p 07056:049.

8011250715 Forwards Executive Branch views on two pending applications for licenses to export highly enriched U to West Germany.
w/o encls.
SHEA, J. R. Office of International Programs, Director. 80/11/18 1p, 07056:043

8011250718 Forwards Executive Branch views on pending application for license to export highly enriched U to Yugoslavia w/o encls
SHEA, J. R. Office of International Programs, Director 80/11/18, 1p, 07056 044

8011260158 Discusses findings re application by Ramsey Engineering Co for license to import 123 2 mg Pu-238, contained in 70 Pu-238 sources. License should be granted
MOORE, R N Office of International Programs, Director 80/10/24 1p 07080:108.

--8011260160 License for Ramsey Engineering Co to import 123 2 mg Pu-238, contained in 70 Pu-238 sources, from any country
DEVINE, J. B. Office of International Programs, Director 80/10/24 1p, 07080 109

8011260240 Requests extension of export license expiration to 810701
WILSON, B. D General Electric Co BDW 80123. 80/11/14, 1p 07071:360

8011260250 Ltr of assurance for Edlow Intl Co to export 0 50 g U-235, in 5 g U & 0 077 g U-235, in 5 g U, to Japan.
MIYABAYASHI, M Japan 80/11/05, 1p 07072 092

8011260312 Requests extension of export license expiration date from 810201 to 820201
MATSON, V. Transnuclear, Inc 80/11/12 1p 07072:206

8011260384 Forwards application for export license for minor nuclear export Ltr of assurance required, w/o encl.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 80/11/17 1p, 07072:315

8011260388 Application by Edlow Intl Co for license to export 26 kg U, as U hexafluoride, to France
HARMON, D Edlow International Co. URN-4 80/10/29 1pp, 07072:316.

8011260402 Executive Branch position re Edlow Intl Co application for license to export 3,790 kg depleted U to United Kingdom
License should be issued
NOSENZO, L V. State, Dept. of, Bureau of Oceans & Internatl. Environ & Scientific Affairs. 80/11/14, 2pp, 07072:331

8011260406 Executive Branch position re Transnuclear, Inc application for license to export 1 704 kg U-235, in 3 735 kg U & 6 384 kg U-235, in 33 kg U to Austria, License should be issued, Ltrs of assurance encl
NOSENZO, L V. State, Dept of, Bureau of Oceans & Internatl. Environ & Scientific Affairs 80/11/10, 4pp 07072:333

8011260436 Executive Branch position re Transnuclear, Inc application for license to export 4 078 kg U-235, enriched to max 93.3%, to Austria License should be issued.
NOSENZO, L V. State, Dept. of, Bureau of Oceans & Internatl Environ. & Scientific Affairs 80/11/10 4pp, 07073:090.

8011260447 License for Edlow Intl Co to export 117,319 kg natural U, in form U-308, to West Germany.
DEVINE, J B Assistant Director for Export/Import & International Safeguards. NUEX-1 80/11/17, 2pp, 01741:019.

8011260451 Amend 1 to license for Transnuclear, Inc extending expiration date from 810201 to 820201.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80-009/01 MISC-. 80/11/17, 1p 01741:019

8011280147 Amend 1 to license for Westinghouse extending expiration date from 810101 to 860101, increasing value of exported equipment & revising description of exported matl
DEVINE, J. B Assistant Director for Export/Import & International Safeguards. 80/11/17, 1p, 06913:001

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ABEL, J. S.	8011060575	50-237 Q	AHEARNE, J. F.	8011170606*	COMMISSION	AHEARNE, J. F.	8011170442*	50-320 P
ABEL, J. S.	8011050110*	50-454 Q	AHEARNE, J. F.	8011170607*	COMMISSION	AHEARNE, J. F.	8011170445*	50-320 P
ABEL, J. S.	8011050123*	50-454 Q	AHEARNE, J. F.	8011170608*	COMMISSION	AHEARNE, J. F.	8011110575	COMMISSION
ABEL, J. S.	8011280206*	50-454 Q	AHEARNE, J. F.	8011170614*	COMMISSION	AHEARNE, J. F.	8011180269	COMMISSION
ABEL, J. S.	8011040197	50-237 P	AHEARNE, J. F.	8011170616*	COMMISSION	AHEARNE, J. F.	8011180274*	COMMISSION
ABEL, J. S.	8011200062	50-249 Q	AHEARNE, J. F.	8011170620*	COMMISSION	AHEARNE, J. F.	8011180277*	COMMISSION
ABEL, J. S.	8011040370	50-295 P	AHEARNE, J. F.	8011170621*	COMMISSION	AHEARNE, J. F.	8011180282*	COMMISSION
ABEL, J. S.	8011040394	50-10 P	AHEARNE, J. F.	8011170625*	COMMISSION	AHEARNE, J. F.	8011180285*	COMMISSION
ABEL, J. S.	8011210769*	50-454 Q	AHEARNE, J. F.	8011170627*	COMMISSION	AHEARNE, J. F.	8011180289*	COMMISSION
ABEL, J. S.	8011060491	50-237 P	AHEARNE, J. F.	8011170630*	COMMISSION	AHEARNE, J. F.	8011180293*	COMMISSION
ABEL, J. S.	8011190347	50-237 P	AHEARNE, J. F.	8011170633*	COMMISSION	AHEARNE, J. F.	8011180301*	COMMISSION
ABEL, J. S.	8011250696	50-10 Q	AHEARNE, J. F.	8011170636*	COMMISSION	AHEARNE, J. F.	8011180616	50-320 U
ABEL, J. S.	8011210592	RE900	AHEARNE, J. F.	8011170639*	COMMISSION	AHEARNE, J. F.	8011180621*	50-320 U
ABEL, J. S.	8011240342	50-373 A	AHEARNE, J. F.	8011170642*	COMMISSION	AHEARNE, J. F.	8011180624*	50-320 U
ABEL, J. S.	8011240349	50-373 A	AHEARNE, J. F.	8011170644*	COMMISSION	AHEARNE, J. F.	8011190334	50-320 P
ABEL, J. S.	8011240278	50-373 K	AHEARNE, J. F.	8011170648*	COMMISSION	AKER, R. E.	8011180723*	50-295 B
ABEL, J. S.	8011240378	50-373 K	AHEARNE, J. F.	8011170652*	COMMISSION	AKER, R. E.	8011230337*	50-295 B
ABERCROMBIE, H.	8011140025	50-294 B	AHEARNE, J. F.	8011170654*	COMMISSION	AKI, K.	8011170504	50-361 A
ABERCROMBIE, H.	8011140035	50-259 B	AHEARNE, J. F.	8011170657*	COMMISSION	AKSTULEWICZ, F.	8011120070	REB
ABERCROMBIE, H.	8011140086	50-259 B	AHEARNE, J. F.	8011170658*	COMMISSION	ALDEN, W. H.	8011250308	50-277 P
ABERCROMBIE, H.	8011180588	50-259 R	AHEARNE, J. F.	8011170662*	COMMISSION	ALDEN, W. H.	8011180673*	50-277 R
ABRAMS, R.	8011100458	PR	AHEARNE, J. F.	8011170664*	COMMISSION	ALLAN, J. M.	8011070590*	40-8364
ABRAMS, R.	8011100616	PR	AHEARNE, J. F.	8011170799*	COMMISSION	ALLAN, J. M.	8011210402*	50-289 Q
ABRUZZO, G.	8011060297*	QA999	AHEARNE, J. F.	8011170803*	COMMISSION	ALLAN, J. M.	8011200151*	50-213 Q
ABT, B. R.	8011120031	40-8402	AHEARNE, J. F.	8011170804*	COMMISSION	ALLEN, Q. N.	8011050121	PROJ
ABT, B. R.	8011050184	40-8084	AHEARNE, J. F.	8011170806*	COMMISSION	ALLEN, J. R.	8011040568*	50-348 Q
ABUAF, N.	8011140174	NURE0	AHEARNE, J. F.	8011170809*	COMMISSION	ALLEN, J. R.	8011210093*	50-327 Q
ACHARD, J. L.	8011050544	NURE0	AHEARNE, J. F.	8011170811*	COMMISSION	ALLENBACH, F. R.	8011000531*	50-289 Q
ACKERMAN, H. C.	8011070631	40-1162	AHEARNE, J. F.	8011170813*	COMMISSION	ALLISON, D. P.	8009290143	50-10 P
ADAM, D.	8011100631*	50-237 T	AHEARNE, J. F.	8011170815*	COMMISSION	ALLRED, D. L.	8011170210	70-2907
ADAMS, J. P.	8011130236	REB	AHEARNE, J. F.	8011170818*	COMMISSION	ANDERSON, B. S.	8011040247	REB
ADDITION, S. L.	8011170554*	PROJ	AHEARNE, J. F.	8011170819*	COMMISSION	ANDERSON, T. H.	8008260408	TOPREP
ADDITION, S. L.	8011170549*	PROJ	AHEARNE, J. F.	8011170822*	COMMISSION	ANDERSON, C.	8009110742	50-322 A
ADRIANA, J. M.	8011180015	50-484 Q	AHEARNE, J. F.	8011170824*	COMMISSION	ANDERSON, T. H.	8011070101	NURE0
ADRIANA, J. M.	8011180015	50-484 Q	AHEARNE, J. F.	8011170827*	COMMISSION	ANDERSON, T. H.	8011050443	TOPREP
AFIFI, B. A.	8011240443	50-329 T	AHEARNE, J. F.	8011170830*	COMMISSION	ANDERSON, T. M.	8011050452*	TOPREP
AGEE, J. R.	8011040094*	QA999	AHEARNE, J. F.	8011170832*	COMMISSION	ANDERSON, C.	8011210675*	50-397 A
AGENSROD, L. D.	8011040253*	40-8481	AHEARNE, J. F.	8011170834*	COMMISSION	ANDERSON, R. W.	8011030471*	50-282 Q
AHEARNE, J. F.	8009100073	COMMISSION	AHEARNE, J. F.	8011170836*	COMMISSION	ANDERSON, O. J.	8011250505	TOPREP
AHEARNE, J. F.	8010020403	COMMISSION	AHEARNE, J. F.	8011170838*	COMMISSION	ANDERSON, T. M.	8011030513	TOPREP
AHEARNE, J. F.	8011050090	50-339 U	AHEARNE, J. F.	8011170841*	COMMISSION	ANDERSON, T. M.	8011140060	TOPREP
AHEARNE, J. F.	8011100044	50-320 P	AHEARNE, J. F.	8011170793	COMMISSION	ANDERSON, P. B.	8011210644*	CONTRACT
AHEARNE, J. F.	8011100055	50-309 F	AHEARNE, J. F.	8011050044	50-294 U	ANDERSON, R. D.	8011100403	50-293 R
AHEARNE, J. F.	8011170345*	50-347 A	AHEARNE, J. F.	8011140678	50-320 P	ANDERSON, J. M.	8011040397	50-329 S
AHEARNE, J. F.	8011120098	COMMISSION	AHEARNE, J. F.	8011170410	50-320 P	ANDERSON, C. R.	8011120401*	50-244 Q
AHEARNE, J. F.	8011170587	COMMISSION	AHEARNE, J. F.	8011170413*	50-320 P	ANDERSON, T. M.	8011240188	TOPREP
AHEARNE, J. F.	8011170588*	COMMISSION	AHEARNE, J. F.	8011170418*	50-320 P	ANDERSON, T. H.	8011210624	50-445 A
AHEARNE, J. F.	8011170591*	COMMISSION	AHEARNE, J. F.	8011170419*	50-320 P	ANDERSON, T. H.	8011250686	TOPREP
AHEARNE, J. F.	8011170592*	COMMISSION	AHEARNE, J. F.	8011170421*	50-320 P	ANDREWS, D. L.	8011210093*	50-327 Q
AHEARNE, J. F.	8011170594*	COMMISSION	AHEARNE, J. F.	8011170422*	50-320 P	ANDREWS, D. L.	8011210137*	50-369 Q
AHEARNE, J. F.	8011170594*	COMMISSION	AHEARNE, J. F.	8011170426	COMMISSION	ANDRUS, N. J.	8011180873	40-4492
AHEARNE, J. F.	8011170598*	COMMISSION	AHEARNE, J. F.	8011170428*	50-320 P	ANDRUS, N. J.	8011060059	40-4492
AHEARNE, J. F.	8011170600*	COMMISSION	AHEARNE, J. F.	8011170433*	50-320 P	ANDRUS, N. J.	8010290379	40-4492
AHEARNE, J. F.	8011170602*	COMMISSION	AHEARNE, J. F.	8011170434*	50-320 P	ANEBHANSLEY, M.	8011060110*	50-298 Q
AHEARNE, J. F.	8011170604*	COMMISSION	AHEARNE, J. F.	8011170434*	50-320 P	ANQ, W. P.	8011050381*	50-364 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ANO, W. P.	8011200460*	50-416 Q	BASKIN, K. P.	8011200247	50-361 A	BETTENHAUSEN, L.	8011200056*	50-334 Q
ANSPACH, K.	8011040379	27-39	BASKIN, K. P.	8011250298	50-361 A	BEVILL, T.	8011200318	50-320 U
ANSPACH, K. Q.	8011030131	27-39	BASKIN, K. P.	8011280071	50-361 A	BIALIK, E. I.	8011040408	50-3 M
ANSPACH, K.	8011100233	27-39	BASKIN, K. P.	8011280009	50-361 A	BIALIK, E. I.	8011100488	PR
ANSPACH, K. Q.	8011110593	27-39	BATEMAN, W. H.	8011180472*	50-354 Q	BIALIK, E. I.	8011100616	PR
ANSPACH, K. Q.	8011250045	27-39	BATES, H. R.	8011110062	PR	BICKWIT, L.	8011040438	50-354 Q
ANSPACH, K. Q.	8011250694	27-39	BATES, R. W.	8011250320*	50-336 B	BICKWIT, L.	8011040490	50-264 Q
ANSPACH, K.	8011240159	27-39	BATTEN, B. Q.	801070362*	MISC	BICKWIT, L.	8011240478*	50-247 T
ANSPACH, K. Q.	8011250038	27-39	BAUM, E. A.	8010160487	50-338 F	BICKWIT, L.	8011240485*	50-247 T
ANSPACH, K. Q.	8011250633	27-39	BAUM, F. H.	8011180579*	50-133 R	BICKWIT, L.	8011250021	50-354 Q
APOSTOLAKIS, Q.	8011190096	NUREQ	BAUMANN, B. B.	8011040015	PR	BIDDLE, C. T.	8011140093	50-466 Q
APPELHANS, A. D.	8011080337	RES	BAUMANN, H.	8011190080	NUREQ	BIDDLE, C. T.	8011140093	50-466 Q
APPEL, R. R.	8011030658	40-8781	BAUMACK, W.	8011110412*	50-244 Q	BIDDLE, C. T.	8011210422	50-466 Q
ARAGON, R.	8011030532	NUREQ	BAUMACK, P. Y.	8011130152*	50-220 Q	BIELANSKI, A. P.	8011190013	50-233 Q
ARCHITZEL, R.	8011130113*	50-54 Q	BAWLEY, S. X.	8011200288*	50-366 B	BIELANSKI, A. P.	8011190013	50-233 Q
ARCHITZEL, R. E.	8011250675*	50-317 Q	BAXLEY, B. X.	8011280062*	50-321 B	BIELANSKI, A. P.	8011250628	50-253 Q
ARLDT, O. A.	8011200470*	REGD	BAXLEY, T. A.	8011040342	50-289 T	BIER, J.	8011040180	50-155 Q
ARNOLD, R. C.	8011120310	50-320 P	BAXTER, T. A.	8011100283	50-483 Q	BIGARELLI, M. J.	8011210515*	50-243 Q
ARNOLD, R. C.	8011120424	50-289 H	BAXTER, T. A.	8011100283	50-483 Q	BIRD, R. D.	8011250331*	50-443 A
ARSENAULT, F. J.	8011100226*	RES	BAXTER, T. A.	8011190196	50-289 Q	BIRKEL, R. A.	8011060162	50-369 A
ARSENAULT, F. J.	8011100232*	RES	BAXTER, T. A.	8011190196	50-289 Q	BIRKEL, R. A.	8011210312	50-369 A
ASH, R. F.	8011190398	50-317 Q	BAWLEY, P. Y.	8011060077	RES	BIRKEL, R. A.	8011100030	50-369 A
ASWELL, D. L.	8011110692	50-382 B	BAWLEY, P. Y.	8011040190	50-302 F	BIRKEL, R. A.	8011170046	50-369 A
ASWELL, D. L.	8011260414*	50-382 Q	BAWLEY, P. Y.	8011030611	50-302 P	BIRKEL, R. A.	8011210616	50-369 A
ASWELL, D. L.	8011240306	50-382 K	BAWLEY, P. Y.	8011090458	50-302 P	BISHOP, T. W.	8011200135*	50-460 Q
ASWELL, D. L.	8011240320*	50-382 K	BAWLEY, P. Y.	8011210249	50-302 Q	BISHOP, T. W.	8011200129*	50-460 Q
ASWELL, D. L.	8011240326*	50-382 K	BAWLEY, P. Y.	8011210384	50-302 Q	BISHOP, C. J.	8011040406	50-409 Q
AULHOUSE, D. L.	8011060709*	50-320 H	BAWLEY, P. Y.	8011110243	50-302 P	BISHOP, T. W.	8011200117*	50-460 Q
AUSTIN, M. A.	8011070546*	70-135	BAWLEY, P. Y.	8011210299	50-302 P	BISHOP, C. J.	8011040409	50-460 Q
AUSTIN, M. A.	8010240369	71-5768	BAWLEY, P. Y.	8011250349	50-302 P	BISHOP, C. J.	8011070198	50-278 Q
AUSTIN, M. P.	8011030242	50-320 P	BAYNE, J. P.	8011030452	50-286 P	BISHOP, C. J.	8011100263	50-278 Q
AUSTIN, M. A.	8011120053	71-4400	BAYNE, J. P.	8011070503	50-286 F	BISHOP, C. J.	8011100451	50-443 Q
AUSTIN, M. A.	8011260074	TOPREP	BAYNE, J. P.	8011040464	50-286 V	BISHOP, C. J.	8011170899	50-338 Q
AUTIO, H. A.	8011100475	50-29 B	BAYNE, J. P.	8011030529	50-286 P	BISHOP, C. J.	8011240491	50-338 Q
AUTIO, H. A.	8011140046	50-29 B	BAYNE, J. P.	8011030536*	50-286 P	BISHOP, C. J.	8011280001	50-367 Q
AVCI, H. I.	8011050554	NUREQ	BAYNE, J. P.	8011040182	50-286 P	BISHOP, C. J.	8011280016	50-263 Q
AXELROD, L. R.	8011120534	MISC	BAYNE, J. P.	8011040186*	50-286 P	BISHOP, C. J.	8011280031	50-443 Q
AYRES, S. T.	8011230577	50-272 Q	BAYNE, J. P.	8011090433	50-286 Q	BISSETT, P. H.	8011100348*	70-820
BACHMANN, R. Q.	8011070176	50-263 Q	BAYNE, J. P.	8011060509	50-333 P	BIXEL, D. A.	7906260194	50-135 P
BACHMANN, R. Q.	8011190016	70-1308	BAYNE, J. P.	8011070490	50-333 P	BJERKE, M. A.	8011260266	NUREQ
BACHOFER, M. L.	8011200223	50-289 H	BAYNE, J. P.	8011170572	50-286 F	BJORKLUND, J.	8011250337*	50-351 A
BAER, R. L.	8011120546	TOPREP	BAYNE, J. P.	8011180433	50-286 P	BLACK, H.	7910010092*	FOIA
BAER, T. B.	8011100218	27-39	BAYNE, J. P.	8011180442*	50-286 P	BLACK, R. L.	8011050412	50-466 Q
BAER, T. B.	8011100225*	27-39	BAYNE, J. P.	8011260311	50-333 Q	BLACK, R. L.	8011060180	50-466 Q
BAILEY, R. J.	8011180450*	50-272 Q	BAYNE, J. P.	8011180678	50-286 F	BLACK, R. L.	8011140511	50-466 Q
BAIR, O. Q.	8011120429*	50-344 R	BAYNE, J. P.	8011250280	50-286 P	BLACK, R. L.	8011190166	50-466 Q
BAIRD, J. B.	8011210718*	50-267 Q	BAYNE, J. P.	8011250342	50-286 P	BLACK, R. L.	8011240502	50-466 Q
BAISDEN, L.	8011170129	CONTRACT	BAYNE, J. P.	8011250327	50-286 P	BLAHNIK, D. E.	8011140603	NUREQ
BAKER, R. R.	8011180853*	50-235 Q	BAYNE, J. P.	8011280015	50-333 F	BLAHNIK, D. E.	8011170954	NUREQ
BAKER, C. E.	8011040250	40-8681	BEACH, A. B.	8011200102*	50-458 Q	BLAKE, J.	8011040357*	50-261 Q
BAKER, D. A.	8011100463	NUREQ	BECHHOEFER, C.	8011100253	50-387 Q	BLAKE, J.	8011170958*	50-413 Q
BALDWIN, D. R.	8011180171*	FOIA	BECHHOEFER, C.	8011140521	50-409 Q	BLOCK, B.	8011070209*	50-237 T
BALDWIN, W. A.	8011040227	50-275 Q	BECHHOEFER, C.	8011170874	50-387 Q	BLUUGH, A. R.	8011190254*	50-277 Q
BALDWIN, W. A.	8011040227	50-275 Q	BECHHOEFER, C.	8011170886	50-409 Q	BLUUGH, A. R.	8011260446*	50-277 Q
BALL, L. H.	8011180163*	50-247 H	BECHHOEFER, C.	8011280013	50-387 Q	BLUNBERG, N.	8011110412*	50-244 Q
BALLANCE, N. B.	8011140688*	40-8412	BECK, N. I.	8011240192*	TOPREP	BLYE, R. W.	8011050016*	70-2909
BALLETINE, J. M.	8011180368	50-327 R	BECKER, S. K.	8011200341*	50-443 Q	BOYDKE, P. J.	8011120619*	50-235 R
BALLINGER, P. L.	8011140020*	50-298 R	BECKSTEDT, W. F.	8011170807	PT21	BOODEN, Q.	8011070617	40-1162
BALTZ, R. H.	8011260283*	50-294 Q	BEDROSIAN, R.	8011190676	NUREQ	BOODEN, Q.	8011050024	40-1162
BAMFORD, W. H.	8011170601*	50-344 Q	BEERS, R.	8011210197	40-8743	BOODEN, L. A.	8011210115	REGD
BARBER, R. H.	8011030058	PR	BEERS, F. C.	8011180584*	50-271 R	BOHN, R. J.	8011030400	50-367 R
BARBELA, H.	8011190696	NUREQ	BEERS, F. C.	8011140390*	50-29 R	BOHN, R. J.	8011040493	50-367 R
BARKER, J. L.	8011190326*	50-10 Q	BELANGER, R.	8011190708	NUREQ	BOHN, R. J.	8011120544	50-367 R
BARKER, D. G.	8011060562	50-498 A	BELKE, W. L.	8011070204*	50-237 T	BOHN, R. J.	8011180140	50-367 R
BARNES, I.	8011170124*	QA999	BELLAMY, R. R.	8011200146	50-320 B	BOHN, R. J.	8011250142	50-367 R
BARNES, I.	8011170858*	QA999	BELLO, R.	8009290477*	SECY	BOLLING, L. A.	8011190058	1&E
BARNES, I.	8011170879*	QA999	BELMORE, C. I.	8011040468*	50-219 R	BONNENBERG, H.	8011210242*	COMMISGION
BARNES, I.	8011060332*	QA999	BENARDY, V.	8011240077	MISC	BONBALL, J. N.	8011190396*	50-443 A
BARNES, I.	8011060289*	QA999	BENDER, M.	8011190344	ACRS	BONBALL, J. N.	8011190383*	50-443 A
BARNES, I.	8011170107*	QA999	BENEDICT, R.	8011130066*	50-286 Q	BONTRAGER, A. J.	8011180524*	50-320 H
BARNETT, P.	8011240180	50-195 Q	BENEDICT, D. E.	8011140121	50-30 W	BOOK, H. E.	8011030047*	70-23
BARNTHOUSE, L. M.	8011180729	50-247 P	BENNETT, W. S.	8011030017*	70-8	BOOK, H. E.	8011030045*	70-23
BARRETT, P. A.	8011200160*	50-341 Q	BENNER, R.	8011180022	PR	BOOK, H. E.	8011060809*	50-373 Q
BARRY, L. W.	8011180319*	State Proc	BENTON, R. P.	8011210104*	CONTRACT	BOOK, H. E.	8011070391*	50-94 Q
BASDEKAB, D. L.	8011110240*	50-243 Q	BERG, R. E.	8011120367	40-8585	BOOK, H. E.	8011060800	50-375 Q
BASKIN, K. P.	8011190295	50-206 B	BERGQREN, J. S.	8011200397	50-280 P	BOOK, H. E.	8011070215	50-187 Q
BASKIN, K. P.	8011100378	50-361 A	BERGMAN, R. K.	8011110144	PR	BOOK, H. E.	8011070223*	50-187 Q
BASKIN, K. P.	8011070390	50-206 P	BERMAN, M.	8011030493	NUREQ	BOOK, H. E.	8011070387	50-94 Q
BASKIN, K. P.	8011040212	50-361 A	BERMAN, M.	8011170688	NUREQ	BOOK, S. L.	8011040403*	40-1162
BASKIN, K. P.	8011040320	50-206 P	BERNATH, L.	8011210463	50-289 H	BOOK, S. L.	8011050407	40-1162
BASKIN, K. P.	801120467	50-206 P	BERNARD, T. J.	8011190498	50-3 H	BOOTH, J. E.	8011180064	50-289 H
BASKIN, K. P.	8011250460	50-361 A	BERNSTEIN, D. L.	8011100283	50-483 Q	BORDENICK, B. M.	8011180041	50-498 Q
BASKIN, K. P.	8011260297	50-206 P	BERNSTEIN, D. L.	8011100283	50-483 Q	BORDENICK, B. M.	8011190024	50-322 Q
BASKIN, K. P.	8011250349	50-361 A	BERNSTEIN, D. L.	8011180139	50-483 Q	BORDENICK, B. M.	8011190167	50-514 Q
BASKIN, K. P.	8011200199	50-361 A	BERNSTEIN, D. L.	8011180139	50-483 Q	BORDENICK, B. M.	8011190185	50-498 Q

PERSONAL AUTHOR INDEX

311

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BORDENICK, B. H.	8011230009	50-277 Q	BRINDLEY, J. H.	8011140015	50-94 J	BUCHHOLZ, R. H.	8011260163	TOPREP
BORDENICK, B. H.	8011230014	50-322 K	BRITE, D. H.	8011030664	NURE0	BUCK, J. H.	8011240176	50-409 Q
BORDENICK, B. H.	8011230004	50-322 Q	BROCK, B. L.	8011060371*	70-734	BUCKLEY, B. C.	8011070318	50-461 K
BORDENICK, B. H.	8011230006	50-322 H	BROCKETT, T. W.	8011060277	50-333 S	BUCKLEY, D. H.	8011190708	NURE0
BORER, R. J.	8010270112	70-1092	BROCKETT, T. W.	8011060283	50-293 S	BURGIN, R. Q.	8011120564*	50-409 F
BORER, R. J.	8011200342	70-1092	BROEHL, D. J.	8011170597	50-344 Q	BUHMEYER, K. J.	8011120176	PR
BORER, R. J.	8011060266	70-820	BROEHL, D. J.	8011260208	50-344 P	BULHART, B. A.	8011040075*	50-320 H
BORDEN, D.	8011210052	NURE0	BROMBERG, B.	8011120677	CONTRACT	BURANEK, D.	8011180498	WASTE HOT
BORGMANN, E. A.	8011030255*	50-358 Q	BROMBERG, B.	8011210027	CONTRACT	BURGER, A.	7812190004*	50-70 P
BORGMANN, E. A.	8011100043*	50-358 Q	BROWNSON, F. L.	8011170781*	CONTRACT	BURGESS, B. L.	8011070040*	50-282 Q
BORGMANN, E. A.	8011030138*	50-358 Q	BROOKS, J.	8011100623	50-466 Q	BURGESS, B. L.	8011050133*	50-282 Q
BORGMANN, E. A.	8011110014*	50-358 Q	BROOKS, W. L.	8011070225*	50-237 T	BURGER, F. J.	8011180584*	50-271 R
BORGMANN, E. A.	8011190742*	50-358 S	BROSB, I. J.	8011290041	PR	BURNETT, P.	8011170066*	50-302 Q
BORGMANN, E. A.	8011030616	50-358 S	BROUGHTON, T. O.	8011060404*	50-289 T	BURNETT, R. F.	8011100514	70-143
BORGMANN, E. A.	8011060175	50-358 Q	BROUGHTON, T. O.	8011060404*	50-289 T	BURNS, S. Q.	8011100627	50-255 Q
BORGMANN, E. A.	8011030591	50-358 A	BROUGHTON, T. O.	8011040547*	50-289 T	BURNS, S. Q.	8011100629*	50-255 Q
BORGMANN, E. A.	8011140055	50-358 S	BROWNS, R. J.	8011030664	NURE0	BURNS, S. Q.	8011120080	50-409 Q
BORGMANN, E. A.	8011130182	50-358 K	BROWNS, C. H.	8011030017*	70-8	BURNS, S. Q.	8011190144	50-409 Q
BORGMANN, E. A.	8011240086	50-358 K	BROWN, J. Y.	8011040222	PROJ	BURSTEIN, S.	8011280196*	50-266 Q
BORGMANN, E. A.	8011210483	50-358 I	BROWN, R. A.	8011030689	40-8711	BURSTEIN, S.	8011170490	50-266 R
BORGONOV, O.	8011140191	NURE0	BROWN, J. A.	8011060334*	50-302 P	BURSTEIN, S.	8011230206	50-266 R
BOSSENMAIER, W.	8011210519	50-312 P	BROWNLEE, V. L.	8011040537*	50-302 Q	BURWELL, S. B.	8011200419	50-445 A
BOSSENMAIER, W.	8011240169	50-312 P	BROWNLEE, V. L.	8011130368*	50-250 Q	BUTENKO, T. A.	8011110809	XPORTRIC
BOSSENMAIER, W.	8011240261	50-312 S	BROWNLEE, V. L.	8011260387*	50-321 Q	BUTENKO, T. A.	8011210116	XPORTRIC
BOSSENMAIER, W.	8011240314	50-312 S	BROWN, G. D.	8011210718*	50-267 Q	BUTLER, S. D.	8011050513*	50-327 Q
BOSSENMAIER, W.	8011240356	50-312 S	BROWN, A.	8011250557*	50-361 A	BYER, B.	8011210317	PR
BOSSENMAIER, W.	8011240368	50-312 S	BROWN, Q. D.	8011060272	1&E	BYRON, P. H.	8011100637*	50-341 Q
BOSSENMAIER, W.	8011250448	50-312 P	BROWN, H. H.	8011040455	50-275 Q	CACUCI, D. O.	8011260265	NURE0
BOTT, J. V.	8011260420	PR	BROWN, H. H.	8011100241	50-275 Q	CADWELL, J. J.	8011120057	RES
BOUCHEY, O. D.	8011170556*	PROJ	BROWN, H. H.	8011040455	50-275 Q	CADWELL, J. J.	8011120683	RES
BOUCHEY, O. D.	8011190364	50-397 A	BROWN, H. H.	8011100241	50-275 Q	CALHOUN, J. R.	8011030354	50-327 S
BOUKNIGHT, J. A.	8011060467	50-498 M	BROWN, R. N.	8011140434*	50-438 A	CALHOUN, J. R.	8011040373	50-327 S
BOUKNIGHT, J. A.	8011060469*	50-498 M	BROWN, R. N.	8011140438*	50-438 A	CALHOUN, J. R.	8011040424	50-259 S
BOUKNIGHT, J. A.	8011060469*	50-498 M	BROWN, S. C.	8011070482	50-404 A	CALHOUN, J. R.	8011040471	50-260 S
BOUKNIGHT, J. A.	8011180047	50-389 M	BROWN, H. H.	8011070234	50-275 Q	CALHOUN, J. R.	8011040389	50-327 S
BOUKNIGHT, J. A.	8011250036	50-389 M	BROWN, L. H.	8011100427	50-275 Q	CALHOUN, J. R.	8011040443	50-327 S
BOURNIA, A.	8011100025	50-373 A	BROWN, H. H.	8011070234	50-275 Q	CALIA, C.	8011190070	NURE0
BOURNIA, A.	8011210612	50-373 A	BROWN, O. F.	8011180028	PR	CAMERON, D. M.	8011180061	FOIA
BOURNIA, A.	8011260041*	50-483 A	BROWNE, R. C.	8011260004	PR	CAMM, F. A.	8011130082*	CRG
BOURNIA, A.	8011260323*	50-389 A	BROWNE, R. C.	8011260165	PR	CAMPBELL, J. E.	8011030488	NURE0
BOHRS, E. S.	8011050182	50-322 Q	BROWNE, R. C.	8011260004	PR	CANTRELL, F. S.	8011040060*	50-390 Q
BOHRS, E. S.	8011100246	50-275 Q	BROWNE, R. C.	8011260165	PR	CANTRELL, F. S.	8011260421*	50-366 Q
BOHRS, E. S.	8011280046	50-322 Q	BRUNNER, E. J.	8011110399*	50-244 Q	CANTRELL, A.	8011120401*	50-244 Q
BOHRS, E. S.	8011280057	50-275 Q	BRUNNER, E. J.	8011200049*	50-334 Q	CAPTON, D.	8011200056*	50-334 Q
BOHRS, E. S.	8011280059	50-488 Q	BRUNNER, E. J.	8011130043	50-289 Q	CAPTON, D. L.	8011180460*	50-29 Q
BOHRS, E. S.	8011280061	50-314 Q	BRUNNER, E. J.	8011210379	50-387 Q	CARLISLE, C. S.	8011170548	PROJ
BOHYER, J. E.	8011070556*	FOIA	BRUNNER, E. J.	8011130143	50-220 Q	CARLSON, R. T.	8011200126*	50-245 Q
BOYD, R. B.	8011140485*	50-367 Q	BRUNNER, E. J.	8011190240*	50-277 Q	CARLSON, R. T.	8011170590*	50-322 Q
BOYD, D. C.	8011180114*	50-409 Q	BRUNNER, E. J.	8011100324	50-271 Q	CARLSON, R. T.	8011190319*	50-352 Q
BOYD, D. C.	8011260375*	50-409 Q	BRUNNER, E. J.	8011130159	50-247 Q	CARLSON, R. T.	8011100321	50-352 Q
BOYD, R. M.	8011210011	PR	BRUNNER, E. J.	8011180808*	50-272 Q	CARLSON, R. T.	8011180466	50-354 Q
BOYER, V. S.	8009290380*	50-352 B	BRUNNER, E. J.	8011110390	50-244 Q	CARLSON, R. T.	8011100269	50-289 Q
BOYLAN, J. C. P.	8011100330	50-387 Q	BRUNNER, E. J.	8011180455	50-29 Q	CARLSON, R. T.	8011100282	50-289 Q
BRADFORD, P. A.	8011200372*	SECY	BRUNNER, E. J.	8011130066*	50-286 Q	CARLSON, R. T.	8011100291	50-289 Q
BRADFORD, W. H.	8011050278*	50-348 Q	BRUNNER, E. J.	8011130061	50-286 Q	CARLSON, R. T.	8011170622	50-352 Q
BRADFORD, P. A.	8011100041*	FOIA	BRUNNER, E. J.	8011260439*	50-277 Q	CARLSON, R. T.	8011130076	50-354 Q
BRADLEY, E. J.	8009290378	50-352 B	BRUNNER, E. J.	8011100340	50-271 Q	CARLSON, R. T.	8011030043	50-287 B
BRAMLETT, L. B.	8011140036*	50-368 B	BRUNNER, E. J.	8011260688	50-309 Q	CARLSON, R. T.	8011050063	50-423 B
BRAMLETT, L. B.	8011170489*	50-313 B	BRUNNER, E. J.	8011210708	50-286 Q	CARLSON, R. T.	8011200100	50-336 Q
BRAMLETT, L. B.	8011180676*	50-313 B	BRUNNER, E. J.	8011250663	50-317 Q	CARLSON, J. D.	8011100069*	50-288 Q
BRAMLETT, L. B.	8011250380*	50-313 B	BRUNNER, E. J.	8011190602*	50-245 Q	CARLSON, R. T.	8011100344	50-443 Q
BRANCH, M. H.	8011180114*	50-409 Q	BRUNNER, E. J.	8011200043	50-334 Q	CARLSON, R. T.	80111200375	50-213 Q
BRANCH, M. H.	8011260375*	50-409 Q	BRUNNER, E. J.	8011190195	50-277 Q	CARLSON, R. T.	8011080078	50-354 B
BRAND, W. E.	8011140501	50-395 M	BRUNNER, E. J.	8011210367	50-387 Q	CARLSON, R. T.	8011080525	50-354 Q
BRAND, W. E.	8011140507*	50-395 M	BRUNNER, E. J.	8011260431	50-277 Q	CARLSON, R. T.	8011100363	50-387 Q
BRAND, W. E.	8011140501	50-395 M	BRUNNER, E. J.	8011110364	50-247 B	CARLSON, R. T.	8011050040	50-352 B
BRAND, W. E.	8011140507*	50-395 M	BRUNNER, E. J.	8011110376	50-293 B	CARLSON, R. T.	8011260425	50-354 Q
BRAND, W. E.	8011180272	FOIA	BRUNNER, E. J.	8011110371	50-247 B	CARLSON, R. T.	8011280171	50-220 Q
BRAY, A. P.	8011030191*	TOPREP	BRUNNER, E. J.	8011240459	1&E	CARLSON, R. T.	8011200164	50-387 B
BREED, A.	8011250508*	TOPREP	BRUNNER, E. J.	8011240468	50-317 B	CARLSON, R. T.	8011050073	50-387 B
BRENNAN, J. E.	8011100062*	50-309 F	BRUNNER, E. J.	8011250542	50-334 B	CARLSON, R. T.	8011200088	50-387 B
BRENNAN, T. P.	8011100300	50-387 Q	BRYAN, S. E.	8011060487	50-295 Q	CARLSON, R. T.	8011170566	50-322 Q
BRIGHT, R. H.	8011200131*	50-219 Q	BRYANT, J. C.	8011040073*	50-413 Q	CARLSON, R. T.	8011170847	50-387 B
BRIGHT, R. H.	8011120086	PR	BRYANT, J. C.	8011210166*	50-370 Q	CARLSON, R. T.	8011190286	50-352 Q
BRIGHT, R. H.	8011200375	50-302 V	BRYANT, J. C.	8011260427*	50-424 Q	CARLSON, R. T.	8011200158	50-387 B
BRIGHT, R. H.	8011040147	50-302 Q	BRYANT, J. C.	8011260352*	50-395 Q	CARLSON, R. T.	8011170755	50-387 B
BRIGHT, R. H.	8011040159	50-302 P	BRYANT, J. K.	8011060503	50-483 F	CARPENTER, P. E.	8011060572*	50-286 P
BRIGHT, R. H.	8011040167	50-302 P	BRYAN, R. H.	8011240440	NURE0	CARPENTER, O. R.	8011240267	50-289 H
BRIGHT, R. H.	8011040204	50-302 P	BRYAN, J. K.	8011190291	50-483 B	CARROTHERS, W. D.	8011110678	XPORTRIC
BRIGHT, R. H.	8011060322	50-302 P	BUCHHOLZ, R. H.	8011040226	TOPREP	CARROLL, D.	8011110388	50-289 Q
BRIGHT, R. H.	8011070634	50-302 Q	BUCHHOLZ, R. H.	8011250246	TOPREP	CARROLL, J. T.	8011140100	50-219 B
BRIGHT, R. H.	8011102333*	50-302 P	BUCHHOLZ, R. H.	8011080585	TOPREP	CARTER, P. D.	8011170275*	70-882
BRIGHT, R. H.	8011110230	50-302 P	BUCHHOLZ, R. H.	8011080585	TOPREP	CARTIER, B. J.	8011170364*	CONTRACT
BRIGHT, R. H.	8011280118	50-302 Q	BUCHHOLZ, R. H.	801120414	NURE0	CARTWRIGHT, W. R.	8011030516	50-338 B
BRIGHT, R. H.	8011180608	50-302 R	BUCHHOLZ, R. H.			CARTWRIGHT, W. R.	8011030524*	50-338 B

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CARTWRIGHT, W. R.	8011040572	50-339 S	CHARLES, E.	8011130006*	50-320 P	CLARK, R. A.	8011030052	50-285 P
CARTWRIGHT, W. R.	8011040580*	50-339 S	CHARLES, E.	8011120380	50-320 P	CLARK, R. A.	8011030077	50-368 P
CARTWRIGHT, W. R.	8011040593	50-339 S	CHARNOFF, O.	8011100283	50-483 Q	CLARK, R. A.	8011030097*	50-368 P
CARTWRIGHT, W. R.	8011040588*	50-339 S	CHARNOFF, O.	8011180139	50-483 Q	CLARK, R. A.	8011030107*	50-368 P
CARTWRIGHT, W. R.	8011070430	50-338 S	CHARNOFF, O.	8011180139	50-483 Q	CLARK, R. A.	8011060367	50-285 P
CARTWRIGHT, W. R.	8011070434*	50-338 S	CHAUDHARY, S. K.	8011200134*	50-245 Q	CLARK, R. A.	8011060375*	50-285 P
CARTWRIGHT, W. R.	8011070340	50-338 S	CHAUDHARY, S.	8011190329*	50-352 Q	CLARK, R. A.	8011060383*	50-285 P
CARTWRIGHT, W. R.	8011070342*	50-338 S	CHAUDHARY, S. K.	8011100276*	50-289 Q	CLARK, R. A.	8011060563	50-259 P
CARTWRIGHT, W. R.	8011070344	50-338 S	CHAUDHARY, S.	8011100292*	50-289 Q	CLARK, R. A.	8011030608	50-317 P
CARTWRIGHT, W. R.	8011070346*	50-338 S	CHELL, W. L.	8011100318	50-387 Q	CLARK, R. A.	8011030604	50-333 P
CARTWRIGHT, W. R.	8011070513	50-339 S	CHEEN, W. S.	8011170797	RES	CLARK, R. A.	8011060530	50-266 P
CARTWRIGHT, W. R.	8011070517*	50-339 S	CHEERY, M. H.	8011250327*	50-454 Q	CLARK, R. A.	8011060001	50-344 F
CARTWRIGHT, W. R.	8011100433	50-339 S	CHEERY, M. H.	8011250333*	50-454 Q	CLARK, R. A.	8011060071	50-266 F
CARTWRIGHT, W. R.	8011100434*	50-339 S	CHEERY, M. H.	8011250323	50-454 Q	CLARK, R. A.	8011060114	50-336 F
CARTWRIGHT, W. R.	8011100494	50-339 S	CHEERY, M. H.	8011250327*	50-454 Q	CLARK, R. A.	8011060528	50-313 P
CARTWRIGHT, W. R.	8011100498*	50-339 S	CHEERY, M. H.	8011250333*	50-454 Q	CLARK, R. A.	8011100415	50-309 P
CARTWRIGHT, W. R.	8011120433	50-339 S	CHESTER, R. O.	8011170789	RES	CLARK, R. A.	8011040515	50-282 P
CARTWRIGHT, W. R.	8011120440*	50-339 S	CHEVERTON, R. D.	8011130246	RES	CLARK, R. A.	8011060143	50-344 P
CARTWRIGHT, W. R.	8011120496	50-339 S	CHIANG, H. J.	8011070413	50-400 S	CLARK, R. A.	8011030108	50-317 P
CARTWRIGHT, W. R.	8011120503*	50-339 S	CHIANG, H. J.	8011240365	50-400 S	CLARK, R. A.	8011060065	50-317 F
CARTWRIGHT, W. R.	8011180554	50-339 S	CHIAN, H. J.	8011240388	50-400 S	CLARK, R. A.	8011070804	50-335 Q
CARTWRIGHT, W. R.	8011180564*	50-339 S	CHILDS, W. V.	8011050501*	50-333 S	CLARK, R. A.	8011070562	50-264 Q
CARTWRIGHT, W. R.	8011180687	50-339 S	CHILDS, W. V.	8011050504*	50-333 S	CLARK, R. A.	8011070595	50-335 Q
CARTWRIGHT, W. R.	8011180693*	50-339 S	CHILDS, W. V.	8011120549*	50-333 S	CLARK, R. A.	8011070597	50-317 Q
CARTWRIGHT, W. R.	8011180700	50-339 S	CHILDS, W. V.	8011120565*	50-333 S	CLARK, R. A.	8011110068	50-338 Q
CARTWRIGHT, W. R.	8011180710*	50-339 S	CHILDS, W. V.	8011250356*	50-333 S	CLARK, R. A.	8011110327	50-368 Q
CARTWRIGHT, W. R.	8011170450	50-338 S	CHILK, S. J.	8011170918*	70-143 Q	CLARK, R. A.	8011110418	50-314 Q
CARTWRIGHT, W. R.	8011170457	50-338 S	CHILK, S. J.	8011170928*	70-143 Q	CLARK, R. A.	8011110442	50-309 Q
CARTWRIGHT, W. R.	8011170458*	50-338 S	CHILK, S. J.	8011170935*	70-143 Q	CLARK, R. A.	8011140683	50-282 Q
CARTWRIGHT, W. R.	8011170461*	50-338 S	CHILK, S. J.	8011070047*	10CFR	CLARK, J. R.	8011120631	71-198
CARTWRIGHT, W. R.	8011170469	50-339 S	CHILK, S. J.	8011200165*	50-328 A	CLARK, R. A.	8011100299	50-344 F
CARTWRIGHT, W. R.	8011170478*	50-339 S	CHILK, S. J.	8011140681*	50-320 P	CLARK, R. A.	8011200023	50-344 P
CARTWRIGHT, W. R.	8011170407	50-338 S	CHILK, S. J.	8011030109	PR	CLARK, R. A.	8011170274	50-317 P
CARTWRIGHT, W. R.	8011170414*	50-338 S	CHILK, S. J.	8011030044	PR	CLARK, R. A.	8011100317	50-259 P
CARTWRIGHT, W. R.	8011240357	50-338 S	CHILK, S. J.	8011210687	10CFR	CLARK, R. A.	8011200075	50-317 P
CARTWRIGHT, W. R.	8011240391*	50-338 S	CHILK, S. J.	8011200457	10CFR	CLARK, R. A.	8011200091	50-344 P
CARTWRIGHT, W. R.	8011250361	50-338 S	CHILK, S. J.	8011200465	REGD	CLARK, R. A.	8011190224	50-282 P
CARTWRIGHT, W. R.	8011250364*	50-338 S	CHILK, S. J.	8011200488	PRH	CLARK, R. A.	8011200085	50-360 P
CARTWRIGHT, W. R.	8011240323	50-339 S	CHILK, S. J.	8011200445	10CFR	CLARK, R. A.	8011200069	50-336 P
CARTWRIGHT, W. R.	8011240328*	50-339 S	CHILK, S. J.	8011210121	PR	CLARK, R. A.	8011210050	50-335 P
CARTWRIGHT, W. R.	8011240340	50-339 S	CHILK, S. J.	8011190506	NUREG	CLARK, R. A.	8011260173	50-313 P
CARTWRIGHT, W. R.	8011240345	50-339 S	CHILK, S. J.	8011070071*	10CFR	CLARK, R. A.	8011260174*	50-313 P
CARTWRIGHT, W. R.	8011240346*	50-339 S	CHILK, S. J.	8011070077*	10CFR	CLARK, R. A.	8011260178*	50-313 P
CARTWRIGHT, W. R.	8011240352*	50-339 S	CHILK, S. J.	8011070078*	10CFR	CLARK, R. A.	8011260219	50-317 P
CARTWRIGHT, W. R.	8011240379	50-339 S	CHILK, S. J.	8011110031	10CFR	CLARK, R. A.	8011260222	50-282 F
CARTWRIGHT, W. R.	8011240383*	50-339 S	CHILK, S. J.	8011120035	XPORTLIC	CLAYTON, F. L.	8011060157*	50-364 Q
CARTWRIGHT, W. R.	8011240398	50-338 S	CHILK, S. J.	8011050183	50-295 Q	CLAYTON, F. L.	8011050371*	50-364 Q
CARTWRIGHT, W. R.	8011240402*	50-338 S	CHILK, S. J.	8011060244	50-484 Q	CLAYTON, F. L.	8010290014*	COMMISIOH
CARTWRIGHT, W. R.	8011260179	50-339 S	CHILK, S. J.	8011040415	50-395 M	CLAYTON, F. L.	8011200442*	50-348 Q
CARTWRIGHT, W. R.	8011260180*	50-339 S	CHILK, S. J.	8011070027	50-263 Q	CLAYTON, F. L.	8011110025	50-364 Q
CARUSO, R.	8011200151*	50-213 Q	CHILK, S. J.	8011070192	50-219 Q	CLAYTON, F. L.	8011110033	50-364 Q
CARUSO, B.	8011140184	NUREG	CHILK, S. J.	8011070018	50-556 Q	CLAYTON, G. L.	8011210212	WASTE MGT
CARUSO, R.	8011170828	50-29 P	CHILK, S. J.	8011100228	50-599 Q	CLAYTON, F. L.	8011070629	50-348 Q
CASE, E. Q.	7812190020*	50-70 P	CHILK, S. J.	8011140053	50-142 Q	CLAYTON, F. L.	8011040469	50-364 A
CASE, E. Q.	7812190026*	50-70 P	CHILK, S. J.	8011200084*	10CFR	CLAYTON, F. L.	8011090471	50-348 F
CASE, E. Q.	7812190013*	50-70 P	CHILK, S. J.	8011140334	50-395 M	CLAYTON, F. L.	8011040308	50-364 A
CASE, E. Q.	8011030597*	50-443 Q	CHILK, S. J.	8011170892	50-295 Q	CLAYTON, F. L.	8011100485	50-348 Q
CASSEL, R.	8011060474	50-247 H	CHILK, S. J.	8011240161	RM	CLAYTON, F. L.	8011140448	50-348 P
CASTRO, G.	8011260003*	CONTRACT	CHILK, S. J.	8011240183	50-142 Q	CLAYTON, F. L.	8011120611	50-364 P
CATCHPOLE, Q. J.	8011070259	40-8745	CHILK, S. J.	8011280008	50-387 Q	CLAYTON, F. L.	8011240114	50-348 Q
CATCHPOLE, Q. J.	8010220504	40-8745	CHILK, S. J.	8011280043	50-142 Q	CLAYTON, F. L.	8011070373	50-348 S
CATCHPOLE, Q. J.	8011110140	40-8745	CHILSON, V. T.	8011180604*	50-250 R	CLAYTON, F. L.	8011070470	50-348 P
CATCHPOLE, Q. J.	8011110149	40-8745	CHO, J.	8011100384	50-275 U	CLAYTON, F. L.	8011110447	50-364 A
CATTON, I.	8011240100	NUREG	CHO, J.	8011200303	50-329 Q	CLAYTON, F. L.	8011120300	50-348 F
CAVANAUGH, W.	8011070411	50-313 P	CHOULES, N. C.	8011120689*	50-266 Q	CLAYTON, F. L.	8011120303	50-364 P
CAVANAUGH, W.	8011100377	50-313 P	CHOULES, N. C.	8011210190*	50-263 Q	CLAYTON, F. L.	8011120389	50-364 J
CAVANAUGH, W.	8011130197	50-313 P	CHOULES, N. C.	8011210174*	50-305 Q	CLAYTON, F. L.	8011210450	50-364 P
CAVANAUGH, W.	8011140187	50-313 P	CHRISTOPHER, K.	8011260059*	50-320 Q	CLAYTON, F. L.	8011140091	50-348 K
CAVANAUGH, W.	8011140420	50-313 P	CHRISTIANSON, W.	8011200007*	50-331 Q	CLAYTON, F. L.	8011140096*	50-348 K
CAVANAUGH, W.	8011280098	50-313 Q	CHRISTOPHER, R.	8011210402*	50-289 Q	CLAYTON, F. L.	8011240364*	50-348 F
CELLIER, F.	8011050010*	70-2909	CHRISTOPHER, N.	8011240098*	50-254 Q	CLAYTON, F. L.	8011180496	50-348 S
CERNE, A. C.	8011100355*	50-443 Q	CHRISTOPH, A.	8011040504	50-361 Q	CLAYTON, F. L.	8011210394	50-364 P
CHAFFEE, A.	8011060144*	50-361 Q	CHRISTENBURY, E.	8011070298	MISC	CLAYTON, F. L.	8011260164	50-364 P
CHAMANIA, F. D.	8011260007	50-445 M	CHRISTIANSON, J. N.	8011140522	50-338 Q	CLAYTON, F. L.	8011280090	50-348 Q
CHANDLER, L. J.	8011260020	50-320 Q	CHRISTENBURY, E.	8011200241	50-269 Q	CLAYTON, F. L.	8011210398	50-348 R
CHAPLIN, S. D.	8011040457*	50-320 S	CIARAMITARO, W.	8011070142*	REVIEW GRP	CLAYTON, F. L.	8011210377	50-348 R
CHAPLIN, S. D.	8011040445*	50-320 S	CIESZKIEWICZ, S.	8011180453*	50-10 R	CLAYTON, F. L.	8011210387	50-348 R
CHAPLIN, S. D.	8011240296*	50-320 S	CIESZKIEWICZ, S.	8011210551*	50-249 S	CLAYTON, F. L.	8011210504	50-348 S
CHAPLIN, S. D.	8011250547*	50-320 S	CLARDY, L. S.	8011200007*	50-331 Q	CLAYTON, F. L.	8011260156	50-364 P
CHAPMAN, D. G.	8011180145*	FOIA	CLARK, P. R.	8011040461*	50-320 P	CLAYTON, F. L.	8011210364	50-364 P
CHAPMAN, L. D.	8011030252	NUREG	CLARK, A. T.	8011030454	50-201 H	CLAYTON, F. L.	8011240305	50-348 S
CHAPMAN, L. D.	8011140601	NUREG	CLARK, R. A.	8011030595*	50-266 F	CLAYTON, F. L.	8011290328	50-348 S
CHAPMAN, L. D.	8011050573	RES	CLARK, R. A.	8011030586	50-285 P	CLAYTON, F. L.	8011260157	50-364 P
CHAPMAN, L. D.	8011200345	RES	CLARK, R. A.	8011030586	50-285 P	CLEBSCH, A.	8011170189	27-10
CHAPMAN, L. D.	8011260317	RES	CLARK, R. A.	8011190059	50-266 P	CLEOD, L. B.	8011140320	NUREG

PERSONAL AUTHOR INDEX

313

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CLEMENS, H. W.	8011120044*	50-320 Q	CONNER, T. B.	8011250378	50-358 Q	COUNSIL, H. Q.	8011200239	50-245 Q
CLEMENS, P. E.	8004070401*	70-364	CONNORS, E. L.	8011190602*	50-245 Q	COUNSIL, H. Q.	8011280020	50-245 P
CLEMENS, P.	8011050521*	70-135	CONSIDINE, E. E.	8011100304	50-387 Q	COUNSIL, H. Q.	8011200167	50-336 Q
CLEMENS, P.	8011070905*	70-1100	CONTE, R.	8011130136*	50-289 Q	COUNSIL, H. Q.	8011040158	50-213 V
CLEMENS, P.	8011100460*	70-1143	CONTE, R. J.	8011170788	50-320 B	COUNSIL, H. Q.	8011170465	50-213 F
CLEMENS, P.	8011070532*	70-398	CONTE, R. J.	8011140970	50-320 B	COUNSIL, H. Q.	8011040320	50-213 P
CLEMENS, P.	8011130060*	50-311 Q	CONWAY, W. F.	8011060477	50-271 U	COUNSIL, H. Q.	8011140007	50-213 P
CLEVELAND, C. J.	8011200108	50-334 P	CONWAY, W. F.	8011110274	50-271 P	COUNSIL, H. Q.	8011040423	50-336 Q
CLIFFORD, M. C.	8011120015*	70-2304	CONWAY, W. F.	8011180978	50-271 R	COUNSIL, H. Q.	8011040439	50-248 P
COCHRAN, T. B.	8011180024*	50-367 Q	COOK, N. Q.	8011130291	PR	COUNSIL, H. Q.	8011070403	50-336 P
COGBURN, T.	8011140384*	50-368 B	COOK, R. J.	8011030111*	50-329 Q	COUNSIL, H. Q.	8011100468	50-336 P
COGBURN, T.	8011250477*	50-313 B	COOK, R. J.	8011060292*	50-329 Q	COUNSIL, H. Q.	8011140007	50-213 P
COGIN, C. L.	8011190400*	50-321 B	COOK, J. W.	8011040163	50-329 Q	COUNSIL, H. Q.	8011200422	50-213 P
COGIN, C. L.	8011190422*	50-321 B	COOK, L. M.	8011120318	REQD	COUNSIL, H. Q.	8011110450	50-213 P
COHEN, I.	8011250121*	70-882	COOK, J. W.	8011060621	50-329 A	COUNSIL, H. Q.	8011200079	50-213 Q
COHEN, I.	8011070537*	70-135	COOK, J. W.	8011190011	50-329 Q	COUNSIL, H. Q.	8011200142	50-245 Q
COHEN, S.	8011140986*	CONTRACT	COOK, J. W.	8011190446*	50-329 Q	COUNSIL, H. Q.	8011180348	50-213 P
COHN, D. B.	8011060446	50-367 Q	COOK, S. A.	8011120099	PR	COUNSIL, H. Q.	8011190108	50-245 P
COHN, D. B.	8011170312	50-367 Q	COOK, J. W.	8011040399	50-329 B	COUNSIL, H. Q.	8011210507	50-245 B
COHN, D. B.	8011280014	50-367 Q	COOK, J. W.	8011040405	50-329 B	COUNSIL, H. Q.	8011200361	50-245 P
COHN, D. B.	8011250310	50-267 Q	COOK, J. W.	8011040511	50-329 B	COUNSIL, H. Q.	8011260233	50-336 V
COLEMAN, H. E.	8011210073*	MISC	COOK, J. W.	8011100620	50-329 B	COUNSIL, H. Q.	8011140347	50-213 P
COLEMAN, E. Q.	8011050553*	50-311 H	COOK, J. W.	8011260019	50-329 Q	COUNSIL, H. Q.	8011240138	50-245 P
COLEMAN, R.	8011100031	CONTRACT	COOK, J. M.	8011110214*	50-295 R	COWILL, C. J.	8011190294*	50-277 Q
COLEMAN, R.	8011170105	CONTRACT	COOK, J. M.	8011140038	50-329 B	COWILL, C. J.	8011260446*	50-277 Q
COLEMAN, R.	8011210072	CONTRACT	COOK, J. M.	8011180424	50-329 A	COWILL, C.	8011240459	50-277 B
COLEMAN, A. C.	8011190178	50-272 Q	COOK, J. M.	8011180151	50-329 A	COX, E. C.	8011120124	PR
COLEMAN, R.	8011260131	CONTRACT	COOK, J. M.	8011260083	50-329 A	COX, E. L.	8011210099	REQD
COLEVILLE, J.	8011200075*	50-344 P	COOLEY, H. J.	8011030047*	70-25	CRABTREE, R. E.	8011210393	PR
COLEY, J. L.	8011200430*	50-438 Q	COONEY, H. J.	8011040486	50-277 B	CRANE, P. A.	8011100067*	50-275 Q
COLEY, J. L.	8011210186*	50-390 Q	COONEY, H. J.	8011170493	50-277 B	CRANE, P. A.	8011030461	REQD
COLLINS, S. J.	8011100334*	50-271 Q	COONEY, H. J.	8011180632	50-277 B	CRANE, P. A.	8011100014	50-275 Q
COLLINS, S. J.	8011100350*	50-271 Q	COONEY, H. J.	8011180645	50-277 R	CRANE, P. A.	8011030406	50-275 Q
COLLINS, R. E.	8011260081*	50-267 Q	COONEY, H. J.	8011280396	50-277 B	CRANE, P. A.	8011210308	50-275 A
COLLINS, J. T.	8011060922	50-320 P	COONEY, H. J.	8011250404*	50-277 B	CRANE, P. A.	8011210318	50-275 A
COLLINS, J. T.	8011060980	50-320 R	COOPER, J. W.	8011070541*	40-8364	CRANE, P. A.	8011260125	50-275 A
COLLINS, P. F.	8011030197	50-263 V	COOPER, J. W.	8011070546*	FOIA	CRANE, P. A.	8011260002	50-275 Q
COLLINS, P. F.	8011070333	NUREG	COPELAND, J. Q.	8011030194	50-466 Q	CREED, J.	8011200497*	50-335 Q
COLLINS, J. T.	8011100227	50-320 P	COPELAND, J. Q.	8011030194	50-466 Q	CREWS, J. L.	8011060131*	50-361 Q
COLLINS, J. T.	8011120083	50-320 R	COPELAND, J. Q.	8011170244	50-466 Q	CREWS, J. L.	8011100065	50-288 Q
COLLINS, P. F.	8011170076	50-266 V	COPELAND, J. Q.	8011170244	50-466 Q	CREWS, J. L.	8011030276	50-344 Q
COLLIER, R. P.	8011170712	NUREG	COPELAND, R. L.	8011070416	50-537 B	CREWS, J. L.	8010702005	50-70 Q
COLLINS, J. T.	8011140644	50-320 R	COPELAND, J. Q.	8011140493	50-466 Q	CREWS, J. L.	8011090342	50-344 Q
COLLINS, J. T.	8011170788	50-320 B	COPELAND, J. Q.	8011180147	50-466 Q	CREWS, J. L.	8010303050	50-206 Q
COLLINS, J. T.	8011140570	50-320 B	COPELAND, J. Q.	8011140493	50-466 Q	CREWS, J. L.	8011040118	50-361 Q
COLLINS, J. T.	8011280111	50-320 P	COPELAND, J. Q.	8011180147	50-466 Q	CRICIONE, J. L.	8011210456*	50-336 B
COLLINS, S. J.	8011200155	50-271 B	COPELAND, R. L.	8011180630	50-537 B	CRICIONE, J. L.	8011210493*	50-336 B
COLLINS, J. T.	8011200331	50-320 R	COPELAND, J. Q.	8011190176	50-466 Q	CROCKER, H. W.	8004070401*	70-364
COLLINS, J. T.	8011280105	50-320 P	COPELAND, J. Q.	8011190176	50-466 Q	CROCKER, H. W.	8011260126*	40-672
COLLINS, P. F.	8011210057	50-289 V	COPELAND, R. L.	8011280047	50-537 B	CROCKER, L. P.	8011100531*	50-287 Q
COLLINS, J. T.	8011200146	50-320 B	CORBERT, J. B.	8011210229	27-47	CROCKET, L.	8011260304	50-219 P
COLONBO, R. M.	8011030622*	50-312 B	CORBERT, Z. C.	8011100094*	50-546 Q	CROCKET, H. W.	8011240454	70-820
COLONBO, R. M.	8011110226*	50-312 R	CORE, M.	8011120476*	50-285 B	CROSSBY, P. J.	8011040432*	50-219 B
COLONBO, R. M.	8011240372*	50-312 B	CORKERN, W. D.	8011060146*	50-289 R	CROSSBY, P. J.	8011250534*	50-219 B
COLON, T. E.	8011040537*	50-302 Q	CORREA, M. A.	8011030430	50-89 J	CROSSMAN, W. A.	8011200076*	50-498 Q
COLTON, J. D.	8011190709	NUREG	CORREA, J. H.	8011060399*	50-289 T	CROSSMAN, W. A.	8011100186*	50-498 Q
COLUMBO, R. M.	8011240362*	50-312 B	CORREA, J. H.	8011060399*	50-289 T	CROSSMAN, W. A.	8011100137*	50-498 Q
COMBS, T. R.	8011180030*	50-367 Q	CORREA, M. A.	8011140048	50-163 J	CROSSMAN, W. A.	8011100116*	50-445 Q
COMPTON, R. M.	8011060232*	QA999	CORREA, M. A.	8011180586	50-272 J	CROSSMAN, W. A.	8011040665*	50-382 Q
COMPTON, R. M.	8011200390*	50-280 Q	CORVELL, O. P.	8011040051*	70-1201	CROSSMAN, W. A.	8011040674*	50-445 Q
COMPTON, R. M.	8011040345*	50-280 Q	CORVELL, O. P.	8011200534*	70-27	CROSSMAN, W. A.	8011200102*	50-458 Q
COMPTON, R. M.	8011260362*	50-250 Q	COSTELLO, J. R.	8011040076*	QA999	CROSSMAN, W. A.	8011170727*	50-482 Q
CONLON, T. E.	8011200463*	50-348 Q	COSTELLO, J. R.	8011060252*	QA999	CROSSMAN, W. A.	8011190289*	50-382 Q
CONLON, T. E.	8011030300*	50-261 Q	COSTELLO, J. R.	8011040184*	50-295 Q	CROSSMAN, W. A.	8011250132*	50-482 Q
CONLON, T. E.	8011130368*	50-290 Q	COTTLE, W. T.	8011050513*	50-327 Q	CROSSMAN, W. A.	8011210631*	50-445 Q
CONLON, T. E.	8011260387*	50-321 Q	COTTLE, W. T.	8011030340*	50-327 B	CROSS, J. L.	8011280083	50-259 Q
CONLON, T. E.	8011260396*	50-416 Q	COTTLE, W. T.	8011040393*	50-327 B	CROUSE, R. P.	8011170411	50-346 Q
CONLON, T. E.	8011210368*	50-348 Q	COTTLE, W. T.	8011040453*	50-327 B	CROUSE, R. P.	8011040475	50-346 P
CONNAUGHTON, M.	8011190193*	50-320 H	COTTLE, W. T.	8011040606*	50-327 B	CROUSE, R. P.	8011040402	50-346 J
CONNAUGHTON, K.	8011110034*	50-10 Q	COTTLE, W. T.	8011120428*	50-327 B	CROUSE, R. P.	8011070463	50-346 V
CONNELLY, O.	8011120106	PR	COTTLE, W. T.	8011120439*	50-327 B	CROUSE, R. P.	8011170122	50-344 Q
CONNOR, E. L.	8011100306*	50-344 P	COTTLE, W. T.	8011120488*	50-327 B	CROUSE, R. P.	8011110223	50-344 F
CONNOR, E. L.	8011100315*	50-344 P	COTTLE, W. T.	8011180648*	50-327 B	CROUSE, R. P.	8011140455	50-344 P
CONNOR, E. L.	8011200028*	50-344 P	COTTLE, W. T.	8011180719*	50-327 B	CROUSE, R. P.	8011280089	50-346 Q
CONNOR, E. L.	8011200033*	50-344 P	COTTLE, W. T.	8011180633*	50-327 B	CROUSE, R. P.	8011170551	50-346 P
CONNOR, T. B.	8011050090	27-39	COTTLE, W. T.	8011180644*	50-327 B	CROUSE, R. P.	8011210615	50-500 A
CONNOR, T. B.	8011050090	27-39	COTTLE, W. T.	8011210497*	50-327 B	CROUSE, R. P.	8011250279	50-346 P
CONNELL, C.	8011180660*	50-286 R	COTTLE, W. T.	8011210574*	50-327 B	CROUSE, R. P.	8011250329	50-346 B
CONNOR, T. B.	8011100233	27-39	COTTLE, W. T.	8011250403*	50-327 B	CROW, W. T.	8011180189*	70-267
CONNOR, T. B.	8011190135	27-39	COTTLE, W. T.	8011250390*	50-327 B	CROW, W. T.	8011110010*	70-162
CONNOR, T. B.	8011190145*	27-39	COTTRELL, W. B.	8011030140*	FOIA	CROW, W. T.	8011130013*	70-1966
CONNOR, T. B.	8011190159*	27-39	COUNSIL, H. Q.	8011200122*	50-245 Q	CROW, W. T.	8011190613*	70-371
CONNOR, T. B.	8011190135	27-39	COUNSIL, H. Q.	8011090219*	50-423 B	CROW, W. T.	8011190758*	70-2913
CONNOR, T. B.	8011190145*	27-39	COUNSIL, H. Q.	8011200114*	50-245 Q	CROW, W. T.	8011180173*	70-267
CONNOR, T. B.	8011190159*	27-39	COUNSIL, H. Q.	8011210717*	50-213 Q	CROW, W. T.	8011180182*	70-267

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CROW, W. T.	8011180309	70-1207	CURTIS, J. R.	8011070991*	50-94	DAWSON, D. M.	8011060455*	70-1308
CROWLEY, B. R.	8011210143*	50-424	CURTIS, N. W.	8011210374*	50-387	DE GUZMAN, A. S.	8011070621	71-371
CRUMP, M. W.	8011110469*	TOPREP	CURTIS, J. R.	8011070223*	50-187	DE GUZMAN, A. S.	8011120651*	71-371
CRUTCHFIELD, D.	8007180289	50-255	CURTIS, N. W.	8011070407	50-388	DE JABON, J. A.	8011180081*	50-320
CRUTCHFIELD, D.	8007250693	50-255	CURTIS, L. H.	8011040399	50-329	DEALE, V. B.	8011050072	50-443
CRUTCHFIELD, D.	8011190002	50-255	CURTIS, N. W.	8011040126	50-387	DEALE, V. B.	8011060211	50-443
CRUTCHFIELD, D.	8011190073	50-219	CURTIS, N. W.	8011040225	50-387	DEALE, V. B.	8011240499	50-443
CRUTCHFIELD, D.	8011200008	50-29	CURTIS, N. W.	8011040233*	50-387	DEALE, V. B.	8011240513	50-443
CRUTCHFIELD, D.	8011200020	50-29	CURTIS, N. W.	8011260071	50-387	DEALE, V. B.	8011280002	50-443
CRUTCHFIELD, D.	8011200064	50-29	CURTIS, J. R.	801120087*	50-369	DECKER, G. R.	8011130138	REB
CRUTCHFIELD, D.	8011200069	50-29	CURTIS, N. W.	8011200242	50-387	DEEG, F. H.	8011050438	50-220
CRUTCHFIELD, D.	8011200264	50-29	CURTIS, N. W.	8011210591	50-387	DEL BELLO, A. B.	8011180102	50-247
CRUTCHFIELD, D.	8011210154	50-29	CURTIS, N. W.	8011230293	50-387	DELGEORGE, L. O.	8011130211*	NUREQ
CRUTCHFIELD, D.	8011190129	50-409	CUTCHIN, J. M.	8011040467	50-289	DELGEORGE, L. O.	8011030190*	50-374
CRUTCHFIELD, D.	8011080480	50-219	CUTCHIN, J. M.	8011050444	50-289	DELGEORGE, L. O.	8011030448	50-373
CRUTCHFIELD, D.	8011050485*	50-219	CUTSHELL, C. E.	8011260429*	50-546	DELGEORGE, L. O.	8011030450	50-373
CRUTCHFIELD, D.	8011050487*	50-219	CYBULSKI, P.	8011060077	REB	DELGEORGE, L. O.	8011030348	50-373
CRUTCHFIELD, D.	8011050492	50-409	CYR, K. D.	8011120080	50-409	DELGEORGE, L. O.	8011030563	50-373
CRUTCHFIELD, D.	8011050498*	50-409	CYR, K. D.	8011170144	50-409	DELGEORGE, L. O.	8011030572	50-373
CRUTCHFIELD, D.	8011050502*	50-409	CZYSCINSKI, K. S.	8011170613	NUREQ	DELGEORGE, L. O.	8011040380	50-373
CRUTCHFIELD, D.	8011060049	50-213	DAHLMAN, L. C.	8011030471*	50-282	DELGEORGE, L. O.	8011040524	50-373
CRUTCHFIELD, D.	8011180019	50-155	DALE, L. F.	8011170281	50-416	DELGEORGE, L. O.	8011170286	50-373
CRUTCHFIELD, D.	8011180034	50-245	DALE, L. F.	8011170281	50-416	DELGEORGE, L. O.	8011040440	50-373
CRUTCHFIELD, D.	8011180251	50-219	DALE, L. F.	8011170267	50-416	DELGEORGE, L. O.	8011050428	50-10
CRUTCHFIELD, D.	8011170112	50-409	DALE, L. F.	8011100424	50-416	DELGEORGE, L. O.	8011170209	50-373
CRUTCHFIELD, D.	8011170544	50-409	DALTROFF, B. L.	8011190203*	50-277	DELGEORGE, L. O.	8011240334	50-373
CRUTCHFIELD, D.	8011180008	50-244	DALTROFF, B. L.	8011029025*	50-277	DELGEORGE, L. O.	8011250284	50-373
CRUTCHFIELD, D.	8011180050	50-255	DALTROFF, B. L.	8011260433*	50-277	DELGEORGE, L. O.	8011250212	50-373
CRUTCHFIELD, D.	8011180205	50-206	DALTROFF, B. L.	8011040561	50-277	DELPOULOS, S. J.	8011260175	50-247
CRUTCHFIELD, D.	8011210015	50-29	DALTROFF, B. L.	8011060366	50-277	DENNEY, P. A.	8011140105	50-322
CRUTCHFIELD, D.	8011050199	50-219	DALTROFF, B. L.	8011190124	50-277	DENEBS, S. J.	8011140003	50-142
CRUTCHFIELD, D.	8011060087	50-244	DALTROFF, B. L.	8011260331	50-277	DENNING, R. S.	8011050583	REB
CRUTCHFIELD, D.	8011060091	50-213	DALTROFF, B. L.	8011180695	50-277	DENNING, R. S.	8011060077	REB
CRUTCHFIELD, D.	8011110097	50-155	DALTROFF, B. L.	8011230370	50-277	DENTON, H. R.	8011180333*	ORR
CRUTCHFIELD, D.	8011030692	50-245	DALZELL, W. O.	8011180477*	50-327	DENTON, H. R.	8011120079	SECV
CRUTCHFIELD, D.	8011030700*	50-245	DANA, R. H.	8011030653	50-201	DENTON, H. R.	8011110640	PR
CRUTCHFIELD, D.	8011030708*	50-245	DANA, R. H.	8011030672	50-201	DENTON, H. R.	8010220338	SECV
CRUTCHFIELD, D.	8011030045	50-10	DANCE, H. C.	8011050513*	50-327	DENTON, H. R.	8011190038	PR
CRUTCHFIELD, D.	8011120007	50-213	DANCE, H. C.	8011130256*	50-327	DENTON, H. R.	8011060385	SECV
CRUTCHFIELD, D.	8011170324	50-255	DANCE, H. C.	8011050574*	50-321	DENTON, H. R.	8011060098	50-289
CRUTCHFIELD, D.	8011130216	50-10	DANCE, H. C.	8011140316*	50-160	DENTON, H. R.	8011060200	50-289
CRUTCHFIELD, D.	8011110500	50-255	DANCE, H. C.	8011060270*	50-321	DENTON, H. R.	8011040346	50-220
CRUTCHFIELD, D.	8011110625	50-213	DANIELSON, D. H.	8011260348*	50-440	DENTON, H. R.	8011180344	50-273
CRUTCHFIELD, D.	8011110641	50-155	DANIELSON, D. H.	8011260364*	50-440	DENTON, H. R.	8011100496	50-155
CRUTCHFIELD, D.	8011110669	50-245	DANIELSON, D. H.	8011230144*	50-373	DENTON, H. R.	8011180303	State & Prov
CRUTCHFIELD, D.	8011240003	50-244	DANIELSON, D. H.	8011170742*	50-456	DENTON, H. R.	8011040317	50-416
CRUTCHFIELD, D.	8011240014	50-219	DANIELSON, D. H.	80111040184*	50-295	DENTON, H. R.	8011030552	50-443
CRUTCHFIELD, D.	8011240028	50-206	DANIELSON, D. H.	8011180797*	50-341	DENTON, H. R.	8011190348*	50-320
CRUTCHFIELD, D.	8011240037	50-237	DANIELSON, D. H.	8011200294*	50-329	DENTON, H. R.	8010290005	50-220
CRUTCHFIELD, D.	8011240051	50-29	DANIELSON, D. H.	8011100034*	50-546	DENTON, H. R.	8011050006*	50-364
CRUTCHFIELD, D.	8011240070	50-409	DANIELSON, D. H.	8011250072*	50-440	DENTON, H. R.	8011130094	DISCLOSURE
CRUTCHFIELD, D.	8011170039	50-409	DARLING, R. C.	8011200246	50-289	DENTON, H. R.	8011050028*	10CFR
CRUTCHFIELD, D.	8011200483	50-244	DARMITZEL, R. W.	8011050447	50-70	DENTON, H. R.	8011050034*	10CFR
CRUTCHFIELD, D.	8011200495	50-245	DAUGHERTY, M. L.	8011140051	50-255	DENTON, H. R.	8011100666	SECV
CRUTCHFIELD, D.	8011210001	50-255	DAVENB, E.	8011110122	PR	DENTON, H. R.	8011180017	50-367
CRUTCHFIELD, D.	8011210002	50-219	DAVENS, E.	8011210045	PR	DENTON, H. R.	8011200156	50-328
CRUTCHFIELD, D.	8011210003	50-29	DAVIDSON, J. A.	8011170601*	50-344	DENTON, H. R.	8011170340	50-367
CRUTCHFIELD, D.	8011210004	50-409	DAVIDSON, D. R.	8011040194*	50-440	DENTON, H. R.	8011180112	50-289
CRUTCHFIELD, D.	8011210005	50-206	DAVIDSON, D. R.	8011190472*	50-440	DENTON, H. R.	8011120422	50-272
CRUTCHFIELD, D.	8011210041	50-213	DAVIDSON, D. R.	8011210447*	50-440	DENTON, H. R.	8011170127	MISC
CRUTCHFIELD, D.	8011230721	50-155	DAVIDSON, D. R.	8011070406	50-440	DENTON, H. R.	8011180087	50-289
CRUTCHFIELD, D.	8011200073	50-29	DAVIDSON, D. R.	8011140043	50-440	DENTON, H. R.	8011210066	MISC
CRUTCHFIELD, D.	8011260236	50-244	DAVIDSON, D. R.	8011180491	50-440	DENTON, H. R.	8011240096	REPOB
CRUTCHFIELD, D.	8011230515	50-387	DAVIS, D. K.	7809290027	50-10	DENTON, H. R.	8011260027*	50-320
CULP, R. H.	8011030194	50-466	DAVIS, A. B.	8011060202	50-373	DEVINE, J. B.	8011140679*	RECV
CULP, R. H.	8011030194	50-466	DAVIS, J. H.	8011030519*	50-321	DEVINE, J. B.	8011030178	XPORTLIC
CULVER, C.	8011110066	PR	DAVIS, A. B.	8011060271	50-264	DEVINE, J. B.	8011030112	XPORTLIC
CULVER, M. W.	8011180614*	50-302	DAVIS, A. B.	8011060281	50-409	DEVINE, J. B.	8011030175	XPORTLIC
CUMMINGS, G. E.	8011170096	NUREQ	DAVIS, A. B.	8011030120	50-373	DEVINE, J. B.	8011070303	XPORTLIC
CUNNINGHAM, A. L.	8011130223*	50-400	DAVIS, J. B.	8011210275*	40-8702	DEVINE, J. B.	8011060279*	XPORTLIC
CUNNINGHAM, O. E.	8011110822	71-9980	DAVIS, A. B.	8011170537	50-440	DEVINE, J. B.	8011260160*	XPORTLIC
CUNNINGHAM, R. E.	8011030009	70-8	DAVIS, A. B.	8011040646	50-254	DEVINE, J. B.	8011030328	XPORTLIC
CUNNINGHAM, R. E.	8011070324	PR	DAVIS, A. B.	8011170942	50-426	DEVINE, J. B.	8011030342	XPORTLIC
CUNNINGHAM, R. O.	8011030478	50-3	DAVIS, A. B.	8011190490	50-150	DEVINE, J. B.	8011030431	XPORTLIC
CUNNINGHAM, O. E.	8011200205	71-9939	DAVIS, A. B.	8011200074	50-454	DEVINE, J. B.	8011030080	XPORTLIC
CUNNINGHAM, H. E.	8011190081	NUREQ	DAVIS, A. B.	8011210419	50-305	DEVINE, J. B.	8011030085	XPORTLIC
CUNNINGHAM, R. O.	8011180241	50-3	DAVIS, J. B.	8011210699*	40-8702	DEVINE, J. B.	8011030091	XPORTLIC
CURRANE, R. A.	8011060392*	QA999	DAVIS, A. B.	8011280221	50-254	DEVINE, J. B.	8011030104	XPORTLIC
CURRAN, J. M.	8011140027	50-206	DAVIS, J. Q.	8011050592*	10CFR	DEVINE, J. B.	8011110703	XPORTLIC
CURRAN, J. M.	8011250471*	50-361	DAVIS, A. B.	8011210613	40-2053	DEVINE, J. B.	8011180012	XPORTLIC
CURRAN, J. M.	8011230494*	50-361	DAVIS, L. D.	8011070025	50-275	DEVINE, J. B.	8011060550	XPORTLIC
CURRAN, J. H.	8011230503*	50-361	DAVIS, A. B.	8011210444	50-440	DEVINE, J. B.	8011060534	XPORTLIC
CURRAN, J. M.	8011230482*	50-361	DAVIS, J. Q.	8011180273	50-201	DEVINE, J. B.	8011060547	XPORTLIC
CURTIS, D. J.	8011210735*	50-275	DAVIS, A. B.	8011210767	50-456	DEVINE, J. B.	8011060686	XPORTLIC
CURTIS, J. R.	8011060809*	50-375	DAWSON, D. M.	8011100270	71-9010	DEVINE, J. B.	8011060532	XPORTLIC

PERSONAL AUTHOR INDEX

315

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DEVINE, J. B.	8011060536	XPORTLIC	DIPIAZZA, R. P.	8011030002	70-2909	EDGAR, Q. L.	8011140062	50-367 Q
DEVINE, J. B.	8011060540	XPORTLIC	DIPIAZZA, R. D.	8011030003	70-2909	EDGAR, Q. L.	8011140063	50-367 Q
DEVINE, J. B.	8011060792	XPORTLIC	DIRCKS, W. J.	8011030273	FOIA	EDWARDS, W. E.	8011040923	70-143
DEVINE, J. B.	8011110202	XPORTLIC	DIRCKS, W. J.	8011170943	FOIA	EDWARDS, W. E.	8011110201	PR
DEVINE, J. B.	8011110206	XPORTLIC	DIRCKS, W. J.	8011170948	FOIA	EDWARDS, J. J.	8011260177	50-289 H
DEVINE, J. B.	8011060788	XPORTLIC	DIRCKS, W. J.	8006300569	FOIA	EHRENSPERGER, W.	8011060458	50-424 A
DEVINE, J. B.	8011070088	XPORTLIC	DIRCKS, W. J.	8008130673	70-820	EICH, E.	8011180462	50-247 R
DEVINE, J. B.	8011070093	XPORTLIC	DIRCKS, W. J.	8011030302	50-335 P	EICHORN, W. H.	8011050409	50-367 Q
DEVINE, J. B.	8011070097	XPORTLIC	DIRCKS, W. J.	8011030147	MISC	EICHORN, W. H.	8011050409	50-367 Q
DEVINE, J. B.	8011170316	MISC	DIRCKS, W. J.	8011030172	50-271 P	EICHORN, W. H.	8011100199	50-367 Q
DEVINE, J. B.	8011100018	XPORTLIC	DIRCKS, W. J.	8011030183	TOPREP	EICHORN, W. H.	8011140083	50-367 Q
DEVINE, J. B.	8011100022	XPORTLIC	DIRCKS, W. J.	8011050037	50-206 H	EICHORN, W. H.	8011140021	50-367 Q
DEVINE, J. B.	8011130412	XPORTLIC	DIRCKS, W. J.	8011130074	ORO	EICHORN, W. H.	8011280030	50-367 Q
DEVINE, J. B.	8011140188	XPORTLIC	DIRCKS, W. J.	8011180826	COMMISSION	EICHORN, W. H.	8011280030	50-367 Q
DEVINE, J. B.	8011140192	XPORTLIC	DIRCKS, W. J.	8011100574	50-367 U	EIDSON, A. F.	8011190695	NUREQ
DEVINE, J. B.	8011140247	XPORTLIC	DIRCKS, W. J.	80111100351	50-344 H	EILPERIN, S.	8011190043	PR
DEVINE, J. B.	8011140256	XPORTLIC	DIRCKS, W. J.	8011110319	FOIA	EISENHUT, D. O.	8008110072	50-213 P
DEVINE, J. B.	8011140261	XPORTLIC	DISE, D. P.	8010290010	50-220 P	EISENHUT, D. O.	8011050354	50-3 P
DEVINE, J. B.	8011140663	XPORTLIC	DISE, D. P.	8011050166	PR	EISENHUT, D. O.	8011140617	50-244 F
DEVINE, J. B.	8011140667	XPORTLIC	DISE, D. P.	8011030481	50-220 P	EISENHUT, D. O.	8011060124	50-213 Q
DEVINE, J. B.	8011190675	XPORTLIC	DISTIBIO, R. R.	8011040242	PROJ	EISENHUT, D. O.	8011060130	50-213 Q
DEVINCENITIS, J.	8011120314	50-443 A	DIXON, Q. N.	8010220042	71-9010	EISENHUT, D. O.	8011060139	50-213 Q
DEVINE, J. B.	8011110821	XPORTLIC	DOAN, P. F.	8011210370	50-298 B	EISENHUT, D. O.	8011060628	50-409 Q
DEVINE, J. B.	8011120682	XPORTLIC	DODDS, R. T.	8011050402	50-344 Q	EISENHUT, D. O.	8011060631	50-409 Q
DEVINE, J. B.	8011130092	XPORTLIC	DODDS, R. T.	8011100076	50-312 Q	EISENHUT, D. O.	8011070283	50-237 Q
DEVINE, J. B.	8011140449	XPORTLIC	DONELSON, B.	8011140191	NUREQ	EISENHUT, D. O.	8011140568	50-373 A
DEVINE, J. B.	8011170120	XPORTLIC	DONELSON, B.	8011170210	70-2909	EISENHUT, D. O.	8011180067	50-245 F
DEVINCENITIS, J.	8011140403	50-443 B	DONELSON, C.	8011180118	70-2909	EISENHUT, D. O.	8011030619	50-213 B
DEVINE, J. B.	8011180784	XPORTLIC	DOUGHERTY, D. J.	8011170777	CONTRACT	EISENHUT, D. O.	8011100486	50-3 P
DEVINE, J. B.	8011140541	MISC	DOUGHERTY, D. J.	8011170781	CONTRACT	EISENHUT, D. O.	8011190237	50-10 P
DEVINE, J. B.	8011140547	XPORTLIC	DOUGHERTY, D. J.	8011180841	CONTRACT	EISENHUT, D. O.	8011190349	50-237 F
DEVINE, J. B.	8011180781	XPORTLIC	DOUGHERTY, D. J.	8011030443	CONTRACT	EISENHUT, D. O.	8011170336	50-10 F
DEVINE, J. B.	8011170759	XPORTLIC	DOUGHERTY, D. J.	8011260003	CONTRACT	EISENHUT, D. O.	8011100537	50-3 P
DEVINE, J. B.	8011180149	XPORTLIC	DRAGONETTE, K. S.	8011060248	27-39	EISENHUT, D. O.	8011260112	50-213 F
DEVINE, J. B.	8011200171	XPORTLIC	DRAGONETTE, K. S.	8011060388	27-39	EISENHUT, D. O.	8011060228	50-335 P
DEVINE, J. B.	8011210020	XPORTLIC	DRALEY, J. E.	8011100640	50-237 T	EISENHUT, D. O.	8011050020	50-339 P
DEVINE, J. B.	8011210042	XPORTLIC	DRENICK, R. F.	8011190696	NUREQ	EISENHUT, D. O.	8011040079	50-133 P
DEVINE, J. B.	8011210082	XPORTLIC	DREW, D. A.	8011050544	NUREQ	EISENHUT, D. O.	8011050555	50-322 A
DEVINE, J. B.	8011210147	XPORTLIC	DRISKILL, D. D.	8011050096	50-498 Q	EISENHUT, D. O.	8011050004	50-364 P
DEVINE, J. B.	8011210190	XPORTLIC	DRISKILL, D. D.	8011260197	50-498 Q	EISENHUT, D. O.	8011050021	50-289 Q
DEVINCENITIS, J.	8011190118	50-443 Q	DRISKILL, D. D.	8011280212	50-498 Q	EISENHUT, D. O.	8011070371	50-298 Q
DEVINE, J. B.	8011210047	XPORTLIC	DREHERICK, A. W.	8011170683	50-280 F	EISENHUT, D. O.	8011170385	50-220 Q
DEVINE, J. B.	8011210034	XPORTLIC	DUCKWORTH, J. P.	8011040378	70-2313	EISENHUT, D. O.	8011070394	50-333 Q
DEVINE, J. B.	8011210088	XPORTLIC	DUNN, J. P.	8011040360	70-2313	EISENHUT, D. O.	8011070474	50-331 Q
DEVINE, J. B.	8011260384	XPORTLIC	DUNN, E. R.	8011240192	TOPREP	EISENHUT, D. O.	8011070493	50-263 Q
DEVINE, J. B.	8011260447	XPORTLIC	DUNKLEBERGER, J.	8011040021	PROJ	EISENHUT, D. O.	8011070508	50-335 Q
DEVINE, J. B.	8011260451	XPORTLIC	DUNN, C. N.	8011030288	50-334 Q	EISENHUT, D. O.	8011070523	50-259 Q
DEVINE, J. B.	8011280147	XPORTLIC	DUNN, C. N.	8011200046	50-334 Q	EISENHUT, D. O.	8011070570	50-266 Q
DEVINE, J. B.	8011260238	70-1840	DUNN, C. N.	8011200276	50-334 Q	EISENHUT, D. O.	8011070573	50-271 Q
DEVILIN, J.	8011260069	50-320 Q	DUNN, C. N.	8011200179	50-334 Q	EISENHUT, D. O.	8011070588	50-293 Q
DEVILIN, J. H.	8011180450	50-272 Q	DUNN, C. N.	8011040386	50-334 V	EISENHUT, D. O.	8011070601	50-336 Q
DEVILIN, J. H.	8011130348	70-371	DUNN, C. N.	8011040294	50-334 F	EISENHUT, D. O.	8011070603	50-317 Q
DEVILIN, J. H.	8011100311	50-199 Q	DUNN, C. N.	8011040375	50-334 F	EISENHUT, D. O.	8011110022	50-249 Q
DEVILIN, J.	8011100388	50-333 Q	DUNN, C. N.	8011170796	50-334 Q	EISENHUT, D. O.	8011110033	50-249 Q
DEVILIN, J.	8011180810	50-344 B	DUNN, C. N.	8011060507	50-334 P	EISENHUT, D. O.	8011110090	50-249 Q
DEWEY, L. S.	8011180047	50-389 M	DUNN, D. R.	8011190703	NUREQ	EISENHUT, D. O.	8011110094	50-247 Q
DEWEY, L. S.	8011250036	50-389 M	DUNN, B. D.	8011140358	50-280 R	EISENHUT, D. O.	8011110077	50-339 Q
DEWEY, L. S.	8011260016	50-389 M	DUNN, C. N.	8011180473	50-334 R	EISENHUT, D. O.	8011110085	50-348 Q
DEWITT, R. B.	8011030550	50-155 P	DUNN, C. N.	8011280075	50-334 P	EISENHUT, D. O.	8011110099	50-334 Q
DEXTER, W. D.	8011200140	40-8743	DUNPHY, P. S.	8011170563	NUREQ	EISENHUT, D. O.	8011110112	50-286 Q
DIHA, V. K.	8011240100	NUREQ	DUPONT, S. O.	8011240098	50-254 Q	EISENHUT, D. O.	8011110155	50-269 Q
DICEY, S. B.	8011070579	40-8364	DUPREE, D.	8011180571	50-327 R	EISENHUT, D. O.	8011110337	50-368 Q
DICEY, S. B.	8011070582	FOIA	DURR, J. P.	8011100298	50-289 Q	EISENHUT, D. O.	8011110426	50-344 Q
DICEY, S. B.	8011050239	PR	DUTTON, D.	8011250335	50-424 B	EISENHUT, D. O.	8011110439	50-315 Q
DICKERSON, M. W.	8011260081	50-267 Q	DWINELL, S. E.	8011110296	50-302 H	EISENHUT, D. O.	8011110448	50-309 Q
DIETCH, R.	8011210148	50-361 K	DYKES, V. B.	8011260457	50-369 H	EISENHUT, D. O.	8011110451	50-315 Q
DIETCH, R.	8011210197	50-361 K	EGLESON, D.	8011100392	XPORTLIC	EISENHUT, D. O.	8011110464	50-312 Q
DIALLOHA, T. L.	8011280212	50-498 Q	EASTBROOK, K.	8011120337	50-244 P	EISENHUT, D. O.	8011110480	50-346 Q
DIQOB, R.	8011180777	50-328 A	EASTMAN, K.	8011040530	50-498 Q	EISENHUT, D. O.	8011110493	50-261 Q
DIQOB, R. M.	8011100223	50-266 P	EASTMAN, K.	8011050489	50-498 Q	EISENHUT, D. O.	8011110501	50-280 Q
DIQOB, R. M.	8011100264	50-390 A	EASTMAN, K.	8011060236	50-498 Q	EISENHUT, D. O.	8011110506	50-255 Q
DIQOB, R. M.	8011120597	50-261 P	EASTMAN, K.	8011050440	50-498 Q	EISENHUT, D. O.	8011110507	50-280 Q
DIQOB, R. M.	8011120599	50-280 P	EASTMAN, K.	8011190202	50-498 H	EISENHUT, D. O.	8011110527	50-250 Q
DIQOB, R. M.	8011190486	50-29 P	EBNETER, S. D.	8011100276	50-287 Q	EISENHUT, D. O.	8011110535	50-324 Q
DIQOB, R. M.	8011110042	50-277 P	EBNETER, S.	8011100292	50-287 Q	EISENHUT, D. O.	8011110559	50-324 Q
DIQOB, R. M.	8011120464	50-312 P	EBNETER, S. D.	8011130084	50-334 Q	EISENHUT, D. O.	8011110570	50-277 Q
DIGMAN, T. G.	8011050152	50-293 Q	EBNETER, S. D.	8011100373	50-387 Q	EISENHUT, D. O.	8011110579	50-277 Q
DIGMAN, T. G.	8011050152	50-293 Q	EBNETER, S. D.	8011260428	50-334 Q	EISENHUT, D. O.	8011110580	50-295 Q
DIGMAN, T. G.	8011190106	50-443 Q	ECKERMAN, K. F.	8011240067	NUREQ	EISENHUT, D. O.	8011110585	50-295 Q
DIGMAN, T. G.	8011190106	50-443 Q	ECONOMOS, N.	8011040358	50-390 Q	EISENHUT, D. O.	8011110606	50-321 Q
DILLEHAY, W.	8011030133	FOIA	EDELSTEIN, B.	8011030122	XPORTLIC	EISENHUT, D. O.	8011110631	50-213 Q
DINITZ, I.	8011030283	50-326 J	EDELSTEIN, B.	8011030126	XPORTLIC	EISENHUT, D. O.	8011110668	50-155 Q
DINITZ, I.	8011140004	50-142 J	EDELSTEIN, B.	8011210091	XPORTLIC	EISENHUT, D. O.	8011110679	50-245 Q
DIPAZZA, R. P.	8011030368	70-1151	EDGAR, Q. L.	8011140062	50-367 Q	EISENHUT, D. O.	8011140171	50-272 Q
DIPAZZA, R. P.	8010020739	40-8304	EDGAR, Q. L.	8011140063	50-367 Q	EISENHUT, D. O.	8011140491	50-271 P

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
EISENHUT, D. O.	8011140638*	50-302 Q	FAHNER, T. C.	8011250633	27-39	FELTON, J. M.	8011180286	50-302 Q
EISENHUT, D. O.	8011140692*	50-282 Q	FARMER, H. S.	8011070092	REVIEW ORP	FELTON, J. M.	8011180296	50-302 Q
EISENHUT, D. O.	8011170294*	50-305 Q	FARNELL, A. S.	8011140042	50-329 Q	FELTON, J. M.	8011180305	50-302 Q
EISENHUT, D. O.	8011170384*	50-313 Q	FARNELL, A. S.	8011140047*	50-329 Q	FELTON, J. M.	8011180360	50-302 Q
EISENHUT, D. O.	8011240007*	50-244 Q	FARNELL, A. S.	8011140042	50-329 Q	FELTON, J. M.	8011180376	50-302 Q
EISENHUT, D. O.	8011240020*	50-219 Q	FARNELL, A. S.	8011140047*	50-329 Q	FELTON, J. M.	8011240501	50-302 Q
EISENHUT, D. O.	8011240032*	50-206 Q	FARNELL, A. S.	8011190126	50-329 Q	FELTON, J. M.	8011240063	50-302 Q
EISENHUT, D. O.	8011240042*	50-237 Q	FARNELL, A. S.	8011190126	50-329 Q	FELTON, J. M.	8011240147	50-302 Q
EISENHUT, D. O.	8011240059*	50-29 Q	FARON, R. S.	8011060441	50-244 P	FERGUSON, R. L.	8011190455*	50-302 Q
EISENHUT, D. O.	8011240076*	50-409 Q	FARON, R. S.	8011170196	50-244 P	FERGUSON, J. H.	8011060310	50-302 Q
EISENHUT, D. O.	8011110532*	50-250 Q	FARON, R. S.	8011200268	50-244 P	FERGUSON, J. H.	8011190282	50-302 Q
EISENHUT, D. O.	8011110409*	50-267 Q	FASANO, A.	8011130136*	50-269 Q	FERGUSON, J. H.	8011240321	50-302 Q
EISENHUT, D. O.	8011110686	50-70 P	FASANO, A. N.	8011200342*	50-269 Q	FERGUSON, J. H.	8011240087	50-302 Q
EISENHUT, D. O.	8011170274	50-317 F	FASANO, A. N.	8011170788	50-320 S	FICKIEB, R. H.	8011030653	50-302 Q
EISENHUT, D. O.	8011190598	50-282 F	FASANO, A. N.	8011140370	50-320 S	FIELDS, J.	8011240000*	50-302 Q
EISENHUT, D. O.	8011190603	50-293 F	FAULKENBERRY, B.	8011060144*	50-361 Q	FIELDER, J.	8011070387	50-302 Q
EISENHUT, D. O.	8011200015	50-263 F	FAULKENBERRY, B.	8011070211*	50-70 Q	FILIMONOV, A.	8011120088	50-302 Q
EISENHUT, D. O.	8011280229*	50-327 Q	FAULKENBERRY, B.	8011050353*	50-206 Q	FINFRACK, I. R.	8011170937*	50-302 Q
EISENHUT, D. O.	8011200045*	50-339 Q	FAUST, C. E.	8011050445*	TOPREP	FINFRACK, I. R.	8009300132	50-302 Q
EISENHUT, D. O.	8011260316	50-389 A	FAUST, C. E.	8011050449*	TOPREP	FINFRACK, I. R.	8011170765	50-302 Q
EISENHUT, D. O.	8011260322*	50-389 A	FAY, C. W.	8011170585	71-9074	FINFRACK, I. R.	8011040460	50-302 Q
ELKSTROM, A. L.	8011100573	FOIA	FAY, C. W.	8011070322	50-266 P	FINFRACK, I. R.	8011030423	50-302 Q
EL-ASHRY, M. T.	8011030554	50-327 P	FAY, C. W.	8011190577	50-266 Q	FINFRACK, I. R.	8011040423	50-302 Q
EL-ASHRY, M. T.	8011040193	50-327 S	FAY, C. W.	8011040420	50-266 P	FINFRACK, I. R.	8011030527	50-302 Q
EL-ASHRY, M. T.	8011140428	50-438 A	FAY, C. W.	8011060448	50-266 Q	FINFRACK, I. R.	8011030562	50-302 Q
EL-ASHRY, M. T.	8011210502	50-327 S	FAY, C. W.	8011100483	50-266 S	FINFRACK, I. R.	8011110257	50-302 Q
ELDER, H. K.	8011140603	NUREQ	FAY, C. W.	8011100487*	50-266 S	FINFRACK, I. R.	8011170559	50-302 Q
ELDER, H. K.	8011170554	NUREQ	FAY, C. W.	8011120325	50-266 V	FINFRACK, I. R.	8011180636	50-302 Q
ELIN, J. O.	8011100076*	50-312 Q	FAY, C. W.	8011120358	50-266 P	FINFRACK, I. R.	8011230210	50-302 Q
ELLENMAN, D.	8011060040*	MISC	FAY, C. W.	8011120368	50-266 V	FINFRACK, I. R.	8011230500	50-302 Q
ELLIS, J.	8011280019	50-445 Q	FAY, C. W.	8011170492*	50-266 R	FINFRACK, I. R.	8011230524	50-302 Q
ELLIS, J.	8011280024	50-445 Q	FAY, C. W.	8011180436	50-266 P	FINLEY, A. O.	8011040218*	50-302 Q
ELROD, B. A.	8011170399*	50-335 Q	FAY, C. W.	8011280081	50-266 Q	FINLEY, A. O.	8011200012*	50-302 Q
ELY, D.	8011120280	50-259 Q	FAZIO, P. V.	8011170902	50-461 Q	FIORRELLI, O.	8011060113	50-302 Q
ELY, R. L.	8011260417	PR	FAZIO, P. V.	8011170906*	50-461 Q	FIORRELLI, O.	8011170204*	50-302 Q
EMERY, R. C.	8011110210	PR	FAZIO, P. V.	8011170913	50-461 Q	FIORRELLI, O.	8011260333	50-302 Q
ENGELKEN, R. H.	8011060793	50-206 Q	FAZIO, P. V.	8011170902	50-461 Q	FIORRELLI, O.	8011260334	50-302 Q
ENGELKEN, R. H.	8011060758	50-528 Q	FAZIO, P. V.	8011170906*	50-461 Q	FIORRELLI, O.	8011200036	50-302 Q
ENGELKEN, R. H.	8011060763	50-312 Q	FAZIO, P. V.	8011170913	50-461 Q	FIORRELLI, O.	8011030084	50-302 Q
ENGELKEN, R. H.	8011060767	50-344 Q	FEARS, J. R.	8011260408	PR	FIORRELLI, O.	8011060242	50-302 Q
ENGELKEN, R. H.	8011060773	50-397 Q	FECHTER, J. V.	8011100299	NUREQ	FIORRELLI, O.	8011030683	50-302 Q
ENGELKEN, R. H.	8011060777	50-133 Q	FEEL, H. F.	8011210717*	50-213 Q	FIORRELLI, O.	8011260372	50-302 Q
ENGELKEN, R. H.	8011030341	50-206 Q	FEEL, H. F.	8011200299	50-245 Q	FIORRELLI, O.	8011180379	50-302 Q
ENGELKEN, R. H.	8011130011	50-344 Q	FEEL, H. F.	8011240138	50-245 P	FIORRELLI, O.	8011200257	50-302 Q
ENGELKEN, R. H.	8011130014	50-275 Q	FEENRER, J.	8011070173*	50-320 H	FIORRELLI, O.	8011040180	50-302 Q
ENGELKEN, R. H.	8011130016	50-312 Q	FEHRINGER, J. M.	8011200113	50-334 P	FIORRELLI, O.	8011040297	50-302 Q
ENGELKEN, R. H.	8011130019	50-206 Q	FEHRINGER, J. M.	8011130018	50-272 P	FIORRELLI, O.	8011040303	50-302 Q
ENGELKEN, R. H.	8011130021	50-133 Q	FETERABEND, C. D.	8011070040*	50-262 Q	FIORRELLI, O.	8011060305	50-302 Q
ENGELKEN, R. H.	8011130024	50-328 Q	FETERABEND, C. D.	8011090153*	50-262 Q	FIORRELLI, O.	8011060284	50-302 Q
ENGELKEN, R. H.	8011130029	50-397 Q	FEIT, R.	8011030651	REVIEW ORP	FIORRELLI, O.	8011170734	50-302 Q
ENGELKEN, R. H.	8011130034	50-361 Q	FEIT, R.	8011240088	REVIEW ORP	FIORRELLI, O.	8011200160*	50-302 Q
ENGELKEN, R. H.	8011200105	50-460 Q	FELDMAN, J. H.	8011180069	50-358 Q	FIORRELLI, O.	8011200200	50-302 Q
ENGELKEN, R. H.	8011200117*	50-460 Q	FELDMAN, J. H.	8011180069	50-358 Q	FIORRELLI, O.	8011180793	50-302 Q
ENGELKEN, R. H.	8011170628	50-328 Q	FELTON, J. M.	8009270337	FOIA	FIORRELLI, O.	8011200150	50-302 Q
ENGELKEN, R. H.	8011170631	50-133 Q	FELTON, J. M.	8011030227	FOIA	FIORRELLI, O.	8011200287	50-302 Q
ENGELKEN, R. H.	8011170638	50-344 Q	FELTON, J. M.	8011030233*	FOIA	FIORRELLI, O.	8011180400	50-302 Q
ENGELKEN, R. H.	8011170640	50-206 Q	FELTON, J. M.	8009190299	50-219 Q	FIORRELLI, O.	8011230281	50-302 Q
ENGELKEN, R. H.	8011170644	50-312 Q	FELTON, J. M.	8011030250	FOIA	FIORRELLI, O.	8011030184	50-302 Q
ENGELKEN, R. H.	8011170649	50-397 Q	FELTON, J. M.	8011030168	FOIA	FIORRELLI, O.	8011100039	50-302 Q
ENGELKEN, R. H.	8011210435	50-206 Q	FELTON, J. M.	8011030152	50-302 P	FIORRELLI, O.	8011100047	50-302 Q
ENGEL, R. E.	8011190206	TOPREP	FELTON, J. M.	8011030193	FOIA	FIORRELLI, O.	8011200238	50-302 Q
ENGEL, R. E.	8011240144	TOPREP	FELTON, J. M.	8011030127	FOIA	FIORRELLI, O.	8011200250	50-302 Q
ENGEL, R. E.	8011210316	TOPREP	FELTON, J. M.	8011060080	50-3 Q	FIORRELLI, O.	8011030132	50-302 Q
ENOT, D.	8011030252	NUREQ	FELTON, J. M.	8011060051	50-259 P	FIORRELLI, O.	8011250067	50-302 Q
ERB, C. M.	8011260348*	50-440 Q	FELTON, J. M.	8011060066	50-458 H	FIORRELLI, O.	8011250057	50-302 Q
ERB, C. M.	8011200040*	50-373 Q	FELTON, J. M.	8011070345	40-8364	FIORRELLI, O.	8011250049	50-302 Q
ERB, C. M.	8011170742*	50-456 Q	FELTON, J. M.	8011100341	FOIA	FIORRELLI, O.	8011120049	50-302 Q
ERB, C. M.	8011100054*	50-546 Q	FELTON, J. M.	8011100056	FOIA	FIORRELLI, O.	8011040191	50-302 Q
ERICKSON, R. P.	8011260401	PR	FELTON, J. M.	8011100019	FOIA	FIORRELLI, O.	8011050104	50-302 Q
ERICKSON, D. M.	8011170785	REB	FELTON, J. M.	8011100033	FOIA	FIORRELLI, O.	8011280233	50-302 Q
ESTES, R. L.	8011250331*	50-445 A	FELTON, J. M.	8011100074	70-1257	FIORRELLI, O.	8011050118	50-302 Q
ESTEY, H. P.	8011030100	70-1257	FELTON, J. M.	8011180032	FOIA	FIORRELLI, O.	8011120417	50-302 Q
EVENS, R. O.	8011050224	PR	FELTON, J. M.	8011070618	FOIA	FIORRELLI, O.	8011170268	50-302 Q
EVERETT, R. C.	8011210718*	50-267 Q	FELTON, J. M.	8011100049	70-820	FIORRELLI, O.	8011190733	50-302 Q
EVRAETS, J. C.	8011210305	PR	FELTON, J. M.	8011180057	FOIA	FIORRELLI, O.	8011190503	50-302 Q
EVRAETS, J. C.	8011240416*	XPORTLIC	FELTON, J. M.	8011110138	FOIA	FIORRELLI, O.	8011190726	50-302 Q
EVRAETS, J. C.	8011240411	XPORTLIC	FELTON, J. M.	8011102090	50-302 D	FIORRELLI, O.	8011170181	50-302 Q
FAHNER, T. C.	8011050221	50-461 Q	FELTON, J. M.	8011170907	70-143	FIORRELLI, O.	8011170206	50-302 Q
FAHNER, T. C.	8011050151	27-39	FELTON, J. M.	8011180150	50-220 H	FIORRELLI, O.	8011170228	50-302 Q
FAHNER, T. C.	8011100233	27-39	FELTON, R. W.	8011200194*	CONTRACT	FIORRELLI, O.	8011170254	50-302 Q
FAHNER, T. C.	8011110593	27-39	FELTON, J. M.	8011140661	FOIA	FIORRELLI, O.	8011260099	50-302 Q
FAHNER, T. C.	8011250043	27-39	FELTON, J. M.	8011180159	FOIA	FIORRELLI, O.	8011190445	50-302 Q
FAHNER, T. C.	8011250694	27-39	FELTON, J. M.	8011180199	FOIA	FIORRELLI, O.	8011190467	50-302 Q
FAHNER, T. C.	8011240159	27-39	FELTON, J. M.	8011180347	FOIA	FIORRELLI, O.	8011190479	50-302 Q
FAHNER, T. C.	8011250039	27-39	FELTON, J. M.	8011180267	50-556 Q	FIORRELLI, O.	8011200137	50-302 Q

PERSONAL AUTHOR INDEX

317

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FIRTH, D. J.	8011210524*	50-312 P	GALLEN, K. P.	8011140062	50-367 Q	GOODMAN, L. S.	8011170503*	50-409 R
FISH, R. F.	8011030280*	50-344 Q	GALLEN, K. P.	8011140063*	50-367 Q	GOODMAN, M. J.	8011170753	50-299 P
FISHER, W. L.	8011060207*	50-373 Q	GALLEN, K. P.	8011140062	50-367 Q	GOODWIN, C.	8011100011*	50-344 Q
FISHER, W. L.	8011260283*	50-254 Q	GALLEN, K. P.	8011140063*	50-367 Q	GOPAL, R.	8011070142*	REVIEW ORP
FISHER, W. L.	8011280224*	50-294 Q	GALLEN, K. P.	8011190028	50-409 Q	GORDDN, A. K.	8011250702*	CONTRACT
FITZIBBONS, R.	8011040417	50-237 Q	GALLEN, K. P.	8011190033*	50-409 Q	GRUDY, P. R.	8011170848*	QA999
FITZIBBONS, R.	8011050200	50-237 Q	GALLEN, K. P.	8011190028	50-409 Q	GRAEBBER, K. L.	8011100401	50-295 S
FITZIBBONS, R.	8011050200	50-237 Q	GALLEN, K. P.	8011190033*	50-409 Q	GRAEBBER, K. L.	8011100410	50-295 S
FITZIBBONS, R.	8011060472	50-237 Q	GALLEN, K. P.	8011210508	50-409 Q	GRAEBBER, K. L.	8011070378	50-295 S
FITZIBBONS, R.	8011170222	50-237 Q	GALLO, R. H.	8011210395*	50-387 Q	GRAEBBER, K. L.	8011110209	50-295 R
FITZIBBONS, R.	8011210513	50-237 Q	GALLO, R. H.	8011100373*	50-387 Q	GRAEBBER, K. L.	8011180716	50-295 S
FITZGERALD, M.	8011230510*	50-219 B	GALLO, R. H.	8011190367	REB	GRAEBBER, K. L.	8011140034	50-295 S
FITZPATRICK, B.	8011050142*	50-305 Q	GARCIA, P. J.	8011070149	40-B452	GRAEBBER, K. L.	8011250318	50-304 B
FLANAGAN, G. F.	8010020486	NUREQ	GARLAND, H.	8011070631	40-1162	GRAEBBER, K. L.	8011250330	50-295 B
FLANAGAN, R. J.	8011250048	PR	GARRITY, J. H.	8011040828	50-309 R	GRAEBBER, K. L.	8011250338	50-295 B
FLANIGAN, L. J.	8011100471	NUREQ	GARRITY, J. H.	8011210563	50-309 S	GRAHAM, M. J.	8011060806*	50-335 Q
FLANIGAN, L. J.	8011170712	NUREQ	GARTLING, D. K.	8011170677	NUREQ	GRANT, H. D.	801030237	FOIA
FLEENOR, C. M.	8011140079	CONTRACT	GARY, R. J.	8011140367	50-445 Q	GRANT, F. H.	801030252	NUREQ
FLEENOR, C. M.	8011180196	CONTRACT	GARY, R. J.	8011140355	50-445 Q	GRANT, H. E.	8011060286*	50-409 Q
FLEENOR, C. M.	8011180062	CONTRACT	GARY, R. J.	8011140361	50-445 Q	GRANT, H.	8011110034*	50-10 Q
FLEISCHAKER, D.	8011100210	50-275 Q	GARY, R. J.	8011030287	50-445 A	GRANT, W. B.	8011260283*	50-254 Q
FLEISCHAKER, D.	8011100210	50-275 Q	GARY, R. J.	8011030585	50-445 B	GRAVES, R. H.	8011180465	50-213 R
FLYNN, J. D.	8011040168	50-388 Q	GARY, R. J.	8011180494	50-445 A	GRAVES, R. H.	8011250433	50-213 R
FLYNN, J. D.	8011040579	50-388 A	GARY, R. J.	8011250326	50-445 A	GRAY, J. R.	8011060101	50-289 Q
FLYNN, J. D.	8011250673	CONTRACT	GASBARRO, D. P.	8011180645*	50-219 S	GRAY, J. R.	8011140113	50-289 Q
FLYNN, J. D.	8011120385	50-358 A	GAT, U.	8011120192	REGOD	GREENMAN, E. O.	8011130050*	50-289 Q
FLYNN, J. D.	8011120528	50-358 A	GAUNT, J.	8011250123	PR	GREENMAN, E. O.	8011130125*	50-247 Q
FLYNN, J. D.	8011240338	50-358 A	GEARS, G. E.	8011140309	NUREQ	GREENMAN, E. O.	8011150254*	50-277 Q
FLYNN, J. D.	8011260209	50-358 A	GEHR, A. C.	8011050406	50-275 Q	GREENMAN, E. O.	8011260444*	50-277 Q
FLYNN, J. D.	8011260210*	50-358 A	GEIGER, G.	8011200243	50-387 Q	GREEN, H. J.	8011040599	50-327 S
FOLEY, T. F.	8011100350*	50-271 Q	GELSTON, A. H.	8011040393*	50-327 B	GREEN, H. J.	8011120421	50-327 B
FOLEY, T. F.	8011250133	PR	GEORGE, D.	8011110615	50-320 P	GREEN, H. J.	8011120432	50-327 B
FOLEY, T. F.	8011060205	70-1470	GEORGE, D.	8011050165	50-275 Q	GREEN, H. J.	8011120453	50-327 B
FORD, E. J.	8011040548*	50-395 Q	GEORGE, D. B.	8011070234	50-275 Q	GREEN, H. J.	8011120481	50-327 B
FORD, E. J.	8011060408	PR	GEORGE, M. D.	8011280202*	50-186 Q	GREEN, D.	8011180594*	50-259 R
FORD, C. S.	8011060412	PR	GEORGE, R. L.	8011210585	50-348 P	GREEN, H. J.	8011120468	50-327 S
FORLENZA, F. O.	8011120426*	50-272 Q	GERSTNER, W. C.	8011030558	50-461 B	GREEN, H. J.	8011120507	50-259 S
FORNEY, W. L.	8011180114*	50-409 Q	GIBBONS, T. D.	8011260396*	50-416 Q	GREENMAN, E.	8011103071	50-247 S
FORNEY, W. L.	8011260375*	50-409 Q	GIBBS, D. C.	8006030286	NUREQ	GREEN, H. J.	8011120572	50-259 S
FOSTER, J. E.	8011260424*	50-346 Q	GIBSON, A. F.	8011050496*	50-230 Q	GREEN, H. J.	8011120589	50-276 S
FOSTER, E. R.	8011050219*	50-423 B	GIBSON, A. F.	8011050519*	50-321 Q	GREEN, H. J.	8011120448	50-260 S
FOSTER, W. E.	8011170858*	QA999	GIBSON, G.	8011210093*	50-327 Q	GREEN, H. J.	8011120580	50-276 S
FOSTER, W. E.	8011170879*	QA999	GIBSON, A. F.	8011050286*	50-364 Q	GREEN, H. J.	8011140381	50-260 S
FOSTER, J. E.	8011200553*	50-346 Q	GIBSON, A. F.	8011260407*	70-143	GREEN, H. J.	8011180640	50-327 S
FOSTER, H.	8011110165	70-1151	GIBSON, A. F.	8011200519*	70-143	GREEN, H. J.	8011180707	50-327 S
FOUKE, R. L.	8011280036	50-445 Q	GIBSON, A. F.	8011280242*	50-369 Q	GREEN, H. J.	8011210480	50-259 S
FOY, J.	8011060219	50-461 Q	GIEBEKE, J. A.	8011280232	NUREQ	GREEN, H. J.	8011180624	50-327 S
FRANCIS, F. E.	8011180015	50-484 Q	GILBERT, L. D.	8011100116*	50-445 Q	GREEN, H. J.	8011180634	50-327 S
FRANCIS, F. E.	8011180015	50-484 Q	GILBERT, D. E.	8011180508	50-263 Q	GREEN, H. J.	8011180692	50-327 S
FRANK, L.	8011040026	PROJ	GILBERTS, D. E.	8011190019	50-282 Q	GREEN, H. J.	8011210537	50-259 S
FRAREY, J. L.	8011070135*	REVIEW ORP	GILBERTS, D. E.	8011190079	50-282 Q	GREEN, H. J.	8011210586	50-276 S
FREDERICK, L. C.	8011030676	REGOD	GILBERTS, D. E.	8011190341	50-263 Q	GREEN, H. J.	8011210601	50-259 S
FREDERICK, E. J.	8011260260	RES	GILBERTS, D. E.	8011240471	50-282 Q	GREEN, H. J.	8011180694	50-259 S
FREDENBURG, E. A.	8011170377	50-397 A	GILBERTS, D. E.	8011260104	50-263 Q	GREENBERG, J.	8011240317*	50-320 P
FREEMAN, R. H.	8011240317*	50-320 P	GILBERTS, D. E.	8011280101	50-263 Q	GREEN, H. J.	8011210457	50-260 S
FRENCH, L. D.	8011100482*	50-29 B	GILBERTS, D. E.	8011100646*	50-237 T	GREEN, H. J.	8011210492	50-327 S
FREY, D. O.	8011250337	50-10 H	GILL, P.	8011100342	50-387 Q	GREEN, H. J.	8011210565	50-327 S
FRIED, D.	8011060213*	50-320 H	GILLESPIE, F. P.	8011130405*	70-143	GREEN, H. J.	8011210598	50-296 S
FROELICH, R. W.	8011130194	NUREQ	GILLEN, D. M.	8011170352	40-8681	GREEN, H. J.	8011240332	50-327 S
FROST, S. R.	8011260101	50-255 Q	GILLEN, D. M.	8011130320	40-2259	GREEN, H. J.	8011250395	50-327 S
FULGINITI, B. A.	8011190285*	50-289 Q	GILLET, H. T.	8011180625*	50-315 R	GREEN, H. J.	8011230409	50-276 S
FUNDERBURG, R. D.	8011040231	PROJ	GILLET, H. T.	8011180657*	50-316 R	GREEN, H. J.	8011230376	50-260 S
FURR, B. J.	8011100461	50-261 Q	GILLET, H. T.	8011180477*	50-327 P	GREEN, H. J.	8011230336	50-327 S
FURR, B. J.	8011210460*	50-324 Q	GILLIS, J. P.	8011140105	50-322 Q	GREEN, H. J.	8011230345	50-259 S
FURR, B. J.	8011260293	50-324 Q	GILMARTIN, D. J.	8011120671	PROJ	GREEN, H. J.	8011230387	50-327 S
FURR, B. J.	8011240118	50-324 Q	GILMAN, R. A.	80111040310*	50-413 Q	GREEN, H. J.	8011230436	50-260 S
FURR, B. J.	8011280031	50-261 Q	GIRARD, E. H.	8011170574	50-275 Q	GREEN, H. J.	8011250447	50-327 S
FURR, B. J.	8011280040	50-324 Q	GLADDA, A. F.	8011140191	NUREQ	GREER, R. J.	8011060295*	50-327 Q
FURR, B. J.	8011280125	50-324 Q	GLANG, J.	80111040430	50-237 Q	GREER, R. J.	8011060274*	50-244 Q
GAD, R. K.	8011190106	50-443 Q	GODDARD, R. J.	8011040419	50-237 Q	GREER, R. J.	8011190496*	50-150 Q
GAD, R. K.	8011190106	50-443 Q	GODDARD, R. J.	8011070182	50-237 T	GREEVES, J. T.	8011140474*	50-367 Q
GAGE, L.	8011100292*	50-289 Q	GODDARD, R. J.	8011180076	50-237 T	GREEVES, J. T.	8011190152*	50-409 Q
GAGLIARDO, J. E.	8011060682*	50-313 Q	GODDARD, R. J.	8011230031	50-471 Q	REGODRY, W. B.	8011100206	REB
GAGLIARDO, J. E.	8011060110*	50-298 Q	GODEL, G. R.	8011140324	NUREQ	OREN, P. C.	8011110611	PR
GAHM, J. W.	8011210478*	50-267 S	GOLDBERG, G. C.	8011030730	50-367 Q	ORIER, B. H.	8011070610*	FOIA
GAHM, J. W.	8011210552*	50-267 S	GOLDBERG, A.	8011190085	NUREQ	ORIER, B. H.	8011130105*	50-34 Q
GAHM, J. W.	8011210581*	50-267 S	GOLDBERG, B. C.	8011050446	50-367 Q	ORIER, B. H.	8011170288*	70-882
GAHM, J. W.	8011140343*	50-267 R	GOLDBERG, B. C.	8011100252	50-395 Q	ORIER, B. H.	8011200118*	50-245 Q
GAHM, J. W.	8011120529*	50-267 S	GOLDBERG, J. R.	8011070081	PROJ	ORIER, B. H.	8011130130	50-289 Q
GAHM, J. W.	8011140401*	50-267 S	GOLDBERG, B. C.	8011070163	50-367 Q	ORIER, B. H.	8011100321	50-289 Q
GAHM, J. W.	8011140411*	50-267 S	GOLDBERG, B. C.	8011140466	50-367 Q	ORIER, B. H.	8011060831	50-322 Q
GAHM, J. W.	8011180667*	50-267 S	GOLDBERG, B. C.	8011130319	50-395 D	ORIER, B. H.	8011060837	50-358 Q
GAJNEB, N. J.	8011180088	70-143	GOLDBERG, B. C.	8011190062	50-250 Q	ORIER, B. H.	8011060837	50-410 Q
GALLAGHER, E. J.	8011170204*	50-483 Q	GOLLER, K. R.	8011060471	ORP	ORIER, B. H.	8011060837	50-387 Q
GALLAGHER, E. J.	8011250062*	50-546 Q	GOODAL, C. E.	8011190292*	50-289 Q	ORIER, B. H.	8011060837	50-412 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ORIER, B. H.	8011060545	50-423 Q	ORIER, B. H.	8011070317	50-333 Q	GRDCE, R. H.	8011190303	50-309 P
ORIER, B. H.	8011060548	50-354 Q	ORIER, B. H.	8011070320	50-272 Q	GRDNENHYER, E. L.	8011170530*	State Prog
ORIER, B. H.	8011060551	50-245 Q	ORIER, B. H.	8011070323	50-354 Q	GRDBEUP, Q. W.	8011070464	50-440 A
ORIER, B. H.	8011060556	50-363 Q	ORIER, B. H.	8011070326	50-423 Q	GRDBS, L. H.	8011180288	50-356 Q
ORIER, B. H.	8011060559	50-244 Q	ORIER, B. H.	8011070330	50-443 Q	GRDBSMAN, K.	8011070623	FOIA
ORIER, B. H.	8011070023	50-309 Q	ORIER, B. H.	8011070331	50-387 Q	GRDBSMAN, H.	8011050188	50-395 Q
ORIER, B. H.	8011070029	50-333 Q	ORIER, B. H.	8011070334	50-271 Q	GRDBSMAN, H.	8011070060	50-266 Q
ORIER, B. H.	8011070030	50-271 Q	ORIER, B. H.	8011070335	50-220 Q	GRDBSMAN, H.	8011140528	50-395 Q
ORIER, B. H.	8011070034	50-286 Q	ORIER, B. H.	8011070339	50-309 Q	GRDBSMAN, H.	8011250643	50-367 Q
ORIER, B. H.	8011070036	50-293 Q	ORIER, B. H.	8011070341	50-334 Q	GRDTER, C.	8011050282	PROJ
ORIER, B. H.	8011070044	50-336 Q	ORIER, B. H.	8011070343	50-3 Q	GRDTENHUIS, M.	8011030698	50-250 P
ORIER, B. H.	8011070045	50-272 Q	ORIER, B. H.	8011200547	50-272 Q	GRDTENHUIS, M.	8011140488	50-250 Q
ORIER, B. H.	8011070050	50-247 Q	ORIER, B. H.	8011300008	50-311 Q	GRDTENHUIS, M.	8011050579	50-250 P
ORIER, B. H.	8011070055	50-289 Q	ORIER, B. H.	8011140063	50-245 Q	GRDTUAGE, T. M.	8011120484	50-461 C
ORIER, B. H.	8011070058	50-317 Q	ORIER, B. H.	8011140066	50-3 Q	GRDVES, K. L.	8011140686*	40-8412
ORIER, B. H.	8011070067	50-277 Q	ORIER, B. H.	8011140069	50-271 Q	GRUAER, M.	8011050282	PROJ
ORIER, B. H.	8011070069	50-334 Q	ORIER, B. H.	8011140070	50-29 Q	GUHIN, M. A.	8011030096	XPORTLIC
ORIER, B. H.	8011070072	50-3 Q	ORIER, B. H.	8011140072	50-309 Q	GUHIN, M. A.	8011060544	XPORTLIC
ORIER, B. H.	8011070074	50-220 Q	ORIER, B. H.	8011140073	50-333 Q	GULDEMOND, W. G.	8011120689*	50-266 Q
ORIER, B. H.	8011030078	70-820	ORIER, B. H.	8011140076	50-272 Q	GULDEMOND, W. G.	8011210149*	50-266 Q
ORIER, B. H.	8011030049	50-309 P	ORIER, B. H.	8011140077	50-286 Q	GUMBLE, F. W.	8011190439*	50-286 S
ORIER, B. H.	8011030067	50-219 Q	ORIER, B. H.	8011140078	50-220 Q	GUNNERSON, F. B.	8011170563	NUREQ
ORIER, B. H.	8011030092	50-293 Q	ORIER, B. H.	8011140080	50-410 Q	GURUNATHAN, S.	8011070379*	50-295 S
ORIER, B. H.	8011130090	50-34 Q	ORIER, B. H.	8011140083	50-354 Q	GURUNATHAN, S.	8011140041*	50-295 S
ORIER, B. H.	8011210393	50-289 Q	ORIER, B. H.	8011140084	50-387 Q	GUTH, R. W.	8011180556	50-320 P
ORIER, B. H.	8011260123	40-672	ORIER, B. H.	8011140116	50-443 Q	HAAB, D.	8011190162*	50-289 H
ORIER, B. H.	8011060599	50-271 F	ORIER, B. H.	8011140119	50-244 Q	HAASB, W. P.	8011060546	MTBC
ORIER, B. H.	8011030072	50-293 Q	ORIER, B. H.	8011140124	50-485 Q	HAASB, W. P.	8011030446	TOPREP
ORIER, B. H.	8011200120	50-219 Q	ORIER, B. H.	8011140129	50-219 Q	HAASB, W. P.	8011100409	TOPREP
ORIER, B. H.	8011200136	50-272 P	ORIER, B. H.	8011140132	50-363 Q	HAASB, W. P.	8011120025	REQDD
ORIER, B. H.	8011200103	50-220 Q	ORIER, B. H.	8011140135	50-322 Q	HAFAE, C. A.	8011120557*	50-409 F
ORIER, B. H.	8011200110	50-245 Q	ORIER, B. H.	8011140137	50-334 Q	HAGEN, C. M.	8011170674	NUREQ
ORIER, B. H.	8011180193	50-293 P	ORIER, B. H.	8011140139	50-412 Q	HAQUE, R. L.	8011120689*	50-266 Q
ORIER, B. H.	8011200141	50-213 Q	ORIER, B. H.	8011140147	50-316 Q	HAQUE, R. L.	8011210149*	50-266 Q
ORIER, B. H.	8011180113	50-213 Q	ORIER, B. H.	8011140235	50-352 Q	HAHN, H. F.	8010270115*	70-1092
ORIER, B. H.	8011200097	50-220 Q	ORIER, B. H.	8011140240	50-277 Q	HAIRR, O. H.	8011110074	FR
ORIER, B. H.	8011180800	50-272 Q	ORIER, B. H.	8011140272	50-293 Q	HAIRSTON, C.	8011170772	CONTRACT
ORIER, B. H.	8011190593	50-245 Q	ORIER, B. H.	8011140275	50-213 Q	HAIRSTON, C. A.	8011170574	50-275 Q
ORIER, B. H.	8011200518	50-269 Q	ORIER, B. H.	8011140277	50-317 Q	HAIRSTON, C.	8011180825	CONTRACT
ORIER, B. H.	8011200545	50-247 B	ORIER, B. H.	8011140279	50-289 Q	HAIRSTON, C.	8011170787	CONTRACT
ORIER, B. H.	8011210325	70-364	ORIER, B. H.	8011140580	50-220 Q	HAIRSTON, C.	8011030440	CONTRACT
ORIER, B. H.	8011210331	70-371	ORIER, B. H.	8011140583	50-277 Q	HAIRSTON, C.	8011260001	CONTRACT
ORIER, B. H.	8011210338	70-820	ORIER, B. H.	8011140585	50-289 Q	HAIRSTON, W. G.	8011210381*	50-348 R
ORIER, B. H.	8011060629	50-219 Q	ORIER, B. H.	8011140588	50-363 Q	HAIRSTON, W. G.	8011210390*	50-364 R
ORIER, B. H.	8011060633	50-363 Q	ORIER, B. H.	8011140591	50-219 Q	HAIRSTON, W. G.	8011180500*	50-348 S
ORIER, B. H.	8011060635	50-322 Q	ORIER, B. H.	8011140594	50-293 Q	HAIRSTON, W. G.	8011210506*	50-348 S
ORIER, B. H.	8011060636	50-516 Q	ORIER, B. H.	8011140598	50-352 Q	HAIRSTON, W. G.	8011210512*	50-348 S
ORIER, B. H.	8011060638	50-443 Q	ORIER, B. H.	8011140599	50-213 Q	HAIRSTON, W. G.	8011240310*	50-348 S
ORIER, B. H.	8011060639	50-277 Q	ORIER, B. H.	8011140605	50-3 Q	HAIRSTON, W. G.	8011250341*	50-348 S
ORIER, B. H.	8011060641	50-271 Q	ORIER, B. H.	8011140609	50-309 Q	HAIRSTON, W. G.	8011250347*	50-348 S
ORIER, B. H.	8011060642	50-352 Q	ORIER, B. H.	8011140613	50-516 Q	HAIST, D. P.	8011200135*	50-460 Q
ORIER, B. H.	8011060644	50-412 Q	ORIER, B. H.	8011140620	50-322 Q	HAIST, D. P.	8011200117*	50-460 Q
ORIER, B. H.	8011060645	50-387 Q	ORIER, B. H.	8011140622	50-271 Q	HALE, C. J.	8011040096*	Q9999
ORIER, B. H.	8011060648	50-334 Q	ORIER, B. H.	8011140625	50-410 Q	HALE, C. J.	8011060252*	Q9999
ORIER, B. H.	8011060649	50-317 Q	ORIER, B. H.	8011140629	50-387 Q	HALL, R. E.	8011140626*	50-244 F
ORIER, B. H.	8011060652	50-3 Q	ORIER, B. H.	8011170663	50-443 Q	HALL, R. E.	8011100116*	50-445 Q
ORIER, B. H.	8011060654	50-272 Q	ORIER, B. H.	8011170676	50-286 Q	HALL, R. E.	8011040674*	50-445 Q
ORIER, B. H.	8011060659	50-293 Q	ORIER, B. H.	8011170831	50-333 Q	HALL, R. E.	8011190289*	50-382 Q
ORIER, B. H.	8011060661	50-354 Q	ORIER, B. H.	8011170843	50-485 Q	HALL, R. E.	8011250132*	50-482 Q
ORIER, B. H.	8011060665	50-485 Q	ORIER, B. H.	8011170857	50-244 Q	HALL, D.	8011240290	50-356 H
ORIER, B. H.	8011060669	50-244 Q	ORIER, B. H.	8011170864	50-29 Q	HALMAN, E. L.	8011170758*	50-275 Q
ORIER, B. H.	8011060672	50-220 Q	ORIER, B. H.	8011170869	50-272 Q	HALMAN, E. L.	8011170795*	CONTRACT
ORIER, B. H.	8011060675	50-309 Q	ORIER, B. H.	8011170877	50-354 Q	HAMILL, K. J.	8011060302	40-8743
ORIER, B. H.	8011060678	50-213 Q	ORIER, B. H.	8011170887	50-245 Q	HAMILL, K. J.	8011170895	40-8743
ORIER, B. H.	8011060680	50-333 Q	ORIER, B. H.	8011170893	50-412 Q	HAMILL, K. J.	8011200261*	50-846 A
ORIER, B. H.	8011060746	50-245 Q	ORIER, B. H.	8011170901	50-317 Q	HAMM, R. C.	8011200264*	50-846 A
ORIER, B. H.	8011070232	50-485 Q	ORIER, B. H.	8011170909	50-334 Q	HANAUER, S. H.	8011120573	50-387 A
ORIER, B. H.	8011070238	50-322 Q	ORIER, B. H.	8011280191	70-1143	HANAUER, S. H.	8011140635	50-387 A
ORIER, B. H.	8011070241	50-316 Q	ORIER, B. H.	8011280194	70-33	HANCOCK, J. A.	8011050227*	50-302 Q
ORIER, B. H.	8011070249	50-289 Q	ORIER, B. H.	8011280197	70-371	HANCOCK, J. A.	8011040482	50-302 B
ORIER, B. H.	8011070265	50-412 Q	ORIER, B. H.	8011280201	70-820	HANCOCK, J. A.	8011110321	50-302 B
ORIER, B. H.	8011070267	50-410 Q	ORIER, B. H.	8011280210	70-364	HANCOCK, J. A.	8011120486	50-302 B
ORIER, B. H.	8011070271	50-286 Q	ORIER, B. H.	8011120632	NUREQ	HANCOCK, J. A.	8011140045	50-302 B
ORIER, B. H.	8011070274	50-244 Q	ORIER, B. H.	8011190070	NUREQ	HANCOCK, J. A.	8011180581	50-302 B
ORIER, B. H.	8011070276	50-293 Q	ORIER, B. H.	8011260307	NUREQ	HAND, C. H.	8011060395	50-269 Q
ORIER, B. H.	8011070280	50-247 Q	ORIER, B. H.	7903200201	50-10 P	HANES, L. F.	8011100265	NUREQ
ORIER, B. H.	8011070284	50-213 Q	ORIER, B. H.	7910160145	50-219 P	HANNAFORD, J.	8011002020	NUREQ
ORIER, B. H.	8011070286	50-363 Q	ORIER, B. H.	7910170010	50-219 P	HANNAFORD, J.	8011180628*	50-245 S
ORIER, B. H.	8011070289	50-219 Q	ORIER, B. H.	8011060035	MTBC	HANNAFORD, J.	8011210191*	10CFR
ORIER, B. H.	8011070292	50-29 Q	ORIER, B. H.	8011030196	50-461 A	HANSEN, L. E.	8011060345	XPORTLIC
ORIER, B. H.	8011070296	50-336 Q	ORIER, B. H.	8011030185	50-461 A	HANSEN, L. E.	8011060349*	XPORTLIC
ORIER, B. H.	8011070300	50-245 Q	ORIER, B. H.	8011030189	50-311 P	HANSEN, L. E.	8011060398	XPORTLIC
ORIER, B. H.	8011070305	50-317 Q	ORIER, B. H.	8011170287	50-311 P	HANSEN, L. E.	8011060402*	XPORTLIC
ORIER, B. H.	8011070308	50-352 Q	ORIER, B. H.	8011180853*	50-255 Q	HANSEN, L. E.	8011100135	71-9070
ORIER, B. H.	8011070312	50-277 Q	ORIER, B. H.	8011120361	50-309 P	HANSEN, W. H.	8011050255	40-259

PERSONAL AUTHOR INDEX

315

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HANSON, L. E.	8011070083	XPORTLIC	HEISHMAN, R. F.	8011180099	50-409 Q	HERSCH, M. M.	8011200362	XPORTLIC
HARDIN, A. K.	80111210431*	50-261 Q	HEISHMAN, R. F.	8011200002	50-331 Q	HERSCH, M. M.	8011200366*	XPORTLIC
HARDICK, R. J.	8011050300*	50-261 Q	HEISHMAN, R. F.	8011180856	50-373 Q	HERSCH, M. M.	8011200370	XPORTLIC
HARKEY, D. R.	8011190143*	50-320 H	HEISHMAN, R. F.	8011180849	50-255 Q	HERSCH, M. M.	8011200373*	XPORTLIC
HARMON, D. W.	8011070109	XPORTLIC	HEISHMAN, R. F.	8011190515	50-10 Q	HERSCH, M. M.	8011210135	XPORTLIC
HARMON, D.	8011260380	XPORTLIC	HEISHMAN, R. F.	8011210183	50-263 Q	HERSLOFF, L. W.	8011030671	REGO
HARMON, D.	8011190670	XPORTLIC	HEISHMAN, R. F.	8011240090	50-254 Q	HERSLOFF, L. W.	8011030697	REGO
HARRAN, G.	8011180639*	50-245 R	HEISHMAN, R. F.	8011240103	50-346 Q	HERT, O. H.	8011250146	PR
HARRISON, P.	8011070381*	50-220 S	HEISHMAN, R. F.	8011260367	50-409 Q	HICKEY, J. W.	8009100228*	SECY
HARRIS, L.	8011190183	NUREO	HEISHMAN, R. F.	8011210142	50-266 Q	HICKEY, C. R.	8011100523	50-320
HARRISTON, W. B.	8011240375*	50-348 F	HEISHMAN, R. F.	8011240074	50-295 Q	HIESTAND, O. S.	8011190028	50-409
HARRISTON, W. B.	8011240384*	50-348 F	HEISHMAN, R. F.	8011110027	50-10 Q	HIESTAND, O. S.	8011190033*	50-409
HARRISTON, W. B.	8011240394*	50-348 F	HEISHMAN, R. F.	8011210164	50-305 Q	HIESTAND, O. S.	8011190028	50-409
HARRISTON, W. B.	8011240477*	50-348 F	HEISHMAN, R. F.	8011050147	50-282 Q	HIESTAND, O. S.	8011190033*	50-409
HARRISTON, W. B.	8011240489*	50-348 F	HEISHMAN, R. F.	8011110007	50-388 Q	HILL, W. M.	8011180814*	50-272
HARRISTON, W. B.	8011240495*	50-348 F	HEISHMAN, R. F.	8011200544*	50-10 Q	HILLMAN, R. E.	8011040468*	50-219
HARRISTON, W. B.	8011240508*	50-348 F	HEISHMAN, R. F.	8011280192	50-266 Q	HIND, J. A.	8011060218*	50-305
HARRISTON, W. B.	8011240519*	50-348 F	HEISKELL, K. M.	8011030480	NUREO	HIND, J. A.	8011060212	50-306
HARRISTON, W. B.	8011240482*	50-348 F	HELLER, L. W.	8011140508*	50-367 Q	HIND, J. A.	8011060699*	50-116
HARRISTON, W. B.	8011240488*	50-348 F	HELLER, L. W.	8011140546*	50-367 Q	HIND, J. A.	8011060694	50-116
HARRISTON, W. B.	8011240497*	50-348 F	HELM, K. S.	8011130088	XPORTLIC	HIND, J. A.	8011200022*	50-409
HARRISTON, W. B.	8011240507*	50-348 F	HELTON, A. H.	8011240051	50-320 P	HIND, J. A.	8011200012*	50-10
HARRISTON, W. B.	8011240515*	50-348 F	HELVICK, C.	8011240167	50-142 Q	HIND, J. A.	8011110019	50-315
HARRISTON, W. B.	8011240526*	50-348 F	HENDERSON, W. J.	8011120121	PR	HIND, J. A.	8011200009	50-10
HARRISTON, W. B.	8011240528*	50-348 F	HENDER, W. R.	8011120135	PR	HIND, J. A.	8011200017	50-409
HARRISTON, W. B.	8011240542*	50-348 F	HENDORSON, J. B.	8011140352	50-397 B	HIND, J. A.	8011190639	50-409
HARRISTON, W. B.	8011240555*	50-340 F	HENDRIE, J. M.	8011110252*	50-263 Q	HINTZ, D. P.	8011120860*	50-237
HARRISTON, W. B.	8011240562*	50-340 F	HENDRIE, J. M.	8011110245*	50-263 Q	HINES, E.	8011070494	50-341
HARRISTON, W. B.	8011240567*	50-348 F	HENDRIE, J. M.	8011140687*	50-320 P	HINES, E.	8011190685	50-341
HART, O.	8011030263*	FOIA	HENDRIE, J. M.	8011120108	COMMISSION	HINES, E.	8011180591	50-341
HART, R. B.	8011180369	FOIA	HENDRIE, J. M.	8011180198	COMMISSION	HINNEFELD, B.	8011050213	PR
HART, J.	8011280036	50-445 Q	HENDRIE, J. M.	8011180201	COMMISSION	HINTZ, A. S.	8011190199	REGO
HARTFIELD, R. A.	8011040418*	50-313 P	HENDRIE, J. M.	8011180202	COMMISSION	HOAGLAND, K. E.	8011260304	50-219
HARTZMAN, M.	8010230078	50-339 P	HENDRIE, J. M.	8011180208	COMMISSION	HOFFMAN, D. P.	7912190466	50-255
HARVEGO, J. H.	8011200124	REB	HENDRIE, J. M.	8011180211	COMMISSION	HOFFMAN, D. P.	8003130577	50-255
HARWOOD, F. C.	8011260127	50-289 H	HENDRIE, J. M.	8011180235	COMMISSION	HOFFMAN, D. P.	8004150627	50-255
HASEN, D. B.	8011030471*	50-282 Q	HENDRIE, J. M.	8011180238	COMMISSION	HOFFMAN, D. P.	8011100533*	50-155
HASSELMAN, T. K.	8011030659	NUREO	HENDRIE, J. M.	8011180242	COMMISSION	HOFFMAN, D. P.	8011100539*	50-155
HAUG, F. W.	8011170898*	40-8743	HENDRIE, J. M.	8011180246	COMMISSION	HOFFMAN, D. P.	8011120530	50-155
HAUGHNEY, C. J.	8011030458	50-201 H	HENDRIE, J. M.	8011180255	COMMISSION	HOFFMAN, D. P.	8011040177	50-155
HAUGHNEY, C. J.	8011260432	50-201 P	HENDRIE, J. M.	8011180255	COMMISSION	HOFFMAN, D. P.	8011030545	50-155
HAUGHNEY, C. J.	8011260437	50-201 P	HENDRIE, J. M.	8011210210	COMMISSION	HOFFMAN, D. P.	8011030568	50-155
HAVERKAMP, D.	8011130136*	50-289 Q	HENDRIE, J. M.	8011180214	COMMISSION	HOFFMAN, D. P.	8011050499	50-250
HAVERKAMP, D. R.	8011100531*	50-289 Q	HENDRIE, J. M.	8011180218	COMMISSION	HOFFMAN, V. C.	8011030653	50-201
HAVERKAMP, D. R.	8011200542*	50-289 Q	HENDRIE, J. M.	8011180220	COMMISSION	HOFFMAN, D. P.	8011030533	50-255
HAKINS, F. C.	8011260424*	50-546 Q	HENDRIX, O.	8011180493	71-112	HOFFMAN, D. P.	8011040128	50-155
HAKINS, F. C.	8011200553*	50-546 Q	HENDRIX, J. M.	8011180223	COMMISSION	HOFFMAN, D. P.	8011040196	50-155
HAKINS, F. C.	8011180409*	50-373 Q	HENDRIX, J. M.	8011180225	COMMISSION	HOFFMAN, D. P.	8011040200	50-255
HAKINS, E.	8011060248	27-39	HENDRIX, J. M.	8011180228	COMMISSION	HOFFMAN, D. P.	8011140452	50-255
HAKINS, E.	8011060388	27-39	HENDRIX, J. M.	8011180231	COMMISSION	HOFFMAN, D. P.	8011180411	50-255
HAKINS, E. F.	8011180152	27-39	HENDRIE, J. M.	8011210234	COMMISSION	HOFFMAN, D. P.	8011180563	50-155
HAKINS, E. F.	8011030115*	CONTRACT	HENDRIE, J. M.	8011100235	50-219 Q	HOFFMAN, D. P.	8011180236	TOPREC
HAYES, D. W.	8011260424*	50-546 Q	HENDRIE, J. M.	8011110235	50-263 Q	HOFFMAN, D. P.	8011180685	50-255
HAYES, D. W.	8011170204*	50-483 Q	HENRY, J. E.	8011200554*	50-546 Q	HOFFMAN, D. P.	8011180715	50-255
HAYES, D. W.	8011180391*	50-483 Q	HENRY, J. J.	8011120579	PRH	HOFFMAN, D. P.	8011180730	50-255
HAYES, D. W.	8011200553*	50-546 Q	HENSLEY, K. D.	8011120531	70-143	HOFFMAN, D. P.	8011180743	50-255
HAYES, D. W.	8011250062*	50-546 Q	HERBEC, K.	8011120539*	50-320 H	HOFFMAN, D. P.	8011200189	50-155
HAYES, D. W.	8011280237*	50-440 Q	HERBEC, J. O.	8011190285*	50-289 Q	HOFFMAN, D. P.	8011210602	71-325
HAYNES, R. C.	8011200135*	50-460 Q	HERDT, A. R.	8011200430*	50-438 Q	HOFFMAN, D. P.	8011240255	50-155
HAYNES, R. C.	8011200129*	50-460 Q	HERDT, A. R.	8011210186*	50-390 Q	HOFFMAN, D. P.	8011230314	50-155
HAYNES, R. C.	8011050360*	50-528 Q	HERDT, A. R.	8011040310*	50-413 Q	HOFFMAN, D. P.	8011250400	50-155
HAYNES, J. O.	8011200059	50-206 Q	HERDT, A. R.	8011050381*	50-364 Q	HOFFMAN, D. P.	8011250452	50-255
HAYNES, J. O.	8011190026	71-9044	HERDT, A. R.	8011210680*	50-395 Q	HOFFMAN, C. H.	8011140474*	50-367
HAYNES, J. O.	8011190032	71-9094	HERDT, A. R.	8011200390*	50-280 Q	HOFFMAN, C. H.	8011140490*	50-367
HAYNES, J. O.	8011190692	71-6601	HERDT, A. R.	8011200460*	50-416 Q	HOLLAND, P.	8011030605*	50-237
HAYNES, J. O.	8011040437	50-206 B	HERDT, A. R.	8011040345*	50-280 Q	HOLLAND, P.	8011030640*	50-237
HAYNES, R. C.	8011200117*	50-460 Q	HERDT, A. R.	8011040357*	50-261 Q	HOLLAND, P.	8011040312*	50-249
HAYWARD, N.	8011120629	PROJ	HERDT, A. R.	8011040358*	50-390 Q	HOLLAND, P.	8011040321*	50-293
HAILE, A. J.	8011030095	State Prog	HERDT, A. R.	8011210238*	50-390 Q	HOLLAND, P.	8011250368*	50-249
HAILE, A. J.	8011060309	State Prog	HERDT, A. R.	8011260362*	50-230 Q	HOLLAND, P.	8011250568*	50-249
HEAD, W. J.	8011030309	40-7869	HERDT, A. R.	8011210145*	50-424 Q	HOLLINGS, J. O.	8011210264	NUREO
HECHT, L. O.	8011110008	NUREO	HERDT, A. E.	8011170568*	50-413 Q	HOLLODY, D. J.	8011100348*	70-820
HECK, P. B.	8011120475*	50-327 B	HERLICH, D. M.	8011030372	40-8728	HOLCHAY, C. F.	8011170776	REB
HECK, F. M.	8011170549*	PROJ	HERNANDEZ, V. A.	8011110328*	50-302 B	HOLCHAY, C. F.	8011260322	REB
HECK, F. M.	8011170552*	PROJ	HERNANDEZ, V. A.	801120490*	50-302 B	HODD, D.	8011060074	50-329
HEISER, E. R.	8011140530*	50-367 Q	HERNANDEZ, V. A.	8011180589*	50-302 S	HOOKE, D. T.	8011210321	PR
HEIDER, L. H.	8011170783	50-271 Q	HERR, R. K.	8011200096*	50-498 Q	HOPKINS, J. B.	8011210190*	50-263
HEIDER, L. H.	8011120532	50-271 P	HERR, R. K.	8011040103*	QA999	HOPKINS, J. B.	8011200280	50-259
HEIDER, L. H.	8011180362	50-271 P	HERR, R. K.	8011180340*	QA999	HORAN, J. T.	8011260035*	70-182
HEIM, O. E.	8011120065*	27-39	HERRMANN, R. B.	8011170453	50-206 P	HORIN, W. A.	8011280065	50-445
HEISER, D. M.	8011120627	PROJ	HERSCH, M. M.	8011030119	XPORTLIC	HORIN, W. A.	8011280065	50-445
HEISHMAN, R. F.	8011070035	50-282 Q	HERSCH, M. M.	8011030124*	XPORTLIC	HORN, A. J.	8011050353*	50-206
HEISHMAN, R. F.	8011120685	50-266 Q	HERSCH, M. M.	8011200407	50-533 A	HORN, B.	8011120280	50-259
HEISHMAN, R. F.	8011090135	50-305 Q	HERSCH, M. M.	8011200409	50-465 A	HOBBS, C. H.	8011050519*	50-321
HEISHMAN, R. F.	8011100034	50-341 Q	HERSCH, M. M.	8011260442	70-2172	HOBSTON, M. D.	8011210700	50-440

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HOVEY, O K	8011040461*	50-320 P	HUNNICUTT, D H	8011040148*	QA999	JANINEK, M	8011140312	State Prog
HOVEY, O K	8011040369	50-320 P	HUNNICUTT, D H	8011050340*	50-285 Q	JANUSKA, A	8011110034*	50-10 Q
HOVEY, O K	8011200392	50-320 S	HUNNICUTT, D H	8011060602*	50-313 Q	JAUDON, J P	8011060582*	50-313 Q
HOVEY, O K	8011040449	50-320 S	HUNSTAD, A A	8011060488*	50-306 S	JENKINS, B	8011040131*	QA999
HOVEY, O K	8011040434	50-320 S	HUNSTAD, A A	8011060496*	50-306 S	JENKINS, B	8011040118*	QA999
HOVEY, O K	8011040458	50-320 P	HUNSTAD, A A	8011170510*	50-282 R	JENKINS, B	8011040110*	QA999
HOVEY, O K	8011070352	50-320 P	HUNSTAD, A A	8011110341*	50-306 S	JENKINS, O R	8011130223*	50-480 Q
HOVEY, O K	8011050417	50-320 P	HUNSTAD, A A	8011180689*	50-306 S	JENKINS, O R	8011040568*	50-348 Q
HOVEY, O K	8011070288	50-320 P	HUNSTAD, A A	8011260182*	50-306 S	JENKINS, O R	8011210093*	50-327 Q
HOVEY, O K	8011070356	50-320 P	HUNT, B D	8011180378	50-556 Q	JENKINS, O R	8011210137*	50-369 Q
HOVEY, O K	8011120612	50-320 S	HUNT, M D	8011050241*	50-302 Q	JENKINS, R V	8011100407*	50-295 S
HOVEY, O K	8011180413	50-320 P	HUNT, M D	8011260427*	50-424 Q	JENSEN, W L	8011040473*	50-289 T
HOVEY, O K	8011120381	50-320 P	HUNTER, V H	8011060318*	QA999	JENSEN, W L	8011040508*	50-289 T
HOVEY, O K	8011180425	50-320 P	HUNTER, R S	8011110023*	50-315 Q	JERNIGAN, E	8011190329*	50-352 Q
HOVEY, O K	8011120501	50-320 P	HUNTER, R S	8011100394	50-315 P	JERNIGAN, E P	8011100379*	50-213 Q
HOVEY, O K	8011190299	50-320 P	HUNTER, R S	8011140095	50-315 V	JERNIGAN, E P	8011200104*	50-336 Q
HOVEY, O K	8011190483	50-320 P	HUNTER, R S	8011180426	50-315 P	JOHNSON, H O	8011170561*	PROJ
HOVEY, O K	8011230277	50-320 P	HUSEBY, D E	8011140460*	50-317 S	JOHNSON, A D	8011060144*	50-361 Q
HOVEY, O K	8011250304	50-320 P	HUSS, J	8011060306*	40-8743	JOHNSON, P H	8011030280*	50-344 Q
HOVEY, O K	8011240291	50-320 S	HUSS, J	8011170921	40-8743	JOHNSON, A R	8011040674*	50-445 Q
HOVEY, O K	8011240294	50-320 S	HUTTON, J C	8011120337*	50-244 P	JOHNSON, C R	8011070358*	71-669B
HOVEY, O K	8011240311	50-320 S	HYDER, L K	8011060408	PR	JOHNSON, C R	8011070350*	71-669B
HOVEY, O K	8011240315	50-320 P	HYDER, L K	8011060412	PR	JOHNSON, C R	8011070338	71-669B
HOVEY, O K	8011250340	50-320 S	IANNI, P W	8011040232*	TOPREP	JOHNSON, C R	8011180768	71-18
HOVEY, O K	8011250317	50-320 S	IANNI, P W	8011250252*	TOPREP	JOHNSON, A R	8011190289*	50-382 Q
HOWE, P W	8011130201*	50-400 Q	IANNI, P W	8011250292*	TOPREP	JOHNSTON, O W	8011050347*	50-344 Q
HOWE, P W	8011130194*	50-400 Q	IANNI, P W	8011250294*	TOPREP	JOHNSON, C R	8011110632	71-669B
HOWE, P W	8011130179*	50-400 Q	IDRISS, I H	8011100085*	FOIA	JOHNSON, C R	8011190017	71-669B
HOWELL, J C	8011210464*	50-324 Q	IDRISS, I H	8011100077*	FOIA	JOHNSON, W P	8011170583	50-309 Q
HOWELL, J C	8011030275*	70-143	INGRAM, F	8011060195	50-3 H	JOHNSON, J	8011110376	50-293 B
HOWELL, S H	8011130204*	NUREG	INGRAM, F	8011060199	50-309 H	JOHNSON, T. L	8011040491*	50-289 T
HOWLETT, O H	8011210400*	50-336 R	INGRAM, F	8011060704	50-320 H	JOHNS, S J	8011240180	50-155 Q
HOYLE, J C	8011130093	ACRB	INGRAM, F	8011120047	50-309 H	JOHNSON, R W	8011260006	50-344 Q
HOYLE, J C	8011130102	ACRB	INGRAM, F. L	8011180128	50-247 H	JONES, W B	8011050017*	70-2709
HOYLE, J C	8011130097	ACRB	INGRAM, F. L	8011180170	50-247 H	JONES, J E	8011070467*	50-335 P
HOYLE, J C	8011130106	ACRB	IPPOLITO, T A	8009180252	50-237 P	JONES, D W	8011200489*	70-1113
HOYLE, J C	8011130110	50-10 Q	IPPOLITO, T A	8011170946	50-333 F	JONES, R K	8011110196	WASTE HOT
HOYLE, J C	8011130147	ACRB	IPPOLITO, T A	8011190499	50-293 F	JONES, W C	8011040495	50-285 P
HOYLE, J C	8011130116	ACRB	IPPOLITO, T A	8011070370	50-290 Q	JONES, J L	8011030491*	50-269 S
HOYLE, J C	8011130120	ACRB	IPPOLITO, T A	8011070384	50-220 Q	JONES, R C	8011060394	50-289 T
HOYLE, J C	8011130151	ACRB	IPPOLITO, T A	8011070391	50-333 Q	JONES, R C	8011060404*	50-289 T
HOYLE, J C	8011130100	ACRB	IPPOLITO, T A	8011070466	50-331 Q	JONES, J. C	8011030465*	50-270 S
HOYLE, J C	8011130157	ACRB	IPPOLITO, T A	8011070484	50-263 Q	JONES, R. C	8011060394	50-289 T
Hsia, D	8011260307	NUREG	IPPOLITO, T A	8011070516	50-289 Q	JONES, R. C.	8011060404*	50-289 T
HUBBARD, R B	8011250333*	50-454 Q	IPPOLITO, T A	8011070569	50-271 Q	JONES, W C	8011040395	50-285 V
HUBER, S A	8011210026	PR	IPPOLITO, T A	8011070581	50-293 Q	JONES, J H	8011250680*	CONTRACT
HUBILL, H D.	8011250511	50-289 S	IPPOLITO, T A	8011110012	50-249 Q	JONES, J L	8011040508*	50-269 S
HUBSON, S.	8011130152*	50-220 Q	IPPOLITO, T A	8011110548	50-324 Q	JONES, W C	8011040505*	50-285 P
HUBSON, T B	8011180108	50-498 Q	IPPOLITO, T A	8011040686	50-271 F	JONES, W C	8011190131	50-283 Q
HUSTER, L J	8011280224*	50-254 Q	IPPOLITO, T A	8011170849	50-254 F	JONES, J L	8011120608*	50-270 S
HUGHES, J	8011260424*	50-346 Q	IPPOLITO, T A	8011170873	50-237 F	JONES, J L	8011120344*	50-269 S
HUGHES, C	8011120021*	50-320 H	IPPOLITO, T A	8011190701	50-271 P	JONES, W C	8011140127	50-283 P
HUGHES, J	8011030093*	50-440 Q	IPPOLITO, T A	8011190743	50-263 F	JONES, J. L.	8011140374*	50-269 S
HUGHES, J	8011250053*	50-440 Q	IPPOLITO, T A	8011200041	50-271 F	JONES, J. L.	8011180712*	50-270 S
HUGHES, R K	8011030592	50-324 P	IPPOLITO, T A.	8011210722	50-271 P	JONES, W C	8011180643	50-285 R
HUGHES, W S	8011210442	50-266 J	IPPOLITO, T A	8011210739*	50-271 P	JONES, W C	8011190491	50-285 P
HUKILL, H D	8010150484	50-289 Q	IPPOLITO, T A	8011210756*	50-271 P	JONES, E. W	8011140532	50-329 Q
HUKILL, H D	8011030680	50-289 Q	IPPOLITO, T A	8011210239	50-254 F	JONES, J T	8011180893*	50-269 S
HUKILL, H D	8011140289	50-289 Q	IRELAND, C D	8011250169	PR	JONES, J L	8011180722*	50-287 S
HUKILL, H D	8011170791	50-289 Q	ISLEY, T	8011180610*	50-346 S	JONES, W C	8011180452*	50-285 P
HUKILL, H D	8011030501	50-287 I	ISLEY, T	8011140432*	50-346 S	JONES, J L	80111210475*	50-270 S
HUKILL, H D	8011170769	50-289 Q	JACKI, I N	8011130066*	50-286 Q	JONES, J. L.	8011240289*	50-287 S
HUKILL, H D	8011060491	50-289 F	JACKSON, R E	8011140526*	50-367 Q	JONES, J. L.	8011250506*	50-270 S
HUKILL, H D	8011070422	50-289 S	JACKSON, J F	8011140282	NUREG	JONTENTZ, R	8011250063	27-43
HUKILL, H D	8011070507	50-289 R	JACOBSEN, T. V.	8011250531*	50-387 R	JOHNSON, A	8011110469*	TOPREP
HUKILL, H D	8011120505	50-289 P	JACOBS, S B	8011110056	NUREG	JORDAN, M. J	8011190526*	50-10 Q
HUKILL, H D	8011120513*	50-289 P	JACOBS, A	8011030436	CONTRACT	JORDAN, R P	8011200124	REG
HUKILL, H D	8011130395	50-289 P	JAKUBOWSKI, C H	8011250082	PR	JORDAN, M	8011110034*	50-10 Q
HUKILL, H D	8011240151	50-289 P	JANECEK, R. F	8008270372	50-237 P	JORDAN, E. L	8011060300	50-397 A
HUKILL, H D	8011240077	50-289 Q	JANECEK, R. F	8008270375	50-237 P	JORDAN, W B	8011040392	50-443 Q
HUKILL, H D	8011190270	50-289 R	JANECEK, R. F.	8011030437	50-237 P	JORDAN, W B	8011040392	50-443 Q
HUKILL, H D	8011200333	50-289 P	JANECEK, R. F.	8011030507	50-237 P	JORDAN, W B	8011040392	50-443 Q
HUKILL, H D	8011200326	50-289 P	JANECEK, R. F.	8011130192	50-10 P	JORDAN, W B	8011050177	50-443 Q
HUKILL, H D	8011250232	50-289 P	JANECEK, R. F.	8011120413	50-237 Q	JORDAN, H	8011280232	NUREG
HUKILL, H D	8011250458	50-289 P	JANECEK, R. F.	8011030577	50-237 P	JORDAN, W H	8011140040	50-596 Q
HUKILL, H D.	8011260194	50-289 P	JANECEK, R. F.	8011120532	50-237 P	JORDAN, W B	8011110599	PR
HULBERT, H	8011190330	40-8502	JANECEK, R. F	8011170249	50-237 Q	JORDAN, W B	8011110599	PR
HULBERT, H	8011170315	40-8502	JANECEK, R. F	8011110486	50-237 F	JOY, J. M.	8011140029*	50-286 R
HULBERT, H	8011170308	40-8502	JANECEK, R. F	8011100481	50-10 V	JOYNER, J. H	8011170322*	70-882
HULBERT, H	8011170325	40-8502	JANECEK, R. F	8011120492	50-10 V	JOYNER, J	8011030102*	90-275 H
HUMPHREY, J. H	8011030978	40-8502	JANECEK, R. F	8011180419	50-237 P	JOYNER, J. H.	8011070588*	70-135
HUMPHREY, J. H	8011250252*	TOPREP	JANECEK, R. F	8011240374	50-254 P	JOYNER, J. H	8011250121*	70-882
HUMPHREY, J. H	8011250292*	TOPREP	JANINEK, M	8011110595	State Prog	JOYNER, J. H.	8011130329*	70-364
HUMPHREY, J. H	8011250294*	TOPREP	JANINEK, M	8011170528	State Prog	JOYNER, J. H	8011070537*	70-135
HUMSTAD, A A	8011210632*	50-282 S	JANINEK, M.	8011110983	State Prog	JOYNER, J. H	8011100348*	70-820

PERSONAL AUTHOR INDEX

321

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JOYNER, J. H.	8011210297*	70-135	KEPPLER, J. O.	8011060291	50-329 Q	KERRIGAN, J.	8011190389	50-528 A
JULIAN, C. A.	8011130256*	50-327 Q	KEPPLER, J. O.	8011170198	50-483 Q	KERRIGAN, J.	8011170037	50-311 P
JULIAN, C.	8011140316*	50-160 Q	KEPPLER, J. O.	8011030098	50-329 Q	KERRIGAN, J.	8011200163	50-311 P
JORGENSEN, R. H.	8011210505	TOPREP	KEPPLER, J. O.	8011100515	50-155 F	KERRIGAN, J.	8011200350	50-528 A
KAGETSU, T. J.	8011180483	WASTE MGT	KEPPLER, J. O.	8011050391	50-305 Q	KETCHEN, E. Q.	8011040323*	50-416 H
KAHLE, J. B.	8011040051*	70-1201	KEPPLER, J. O.	8011250136	50-373 Q	KETCHEN, E. Q.	8011130310	70-2623
KAHLE, J. B.	8011200489*	70-1113	KEPPLER, J. O.	8011200548	50-546 Q	KETCHEN, E. Q.	8011240197	50-369 H
KAHLE, J. B.	8011200934*	70-27	KEPPLER, J. O.	8011040297	50-461 A	KETCHEN, E. Q.	8011240201	50-369 H
KALIVIANAKIS, N.	8011100436	50-265 S	KEPPLER, J. O.	8011030248	50-358 Q	KETZLACH, N.	8011190125	70-2936
KALIVIANAKIS, N.	8011100400	50-254 S	KEPPLER, J. O.	8011060172	50-10 Q	KEY, W. J.	8011060133*	50-440 Q
KALIVIANAKIS, N.	8011140014	50-254 S	KEPPLER, J. O.	8011260271	50-254 Q	KIDD, G. E.	8011260139	50-289 H
KALIVIANAKIS, N.	8011110186	50-254 R	KEPPLER, J. O.	8011040597	50-331 F	KIMERLING, N.	8011180176*	50-247 H
KALIVIANAKIS, N.	8011100492	50-254 P	KEPPLER, J. O.	8011070282	50-409 Q	KING, T. A.	8011180092*	50-289 H
KALIVIANAKIS, N.	8011180595	50-265 S	KEPPLER, J. O.	8011070235	50-155 Q	KINNEHAN, J. D.	8011130194*	70-2116
KALIVIANAKIS, N.	8011180617	50-265 S	KEPPLER, J. O.	8011070287	50-255 Q	KINNEHAN, J. D.	8011120022*	70-2304
KALIVIANAKIS, N.	8011250354	50-254 S	KEPPLER, J. O.	8011070260	50-440 Q	KINNEHAN, J. D.	8011260037*	70-182
KALIVIANAKIS, N.	8011250343	50-265 S	KEPPLER, J. O.	8011070263	50-282 Q	KINNEHAN, J. D.	8011140677*	40-8412
KALIVIANAKIS, N.	8011250348	50-254 S	KEPPLER, J. O.	8011070266	50-305 Q	KINNEHAN, J. D.	8011140674	40-8412
KALIVIANAKIS, N.	8011250367	50-265 S	KEPPLER, J. O.	8011070270	50-315 Q	KINNEHAN, J. D.	8011210275*	40-8702
KALIMAN, Q.	8011200146	50-320 S	KEPPLER, J. O.	8011070273	50-263 Q	KINNEHAN, J. D.	8011210265	40-8702
KAMMERER, C.	8011030270*	FOIA	KEPPLER, J. O.	8011070278	50-341 Q	KINNEHAN, J. D.	8011130177	70-2116
KAMMERER, C.	8011040382	50-201 Q	KEPPLER, J. O.	8011070281	50-247 Q	KINNEHAN, J. D.	8011120011	70-2304
KANE, W.	8011060151	50-395 P	KEPPLER, J. O.	8011070285	50-10 Q	KINNEHAN, J. D.	8011210689	40-8702
KANE, W. F.	8011060070	50-395 Q	KEPPLER, J. O.	8011070294	50-266 Q	KINNEHAN, J. D.	8011210699*	40-8702
KANE, W. F.	8011060094	50-395 A	KEPPLER, J. O.	8011070297	50-483 Q	KINNEHAN, J. D.	8011260066	70-261
KANE, W. F.	8011060226	50-395 A	KEPPLER, J. O.	8011070301	50-346 Q	KINNEHAN, J. D.	8011260028	70-182
KANE, W. F.	8011060083	50-382 A	KEPPLER, J. O.	8011070304	50-546 Q	KINNEY, W. H.	8011060266	70-820
KANE, W. F.	8011190228	50-395 F	KEPPLER, J. O.	8011070307	50-367 Q	KINNEY, W. H.	8011240454	70-820
KANE, W.	8011030600	50-395 A	KEPPLER, J. O.	8011070310	50-358 Q	KINNEHAN, J.	8011250335	18E
KANE, W.	8011070161	50-395 A	KEPPLER, J. O.	8011070314	50-461 Q	KINTNER, L. L.	8011060223	50-364 A
KANE, W.	8011260246	50-395 A	KEPPLER, J. O.	8011070315	50-331 Q	KINTNER, L. L.	8011060276	50-364 A
KANNARD, J. R.	8011280023	TOPREP	KEPPLER, J. O.	8011120115	50-305 Q	KINTNER, L. L.	8011060089	50-364 A
KAPLAN, A. L.	8011060197	71-9019	KEPPLER, J. O.	8011170557	50-315 Q	KINTNER, L. L.	8011050275	50-341 A
KAPLAN, A. L.	8011060607	70-1113	KEPPLER, J. O.	8011190009	50-409 Q	KINTNER, L. L.	8011120041	50-364 P
KAPLAN, A. L.	8011060215	70-1113	KEPPLER, J. O.	8011190029	50-346 Q	KINTNER, L. L.	8011260244	50-341 F
KAPLAN, A. L.	8011200481*	70-1113	KEPPLER, J. O.	8011190034	50-263 Q	KIPPER, M.	8011040904	50-361 Q
KARNAN, M.	8011190046	50-461 Q	KEPPLER, J. O.	8011190040	50-10 Q	KIRK, W. F.	8011100294	71-3086
KARNAN, M.	8011190050*	50-461 Q	KEPPLER, J. O.	8011190051	50-303 Q	KIRK, O. B.	8011030940*	50-327 S
KARNAN, M.	8011190055*	50-461 Q	KEPPLER, J. O.	8011190057	50-153 Q	KIRK, O. B.	8011040453*	50-327 S
KASPER, A. R.	8011210109	REQD	KEPPLER, J. O.	8011190067	50-266 Q	KIRK, O. B.	8011120428*	50-327 S
KASS, A. W.	8011060109	FOIA	KEPPLER, J. O.	8011190191	50-10 F	KIRK, O. B.	8011120439*	50-327 S
KASTENBERG, W. E.	8011240100	NUREG	KEPPLER, J. O.	8011190220	50-331 Q	KIRK, O. B.	8011120488*	50-327 S
XAUFMAN, H. C.	8011240498	RES	KEPPLER, J. O.	8011190501	40-2061	KIRK, O. B.	8011210497*	50-327 S
KAY, J. A.	8011200329	50-29 P	KEPPLER, J. O.	8011190510	40-2061	KIRK, O. B.	8011210574*	50-327 S
KEARNEY, J. J.	8011030068	PR	KEPPLER, J. O.	8011190522	40-2061	KIRK, O.	8011250390*	50-327 S
KEARNEY, J. J.	8011030063	PR	KEPPLER, J. O.	8011190540	40-2061	KIRSCH, D. F.	8011200135*	50-460 Q
KEELER, C. D.	8011050541	RES	KEPPLER, J. O.	8011190597	40-2061	KIRSCH, D. F.	8011200129*	50-460 Q
KEENEYNE, K. D.	8011190260	40-1341	KEPPLER, J. O.	8011200544	40-2061	KISTER, H. B.	8011130152*	50-220 Q
KEHRET, D.	8011100439*	50-265 S	KEPPLER, J. O.	8011190578	40-2061	KISTER, H. B.	8011130066*	50-266 Q
KEITH, R. R.	8011180614*	50-272 Q	KEPPLER, J. O.	8011240102	40-2061	KISTER, H.	8011210715*	50-266 Q
KEITH, R. R.	8011100531*	50-289 Q	KEPPLER, J. O.	8011240121	40-2061	KLEINSORGE, H. P.	8011210680*	50-395 Q
KEITH, R. R.	8011210402*	50-289 Q	KEPPLER, J. O.	8011240126	40-2061	KLOEPPING, R. J.	8011210333	PR
KEITH, R. R.	8011200131*	50-219 Q	KEPPLER, J. O.	8011240132	40-2061	KNAPP, P. J.	8011190632*	50-29 Q
KEITH, R. R.	8011120140	PR	KEPPLER, J. O.	8011240141	40-2061	KNAPP, P. J.	8011170946*	50-219 Q
KEITH, R. R.	8011200395*	SECY	KEPPLER, J. O.	8011170112	50-266 P	KNAPP, P. J.	8011050521*	70-133
KELLEY, W. D.	8011170771*	QA999	KEPPLER, J. O.	8011180075	50-10 H	KNAPP, P. J.	8011070305*	70-1100
KELLEY, W. D.	8011170861*	QA999	KEPPLER, J. O.	8011180086	50-10 H	KNAPP, P. J.	8011100460*	70-1143
KELLEY, D. L.	8011050340*	50-265 Q	KEPPLER, J. O.	8011180111	50-10 H	KNAPP, P. J.	8011070332*	70-398
KELLEY, W. D.	8011060307*	QA999	KEPPLER, J. O.	8011180115	50-10 H	KNAPP, P. J.	8011130060*	50-311 Q
KELLOOO, P. J.	8011060168*	50-364 Q	KEPPLER, J. O.	8011180120	50-10 H	KNAPP, P. J.	8011240459	11E
KELLOOO, P. J.	8011050268*	50-261 Q	KEPPLER, J. O.	8011180124	50-10 H	KNAPP, P. J.	8011240468	50-317 S
KELLOOO, P. J.	8011040319*	50-324 Q	KEPPLER, J. O.	8011180127	50-10 H	KNECHT, W. L.	8011170552*	PROJ
KELLOOO, P. J.	8011210431*	50-261 Q	KEPPLER, J. O.	8011180132	50-10 H	KNICELEY, J. R.	8011060699*	50-116 Q
KELLY, R. B.	8011060239*	QA999	KEPPLER, J. O.	8011180134	50-10 H	KNIEL, K.	8011190035*	40-8027
KEMPER, J. S.	8011190307*	50-352 Q	KEPPLER, J. O.	8011180137	50-10 H	KNIIGHTON, O. W.	8011140471*	50-367 Q
KEMPER, J. S.	8011140396	50-352 S	KEPPLER, J. O.	8011180141	50-10 H	KNIIGHT, J. P.	8011140494*	50-367 Q
KEMPER, J. S.	8011180497	50-277 P	KEPPLER, J. O.	8011180143	50-10 H	KNIIGHT, J. P.	8011140538*	50-367 Q
KENDIQ, J. F.	8011190068	1&C	KEPPLER, J. O.	8011180146	50-10 H	KNIIGHT, J. P.	8011050405*	50-395 A
KENNA, W. B.	8011130392*	70-143	KEPPLER, J. O.	8011180175	50-10 H	KNIIGHTON, O. W.	8011100287	MISC
KENNA, W. B.	8011040039*	70-1201	KEPPLER, J. O.	8011180187	50-10 H	KNIIGHT, P. F.	8011240101	NUREG
KENNA, W. B.	8011200489*	70-1113	KEPPLER, J. O.	8011200539	50-10 Q	KNIIGHT, J. P.	8011190751*	50-443 Q
KENNA, W. B.	8011210462*	50-324 Q	KEPPLER, J. O.	8011210759*	50-546 A	KNOP, R. C.	8011030111*	50-329 Q
KENNA, W. B.	8011200529	70-27	KEPPLER, J. O.	8011240018	70-8	KNOP, R. C.	8011060292*	50-329 Q
KENNA, W. B.	8011030272	70-143	KEPPLER, J. O.	8011260416	50-346 Q	KNOP, R. C.	8011200214*	50-461 Q
KENNA, W. B.	8011030260	50-321 Q	KEPPLER, J. O.	8011210730	50-305 Q	KNOP, R. C.	8011200160*	50-341 Q
KENNA, W. B.	8011040030	70-1201	KEPPLER, J. O.	8011280199	50-186 Q	KNOP, R. C.	8011250286*	50-461 Q
KENNA, W. B.	8011130377	70-143	KEPPLER, J. O.	8011280204	50-484 Q	KNOTT, J. B.	8011210279	50-395 Q
KENNA, W. B.	8011200477	70-1113	KEPPLER, J. O.	8011280214	70-925	KNOTT, J. B.	8011210285*	50-395 Q
KENNA, W. B.	8011210439	50-324 Q	KERLIN, T. W.	8011070472	50-336 P	KNOTT, J. B.	8011210285*	50-395 Q
KENNA, W. B.	8011120609	50-293 R	KERLIN, T. W.	8011070478*	50-336 P	KOBORI, L.	8011060371*	70-734
KENNY, T.	8011210715*	50-286 Q	KERR, O. W.	8011120565*	State Prog	KOCH, L. J.	8011030070	50-461 S
KENNY, T. J.	8011110364	50-247 S	KERR, O. W.	8011170093	40-8311	KOCH, L. J.	8011190483*	50-461 Q
KENMORTHY, L. D.	8011170721	NUREG	KERR, O. W.	8011120690	State Prog	KOCH, L. J.	8011040539*	50-461 S
KEPPLER, J. O.	8011070600*	FOIA	KERRIGAN, J.	8011060986	50-328 A	KOCH, L. J.	8011200248	50-461 K
KEPPLER, J. O.	8007280363	PT9		8011040619	50-311 F			

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KOCHER, D C	8011170780	RES	LEE, E W K	8011200294*	50-329 Q	LITTLE, W S	8011070040*	50-282 Q
KOCHER, R.	8011110302*	50-346 S	LEE, K W	8011280232	NUREQ	LITTLE, W S	8011200007*	50-331 Q
KOESTER, O L	8011170194	50-482 S	LEE, O R	8011280035*	50-267 Q	LITTLE, B H	8011100037*	50-341 Q
KOESTER, O L	8011120582	50-482 S	LEE, R L	8011200214*	50-461 Q	LITTLE, W S	8011050153*	50-282 Q
KOESTER, O L	8011140518	50-482 S	LEE, R L	8011280237*	50-440 Q	LITVACK, S M	8011070316	50-413 H
KOESTER, O L	8011200034*	50-482 Q	LEE, T D.	8011130409*	70-143	LIU, J. S. K.	8011100471	NUREQ
KOESTER, O L	8011040321	50-482 S	LEES, E A.	8011040262*	0A999	LIVERMAN, J. L.	8011100087*	50-10 P
KOESTER, O L	8011230287	50-482 H	LEIBY, A. C.	8011180435	50-285 P	LIVERMORE, H. H.	8011250286*	50-461 Q
KOHLER, J E	8011240084*	50-295 Q	LEMPGES, T E	8011070380	50-220 S	LOFF, R	8011170140*	CONTRACT
KONKLIN, J E	8011060133*	50-440 Q	LEMPGES, T E	8011050448	50-220 V	LONG, R L	8011040461*	50-320 P
KONKLIN, J E	8011060251*	50-440 Q	LEMPGES, T E	8011140332	50-220 R	LONG, F. J.	8011030753*	50-395 Q
KONKLIN, J E	8011040300*	50-346 Q	LEMPGES, T E	8011180459	50-220 P	LONG, F. J.	8011030747	50-395 Q
KONOPINSKI, V J	8011120091	PR	LENAHAN, J J	8011210368*	50-348 Q	LONG, D Q	8011120345	TORREP
KOPACZ, J J	8011100406*	50-254 S	LESSOR, L C	8011210499	50-298 S	LONGSHINE, D E	8011030488	NUREQ
KORNER, R L	8011060572*	50-286 P	LESSOR, L C	8011210364	50-298 S	LOMHIS, J S	8011120327	RECQD
KOSIK, L.	8011180049	50-398 Q	LESSOR, L C	8011140018	50-298 R	LOMHIS, J S	8011210077	RECQD
KOSIK, L.	8011180049	50-398 Q	LESSOR, L C	8011210488	50-298 S	LOPRESTI, D A	8011120110	PR
KOTSENA, H O	8011280077*	50-334 P	LESSY, R P	8011040458	50-443 Q	LORD, P. H	8011170297*	70-882
KOUNTANTIS, B	8011210471	50-254 Q	LESSY, R P	8011100629	50-443 Q	LORD, P. H	8011170284*	70-882
KOUNTANTIS, B	8011210474*	50-254 Q	LESSY, R P	8011130301	50-482 Q	LORD, P. H	8011170278*	70-882
KOUTS, H. J C	8011140176	NUREQ	LESSY, R P	8011190746	50-443 Q	LORD, P. H	8011170266*	70-882
KOVALSKI, B	8011170048*	50-320 H	LESSY, R P	8011250650	50-443 Q	LOWRY, L M	8011170730	NUREQ
KRAUSE, L	8011060073	50-458 H	LENAHAN, J C	8011240428	NUREQ	LOWRY, R C	8011180454	NUREQ
KRAWCZAK, A T	8011230375*	50-304 S	LEVINE, J	8011250033*	50-471 Q	LUBENAU, J. D	8011120561	State Proj
KROON, J C	8011120322	RECQD	LEWIS, M. I	8011100253*	50-320 H	LUBENAU, J. D	8011190058	I&E
KROON, J. C	8011210062	RECQD	LEWIS, R C	8011050231*	50-302 Q	LUBENAU, J. D	8011190068	I&E
KUCHERLAPTI, R	8011230086	PR	LEWIS, R C	8011060160*	50-364 Q	LUCC, J. E.	8011170473	50-204 P
KUEHN, J L	8002070263	50-255 P	LEWIS, R C	8011050507	50-327 Q	LUEBKE, E A	8011060395	50-219 Q
KUEHN, J L	8004110308	50-155 P	LEWIS, R C	8011050564*	50-321 Q	LUMB, R F	8011050155	PR
KUSHNER, W L	8011070558*	70-135	LEWIS, R C.	8011060136*	50-269 Q	LUNDVALL, A E	8011030926	50-317 V
KUSHNER, W L	8011210297*	70-135	LEWIS, R C	8011130248*	50-327 Q	LUNDVALL, A E	8011030822	50-317 P
KUZMYCZ, O	8011140689	50-267 P	LEWIS, R C	8011050261*	50-261 Q	LUNDVALL, A E	8011170111	50-317 Q
LA ROCHE, O	8011140309	NUREQ	LEWIS, R C.	8011040541	50-393 Q	LUNDVALL, A E.	80111260056	50-317 Q
LACEY, W S.	8011030484*	50-334 S	LEWIS, R C.	8011040313	50-324 Q	LUNDVALL, A E	8011050416	50-317 P
LACEY, W S.	8011120354*	50-334 S	LEWIS, R C.	8011050273	50-348 Q	LUNDVALL, A E	8011050328	50-317 P
LACEY, W S	8011120447*	50-334 S	LEWIS, R C.	8011060263	50-321 Q	LUNDVALL, A E	8011050488	50-317 P
LACEY, W S.	8011240301*	50-334 S	LEWIS, R C	8011060803	50-335 Q	LUNDVALL, A E	8011050506	50-317 P
LACEY, W S	8011250520*	50-334 S	LEWIS, R C	8011050290	50-344 Q	LUNDVALL, A E	8011100045	50-317 R
LACEY, W S	8011250470*	50-334 S	LEWIS, R C	8011140313	50-160 Q	LUNDVALL, A E	8011200148	50-317 Q
LACEY, W S.	8011260186*	50-334 S	LEWIS, R C.	8011170056	50-302 Q	LUNDVALL, A E	8011140201	50-317 P
LADD, D R	8011100322	50-387 Q	LEWIS, R C	8011170391	50-335 Q	LUNDVALL, A E	8011140208	50-317 P
LAFLEUR, J D.	8011120687	SECY	LEWIS, R C	8011210429	50-261 Q	LUNDVALL, A E	8011140205	50-317 P
LAFLEUR, J D.	8011200139*	50-328 A	LEWIS, L.	8011050220	PR	LUNDVALL, A E	8011240134	50-317 P
LAOTIEHEKI, J S	8011060490*	50-317 S	LEWIS, R C	8011050247	50-261 Q	LUNDVALL, A E	8011250307	50-317 P
LAOTIEHEKI, J S	8011140460*	50-317 S	LEWIS, R C	8011060117	50-269 Q	LUNDVALL, A E.	8011210291	50-317 P
LAOTIEHEKI, J S	8011230363*	50-318 S	LEWIS, R C.	8011060153	50-364 Q	LUTA, V R.	8011060521*	50-320 H
LAQNHABING, R	8011130407	50-275 H	LEWIS, R C	8011050222	50-302 Q	LUTA, V R.	8011180642	50-320 P
LAHEY, R. T	8011050344	NUREQ	LEWIS, R C	8011050556	50-321 Q	LUTE, F. J.	8011210037*	CONTRACT
LAHEY, R. T	8011170393	NUREQ	LEWIS, R C.	8011130232	50-327 Q	LYNCH, M. D.	8011140476*	50-367 Q
LAINAS, Q	7910300350	50-255 P	LEWIS, R C	8011200464	50-302 Q	LYNCH, M. D	8011140479*	50-367 Q
LAINAS, Q C	8011060079	50-29 F	LEWIS, M. I	8011210007	PR	LYNCH, D.	8011140497*	50-367 Q
LAINAS, Q C	8011210443	50-250 P	LEX, B L	8007240182	50-424 S	LYNCH, M. D	8011140505*	50-367 Q
LAINAS, Q C	8011170728	50-155 P	LI, C Y	8011060210	50-317 P	LYNCH, M. D	8011140512*	50-367 Q
LAMAH, J T	8011200197	40-8714	LIBRIZZI, F. P.	8011030565	50-272 S	LYNCH, M. D	8011140517*	50-367 Q
LAMASTER, K F	8011140050*	50-302 S	LIBRIZZI, F. P	8011060416	50-272 V	LYNCH, M. D.	8011170343*	50-367 A
LAMB, H R.	8011180435	50-285 P	LIBRIZZI, F. P	8011250237	50-311 Q	LYNCH, M. D.	8011070169*	50-367 Q
LANDRY, E. J.	8011280007	50-289 H	LIBRIZZI, F. P	8011040433	50-272 S	MACARTHUR, T. C	8011260129*	40-672
LANDSMAN, R. B	8011180391*	50-483 Q	LIBRIZZI, F. P	8011200291	50-272 S	MACARTHUR, T. C.	80112100373*	50-309 Q
LANDSMAN, R. B	8011200160*	50-341 Q	LIBRIZZI, F. P.	8011250296	50-272 P	MACARTHUR, T. C	8011210736*	50-213 Q
LANDSMAN, R. H.	8011140542	50-445 H	LIBRIZZI, F. P	8011280035	50-272 S	MACARTHUR, T. C.	8011060620*	70-1113
LANDSMAN, R. H	8011140542	50-445 H	LICCIARDO, R B	8011050585	50-305 P	MACARTHUR, T. C	8011100098*	40-8349
LANG, E A.	8011280132	PROJ	LICHTENBERGER	8011070489*	70-1100	MACARTHUR, T. C	8011100111*	50-259 Q
LANGSTON, N. E.	8011040426	50-313 I	LICHTENBERGER	8011170374*	0A999	MACARTHUR, T. C	8011100111*	50-259 Q
LANNING, D. D	8011190081	NUREQ	LILLEY, M P	8011120337*	50-244 P	MACARTHUR, T. C	8011040568*	50-348 Q
LAMPHER, L C	8011040453	50-275 Q	LIN, J C	8011240466	RES	MACARTHUR, T. C.	8011210415*	50-327 Q
LAMPHER, L C.	8011040455	50-275 Q	LINDER, F	8011190647*	50-409 Q	MACDONALD, C. E	8011180013*	71-9091
LASLO, H H	8011210461	50-247 H	LINDER, F.	8011040179	50-409 P	MACDONALD, C. E.	8011060233	71-397
LATHAM, S. B	8011040411	50-322 Q	LINDER, F.	8011120340	50-409 V	MACDONALD, C. E.	8011060240*	71-397
LAUSEN, M	8011120087*	50-369 Q	LINDER, F.	8011040410	50-409 P	MACDONALD, C. E	8011060354	71-6698
LAUDIO, B.	8011070851	FOIA	LINDER, F.	8011120582	50-409 F	MACDONALD, C. E	8011060362*	71-6698
LAUTON, K. D	8011120030	40-8084	LINDER, F.	8011120397	50-409 F	MACDONALD, C. E	8011030546	71-102
LAVERTY, J. H	8011050207	50-387 Q	LINDER, F.	8011170502	50-409 R	MACDONALD, C. E	8011100502	71-3086
LAVERTY, J. H	8011260010	50-387 Q	LINDER, F.	8011180684	50-409 S	MACDONALD, C. E	8011100497	71-3939
LAWRENCE, L. I	8011210491*	50-298 S	LINDER, F.	8011290523	50-409 S	MACDONALD, C. E	8011030201	71-6668
LAZARUS, H. J	8011280692*	50-309 Q	LINDER, F.	8011240358	50-409 A	MACDONALD, C. E.	8011030207*	71-6668
LAZO, R H	8011250984	50-133 Q	LINDHOLM, R H.	8011050057	PR	MACDONALD, C. E	8011030213	71-9057
LEAR, O. E	8010020309	50-364 A	LINEHAN, J	8011170352	40-8681	MACDONALD, C. E	8011030220*	71-9057
LEBERSTEIN, J. H	8011040014*	50-281 P	LINERMAN, J. J.	8011060056	40-299	MACDONALD, C. E.	8011030226	71-248
LEBLAND, J. V	8011170840*	0A999	LINERMAN, J. J.	8011190037	40-3453	MACDONALD, C. E.	8011030232*	71-248
LEBO, C D.	8011040170	CONTRACT	LINERMAN, J. J.	8011120645	40-3453	MACDONALD, C. E.	8011120602	71-6679
LEBO, C. D	8011200188	CONTRACT	LINENBERGER, O	8011170908	50-466 Q	MACDONALD, C. E	8011170581	71-164
LEBOEUF, R. J	8011180435	50-285 P	LINENBERGER, O.	8011290010	50-466 Q	MACDONALD, C. E.	8011170582	71-121
LEE, A. J.	8011200134*	50-245 Q	LINZEY, H. T	8011060104*	50-289 H	MACDONALD, C. E.	8011170584*	71-121
LEE, E. H. K.	8011260364*	50-440 Q	LIPLESE, M. I.	8011200340	50-443 Q	MACDONALD, C. E	8011170883	71-3939
LEE, E. H. K.	8011030111*	50-329 Q	LIPLESE, M. I.	8011200341*	50-443 Q	MACDONALD, C. E	8011170888*	71-3939

PERSONAL AUTHOR INDEX

323

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MACDONALD, C. E.	8011130081	71-382	MANN, M.	8011140378	50-366 S	MAS, P. J.	8011120110	PR
MACDONALD, C. E.	8011130085*	71-382	MANN, M.	8011180658	50-366 S	MASON, J. D.	8011250120	PR
MACDONALD, C. E.	8011180407	71-400	MANN, M.	8011190270	50-321 R	MASRI, S. F.	8011280231	NUREQ
MACDONALD, C. E.	8011180415*	71-400	MANN, M.	8011190392	50-321 S	MATERS, B. R.	8011170515	50-341 A
MACDONALD, C. E.	8011180423	71-395	MANN, M.	8011190405	50-321 S	MATHEWS, E. R.	8011050394*	50-305 Q
MACDONALD, C. E.	8011180429*	71-395	MANN, M.	8011190417	50-321 S	MATHEWS, E. R.	8011210732*	50-305 Q
MACDONALD, C. E.	8011180367	71-3026	MANN, M.	8011200281	50-366 S	MATHEWS, E. R.	8011210738*	50-305 Q
MACDONALD, C. E.	8011180845	71-6273	MANN, M.	8011280360	50-321 S	MATHEWS, E. R.	8011030320	50-305 P
MACDONALD, C. E.	8011180846*	71-6273	MANSER, H. C.	8011130387*	70-143	MATHEWS, E. R.	8011040532	50-305 P
MACDONALD, C. E.	8011200271	71-3026	MANSER, H. C.	8011050048	70-143	MATHEWS, E. R.	8011040404	50-305 P
MACDONALD, C. E.	8011200336	71-9141	MANSER, H. C.	8011060409	70-143	MATHEWS, E. R.	8011040428	50-305 P
MACDONALD, C. E.	8011200339	71-6294	MANSER, H. C.	8011210360	70-143	MATHEWS, E. R.	8011140022	50-305 R
MACDONALD, C. E.	8011190749	71-6386	MANSER, H. C.	801120296	70-143	MATHEWS, E. R.	8011180670	50-305 B
MACDONALD, C. E.	8011190772*	71-6386	MANSER, H. C.	8011070432	70-143	MATHEWS, E. R.	8011210377	50-305 P
MACDONALD, C. E.	8011210743	71-398	MANSER, H. C.	801120295	70-143	MATSON, V.	8011140690*	SECY
MACDONALD, C. E.	8011260334	71-9070	MANSER, H. C.	8011200510	70-143	MATSON, V.	8011060335	XPORTRIC
MACDONALD, C. E.	8011260340*	71-9070	MANSER, H. C.	8011180567	70-143	MATSON, V.	8011060360*	XPORTRIC
MACDONALD, C. E.	8011250639	71-3	MAR, C. R.	8011120564*	50-409 F	MATSON, V.	8011050055	XPORTRIC
MACDONALD, C. E.	8011250644*	71-3	MAR, C. R.	8011180528*	50-320 H	MATSON, V.	8011260312	XPORTRIC
MACHALINSKI, H.	8011120065*	27-39	MARCHETTI, A.	8011110672	XPORTRIC	MATTHEWS, C. H.	8011030438*	CONTRACT
MACHON, R. D.	8011040470	50-293 S	MARCHAL, J.	8011110691	XPORTRIC	MATTIA, J. C.	8011170634*	50-352 Q
MACHON, R. D.	8011110043	50-293 S	MARCHAL, J.	8011110697	XPORTRIC	MATTIA, J. C.	8011190329*	50-352 Q
MACHON, R. D.	8011050299	50-293 S	MARCHAL, J.	8011107119	XPORTRIC	MATTIA, J. C.	8011100332*	50-352 Q
MACHON, R. D.	8011060483	50-293 S	MARCHAL, J.	8011120002	XPORTRIC	MATTIA, M. J.	8011030115*	CONTRACT
MACHON, R. D.	8011120920	50-293 S	MARCHAL, J.	8011200219	XPORTRIC	MATTIMOE, J. J.	8011100017	50-312 Q
MACHON, R. D.	8011180638	50-293 S	MARITTI, E. J.	8011070584*	FOIA	MATTIA, M. J.	8011060296*	CONTRACT
MACHON, R. D.	8011170420	50-293 S	MAR, C. E.	8011060296*	CONTRACT	MATTIA, M. J.	8011040174*	CONTRACT
MACHON, R. D.	8011180427	50-293 R	MAR, C. E.	8011170730	NUREQ	MATTIMOE, J. J.	8011030340	50-312 P
MACHON, R. D.	8011190407	50-293 S	MARRANZINO, A.	8011120657	71-382	MATTIMOE, J. J.	8011040208	50-312 P
MACHON, R. D.	8011190442	50-293 S	MARSH, R. J.	8011030753*	50-395 Q	MATTIMOE, J. J.	8011190201	50-312 Q
MACHON, R. D.	8011210516	50-293 S	MARSHALL, J. A.	8011240010	40-8584	MATTIMOE, J. J.	8011030615	50-312 B
MACHON, R. D.	8011040468*	50-219 R	MARSHALL, P. E.	8011250076	PR	MATTIMOE, J. J.	8011120478	50-312 P
MACHON, R. D.	8011170793	COMMISSION	MARSHALL, W. H.	8011180166	50-329 Q	MATTIMOE, J. J.	8011110192	PR
MACHON, R. D.	8011260069*	50-320 Q	MARTER, N. R.	8011100310*	50-320 H	MATTIA, M. J.	8011100033*	CONTRACT
MACHON, R. D.	8011130348*	70-371	MARTENSEN, W. P.	8011030280*	50-344 Q	MATTIMOE, J. J.	8011120416	50-312 P
MADDOX, B. O.	8011040606*	50-327 S	MARTIN, W. J.	8011170309*	70-882	MATTIMOE, J. J.	8011120456	50-312 P
MADDOX, B. O.	8011180633*	50-327 S	MARTIN, W. J.	8011170322*	70-882	MATTIA, M. J.	8011130330	50-312 Q
MADDOX, B. O.	8011250403*	50-327 S	MARTIN, W. O.	8011170305*	70-882	MATTIA, M. J.	8011170113*	CONTRACT
MADSEN, O. L.	8011050393	50-298 Q	MARTIN, W. O.	8011070352*	70-135	MATTIA, M. J.	8011250680*	CONTRACT
MADSEN, O. L.	8011050337	50-285 Q	MARTIN, W. O.	8011100369*	50-244 Q	MATTIMOE, J. J.	8011120370	50-312 V
MADSEN, O. L.	8011060093	50-298 Q	MARTIN, W. O.	8011180443*	50-272 Q	MATTIA, M. J.	8011170364*	CONTRACT
MADSEN, O. L.	8011060670	50-313 Q	MARTIN, W. O.	8011180529*	50-354 Q	MATTIMOE, J. J.	8011180635	50-312 P
MADSEN, O. L.	8011260079*	50-267 Q	MARTIN, W. O.	8011250110	70-882	MATTIA, M. J.	8011200194*	CONTRACT
MADSEN, O. L.	8011280032	50-267 Q	MARTIN, R. D.	8011050241*	50-302 Q	MATTIA, M. J.	8011210104*	CONTRACT
MADSEN, O. L.	8011190631	50-285 Q	MARTIN, R. D.	8011060149*	50-269 Q	MATTIA, M. J.	8011280702*	CONTRACT
MADSEN, O. L.	8011260105	50-298 Q	MARTIN, O. R.	8011030151*	MISC	MATTIMOE, J. J.	8011260154	50-312 Q
MADSEN, O. L.	8011260073	50-267 Q	MARTIN, T. T.	8011100334*	50-271 Q	MATTIA, M. J.	8011260135*	CONTRACT
MADSEN, O. L.	8011110228	50-313 Q	MARTIN, T. J.	8011050119*	50-354 S	MATTIOX, A.	8011210345	PR
MADSEN, O. L.	8011260045	50-298 Q	MARTIN, W. O.	8011100381	50-333 Q	MAURIN, L. V.	8011210511	50-382 A
MADSEN, O. L.	8011260272	50-313 Q	MARTIN, W. O.	8011130321	70-364	MAY, E. L.	8011140052*	50-29
MADSEN, O. L.	8011210694*	10CFR	MARTIN, W. O.	8011130341	70-371	MAY, T. J.	8011250359	50-293 I
MADSEN, O. L.	8011200452*	10CFR	MARTIN, W. O.	8011100303	50-199 Q	MAYER, L. O.	8011030396	50-263 P
MADSEN, O. L.	8011120405	50-356 H	MARTIN, W. O.	8011070534	70-135	MAYER, L. O.	8011030435	50-263 V
MADSEN, O. L.	8011140008	50-237 S	MARTIN, W. O.	8011100329	70-820	MAYER, L. O.	8011040122	50-282 V
MADSEN, O. L.	8011250334*	50-249 S	MARTIN, R.	8011060804*	50-335 Q	MAYER, L. O.	8011030467	50-282 Q
MAHONEY, R. C.	8011030443*	CONTRACT	MARTIN, T. T.	8011100350*	50-271 Q	MAYER, L. O.	8011030597	50-263 S
MAYER, J. E.	8011040384	50-244 H	MARTIN, T. T.	8011250652*	50-309 Q	MAYER, L. O.	8011040486	50-306 S
MAYER, J. E.	8011040237	50-244 P	MARTIN, L. E.	8011040674*	50-445 Q	MAYER, L. O.	8011060494	50-306 P
MAYER, J. E.	8011040459	50-244 S	MARTIN, R. D.	8011050278*	50-348 Q	MAYER, L. O.	8011120333	50-263 P
MAYER, J. E.	8011060447*	50-244 P	MARTIN, W. O.	8011210280	70-135	MAYER, L. O.	8011130411	50-263 P
MAYER, J. E.	8011120335	50-244 P	MARTIN, W. O.	8011260064	50-320 Q	MAYER, L. O.	8011170217	50-282 P
MAYER, J. E.	8011170200*	50-244 P	MARTIN, R.	8011170066*	50-302 Q	MAYER, L. O.	8011110331	50-306 P
MAYER, J. E.	8011120399	50-244 Q	MARTIN, R. D.	8011170399*	50-335 Q	MAYER, L. O.	8011140263	50-282 P
MAYER, J. E.	8011140103	50-244 P	MARTIN, L. E.	8011190289*	50-382 Q	MAYER, L. O.	8011170508	50-282 P
MAYER, J. E.	8011200274*	50-244 P	MARTIN, W. O.	8011070541	70-135	MAYER, L. O.	8011180248	50-263 P
MAYER, J. E.	8011180668	50-244 P	MARTIN, W. O.	8011100360	50-244 Q	MAYER, L. O.	8011180580	50-306 S
MAKPEACE, J. H.	8011030691*	50-247 S	MARTIN, W. O.	8011180439	50-272 Q	MAYER, L. O.	8011170802	50-282 P
MAKPEACE, J. H.	8011180664*	50-247 S	MARTIN, W. O.	8011170259	70-882	MAYER, L. O.	8011170535	50-263 P
MAKPEACE, J. H.	8011180679*	50-247 S	MARTIN, J. B.	8011200378	50-10 P	MAYER, L. O.	8011210449	50-263 P
MAKPEACE, J. H.	8011250377	50-272 Q	MARTIN, R. E.	8011060169	50-313 P	MAYER, L. O.	8011210628	50-282 P
MALAFEE, V.	8011070199*	50-237 T	MARTIN, W.	8011180810	50-344 S	MAYER, L. O.	80111210482	50-263 P
MALARD, J. C.	8011170701*	PR	MARTIN, J. B.	8011200611	27-39	MAYER, L. O.	8011210484	50-282 P
MALLORY, K.	8011170808*	50-247 P	MARTIN, D. E.	8011180284	40-8745	MAYER, L. O.	8011250410	50-282 P
MALLORY, C. W.	8010310152	71-9086	MARTIN, P. E.	8011190708	NUREQ	MAYER, L. O.	8011260181	50-306 P
MALMROB, H. H.	8011030280*	50-344 Q	MARTIN, T. T.	8011100376	50-293 S	MAYER, L. O.	8011280063	50-282 P
MALMROB, H. H.	8011050347*	50-344 Q	MARTIN, L. Z.	8011180056	50-289 H	MAYER, L. O.	8011280066*	50-282 P
MALONEY, O. P.	8011200005	50-315 Q	MARTIN, T. J.	8011190487	50-354 S	MCCABE, E. C.	8011280176*	50-220
MALTESE, H. J.	8011070290	50-333 F	MARTIN, T. T.	8011200155	50-271 S	MCCABE, E. C.	8011130113*	50-34
MANATALA, H. K.	8011110002	REB	MARTIN, R. E.	8011180156	50-282 F	MCCABE, E. C.	8011190329*	50-352
MANCUBO, F.	8011210592	NUREQ	MARTIN, D.	8011210432	50-361 S	MCCABE, E. C.	8011210395*	50-387
MANGLER, J. W.	8011100215	50-282 P	MARTIN, T. J.	8011190512	50-354 S	MCCABE, E. C.	8011190254*	50-277
MANIK, A.	8011180180*	50-320 H	MARTORE, J. A.	8011060174	50-416 F	MCCABE, E. C.	8011260446*	50-277
MANN, M.	8011100217	50-321 S	MARTORE, J. A.	8011030735	50-416 F	MCCABE, E. C.	8011250675*	50-317
MANN, M.	8011120445	50-366 S	MARTORE, J. A.	8011030741	50-416 A	MCCABE, E. C.	8011180810	50-344
MANN, M.	8011120499	50-366 S	MARTORE, J. A.	8011170038	50-416 F	MCCABE, E. C.	8011110364	50-247

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MCCABE, E. C.	8011240459	50-277 B	MENAHARA, A. E.	8011180596*	50-244 R	MILLS, L. M.	8011040090	50-239 Q
MCCABE, E. C.	8011240468	50-317 B	MENHILL, W. H.	8011060278*	GA999	MILLS, L. M.	8011040140	50-239 Q
MCCABE, E. C.	8011280342	50-334 B	MENHILL, W. H.	8011170388*	GA999	MILLS, L. M.	8011200411*	50-438 Q
MCCALLISTER, P.	8011140574*	50-367 Q	MCPHAIL, P. C.	8011200819*	70-143	MILLS, L. M.	8011210144*	50-390 Q
MCCALLISTER, P.	8007290759	50-329 A	MCPHAIL, J. E.	8011140315*	State Prog	MILLS, L. M.	8011130119	50-239 Q
MCCONNAUGHAY	8011110812	PROJ	MCQUEEN, D. J.	8011180204	FOIA	MILLS, L. M.	8011140271	50-327 Q
MCCORKLE, O. W.	8002110367	70-1027	MCREDY, R.	8011120401*	50-244 Q	MILLS, L. M.	8011110699	50-390 Q
MCCORKLE, O. W.	8011040377	70-1257	MEDLOCK, R. L.	8011100418	40-8452	MILLS, L. M.	8011210078*	50-327 Q
MCCORKLE, O. W.	8011040191	50-371 F	MEDLOCK, R. L.	8011230699	CONTRACT	MILLS, L. M.	8011110162	PR
MCCOY, L. C.	8011040219*	50-361 A	MEINERT, D. L.	8011140434*	50-438 A	MILLS, L. M.	8011210209*	50-390 Q
MCCOY, J. J.	8011120360*	50-237 P	MEINERT, D. L.	8011140438*	50-438 A	MILLS, L. M.	8011180489	71-6568
MCCRACKEN, R. G.	8011110081	PR	MEISS, R. L.	8011050168	PROJ	MILLS, L. M.	8011210134*	50-390 Q
MCDONALD, Z. D.	8011180013*	71-9091	MELEHAN, J. B.	8011280077*	50-334 P	MILLS, L. M.	8011030476	50-390 Q
MCDONALD, J. A.	8011050268*	50-261 Q	MELTINGER, C. W.	8011180060	50-289 B	MILLS, L. M.	8011030590	50-328 Q
MCDONALD, D. D.	8011100026	FOIA	MELTINGER, K.	8011110317*	50-346 B	MILLS, L. M.	8011030627	50-259 F
MCDONALD, Z. D.	8011180010	71-9091	MELSTAD, K.	8011140432*	50-346 B	MILLS, L. M.	8011060688	50-438 Q
MCDONELL-BOYER	8011170780	REB	MENARD, H. H.	8011190217	40-8743	MILLS, L. M.	8011030347	50-327 F
MCDUFFIE, H. A.	8011070436	50-400 A	MERRILL, B. H.	8011050300*	50-261 Q	MILLS, L. M.	8011050484	50-390 Q
MCDUFFIE, H. A.	8011070460	50-400 V	MERRILL, D. N.	8011180052	50-387 Q	MILLS, L. M.	8011030475	50-327 F
MCDUFFIE, H. A.	8011140431	50-400 Q	MERRILL, D. N.	8011190378*	50-443 A	MILLS, L. M.	8011040529	50-239 R
MCLEOD, W. N.	8011180079	REB	MERSON, B. D.	8011240319	50-317 R	MILLS, L. M.	8011170152	71-6722
MCLEOD, W. N.	8011130252	REB	MERSON, B. D.	8011240324*	50-317 R	MILLS, L. M.	8011030462	50-328 Q
MCLEOD, W. N.	8011120094	PR	MERSON, J. T.	8011070146	50-454 Q	MILLS, L. M.	8011030472	50-438 Q
MCFLARLAND, C. R.	8011210166*	50-370 Q	METZGER, R. L.	8011120162	PR	MILLS, L. M.	8011040164	50-327 P
MCFLARLAND, C. R.	8011070244	50-369 Q	MEYERS, B.	8011030022*	70-8	MILLS, L. M.	8011040172	50-390 A
MCFLARLAND, C. R.	8011070244	50-369 Q	MEYERS, B.	8011100051	NUREO	MILLS, L. M.	8011060527	50-390 F
MCFLARLAND, C. R.	8011140056	50-369 Q	MICHEL, G. J.	8011040566	71-5059	MILLS, L. M.	8011070306	50-318 A
MCFLARLAND, C. R.	8011140056	50-369 Q	MICHEL, G. J.	8011040497	70-143	MILLS, L. M.	8011070389	50-438 Q
MCFLARLAND, C. R.	8011140056	50-369 Q	MICHEL, G. J.	8011070348	70-143	MILLS, L. M.	8011070429	50-328 Q
MCFLARLAND, C. R.	8011140056	50-369 Q	MIDURA, H. J.	8011060419	50-272 B	MILLS, L. M.	8011070455	50-390 Q
MCFLARLAND, C. R.	8011180153	50-369 Q	MIDURA, H. J.	8011180621	50-272 R	MILLS, L. M.	8011100470	50-390 Q
MCFLARLAND, C. R.	8011180153	50-369 Q	MIDURA, H. J.	8011170446	50-272 R	MILLS, L. M.	8011120248	50-259 V
MCFLARLAND, C. R.	8011280041	50-488 Q	MIDURA, H. J.	8011180583	50-311 R	MILLS, L. M.	8011120378	50-390 Q
MCFLARLAND, C. R.	8011280041	50-488 Q	MIDURA, H. J.	8011210534*	50-317 B	MILLS, L. M.	8011140067	50-390 Q
MCFLARLAND, C. R.	8011190208	50-289 Q	MIDURA, H. J.	8011100083	50-10 P	MILLS, L. M.	8011140079	50-553 B
MCFLARLAND, C. R.	8011170603*	50-322 Q	MILLER, J.	8011040326*	50-416 H	MILLS, L. M.	8011140557	50-553 B
MCFLARLAND, C. R.	8011170603*	50-322 Q	MILLER, D. E.	8011060207*	50-373 Q	MILLS, L. M.	8011110239	50-327 P
MCFLARLAND, C. R.	8011190329*	50-352 Q	MILLER, W. H.	8011200463*	50-348 Q	MILLS, L. M.	8011100474	50-327 P
MCFLARLAND, C. R.	8011180472*	50-354 Q	MILLER, J. R.	8011030202	50-199 F	MILLS, L. M.	8011130391	50-328 Q
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, W. O.	8011030370	50-286 F	MILLS, L. M.	8011140049	50-328 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, J. A.	8011030325	50-112 P	MILLS, L. M.	8011190715	50-390 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, W. O.	8011070328	50-312 P	MILLS, L. M.	8011190737	50-366 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, J. R.	8011100001	50-72 P	MILLS, L. M.	8011100050	50-260 P
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, J. R.	8011100004*	50-72 P	MILLS, L. M.	8011140016	50-390 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, W. O.	8011060088	40-8692	MILLS, L. M.	8011140107	50-289 P
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, J. A.	8011060524	50-245 P	MILLS, L. M.	8011140118	50-239 F
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, W. O.	8011190001	40-8745	MILLS, L. M.	8011190281	50-438 Q
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, J. R.	8011110402	50-267 Q	MILLS, L. M.	8011130381	50-439 Q
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, B. A.	8011040510	50-498 Q	MILLS, L. M.	8011140011	50-390 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, W. O.	8011110770	50-289 P	MILLS, L. M.	8011140092	50-390 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, W. O.	8011140532	71-6581	MILLS, L. M.	8011140325	50-259 V
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, J. R.	8011120594	HIBC	MILLS, L. M.	8011140439	50-328 A
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, W. O.	8011120583	50-321 P	MILLS, L. M.	8011210448	50-438 Q
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, H. J.	8011180284	40-8745	MILLS, L. M.	8011180488	50-438 Q
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, H. E.	8011050143	50-267 Q	MILLS, L. M.	8011180545	50-328 A
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011060395	50-267 Q	MILLS, L. M.	8011190117	50-390 R
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011140081	50-326 P	MILLS, L. M.	8011180469	50-327 P
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011170121	TOPREP	MILLS, L. M.	8011180527	50-327 V
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011170141	TOPREP	MILLS, L. M.	8011180551	50-553 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011170147	70-143	MILLS, L. M.	8011210580	50-328 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, J. R.	8011120616	50-73 P	MILLS, L. M.	8011240164	50-259 P
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, J. R.	8011120620*	50-73 P	MILLS, L. M.	8011210271	50-327 P
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, J. R.	8011210126	50-73 P	MILLS, L. M.	8011250428	50-260 Q
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, J. R.	8011210131*	50-73 P	MILLS, L. M.	8011250295	50-328 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, W. O.	8011180869	TOPREP	MILLS, L. M.	8011250305	50-390 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, W. O.	8011100412	50-267 P	MILLS, L. M.	8011250357	50-438 A
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, L. M.	8011170451*	50-272 R	MILLS, L. M.	8011250406	50-239 F
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, L. M.	8011180987*	50-311 R	MILLS, L. M.	8011260148	50-327 P
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011140814	50-445 M	MINECK, D. L.	8011180316	50-331 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011260261	50-580 A	MINECK, D. L.	8011180325	50-331 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011260265	50-452 A	MINECK, D. L.	8011180410	50-331 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011260269	50-392 A	MINECK, D. L.	8011250228	50-331 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011190013	50-255 Q	MINECK, D. L.	8011180611	50-331 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011190013	50-255 Q	MINECK, D. L.	8011180623	50-331 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011170881	50-329 Q	MINECK, D. L.	8011180696	50-331 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011240431	70-1151	MINECK, D. L.	8011180702	50-331 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011240438	71-9136	MINECK, D. L.	8011200302	50-331 R
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011240438	NUREO	MINECK, D. L.	8011260254	50-331 B
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011210161*	50-390 Q	MINECK, D. L.	8011070157	50-261 Q
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011100454	50-259 Q	MINECK, D. L.	8011030071	SECV
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011140026	50-318 B	MINECK, D. L.	8011200361	SECV
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011130241*	50-327 Q	MINECK, D. L.	8011200398	SECV
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011260407*	70-143	MINECK, D. L.	8011200393	SECV
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.	8011050175	40-1341	MINECK, D. L.	7906180095	REOED
MCFLARLAND, C. R.	8011100332*	50-352 Q	MILLER, M. E.			MINECK, D. L.	8009190587*	FOIA

PERSONAL AUTHOR INDEX

325

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HINOSQUE, R. B.	8009100225	SECY	HORTON, K. V.	8011030438*	CONTRACT	MURPHY, C. E.	8011260423	50-369 Q
HINOSQUE, R. B.	8011060034	PR	HORTON, K. V.	8011170140*	CONTRACT	MURPHY, W. P.	8011180653	50-271 S
HINOSQUE, R. B.	8011060061	REG00	HORTON, K. V.	8011120644*	CONTRACT	MURPHY, W. P.	8011180663*	50-271 S
HINOSQUE, R. B.	8011170675	PR	HORTON, K. V.	8011120681*	CONTRACT	MURRAY, T. D.	8011100484	50-346 S
HINOSQUE, R. B.	8011210208*	10CFR	HORTON, K. V.	8011210037*	CONTRACT	MURRAY, T. D.	8011110308	50-346 S
HINOR, G. C.	8011250333*	50-454 Q	HOBSELEY, N. C.	8011170238*	50-259 Q	MURRAY, W. R.	8011040011	50-339 P
HIRAGLIA, F. J.	8011030086	50-273 H	HOBSELEY, N. C.	8011060778	118C	MURRAY, T. D.	8011060476	50-346 S
HIRAGLIA, F. J.	8011190643	50-273 H	HOTT, J. E.	8011070467*	50-335 P	MURRAY, R.	8011180613*	50-265 S
HIRAGLIA, F. J.	8011050562	50-273 H	HOTT, J. E.	8011070462	50-335 P	MURRAY, T. D.	8011110247	50-346 S
HIRAGLIA, F. J.	8011060097	50-273 H	HOTYCKA, M.	8011190498	50-3 H	MURRAY, T. D.	8011110293	50-346 S
HIRAGLIA, F. J.	8011060037	50-273 H	HOUNT, D. H.	8011040028	PROJ	MURRAY, T. D.	8011110316	50-346 S
HIRAGLIA, F. J.	8011060039	50-273 H	HOYER, R. A.	8011200305	50-289 H	MURRAY, T. D.	8011180602	50-346 R
HIRAGLIA, F. J.	8011170098	50-311 Q	HROCZKA, E. J.	8011030441	50-245 S	MURRAY, T. D.	8011110197	50-346 S
HIRAGLIA, F. J.	8011170514	50-273 H	HROCZKA, E. J.	8011040463	50-336 S	MURRAY, T. D.	8011110263	50-346 S
HIRAGLIA, F. J.	8011210721	50-273 H	HROCZKA, E. J.	8011120373	50-245 S	MURRAY, T. D.	8011140426	50-346 S
HIRAGLIA, F. J.	8011210731	50-273 H	HROCZKA, E. J.	8011120537	50-245 S	MUSE, L. A.	8011120158	PR
HITCHELL, D. O.	8011070426*	50-289 S	HROCZKA, E. J.	8011200311	50-246 B	MYERS, D.	8011060149*	50-269 Q
HITCHELL, D. O.	8011190273*	50-289 S	HROCZKA, E. J.	8011180629	50-245 R	MYNATT, F. R.	8011050576	REB
HITTL, R. L.	8011170371	50-354 A	HROCZKA, E. J.	8011210396	50-336 R	MYRADO, A.	8011120538*	50-263 R
HITTL, R. L.	8011130208	50-272 F	HROCZKA, E. J.	8011210455	50-336 S	NABARD, H. O.	8011110130	PR
HIVASAYASHI, M.	8011110709	XPORTLIC	HROCZKA, E. J.	8011210489	50-336 S	NAPUDA, O.	8011130050*	50-289 Q
HIVASAYASHI, M.	8011260250	XPORTLIC	HROCZKA, E. J.	8011250388	50-245 S	NAPUDA, O.	8011130165*	50-247 Q
HOFFMAN, L.	8011210238*	50-390 Q	HROCZKA, E. J.	8011250383	50-336 S	NAREBUT, P. P.	8011030280*	50-344 Q
HOFFETT, T.	8011170440	50-247 U	HROCZKA, E. J.	8011250377	50-245 S	NAREBUT, P. P.	8011050402*	50-344 Q
HOGGLESKO, F. J.	8011100403	50-293 R	HUCHNICKI, E. D.	8011170251	PR	NARDACCI, G. A.	8011100528*	50-320 R
HOIENI, P.	8011190096	NUREQ	MUELLER, J. R.	8010270115*	70-1092	NARETTO, C. J.	8011130138	REB
HOELLE, S. A.	8011030672	50-201 P	MUELLER, R.	8011250474*	50-283 S	NARROW, L.	8011170603*	50-322 Q
HONNIE, D. I.	8011060084	REB	MULKEY, J. P.	8011030278*	50-346 Q	NATARAJA, H. S.	8011190036*	50-409 Q
HONNERRATE, C.	8011170721	NUREQ	MURALIDHARAN, R.	8011030428	NUREQ	NAUGHTON, W. R.	8011050427	50-295 P
HORTON, K. V.	8011190263*	50-146 Q	MURLEY, T. E.	8011180829*	COMMISSION	NAUGHTON, W. F.	8011030531	50-454 K
HORTON, K. V.	8011190235*	50-146 Q	MURLEY, T. E.	8011030205	50-3 P	NECK, H.	8011180467*	50-213 R
HORTON, K. V.	8011260304	50-146 R	MURLEY, T. E.	8011070359	MISC	NEFF, R. D.	8011210718*	50-267 Q
HORTI, W. A.	8011060480	50-247 S	MURLEY, T. E.	8011040634	REVIEW QRP	NEIGHBOR, J. D.	8011070174	50-280 F
HORTI, W. A.	8011170521	50-3 R	MURPHY, C. E.	8011200425*	50-438 Q	NETSLER, J. H.	8011200040*	50-373 Q
HOODY, D. E.	8011190619*	50-29 Q	MURPHY, C. E.	8011210169*	50-390 Q	NETSLER, J. H.	8011260378*	50-346 Q
HOODY, D. E.	8011210336*	50-309 Q	MURPHY, C. E.	8011040304*	50-413 Q	NETSLER, J. H.	8011180409*	50-373 Q
HOODY, D. E.	8011200172	50-309 Q	MURPHY, C. E.	8011210668*	50-395 Q	NELP, W. B.	8011210327	PR
HOODY, D. E.	8011140389	50-29 R	MURPHY, C. E.	8011050375*	50-364 Q	NELSON, J. L.	8011090016*	70-2909
HOODY, D. E.	8011180169	50-309 P	MURPHY, C. E.	8011200382*	50-280 Q	NELSON, R. L.	8011050142*	50-303 Q
HOONEY, G.	8011120649	40-8502	MURPHY, C. E.	8011200431*	50-416 Q	NELSON, J. D.	8011030184*	40-8084
HOONEY, G.	8011030336	40-8502	MURPHY, C. E.	8011040337*	50-280 Q	NELSON, J. D.	8011050178	40-8084
MOORE, J. B.	8011100387*	70-1143	MURPHY, C. E.	8011200449*	50-348 Q	NERENBERG, A. L.	8011100036	FOIA
MOORE, R. N.	8011170863	XPORTLIC	MURPHY, C. E.	8011040034	50-390 Q	NEUFER, A. O.	8011200300*	50-338 R
MOORE, S. F.	8011180161	FOIA	MURPHY, C. F.	8011040553	50-390 Q	NEUMANN, H. R.	8011050170	40-8697
MOORE, R.	8011120110	PR	MURPHY, C. E.	8011040352	50-261 Q	NEUMANN, H. R.	8011110828	40-8380
MOORE, R. N.	8011060273	XPORTLIC	MURPHY, C. E.	8011040531	50-302 Q	NEUMANN, R.	8011050211	50-461 Q
MOORE, R. N.	8011260158	XPORTLIC	MURPHY, C. E.	8011210219*	50-390 Q	NEUWEO, H.	8011110602*	State Prog
MOORE, O. W.	8011040376	50-334 R	MURPHY, C. E.	8011050297	50-261 Q	NEUWEO, H.	8011110607*	State Prog
MOORE, O. W.	8011040377*	50-334 R	MURPHY, C. E.	8011040068*	50-413 Q	NEVIN, A.	8011100312	50-387 Q
MOORE, R. N.	8011110657	XPORTLIC	MURPHY, C. E.	8011130386	50-250 Q	NEWMARK, N. M.	8011170578*	50-275 Q
MOORE, R. N.	8011110665	XPORTLIC	MURPHY, C. E.	8011260380	50-321 Q	NEWMARK, N. M.	8011170795*	CONTRACT
MOORE, R. N.	8011110735	XPORTLIC	MURPHY, C. E.	8011210139	50-424 Q	NEWMAN, J. R.	8011140093	50-466 Q
MOORE, J. E.	8011040442	50-155 Q	MURPHY, C. E.	8011260392	50-416 Q	NEWMAN, J. R.	8011140093	50-466 Q
MOORE, J. E.	8011050441	50-596 Q	MURPHY, C. E.	8011210158*	50-370 Q	NEWMAN, J. R.	8011180147	50-466 Q
MOORE, J. E.	8011060372	50-155 Q	MURPHY, C. E.	8011260418	50-566 Q	NEWMAN, J. R.	8011180147	50-466 Q
MOORE, J. E.	8011060378*	50-155 Q	MURPHY, C. E.	8011260422	50-424 Q	NEWMAN, J. R.	8011190176	50-466 Q
MOORE, T. S.	8011240176	50-409 Q	MURPHY, C. E.	8011170565*	50-413 Q	NEWMAN, J. R.	8011190176	50-466 Q
MORRETTI, E. J.	801070606*	FOIA	MURPHY, C. E.	8011260346	50-395 Q	NEWTON, E.	8011210355*	50-289 Q
MORGAN, H. E.	8011250471*	50-361 A	MURPHY, C. E.	8011260356	50-250 Q	NICHOLS, T. C.	8011210653*	50-393 Q
MORGAN, H. E.	8011250482*	50-361 A	MURPHY, D. W.	8011260283*	50-254 Q	NICHOLS, T. C.	8011030494	50-393 A
MORGAN, H. E.	8011250503*	50-361 A	MURPHY, C. E.	8011040299	50-413 Q	NICHOLS, T. C.	8011040569	50-395 V
MORIN, J. P.	8011030061	50-322 K	MURPHY, C. E.	8011040325	50-280 Q	NICHOLS, T. C.	8011040221	50-395 F
MORISTA, A. V.	8011170448	50-293 Q	MURPHY, C. E.	8011050366	50-364 Q	NICHOLS, T. C.	8011040268	50-395 A
MORISTA, A. V.	8011040516	50-293 V	MURPHY, W. P.	8011040378	50-271 S	NICHOLS, T. C.	8011040274	50-395 A
MORISTA, A. V.	8011040509	50-293 Q	MURPHY, W. P.	8011040381*	50-271 S	NICHOLS, T. C.	8011090479	50-395 S
MORISTA, A. V.	8011060473	50-293 P	MURPHY, W. P.	8011040385	50-271 S	NICHOLS, T. C.	8011060439	50-395 A
MORISTA, A. V.	8011040502	50-293 P	MURPHY, W. P.	8011040387*	50-271 S	NICHOLS, T. C.	8011060464	50-395 Q
MORISTA, A. V.	8011060459	50-293 P	MURPHY, W. P.	8011030360	50-271 S	NICHOLS, T. C.	8011070264	50-395 V
MORISTA, A. V.	8011170408	50-293 Q	MURPHY, W. P.	8011030967*	50-271 S	NICHOLS, T. C.	8011100357	50-395 A
MORISTA, A.	8011070457	50-293 P	MURPHY, W. P.	8011030499	50-271 S	NICHOLSON, N. A.	8011210618*	40-2053
MORISTA, A. V.	8011120343	50-293 P	MURPHY, W. P.	8011030509*	50-271 S	NICHOLS, T. C.	8011100371	50-395 A
MORISTA, A. V.	8011240479	50-293 Q	MURPHY, C. E.	8011200376	50-280 Q	NICHOLS, T. C.	8011130206	50-395 A
MORISTA, A. V.	8011210578	50-293 P	MURPHY, C. E.	8011200405	50-438 Q	NICHOLS, T. C.	8011120466	50-395 A
MORRISON, H. P.	8011040407	50-395 H	MURPHY, C. E.	8011200436	50-348 Q	NICHOLS, T. C.	8011180549	50-395 S
MORRIS, R. H.	8011190003	50-599 A	MURPHY, C. E.	8011210124	50-390 Q	NICHOLS, T. C.	8011200275	50-395 A
MORROW, D.	8011190336	40-8502	MURPHY, C. E.	8011210195	50-390 Q	NICHOLS, T. C.	8011240329	50-395 S
MORROW, D.	8011170131	40-8502	MURPHY, C. E.	8011200438	50-416 Q	NICHOLS, T. C.	8011140344	50-395 D
MORROW, D.	8011190345	40-8502	MURPHY, W. P.	8011110304	50-271 S	NICHOLS, T. C.	8011180699	50-395 H
MORROW, D.	8011120641	40-8502	MURPHY, W. P.	8011110313*	50-271 S	NICHOLS, T. C.	8011210465	50-395 A
MORROW, D.	8011110131	40-8502	MURPHY, W. P.	8011170800*	50-271 S	NICHOLS, T. C.	8011210503	50-395 A
MORROW, D.	8011110125	40-8502	MURPHY, W. P.	8011170496	50-271 S	NICHOLS, T. C.	8011240333	50-395 S
MORSE, A. K.	8011050042	50-409 Q	MURPHY, C. E.	8011210361	50-348 Q	NICHOLS, T. C.	8011180122	50-395 K
MORSE, A. K.	8011050044*	50-409 Q	MURPHY, C. E.	8011210647	50-395 Q	NICHOLS, T. C.	8011260196	50-395 A
MORSE, A. K.	8011280021	50-409 Q	MURPHY, W. P.	8011240406	50-271 S	NICHOLS, T. C.	8011260092	50-395 A
MORSE, A. K.	8011280023*	50-409 Q	MURPHY, W. P.	8011240412*	50-271 S	NICKOLAUS, J. W.	8011240208	XPORTLIC

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NICOLOSI, B. L.	8011100083	50-10 P	OLMSTEAD, W. J.	8011100273*	50-275 Q	PARKER, W. O.	8011210183	50-370 Q
NILSON, R.	8011100082*	FOIA	OLMSTEAD, W. J.	8011050451	50-275 Q	PARKER, W. O.	8011040146	50-269 P
NILSON, R.	8011100084*	FOIA	OLMSTEAD, W. J.	8011070037	50-275 Q	PARKER, W. O.	8011050442	50-369 S
NILSON, R.	8011120618	71-3	OLMSTEAD, W. J.	8011070230	50-275 Q	PARKER, W. O.	8011060499	50-269 P
NIX, R. T.	8011120452*	50-366 S	OLSEN, A. R.	8011190081	NUREG	PARKER, W. O.	8011060502	50-269 P
NIX, R. T.	8011120519*	50-366 S	OLSHAN, L.	8011060298	50-247 P	PARKER, W. O.	8011040478	50-269 S
NIX, R. T.	8011140380*	50-366 S	OLSHAN, L.	8011070167	50-247 P	PARKER, W. O.	8011040481	50-269 P
NIX, R. T.	8011160706*	50-366 S	OLSON, R. C.	8011060468	50-317 H	PARKER, W. O.	8011070354	50-369 A
NIX, R. T.	8011190412*	50-321 S	OLSON, J. F.	8011190275	PR	PARKER, W. O.	8011070439	50-269 P
NORDERHAUG, L. R.	8011060366	70-734	OPREA, O. W.	8011120637	50-498 S	PARKER, W. O.	8011110496	50-269 P
NORDERHAUG, L. R.	8011060371*	70-734	OPREA, O. W.	8011190630	50-498 S	PARKER, W. O.	8011210768	50-369 Q
NORDERHAUG, L. R.	8011060812	70-25	OPREA, O. W.	8011060188*	50-498 A	PARKER, W. O.	8011120334	50-269 P
NORDERHAUG, L. R.	8011200026	50-312 Q	OPREA, O. W.	8011030598	50-498 Q	PARKER, W. O.	8011210125	50-369 Q
NOREIKA, R.	8011100305	50-387 Q	OPREA, O. W.	8011210763*	50-498 Q	PARKER, W. O.	8011260330	50-269 Q
NOREIKA, R.	8011100305	50-387 Q	OPREA, O. W.	8011030583	50-498 S	PARKER, W. O.	8011180542	50-369 A
NOREL, I. U. S. C. E.	80111260424*	50-546 Q	OPREA, O. W.	8011040173	50-498 A	PARKER, W. O.	8011120604	50-270 S
NOREL, I. U. S. C. E.	8011200593*	50-546 Q	OPREA, O. W.	8011120341	50-498 S	PARKER, W. O.	8011120339	50-269 P
NORDAN, H. E.	80111250494*	50-361 A	OPREA, O. W.	8011120348	50-498 A	PARKER, W. O.	8011130199	50-269 P
NORRHOLOM, L. J.	8011180814*	50-272 Q	OPREA, O. W.	8011120362	50-498 S	PARKER, W. O.	8011140398	50-269 P
NORRHOLOM, L. J.	8011100531*	50-289 Q	OPREA, O. W.	8011180622	50-498 S	PARKER, W. O.	8011140372	50-269 S
NORTON, J.	8011170086	XPORTLIC	OPREA, O. W.	8011190305	50-498 K	PARKER, W. O.	8011180418	50-369 A
NORTON, J. F.	8011170090*	XPORTLIC	ORDERS, W.	8011060149*	50-269 Q	PARKER, W. O.	8011180392	50-269 P
NORTON, B.	8011050406	50-273 Q	OSTER, J.	8011180717	50-10 J	PARKER, W. O.	8011180446	50-270 S
NORTON, H. E.	8011280070	PR	OSTER, J.	8011250332	50-10 J	PARKER, W. O.	8011180704	50-270 S
NOSENZO, L. V.	8011060308	XPORTLIC	OSUCH, J. C.	8011280058*	50-272 S	PARKER, W. O.	8011280238	50-369 Q
NOSENZO, L. V.	8011060330	XPORTLIC	OTTINGER, R. L.	8011170215	50-247 U	PARKER, W. O.	8011180582	50-269 R
NOSENZO, L. V.	8011060336	XPORTLIC	QUZTS, J. E.	8011040319*	50-324 G	PARKER, W. O.	8011180585	50-269 S
NOSENZO, L. V.	8011060348	XPORTLIC	OVERLID, T. W.	8011030603*	50-263 S	PARKER, W. O.	8011180711	50-287 S
NOSENZO, L. V.	8011060358	XPORTLIC	OWSLEY, O. F.	8011140002	TOPREP	PARKER, W. O.	8011200178	50-269 P
NOSENZO, L. V.	8011060393	XPORTLIC	OWSLEY, O. F.	8011170495	TOPREP	PARKER, W. O.	8011180348	50-269 P
NOSENZO, L. V.	8011140668*	SEGY	OWSLEY, O. F.	8011100414	TOPREP	PARKER, W. O.	8011190494	50-369 S
NOSENZO, L. V.	8011060796	XPORTLIC	FACE, P. L.	8011040492*	50-335 S	PARKER, W. O.	8011210473	50-270 S
NOSENZO, L. V.	8011170812	XPORTLIC	FACE, P. L.	8011100460*	50-335 S	PARKER, W. O.	8011210498	50-369 A
NOSENZO, L. V.	8011210130	XPORTLIC	PACH, R. W.	8011100113	NUREG	PARKER, W. O.	8011250172	50-269 F
NOSENZO, L. V.	8011210122	XPORTLIC	PADILLA, R.	8011060204*	71-9019	PARKER, W. O.	8011240288	50-287 S
NOSENZO, L. V.	8011260406	XPORTLIC	PAGE, R. Q.	8011060179	70-27	PARKER, W. O.	8011250261	50-369 A
NOSENZO, L. V.	8011260436	XPORTLIC	PAGE, R. Q.	8011060183	70-286 Q	PARKER, W. O.	8011280291	50-269 P
NOSENZO, L. V.	8011260402	XPORTLIC	PAGE, R. Q.	8011110006	70-162	PARKER, W. O.	8011250365	50-269 S
NOVAK, T. M.	8010230539	50-285 S	PAGE, R. Q.	8011130010	70-1966	PARKER, W. O.	8011250480	50-270 S
NOVAK, T. M.	8011060957	50-317 P	PAGE, R. Q.	8011190607	70-371	PARKER, W. O.	8011190367*	50-320 H
NOVAK, T. M.	8011190146	50-321 P	PAGE, R. Q.	8011190707	70-2913	PARKY, J. D.	8011190041*	50-409 Q
NOVAK, T. M.	8011280092	50-250 P	PAGE, R. Q.	8011180168	70-267	PARME, A. L.	8011200261*	50-546 A
NOVARRO, J. P.	8011200269	50-322 Q	PAGE, R. Q.	8011180299	70-1131	PARME, A. L.	8011200264*	50-546 A
NOVARRO, J. P.	8011200185	50-322 Q	PAOLINO, J. A.	8011070575*	FOIA	PARDONS, C. H.	8011190664*	50-289 H
NOVICKI, S. J.	8011030606	50-206 P	PANKRATZ, D. R.	8011180221	NUREG	PARTLOW, J. Q.	8011100112*	FOIA
NOVICKI, S. J.	8011180160	50-206 P	PAOLINO, R. J.	8011170603*	50-322 Q	PARTLOW, J. Q.	8011100425	70-364
NOYES, A. W.	8011130181*	70-2116	PAOLINO, R. J.	8011210715*	50-286 Q	PARTLOW, J. Q.	8011100517	70-824
NUNN, D. E.	8011250285	50-361 A	PAOLINO, R. J.	8011260428*	50-354 Q	PARTLOW, J. Q.	8011180006	70-371
NUTT, H. T.	8011170556*	PROJ	PAPAY, L. T.	8011060126*	50-361 Q	PARTLOW, J. Q.	8011140536	70-33
NUTT, H. T.	8011170549*	PROJ	PAPAY, L. T.	8011170547	50-361 S	PARTLOW, J. Q.	8011180875	70-371
NUTT, H. T.	8011170552*	PROJ	PAPAY, L. T.	8011230301	50-361 S	PARTLOW, J. Q.	8011250080	70-371
O'BRIEN, T.	8011030206	FOIA	PAPERIELLO, C. J.	8011060295*	50-329 Q	PASTERNAK, R. J.	8008130621	50-333 Q
O'CONNOR, P. W.	8011070190*	50-237 T	PAPERIELLO, C. J.	8011060274*	50-264 Q	PASTERNAK, R. J.	8011060498	50-333 S
O'HANLON, J. P.	8011040543	50-313 P	PAPERIELLO, C. J.	8011060286*	50-409 Q	PASTERNAK, R. J.	8011060503	50-333 S
O'MALLEY, T. E.	8011210053	XPORTLIC	PAPERIELLO, C. J.	8011030128*	50-373 Q	PASTERNAK, R. J.	8011120483	50-333 R
O'MARA, R. E.	8011250160	PR	PAPERIELLO, C. J.	8011170947*	50-456 Q	PASTERNAK, R. J.	8011110490	50-333 P
O'NEILL, B.	8011210699*	40-8702	PAPERIELLO, C. J.	8011210424*	50-305 Q	PASTERNAK, R. J.	8011205943	50-333 S
O'NEILL, J.	8011060481*	50-346 S	PAPERIELLO, C. J.	8011190496*	50-150 Q	PASTERNAK, R. J.	8011205956	50-333 S
O'NEILL, J. P.	8011240194	PR	PAPERIELLO, C. J.	8011110034*	50-10 Q	PATE, R. J.	8011060144*	50-361 Q
O'REILLY, J. P.	8011200494	50-335 Q	PAPERIELLO, C. J.	8011200085*	50-454 Q	PATSEY, J. J.	8011060577*	50-286 P
O'REILLY, J. P.	8011090477*	50-250 Q	PAPERIELLO, C. J.	8011210618*	40-2053	PATTERSON, J. P.	8011060218*	50-306 Q
O'REILLY, J. P.	8011200417*	50-438 Q	PAPPAS, H.	8011070079	ORQ	PATTERSON, J. P.	8011200012*	50-10 Q
O'REILLY, J. P.	8011090512*	50-321 Q	PAPPAS, H.	8011240140	ORQ	PATTERSON, T. L.	8011180647*	50-285 R
O'REILLY, J. P.	8011170660	50-261 Q	PAPPAS, H.	8011060790	ORQ	PAUL, R. A.	8011070575*	FOIA
O'REILLY, J. P.	8011170666	50-250 Q	PAPPAS, H.	8011130003	ORQ	PAUL, R. A.	8011110034*	50-10 Q
O'REILLY, J. P.	8011170669	50-259 Q	PAPPAS, H.	8011130005	ORQ	PAUL, T. W.	8011120280	50-239 P
O'REILLY, J. P.	8011170672	50-280 Q	PARENT, C. D.	8011040024	PROJ	PAULSON, W.	8011060052	50-217 P
O'REILLY, J. P.	8011170678	50-488 Q	PARIKH, K.	8011170227*	50-483 Q	PAULSON, W. A.	8011060384*	50-195 Q
O'REILLY, J. P.	8011170685	50-349 Q	PARIKH, K.	8011170232*	50-483 Q	PEACOCK, D. G.	8011140682*	40-8412
O'REILLY, J. P.	8011170687	50-328 Q	PARIS, W. C.	8011070440	40-299	PEARSON, R. J.	8011205644*	50-409 F
O'REILLY, J. P.	8011240511	70-1113	PARIS, D. H.	8011140040	50-596 Q	PEEPLES, W. P.	8011110184	PR
O'REILLY, J. P.	8011210295	50-324 Q	PARKER, W. O.	8011040302*	50-413 Q	PEERY, W. W.	8011030699	40-6586
O'SHAUGHNESSY	8011250124	FR	PARKER, W. O.	8011070107	NUREG	PELL, D. M.	8011050159	50-289 Q
DAKLEY, D. T.	8011100091*	50-10 P	PARKER, W. O.	8011060128*	50-269 Q	PELL, D. M.	8011050158	50-289 Q
DAKLEY, D. T.	8011170727*	50-482 Q	PARKER, W. O.	8011040064	50-413 Q	PELLTIER, I. A.	8011170188	50-358 A
DEBTHANN, H. J.	8011030128*	50-373 Q	PARKER, W. O.	8011130068	50-269 Q	PENDERGRAFT, R.	8011100449*	50-368 S
DEBTHANN, H. J.	8011210424*	50-305 Q	PARKER, W. O.	8011030487	50-269 S	PENDERGRAFT, R.	8011100444*	50-368 S
DEBTHANN, H. J.	8011110034*	50-10 Q	PARKER, W. O.	8011030356	50-369 F	PENDERGRAFT, R.	8011110289*	50-368 S
OH, I.	8011240101	NUREG	PARKER, W. O.	8011250188	50-269 Q	PENDERGRAFT, R.	8011110300*	50-368 S
OH, I.	8011140324	NUREG	PARKER, W. O.	8011030440	50-270 S	PENDERGRAFT, R.	8011140033*	50-368 S
OLIV, H. E.	8011090532	NUREG	PARKER, W. O.	8011040533	50-369 A	PENDERGRAFT, R.	8011170476*	50-368 S
OLIVER, J. A.	8011070095	NUREG	PARKER, W. O.	8011050390	50-269 A	PENDERGRAFT, R.	8011180509*	50-368 S
OLLER, R. E.	8011170124*	QA999	PARKER, W. O.	8011100429	50-269 Q	PENDERGRAFT, R.	8011170487*	50-368 S
OLLER, R. E.	8011060289*	QA999	PARKER, W. O.	8011070386	50-369 A	PENDERGRAFT, R.	8011180420*	50-368 R
OLMSTEAD, W. J.	8011040422	50-275 Q	PARKER, W. O.	8011170562	50-413 Q	PENDERGRAFT, R.	8011210454*	50-368 S

PERSONAL AUTHOR INDEX

327

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PERLMAN, J	8011140886*	CONTRACT	POTAPQVS, U	8011060231	QA999	RECORD, D J	8011120442*	50-327 S
PERLMAN, J	8011180203*	CONTRACT	POTAPQVS, U	8011060256	QA999	REED, C	8011060360	50-454 Q
PERLMAN, J	8011180066*	CONTRACT	POTAPQVS, U	8011170833	QA999	REED, E C	8011280416	50-289 P
PERRY, C. D	8011200497*	50-335 Q	POTAPQVS, U	8011170842	QA999	REED, R W	8011240201*	50-321 P
PERRIN, J. S.	8011170730	NUREQ	POTAPQVS, U	8011170862	QA999	REED, J Q	8011280026	50-493 Q
PERROTTI, D. J.	8011210093*	50-327 Q	POTAPQVS, U	8011180313	QA999	REEDER, D. L.	8011130153	RES
PERRY, D. T.	8011240192*	TOPREP	POTAPQVS, U	8011170349	QA999	REEVES, E. A.	7908240206	50-409 P
PERRY, J. C.	8011070420*	50-344 S	POTE, D. R.	8011190396*	50-443 A	REEVES, M.	8011030488	NUREQ
PERRY, J. C.	8011070502*	50-344 S	POTE, D. R.	8011190383*	50-443 A	REHN, T. A.	8011070066	COMMISSION
PERRY, J. C.	8011070526*	50-344 S	POTTER, J. P.	8011260129*	40-672	REHN, T. A.	8011140653	COMMISSION
PERRY, J. C.	8011180677*	50-344 S	POTTER, J. P.	8011210373*	50-309 Q	REHN, T. A.	8011210165	COMMISSION
PERRY, J. C.	8011250464*	50-344 S	POTTER, J. P.	8011210736*	50-213 Q	REID, R. W.	8011050208	50-269 P
PETERSON, R.	8011190264	40-8502	POTTER, J. P.	8011060620*	70-1113	REID, R. W.	8011030041	50-302 F
PETERSON, R.	8011170329	40-8502	POTTER, J. P.	8011100098*	40-8949	REID, R. W.	8011030062	50-321 F
PETERSON, R. H.	8011180024*	50-367 Q	POTTER, J. P.	8011100111*	50-259 Q	REID, R. W.	8011040001	50-313 F
PETERSON, H. B.	8011030237	50-320 P	POTTER, J. P.	8011210415*	50-327 Q	REID, R. W.	8011030057	50-269 P
PETERSON, R.	8011040595	NUREQ	POTTHOFF, F. H.	8011280004	50-466 Q	REID, R. W.	8011030704	50-269 S
PETERSON, H. R.	8011120430	XPORTLIC	POWELL, O. H.	8011210264	NUREQ	REID, R. W.	8011060528	50-313 P
PETERSON, H. T.	8011240421	PR	POKER, D. F.	8011030174	FOIA	REID, R. W.	8011050019	50-289 Q
PETERSON, H. T.	8011260095	PR	POKER, E. J.	8011200162	50-275 S	REID, R. W.	8011060096	50-269 P
PFEEFERDORF, W.	8011060187	50-488 Q	POYER, R. W.	8011230288	40-2259	REID, R. W.	8011060102	50-313 F
PHILLIPS, H. S.	8011100186*	50-498 Q	PRELEBNIK, H. L.	8011030236	PR	REID, R. W.	8011110139	50-269 Q
PHILLIPS, H. S.	8011100137*	50-498 Q	PREMUZIC, E. T.	8011110002	RES	REID, R. W.	8011110459	50-312 Q
PHILLIPS, H. S.	8011040219*	50-361 A	PRESTON, C. C.	8011180079	RES	REID, R. W.	8011110474	50-346 Q
PHILLIPS, H. P.	8011170947	50-456 Q	PRESTON, C. C.	8011130282	RES	REID, R. W.	8011110863	50-277 Q
PHILLIPS, C. J.	8011200085*	50-454 Q	PRESTON-SMITH	8011040555	NUREQ	REID, R. W.	8011110600	50-321 Q
PICKENS, T. A.	8011100650*	50-237 T	PRICE, H.	8011190808	NUREQ	REID, R. W.	8011140630	50-302 Q
PICKLEBINDER, H.	8011260172*	PR	PRICE, A. R.	8011230139	PR	REID, R. W.	8011170373	50-313 Q
PIELAGE, H. W.	8011100256	NUREQ	PUCKETT, J. M.	8011210415*	50-327 Q	REID, R. W.	8011040609	50-269 P
PILANT, J. M.	8011260051*	50-298 Q	PURPLE, R. A.	8011170109*	50-311 Q	REID, R. W.	8011100808	50-289 H
PILANT, J. M.	8011110248	50-298 F	PUTNAM, F.	8011170319	40-8502	REID, R. W.	8011070125	50-277 P
PILANT, J. M.	8011060462	50-298 P	PUTNAM, F.	8011210649	40-8502	REID, R. W.	8011070130*	50-277 P
PILANT, J. M.	8011070325	50-298 Q	QUEENER, D. B.	8011140669	NUREQ	REID, R. W.	8011070143*	50-277 P
PILANT, J. M.	8011140031	50-298 V	QUICK, D. R.	8011040548*	50-395 Q	REID, R. W.	8011140264	50-321 P
PIRTLE, O. L.	8011200022*	50-409 Q	QUICK, D. R.	8011050292*	50-364 Q	REID, R. W.	8011140267*	50-321 P
PLESSET, H. S.	8008180461	ACR8	QUIGLEY, T. W.	8011030571*	40-8743	REID, R. W.	8011140276*	50-321 P
PLESSET, H. S.	8011180094	ACR8	QUIGLEY, T. W.	8011100240	40-8743	REID, R. W.	8011140168	50-269 P
PLESSET, H. S.	8011180101	ACR8	QUIGLEY, T. W.	8011030564	40-8743	REID, R. W.	8011170821	50-277 P
PLESSET, H. S.	8011190344	ACR8	QUIGLEY, T. W.	8011030074	40-8743	REID, R. W.	8011170471	50-313 P
PLESSET, H. S.	8011190320	50-70 Q	QUIGLEY, T. W.	8011100012	40-8743	REID, R. W.	8011190214	50-289 P
PLESSET, H. S.	8011190374	ACR8	QUIGLEY, T. W.	8011040114	40-8743	REID, R. W.	8011190234*	50-289 P
PLESSET, H. S.	8011190376	ACR8	QUIGLEY, T. W.	8011030173	40-8743	REID, R. W.	8011190243*	50-289 P
PLESSET, H. S.	8011190385	50-275 Q	RADER, R. M.	8011030030	27-39	REID, R. W.	8011200083	50-321 P
PLUMLEE, K. E.	8011190632*	50-29 G	RADER, R. M.	8011030030	27-39	REID, R. W.	8011190671	50-269 P
PLUMLEE, K. E.	8011170946*	50-219 Q	RADER, R. M.	8011190135	27-39	REID, R. W.	8011200016	50-289 P
POCHAL, W. F.	8011050466	XPORTLIC	RADER, R. M.	8011190145*	27-39	REID, R. W.	8011200061	50-277 P
POGGIO, A. J.	8011190703	NUREQ	RADER, R. M.	8011190159*	27-39	REID, R. W.	8011200065	50-289 P
POJRIER, H. R.	8011100396	50-445 M	RADER, R. M.	8011190135	27-39	REID, R. W.	8011200091	50-312 F
POLK, H.	8011140474*	50-367 Q	RADER, R. M.	8011190145*	27-39	REID, R. W.	8011230542	50-321 F
POLK, J.	8011200347	50-346 P	RADER, R. M.	8011190159*	27-39	REID, R. W.	8011260258	50-321 P
POLLARD, R. D.	8011040335	50-247 Q	RAQAN, V. S.	8011030672	50-201 P	REID, R. W.	8011240522	50-312 P
POOLE, D. C.	8011140030	50-302 S	RAQAN, R.	8011100652*	50-237 T	REID, R. W.	8011260199	50-321 P
POOLE, D. C.	8011140037	50-302 S	RAGER, M. S.	8011180619*	50-331 S	REID, R. W.	8011260205*	50-321 P
POOLE, D. C.	8011140110	50-302 S	RAGER, M. S.	8011180631*	50-331 S	REID, R. W.	8011260173	50-313 P
POOLE, D.	8011110233*	50-302 P	RAGER, M. S.	8011180705*	50-331 S	REID, R. W.	8011260174*	50-313 P
POOLE, D.	8011120486	50-302 S	RAGER, M. S.	8011180708*	50-331 S	REID, R. W.	8011260370	50-364 Q
POPP-MOODAND, P.	8011040304	50-361 Q	RAHMAN, R. O.	8011110086	PR	REIDHAAR, D. L.	8011240167	50-142 Q
PORTER, W. L.	8011060465	50-269 Q	RANDALL, J. D.	8011030069	71-398	REIHAIN, F. W.	8011190526*	50-10 S
PORTER, W. L.	8011140054	50-369 Q	RANDOLPH, M. L.	8011170789	RES	REIHAIN, F. W.	8011110034*	50-10 Q
PORTER, W. L.	8011140504	50-269 Q	RANDOLPH, J. M.	8011030575*	50-272 S	REIB, E. J.	8011060196	50-412 Q
PORTER, W. L.	8011180153	50-369 Q	RANDOLPH, J. M.	8011040431*	50-272 S	REIBENHAVER, D.	8011240420	NUREQ
POTAPQVS, U.	8011040135*	QA999	RANDOLPH, J. M.	8011200296*	50-272 S	REKITO, W. A.	8011180460*	50-29 Q
POTAPQVS, U.	8011040125*	QA999	RANSBOFF, J. A.	8011100249*	71-121	REMAKUS, L. P.	8011100373*	50-387 Q
POTAPQVS, U.	8011170763	QA999	RASBURY, J. L.	8011180691*	50-327 S	REMLEY, M. E.	8011060422	70-25
POTAPQVS, U.	8011170853	QA999	RASKIN, D. B.	8011170244	50-466 Q	RENBORGER, D. L.	8011190451*	50-460 Q
POTAPQVS, U.	8011040087*	QA999	RASKIN, D. B.	8011170244	50-466 Q	RENBORGER, D. L.	8011030189	PR
POTAPQVS, U.	8011040113*	QA999	RASKIN, D. B.	8011140493	50-466 Q	RENBORGER, D. L.	8011050433	50-397 S
POTAPQVS, U.	8011170116	QA999	RASKIN, D. B.	8011140493	50-466 Q	RENBORGER, D. L.	8011280093	50-397 Q
POTAPQVS, U.	8011060249*	QA999	RATHKOPF, C. L.	8011060249*	50-320 H	RENBORGER, D. L.	8011070444	50-397 A
POTAPQVS, U.	8011170872*	QA999	RATHKOPF, C. L.	8011060617*	50-320 H	REQUA, Q.	8011030434	50-309 F
POTAPQVS, U.	8011040153	QA999	RATTA, A. D.	8011130329*	70-364	REQUA, Q.	8011030711	50-309 P
POTAPQVS, U.	8011060267*	QA999	RAUSCH, J. K.	8011060073*	50-413 Q	REKINOFF, M.	8008140305	FOIA
POTAPQVS, U.	8011060314	QA999	RAUSCH, J. K.	8011260382*	50-395 Q	REYER, L. A.	8011240113*	50-346 Q
POTAPQVS, U.	8011060326	QA999	RAUSCH, T. J.	8011040586	50-373 Q	REYNOLDS, S.	8011190329*	50-352 Q
POTAPQVS, U.	8011180340*	QA999	RAUSCH, T. J.	8011210251	50-373 Q	REYNOLDS, S. D.	8011100298*	50-289 Q
POTAPQVS, U.	8011060287	QA999	RAVENSCHROFT, N.	8008270692*	FOIA	REYNOLDS, J.	8011100210	50-275 Q
POTAPQVS, U.	8011060313	QA999	RAHLING, J.	8011030589	40-8743	REYNOLDS, N. S.	8011280065	50-445 Q
POTAPQVS, U.	8011170378*	QA999	RAYMOND, W. J.	8011100334*	50-271 Q	REYNOLDS, N. S.	8011280065	50-445 Q
POTAPQVS, U.	8011180332*	QA999	RAYMOND, W. J.	8011100350*	50-271 Q	RHEE, S. J.	8011180607*	50-237 S
POTAPQVS, U.	8011060301*	QA999	RAYMOND, W. J.	8011200155	50-271 S	RHOADS, O. G.	8011210395*	50-387 Q
POTAPQVS, U.	8011170101	QA999	REAVES, M. J.	8011030247*	FOIA	RHODE, Q. K.	8011030497	50-410 A
POTAPQVS, U.	8011060293	QA999	REAVIS, J. A.	8011180592*	50-269 R	RHODE, Q. K.	8011040421	50-410 A
POTAPQVS, U.	8011060387	QA999	REBA, R. C.	8011110060	PR	RHODE, Q. K.	8011070465	50-410 A
POTAPQVS, U.	8011040080	QA999	REBELOWSKI, T.	8011130066*	50-286 Q	RHODE, Q. K.	8011180637	50-220 P
POTAPQVS, U.	8011040105	QA999	REBELOWSKI, T.	8011210713*	50-286 Q	RHODE, Q. K.	8011250369	50-410 A

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RHYNE, S W	8011030254	FOIA	RDWE, C.	8011210275*	40-8702	SCHNEIDER, F W	8011200282	50-272 Q
RICHARD, M	8011120193	PR	RDWE, C.	8011210699*	40-8702	SCHNEIDER, F W	8011120316	50-272 Q
RICKS, N R	8011230019	NUREO	RDWE, S S	8011180762*	71-24	SCHNEIDER, F W	8011210339	PR
RIDGWAY, K R	8011260375*	30-409 Q	RDWEY, C W	8011050291	PR	SCHNEIDER, F W	8011260013	50-272 Q
RIEDLINGER, B A	8011070555	40-8323	RDWEY, E J	8011250539*	50-237 B	SCHNEIDER, F W	8011260086	50-272 Q
RIEGER, S N	8011030372	40-8728	RUBENSTEIN, L S	8011190252	50-124 P	SCHNEIDER, B	8011190498	50-3 H
RIESLAND, J	8011060283	50-293 B	RUBENSTEIN, L S.	8011120569	50-124 P	SCHNEIDER, F W	8011250300*	50-272 P
RIETHLE, H E	8011230262	50-320 R	RUDISILL, G D.	8011030089*	71-399	SCHROEDER, F	8011060553	NUREO
RILEY, R H	8011170437*	COMMISSION	RUITER, Q H	8011140024*	50-305 R	SCHROEDER, F	8011120665	NUREO
RILEY, J L	8011170472	50-369 Q	RUELING, D H	8011120637	71-382	SCHUH, M	8011190172*	50-320 H
RILEY, J L	8011170505*	50-369 Q	RUSSELL, W T	8011050014	50-244 P	SCHULTZ, W H	8011070568*	FOIA
RIOB, J	8011130361*	50-387 Q	RUSSELL, L B.	8011060489	50-317 B	SCHULTZ, W H	8011070572*	FOIA
RITSHER, J A	8011240354	50-443 Q	RUSSELL, L B.	8011070332	50-317 B	SCHUMANN, C E	8011050430*	50-295 P
RITSHER, J A	8011280003	50-443 Q	RUSSELL, L B.	8011070405	50-318 B	SCHUMACHER, M C	8011260283*	50-284 Q
RITSHER, J A	8011190371	50-443 A	RUSSELL, L B	8011100452	50-318 S	SCHUSTER, M D	8011200162	50-275 B
RIZZO, P Q	8011070336*	50-317 B	RUSSELL, L B	8011140462	50-317 B	SCHWART, J	8011060219	50-461 Q
RIZZO, P Q	8011070410*	50-318 B	RUSSELL, L B	8011140456	50-317 B	SCHWENCER, A	7812190001	50-70 P
RIZZO, P Q	8011100453*	50-318 B	RUSSELL, L B.	8011180654	50-318 B	SCHWENCER, A	7812190001	50-70 P
RIZZO, P Q	8011190421*	50-318 B	RUSSELL, T A	8011240317*	50-320 P	SCHWEIBINZ, E R	8011260424*	50-346 Q
RIZZO, P Q	8011250363*	50-318 B	RUSSELL, L B	8011190416	50-318 B	SCHWENCER, A	8011030031	50-364 A
ROBERTS, H W	8011040148*	QA999	RUSSELL, L B	8011210526	50-317 B	SCHWENSBFEIR, R	8011030305	70-33
ROBERTS, M W	8011050386*	50-298 Q	RUSSELL, W T	8011280150	50-155 P	SCHWEIBINZ, E R	8011040309*	50-346 Q
ROBERTS, E	8011280077*	50-334 P	RUSSELL, L B	8011230360	50-318 B	SCHWEIBINZ, E R	8011260311*	50-456 Q
ROBERTS, H W	8011060332*	QA999	RUSSELL, L B	8011260183	50-318 B	SCHWENCER, A	8011030359	50-348 D
ROBERTS, E W	8011200346	50-289 P	RUTHRAUFF, F R	8011060206*	50-289 H	SCHWENCER, A	8011050404	50-395 A
ROBERSON, H E	8011060490*	50-317 B	RYAN, R Q.	8011030075*	EECY	SCHWENCER, A	8011120587	50-498 A
ROBINSON, J C	8011070467*	50-335 P	RYAN, R Q.	8011030075*	EECY	SCHWENCER, A	8011260236	50-327 P
ROBINSON, D L	8011210174*	50-305 Q	RYAN, R Q.	8011200369*	EECY	SCHWENCER, A	8011200400	50-358 M
ROBINSON	8011280027*	50-356 Q	RYAN, R Q.	8011200388*	EECY	SCHWENCER, A	8011200401*	50-358 M
ROCKHOLD, H C.	8011200113	50-334 P	RYAN, R Q.	8011060479*	Estate Prog	SCHWENCER, A	8011260318	50-395 D
ROCKHOLD, H C	8011130018	50-272 P	RYAN, M T	8011170780	RES	SCHWENCER, A	8011260321*	50-395 D
RODRIGUEZ, R J	8011120386	50-312 B	RYKIEWICH, D P	8011260415	PR	SCHWENCER, A	8011280226	50-327 Q
RODRIGUEZ, R J	8011120472	50-312 B	SACKETT, K E	8011140320	NUREO	SCHWEIBINZ, E	8011200137	50-346 B
RODRIGUEZ, R J.	8011120479	50-312 B	SAGENDORF, J F	8010230019	NUREO	SCHWENCER, A	8011260107	50-395 D
RODRIGUEZ, R J	8011210599	50-312 B	SAIKI, T.	8011110212	XPORTLIC	SCHWENCER, A	8011240005	50-352 A
RODRIGUEZ, R J	8011110222	50-312 R	SAIKI, T	8011070113	XPORTLIC	SCINTO, J. F.	8009190630*	50-219 Q
RODRIGUEZ, R J	801120601	50-312 S	SALMON, F.	8011140465	50-334 P	SCOTT, J C	8011050017*	70-2909
RODRIGUEZ, R J	8011210589	50-312 S	SALTZHAN, J	8011110704	50-413 H	SCOTT, J.	8010240404	50-466 H
ROESCH, R M	8011110816	PRQJ	SALTZHAN, J	8011170042	50-413 H	SCOTT, D J	8011030594	50-237 B
ROGERS, L	8011170223*	50-259 Q	SALTZHAN, J.	8011260012	50-97 J	SCOTT, D J	8011030632	50-237 B
ROGERS, R F	8011050574*	50-321 Q	SALTZHAN, J	8011260014	50-326 J	SCOTT, D J.	8011040474	50-249 B
ROGERS, R F	8011060270*	50-321 Q	SALTZHAN, J	8011260017	50-142 J	SCOTT, A D	8011180480	40-8698
ROGERS, J E	8011170868*	QA999	SALTZHAN, J.	8011260025	50-97 J	SCOTTM, L N	8011100403	50-293 R
ROGERS, W O	8011240113*	50-346 Q	SALTZHAN, J.	8011260029	50-142 J	SCOTT, D J	8011070382	50-249 B
ROHMAN, A J	8011170929	NUREO	SALTZHAN, R. S	8011120093	50-275 Q	SCOTT, R Q	8011190085	NUREO
ROMANDER, C M	8011190709	NUREO	SALTZHAN, R. S	8011120100*	50-275 Q	SCOTT, D J	8011140005	50-237 B
ROMAN, T W	8011140336*	50-220 R	SAH, R Q	8011140200	NUREO	SCOTT, D J	8011180447	50-10 R
ROMINE, W D	8011040375*	50-327 B	SAHELBOH, A	8011060219	50-441 Q	SCOTT, D J	8011180600	50-237 B
ROMEN, Y	8011260266	NUREO	SAMMONS, J. H	8011050180	PR	SCOTT, D J	8011230529	50-237 B
ROONEY, V L	8011030613	50-271 P	SAMSON, C H	8011040483	50-128 P	SCOTT, D J.	8011210543	50-249 B
ROONEY, M A	8011050171	70-1308	SANDERS, F. W.	8011200134*	50-245 Q	SCOTT, D J.	8011280588	50-249 B
ROONEY, M A	8011060452	70-1308	SANDERS, F. D	8011210539	50-249 J	SCOTT, D J	8011280322	50-249 B
ROONEY, M A	8011050171	70-1308	SARGANT, P. S.	8011040476	50-320 U	SCOTT, D J	8011230325	50-249 B
ROONEY, M A	8011110587	70-1308	SARGENT, T O	8011070090	NUREO	SCOTT, D J.	8011280344	50-10 P
ROONEY, M A	8011110587	70-1308	SARGOUR, B.	8011110203*	50-346 R	SCOTT, D J	8011230475	50-237 R
ROONEY, V.	8011170064	50-271 P	SARTOR, H	8011260168*	50-387 Q	SEAL, M M	8011100578*	50-367 U
ROONEY, M A	8011180037	70-1308	SASSANI, A	8011100292*	50-289 Q	SEAL, M M	8011190648*	50-275 H
ROONEY, M A	8011180037	70-1308	SASSANI, A	8011230675*	50-317 Q	SEAL, M M.	8011180119*	50-289 H
ROOT, L. D	8011090023	50-331 Q	SAVADE, M. R.	8011210102	REOQD	SEGEV, A	8011100471	NUREO
ROOT, L. D	8011060605	50-331 Q	SCARANO, R A.	8011170415*	40-1162	SEGEV, A	8011170712	NUREO
ROOT, L. D	8011190098	50-331 Q	SCARANO, R. A.	8011170404	40-1162	SEIDLE, W C.	8011200094*	50-498 Q
ROOT, L. D	8011210603	50-331 V	SCARANO, R A	8011250150	40-8676	SEIDLE, W C.	8011100172	50-498 Q
ROOT, L. D	8011210610	50-331 V	SCARANO, R. A.	8011170245	40-8084	SEIDLE, W C.	8011200029	50-482 Q
ROOT, L. D.	8011140058	50-331 P	SCARANO, R A	8011030378	40-2259	SEIDLE, W C	8011100102	50-445 Q
ROOT, L. D	8011280028	50-331 Q	SCARANO, R A	8011120647	WASTE MOT	SEIDLE, W. C.	8011100109	50-498 Q
ROSENBERG, J	8011110092	PR	SCARANO, R A	8011190007	40-1341	SEIDLE, W C.	8011210751	50-445 Q
ROSENTHAL, A. B	8011240176	50-409 Q	SCHAFFSTALL, R.	8011210555	50-29 P	SEIDLE, W C.	8011040660	50-382 Q
ROSS, J F	8011120131	PR	SCHAPKER, J F	8011180391*	50-483 Q	SEIDLE, W C.	8011040668	50-445 Q
ROSS, T K	8011040014*	50-281 P	SCHER, J L	8011210499*	50-298 B	SEIDLE, W C.	8011200102*	50-439 Q
ROSS, D F.	8011040488*	50-289 T	SCHERER, C L	8011240316	50-289 H	SEIDLE, W. C	8011200098	50-458 Q
ROSS, W J	8011210113	50-334 P	SCHENDEL, K. R.	8011070293	40-8502	SEIDLE, W C.	8011170720	50-482 Q
ROSS, H. H	8011050202	PR	SCHENDEL, K. R	8011110188	40-8304	SEIDLE, W C.	8011190283	50-382 Q
ROSTOCZY, Z R.	8011040480*	50-289 T	SCHERER, A. E.	8011110461	TOPREP	SEIDLE, W. C.	8011250126	50-482 Q
ROSTOCZY, Z R.	8011200237	NIBC	SCHERER, A. E	8011120491	TOPREP	SEIDLE, W C.	8011210621	50-445 Q
ROTH, J	8011260126*	40-672	SCHMIDT, L	8011050163	PR	SEIDLE, W. C.	8011210753	50-498 Q
ROTHE, P H	8011140200	NUREO	SCHMILL, H.	8011110160	40-8743	SEIDLE, W. C.	8011260413	50-382 Q
ROTHE, R E	8011140324	NUREO	SCHMIDT, A D.	8011040487	50-335 S	SEIFFERT, S. L.	8011030937	RES
ROTHBERG, R	8011040472*	50-336 B	SCHMIDT, H C.	8011140458	50-445 A	SEIKEN, S. J.	8011170550	50-482 Q
ROTHLEBERGER	8011210014	PR	SCHMIDT, A D.	8011100476	50-335 B	SEIKEN, S. J.	8011120497	50-482 B
ROTHSCHILD, H U	8011080432	50-445 Q	SCHMIDT, H. C	8011040593	50-445 A	SEKULER, S	8011050211	50-461 Q
ROTHSCHILD, H U.	8011100430	70-1308	SCHMIDT, A. D.	8011180599*	50-250 R	SELBY, J M	8011210718*	50-267 Q
ROTHSCHILD, H U	8011120082	50-369 Q	SCHMIDT, D. F.	8011170212*	50-483 Q	SELBY, J M.	8011260283*	50-254 Q
ROTHSCHILD, H U	8011120087*	50-369 Q	SCHMIDT, D. F.	8011170221*	50-483 Q	SELLS, D.	8011190927	50-352 A
ROW, D. O	8011210264	NUREO	SCHNEIDER, R. A.	8011100096*	70-1257	SELLS, D. E.	8011120328	50-352 H
ROWE, C. A.	8011140677*	40-8412	SCHNEIDER, F. W	8011180895*	50-272 Q	SELLS, D.	8011190466	50-498 A

PERSONAL AUTHOR INDEX

329

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SEKEL, H	8011180095	50-153 Q	SHEA, J R	8011190010	SECY	SMITH, C V	8011200391*	SECY
SEKEL, H	8011250043	50-153 Q	SHEA, J R	8011190666	XPORTLIC	SMITH, I H	8011100261*	50-395 Q
SEKEL, H	8011250043	50-153 Q	SHEA, J R	8011180601	XPORTLIC	SMITH, O H	8004070383	70-364
SEKEL, H E	8011190275	PR	SHEA, J R	8011240059	XPORTLIC	SMITH, O H	8011190624*	50-229 Q
SEYFRIT, K V	8011040103*	QA999	SHEA, K H	8011140498	50-367 Q	SMITH, A E	80111060137*	50-289 R
SEYFRIT, K V	8011040099	QA999	SHEA, K H	8011140498	50-367 Q	SMITH, O H	8011170939*	50-219 Q
SEYFRIT, K V	8011110021	QA999	SHEA, J R	8011250711	XPORTLIC	SMITH, B W	8011050241*	50-302 Q
SEYFRIT, K V	8011170845*	QA999	SHEA, J R	8011250715	XPORTLIC	SMITH, O H	8011050517	70-135
SEYFRIT, K V	8011070062	50-445 Q	SHEA, J R	8011250718	XPORTLIC	SMITH, O H	8011070494*	70-1100
SEYFRIT, K V	8011130327	QA999	SHEA, K H	8011250184	50-367 Q	SMITH, O H	8011100456*	70-1143
SEYFRIT, K V	8011130331	QA999	SHEA, K H	8011280033	50-367 Q	SMITH, O	8011100388*	50-333 Q
SEYFRIT, K V	8011130333	QA999	SHEALY, H Q	8011040235	PRDJ	SMITH, O H	8011070528	70-398
SEYFRIT, K V	8011130335	QA999	SHEARER, J	8010220524	50-387 Q	SMITH, O H	8011210556*	50-309 Q
SEYFRIT, K V	8011130337	QA999	SHEDELSKY, J T	8011190602*	50-245 Q	SMITH, J R	8011070142*	REVIEW GRP
SEYFRIT, K V	8011130339	QA999	SHELDON, K P	8011180024*	50-367 Q	SMITH, O H	8011210724*	50-213 Q
SEYFRIT, K V	8011130342	QA999	SHELLY, F L	8011180752*	50-320 H	SMITH, O H	8011130054	50-311 Q
SEYFRIT, K V	8011130345	QA999	SHELLEY, W J	8011030060	REQD	SMITH, R H	8011100373*	50-387 Q
SEYFRIT, K V	8011130349	QA999	SHELLEY, W T	8011190025	40-8027	SMITH, R H	8011210402*	50-289 Q
SEYFRIT, K V	8011130353	QA999	SHELLEY, W J	8010290375	40-8727	SMITH, B	8011170066*	50-302 Q
SEYFRIT, K V	8011130357	QA999	SHEPLEY, S E	8011180860*	50-373 Q	SMITH, T H	8011200151*	50-213 Q
SEYFRIT, K V	8011130360	QA999	SHEER, T. B.	8011100123*	FOIA	SMITH, O H	8011100359	70-1143
SEYFRIT, K V	8011130364	QA999	SHERWOOD, Q Q	8011070041*	10CFR	SMITH, J H	8011170855	RES
SEYFRIT, K V	8011130366	QA999	SHERWOOD, Q Q	8011030629	50-237 B	SMITH, J D	8011240113*	50-346 Q
SEYFRIT, K V	8011130370	QA999	SHERWOOD, Q Q	8011070085*	10CFR	SMITH, T. H.	8011190602*	50-245 Q
SEYFRIT, K V	8011130373	QA999	SHEWENSKI, W J	8011100667*	50-237 T	SMITH, O H	8011070484	70-1100
SEYFRIT, K V	8011130376	QA999	SHIELDS, S W	8011030686*	50-546 S	SMITH, O H	8011190250	50-146 Q
SEYFRIT, K V	8011130380	QA999	SHIELDS, S W	8011050185	PR	SMITH, O H	8011190609	50-29 Q
SEYFRIT, K V	8011130383	QA999	SHIELDS, S W	8011030584	50-546 S	SMITH, O H	8011170932	50-219 Q
SEYFRIT, K V	8011130386	QA999	SHIELDS, S W	8011210287	NUREQ	SMITH, R H	8011120648	71-371
SEYFRIT, K V	8011130390	QA999	SHIELDS, S W	8011200011	50-546 A	SMITH, J. B.	8011190179	40-8743
SEYFRIT, K V	8011130393	QA999	SHIELDS, S W	8011170169	50-546 Q	SMITH, O H	8011210326	50-307 Q
SEYFRIT, K V	8011130397	QA999	SHIELDS, S W	8011200032	50-546 A	SMITH, O H	8011210711	50-213 Q
SEYFRIT, K V	8011140117	50-298 Q	SHIELDS, S W	8011100398	50-546 S	SMITH, R L	8011040398	50-271 P
SEYFRIT, K V	8011140123	50-313 Q	SHIELDS, S W	8011100477	50-546 S	SMITH, D	8011140309	NUREQ
SEYFRIT, K V	8011140126	50-267 Q	SHIELDS, S W	8011140395	50-546 H	SMITH, B W	8011030664	NUREQ
SEYFRIT, K V	8011140130	50-285 Q	SHIELDS, S W	8011210734*	50-546 A	SMITH, I W	8011170896	50-289 Q
SEYFRIT, K V	8011200102*	50-458 Q	SHIELDS, S W	8011190533	50-546 B	SMITH, O H.	8011240454	70-820
SEYFRIT, K V	8011210714	50-267 Q	SHIELDS, S W	8011250413	50-546 A	SMITH, R. L.	8011240083	50-271 P
SEYFRIT, K V	8011200063	50-498 Q	SHIELDS, S W	8011250434	50-546 S	SMITH, I W	8011280006	50-287 Q
SEYFRIT, K V	8011060745	50-298 Q	SHIELDS, S W	8011250289	50-546 S	SHOKER, C B	8011180678*	50-305 S
SEYFRIT, K V	8011060749	50-285 Q	SHIMA, S	8011210101	XPORTLIC	SHNAIDER, R. P.	8011100060	GEN TEC IS
SEYFRIT, K V	8011060751	50-267 Q	SHIVELY, C N	801110273*	50-313 S	SHOW, B A	8011180590	50-244 R
SEYFRIT, K V	8011060757	50-445 Q	SHIVELY, C N	801110287*	50-368 S	SHYDER, B. J.	8010240636	50-320 H
SEYFRIT, K V	8011060761	50-498 Q	SHIVELY, C N	8011140386*	50-368 S	SHYDER, B. J.	8011190342*	50-320 P
SEYFRIT, K V	8011060765	50-498 Q	SHIVELY, C N	8011210609*	50-368 S	SHYDER, B. J.	8011040102	50-320 H
SEYFRIT, K V	8011060768	50-482 Q	SHIVELY, C N	8011210390*	50-368 S	SHYDER, B. J.	8011040108	50-320 H
SEYFRIT, K V	8011060770	50-382 Q	SHIVELY, C N	8011210626*	50-313 S	SHYDER, B. J.	8011190659	50-289 H
SEYFRIT, K V	8011060774	50-313 Q	SHIVELY, C N	8011280052*	50-368 S	SHYDER, B. J.	8011190678	50-320 H
SEYFRIT, K V	8011260197*	50-498 Q	SHORB, E M	8011140489*	50-367 Q	SHYDER, B. J.	8011040070	50-320 H
SEYFRIT, K V	8011260195	50-498 Q	SHORB, E M	8011040429	50-367 A	SHYDER, B. J.	8011060208	50-320 H
SEYFRIT, K V	8011280208	50-498 Q	SHORB, E M	8011210566	50-367 A	SHYDER, B. J.	8011060221	50-320 H
SEYFRIT, K V	8011280212*	50-498 Q	SHUM, E Y	8011200919*	70-143	SHYDER, B. J.	8011060237	50-320 H
SEYFRIT, K V	8011040603	50-498 A	SIDES, W H	8011240101	NUREQ	SHYDER, B. J.	8011060517	50-320 H
SEYFRIT, K V	8011130037	50-498 Q	SIEPKEN, D L	8011110115	27-39	SHYDER, B. J.	8011060611	50-320 H
SEYFRIT, K V	8011130040	50-482 Q	SIEGEL, B L	8011070080	TOPREP	SHYDER, B. J.	8011070168	50-320 H
SEYFRIT, K V	8011130044	50-458 Q	SIEGEL, B. A.	8011110070	PR	SHYDER, B. J.	8011100271	50-320 H
SEYFRIT, K V	8011130048	50-382 Q	SIEGEL, W D	8011180354	FOIA	SHYDER, B. J.	8011100234	50-320 H
SEYFRIT, K V	8011130052	50-445 Q	SIMMEL, I.	8011140300*	50-367 Q	SHYDER, B. J.	8011100247	50-320 H
SEYFRIT, K V	8011170019	50-382 Q	SILBERG, J E	8011050408	50-387 Q	SHYDER, B. J.	8011100493	50-320 H
SEYFRIT, K V	8011170023	50-482 Q	SILBERG, J E	8011050408	50-387 Q	SHYDER, B. J.	8011130167	50-320 H
SEYFRIT, K V	8011170025	50-458 Q	SILBERG, J E	8011130334	50-387 Q	SHYDER, B. J.	8011040626	50-320 Y
SEYFRIT, K V	8011170029	50-445 Q	SILBERG, J E	8011130350*	50-387 Q	SHYDER, B. J.	8011110762	50-320 P
SEYFRIT, K V	8011170031	50-498 Q	SILBERG, J E	8011130375*	50-387 Q	SHYDER, B. J.	8011120605	50-320 P
SEYFRIT, K V	8011170609	50-445 Q	SILBERG, J E	8011130334	50-387 Q	SHYDER, B. J.	8011120607	50-320 P
SEYFRIT, K V	8011170611	50-498 Q	SILBERG, J E	8011130350*	50-387 Q	SHYDER, B. J.	8011060662	50-320 P
SEYFRIT, K V	8011170615	50-382 Q	SILBERG, J E	8011130334	50-387 Q	SHYDER, B. J.	8011110566	50-320 T
SEYFRIT, K V	8011170619	50-458 Q	SILBERG, J E	8011130350*	50-387 Q	SHYDER, B. J.	8011110626	50-320 H
SEYFRIT, K V	8011170623	50-482 Q	SILBERG, J E	8011130375*	50-387 Q	SHYDER, B. J.	8011110788	50-320 H
SHAFER, R	8011060572*	50-286 P	SILVER, R D	8002140231	50-255 P	SHYDER, B. J.	8011120017	50-320 H
SHAFER, D Q	8011260065	50-219 P	SIMANIS, A.	8011040227	PRDJ	SHYDER, B. J.	8011120038	50-320 Q
SHAFNER, J	8011060248	27-39	SIMCHUK, J D.	8011040027	71-9132	SHYDER, B. J.	8011180522	50-320 H
SHAFNER, J	8011060388	27-39	SIMONETTI, Q	8011130050*	50-289 Q	SHYDER, B. J.	8011120042	50-320 T
SHAIN, W Q	8011240287	50-289 H	SIMONIAN, S B.	8011030658	NUREQ	SHYDER, B. J.	8011130001	50-320 P
SHALLER, D V	8011180615	50-315 R	SINGH, K P.	8011050294*	50-341 A	SHYDER, D. J.	8011050573	50-320 T
SHALLER, D. V.	8011180641	50-316 R	SINISGALLI, A J	8011180841*	CONTRACT	SHYDER, R J	8011170027	50-320 H
SHALL, L C	8011190163*	50-548 Q	SINKIN, S A	8011250588	50-498 Q	SHYDER, B. J.	8011170045	50-320 H
SHANKAWY, H	8011130136*	50-289 Q	SINKLE, T. J	8011060577*	50-286 P	SHYDER, B. J.	8011170102	50-320 H
SHAFAR, H K	8011200402*	SECY	SINKNER, P	8011140316*	50-160 Q	SHYDER, B. J.	8011180077	50-320 H
SHAFAR, H K	8011050465	50-272 Q	SKLAR, J B	8011250214*	50-219 R	SHYDER, B. J.	8011180097	50-320 H
SHAFAR, H K	8011070240	50-466 Q	SKOVHOLT, D J	8011060542	HTCC	SHYDER, B. J.	8011120553	50-320 H
SHEA, J. R.	8010220457	SECY	SLABACK, L. A	8011250091	PR	SHYDER, B. J.	8011130049	50-320 T
SHEA, J. R.	8010300009	SECY	SMEDIRA, C	8011100249*	71-121	SHYDER, B. J.	8011170889	50-320 H
SHEA, J. R.	8010300493	SECY	SMEDIRA, C	8011100245*	71-121	SHYDER, B. J.	8011180526	50-320 H
SHEA, J. R.	8011120037	XPORTLIC	SMEDIRA, C.	8011180503	71-9044	SHYDER, B. J.	8011180177	50-320 H
SHEA, J. R.	8011140656	SECY	SMIDA, Q	8011170524*	50-275 H	SHYDER, B. J.	8011180188	50-320 H

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SNYDER, B J	8011180747	50-320 H	STARK, R M	8011170053	50-483 C	STREETER, J F	8011210174*	50-305 G
SNYDER, B J	8011190138	50-320 H	STARKEY, R B	8011140391	50-261 R	STREIT, R D	8011190085	NUREG
SNYDER, B J	8011190157	50-289 H	STARKEY, R M	8011200353	50-483 A	STRONO, T R	8011170534*	State Prog
SNYDER, B J	8011190168	50-320 H	STARKEY, R B	8011170432	50-261 S	STROBINDER, J	8011170721	NUREG
SNYDER, B J	8011190181	50-320 H	STARKEY, R B	8011170444*	50-261 S	STRUMWASSER	8011050168	PROJ
SNYDER, B J	8011190189	50-320 H	START, O E	8010230019	NUREG	STUKENBROEKER	8004080069	XPORTLIC
SNYDER, B J	8011200092	50-320 P	STEED, L B	8011040377*	50-334 R	STULL, J E	8011190690*	50-320 H
SNYDER, B J	8011180016	50-320 H	STEELE, K E	8011280173	State Prog	STULL, J E	8011190684*	50-320 H
SNYDER, B J	8011190351	50-320 H	STEFFES, C	8011140019*	50-254 S	SU, T H	7903120459	50-220 P
SNYDER, B J	8011190355	50-320 H	STEKA, T	8011170066*	50-302 Q	SUDD, Y	8011120632	NUREG
SNYDER, B J	8011190545	50-320 H	STELLO, V	8011120687	SECY	SULLIVAN, O	8011100327	50-387 Q
SNYDER, B J	8011190549	50-320 H	STELLO, V	8011060257	50-293 Q	SULLIVAN, T J	8011210038	NUREG
SNYDER, B J	8011190553	50-320 H	STELLO, V	8010220338	SECY	SUMMERS, R	801070537*	70-135
SNYDER, B J	8011200424	50-320 H	STELLO, V	8011060801	50-289 Q	SURPRENANT, E L	801050217	PR
SNYDER, B J	8011260023*	50-320 Q	STELLO, V	8011060793	50-237 Q	SUTPHIN, R	8011030111*	50-329 G
SOFFER, L	8011170349*	50-367 A	STELLO, V	8011060797*	50-237 Q	SUTTON, J W	8011040156*	GA999
SOLARI, A J	8011120167	FR	STELLO, V	8011060216	50-333 Q	SWANDY, O T	8011060046	50-3453
SOLBRIG, C H	8011060124	RES	STELLO, V	8011060225*	50-333 Q	SWANDY, O T	801050228	40-3453
SOLEN, E L	8011060577*	50-285 P	STELLO, V	8011210623	50-293 Q	SWANDY, O T	8011190022	40-3453
SOON, A L	8011180192*	70-267	STELLO, V	8011210637*	50-293 Q	SWARTZMAN, O L	8011180165*	FOIA
SOON, A L	8011110010*	70-162	STELLO, V	8011140673	50-255 Q	SWARTZMAN, O	8011180171*	FOIA
SOON, A L	8011180173*	70-267	STELLO, V	8011170256	50-397 Q	SWART, F E	8011210312	50-267 P
SOUDER, J L	8011060016	50-266 F	STELLO, V	8011210741	50-346 A	SWART, F E	8011180440	50-267 P
SOUDER, J L	8011060012	50-266 F	STELLO, V	8011200472	50-237 Q	SWEENEY, L E	8011030628	50-289 T
SOUDER, J L	8011060019	50-338 F	STEPHEN, C R	8011200295	50-445 Q	SWEENEY, L E	8011030352	50-289 T
SOUDER, J L	8011060177	50-206 F	STEPTOE, P P	8011040315	50-10 Q	SWEENEY, L E	8011040412	50-289 T
SOUDER, J L	8011130103	50-395 F	STEPTOE, P P	8011050216	50-237 Q	SWEENEY, L E	8011040435	50-289 T
SOUDER, J L	8011050434*	50-445 Q	STEPTOE, P P	8011050381	50-237 Q	SWEENEY, L E	8011110281	50-289 T
SOUDER, J L	8011120593	50-338 F	STEPTOE, P P	8011060453	50-237 Q	SWEENEY, L E	8011210343	50-289 T
SOUDER, J C	8011170126	50-266 F	STEPTOE, P P	8011100630	50-237 T	SWEENEY, L E	8011180224	50-289 T
SOUDER, J L	8011170138	50-338 F	STEPTOE, P P	8011170235	50-373 Q	SWETLAND, P D	8011250692*	50-309 Q
SOUDER, J L	8011170132	50-327 F	STEPTOE, P P	8011180129	50-237 Q	SYLVIA, B R	8011200379*	50-280 Q
SOUDER, J L	8011170001	50-352 F	STERNBERG, D H	8011030280*	50-344 Q	SYLVIA, B R	8011040151	50-338 Q
SOUDER, J L	8011170003	50-329 F	STERNBERG, D	8011100531*	50-289 Q	SYLVIA, B R	8011040330*	50-280 Q
SOUDER, J L	8011170007	50-245 F	STERNBERG, D H	8011100069*	50-288 Q	SYLVIA, B R	8011100431	50-280 Q
SOUDER, J L	8011170011	50-295 F	STERN, W C	8011030106	XPORTLIC	SYLVIA, B R	8011030645	50-338 F
SOUDER, J L	8011170017	50-289 F	STERNBERG, D H	8011030347*	50-344 Q	SYLVIA, B R	8011040312	50-339 P
SOUDER, J L	8011170021	50-220 F	STERN, W C	8011030464	XPORTLIC	SYLVIA, B R	8011040327	50-280 Q
SOUDER, J L	8011180317	50-3 F	STETKA, T F	8011030241*	50-302 Q	SYLVIA, B R	8011040506	50-280 F
SOUDER, J L	8011180321	50-443 F	STEVENSON, H O	8011140282	NUREG	SYLVIA, B R	8011040519*	50-280 F
SOUDER, J L	8011180323	50-322 F	STEVENSON, R L	8011130013*	70-1966	SYLVIA, B R	8011070376	50-339 R
SOUDER, J L	8011180328	50-309 F	STEVENSON, R L	8011190613*	70-371	SYLVIA, B R	8011260338	50-280 Q
SOUDER, J L	8011180331	50-341 F	STEVENSON, R L	8011190755*	70-2913	SYLVIA, B R	8011070479	50-280 Q
SOUDER, J L	8011180336	50-367 F	STEVENSON, S C	8011120469	50-285 S	SYLVIA, B R	8011100509	50-339 P
SOUDER, J L	8011180337	50-334 F	STEVENSON, S C	8011230465	50-285 S	SYLVIA, B R	8011100367	50-338 P
SPANGLER, R O	8011050386*	50-298 Q	STEWART, R C	8011040665*	50-382 Q	SYLVIA, B R	8011100464	50-339 P
SPANGLER, R O	8011060110*	50-298 Q	STEWART, R C	8011190289*	50-382 Q	SYLVIA, B R	8011110320	50-280 P
SPANGLER, R O	8011260106*	50-298 Q	STIEDE, B	8006020268	TOPREP	SYLVIA, B R	8011110335	50-338 P
SPARKS, D T	8011040082	RES	STOCKB, B	8011120090	PR	SYLVIA, B R	8011120281	50-280 Q
SPECTOR, S H	8011040466*	50-244 S	STODDARD, J	8011190183	NUREG	SYLVIA, B R	8011210352	50-280 Q
SPENCER, O S	8011190453*	50-460 Q	STODDART, P O	8011040900*	50-289 T	SYLVIA, B R	8011140387	50-280 R
SPENCER, O S	8011050400	50-344 Q	STOHR, J P	8011130207*	50-400 Q	SYLVIA, B R	8011200298	50-338 R
SPENCER, O S	8011100070	50-312 Q	STOHR, J P	8011060613*	70-1113	SYLVIA, B R	8011240300	50-288 P
SPENCER, O S	8011190449	50-460 Q	STOHR, J P	8011100089	40-8549	SYLVIA, B R	8011210216	50-280 P
SPENCER, J S	8011190014	50-461 A	STOHR, J P	8011100104	50-259 Q	SYLVIA, B R	8011260263	50-339 P
SPENCER, O S	8011050356	50-528 Q	STOHR, J P	8011040565	50-348 Q	SYLVIA, B R	8011240091	50-281 S
SPENCER, O S	8011100061	50-275 Q	STOHR, J P	8011210083*	50-327 Q	SYLVIA, B R	8011240349	50-280 Q
SPENCER, J S	8011200203	50-461 A	STOHR, J P	8011050281	50-364 Q	SYLVIA, B R	8011250355	50-280 P
SPENCER, O S	8011200117*	50-460 Q	STOHR, J P	8011260399	70-143	SYSLD, J	8011110322*	50-346 S
SPESBARD, R L	8011190526*	50-10 Q	STOHR, J P	8011210129*	50-369 Q	SZHAJKOWSKI, R	8011050171	70-1308
SPESBARD, R L	8011180860*	50-373 Q	STOHR, J P	8011210405	50-327 Q	SZHAJKOWSKI, R	8011050171	70-1308
SPESBARD, R L	8011240098*	50-254 Q	STOHR, J P	8011200915*	70-143	SZHAJKOWSKI, R	8011050410	70-1308
SPESBARD, R L	8011110034*	50-10 Q	STOHR, J P	8011260240*	50-369 Q	SZHAJKOWSKI, R	8011050411*	70-1308
SPESBARD, R L	8011240084*	50-295 Q	STOHR, J P	8011050148	50-327 P	SZHAJKOWSKI, R	8011050410	70-1308
SPETH, O	8011190353*	50-320 P	STOHR, J P	8011050501	50-321 Q	SZHAJKOWSKI, R	8011050411*	70-1308
SPIEGEL, O	8011140542	50-445 H	STOHR, J P	8011050467	50-250 Q	SZHAJKOWSKI, R	8011110587	70-1308
SPIEGEL, O	8011140542	50-445 H	STOHR, J P	8011130187*	50-400 Q	SZHAJKOWSKI, R	8011110587	70-1308
SPIEGEL, N W	8011050164	50-396 Q	STOHR, J P	8011130172	50-400 Q	SZHAJKOWSKI, R	8011180037	70-1308
SPIEGEL, N W	8011050144	50-396 Q	STOHR, J P	80111240569	70-27	SZHAJKOWSKI, R	8011180037	70-1308
SPITZNGLE, L A	8011250154	PR	STOHR, J P	8011240589	70-1201	TABOAS, A L	8011030017*	70-8
SPRAQUE, O R	8011190394*	50-443 A	STOHR, J P	8011240591	70-1151	TAMBLING, T N	8011240113*	50-344 Q
SPRAQUE, O R	8011190383*	50-443 A	STOHR, J P	8011250002	70-1113	TANG, D T	8011050449*	TOPREP
SPRING, E R	8011120606	50-289 Q	STOHR, J P	8011250007	70-143	TAPIA, J I	8011250132*	50-482 Q
STAHL, C	8011060563	50-259 F	STOHR, J P	8011210068	50-327 Q	TAUBER, H	8011250282	NUREG
STAHL, D H	8011050200	50-237 Q	STONE, C H	8011170697	NUREG	TAWA, K	8011030131	XPORTLIC
STAHL, D H	8011050200	50-237 Q	STONE, J	8011180066*	CONTRACT	TAWA, K	8011110221*	XPORTLIC
STAHL, D H	8011100416*	50-295 S	STOREY, K	8011050145	PROJ	TAWA, K	8011070120*	XPORTLIC
STAHL, D H	8011250343*	50-295 S	STOTT, S J	8011280231	NUREG	TAYLOR, R O	8011100116*	50-445 Q
STARKEY, R B	8011050257*	50-261 Q	STOTZ, J	8011110272*	50-346 S	TAYLOR, P A	8011210093*	50-327 Q
STARKEY, R B	8011030417	50-261 S	STRACCI, F P	8011101236	PR	TAYLOR, R O	8011210631*	50-445 Q
STARKEY, R B	8011030423*	50-261 S	STRACHAN, A R	8011040447*	50-206 S	TAYLOR, R R	8011100145	71-248
STARKEY, R B	8011070153	50-387 A	STRAIT, R A	8011030582	40-8743	TAYLOR, J H	8011040550	TOPREP
STARKEY, R B	8011100027	50-482 A	STRAUB, B B	8011260175	50-247 H	TAYLOR, R R	8011180876	XPORTLIC
STARKEY, R B	8011100386	50-261 S	STREETER, J F	8011180114*	50-409 Q	TAYLOR, C H	8011120313	70-2313
STARKEY, R B	8011100391*	50-261 S	STREETER, J F	8011210190*	50-263 Q	TAYLOR, J H	8011180258	TOPREP

PERSONAL AUTHOR INDEX

331

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TEDESCO, R. L.	8011030219	50-445 A	TOLLISON, A. C.	8011120577	50-324 S	TRIMBLE, D. C.	8011110280	50-368 S
TEDESCO, R. L.	8011030208	50-445 A	TOLLISON, A. C.	8011030413	50-324 S	TRIMBLE, D. C.	8011110295	50-368 S
TEDESCO, R. L.	8011030588	50-389 A	TOLLISON, A. C.	8011030418*	50-324 S	TRIMBLE, D. C.	8011110029	50-368 S
TEDESCO, R. L.	8011030525	50-352 A	TOLLISON, A. C.	8011030421	50-324 S	TRIMBLE, D. C.	8011110032	50-368 S
TEDESCO, R. L.	8011030535	50-498 A	TOLLISON, A. C.	8011030425*	50-324 S	TRIMBLE, D. C.	8011100313	50-313 P
TEDESCO, R. L.	8011060054	50-440 A	TOLLISON, A. C.	8011100469	50-325 S	TRIMBLE, D. C.	8011110261	50-313 S
TEDESCO, R. L.	8011050591	50-311 H	TOLLISON, A. C.	8011100473*	50-325 S	TRIMBLE, D. C.	8011110250	50-313 P
TEDESCO, R. L.	8011110170	50-329 A	TOLLISON, A. C.	8011040454	50-324 S	TRIMBLE, D. C.	8011110278	50-313 P
TEDESCO, R. L.	8011060525	TOPREP	TOLLISON, A. C.	8011040462*	50-324 S	TRIMBLE, D. C.	8011110414	50-313 R
TEDESCO, R. L.	8011060068	50-395 V	TOLLISON, A. C.	8011100462	50-324 S	TRIMBLE, D. C.	8011110277	50-368 S
TEDESCO, R. L.	8011100408	50-387 A	TOLLISON, A. C.	8011100465*	50-324 S	TRIMBLE, D. C.	8011110383	50-368 S
TEDESCO, R. L.	8011100421	50-387 A	TOLLISON, A. C.	8011120450	50-324 S	TRIMBLE, D. C.	8011110385	50-368 S
TEDESCO, R. L.	8011110745	TOPREP	TOLLISON, A. C.	8011120460*	50-324 S	TRIMBLE, D. C.	8011120466	50-368 S
TEDESCO, R. L.	8011170439	50-395 A	TOLLISON, A. C.	8011140010	50-324 S	TRIMBLE, D. C.	8011170484	50-313 S
TEDESCO, R. L.	8011170774	50-395 A	TOLLISON, A. C.	8011140013*	50-324 S	TRIMBLE, D. C.	8011180507	50-368 S
TEDESCO, R. L.	8011110571	50-373 A	TOLLISON, A. C.	8011140039	50-325 S	TRIMBLE, D. C.	8011170480	50-368 S
TEDESCO, R. L.	8011140298	50-339 P	TOLLISON, A. C.	8011140044*	50-325 S	TRIMBLE, D. C.	8011180669	50-313 S
TEDESCO, R. L.	8011170576	50-416 A	TOLLISON, A. C.	8011140394	50-324 R	TRIMBLE, D. C.	8011210595	50-368 S
TEDESCO, R. L.	8011170579	50-373 A	TOLLISON, A. C.	8011140442	50-324 S	TRIMBLE, D. C.	8011180417	50-368 R
TEDESCO, R. L.	8011190287	50-311 V	TOLLISON, A. C.	8011140450*	50-324 S	TRIMBLE, D. C.	8011210453	50-368 S
TEDESCO, R. L.	8011200499	50-341 A	TOLLISON, A. C.	8011180713	50-324 S	TRIMBLE, D. C.	8011240292	50-313 P
TEDESCO, R. L.	8011200551	50-498 A	TOLLISON, A. C.	8011180721*	50-324 S	TRIMBLE, D. C.	8011240376	50-368 P
TEDESCO, R. L.	8011190137	50-369 A	TOLLISON, A. C.	8011180574	50-324 S	TRIMBLE, D. C.	8011210584	50-368 S
TEDESCO, R. L.	8011190872	50-369 A	TOLLISON, A. C.	8011180661	50-324 S	TRIMBLE, D. C.	8011210609	50-313 S
TEDESCO, R. L.	8011200044	50-339 P	TOLLISON, A. C.	8011180718	50-324 S	TRIMBLE, D. C.	8011250316	50-313 S
TEDESCO, R. L.	8011200354	50-327 P	TOLLISON, A. C.	8011180725*	50-324 S	TRIMBLE, D. C.	8011250469	50-313 S
TEDESCO, R. L.	8011210253	50-440 A	TOLLISON, A. C.	8011210470	50-325 S	TRIMBLE, D. C.	8011280049	50-368 S
TEDESCO, R. L.	8011260239	50-348 P	TOLLISON, A. C.	8011210472*	50-325 S	TRIPPODEB, J. O.	8011110130	FR
TEDESCO, R. L.	8011180291	50-2 P	TOLLISON, A. C.	8011210451	50-324 S	TRIPP, L. E.	8011200134*	50-245 Q
TEDESCO, R. L.	8011190580	50-369 A	TOLLISON, A. C.	8011210452*	50-324 S	TRIPP, L. E.	8011100298*	50-289 Q
TEDESCO, R. L.	8011210010	50-361 A	TOLLISON, A. C.	8011250414	50-324 S	TRIPP, L. E.	8011100379*	50-213 Q
TEDESCO, R. L.	8011190448	50-311 P	TOLLISON, A. C.	8011250417*	50-324 S	TRIPP, L. E.	8011200104*	50-336 Q
TEDESCO, R. L.	8011210176	TOPREP	TOLLISON, A. C.	8011250422	50-324 S	TRIPP, L. E.	8011280176*	50-220 Q
TEDESCO, R. L.	8011190588	50-416 C	TOLLISON, A. C.	8011250426*	50-324 S	TROSKOSKI, H.	8011200056*	50-334 Q
TEDESCO, R. L.	8011190654	50-397 A	TOLLISON, A. C.	8011250431	50-324 S	TROUP, O. L.	8011050286*	50-364 Q
TEDESCO, R. L.	8011200220	50-339 P	TOLLISON, A. C.	8011250446*	50-324 S	TROUP, O. L.	8011280242*	50-369 Q
TEDESCO, R. L.	8011210229	50-329 A	TOLLISON, A. C.	8011250374	50-324 S	TRUSSSELL, H. M.	8011190328	40-8064
TEDESCO, R. L.	8011260326	50-395 A	TOLLISON, A. C.	8011250379*	50-324 S	TU888, R. C.	8011110193*	50-254 R
TEDESCO, R. L.	8011280138	50-329 A	TOLLISON, A. C.	8011250382	50-324 S	TU888, R. C.	8011250352*	50-254 S
TEDESCO, R. L.	8011210481	50-328 A	TOLLISON, A. C.	8011250386*	50-324 S	TUCKER, H. B.	8011260009*	FR
TEDESCO, R. L.	8011260044	50-445 C	TOLLISON, A. C.	8011250478	50-325 S	TUNSTALL, J. E.	8011060296*	CONTRACT
TEDESCO, R. L.	8011260252	50-369 F	TOLLISON, A. C.	8011250483*	50-325 S	TURI, O. P.	8011060248	27-39
TEDESCO, L.	8011260167	50-387 Q	TOLLISON, A. C.	8011250486	50-324 S	TURI, O. P.	8011060388	27-39
TEDFORD, C. F.	8011050140	PROJ	TOLLISON, A. C.	8011250490*	50-324 S	TURK, B. E.	8011200307	70-2909
TEDFORD, C. F.	8011280169	State Prog	TOLLISON, A. C.	8011250489	50-324 S	TURK, B.	8011240186	70-2909
TEDFORD, C. F.	8011210656	PR	TOLLISON, A. C.	8011250497*	50-324 S	TURK, B.	8011250583	50-445 Q
TENIER, B. E.	8011040089*	GA999	TOMPKINS, B. A.	8011070020	50-269 Q	TURNER, B.	8011050294*	50-341 A
TERAO, D.	8011260078	50-339 P	TOMPKINS, B. A.	8011070031	50-272 Q	TURNER, R. D.	8011260304	50-219 P
TERNEY, W. B.	8011110469*	TOPREP	TOMPKINS, B. A.	8011070043	50-155 Q	TUSTUS, P. E.	8010270291	50-397 A
THIES, A. C.	8011210440	50-269 G	TONGUE, T. H.	8011190526*	50-10 Q	TWEED, R. H.	8011200461*	10CFR
THOM, T.	8011180594*	50-239 R	TONGUE, T.	8011110034*	50-10 Q	UDALL, H.	8011110584*	COMMISSION
THOMAS, J. A.	8011170946*	50-219 Q	TOOLE, R. J.	8011120436	50-289 S	UDALL, H. K.	8011050062*	50-296 U
THOMAS, R. D.	8011030047*	70-23 Q	TOTH, A. D.	8011200129*	50-460 Q	UDALL, H. K.	8011050068*	50-296 U
THOMAS, M.	8011040060*	50-390 Q	TOTH, A. D.	8011200117*	50-460 Q	UHRIG, R. E.	8008280384	50-333 P
THOMAS, J. A.	8011200131*	50-219 Q	TOURTELLOTT, J.	8011200067*	50-289 F	UHRIG, R. E.	8010240648	50-250 Q
THOMAS, M.	8011260421*	50-566 Q	TOURTELLOTT, J.	8011190268	50-289 Q	UHRIG, R. E.	8011050473*	50-250 Q
THOMAS, E. B.	8011030477	50-220 P	TOURTELLOTT, J.	8011190200	50-289 Q	UHRIG, R. E.	8011140655	50-250 Q
THOMAS, M. N.	8011040012	50-281 P	TOWSEND, H. C.	8011130144	RES	UHRIG, R. E.	8011070311	50-335 R
THOMAS, J. W.	8011210309	FR	TOYNE, G. H.	8011250272	50-331 J	UHRIG, R. E.	8011070319	50-250 R
THOMAS, E. B.	8011030678	50-341 K	TRAMMELL, C. H.	8011030280*	50-344 Q	UHRIG, R. E.	8011040391	50-250 P
THOMAS, J. Y.	8011170661	NUREO	TRAMMELL, C. H.	8011060253	50-344 P	UHRIG, R. E.	8011120508	50-335 P
THOMAS, R. D.	8011190033	27-10	TRAMM, T. R.	8011110563	50-426 C	UHRIG, R. E.	8011040498	50-389 F
THOMPSON, O. D.	8002260174	50-367 A	TRAMM, T. R.	8011120317	50-295 P	UHRIG, R. E.	8011260153	50-335 Q
THOMPSON, O. D.	8011140569*	50-367 Q	TRAMM, T. R.	8011100389	50-10 P	UHRIG, R. E.	8011030556	50-335 P
THOMPSON, O. D.	8003230884	50-367 A	TRAMM, T. R.	8011120365	50-454 K	UHRIG, R. E.	8011040220	50-335 P
THOMPSON, D.	8011210128*	PR	TRAMM, T. R.	8011180335	50-295 P	UHRIG, R. E.	8011040401	50-250 P
THOMPSON, D.	8011210141*	PR	TRAMM, T. R.	8011170218	50-295 P	UHRIG, R. E.	8011050436	50-250 P
THOMPSON, M. A.	8011110175	WASTE MGT	TRAMMELL, C. H.	8011200413	50-344 P	UHRIG, R. E.	8011050474	50-250 P
THOMPSON, D.	8011060277	50-333 S	TRAMM, T. R.	8011260213	50-295 F	UHRIG, R. E.	8011060260	50-250 P
THOMPSON, M. A.	8011280177	WASTE MGT	TRAUTMAN, D.	8011110238*	50-345 S	UHRIG, R. E.	8011060492	50-369 A
THORNBERG, H. D.	8011170234*	50-259 G	TRAVIESO-DIAZ,	8011130324	50-387 Q	UHRIG, R. E.	8011100490	50-335 P
THORNBERG, H. D.	8011140352	50-397 S	TRAVIESO-DIAZ,	8011130350*	50-387 Q	UHRIG, R. E.	8011140059	50-389 S
THURMAN, P.	8011210450*	50-263 S	TRAVIESO-DIAZ,	8011130373*	50-387 Q	UHRIG, R. E.	8011260147	50-250 Q
TILLMAN, A.	8011210444*	50-324 Q	TRAVIESO-DIAZ,	8011130334	50-387 Q	UHRIG, R. E.	8011070299	50-250 V
TILLMAN, A.	8011030267*	50-321 Q	TRAVIESO-DIAZ,	8011130350*	50-387 Q	UHRIG, R. E.	8011100352	50-250 P
TIMKO, D. R.	8011180476*	50-334 R	TRIMBLE, J. E.	8011030177*	50-271 P	UHRIG, R. E.	8011100390	50-250 P
TITTIM, H.	8011040545	50-369 H	TRIMBLE, D. C.	8011120280*	50-313 Q	UHRIG, R. E.	8011280114	50-230 Q
TITTLE, L. B.	8011060334*	50-302 P	TRIMBLE, D. C.	8011110236*	50-313 Q	UHRIG, R. E.	8011280131	50-335 Q
TODIN, W. J.	8011200497*	50-335 Q	TRIMBLE, D. C.	8011040413	50-313 P	UHRIG, R. E.	8011140134	50-230 P
TODIN, W. J.	8011030275*	70-143	TRIMBLE, D. C.	8011070809	50-313 P	UHRIG, R. E.	8011280135	50-335 Q
TOLLISON, A. C.	8011030410	50-324 S	TRIMBLE, D. C.	8011100326	50-368 P	UHRIG, R. E.	8011190317	50-335 P
TOLLISON, A. C.	8011030618	50-324 S	TRIMBLE, D. C.	8011040245	50-313 P	UHRIG, R. E.	8011202555	50-335 P
TOLLISON, A. C.	8011030414*	50-324 S	TRIMBLE, D. C.	8011050443	50-313 V	UHRIG, R. E.	8011210357	50-389 R
TOLLISON, A. C.	8011030624*	50-324 S	TRIMBLE, D. C.	8011100447	50-368 S	UHRIG, R. E.	8011250193	50-335 P
TOLLISON, A. C.	8011140023	50-324 S	TRIMBLE, D. C.	8011100440	50-368 S	ULLRICH, H. T.	8011060554	50-277 S

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ULLRICH, H. T.	8011120500	50-277 S	VARQA, S. A.	8011120407	50-295 P	WATAUS, C.	8011100339	50-387 Q
ULLRICH, W. T.	8011120510	50-277 S	VARQA, S. A.	8011120410*	50-295 P	WATERS, D. B.	8010290019*	COMM8810N
UNDERWOOD, P. R.	8011190293*	50-321 R	VARQA, S. A.	8011190561	50-280 P	WATERS, J. R.	8011240084*	50-295 Q
URBAN, J. R.	8011180047	50-389 M	VARQA, S. A.	8011050399	50-250 P	WATFORD, M. L.	8011140392*	50-261 R
URBAN, J. R.	8011230036	50-389 M	VARQA, S. A.	8011050603*	50-250 P	WATTS, T. E.	8011210248	50-373 Q
URISH, J.	8011030493	50-461 Q	VARQA, S. A.	8011030609*	50-250 P	WATTS, T. E.	8011210241	50-373 Q
URQUHART, O. T.	8011060399*	50-289 T	VARQA, S. A.	8011050611	50-348 P	WEATHERBEE, L.	8011110180	PR
URQUHART, O. T.	8011190293*	50-289 T	VARQA, S. A.	8011050615*	50-348 P	WEEKS, J. R.	8011180557	50-10 P
UTLEY, E. E.	8011280143	50-261 Q	VARQA, S. A.	8011080618*	50-348 P	WEEKS, J. R.	8011180512	50-10 P
UTLEY, E. E.	8011070498	50-261 Q	VARQA, S. A.	8011170814	50-286 F	WEEKS, J. R.	8011070219*	50-237 T
UTLEY, E. E.	8011120307	50-324 P	VARQA, S. A.	8011100046*	50-247 P	WEEKS, E. D.	8011180576	50-133 R
UTLEY, E. E.	8011120393	50-261 P	VARQA, S. A.	8011100040	50-247 P	WEGST, W.	8011120172	PR
UTLEY, E. E.	8011120437	50-261 V	VARQA, S. A.	8011100044*	50-247 P	WEISS, A. J.	8011000083	50-10 P
UTLEY, E. E.	8011130222	50-324 P	VARQA, S. A.	8011100051*	50-247 P	WEISS, A. J.	8011170613	NUREQ
UTLEY, E. E.	8011140090	50-261 P	VARQA, S. A.	8011140636	50-315 P	WEISS, E. R.	8011060088	50-259 P
UTLEY, E. E.	8011120404	50-261 F	VARQA, S. A.	8011170477	50-295 P	WEISS, E. R.	8011040392	50-443 Q
UTLEY, E. E.	8011180356	50-261 P	VARQA, S. A.	8011170651	50-261 P	WEISS, E. R.	8011040335	50-247 Q
UTLEY, E. E.	8011180377	50-324 P	VARQA, S. A.	8011170735	50-315 P	WEISS, E. R.	8011040392	50-443 Q
UTLEY, E. E.	8011210202	50-325 P	VARQA, S. A.	8011170800	50-247 P	WEISS, C. R.	8011240516	50-247 T
UTLEY, E. E.	8011260192	50-261 P	VARQA, S. A.	8011180194	50-315 F	WEISS, J. D.	8011180525	70-487
UTLEY, E. E.	8011250362	NUREQ	VARQA, S. A.	8011190212	50-315 F	WEISS, E. R.	8011050177	50-443 Q
VALORE, C. J.	8011140101	50-272 Q	VARQA, S. A.	8011190738	50-286 Q	WEISS, E. R.	8011050177	50-443 Q
VAN BRUNT, E. E.	8010240079	50-528 Q	VARQA, S. A.	8011210220	50-250 P	WEISS, D.	8011180878	40-8681
VAN BRUNT, E. E.	8010270462	50-528 T	VARQA, S. A.	8011280085	50-280 P	WEISS, E.	8011240309	50-322 H
VAN BRUNT, E. E.	8011120373	50-528 B	VARQA, S. A.	8011280097	50-3 F	WEISS, E. R.	8011110599	PR
VAN BRUNT, E. E.	8011120477	50-528 B	VASSALLO, D. B.	8011140482*	50-367 Q	WEISS, E. R.	8011110599	PR
VAN BRUNT, E. E.	8011170570	50-528 B	VASSALLO, D. B.	8011190509*	NUREQ	WEISS, E. R.	8011210215	50-269 P
VAN BRUNT, E. E.	8011170577	50-528 B	VAUGHAN, N. D.	8011060408	PR	WEISS, D.	8011210707	40-4492
VAN BRUNT, E. E.	8011170575	50-528 B	VAUGHAN, N. D.	8011060412	PR	WELLS, Q. Z.	8011180038	FDIA
VAN BICKEL, J.	8011120039*	50-331 R	VENEQAN, M.	8011070628	71-9141	WENDERLICH, R. L.	8011070336*	50-317 B
VAN VRANKEN, J.	8011060201	50-237 Q	VERRELLI, D. M.	8011060342	50-277 F	WENDERLICH, R. L.	8011070410*	50-318 B
VAN WINKLE, H.	8011180538	REB	VERRECCHIA, P.	8011110312	FOIA	WENDERLICH, R. L.	8011100453*	50-318 B
VAN WINKLE, H.	8011180729	50-247 P	VERRELLI, D. M.	8011060148	50-321 F	WENDERLICH, R. L.	8011190421*	50-318 B
VANDEL, T. E.	8011030111*	50-327 Q	VERRELLI, D. M.	8011250655*	50-321 F	WENDERLICH, R. L.	8011210334*	50-317 B
VANDEL, T. E.	8011170727*	50-482 Q	VIGIL, J. C.	8011140282	NUREQ	WENDERLICH, R. L.	8011260184*	50-318 B
VANDENBURGH, D.	8011030543	50-29 P	VINCE, M. A.	8011170393	NUREQ	WENNER, B.	8011140404	50-596 Q
VANDENBURGH, D.	8011030599	50-29 P	VINT, J.	8011050282	PROJ	WENGLAWSKI, F.	8011060807*	50-378 Q
VANDELL, T. D.	8011190245	40-299 P	VITTELL, J. B.	8011100333	50-387 Q	WENGLAWSKI, F.	8011070591*	50-94 Q
VANDENBURGH, D.	8011030320	50-29 P	VOGLER, B. H.	8011180162	PROJ	WENGLAWSKI, F. A.	8011070223*	50-187 Q
VANDORRN, P. K.	8011040073*	50-413 Q	VOIGT, H. H.	8011190156	50-548 Q	WENZINGER, E. C.	8011250103	REODD
VARANINI, E. E.	8011110611	PR	VOLLEN, R. J.	8011060463	50-367 Q	WERLING, J. A.	8010120534	50-334 B
VARELA, A. A.	8011200134*	50-245 Q	VOLLEN, R. J.	8011170358	50-367 Q	WERLING, J. A.	8011030479	50-334 B
VARELA, A. A.	8011100292*	50-289 Q	VOLLEN, R. J.	8011170361	50-367 Q	WERLING, J. A.	8011120351	50-334 B
VARELA, A. A.	8011130084*	50-334 Q	VOLLEN, R. J.	8011170358	50-367 Q	WERLING, J. A.	8011120442	50-334 B
VARELA, A. A.	8011100373*	50-387 Q	VOLLEN, R. J.	8011170381	50-367 Q	WERLING, J. A.	8011240298	50-334 B
VARQA, S. A.	8011110003	50-261 F	VOLLEN, R. J.	8011170214	50-367 Q	WERLING, J. A.	8011240273	50-334 B
VARQA, S. A.	8011180009	TOPREP	VOLLEN, R. J.	8011170272*	50-367 Q	WERLING, J. A.	8011240307	50-334 B
VARQA, S. A.	8011100423	50-334 F	VOLLEN, R. J.	8011240170	50-367 Q	WERLING, J. A.	8011250513	50-334 B
VARQA, S. A.	80111004275	50-334 P	VOLLEN, R. J.	8011280005	50-367 Q	WERLING, J. A.	8011250461	50-334 B
VARQA, S. A.	8011100280*	50-334 P	VOLLEN, R. J.	8011280005	50-367 Q	WERLING, J. A.	8011260185	50-334 B
VARQA, S. A.	8011030231	50-261 P	VORDERBRUEGGEN	8011030360*	50-528 Q	WERNER, J.	8011100488*	50-346 B
VARQA, S. A.	8011030238*	50-261 P	VOTH, M. H.	8011130099*	50-54 Q	WESCOTT, H. M.	8011200214*	50-461 Q
VARQA, S. A.	8011030240*	50-261 P	WADE, Q. E.	8011040232*	TOPREP	WEST, E.	8011170137*	MISC
VARQA, S. A.	8011060214	50-315 P	WADE, Q. E.	8011250232*	TOPREP	WEST, J. H.	8011110778	XPORTLIC
VARQA, S. A.	8011060222*	50-315 P	WADE, Q. E.	8011250292*	TOPREP	WEST, J. M.	8011110801	XPORTLIC
VARQA, S. A.	8011060241*	50-315 P	WADE, Q. E.	8011250294*	TOPREP	WEST, J. M.	8011110823	XPORTLIC
VARQA, S. A.	8011100500	50-247 P	WADE, D. C.	8011140434*	50-438 A	WESTERMAN, T. F.	8011050386*	50-298 Q
VARQA, S. A.	8011110128	50-286 P	WADE, D. C.	8011140438*	50-438 A	WESTERMAN, T. F.	8011060110*	50-298 Q
VARQA, S. A.	8011130041	50-334 P	WAGNER, A. Q.	8011060168*	50-364 Q	WESTERMAN, T. F.	8011260081*	50-267 Q
VARQA, S. A.	8011130145	50-230 F	WAGNER, F. T.	8011030082	71-399	WESTERMAN, T. F.	8011260106*	50-298 Q
VARQA, S. A.	8011130154	50-280 F	WALKER, R. D.	8011180860*	50-373 Q	WETTERHAHN, M. J.	8011250578	50-358 Q
VARQA, S. A.	8011100538	50-305 F	WALKER, J.	8011260412	PR	WHICHER, J. M.	8011170214	50-367 Q
VARQA, S. A.	8011030200	50-334 P	WALKUSH, J.	8011190183	NUREQ	WHICHER, J. M.	8011170272*	50-367 Q
VARQA, S. A.	8011030209*	50-334 P	WALLACE, P.	8011190080	NUREQ	WHICHER, J. M.	8011170214	50-367 Q
VARQA, S. A.	8011030223*	50-334 P	WALPOLE, J. R.	8011040403*	40-1162	WHICHER, J. M.	8011170272*	50-367 Q
VARQA, S. A.	8011100546	50-250 P	WALTON, Q.	8011190329*	50-352 Q	WHICHER, J. M.	8011170272*	50-367 Q
VARQA, S. A.	8011110105	50-250 P	WARD, J. D.	8011040169	PROJ	WHITTELL, D. E.	8011240170	50-367 Q
VARQA, S. A.	8011110117	50-250 P	WARD, K. D.	8011250072*	50-440 Q	WHITTELL, D. E.	8011170771*	QA999
VARQA, S. A.	8011100504	50-250 F	WARD, S. M.	8011250331*	50-449 A	WHITTELL, D. E.	8011170861*	QA999
VARQA, S. A.	8011130022	50-261 P	WAREHBOUR, D.	8011100383	50-267 V	WHITE, L. D.	8009030345	50-244 P
VARQA, S. A.	8011130028*	50-261 P	WAREHBOUR, D.	8011210477	50-267 B	WHITE, L. D.	8009030485	50-244 P
VARQA, S. A.	8011130033*	50-261 P	WAREHBOUR, D.	8011210541	50-267 B	WHITTELL, D. E.	8011060316*	QA999
VARQA, S. A.	8011140639	50-281 P	WAREHBOUR, D.	8011210575	50-267 B	WHITTELL, D. E.	8011060278*	QA999
VARQA, S. A.	8011110047	50-247 Q	WAREHBOUR, D. W.	8011120523	50-267 B	WHITTELL, D. E.	8011060321*	QA999
VARQA, S. A.	8011110078	50-348 Q	WAREHBOUR, D. W.	8011180620	50-267 P	WHITTELL, D. E.	8011180340*	QA999
VARQA, S. A.	8011110088	50-334 Q	WAREHBOUR, D.	8011140340	50-267 R	WHITTELL, D. E.	8011060318*	QA999
VARQA, S. A.	8011110100	50-286 Q	WAREHBOUR, D.	8011140399	50-267 B	WHITTELL, D. E.	8011060307*	QA999
VARQA, S. A.	8011110431	50-313 Q	WAREHBOUR, D.	8011140406	50-267 B	WHITTELL, D. E.	8011170388*	QA999
VARQA, S. A.	8011110488	50-261 Q	WAREHBOUR, D. W.	8011250275	50-267 P	WHITENER, H. L.	8011050292*	50-364 Q
VARQA, S. A.	8011110497	50-280 Q	WAREHBOUR, D.	8011180659	50-267 B	WHITE, J. R.	8011240489	50-277 B
VARQA, S. A.	8011110522	50-250 Q	WAREHBOUR, D. W.	8011250258	50-267 F	WHITMAN, Q. D.	8011240440	NUREQ
VARQA, S. A.	8011110573	50-295 Q	WARNICK, R. F.	8011120689*	50-266 Q	WHITNEY, G. O.	8011180434*	50-293 R
VARQA, S. A.	8011140189	50-272 Q	WARNICK, R. F.	8011050142*	50-305 Q	WICHERS, D. L.	8011170293	40-8502
VARQA, S. A.	8011170287	50-305 Q	WARNICK, R. F.	8011240113*	50-346 Q	WICHERS, D. L.	8011170292	40-8502
VARQA, S. A.	8011170456	50-295 P	WARNICK, R. F.	8011210149*	50-266 Q	WICHERS, D. L.	8011190340	40-8502

PERSONAL AUTHOR INDEX

333

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WICKERS, D. L.	8011120635	40-8502	WILSON, B. D.	8011260240	XPORTLIC	YIN, I. T.	8011250144*	50-373 Q
WICKERS, D. L.	8011120643	40-8502	WILSON, J. L.	8011210510	50-280 B	YIN, I. T.	8011040184*	50-295 Q
WICKERS, D. L.	8011120638	40-8502	WILSON, J. L.	8011210522*	50-280 B	YIN, I. T.	8011180797*	50-341 Q
WICKERS, D. L.	8010230193	40-8502	WILSON, J. L.	8011250366	50-280 B	YOUNGBLOOD, B. J.	8010210784	50-369 A
WICKERS, D. L.	8011110646	40-8502	WILSON, J. L.	8011250372*	50-280 B	YOUNGBLOOD, B. J.	8011040261	50-369 P
WICKERS, D. L.	8011170740	40-8502	WINN, L.	8011050230	PR	YOUNGBLOOD, B. J.	8011050012*	50-364 P
WIDNER, W. A.	8011050508*	50-321 Q	WINSTON, G. B.	8011130138	RES	YOUNGBLOOD, B. J.	8011030573*	50-155 P
WIDNER, W. A.	8011050537*	50-321 Q	WITHERSPOON, J.	8011170776	RES	YOUNGBLOOD, B. J.	8011140323	50-397 A
WIDNER, W. A.	8011170427	50-321 Q	WITHERSPOON, J.	8011260022	RES	YOUNG, H. W.	8011240067	NUREO
WIDNER, W. A.	8011070277	50-321 P	WITHERS, B. D.	8011100008	50-344 Q	YOUNGBLOOD, B. J.	8011110049	50-387 A
WIDNER, W. A.	8011070425	50-321 P	WITHERS, B. D.	8011040416	50-344 F	YOUNG, F. W.	8011060478	State Prog
WIDNER, W. A.	8011260192	50-321 Q	WITHERS, B. D.	8011030569	50-344 P	YOUNGBLOOD, B. J.	8011190592	50-369 A
WIDNER, W. A.	8011060466	50-321 V	WITHERS, B. D.	8011030580*	50-344 P	YOUNGBLOOD, B. J.	8011200039	50-339 Q
WIDNER, W. A.	8011060500	50-321 P	WITHERS, B. D.	8011030269	50-344 P	YOUNGBLOOD, B. J.	8011210635	50-389 A
WIDNER, W. A.	8011100472	50-366 Q	WITHERS, B. D.	8011040518	50-344 V	YOUNGBLOOD, B. J.	8011210632	50-397 A
WIDNER, W. A.	8011100478	50-321 Q	WITHERS, B. D.	8011040279	50-344 P	YOUNGBLOOD, B. J.	8011210204	50-500 A
WIDNER, W. A.	8011260142	50-321 Q	WITHERS, B. D.	8011040285*	50-344 P	YOUNGBLOOD, B. J.	8011260038	50-483 A
WIDNER, W. A.	8011210237	50-321 Q	WITHERS, B. D.	8011180381	50-344 P	YOUNGBLOOD, B. J.	8011260248	50-339 P
WIDNER, W. A.	8011240050	50-321 Q	WITHERS, B. D.	8011180394*	50-344 P	YOUNGBLOOD, B. J.	8011260251*	50-339 P
WIDNER, W. A.	8011180432	50-366 P	WITHERS, B. D.	8011200143	50-155 Q	YOUNGBLOOD, B. J.	8011260258*	50-339 P
WIDNER, W. A.	8011210611	50-321 P	WITHERS, B. D.	8011100489	50-155 P	YUNDT, C. P.	8011070413	50-344 B
WIDNER, W. A.	8011180020*	50-320 H	WITHERS, B. D.	8011170571*	50-322 Q	YUNDT, C. P.	8011070495	50-344 B
WIESE, J. H.	8011090016*	70-2709	WOLFE, B. J.	8011070214*	50-237 T	YUNDT, C. P.	8011070521	50-344 B
WIGGINS, E.	8011200036*	50-334 Q	WOLFE, B. J.	8011180083*	50-237 T	YUNDT, C. P.	8011120425	50-344 R
WIGGINS, E.	8011030110	CONTRACT	WOLF, B.	8011100238*	50-320 H	YUNDT, C. P.	8011180671	50-344 B
WIGGINS, E.	8011060294	CONTRACT	WOLFE, B. J.	8011040400	40-1162	YUNDT, C. P.	8011250451	50-344 B
WIGGINS, D.	8011060298	50-247 P	WOLFE, B. J.	8011050137	50-466 Q	ZABEL, B. A.	8011170906*	50-461 Q
WIGGINS, D.	8011070167	50-247 P	WOLFE, B. J.	8011170908	50-466 Q	ZABEL, B. A.	8011170913	50-461 Q
WIGGINS, E. J.	8011170360	CONTRACT	WOLFE, B. J.	8011190188	50-466 Q	ZABEL, B. A.	8011170906*	50-461 Q
WIGGINS, E. J.	8011210006	CONTRACT	WOLFE, B. J.	8011230376	50-374 Q	ZABEL, B. A.	8011170913	50-461 Q
WILBOURNE, J. C.	8011140693*	40-8412	WOLFE, B. J.	8011280010	50-466 Q	ZAHLER, R. E.	8011140075	50-289 Q
WILBUR, L. C.	8011260351	50-134 F	WOLFE, B. J.	8011280012	50-466 Q	ZAHLER, R. E.	8011140075	50-289 Q
WILKEY, A. M.	8011180648*	50-327 B	WOLFE, W.	8011260170*	50-387 Q	ZAHLER, R. E.	8011170231	50-289 Q
WILKEY, A. M.	8011180644*	50-327 B	WOLFE, B. J.	8011280039	50-466 Q	ZAHLER, R. E.	8011190279	50-289 Q
WILLET, D. J.	8011100069*	50-288 Q	WOLFF, T. A.	8011030665	PROJ	ZAHLER, R. E.	8011170231	50-289 Q
WILLIAMS, C. C.	8011260424*	50-546 Q	WOLFF, C. E.	8011110179	40-8602	ZAIS, A. H.	8011180327*	0A999
WILLIAMS, C. C.	8011060133*	50-440 Q	WOLFF, C. W.	8011050151	27-39	ZAIS, A. H.	8011180320*	0A999
WILLIAMS, B. L.	801120113*	COMMISSION	WOLFF, C. W.	8011110393	27-39	ZARAKAS, P.	8011030517	50-247 P
WILLIAMS, C. C.	8011200040*	50-373 Q	WOLFF, C. E.	8011180337	40-8602	ZARAKAS, P.	8011030685	50-247 B
WILLIAMS, C. C.	8011030093*	50-440 Q	WOLLETT, B. A.	8011206640	CONTRACT	ZARAKAS, P.	8011070398	50-247 P
WILLIAMS, C. C.	8011060251*	50-440 Q	WOLTER, E. F.	8011130329*	70-364	ZARAKAS, P.	8011190339	50-247 P
WILLIAMS, C. C.	8011260378*	50-546 Q	WONG, T.	8011230319	40-299	ZARAKAS, P.	8011180457	50-247 R
WILLIAMS, F. J.	8011130066*	50-286 Q	WONG, T.	8011230324	40-299	ZARAKAS, P.	8011180656	50-247 B
WILLIAMS, C. C.	8011040300*	50-546 Q	WOOD, E. C.	8011240341	50-309 B	ZARAKAS, P.	8011180672	50-247 B
WILLIAMS, C. C.	8011040309*	50-546 Q	WOOD, R. S.	8011030810	NUREO	ZARAKAS, P.	8011180683	50-3 R
WILLIAMS, C. C.	8011060311*	50-456 Q	WOODARD, K.	8011210092	REPOD	ZAVADOSKI, R. H.	8011050496*	50-250 Q
WILLIAMS, C. C.	8011180409*	50-373 Q	WOODRUFF, R. L.	8011030696	40-8011	ZEFF, R. W.	8011040036*	70-1201
WILLIAMS, D.	8011100063	FOIA	WOODRUFF, R. L.	8011030682	40-8694	ZIBULSKY, H.	8011250121*	70-882
WILLIAMS, C. C.	8011230053*	50-440 Q	WOODS, H. A.	8011070377*	50-339 R	ZIEMANN, D. L.	7905090029	50-255 P
WILLIAMS, R. F.	8011120681*	CONTRACT	WOODS, H. A.	8011200300*	50-338 R	ZIEMANN, D. L.	7905240271	50-155 P
WILLIAMS, H. M.	8011060227	50-275 Q	WOODS, T. O.	8011180448	50-528 A	ZIEMANN, D. L.	7910150653	50-245 P
WILLIAMS, E. A.	8011140397*	50-324 R	WOODS, O. R.	8011240167	50-142 Q	ZIEMANN, D. L.	7910160306	50-255 P
WILLIAMS, C. C.	8011200137	50-546 Q	WOOLEVER, E. J.	8011030581	50-412 A	ZIEMANN, D. L.	7911140129	50-255 P
WILLMAN, P. L.	8011050211	50-461 Q	WOOLEVER, E. J.	8011140407	50-412 B	ZIEMANN, D. L.	7912110020	50-255 P
WILSON, J. L.	8011100505*	50-281 B	WOOLEVER, E. J.	8011180603	50-412 B	ZIEMANN, D. L.	7912180081	50-255 P
WILEON, B. D.	8011050468	XPORTLIC	WOOLEVER, E. J.	8011190504	50-412 B	ZIEMANN, D. L.	8003070274	50-255 P
WILSON, B. D.	8011050476*	XPORTLIC	WOOLEVER, E. J.	8011210562	50-344 P	ZIMMERMAN, B. R.	8011110177	PR
WILSON, J. L.	8011030432	50-280 B	WOOLEVER, E. J.	8011230321	50-412 B	ZIRWAS, K.	8011070383*	50-249 B
WILSON, J. L.	8011030433*	50-280 B	WOOLFENDEN, J. M.	8011230113	PR	ZITTEL, H. E.	8011260323	RES
WILSON, J. L.	8011040594	50-280 B	WOOLSTENHULME	8011230202	50-445 A	ZUBER, N.	8011050568	NUREO
WILSON, J. L.	8011040602*	50-280 B	WOOTON, R. O.	8011050554	NUREO			
WILSON, J. L.	8011040571	50-281 B	WOREHAM, C.	8011200265	50-289 H			
WILSON, J. L.	8011040576*	50-281 B	WOZNIAK, D. R.	8011180864	XPORTLIC			
WILSON, J. L.	8011040586*	50-281 B	WRAY, J. R.	8011030496*	50-230 Q			
WILSON, J. L.	8011040592*	50-281 B	WRAY, J. R.	8011200534*	70-27			
WILSON, J. L.	8011100501	50-281 B	WRIGHT, M.	8011100661*	50-237 T	ZUFELT, E.	8011120487*	50-333 R
WILSON, B. D.	8011200404	XPORTLIC	WRINKLE, H. H.	8011210726*	50-275 H	ZULLA, B. S.	8011050018	71-9089
WILSON, J. L.	8011140012	50-281 B	WULLER, G. E.	8011040485	50-461 A	ZULLA, B. S.	8011060569	50-286 P
WILSON, J. L.	8011140017*	50-281 B	WYATT, J. K.	8011070402	50-382 A	ZULLA, B. S.	8011180552	50-286 P
WILSON, J. L.	8011140006	50-280 B	WYKOFF, D.	8011250553*	50-265 B	ZULLA, B. S.	8011180651	50-286 R
WILSON, J. L.	8011140009*	50-280 B	WYKOFF, D. L.	8011250371*	50-265 B			
WILSON, K. L.	8011180546	50-393 D	YALICH, M.	8011090445*	TOPREP			
WILSON, B. D.	8011260242	70-2314	YALICH, M.	8011090449*	TOPREP			
WILSON, J. L.	8011180601	50-281 B	YANDELL, L.	8011060110*	50-298 Q	ZULLA, B. S.	8011190437	50-286 B
WILSON, J. L.	8011180618*	50-281 B	YATO, W. Y.	8011140176	NUREO	ZWETZIG, G. B.	8011070211*	50-70 Q

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Reese-Cleveland Co.,	Namco Controls Div.	8011060577*	50-286 P
		8011060582*	50-286 P
Jouray, Alcorn	-	8011040232*	TOPREP
Isabian Associates		8011030515	UNREG
Agriculture, Dept. of		8011100035*	CONTRACT
Alabama Power Co.		8011020014*	COMM18810H
		801104030*	50-364 A
		8011040469	50-364 A
		8011050371*	50-364 D
		8011050471	50-348 F
		8011060157*	50-364 Q
		8011070373	50-348 S
		8011070374*	50-348 S
		8011070375*	50-348 S
		8011070470	50-348 P
		8011070629	50-348 D
		8011100405	50-348 D
		8011110025	50-364 Q
		8011110033	50-364 Q
		8011110447	50-364 A
		8011120300	50-348 F
		8011120300	50-348 F
		8011120303	50-364 P
		8011120611	50-364 P
		8011120614*	50-364 P
		8011140091	50-348 K
		8011140091	50-348 K
		8011140096*	50-348 K
		8011140098*	50-348 K
		8011170448	50-348 P
		8011180496	50-348 S
		8011180500*	50-348 S
		8011200442*	50-348 Q
		8011210364	50-364 P
		8011210370*	50-364 P
		8011210377	50-348 R
		8011210381*	50-348 R
		8011210387	50-364 Q
		8011210389	50-364 J
		8011210390*	50-364 J
		8011210394	50-364 P
		8011210398	50-348 R
		8011210490	50-364 Q
		8011210504	50-348 S
		8011210506*	50-348 S
		8011210512*	50-348 S
		8011210585	50-348 P
		8011210585	50-348 P
		8011240114	50-348 Q
		8011240305	50-348 S
		8011240310*	50-348 S
		8011240364*	50-348 F
		8011240364*	50-348 F
		8011240375*	50-348 F
		8011240375*	50-348 F

[illegible]

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
American Association of Physicists in Medicine	8011120094	PR
American Institute of Aeronautics & Astronautics	8011070362*	MISC
American Mining Congress	8011120182 8011120186 8011210115	MEGGO REGGO REGGO
American Society of Mechanical Engineers Analysis & Measurement Services Corp.	8011260139 8011070472 8011070478*	50-289 H 50-336 P 50-336 P
Anti-Nuclear Group Representing York Argonne National Laboratory	8011050158 8011100466	50-289 G NIREG
Arizona Public Service Co.	8011190505* 8011190528* 8011240428 8010240079 8010270462	40-2061 40-2061 NIREG 50-528 Q 50-528 T
	8010270468* 8011120373 8011120373 8011120477 8011120477	50-528 T 50-528 Q 50-528 Q 50-528 Q 50-528 S
	8011170570 8011170575 8011170577 8011180448 8011050140	50-528 Q 50-528 Q 50-528 Q 50-528 A PPGJ
Arizona, State of	8011210656 8011280169 8011250113 8011040245 8011040413	PP State Pron PP 50-313 P 50-313 P
Arizona, Univ. of	8011040426 8011040426 8011040543 8011040543 8011050463	50-313 I 50-313 I 50-313 P 50-313 P 50-313 V
Arkansas Power & Light Co.	8011050463 8011070411 8011070411 8011070419* 8011070419*	50-313 V 50-313 P 50-313 P 50-313 P 50-313 P
	8011070509 8011100326 8011100377 8011100377 8011100382*	50-313 P 50-368 P 50-313 P 50-313 P 50-313 P
	8011100382*	50-313 P
	8011100382*	50-313 P
	8011100440 8011100444* 8011100447 8011100449*	50-368 Q 50-368 Q 50-368 Q 50-368 Q
	8011100513 8011100513 801110236* 801110236* 801110236*	50-313 P 50-313 P 50-313 Q 50-313 Q 50-313 Q
	801110273* 801110277 801110260 801110267* 801110260*	50-313 Q 50-368 Q 50-368 Q 50-368 Q 50-368 Q
	801110295 801110300* 801110503 8011130197 8011130197	50-368 Q 50-368 Q 50-313 P 50-313 P 50-313 P
	801110205* 801110305* 8011140028 8011140032 8011140033*	50-313 Q 50-313 Q 50-368 Q 50-368 Q 50-368 Q
	8011140036* 8011140187 8011140197* 8011140278 8011140278	50-368 Q 50-313 P 50-313 P 50-313 P 50-313 P
	8011140383 8011140384* 8011140385 8011140386* 8011140414	50-368 Q 50-368 S 50-368 Q 50-368 S 50-313 R
	8011140414 8011140416* 8011140420	50-313 Q 50-313 P 50-313 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011140424*	50-313 P
	8011170466	50-368 Q
	8011170476*	50-368 Q
	8011170480	50-368 Q
	8011170484	50-313 Q
	8011170487*	50-368 Q
	8011170489*	50-313 S
	8011180243*	50-313 P
	8011180243*	50-313 P
	8011180417	50-368 R
	8011180420*	50-368 Q
	8011180507	50-368 S
	8011180509*	50-368 S
	8011180669	50-313 Q
	8011180676*	50-313 Q
	8011210453	50-368 Q
	8011210454*	50-368 Q
	8011210584	50-368 Q
	8011210590*	50-368 Q
	8011210595	50-368 S
	8011210605*	50-368 Q
	8011210609	50-313 Q
	8011210626*	50-313 S
	8011240292	50-313 P
	8011240376	50-368 P
	8011250316	50-313 Q
	8011250380*	50-313 S
	8011250469	50-313 S
	8011250477*	50-313 S
	8011260780*	50-313 Q
	8011280049	50-368 Q
	8011280052*	50-368 S
	8011280098	50-313 Q
Arkansas, State of	801120681*	CONTRACT
Army, Dept. of; Corps of Engineers	8007290759	50-329 A
	8011030592	50-324 P
	8011140530*	50-367 G
	8011140574*	50-367 G
Atlas Minerals	8011050228	40-3453
	8011060046	40-3453
	8011190022	40-3453
Atomic Industrial Forum	8006030286	NIREG
	8011130204*	NIREG
	8011280132	PROJ
Austin College	8011120113*	COMMISSION
Automated Correspondence Systems, Inc.	8011260136*	CONTRACT
Automated Datatron, Inc.	8011060296*	CONTRACT
Babcock & Wilcox Co.	8011040249*	50-313 P
	8011040550	TOPREP
	8011060351	50-289 T
	8011060399*	50-289 T
	8011060404*	50-289 T
	8011070546*	70-135
	801110508*	50-313 P
	8011180258	TOPREP
	8011180262*	TOPREP
	8011210524*	50-312 P
Babcock & Wilcox Co., Nuclear Material Div.	8010240369	71-5768
	8011040036*	70-1201
	8011120053	71-6400
	8011260074	TOPREP
Baker & Butts	8011050194	50-466 Q
	8011140093	50-466 Q
	8011140493	50-466 Q
	8011170244	50-466 Q
	8011180108	50-299 Q
	8011180147	50-466 Q
	8011190176	50-466 Q
	8011210422	50-466 Q
Baldwin, H. A.	8011060227	50-275 Q
Baltimore Gas & Electric Co.	8011030522	50-317 P
	8011030526	50-317 P
	8011050328	50-317 P
	8011050416	50-317 P
	8011050488	50-317 P
	8011050506	50-317 P
	8011050510*	50-317 P
	8011050515*	50-317 P
	8011060468	50-317 H
	8011060489	50-317 Q
	8011060490*	50-317 S
	8011070332	50-317 S
	8011070336*	50-317 S
	8011070405	50-318 S

CORPORATE SOURCE INDEX

337

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011070410*	50-318 A		8011280072*	50-416 K
	8011100045	50-317 P		8011280074*	50-416 V
	8011100052	50-318 S		8011280076*	50-416 V
	8011100453*	50-318 A	Bechtel Power Corp. (subs. of Bechtel Corp.)	8007240182	50-424 S
	8011140201	50-317 P		8011040203*	50-237 P
	8011140201	50-317 A		8011040209*	50-237 P
	8011140205	50-317 P		8011040215*	50-237 P
	8011140208	50-317 P		8011130761*	50-387 Q
	8011140456	50-317 S		8011170227*	50-483 Q
	8011160460*	50-317 A		8011170232*	50-483 Q
	8011140462	50-317 A		8011200066*	50-249 Q
	8011170111	50-317 Q		8011200071*	50-249 Q
	8011170111	50-317 Q		8011200078*	50-249 Q
	8011180654	50-318 S		8011200081*	50-249 Q
	8011180662*	50-318 S		8011200081*	50-249 Q
	8011190358	50-317 Q		8011200081*	50-249 Q
	8011190416	50-318 S		8011200087*	50-249 Q
	8011190421*	50-318 A		8011200087*	50-249 Q
	8011200148	50-317 Q		8011200087*	50-249 Q
	8011210291	50-317 P		8011200094*	50-249 Q
	8011210526	50-317 S		8011200094*	50-249 Q
	8011210534*	50-317 S		8011200094*	50-249 Q
	8011240134	50-317 P		8011200094*	50-249 Q
	8011240319	50-317 P		8011200094*	50-249 Q
	8011240319	50-317 Q		8011200094*	50-249 Q
	8011240324*	50-317 P		8011200107*	50-249 Q
	8011240324*	50-317 Q		8011200107*	50-249 Q
	8011250307	50-317 P		8011200107*	50-249 Q
	8011250360	50-318 A		8011250311*	50-317 P
	8011250363*	50-318 S		8011250315*	50-317 P
	8011260056	50-317 Q		8011250315*	50-317 P
	8011260056	50-317 Q		8011250317*	50-317 P
	8011260183	50-318 A		8011250317*	50-317 P
	8011260184*	50-318 A		8011260102*	50-255 Q
	8011050255	40-299	Bechtel Power Corp. (subs. of Bechtel Corp.)	8011210197	40-4743
Bar Engineering Co.	8011030216*	FOIA	Bechtel Power Corp. (subs. of Bechtel Corp.)	8011170807	PT21
Battelle Memorial Institute, Columbus Laboratories	8011030225*	FOIA	Berman & Gianque	8011180038	FOIA
	8011040468*	50-219 R	Binder, Elster, Mendelson & Wheeler, Inc.	8011210013*	CONTRACT
	8011050554	NUREG	Blaw-Tec, Inc.	8011190080	NUREG
	8011050583	RES	Black & Veatch	8011210099	REGG0
	8011060077	RES	Bonnenberg & Dreyer Ingenieurgesellschaft	8011210242*	COMMISSION
	8011100471	NUREG	ft MBH		
	8011170712	NUREG	Borg-Warner Corp., Byron Jackson Pump Div.	8011170086	EXPORT I.F.
	8011170730	NUREG		8011170090*	EXPORT I.F.
	8011210037*	CONTRACT	Boston Edison Co.	8011040470	50-293 A
				8011040502	50-293 P
Battelle Memorial Institute, Pacific Northwest Laboratory	8011280232	NUREG		8011040509	50-293 Q
	8011030664	NUREG		8011040516	50-293 V
	8011100463	NUREG		8011040521*	50-293 A
	8011140603	NUREG		8011050152	50-293 Q
	8011170554	NUREG		8011050299	50-293 A
	8011170674	NUREG		8011050305*	50-293 A
	8011180766	RES		8011060459	50-293 P
	8011180787	RES		8011060473	50-293 P
	8011190081	NUREG		8011060483	50-293 A
Bay Creek Uranium Co.	8011100418	40-8452		8011060484*	50-293 A
Bechtel Associates Professional Corp.	8011180155*	50-329 A		8011070409	50-293 A
Bechtel Corp.	8011280029*	50-331 R		8011070457	50-293 P
	7912190487*	50-255 P		8011100403	50-293 A
	8003130581*	50-255 P		8011100454	50-293 A
	8003130585*	50-255 P		8011100455*	50-293 A
	8003130587*	50-255 P		8011120343	50-293 P
	8003130590*	50-255 P		8011120520	50-293 Q
	8003130592*	50-255 P		8011120526*	50-293 Q
	8011040199*	50-185 P		8011170408	50-293 Q
	8011060624*	50-329 A		8011170420	50-293 A
	8011060640*	50-329 A		8011170429*	50-293 A
	8011060643*	50-329 A		8011170448	50-293 A
	8011060643*	50-329 A		8011180427	50-293 Q
	8011060647*	50-329 A		8011180434*	50-293 Q
	8011060647*	50-329 A		8011180638	50-293 A
	8011060651*	50-329 A		8011180650*	50-293 A
	8011060654*	50-329 A		8011190407	50-293 A
	8011060654*	50-329 A		8011190411*	50-293 A
	8011060657*	50-329 A		8011190442	50-293 A
	8011060657*	50-329 A		8011190444*	50-293 A
	8011060662*	50-329 A		8011210516	50-293 A
	8011060666*	50-329 A		8011210521*	50-293 A
	8011060666*	50-329 A		8011210578	50-293 P
	8011060671*	50-329 A		8011220302	50-293 S
	8011060671*	50-329 A		8011220479	50-293 P
	8011170553*	50-346 P		8011250359	50-293 T
	8011240443	50-329 T	Brand & Hall	8011140501	50-395 T
	8011280070*	50-416 K		8011140507*	50-395 T

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Brandeis Univ. Brookhaven National Laboratory	8011210346 8011070219* 8011100083 8011100002 8011120057	PR 50-237 T 50-10 P RES RES
	8011120483 8011140176 8011140426* 8011170529 8011170613	RES NUREG 50-244 F NUREG NUREG
Brown & Root Corp. (subs. of Halliburton Corp.) Brownsville, TX Burns & Roe Co.	8011180512 8011180557 8011040183* 8011140542 8011070358*	50-10 P 50-10 A 50-498 A 50-445 M 50-320 P
Business Organized for a Safe Society Businessmen for the Public Interest C-E Power Systems	8011190696 8011100573 8011060463 8011110461 8011110469*	NUREG FOIA 50-367 G TOPREP TOPREP
	8011110778 8011110801 8011110823 8011200207* 8011260415	XPORTLIC XPORTLIC XPORTLIC 50-361 A PR
CIBA-GEIGY Corp.	8011030074 8011030564 8011030571* 8011040114 8011050173	40-8743 40-8743 40-8743 40-8743 40-8743
CONOCO, Inc. (Continental Oil Co.)	8011100012 8011100240 8011250702* 8011040407 8011040169	40-8743 40-8743 CONTACT 50-395 M PROJ
	8011040455 8011050165 8011050168 8011070234 8011110611	50-275 G 50-275 G PROJ 50-275 G PR
California, Univ. of, Berkeley	8011130291 8011140003 8011210264 8011240167 8011140081	PR 50-142 I NURFG 50-142 G 50-326 P
California, Univ. of, Irvine		
California, Univ. of, Los Angeles	8011110130 8011120172 8011190096 8011210305 8011240100	PR PR NUREG PR NUREG
	8011240411 8011240416* 8011110474 8011170472 8011170472	XPORTLIC XPORTLIC XPORTLIC 50-369 G 50-369 G
Canada Carolina Environmental Study Group	8011170505* 8011170505* 8010290019* 8011030410 8011030413	50-369 G 50-369 G CONMIGSTON 50-324 G 50-324 G
Carolina Power & Light Co.	8011030418* 8011030417 8011030418* 8011030421 8011030423*	50-324 G 50-261 A 50-324 G 50-324 S 50-261 A
	8011030425* 8011030418 8011030620* 8011040454 8011040462*	50-324 A 50-324 A 50-324 G 50-324 A 50-324 A
	8011050257* 8011070413 8011070413 8011070413 8011070413	50-261 A 50-400 G 50-400 G 50-400 G 50-400 G
	8011070436 8011070436 8011070436 8011070436 8011070460	50-400 A 50-400 A 50-400 A 50-400 A 50-400 V
	8011070460 8011070460 8011070460 8011070498	50-400 V 50-400 V 50-400 V 50-261 A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011100386 8011100391* 8011100461 8011100462 8011100465*	50-261 S 50-261 S 50-261 G 50-324 J 50-324 J
	8011100469 8011100473* 8011120307 8011120307 8011120393	50-325 S 50-325 S 50-324 P 50-324 P 50-261 P
	8011120393 8011120393 8011120404 8011120437 8011120437	50-261 P 50-261 P 50-261 F 50-261 V 50-261 V
	8011120437 8011120437 8011120450 8011120460* 8011120577 8011130179*	50-261 V 50-261 V 50-324 A 50-324 A 50-324 S 50-400 G
	8011130196* 8011130201* 8011130222 8011130222 8011130230*	50-400 G 50-400 G 50-324 P 50-324 P 50-324 P
	8011130230* 8011140010 8011140013* 8011140023 8011140039	50-324 P 50-324 S 50-324 S 50-324 S 50-325 V
	8011140044* 8011140090 8011140094* 8011140391 8011140392*	50-325 S 50-261 P 50-261 P 50-261 P 50-261 P
	8011140394 8011140394 8011140397* 8011140431 8011140442	50-324 P 50-324 P 50-324 G 50-400 G 50-324 A
	8011140450* 8011170432 8011170444* 8011180356 8011180361*	50-324 S 50-261 A 50-261 S 50-261 P 50-261 P
	8011180365*	50-261 P
	8011180377 8011180377 8011180384* 8011180384*	50-324 P 50-324 P 50-324 P 50-324 P
	8011180574 8011180661 8011180713 8011180718 8011180721*	50-324 A 50-324 A 50-324 J 50-324 A 50-324 V
	8011180725* 8011210202 8011210451 8011210452* 8011210460*	50-324 S 50-325 P 50-324 S 50-324 S 50-324 A
	8011210470 8011210472* 8011240118 8011240365 8011240365	50-325 S 50-325 A 50-324 A 50-400 S 50-400 S
	8011240365 8011240365 8011240388 8011240388 8011240388	50-401 A 50-401 A 50-400 S 50-400 A 50-400 S
	8011250362 8011250374 8011250379* 8011250382 8011250386*	NURFG 50-324 A 50-324 S 50-324 A 50-324 A
	8011250414 8011250417* 8011250422 8011250426* 8011250431	50-324 A 50-324 S 50-324 S 50-324 A 50-324 A
	8011250446* 8011250478 8011250485* 8011250486 8011250489	50-324 A 50-325 A 50-325 A 50-324 S 50-324 A

CORPORATE SOURCE INDEX

339

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011250490*	50-324 A		8011060309	State Prog
	8011250497*	50-324 S	Columbia Univ.	8011170266*	70-A82
	8011260192	50-261 P		8011170275*	70-882
	8011260293	50-324 Q		8011170278*	70-882
	8011260293	50-324 Q		8011170284*	70-882
	8011280031	50-261 Q		8011170297*	70-A82
	8011280040	50-320 Q	Combustion Engineering, Inc.	8011050331*	50-317 P
	8011280040	50-320 Q		8011120491	TOPREP
	8011280125	50-320 Q		8011170374*	44999
	8011280143	50-261 Q		8011260270	50-317 P
	8011280143	50-261 Q		8011670489*	70-1100
Carpenter Technology Corp.	8011280143	50-261 Q	Combustion Engineering, Inc., L-E Minerals Div.	8010230019	NUREG
	8011180864	XPORTLIC	Commerce Dept. of National Oceanographic & Atmospheric Administration	8011190292*	50-289 G
Center for Development Policy	8011180866*	XPORTLIC	Commerce Dept. of Commonwealth Edison Co.	8006020268	TOPREP
	8011100036	FOIA		8008270372	50-237 P
Central Electric Power Cooperative, Inc.	8011140501	50-395 H		8008270375	50-237 P
	8011140507*	50-395 U		8011030190*	50-374 R
Chem-Nuclear Systems, Inc.	8011210229	27-47		8011030437	50-237 P
	8011210232*	27-47		8011030448	50-373 A
	8011210235*	27-47		8011030448	50-373 A
Cherry, H. H./Cherry, Flynn & Kenter	8011250323	50-454 G		8011030450	50-373 A
	8011250323	50-454 G		8011030450	50-373 A
	8011250327*	50-454 G		8011030507	50-237 P
	8011250327*	50-454 G		8011030531	50-454 K
	8011250333*	50-454 G		8011030531	50-454 K
Chevron Industries, Inc., Chevron Resources Co. Div.	8011120310	REGGD		8011030531	50-054 K
Christa-Maria	8011180095	50-155 G		8011030531	50-454 K
	8011250043	50-155 G		8011030544*	50-454 K
Cincinnati Gas & Electric Co.	8011030138*	50-358 Q		8011030548	50-373 A
	8011030255*	50-358 Q		8011030548	50-373 A
	8011030591	50-358 A		8011030563	50-373 A
	8011030593*	50-358 A		8011030563	50-373 A
	8011030616	50-358 A		8011030572	50-373 A
	8011040168	50-358 Q		8011030572	50-373 A
	8011040579	50-358 A		8011030577	50-237 P
	8011060175	50-358 Q		8011030594	50-237 P
	8011100043*	50-358 Q		8011030605*	50-237 P
	8011110014*	50-358 Q		8011030632	50-237 P
	8011120385	50-358 A		8011030640*	50-237 P
	8011120520	50-358 A		8011040197	50-237 P
	8011130182	50-358 K		8011040370	50-295 P
	8011130186*	50-358 K		8011040370	50-295 P
	8011140055	50-358 Q		8011040380	50-373 A
	8011190742*	50-358 P		8011040380	50-373 A
	8011210483	50-358 T		8011040394	50-10 P
	8011210486*	50-358 T		8011040394	50-10 P
	8011240086	50-358 K		8011040394	50-10 P
	8011240338	50-358 A		8011040394	50-10 P
	8011260209	50-358 A		8011040394	50-10 P
	8011260210*	50-358 A		8011040394	50-10 P
Citizens Association for Sound Energy	8011280019	50-445 G		8011040394	50-10 P
	8011280019	50-445 G		8011040394	50-10 P
	8011280024	50-445 G		8011040394	50-10 P
	8011280024	50-445 G		8011040394	50-10 P
Citizens Concerned About Nuclear Power, Inc.	8011040510	50-498 Q		8011040394	50-10 P
	8011040510	50-498 Q		8011040394	50-10 P
	8011040530	50-498 Q		8011040440	50-373 A
	8011040530	50-498 Q		8011040440	50-373 A
	8011050440	50-498 Q		8011040446*	50-373 A
	8011050489	50-498 Q		8011040446*	50-373 A
	8011050489	50-498 G		8011040474	50-249 P
	8011060234	50-498 G		8011040512*	50-249 P
	8011060234	50-498 G		8011040520	50-373 A
	8011190202	50-498 P		8011040520	50-373 A
	8011250588	50-498 G		8011040556	50-373 Q
Citizens for Fair Utility Regulation	8011280036	50-445 G		8011050110*	50-454 Q
Clatsop County Citizens for Safe Energy	8011040326*	50-416 H		8011050123*	50-454 Q
Cleveland Clinic Cleveland, OH	8011120099	PP		8011050123*	50-454 Q
Cleveland Electric Illuminating Co.	8011040194*	50-440 Q		8011050200	50-237 Q
	8011070406	50-440 S		8011050427	50-295 P
	8011070464	50-440 A		8011050428	50-10 F
	8011140043	50-440 S		8011050428	50-10 F
	8011180491	50-440 S		8011050428	50-10 F
	8011190472*	50-440 Q		8011050428	50-10 F
	8011210447*	50-440 Q		8011050428	50-10 F
Cleveland-Cliffs Iron Co. Cohn, D.B.	8011200197	40-8714		8011050430*	50-295 P
	8011060446	50-367 Q		8011060491	50-237 P
	8011170312	50-367 G		8011060560	50-454 Q
	8011280014	50-367 G		8011060575	50-237 Q
Colorado State Univ.	8011050178	40-8084		8011070146	50-454 Q
	8011050184*	40-8084		8011070146	50-454 Q
	8011120031	40-8602		8011070378	50-295 S
Colorado, State of	8011030095	State Prog		8011070379*	50-295 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011070382	50-249 S		8011140041*	50-295 S
	8011070383*	50-249 S		8011170209	50-373 A
	8011100389	50-10 P		8011170209	50-373 A
	8011100389	50-10 P		8011170249	50-237 Q
	8011100389	50-10 P		8011170249	50-237 Q
	8011100389	50-10 P		8011170249	50-237 Q
	8011100389	50-10 P		8011170286	50-373 S
	8011100389	50-10 P		8011170286	50-373 S
	8011100389	50-10 P		8011180335	50-295 P
	8011100389	50-10 P		8011180335	50-295 P
	8011100389	50-10 P		8011180419	50-237 S
	8011100389	50-10 P		8011180447	50-10 P
	8011100400	50-254 S		8011180447	50-10 P
	8011100401	50-295 S		8011180447	50-10 P
	8011100406*	50-254 S		8011180453*	50-10 P
	8011100407*	50-295 S		8011180595	50-265 S
	8011100410	50-295 S		8011180600	50-237 S
	8011100416*	50-295 S		8011180607*	50-237 S
	8011100436	50-265 S		8011180613*	50-265 S
	8011100439*	50-265 S		8011180617	50-265 S
	8011100481	50-10 V		8011180628*	50-265 S
	8011100481	50-10 V		8011180716	50-295 S
	8011100481	50-10 V		8011180717	50-10 J
	8011100481	50-10 V		8011180723*	50-295 S
	8011100481	50-10 V		801119021A	50-295 P
	8011100481	50-10 V		8011190218	50-295 P
	8011100481	50-10 V		8011190222*	50-295 P
	8011100481	50-10 V		8011190222*	50-295 P
	8011100481	50-10 V		8011190347	50-237 P
	8011100492	50-254 P		8011200062	50-249 Q
	8011100492	50-254 P		8011210241	50-373 Q
	8011100631*	50-237 T		8011210241	50-373 Q
	8011100631*	50-237 T		8011210248	50-373 Q
	8011100634*	50-237 T		8011210251	50-373 Q
	8011100635*	50-237 T		8011210251	50-373 Q
	8011100635*	50-237 T		8011210292	REGG
	8011100638*	50-237 T		8011210543	50-249 S
	8011100638*	50-237 T		8011210551*	50-249 S
	8011100640*	50-237 T		8011210769*	50-456 Q
	8011100640*	50-237 T		8011210769*	50-456 Q
	8011100642*	50-237 T		8011240278	50-373 K
	8011100642*	50-237 T		8011240278	50-373 K
	8011100646*	50-237 T		8011240280*	50-373 K
	8011100646*	50-237 T		8011240280*	50-373 K
	8011100650*	50-237 T		8011240334	50-373 A
	8011100650*	50-237 T		8011240342	50-373 A
	8011100652*	50-237 T		8011240342	50-373 A
	8011100652*	50-237 T		8011240369	50-373 A
	8011100656*	50-237 T		8011240369	50-373 A
	8011100661*	50-237 T		8011240374	50-254 P
	8011100667*	50-237 T		8011240378	50-373 K
	8011100667*	50-237 T		8011240378	50-373 K
	8011110186	50-254 R		8011240380*	50-373 K
	8011110186	50-254 R		8011240380*	50-373 K
	8011110193*	50-254 Q		8011240386*	50-254 P
	8011110209	50-295 Q		8011250212	50-373 A
	8011110209	50-295 R		8011250212	50-373 A
	8011110214*	50-295 P		8011250284	50-373 K
	8011110214*	50-295 Q		8011250284	50-373 K
	8011110286	50-237 F		8011250318	50-304 I
	8011110486	50-237 F		8011250322	50-249 S
	8011110563	50-456 C		8011250325	50-249 S
	8011110563	50-456 C		8011250330	50-295 S
	8011120317	50-295 P		8011250332	50-10 J
	8011120317	50-295 P		8011250334*	50-249 S
	8011120365	50-454 K		8011250337*	50-295 S
	8011120415	50-237 Q		8011250338	50-295 S
	8011120492	50-10 V		8011250343*	50-295 S
	8011120492	50-10 V		8011250346	50-10 P
	8011120492	50-10 V		8011250348	50-254 S
	8011120492	50-10 V		8011250352*	50-254 S
	8011120492	50-10 V		8011250354	50-254 S
	8011120492	50-10 V		8011250367	50-265 A
	8011120492	50-10 V		8011250368*	50-249 S
	8011120492	50-10 V		8011250371*	50-265 S
	8011120492	50-10 V		8011250375*	50-304 S
	8011120552	50-237 P		8011250475	50-237 P
	8011120552	50-237 P		8011250475	50-237 P
	8011130192	50-10 P		8011250529	50-237 S
	8011130211*	UREG		8011250534*	50-237 S
	8011140005	50-237 S		8011250545	50-265 S
	8011140008*	50-237 S		8011250553*	50-265 S
	8011140014	50-254 S		8011250558	50-249 S
	8011140019*	50-254 S		8011250568*	50-249 S
	8011140034	50-295 S		8011250696	50-10 Q

CORPORATE SOURCE INDEX

341

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Congress (Joint & Rotating Committees, etc.) Connecticut Yankee Atomic Power Co.	8011250696	50-10	Corn Belt Power Cooperative Coulter Region Energy Coalition	801120619*	50-255
	8011260213	50-295		8011140038	50-329
	8011240206*	50-454		8011140042	50-329
	8011180279*	50-556		8011140042	50-329
	8011040320	50-213		8011140047*	50-329
	8011040363*	50-213		8011140051	50-255
	8011040366*	50-213		8011140052	50-255
	8011100422	50-213		8011140057*	50-255
	8011110450	50-213		8011180151	50-329
	8011110453*	50-213		8011180236	TOPREP
Connecticut, State of Gannett, Moore & Corbin	8011140007	50-213	Council on Environmental Quality Crescent, Inc. Critical Mass Energy Project Cyprus Mines Corp.	8011180411	50-255
	8011140349	50-213		8011180420	50-329
	8011170465	50-213		8011180563	50-155
	8011180348	50-213		8011180685	50-255
	8011180465	50-213		8011180697*	50-255
	8011180467*	50-213		8011180715	50-255
	8011200079	50-213		8011180724*	50-255
	8011210177*	50-213		8011180730	50-255
	8011250433	50-213		8011180735*	50-255
	8011250444*	50-213		8011160743	50-255
Consolidated Controls Corp. (subs. of Coulter Corp.) Consolidated Edison Co. of New York	8011210592	NUREG	Corn Belt Power Cooperative Coulter Region Energy Coalition	8011180748*	50-255
	8011050050	27-39		8011190011	50-329
	8011190135	27-39		8011190011	50-329
	8011190145*	27-39		8011190013	50-255
	8011190159*	27-39		8011190126	50-329
	8011250578	50-356		8011190446*	50-329
	8011170553*	50-346		8011190446*	50-329
	8011030517	50-247		8011200143	50-155
	8011030685	50-247		8011200189	50-155
	8011030691*	50-247		8011210038	NUREG
Consolidated Intervenor Consumers Power Co.	8011060122*	50-3	D'Appolonia Consulting Engineers, Inc. Delaware Power Cooperative	8011210602	71-325
	8011060122*	50-309		8011240255	50-155
	8011060480	50-247		8011250314	50-155
	8011070398	50-247		8011250340	50-155
	8011170521	50-3		8011250344*	50-155
	8011180457	50-247		8011250389*	50-155
	8011180462*	50-247		8011250400	50-155
	8011190656	50-247		8011250404*	50-155
	8011190664*	50-247		8011250452	50-255
	8011180672	50-247		8011250628	50-255
Consolidated Intervenor Consumers Power Co.	8011180679*	50-247	D'Appolonia Consulting Engineers, Inc. Delaware Power Cooperative	8011260019	50-329
	8011180683	50-3		8011260019	50-329
	8011180683	50-3		8011260083	50-329
	8011180683	50-3		8011260083	50-329
	8011180690*	50-3		8011260087*	50-329
	8011180690*	50-3		8011260101	50-255
	8011190339	50-247		8011260772	50-331
	8011050042	50-409		8011280021	50-409
	8011050044*	50-409		8011280023*	50-409
	7906260194	50-155		8011190353*	50-320
Consolidated Intervenor Consumers Power Co.	7912190466	50-255	D'Appolonia Consulting Engineers, Inc. Delaware Power Cooperative	8011140200	NUREG
	8002070263	50-255		8011030153	FNIA
	8003130577	50-255		8011110175	NASTL MGT
	8004110306	50-155		8011280177	NASTL MGT
	8004190627	50-255		8011210571*	50-367
	8011030533	50-255		8011040179	50-409
	8011030539*	50-255		8011040410	50-409
	8011030545	50-155		8011120340	50-409
	8011030550*	50-155		8011120397	50-409
	8011030568	50-155		8011120542	50-409
Consolidated Intervenor Consumers Power Co.	8011030573*	50-155	D'Appolonia Consulting Engineers, Inc. Delaware Power Cooperative	8011170502	50-409
	8011040128	50-155		8011170501*	50-409
	8011040128	50-155		8011180684	50-409
	8011040163	50-329		8011190028	50-409
	8011040177	50-155		8011190033*	50-409
	8011040196	50-155		8011190041*	50-409
	8011040197*	50-155		8011190647*	50-409
	8011040200	50-255		8011240358	50-409
	8011040399	50-329		8011250523	50-409
	8011040399	50-329		8011180540*	40-8602
Consolidated Intervenor Consumers Power Co.	8011040405	50-329	Debevoise & Liberman	8011180543*	40-8602
	8011040405	50-329		8011190036*	50-409
	8011040511	50-329		8011070244	50-369
	8011040511	50-329		8011140056	50-369
	8011050499	50-255		8011140504	50-269
	8011050503*	50-255		8011140153	50-369
	8011060621	50-329		8011210279	50-195
	8011100489	50-155		8011210265*	50-395
	8011100533*	50-155		8011260004	PR
	8011100539*	50-155		8011260165	PR
Consolidated Intervenor Consumers Power Co.	8011100620	50-329	Defense, Dept. of, Defense Nuclear Agency	8011280041	50-488
	8011100620	50-329		8011280065	50-445
	8011120609	50-255		8011250091	PR

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Delaware, State of Detroit Edison Co.	8011120629	PROJ
	8011030684*	50-341 K
	8011070454	50-341 S
	8011070454	50-341 S
	8011170515	50-341 A
Dictaphone Corp. Duke Power Co.	8011180591	50-341 q
	8011190685	50-341 q
	8011250282	MUREG
	8011170364*	CONTACT
	8011030356	50-369 F
	8011030460	50-270 S
	8011030465*	50-270 q
	8011030487	50-269 S
	8011030491*	50-269 q
	8011040064	50-413 q
	8011040146	50-269 P
	8011040146	50-269 P
	8011040146	50-269 P
	8011040149*	50-269 P
	8011040149*	50-269 P
	8011040149*	50-269 P
	8011040302*	50-413 q
	8011040478	50-269 q
	8011040481	50-269 P
	8011040481	50-269 P
	8011040481	50-269 P
	8011040481	50-269 P
	8011040505*	50-269 S
	8011040533	50-369 A
	8011040533	50-369 A
	8011050390	50-369 A
	8011050390	50-369 A
	8011050442	50-369 S
	8011060128*	50-269 G
	8011060465	50-269 G
	8011060465	50-269 G
	8011060465	50-269 G
	8011060499	50-269 P
	8011060499	50-269 P
	8011060499	50-269 P
	8011060502	50-269 P
	8011060502	50-269 P
	8011060504*	50-269 P
	8011060504*	50-269 P
	8011060504*	50-269 P
	8011070107	MUREG
	8011070244	50-369 G
	8011070244	50-369 G
	8011070354	50-369 A
	8011070386	50-369 A
	8011070439	50-269 P
	8011070439	50-269 P
	8011070439	50-269 P
	8011070466*	50-269 P
	8011070466*	50-269 P
	8011070466*	50-269 P
	8011100429	50-269 q
	8011100429	50-269 q
	8011110496	50-269 P
	8011110496	50-269 P
	8011120092*	50-369 G
	8011120092*	50-369 G
	8011120334	50-269 P
	8011120334	50-269 P
	8011120334	50-269 P
	8011120359	50-269 q
	8011120344*	50-269 q
	8011120604	50-270 q
	8011120608*	50-270 q
	8011130068	50-269 G
	8011130199	50-269 P
	8011130199	50-269 P
	8011130199	50-269 P
	8011130203*	50-269 P
	8011130203*	50-269 P
	8011130203*	50-269 P
	8011140056	50-369 G
	8011140056	50-369 G
	8011140056	50-369 G
	80111400372	50-269 q
	8011140374*	50-269 S
	8011140398	50-269 P
	8011140398	50-269 P
	8011140398	50-269 P
	8011140504	50-269 q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011140504	50-269
	8011170562	50-413
	8011180153	50-369
	8011180153	50-369
	8011180392	50-269
	8011180392	50-269
	8011180392	50-269
	8011180396*	50-269
	8011180396*	50-269
	8011180418	50-369
	8011180446	50-270
	8011180542	50-369
	8011180548	50-269
	8011180582	50-269
	8011180582	50-269
	8011180585	50-269
	8011180592*	50-269
	8011180592*	50-269
	8011180592*	50-269
	8011180593*	50-269
	8011180704	50-270
	8011180711	50-269
	8011180712*	50-270
	8011180722*	50-269
	8011190494	50-369
	8011200178	50-269
	8011200178	50-269
	8011210125	50-369
	8011210153	50-170
	8011210440	50-269
	8011210440	50-269
	8011210440	50-269
	8011210473	50-270
	8011210475*	50-270
	8011210498	50-369
	8011210498	50-369
	8011210500*	50-369
	8011210559	50-269
	8011210559	50-269
	8011210559	50-269
	8011210768	50-369
	8011210768	50-369
	8011240288	50-269
	8011240289*	50-269
	8011250172	50-269
	8011250172	50-269
	8011250172	50-269
	8011250180	50-269
	8011250261	50-369
	8011250291	50-269
	8011250291	50-269
	8011250365	50-269
	8011250480	50-270
	8011250506*	50-270
	8011260004	PR
	8011260009*	PR
	8011260165	PR
	8011260330	50-269
	8011260330	50-269
	8011280041	50-488
	8011280230	50-369
	8010150534	50-334
	8011030288*	50-334
	8011030479	50-334
	8011030484*	50-334
	8011030581	50-412
	8011040294	50-334
	8011040375	50-334
	8011040376	50-334
	8011040377*	50-334
	8011040386	50-334
	8011060507	50-334
	8011120351	50-334
	8011120354*	50-334
	8011120442	50-134
	8011120447*	50-334
	8011140407	50-412
	8011140465	50-334
	8011170746	50-334
	8011180473	50-334

CORPORATE SOURCE INDEX

343

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011180475*	50-334 R		8011180546	50-395 D
	8011180603	50-412 A		8011170808*	50-247 P
	8011190504	50-412 S	Essex Corp.	8011110472	XPORTLIC
	8011200046*	50-334 Q	European Communities, Commission of	8011110691	XPORTLIC
	8011200179	50-334 Q		8011110497	XPORTLIC
	8011200276	50-334 Q		8011110718	XPORTLIC
	8011210562	50-344 P		8011120002	XPORTLIC
	8011210568*	50-344 P		8011200213	XPORTLIC
	8011240273	50-334 A		8011190328	40-8064
	8011240298	50-334 B	Exxon Minerals Corp, USA	8011030100	70-1257
	8011240301*	50-334 A	Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)		
	8011240307	50-334 S		8011060345	XPORTLIC
	8011250321	50-412 A		8011060349*	XPORTLIC
	8011250461	50-334 S		8011060398	XPORTLIC
	8011250470*	50-334 A		8011060402*	XPORTLIC
	8011250513	50-334 S		8011070083	XPORTLIC
	8011250520*	50-334 S		8011100062*	FOIA
	8011260185	50-334 S		8011100086*	FOIA
	8011260186*	50-334 S		8011100096*	70-1257
	8011280075	50-334 P		8011100414	TNPREP
ES&G Idaho, Inc.	8011100215	50-282 P		8011120610	71-3
	8011130144	RES		8011120622*	71-3
	8011130236	RES		8011140002	TNPREP
	8011140320	NUREG		8011170495	TNPREP
	8011170563	NUREG	F.H.Faxon Co., Inc.	8011080174*	CDYTRACT
	8011200108	50-334 P	Federal American Partners	8010290379	40-0492
	8011200113	50-334 P		8010290381*	40-4492
	8011200124	RES		8011060069	40-4492
ES&G, Inc.	8011200346	50-269 P		8011180473	40-4492
	8010270115*	70-1092		8011130087*	URG
	8011200343*	70-1092	Federal Emergency Management Agency	8011170793	COMMISSION
	8011210471	50-254 Q			
	8011210471	50-254 Q	Feldman, J.H., Jr.	8011180069	50-358 G
	8011210474*	50-254 Q	Fleischacker, D. S.	8011100210	50-275 G
	8011210474*	50-254 Q	Florida Power & Light Co.	8008280384	50-335 P
				8011020648	50-250 Q
				8010280648	50-250 Q
Esasco Services, Inc. (subs. of Esmerch Corp.)	8011040085*	QA999		8011030556	50-335 P
Ecological Analysts, Inc.	8011170498*	40-8743		8011030561*	50-335 P
Edison Electric Institute	8011030063	PR		8011040220	50-335 P
	8011030065	PR		8011040391	50-250 Q
Edlow International Co.	8005270692*	FOIA		8011040401	50-250 Q
	8011070109	XPORTLIC		8011040487	50-335 Q
	8011190670	XPORTLIC		8011040492*	50-335 S
	8011240368	XPORTLIC		8011040498	50-389 F
Eichhorn, Eichhorn & Link	8011050409	50-367 Q		8011050436	50-250 P
	8011100199	50-367 Q		8011050436	50-250 P
	8011140021	50-367 Q			
	8011140085	50-367 Q		8011050473*	50-250 Q
	8011140498	50-367 Q		8011050474	50-250 Q
Electric Power Research Institute	8011280030	50-367 Q		8011050474	50-250 P
	8011140184	NUREG		8011060260	50-250 Q
Energy Fuels Nuclear, Inc.	8011040250	40-8681		8011060260	50-250 Q
Energy Research & Development Admin. (Presently DOE)	8011100087*	50-10 P		8011060492	50-389 A
Energy, Dept. of	8011030022*	70-8		8011070299	50-250 V
	8011030024*	70-8		8011070311	50-335 P
	8011030050	PP		8011070319	50-250 Q
	8011060249*	50-320 H		8011100352	50-250 P
	8011060617*	50-320 H		8011100352	50-250 P
	8011170137*	478C		8011100390	50-250 P
	8011170508	PROJ		8011100390	50-250 P
	8011170556*	PROJ		8011100476	50-335 Q
	8011180020*	50-320 H		8011180080*	50-335 Q
	8011180028	PR		8011180090	50-335 P
Energy, Dept. of, Clinch River Breeder Reactor Plant	8011070416	50-537 Q		8011180491*	50-335 P
	8011070417*	50-537 R		8011170508	50-334 P
	8011180630	50-537 R		8011120512*	50-335 P
	8011280047	50-537 R		8011140059	50-389 Q
	8011280048*	50-537 R		8011140110	50-302 S
Energy, Dept. of, Idaho Operations Office	8011050537	HFS		8011140130	50-250 P
	8011050541	HFS		8011140656	50-250 Q
	8011060084	RES		8011180047	50-389 M
	8011130016	50-272 P		8011180599	50-250 P
	8011130138	RES		8011180599	50-250 P
	8011130153	RES		8011180604*	50-250 R
	8011200458	RES		8011180604*	50-250 R
	8011240466	RES			
Environmental Protection Agency	8011060137*	50-289 R		8011180608*	50-250 R
	8011060146*	50-289 R		8011190517	50-335 P
	8011100091*	50-10 P		8011190523*	50-335 P
	8011110074	PP		8011200255	50-335 P
	8011110568*	50-320 T		8011200258*	50-335 P
	8011140128*	50-30 W		8011210299	50-302 P
	8011140309	NUREG		8011210357	50-389 P
				8011250036	50-389 M
				8011250193	50-335 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Florida Power Corp.	8011260147	50-250 A		8011060204*	71-9019
	8011260147	50-250 A		8011060215	70-1113
	8011260153	50-335 A		8011060585	TOPREP
	8011280114	50-250 C		8011060607	70-1113
	8011280114	50-250 A		8011070041*	10CFR
	8011280131	50-335 A			
	8011280135	50-335 A		8011070085*	10CFR
	8011030159*	50-302 P		8011120414	NUREG
	8011030611	50-302 P	General Motors Corp.	8011200205	71-5939
	8011040147	50-302 A	General Public Utilities	8011070105	XPORTLIC
				8011210355*	50-289
	8011040159	50-302 P			
	8011040167	50-302 P	General Public Utilities - GPU Service Corp.	8011060399*	50-289
	8011040190	50-302 F			
	8011040204	50-302 A		8011060404*	50-289
	8011040482	50-302 S		8011110388	50-289
				8011120606	50-289
	8011040499*	50-302 A		8011250262	50-320
	8011050227*	50-302 A			
	8011050458	50-302 P		8011250264*	50-320
	8011060322	50-302 A	George Washington Univ. Medical Center Wash, DC	8011110060	PR
	8011060334*	50-302 P	Georgia Institute of Technology	8011210011	PR
			Georgia Power Co.	8011050508*	50-321
	8011070634	50-302 D		8011050559*	50-321
	8011110230	50-302 P			
	8011110233*	50-302 P		8011060458	50-424
	8011110243	50-302 P		8011060466	50-321
	8011110321	50-302 S		8011060466	50-321
				8011060500	50-321
	8011110328*	50-302 A		8011060500	50-321
	8011120486	50-302 S			
	8011120490*	50-302 S		8011070277	50-321
	8011140030	50-302 S		8011070282*	50-321
	8011140037	50-302 S		8011070425	50-321
				8011100217	50-321
	8011140045	50-302 S		8011100472	50-366
	8011140050*	50-302 S			
	8011180581	50-302 A		8011100478	50-321
	8011180589*	50-302 A		8011120445	50-366
	8011180608	50-302 R		8011120452*	50-366
			8011120499	50-366	
8011180614*	50-302 H		8011120519*	50-366	
8011200335	50-302 V				
8011210249	50-302 A		8011140378	50-366	
8011210384	50-302 A		8011140380*	50-366	
8011250349	50-302 P		8011170427	50-321	
			8011180432	50-366	
			8011180698	50-366	
Gary, IN	8011280118	50-302 A			
General Atomic Co. (subs. of Gulf Oil Co.)	8011250310	50-267 G		8011180706*	50-366
	8011140048	50-163 J		8011190290	50-321
General Electric Co.	8011030191*	TOPREP		8011190293*	50-321
	8011030629	50-237 A		8011190392	50-321
				8011190400*	50-321
	8011050171	70-1308			
	8011050410	70-1308		8011190405	50-321
	8011050411*	70-1308		8011190412*	50-321
	8011050447	50-70 P		8011190417	50-321
	8011050468	XPORTLIC		8011190422*	50-321
	8011050476*	XPORTLIC		8011200281	50-366
	8011060262*	42999			
	8011060455*	70-1308		8011200288*	50-366
	8011100270	71-9010		8011210257	50-321
	8011110587	70-1308		8011210257	50-321
				8011210611	50-321
	8011110822	71-59A0		8011240050	50-321
	8011120345	TOPREP		8011240050	50-321
	8011140062	50-367 G		8011250335	50-424
	8011140065*	50-367 G		8011260142	50-321
	8011140184	NUREG		8011260152	50-321
				8011260060	50-321
	8011180637	70-1308			
	8011140221	NUREG		8011280062*	50-321
	8011190206	TOPREP	Georgia, State of	8011040227	PROJ
	8011200308	TOPREP		8011120678	PROJ
	8011200404	XPORTLIC	Georgia, Univ. of	8011120158	PR
			Geotechnical Engineers, Inc.	8011260003*	CONTRACT
	8011200481*	70-1113			
	8011210206*	50-325 P	Gilbert/Commonwealth Cos.	8011060329*	50-302
	8011210316	TOPREP		8011100376*	50-395
	8011240144	TOPREP	Gulf Energy & Environmental Systems	8011030247*	FOIA
	8011240381*	50-254 P	Gulf Nuclear, Inc.	8011110184	PR
			Hamm Engineers, Inc.	8011200261*	50-546
	8011240393*	50-254 P			
	8011250246	TOPREP		8011200264*	50-546
	8011250252*	TOPREP	Hanford Engineering Development Laboratory	8011130252	RES
	8011250292*	TOPREP			
	8011250294*	TOPREP		8011170549*	PROJ
				8011170552*	PROJ
	8011250505	TOPREP		8011170556*	PROJ
	8011250508*	TOPREP			
	8011260163	TOPREP		8011170561*	PROJ
	8011260240	XPORTLIC		8011180079	RES
	8011260242	70-2314	Hanover County, VA	8010160498*	50-336
General Electric Co., Nuclear Energy Products Div.	8011030428	NUREG	Harding-Lawson Associates	8011120065*	27-39
			Hartford Hosp., Hartford, CT	8011120110	PR
	8011040226	TOPREP			
	8011060197	71-9019	Hill Christopher & Phillips	8011040455	50-275
				8011040456	50-275

345

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011070234	50-275 G		801110593	27-39
	8011070234	50-275 G		8011110602*	State Prod
	8011100241	50-275 G		8011110607*	State Prod
	8011100241	50-275 G		8011240159	27-39
	8011100427	50-275 G		8011250038	27-39
Hittman Corp.	8011100427	50-275 G		8011250045	27-39
Hittman Nuclear & Development Corp.	8011210588*	50-348 P		8011250633	27-39
(subs. Hittman Corp.)	8010310152	71-9086		8011250694	27-39
	8010310162*	71-9086	Indiana & Michigan Electric Co.	8011100394	50-315 P
	8011180762	71-24		8011110023	50-315 G
	8011180770*	71-24		8011140095	50-315 V
Keywell, Inc.	8011100259	NUREG		8011180026	50-315 P
House of Rep.	8011050230	PR		8011190426	50-315 P
	8011100623	50-466 G		8011190615	50-315 G
	8011170215	50-247 H		8011190625*	50-315 G
House of Rep., Appropriations	8011200315	50-320 H		8011180641	50-316 R
House of Rep., Foreign Affairs	8011113407	50-275 H		8011180657*	50-316 R
House of Rep., Government Operations	8011170440	50-247 H		8011200005	50-315 G
House of Rep., Interior & Insular Affairs	8011050062*	50-296 H		8011180061	FRJA
	8011050066*	50-296 H		8011120086	PR
	8011110584*	COMMISSION	Indiana Univ. Medical Center Indianapolis, IN	8011120153	PR
Planning & Urban Development, Dept. of	8011110210	PR	Indiana, State of	8011120090	PR
Position Lighting & Power Co.	8011030583	50-498 G		8011120091	PR
	8011030598	50-498 G		8011250146	PR
	8011030598	50-498 G	Inhalation Toxicology Research Institute	8011190695	NUREG
	8011040173	50-498 A		8011100265	NUREG
	8011040173	50-498 A	Institute of Electrical & Electronic Engineers	8011100113	NUREG
	8011040178*	50-498 A	Institute of Nuclear Power Operations	8011030589	40-8703
	8011040178*	50-498 A	Interior, Dept. of	8011050017*	70-2909
	8011040188*	50-498 A		8011210014	PR
	8011050194	50-466 G		8011250036	50-389 H
	8011060469*	50-498 M		8011190179	40-8743
	8011060469*	50-498 M	Interior, Dept. of, Bureau of Mines	8011060461	50-329 C
	8011060562	50-498 A	Interior, Dept. of, Fish & Wildlife Service	8011120484	50-461 F
	8011060562	50-498 A		8011190260	40-1341
	8011120341	50-498 G		8011250202	50-445 A
	8011120341	50-498 G		801120657	71-342
	8011120348	50-498 A		801120661*	71-382
	8011120362	50-498 G	Interior, Dept. of, Geological Survey	8011900003	50-499 A
	8011120362	50-498 G		8011190217	40-8743
	8011120637	50-498 G		8011030582	40-8743
	8011120637	50-498 G	Interior, Dept. of, National Park Service	8011200746	50-289 H
	8011140093	50-466 G	International Brotherhood of Electrical Workers	8011050023	50-331 G
	8011140493	50-466 G			
	8011170244	50-466 G			
	8011180147	50-466 G		8011060605	50-331 G
	8011180622	50-498 G		8011140058	50-331 P
	8011190176	50-466 G		8011180316	50-331 G
	8011190305	50-498 G		8011180325	50-331 G
	8011190305	50-498 G		8011180410	50-331 G
	8011190308*	50-498 G		8011180411	50-331 G
	8011190308*	50-498 G		8011180619*	50-331 G
	8011190630	50-498 G		8011180623	50-331 G
	8011190630	50-498 G		8011180631*	50-331 A
	8011210763*	50-498 G		8011180696	50-331 G
	8011210763*	50-498 G		8011180702	50-331 G
	8011210763*	50-498 G		8011180705*	50-331 G
Lawrence & Farrell	8011050164	50-496 G		8011180708*	50-331 G
McIntyre & Williams	8011140522	50-338 R		8011190098	50-331 G
Anthropological Associates, Inc.	8011100528*	50-320 R		8011200302	50-331 G
	8011250531*	50-387 R		8011200309*	50-331 G
	8011040082	REF		8011210603	50-331 V
Idaho National Engineering Laboratory	8011040247	REF		8011210610	50-331 V
Idaho Nuclear Corp.	8011040231	PROJ		8011250728	50-331 S
Idaho, State of	8011030470	50-461 S		8011260754	50-331 G
Illinois Power Co.	8011030558	50-461 S		8011280028	50-331 G
	8011040485	50-461 A		8011040617	50-237 G
	8011040539	50-461 G		8011040515	50-410 G
	8011170902	50-461 G		8011050200	50-237 G
	8011170902	50-461 G		8011050200	50-237 G
	8011170906*	50-461 G		8011050216	50-237 G
	8011170906*	50-461 G			
	8011170906*	50-461 G		8011060381	50-237 G
	8011170913	50-461 G		8011060381	50-237 G
	8011170913	50-461 G		8011060381	50-237 G
	8011190014	50-461 A		8011060781	50-237 G
	8011190483*	50-461 G		8011060453	50-237 G
	8011200203	50-461 A		8011060453	50-237 G
	8011200248	50-461 K		8011060453	50-237 G
	8011200258*	50-461 K		8011060472	50-237 G
Illinois, State of	8011040379	27-39		8011100630	50-237 T
	8011050151	27-39			
	8011050211	50-461 G		8011140042	50-329 G
	8011060201	50-237 G			
	8011100233	27-39			
	8011100241	50-275 G			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011100042	50-329 G		8011200268	50-244 P
	8011100047*	50-329 G		8011250327*	50-454 G
	8011100047*	50-329 G	League of Women Voters of Rockford, IL	8011250327*	50-454 G
	8011170222	50-237 G		8011250333*	50-454 G
	8011170235	50-373 G		8011250333*	50-454 G
	8011180129	50-237 G		8011260304	50-219 P
	8011190013	50-255 G	Lehigh Univ.	8011050061	50-322 K
	8011190126	50-329 G	Long Island Lighting Co.	8011170571*	50-322 K
	8011210513	50-237 G		8011200185	50-322 G
Island Closeup News Service	8011070623	FOIA		8011200269	50-322 G
	8011130088	XPORTLIC		8011100206	NES
Isotope Products Laboratories	8011170214	50-367 G	Los Alamos Scientific Laboratory	8011140282	NUREG
Isaak Nathan League of America, Porter County Chapter	8011170272*	50-367 G		8010160495*	50-338 P
	8011170358	50-367 G	Louisiana County, VA	8011070402	50-382 A
	8011170381	50-367 G	Louisiana Power & Light Co.	8011110692	50-382 S
	8011280005	50-367 G		8011210511	50-382 A
Japan	8011110709	XPORTLIC		8011240306	50-382 K
	8011120632	NUREG		8011240320*	50-382 K
Jersey Central Power & Light Co.	8011260250	XPORTLIC		8011240326*	50-382 K
	8009300132	50-219 G		8011250402	50-382 X
	8011030527	50-219 P		8011260414*	50-382 G
	8011030527	50-219 P	Lovepeace (formed & Environmental) Research Institute	8011190695	NUREG
	8011030562	50-219 P		8011050194	50-466 G
	8011030628	50-289 T	Lowenstein, Newman, Keis, Axelrad & Toll	8011060467	50-494 G
	8011040412	50-289 T		8011060467	50-494 G
	8011040425	50-219 G		8011060469*	50-494 G
	8011040432*	50-219 G		8011060469*	50-494 G
	8011040435	50-289 T		8011140093	50-466 G
	8011040460	50-219 G		8011140493	50-466 G
	8011050423	50-219 P		8011140498	50-367 G
	8011050425*	50-219 P		8011170244	50-466 G
	8011110257	50-219 G		8011180147	50-466 G
	8011110267*	50-219 G		8011190176	50-466 G
	8011110281	50-289 T		8011250184	50-367 G
	8011120516	50-219 G		8011280033	50-367 G
	8011140100	50-219 G		8011140101	50-272 G
	8011170559	50-219 G	Lower Alloways Creek, NJ	8011250333*	50-454 G
	8011170765	50-219 G	MHD Technical Associates	8011040528	50-309 R
	8011170937*	50-219 G	Maine Yankee Atomic Power Co.	8011040536*	50-309 R
	8011180224	50-289 T		8011060122*	50-3 G
	8011180616	50-219 G		8011120361	50-309 P
	8011180645*	50-219 G		8011170583	50-309 G
	8011210343	50-289 G		8011180169	50-309 P
	8011250210	50-219 R		8011190303	50-309 P
	8011250214*	50-219 G		8011200172	50-309 G
	8011250500	50-219 G		8011210336*	50-309 G
	8011250510*	50-219 G		8011210563	50-309 G
	8011250524	50-219 G		8011240341	50-309 G
	8011250534*	50-219 G		8011300062*	50-309 G
John A. Plume & Associates, Engineers (subs. URS Corp.)	8011100063	FOIA	Maine, State of Mapleton Intervenor	8011180166	50-329 F
	8011050294*	50-341 A	Marsh & McLennan, Inc., & M Nuclear Consultants, Inc. Div.	8011030430	50-89 I
Joseph Oak Corp.	8011070316	50-413 G		8011070387	50-302 J
Justice, Dept. of	8011180047	50-389 G		8011180586	50-272 J
	8011040321	50-482 G	Martin Marietta Corp.	8011180354	FOIA
Kansas Gas & Electric Co.	8011170562	50-482 G	Maryland, State of	8011040501	50-320 P
	8011140618	50-482 G		801110812	PROJ
	8011170194	50-482 G		8011140315*	State Proc
	8011200030*	50-482 G		8011250154	PR
	8011250287	50-482 G	Maryland, Univ. of, Baltimore	801120632	NUREG
Kansas, State of	8011050121	PROJ	Massachusetts Institute of Technology	8011170504	50-361 A
	8011120514	HTSC		8011190070	NUREG
Kay-Ray, Inc.	8011180329*	HA999		8011260307	NUREG
Kee Corp., Kay Brook Div.	8011180327*	HA999		8011190383*	50-443 A
	8011040222	PROJ	Massachusetts, State of	8011190396*	50-443 A
Kentucky, State of	8011170868*	HA999		8011200340	50-443 G
White Co. (subs. of Harvey Hubbell, Inc.)	8011040060	REGGD		8011200340	50-443 G
	8010290375	40-8727		8011200341*	50-443 G
Kerr-McGee Corp.	8010290377*	40-8727		8011200341*	50-443 G
Kerr-McGee Nuclear Corp.	8011190025	40-8027	Massachusetts, Univ. of, Medical School	8011210339	PP
	8011180669	50-358 G	Mayer, Brown & Platt	8011050171	70-1308
Kosik, L. S.	8011130181*	70-2116		8011050410	70-1308
	8011030659	NUREG		8011050411*	70-1308
Lawrence General Hosp., Lawrence, MA	8011190085	NUREG		8011060452	70-1308
Lawrence Livermore Laboratory	8011190096	NUREG		8011110587	70-1308
	8011190096	NUREG		8011180037	70-1308
	8011190096	NUREG		8011120015*	70-2304
	8011190096	NUREG	Medical College of Pennsylvania & Hosp., Philadelphia, PA	8010150484	50-289 G
	8011190096	NUREG	Metropolitan Edison Co.	8011030352	50-289 G
	8011190096	NUREG		8011030501	50-289 G
	8011190096	NUREG		8011030680	50-289 G
	8011190096	NUREG		8011040388	50-320 P
	8011190096	NUREG		8011040436	50-320 G

347

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011040445*	50-320		8011060107	50-416
	8011040449	50-320		8011060107	50-416
	8011040457*	50-320		8011060700	50-416
	8011040458	50-320		8011060700	50-416
	8011040461*	50-320		8011060700	50-416
	8011040547*	50-289		8011100420	50-016
	8011050417	50-320		8011120350	50-016
	8011050418*	50-320		8011120355	50-016
	8011050420*	50-320		8011120355	50-016
	8011060394	50-289		8011140001	50-416
	8011060399*	50-289		8011140001	50-416
	8011060404*	50-289		8011140004	50-416
	8011060451	50-289		8011140007	50-416
	8011070288	50-320		8011140007	50-416
	8011070291*	50-320		80111400102	50-416
	8011070352	50-320		80111400102	50-416
	8011070356	50-320		8011140011	50-416
	8011070422	50-289		8011140011	50-416
	8011070426*	50-289		8011140011	50-416
	8011070507	50-289		8011170267	50-416
	8011120310	50-320		8011170281	50-416
	8011120381	50-320		8011180401	50-416
	8011120436	50-289		8011180492	50-416
	8011120501	50-320		8011180502	50-416
	8011120505	50-289		8011180686	50-416
	8011120513*	50-289		8011190410	50-416
	8011120518*	50-289		8011190523	50-416
	8011120612	50-320		8011200486*	50-416
	8011130395	50-289		8011250267	50-416
	8011140075	50-289		8011250267	50-416
	8011140289	50-289		8011250270*	50-416
	8011170231	50-289		8011250270*	50-416
	8011170769	50-289		8011250466	50-416
	8011170791	50-289		8011280064	50-416
	8011180413	50-320		8011280067*	50-416
	8011180425	50-320		8011280069*	50-416
	8011190196	50-289		8011050057	PR
	8011190270	50-289		8011280202*	50-186
	8011190273*	50-289		8011030443*	CONTRACT
	8011190285*	50-289		8011210101	XPORTLIC
	8011190799	50-320		8011210111*	XPORTLIC
	8011190485	50-320		8011070113	XPORTLIC
	8011200333	50-289		8011070120*	XPORTLIC
	8011200336	50-289		8011110212	XPORTLIC
	8011200352	50-320		8011110221*	XPORTLIC
	8011240151	50-289			
	8011240158*	50-289			
	8011240291	50-320			
	8011240294	50-320			
	8011240296*	50-320			
	8011240311	50-320			
	8011240315	50-320			
	8011240317*	50-320			
	8011250232	50-289			
	8011250297	50-320			
	8011250304	50-320			
	8011250416	50-289			
	8011250424	50-289			
	8011250458	50-289			
	8011250511	50-289			
	8011250517	50-320			
	8011250540	50-320			
	8011250547*	50-320			
	8011260077	50-289			
	8011260194	50-289			
	8004290477*	SECY			
	8011180069	50-358			
	8011110586*	State Proc			
	8011030438*	CONTRACT			
	8011050239	PR			
	8011120167	PR			
	8011190367	RES			
	8011250076	PP			
	8011250133	PR			
	8011250139	PR			
	8011260401	PR			
	8011190285*	50-289			
	8011240010	40-6584			
	8011180022	PR			
	8011190275	PR			
	8011030457	50-416			
	8011030457	50-416			
	8011030620	50-416			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	801110248	50-298 F		8011210396	50-336 P
	8011140118	50-298 R		8011210400*	50-336 P
	8011140020*	50-298 R		8011210455	50-336 S
	8011140031	50-298 V		8011210456*	50-336 S
	8011210488	50-298 S		8011210489	50-336 S
	8011210491*	50-298 S		8011210493*	50-336 S
	8011210495	50-298 S		8011210507	50-245 S
	8011210499*	50-298 S		8011210515*	50-245 S
	8011210564	50-298 S		8011240138	50-245 P
	8011210570*	50-298 S		8011240361	50-245 P
	8011260051*	50-298 Q		8011240370*	50-245 P
Nebraska, State of	8011280173	State Proj		8011250313	50-336 S
Neutron Products, Inc.	8011100245	71-121		8011250320*	50-336 S
	8011100249*	71-121		8011260233	50-336 Y
	8011140503	71-9044		8011280020	50-245 P
	8011040242	PROJ	Northeast Utilities	8011040158	50-213 Y
New England Coalition on Nuclear Pollution	8011040392	50-443 G		8011040463	50-336 S
	8011050177	50-443 G		8011040472*	50-336 S
	8011110599	PR		801180629	50-245 P
New Jersey, State of	8011030635*	50-289 T		801180635*	50-245 P
	8011040014*	50-289 T		8011200142	50-245 Q
	8011040441*	50-289 T		8011200167	50-336 Q
	8011050163	PP		8011200311	50-245 S
	8011110288*	50-289 T		8011250377	50-245 S
	8011170426*	50-272 G		8011250385*	50-245 S
	8011120671	PROJ		8011250388	50-245 S
	8011180229*	50-289 T	Northeast Utilities Service Co.	8011250391*	50-245 S
	801121037**	50-289 G	Northern Indiana Public Service Co.	8011140356*	50-213 P
	8011250577	50-272 G		8011030400	50-367 S
New Mexico, State of	8011030665	PROJ		8011040429	50-367 L
	8011210212	WASTE MGT		8011040493	50-367 P
New York State Electric & Gas Corp.	8011050164	50-596 G		8011050409	50-367 G
New York, State of	8011030653	50-201 P		8011120544	50-367 R
	8011030672	50-201 P		8011140489*	50-367 G
	8011040021	PROJ		8011140498	50-367 G
	8011040408	50-3 H		8011180140	50-367 P
	8011040408	50-3 H		8011210566	50-367 A
	8011100456	PR		8011250142	50-367 R
	8011100616	PR		8011280030	50-367 Q
Newberry Township, York Haven, PA	8011120044*	50-320 G	Northern States Power Co.	8011030435	50-243 Y
	8011280025	TOPREP		8011030467	50-282 Q
Newport News Industrial Corp. (subs. of Newport News Shipbuilding & Dry Dock Co.)	8011280027*	TOPREP		8011030471*	50-282 Q
	8010290010*	50-220 P		8011030596	50-263 P
	8011030481*	50-220 P		8011030597	50-263 S
	8011030485*	50-220 P		8011030603*	50-263 S
	8011030497	50-410 A		8011040122	50-282 Y
	8011040421	50-410 A		8011060486	50-306 S
	8011050166	PR		8011060488*	50-306 S
	8011050448	50-220 V		8011060494	50-306 S
	8011070380	50-220 S		8011060496*	50-306 S
	8011070381*	50-220 S		8011110331	50-306 S
	8011070465	50-410 A		8011110341*	50-306 S
	8011070469*	50-410 A		8011120533	50-263 P
	8011140332	50-220 P		8011120538*	50-263 P
	8011140336*	50-220 R		8011130411	50-263 P
	8011180459	50-220 P		8011140263	50-282 P
	8011180637	50-220 P		8011140263	50-282 P
	8011250369	50-410 A		8011170217	50-282 P
	8011030082	71-399		8011170508	50-282 R
	8011030089*	71-399		8011170510*	50-282 R
North Carolina, State of				8011170555	50-263 P
	801104002*	PROJ		8011170555	50-263 P
North Dakota, State of	8011180015	50-484 R		8011170555	50-263 P
Northeast Nuclear Energy Co. (subs. of Northeast Utilities)	8011030441	50-245 S		8011170802	50-282 S
	8011030445*	50-245 S		8011180248	50-263 P
	8011040423	50-336 Q		8011180508	50-263 Q
	8011040427*	50-336 Q		8011180680	50-306 S
	8011040431*	50-336 Q		8011180689*	50-306 S
	8011040439	50-245 P		8011190019	50-282 Q
	8011040444*	50-245 P		8011190019	50-282 Q
	8011040450*	50-245 P		8011190079	50-282 Q
	8011050219*	50-421 S		8011190079	50-282 Q
	8011070403	50-336 P		8011190341	50-263 Q
	8011100468	50-336 P		8011210449	50-263 S
	8011120375	50-245 S		8011210450*	50-263 S
	8011120537	50-245 S		8011210482	50-263 P
	8011140407	50-213 P		8011210484	50-282 P
	8011140407	50-213 P		8011210628	50-282 S
	8011140407	50-213 P		8011210632*	50-282 S
	8011190108	50-245 P		8011240471	50-282 Q
	8011200114*	50-245 Q		8011250410	50-282 Q
	8011200122*	50-245 Q		8011260104	50-263 Q
	8011200259	50-245 G		8011260181	50-306 S
				8011260182*	50-306 S
				8011280022	50-282 P

349

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011280022	50-282		8011170251	PR
	8011280063	50-282		8011640395	50-285
	8011280063	50-282	Omaha Public Power District	8011640095	50-285
	8011280066*	50-282		8011640507	50-285
	8011280066*	50-282		801170469	50-285
	8011280066*	50-282		8011120476*	50-285
	8011280068*	50-282		8011140127	50-285
	8011280101	50-263		8011180452*	50-285
Nuclear Assurance Corp.	8011070310	71-6698		8011180461*	50-285
	8011070350*	71-6698		8011180443	50-285
	8011070355*	71-6698		8011180647*	50-285
	8011110632	71-6698		8011190131	50-285
	8011180768	71-18		8011190163*	50-285
	8011180772*	71-18		8011190491	50-285
	8011190017	71-6698		8011250465	50-285
	8011050050	27-39		8011250474*	50-285
Nuclear Engineering Co., Inc., (subs. of Taledyne, Inc.)	8011100218	27-39	Oregon, State of	8011010026	PROJ
	8011100225*	27-39	P.S. Andersen	8011120644*	CONTRACT
	8011100233	27-39	Pacific Gas & Electric Co.	8011010661	REGDO
	8011170189	27-10		8011040555	NUREG
	8011190135	27-39		8011050168	PROJ
	8011190145*	27-39		8011050406	50-275
	8011190159*	27-39		8011100014	50-275
Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.)	8011040497	70-143		8011100067*	50-275
	8011040525	70-143		8011164402*	50-344
	8011040566	71-5059		8011180576	50-133
	8011050048	70-143		8011180579*	50-133
	8011060409	70-143		8011210104*	CONTRACT
	8011070348	70-143		8011210308	50-275
	8011070432	70-143		8011210300	50-275
	8011070435*	70-143		8011210318	50-275
	8011120295	70-143		8011210318	50-275
	8011120296	70-143		8011260002	50-275
	8011120313	70-2313		8011260125	50-275
	8011120531	70-143		8011260125	50-275
	8011120631	71-198	Pacific Scientific, Kin-Tech Div.	8011600110*	UA999
	8011130187*	70-143		8011040118*	UA999
	8011180567	70-143	Parameter, Inc.	8011040131*	UA999
	8011200510	70-143	Pathfinder Mines Corp.	8011170140*	CONTRACT
	8011210360	70-143		8011250288	40-2259
	8011040560	70-2313	Pell, D.M.	8011050158	50-289
Nuclear Fuel Services, Inc., West Valley Reprocessing Plant	8011040567*	70-2313	Pennsylvania Power & Light Co.	8011040126	50-387
	8011040578*	70-2313		8011040126	50-387
Nuclear Packaging, Inc.	8011040027	71-9132		8011040132*	50-387
	8011040029*	71-9132		8011040132*	50-387
	8011100135	71-9070		8011040136*	50-387
	8011100139*	71-9070		8011040142*	50-387
Nuclear Pharmacy, Inc.	8011100026	FOIA		8011040142*	50-387
Nuclear Services Corp.	8011120560*	50-237		8011040225	50-387
ORE, Inc.	8011170113*	CONTRACT		8011040225	50-387
Oak Ridge National Laboratory	8010020486	NUREG		8011040225	50-387
	8011030140*	FOIA		8011040233*	50-387
	8011030480	NUREG		8011040233*	50-387
	8011050578	RES		8011050008	50-387
	8011060408	PR		8011070407	50-388
	8011060412	PR		8011130334	50-387
	8011120192	REGDO		8011130334	50-387
	8011130246	RES		8011130350*	50-387
	8011140158	NUREG		8011130350*	50-387
	8011140669	NUREG		8011130375*	50-387
	8011170661	NUREG		8011200242	50-387
	8011170776	RES		8011200242	50-387
	8011170780	RES		8011200242	50-387
	8011170789	RES		8011200249*	50-387
	8011170797	RES		8011200249*	50-387
	8011170855	RES		8011210374*	50-387
	8011180538	RES		8011210591	50-387
	8011180729	50-247		8011250293	50-387
	8011240101	NUREG		8011250293	50-387
	8011240440	NUREG		8011250515	50-387
	8011260022	RES		8011250515	50-387
	8011260260	RES	Pennsylvania State Univ.	8011260071	50-387
	8011260266	NUREG		8011030478	50-5
	8011260323	RES	Pennsylvania, State of	8011180281	50-5
	8011260454	NUREG		8011110568*	50-320
	8010220504	40-8745		8011210309	PR
Ogle Petroleum, Inc.	8011070859	40-8745	Pennsylvania, Univ. of	8011030219	FOIA
	8011110140	40-8745	Pepper Hamilton & Sheetz	8011060187	50-888
	8011110149	40-8745	Pfeifferkorn & Conley, P.A.	8009290376	50-352
	8011110086	PR	Philadelphia Electric Co.	8009290378	50-352
	8011210102	REGDO		8009290380*	50-352
Ohio State Univ.	8011110816	PROJ		8009290382*	50-352
	8011110816	PROJ		8010290025*	50-277
	8011110816	PROJ		8011040486	50-277

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011040561	50-277 F		8011060506*	50-333 F
	8011040561	50-277 F		8011060509	50-333 F
	8011040554	50-277 G		8011060569	50-286 F
	8011040566	50-277 P		8011070290	50-333 F
	8011060566	50-277 P		8011070490	50-333 F
	8011120500	50-277 G		8011070503	50-286 F
	8011120510	50-277 G		8011110490	50-333 F
	80111100396	50-352 G		8011110492*	50-333 F
	80111100093	50-277 G		8011120483	50-333 F
	80111100497	50-277 P		8011120487*	50-333 F
	801111801197	50-277 P		8011120503	50-333 F
	80111180497	50-277 P		8011120549*	50-333 F
	80111180652	50-277 P		8011120556	50-333 F
	80111180665	50-277 P		8011120568*	50-333 F
	80111180665	50-277 P		8011170572	50-286 F
	80111180673*	50-277 P		8011180433	50-286 F
	80111180673*	50-277 P		8011180442*	50-286 F
	80111180695	50-277 P		8011180449*	50-286 F
	8011190124	50-277 Q		8011180552	50-286 F
	8011190124	50-277 Q		8011180651	50-286 F
	8011190203*	50-277 Q		8011180660*	50-286 F
	8011190307*	50-352 Q		8011180675	50-286 F
	8011250299*	50-277 P		8011190437	50-286 F
	8011250308	50-277 P		8011190439*	50-286 F
	8011250370	50-277 P		8011250280	50-286 F
	8011250370	50-277 P		8011250342	50-286 F
	8011250396	50-277 S		8011250356*	50-333 F
	8011250404*	50-277 S		8011250527	50-286 F
	8011260331	50-277 Q		8011260311	50-333 F
	8011260433*	50-277 Q		8011280015	50-333 F
Pickard, Lohr & Garrick Piano Archaeological Consultants Plateau Resources, Ltd.	8011210092	NEGRO	Prairie Alliance	8011050493	50-461 F
	8011040253*	40-86A1		8011060719	50-461 F
	8011030309	40-7849	President of US & Executive Offices	8011100578*	50-367 F
	8011180440	40-8698		8011180119*	50-289 F
Porter County Chapter Intervenor	8011240170	50-367 G		8011190648*	50-275 F
Portland Central Electric Co.	8011030569	50-344 P	Press Intelligence, Inc.	8011250680*	CONTRACT PR
	8011030580*	50-344 P	Princeton Univ.	8011120124	PR
	8011030587*	50-344 P		8011130841*	CONTRACT PR
	8011040279	50-344 P		8011250086	PR
	8011040285*	50-344 P	Pritsker & Associates, Inc.	8011030252	MUREU
	8011040290*	50-344 P	Procter & Gamble Co.	8011210321	PR
	8011040416	50-344 F	Public Service Co. of Colorado	8011100383	50-267 F
	8011040518	50-344 V		8011120312	50-267 F
	8011050269	50-344 P		8011120523	50-267 F
	8011070415	50-344 F		8011120529*	50-267 F
	8011070420*	50-344 F		8011140340	50-267 F
	8011070496	50-344 G		8011140343*	50-267 F
	8011070502*	50-344 F		8011140399	50-267 F
	8011070521	50-344 F		8011140401*	50-267 F
	8011070526*	50-344 F		8011140406	50-267 F
	8011100008	50-344 P		8011140411*	50-267 F
	8011100011*	50-344 P		8011180440	50-267 F
	8011120425	50-344 P		8011180620	50-267 F
	8011120428*	50-344 F		8011180659	50-267 F
	8011170597	50-344 Q		8011180667*	50-267 F
	8011180381	50-344 P		8011210477	50-267 F
	8011180390*	50-344 P		8011210478*	50-267 F
	8011180671	50-344 F		8011210541	50-267 F
	8011180677*	50-344 F		8011210552*	50-267 F
	8011250451	50-344 F		8011210575	50-267 F
	8011250464*	50-344 F		8011210581*	50-267 F
	8011260006	50-344 P		8011250250	50-267 F
	8011260208	50-344 P		8011250275	50-267 F
Powder River Basin Resource Council Power Authority of the State of New York	8011060306*	40-8703	Public Service Co. of Indiana, Inc.	8011280035*	50-267 F
	8008170621	50-333 P		8011030584	50-546 F
	8008170627*	50-333 P		8011030686*	50-546 F
	8011030452	50-286 P		8011050185	PR
	8011030529	50-286 P		801100398	50-546 F
	8011030536*	50-286 P		801100398	50-546 F
		50-286 P		801100477	50-546 F
		50-286 P		801100477	50-546 F
		50-286 P		8011140395	50-546 F
		50-286 P		8011140395	50-546 F
		50-286 V		8011170168	50-546 F
		71-9089		8011170168	50-546 F
		50-220 J		8011190533	50-546 F
		50-220 J		8011200011	50-546 F
		50-220 J		8011200052	50-546 F
		50-286 Q		8011200052	50-546 F
		Q		8011210287	50-546 F
				8011210754*	50-546 F
				8011210754*	50-546 F
				8011250289	50-546 F
				8011250413	50-546 F
				8011250454	50-546 F

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
Public Service Co. of New Hampshire	8011030576	REGD	Rocky Mountain Energy Co.	8011060422	70-25	
	8011030314	50-443 A		8011060415	50-94	
	8011040403	50-443 A		8011030671	REGD	
	8011090106	50-443 A		8011030697	REGD	
	8011090378*	50-443 A		8011050170	40-4697	
Public Service Electric & Gas Co. of New Jersey	8011030565	50-272 A	Ropes & Gray	8011110825	40-8340	
	8011030575*	50-272 A		8011050152	50-293	
	8011040433	50-272 A		8011190106	50-443	
	8011040451*	50-272 A		8011190371	50-443	
	8011050119*	50-354 A		8011240354	50-443	
	8011050529*	50-354 D	Roswell Park Memorial Institute Hynearson & Loudin	8011240354	50-443	
	8011060416	50-272 V		8011280003	50-443	
	8011060419	50-272 A		8011280003	50-443	
	8011120316	50-272 D		8011250041	PR	
	8011130204	50-272 F		8011070551	FOIA	
	8011170371	50-354 A	SAHCL, Stan A. Huber Consultants, Inc. SEP Owners Group SRI International	8011210026	PR	
	8011170446	50-272 R		8011210455	50-29	
	8011170451*	50-272 R		8011190709	NUREG	
	8011180583	50-311 R		8011030340	50-312	
	8011180587*	50-311 A		8011030615	50-312	
	8011180621	50-272 R		8011030622*	50-312	
	8011180627*	50-272 R		8011440208	50-312	
	8011180805*	50-272 D		8011040214*	50-312	
	8011190487	50-354 S		8011100017	50-312	
	8011190512	50-354 S		8011110192	PR	
8011200282	50-272 D	8011110222		50-312		
8011200291	50-272 A	8011110226*		50-312		
8011200296*	50-272 S	8011120370		50-312		
8011250237	50-311 D	8011120386		50-312		
8011250258*	50-311 D	8011120416		50-312		
	8011250296	50-272 D		8011120456	50-312	
	8011250296	50-272 D		8011120472	50-312	
	8011250300*	50-272 P		8011170478	50-312	
	8011250300*	50-272 D		8011120479	50-312	
	8011250302*	50-272 P		8011120601	50-312	
	8011250306*	50-272 P	8011130330	50-312		
	8011250697*	50-272 P		8011180655	50-312	
	8011250697*	50-272 P		8011190201	50-312	
	8011250698*	50-272 D		8011210519	50-312	
	8011260013	50-272 A		8011210589	50-312	
R&M Consultants, Inc. RPF Ecological Associates	8011260086	50-272 V		8011210599	50-312	
	8011280055	50-272 A		8011240169	50-312	
	8011280058*	50-272 S		8011240174*	50-312	
	8011050016*	70-2909		8011240261	50-312	
	8011140556	50-320 D		8011240314	50-312	
			8011240318*	50-312		
Radiation Management Corp.	8011170781*	CONTRACT		8011240356	50-312	
	8011210053	XPDRILIC		8011240362*	50-312	
	8011250522*	50-387 R		8011240364	50-312	
	8011030206	FOIA		8011240372*	50-312	
Rand Corp. Rensselaer Polytechnic Inst.	8011050544	NUREG		8011250448	50-312	
Research Triangle Institute Resource Management Associates Reuter-Stokes, Inc.	8011170393	NUREG		8011260154	50-312	
	8011260417	PR		8011120760	50-259	
	8011180161	FOIA		8011250557*	50-361	
	8011120322	REGD		8011200265	50-289	
Rhode Island Public Interest Research Group Rfo Algon, Ltd. Riverside, CA Rochester Gas & Electric Corp.	80111210062	REGD	San Jose State Univ. San Luis Obispo Mothers for Peace	8011210333	PR	
	801110312	FOIA		8011060227	50-275	
	8011120030	40-A084		8011100210	50-275	
	8011250557*	50-361 A		8011030252	NUREG	
	8009030485	50-244 P		8011030484	NUREG	
	8009030545	50-244 D	Sandia Laboratories	8011030495	NUREG	
	8011040237	50-244 D		8011040342	NUREG	
	8011040240*	50-244 P		8011050526	NUREG	
	8011040384	50-244 H		8011050573	RES	
	8011040459	50-244 A		8011140601	NUREG	
	8011040466*	50-244 A		8011170668	NUREG	
	8011060447*	50-244 P		8011170697	NUREG	
	8011060449*	50-244 P		8011170785	HF3	
	8011120335	50-244 D		8011200345	HF3	
	8011120337*	50-244 D		8011260317	HF3	
	8011120399	50-244 D	Sandyk Special Metals Corp. Sargent & Lundy, Inc.	8011240205	XPDRILIC	
	8011120401*	50-244 D		8011040373*	50-295	
	8011140103	50-244 P		8011120327	REGD	
	8011170200*	50-244 D		8011170211*	50-373	
	8011170205*	50-244 P		8011180334*	50-295	
	8011180590	50-244 R		8011140342*	50-295	
	8011180596*	50-244 R		8011140343*	50-295	
	8011180664	50-244 P		8011180346*	50-295	
	8011290274*	50-244 D		8011210077	REGD	
	8011200277*	50-244 P		8011260224*	50-295	
	8011250160	PR	8011260225*	50-295		
	Rockwell International Corp. Rockwell International Corp., Energy Systems Div.	8011140324		NUREG	8011260228*	50-295
		8011030017*		70-8	8011260231*	50-295
					8011260234*	50-295
					8011260237*	50-295

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011260201*	50-295 F		80112104967*	50-395 A
	8011260203*	50-295 F		80112104968*	50-395 A
	8011260205*	50-295 F		80112104969*	50-395 A
	8011260207*	50-295 F		8011210503	50-395 A
	8011260209*	50-295 F		8011210663*	50-395 A
	8011260253*	50-295 F			
	8011260259*	50-295 F		8011260329	50-395 S
	8011260262*	50-295 F		8011260333	50-395 S
	8011260266*	50-295 F		8011260482*	50-361 A
	8011260273*	50-295 F		8011260092	50-395 A
				8011260196	50-395 A
	8011260276*	50-295 F	South Carolina Public Service Authority	8011100344	50-395 D
	8011260278*	50-295 F		8011260596	50-395 D
	8011260284*	50-295 F	South Carolina, State of	8011040235	PROJ
	8011260290*	50-295 F	South Dakota, State of	8011180015	50-088 A
	8011260296*	50-295 F	Southern California Edison Co.	8011040212	50-361 A
	8011260301*	50-295 F			
Sessafraus Audubon Society	8011250537	50-10 H		8011040212	50-361 A
Sexton Nuclear Experimental Corp.	8011190255*	50-146 G		8011040437	50-206 A
	8011190263*	50-146 G		8011040447*	50-206 A
	8011200304	50-146 G		8011040520	50-206 P
				8011040526*	50-206 P
Schiff, Hardin & Raite	8011170902	50-461 G		8011060126*	50-361 G
	8011170902	50-461 G		8011070399	50-206 D
	8011170906*	50-461 G		8011100378	50-361 A
	8011170906*	50-461 G		8011120467	50-206 D
	8011170913	50-461 G		8011140027	50-206 R
Science Applications, Inc.	8011170913	50-461 G		8011140029*	50-206 R
	8011140191	NUREG		8011170547	50-361 S
	8011190183	NUREG		8011190026	71-9044
	8011190708	NUREG		8011190032	71-9099
Senate	8011040476	50-320 H		8011190295	50-206 A
Senate, Environment & Public Works	8011030263*	FOIA		8011190692	71-6601
Shaker Research Corp.	8011070135*	REVIEW GRP		8011200059	50-206 G
Shannon & Wilson, Inc.	8011030515	NUREG		8011200199	50-361 A
	8011180204	FOIA		8011200199	50-361 A
	8011180210*	FOIA		8011200247	50-361 A
Shaw, Pittman, Potts & Trowbridge	8011040542	50-289 T		8011200247	50-361 A
	8011050408	50-387 G		8011210148	50-361 K
	8011100283	50-483 G		8011210148	50-361 K
	8011130334	50-387 G		8011210157*	50-361 K
	8011130350*	50-387 G		8011210157*	50-361 K
	8011130375*	50-387 G		8011210442	50-206 J
	8011140075	50-289 G		8011200297	50-206 D
	8011170231	50-289 G		8011249285	50-361 A
	8011180139	50-483 G		8011250285	50-361 A
	8011190196	50-209 G		8011250298	50-361 A
	8011190279	50-289 G		8011250301	50-361 A
Sheldon, Harman & Weiss	8011040392	50-443 G		8011250301	50-361 A
	8011050177	50-443 G		8011250460	50-361 A
	8011060058	50-259 P		8011250471*	50-361 A
	8011110599	PP		8011250471*	50-361 A
	8011240516	50-247 T		8011250482*	50-361 A
Shoreham Opponents Coalition	8011040411	50-322 G		8011250482*	50-361 A
Sierra Club	8005140305	FOIA		8011250494*	50-361 A
	8011180020*	50-367 G		8011250494*	50-361 A
Sierra Geophysics, Inc.	8011180369	FOIA		8011250503*	50-361 A
Sigma Chemical Co. (subs. of Sigma-Aldrich Corp.)	8011030106	XPORTLIC		8011250503*	50-361 A
	8011050464	XPORTLIC		8011250549	50-361 A
	8011210796	XPORTLIC		8011250549	50-361 A
Sigma Instruments, Inc., International Instruments Div.	8011170840*	HA499		8011250557*	50-361 A
				8011280009	50-361 A
Small Business Administration	8011060296*	ENHACT			
				8011280011*	50-361 A
Society of Nuclear Medicine	8011120135	PP		8011280071	50-361 A
South Carolina Electric & Gas Co.	8011030494*	50-395 A		8011280073*	50-361 A
	8011040221	50-395 F		8011280073*	50-361 A
	8011040268	50-395 A	Southern California Univ. of	8011280231	NUREG
	8011040274	50-395 A			
	8011040569	50-395 V	Southern Science, Inc.	8011050294*	50-341 E
	8011050479	50-395 S	Southwest Research Institute	8011120557*	50-409 F
	8011060439	50-395 A	Spiegel & McVernau	8011180396	50-445 V
	8011060464	50-395 D		8011140542	50-445 V
	8011070264	50-395 V		8011180015	50-484 F
	8011100357	50-395 A	Square D Co., Electromagnetic Industries	8011170548*	HA499
	8011100371	50-395 A	St. Louis Univ.	8011170453	50-206 P
	8011120466	50-395 A	Standardized Nuclear Unit Power Plant System	8011120497	50-482 S
	8011130206	50-395 A			
	8011180122	50-395 K	State, Dept. of	8011170550	50-482 G
				8011060303	XPORTLIC
	8011180126*	50-395 V			
	8011180549	50-395 A		8011060308	XPORTLIC
	8011180699	50-395 H		8011060330	XPORTLIC
	8011200275	50-395 A		8011060336	XPORTLIC
	8011200279*	50-395 A	State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs	8011060348	XPORTLIC
				8011030096	XPORTLIC
	8011210285*	50-395 G			
	8011210466	50-395 A		8011060538	XPORTLIC
	8011210466*	50-395 A		8011060544	XPORTLIC
				8011060796	XPORTLIC

353

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011120378	50-390
	8011120421	50-327
	8011120426*	50-327
	8011120432	50-327
	8011120439*	50-327
	8011120448	50-260
	8011120455	50-327
	8011120457*	50-260
	8011120462*	50-327
	8011120468	50-327
	8011120475*	50-327
	8011120481	50-327
	8011120488*	50-327
	8011120507	50-259
	8011120517*	50-259
	8011120572	50-259
	8011120576*	50-259
	8011120580	50-296
	8011120585*	50-296
	8011120589	50-296
	8011120595*	50-296
	8011130119	50-259
	8011130241*	50-327
	8011130381	50-439
	8011130391	50-328
	8011140011	50-390
	8011140011	50-390
	8011140016	50-390
	8011140025	50-296
	8011140026	50-518
	8011140035	50-259
	8011140049	50-328
	8011140049	50-328
	8011140067	50-390
	8011140067	50-390
	8011140079	50-553
	8011140079	50-553
	8011140086	50-259
	8011140092	50-390
	8011140092	50-390
	8011140107	50-259
	8011140107	50-259
	8011140107	50-259
	8011140118	50-259
	8011140118	50-259
	8011140118	50-259
	8011140271	50-327
	8011140325	50-259
	8011140325	50-259
	8011140325	50-259
	8011140325	50-259
	8011140325	50-259
	8011140325	50-259
	8011140325	50-259
	8011140381	50-260
	8011140382*	50-260
	8011140426	50-438
	8011140428	50-438
	8011140434*	50-438
	8011140434*	50-438
	8011140438*	50-438
	8011140436*	50-438
	8011140439	50-328
	8011140557	50-553
	8011140557	50-553
	8011170152	71-6722
	8011180449	50-327
	8011180468	50-438
	8011180489	71-6568
	8011180527	50-327
	8011180527	50-327
	8011180530*	50-327
	8011180510*	50-327
	8011180515	50-328
	8011180551	50-553
	8011180568	50-327
	8011180571*	50-327
	8011180588	50-259
	8011180588	50-259
	8011180588	50-259
	8011180594*	50-259
	8011180624	50-327
	8011180633*	50-327
	8011180638	50-327
	8011180640	50-327

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011180644*	50-327	Texas Utilities Generating Co.	8011030287	50-445
	8011180644*	50-327		8011030585	50-445
	8011180682	50-327		8011140355	50-445
	8011180691*	50-327		8011140361	50-445
	8011180694	50-259		8011140367	50-445
	8011180701*	50-259		8011180494	50-445
	8011180707	50-327		8011250326	50-445
	8011180719*	50-327		8011250331*	50-445
	8011190117	50-390		8011280065	50-445
	8011190122*	50-390	Texas Utilities Services, Inc.	8011040535	50-445
	8011190122*	50-390		8011140458	50-445
	8011190281	50-438		8011250331*	50-445
	8011190281	50-438	Texas Univ. of Cancer Center	8011250070	PR
	8011190715	50-390	The Express Easton, PA	8011260065	50-219
	8011190715	50-390	Three Mile Island Alert	8011190208	50-289
	8011190737	50-566		8011040402	50-346
	8011200411*	50-438	Toledo Edison Co.	8011040475	50-346
	8011200422*	50-438		8011060476	50-346
	8011210078*	50-327		8011060481*	50-346
	8011210134*	50-390		8011070463	50-346
	8011210144*	50-390		8011100484	50-346
	8011210161*	50-390		8011100488*	50-346
	8011210209*	50-390		8011101197	50-346
	8011210271	50-327		8011110203*	50-346
	8011210276*	50-327		8011110223	50-346
	8011210448	50-438		8011110247	50-346
	8011210448	50-438		8011110258*	50-346
	8011210457	50-260		8011110263	50-346
	8011210458*	50-260		8011110272*	50-346
	8011210480	50-259		8011110293	50-346
	8011210485*	50-259		8011110302*	50-346
	8011210492	50-327		8011110308	50-346
	8011210497*	50-327		8011110316	50-346
	8011210502	50-327		8011110317*	50-346
	8011210537	50-259		8011110322*	50-346
	8011210548*	50-259		8011140426	50-346
	8011210565	50-327		8011140432*	50-346
	8011210574*	50-327		8011140455	50-346
	8011210580	50-328		8011170122	50-346
	8011210586	50-296		8011170411	50-346
	8011210596*	50-296		8011170551	50-346
	8011210598	50-296		8011180602	50-346
	8011210601	50-259		8011180610*	50-346
	8011210606*	50-296		8011210615	50-500
	8011210609*	50-259		8011250779	50-346
	8011240164	50-259		8011250329	50-346
	8011240332	50-327		8011280089	50-346
	8011240337*	50-327	Transamerica Delaval, Inc.	8011210432	50-361
	8011250245	50-328	Transnuclear, Inc.	8011050055	XPORTLIC
	8011250305	50-390		8011060355	XPORTLIC
	8011250336	50-327		8011060360*	XPORTLIC
	8011250345	50-259		8011110809	XPORTLIC
	8011250350*	50-259		8011140684*	SECY
	8011250357	50-438		8011140690*	SECY
	8011250376	50-260		8011210116	XPORTLIC
	8011250384*	50-260		8011260312	XPORTLIC
	8011250387	50-327	U. S. Water Resources Council	8011030151*	MISC
	8011250390*	50-327	U.S. District Court, District of Columbia	8011250027*	50-556
	8011250395	50-327	Union Carbide Corp.	8011070440	40-299
	8011250403*	50-327		8011070445*	40-299
	8011250406	50-259		8011110136	PR
	8011250406	50-259		8011110196	ASTE MGT
	8011250409	50-296		8011130099*	50-54
	8011250419*	50-296		8011180483	ASTE MGT
	8011250428	50-260		8011250319	40-299
	8011250436	50-260		8011250324	40-299
	8011250442*	50-260	Union Electric Co.	8011060505	50-483
	8011250449	50-327		8011100783	50-483
	8011250455*	50-327		8011170212*	50-483
		50-327		8011170221*	50-483
		50-280		8011180139	50-483
		50-280		8011190291	50-483
		50-280		8011040335	50-247
		50-259	Union of Concerned Scientists	8011060392*	40-299
		50-259	United Engineers & Constructors, Inc.		
			(subs. of Raytheon Co.)	801120564*	50-409
		70-143	United Kingdom	8011100202	NUREG
		40-8728		8011250125	PP
		40-8781	United Nuclear Corp.	8011110179	40-8602
		40-8781		8011180537	40-8602
		71-398	United Nuclear Corp., Naval Products Div.	8011100794	71-5086
		71-398		8011180288	50-556
		50-128	United Press International	8011200554*	50-546
		50-128	United States Testing Co., Inc.	8011250043	50-155
		50-128	Urban Law Institute	8011250120	PR
		70-33	Utah, State of		

CORPORATE SOURCE INDEX

355

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Venegas Industrial Testing Laboratories, Inc.	8011070628	71-9181
Vermont Yankee Nuclear Power Corp.	8011030177*	50-271 P
	8011030499	50-271 S
	8011030509*	50-271 S
	8011030560	50-271 S
	8011030567*	50-271 S
	8011040378	50-271 S
	8011040381*	50-271 S
	8011040385	50-271 S
	8011040387*	50-271 S
	8011040398	50-271 P
	8011060477	50-271 U
	8011110274	50-271 P
	8011110306	50-271 S
	8011110313*	50-271 S
	8011120532	50-271 P
	8011120539*	50-271 P
	8011170496	50-271 S
	8011170500*	50-271 R
	8011170783	50-271 Q
	8011180362	50-271 P
	8011180371*	50-271 P
	8011180578	50-271 R
	8011180584*	50-271 R
	8011180653	50-271 S
	8011180663*	50-271 S
	8011240083	50-271 P
	8011240406	50-271 S
	8011240412*	50-271 S
	8011110081	PR
Vet. Admin. Hosp. Bronx, NY		
Vet. Admin. Hosp. Hines, IL	8011260408	PR
Vet. Admin. Hosp. Nash, D.C.	8011110062	PR
Vet. Admin. Medical Center Ann Arbor, MI	8011110066	PR
	8011110150	PR
Virginia Electric & Power Co.	8010160487	50-338 F
	8011030432	50-280 S
	8011030433*	50-280 S
	8011030516	50-338 S
	8011030524*	50-338 S
	8011030645	50-338 F
	8011040011	50-339 P
	8011040012	50-281 P
	8011040019*	50-281 P
	8011040151	50-338 Q
	8011040312	50-339 P
	8011040327	50-280 Q
	8011040327	50-280 Q
	8011040327	50-280 Q
	8011040330*	50-280 Q
	8011040506	50-280 F
	8011040506	50-280 F
	8011040519*	50-280 F
	8011040519*	50-280 F
	8011040527*	50-280 F
	8011040527*	50-280 F
	8011040571	50-281 S
	8011040572	50-339 S
	8011040576*	50-281 S
	8011040580*	50-339 S
	8011040583	50-339 S
	8011040586*	50-281 S
	8011040588*	50-339 S
	8011040592*	50-281 S
	8011040594	50-280 S
	8011040602*	50-280 S
	8011060310	50-339 P
	8011060317*	50-339 P
	8011070340	50-338 S
	8011070342*	50-338 S
	8011070344	50-338 S
	8011070346*	50-338 S
	8011070376	50-339 P
	8011070377*	50-339 R
	8011070430	50-338 S
	8011070434*	50-338 S
	8011070452	50-404 A
	8011070479	50-280 Q
	8011070479	50-280 Q
	8011070513	50-339 S
	8011070517*	50-339 S
	8011100367	50-338 P
	8011100367	50-338 P
	8011100431	50-280 Q
	8011100431	50-280 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8011100431	50-280 Q
	8011100433	50-339 S
	8011100434*	50-339 S
	8011100464	50-339 P
	8011100467*	50-339 P
	8011100494	50-339 S
	8011100494*	50-339 S
	8011100501	50-281 S
	8011100505*	50-281 S
	8011100509	50-339 P
	8011110320	50-280 P
	8011110320	50-280 P
	8011110320	50-280 P
	8011110320	50-280 P
	8011110320	50-280 P
	8011110335	50-338 P
	8011120281	50-280 Q
	8011120433	50-339 S
	8011120440*	50-339 S
	8011120496	50-339 S
	8011120503*	50-339 S
	8011140006	50-280 S
	8011140009*	50-280 S
	8011140012	50-281 S
	8011140017*	50-281 S
	8011140387	50-280 P
	8011140388*	50-280 Q
	8011170407	50-338 S
	8011170414*	50-338 S
	8011170450	50-338 S
	8011170457	50-338 S
	8011170458*	50-338 S
	8011170461*	50-338 S
	8011170469	50-339 S
	8011170478*	50-339 S
	8011180554	50-339 S
	8011180564*	50-339 S
	8011180601	50-281 S
	8011180609*	50-281 S
	8011180618*	50-281 S
	8011180687	50-339 S
	8011180693*	50-339 S
	8011180700	50-339 S
	8011180710*	50-339 S
	8011190282	50-280 P
	8011190282	50-280 P
	8011190287*	50-280 P
	8011190287*	50-280 P
	8011200298	50-338 Q
	8011200300*	50-338 Q
	8011200379*	50-280 Q
	8011210216	50-280 P
	8011210352	50-280 Q
	8011210510	50-280 S
	8011210510	50-280 S
	8011210522*	50-280 S
	8011210535*	50-280 S
	8011210550*	50-280 S
	8011240091	50-281 S
	8011240300	50-280 P
	8011240300	50-280 P
	8011240321	50-339 S
	8011240321	50-339 S
	8011240328*	50-339 S
	8011240343	50-339 S
	8011240345	50-339 S
	8011240366*	50-339 S
	8011240349	50-280 S
	8011240349	50-280 S
	8011240352*	50-339 S
	8011240379	50-339 S
	8011240383*	50-339 S
	8011240387	50-338 S
	8011240391*	50-338 S
	8011240398	50-338 S
	8011240402*	50-338 S
	8011250355	50-280 P
	8011250361	50-338 S
	8011250364*	50-338 S
	8011250366	50-280 P
	8011250372*	50-280 P
	8011260089	50-280 V
	8011260089	50-280 V
	8011260089	50-280 V
	8011260179	50-339 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Virginia, State of	8011260180*	50-339 S		8011100483	50-266
Vollers, R. J.	8011260263	50-339 P		8011100487*	50-266
	8011060505*	50-338 F		8011120325	50-266
	8011170214	50-367 G		8011120325	50-266
	8011170272*	50-367 G		8011120358	50-266
	8011170358	50-367 G		8011120358	50-266
	8011170381	50-367 G		8011120368	50-266
	8011280005	50-367 G		8011120368	50-266
W.A. Wahler & Associates, Inc.	8011180498	WASTE MGT		8011170490	50-266
Walter Kidde & Co., Inc.; Renwal, Inc.	8011180477*	50-327 G		8011170490	50-266
Washington Public Power Supply System	8011050189	PR		8011170492*	50-266
	8011050433	50-397 S		8011170585	71-907
	8011070444	50-397 A		8011180436	50-266
	8011170377	50-397 A		8011180436	50-266
	8011190364	50-397 A		8011190577	50-266
	8011190451*	50-460 G		8011190577	50-266
	8011190455*	50-460 G		8011250206	50-266
	8011280093	50-397 G		8011250206	50-266
Washington Univ. Medical Center St. Louis, MO	8011050224	PR		8011280081	50-266
	8011110070	PR		8011280081	50-266
Washington, State of	8011120427	PROJ	Wisconsin Public Service Corp.	8011280196*	50-266
	8011170530*	State Prod		8011030520	50-305
	8011170534*	State Prod		8011040408	50-305
Washington, Univ. of	8011180165*	FOIA		8011040428	50-305
	8011180171*	FOIA		8011040532	50-305
	8011210317	PR		8011050394*	50-305
	8011210327	PR		8011140022	50-305
	8011140102	50-247 G		8011140024*	50-305
Westchester County, NY	8011040219*	50-361 A		8011180670	50-305
Westco Services, Inc.	8011040403*	40-1162		8011180678*	50-305
Western Nuclear, Inc. (subs. of Phelps Dodge Corp.)					
	8011050024	40-1162		8011210577	50-305
	8011070617	40-1162		8011210732*	50-305
Westinghouse Electric Corp.	8008260408	TOPREP	Miss, Janney, Listner & Association, Inc.	8011210738*	50-305
	8011020739	40-8304	Woodward-Clyde Consultants, Inc.	79-2190496*	50-255
	8011020745*	40-8304		8011100077*	FOIA
	8011030119	XPORTLIC		8011100085*	FOIA
	8011030124*	XPORTLIC		8011100094*	FOIA
	8011030368	70-1151	Worcester Polytechnic Inst.	8011250351	50-134
	8011050002	70-2909	Wyoming Mineral Corp.	8010230193	40-8502
	8011050005*	70-2909		8011030578	40-8502
	8011050010*	70-2909			
	8011050443	TOPREP		8011070293	40-8502
	8011050445*	TOPREP		8011101888	40-8502
	8011050449*	TOPREP		8011106446	40-8502
	8011050466	XPORTLIC		801110650*	40-8502
				8011120367	40-8505
				8011120635	40-8502
	8011060572*	50-266 P		8011120638	40-8502
	8011070101	NUMRG		8011120643	40-8502
	8011070142*	REVIEW GMP		8011170292	40-8502
	8011100387*	70-1143		8011170293	40-8502
	8011110165	70-1151			
	8011140660	TOPREP		8011170308	40-8502
	8011200362	XPORTLIC		8011170315	40-8502
	8011200366*	XPORTLIC		8011170319	40-8502
	8011200370	XPORTLIC		8011170325	40-8502
	8011200373*	XPORTLIC		8011170740	40-8502
	8011200407	50-533 A			
	8011200409	50-765 A	Wyoming Outdoor Council	8011190330	40-8502
	8011210135	XPORTLIC		8011190340	40-8502
	8011240188	TOPREP		8011040403*	40-1162
	8011240192*	TOPREP	Wyoming, State of	8011050407	40-1162
	8011250686	TOPREP		8011030336	40-8502
	8011260198*	50-395 A			
	8011260200*	50-395 A		8011070631	40-1162
	8011260204*	50-395 A		801110125	40-8502
	8011260207*	50-395 A		8011110131	40-8502
	8011260442	70-2172		8011120441	40-8502
	8011260477*	50-334 P		8011120449	40-8502
	8011050457*	TOPREP			
Westinghouse Electric Corp., Nuclear Energy Systems	8011174601*	50-344 G		8011170131	40-8502
Westinghouse Electric Corp., PAR Systems Div.	8011030513	TOPREP		8011170329	40-8502
	8011030521*	TOPREP		8011170921	40-8743
	8011030530*	TOPREP		8011190264	40-8502
	8011170222*	50-445 A		8011190336	40-8502
	8011210505	TOPREP			
Westinghouse Operating Plants Owners Group	8011040420	50-266 P		8011190345	40-8502
Wisconsin Electric Power Co.	8011000420	50-266 P		8011200140	40-8743
	8011060448	50-266 G		8011030543	50-29 P
	8011060448	50-266 G		8011030549*	50-29 P
	8011070322	50-266 P		8011030599	50-29 P
	8011070322	50-266 P			
				8011030610*	50-29 P
				8011050320	50-29 P
				8011050325*	50-29 P
				8011100475	50-29 S
				8011100482*	50-29 S
				8011110201	PP
				8011140046	50-29 P
				8011140052*	50-29 S
				8011140389	50-29 P
				8011140390*	50-29 P

CORPORATE SOURCE INDEX

357

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
-----	8011190118*	50-443 G
	8011190619*	50-29 G
	8011200329	50-29 P

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
04707-022-19	8011070469*	50-410 A	
15-1120590-00	8011210524*	50-312 P	BWNP-20004(4-74
2182	8011060329*	50-302 P	
8011040082	8011040082	REG	TFBP-TR-311
8011050537	8011050537	REG	EQO-TFSP-5230
8011050541	8011050541	REG	EQO-LOFT-5161
8011050573	8011050573	REG	SAND80-2428
8011050578	8011050578	REG	
8011050583	8011050583	REG	
8011060077	8011060077	REG	
8011060084	8011060084	REG	EQO-EA-5256
8011100204	8011100204	REG	
8011100215	8011100215	50-282 P	
8011100224	8011100224*	REG	
8011100232	8011100232*	REG	
8011120057	8011120057	REG	
8011120070	8011120070	REG	
8011120683	8011120683	REG	
8011130018	8011130018	50-272 P	EQO-EA-5265
8011130138	8011130138	REG	EQO-EA-5253
8011130153	8011130153	REG	EQO-LOFT-5270
8011130236	8011130236	REG	EQO-LOFT-5242
8011130246	8011130246	REG	TGP-1007
8011130252	8011130252	REG	8053621
8011170776	8011170776	REG	ORNL/HASRD-99
8011170780	8011170780	REG	ORNL/HASRD-97
8011170785	8011170785	REG	
8011170789	8011170789	REG	ORNL/HASRD-98
8011170797	8011170797	REG	ORNL/ED/EAB-80
8011170855	8011170855	REG	ORNL/MCD/NECB-8
8011180079	8011180079	REG	8052960
8011180538	8011180538	REG	
8011180729	8011180729	50-247 P	
8011180766	8011180766	REG	
8011180787	8011180787	REG	
8011190367	8011190367	REG	
8011200108	8011200108	50-334 P	EQO-EA-5275
8011200113	8011200113	50-334 P	EQO-EA-5254
8011200124	8011200124	REG	L-4472
8011200345	8011200345	REG	
8011200346	8011200346	50-289 P	EQO-EA-5258
8011240158	8011240158	REG	EQO-LOFT-5276
8011240466	8011240466	REG	EQO-CAAP-5277
8011260022	8011260022	REG	ORNL/HASRD-96
8011260260	8011260260	REG	
8011260317	8011260317	REG	
8011260323	8011260323	REG	ORNL/ED/EIB-138
PL-TDF 1A R5	8011180243*	50-313 P	
AM-10146	8011180262*	TOPREP	
AM-1606	8011040249*	50-313 P	
AM-1626	8011110508*	50-313 P	
ML-NUREQ-28403	8011110002	REG	
EN-140(8)-NP	8011200207*	50-361 A	
EN-144(3)-NP	8011260270	50-317 P	
ENPD-193-NP R1A	8011110469*	TOPREP	

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
EDP-5R2	8011210467*	50-395 A	
EI/NNI-77-7-NP	8011280027*	TOPREP	
EQP-1 R1	8011210466*	50-395 A	
EQP-13	8011210468*	50-395 A	
EQP-14	8011210469*	50-395 A	
EQDP-E6E-20 R2	8011050452*	TOPREP	
ERDA-1538	8011100087*	50-10 P	UC-70
HEDL-SA-1919FP	8011170556*	PROJ	
IDO-10074 R1	8011030024*	70-B	IDO-10074
LO-31-79-031	8011130144	REG	RE-A-79-047
LTR 10-13 RD	8011040247	REG	
MW79-720	8011210571*	50-367 A	
NEDO-11209-04A RA	8011280508*	TOPREP	
771214	7812190001	50-70 P	
NEDO-24146A	8011240393*	50-234 P	
NEDO-24239	8011210206*	50-325 P	
NEDO-24615 V1	8011250252*	TOPREP	80NED023
NEDO-24615 V2	8011250292*	TOPREP	80NED023
NEDO-24615 V3	8011250294*	TOPREP	80NED023
NEDO-24778	8011040232*	TOPREP	80NED018
NEDO-24855	8011240381*	50-234 P	
NPD-STD-001 R5	8011100150*	71-248	17670
NUREQ-C020 V4 N10	8011240436	NUREQ	
NUREQ-C090 V3 N01	8011030647	NUREQ	
NUREQ-0117 DRAFT	8010220282*	10CFR	
NUREQ-0304 V5 N01	8011050532	NUREQ	
NUREQ-0435 V2 N03	8011050523	NUREQ	
NUREQ-0487 81	8011210675*	50-397 A	
NUREQ-0534 SUPP	8011130325*	50-395 D	
NUREQ-0540 V2 N07	8011110617	NUREQ	
NUREQ-0540 V2 N08	8011280233	NUREQ	
NUREQ-0580 V9 N04	8011060664	NUREQ	
NUREQ-0584 R2 DRAFT	8011030510	NUREQ	
NUREQ-0639	8011170424*	40-1162	
NUREQ-0688	8011170721	NUREQ	
NUREQ-0697	8011050008*	50-364 P	
NUREQ-0707	8011240067	NUREQ	
NUREQ-0724	8011050568	NUREQ	
NUREQ-0725 DRAFT	8011170847*	COMMISSION	
NUREQ-0731 DRAFT	8011060359*	BECC	
NUREQ-0735	8011030429	NUREQ	45FR71023
NUREQ-0737	8011190215	NUREQ	
NUREQ-0738	8011140309	NUREQ	EPA 600/4-80-04
NUREQ-0739	8011240085	NUREQ	
NUREQ-0857	8011240420	NUREQ	
NUREQ/CR-0568	8011170697	NUREQ	SAND78-2428
NUREQ/CR-0849 V1 N02	8011190703	NUREQ	UCRL-52715-80-2
NUREQ/CR-0983 V9	80111040342	NUREQ	SAND79-1566
NUREQ/CR-1154 V1 N03	8011030482	NUREQ	GEAP-21304-13
NUREQ/CR-1154 V1 N04	8011140184	NUREQ	GEAP-21304-16
NUREQ/CR-1177 V13	8011170688	NUREQ	SAND79-2290
NUREQ/CR-1187	8011140200	NUREQ	CREARE TN-310
NUREQ/CR-1266 V1	8011140603	NUREQ	
NUREQ/CR-1266 V2 APP	8011170554	NUREQ	
NUREQ/CR-1275	8011030480	NUREQ	ORNL/NUREQ/N81C

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREG/CR-1376	8011030488	NUREG	SANDBO-0717	NUREG/CR-1764	8011190080	NUREG	
NUREG/CR-1394	8010230019	NUREG	NRC-03-79-132	NUREG/CR-1775	8011190708	NUREG	SA101380-469LJ/
NUREG/CR-1454 V1	8011170474	NUREG	PNL-3380-1 V1	NUREG/CR-1776	8011280232	NUREG	BMI-2060
NUREG/CR-1498	8011100463	NUREG	PNL-3324	NUREG/CR-1778	8011240100	NUREG	
NUREG/CR-1509	8011030495	NUREG	SANDBO-1304	ORNL/EIS-133/V2	8011060412	PR	
NUREG/CR-1517	8011260304	50-219 P		ORNL/EIS-156/V1	8011060408	PR	
NUREG/CR-1526 V2	8011100466	NUREG	ANL-80-34	ORP/BID 72-1	8011100091*	50-10 P	
NUREG/CR-1539	8011240428	NUREG	ANL-80-53	GUAD-1-79-234 R3	8011120560*	50-237 P	NSC-COM-0219-R0
NUREG/CR-1560	8011030659	NUREG	UCRL-15218	R-8007	8011070467*	50-335 P	
NUREG/CR-1565	8011030672	50-201 P	NYSQB/24 01 029	RH-80-B-WB1	8011190122*	50-390 R	
NUREG/CR-1566	8011030633	50-201 P		RMC-TR-80 01	8011250522*	50-387 R	
NUREG/CR-1571	8011170730	NUREG	BMI-2057	SECY-77-461	8011030071	SECY	
NUREG/CR-1572 V12	8011050526	NUREG	SANDBO-1072	SECY-78-011B	8011120687	SECY	
NUREG/CR-1588	8011190709	NUREG		SECY-78-044	8011200361	SECY	
NUREG/CR-1591	8011030252	NUREG	SANDBO-0529	SECY-78-044A	8011200383	SECY	
NUREG/CR-1603	8011190085	NUREG	UCRL-5300	SECY-78-111	8011200388	SECY	
NUREG/CR-1615	8011170661	NUREG	ORNL/NUREG/CSD/	SECY-79-362	8009190587*	FOIA	
NUREG/CR-1617	8011170529	NUREG	BNL-NUREG-51254	SECY-79-650	8011170943*	FOIA	
NUREG/CR-1618	8011140176	NUREG	BNL-NUREG-51255	SECY-79-650A	8011170948*	FOIA	
NUREG/CR-1619	8011140601	NUREG	SANDBO-1741	SECY-80-367	8011120079	SECY	IEB-79-018
NUREG/CR-1623	8011170563	NUREG	E00-2052	SECY-80-392	8009100225	SECY	
NUREG/CR-1627	8011240440	NUREG	ORNL/NUREG/TH-4	SECY-80-409	8009290528*	SECY	
NUREG/CR-1642	8011030515	NUREG	NRC-04-76-200	SECY-80-423	8010220339	SECY	IEB-79-018
NUREG/CR-1644	8011280231	NUREG		SECY-80-440	8011060353	SECY	
NUREG/CR-1646	8011140669	NUREG	ORNL/NUREG/NSIC	SECY-80-451A	8010300493	SECY	
NUREG/CR-1653	8011140324	NUREG	RFP-3129	SECY-80-45J	8010220457	SECY	
NUREG/CR-1654	8011140282	NUREG	LA-8494-PR	SECY-80-459	8010300009	SECY	
NUREG/CR-1669	8011190695	NUREG	LHF-76	SECY-80-485	8011100666	SECY	IEB-79-018
NUREG/CR-1670 V1	8011030664	NUREG	PNL-3396	SECY-80-486A	8011080592*	10CFR	
NUREG/CR-1673	8011190696	NUREG		SECY-80-487	8011140656	SECY	
NUREG/CR-1683 ERR	8011120065*	27-39		SECY-80-493	8011190010	SECY	
NUREG/CR-1684 V1	8011140191	NUREG	SA101580-343LJ	SECY-A-80-179	8011240486*	50-247 T	
NUREG/CR-1692	8011170393	NUREG		SECY-A-80-179A	8011240478*	50-247 T	
NUREG/CR-1693	8011170613	NUREG	BNL-NUREG-51265	TC-1778	8011170561*	PROJ	
NUREG/CR-1699	8011190070	NUREG		TH-586	8011090294*	50-341 A	OAT J-2437
NUREG/CR-1710 V2	8011260454	NUREG	ORNL/NUREG/TH-4	VEP-FRD-37	8011040014*	50-281 P	
NUREG/CR-1711	8011050354	NUREG	BMI-2064	WAMD-011	8010270115*	70-1092	
NUREG/CR-1712	8011260307	NUREG	NRC-04-74-232	WAMD-011 ADD	8011200343*	70-1092	
NUREG/CR-1713	8011120632	NUREG		WCAP-8587-E20A S2	8011050443*	TOPREP	
NUREG/CR-1718	8011050344	NUREG		WCAP-8587-E20B	8011050449*	TOPREP	
NUREG/CR-1721	8011210264	NUREG	UCRL-15273	WCAP-9224 APP A	8011030921*	TOPREP	
NUREG/CR-1722	8011190096	NUREG	UCRL-15274	WCAP-9224 APP B	8011030930*	TOPREP	
NUREG/CR-1723	8011260266	NUREG	ORNL/NUREG/TH-4	WCAP-9613	8011170601*	50-344 P	IEB-79-13
NUREG/CR-1724	8011140198	NUREG	ORNL/NUREG/TH-4	WCAP-9769	8011280077*	50-334 P	
NUREG/CR-1727	8011140320	NUREG	E00-2063	WR(70)-40-2-80 1 V1	8011140434*	50-438 A	
NUREG/CR-1742	8011100471	NUREG	BMI-2065	WR(70)-40-2-80 1 V2	8011140438*	50-438 A	
NUREG/CR-1743	8011170712	NUREG	BMI-2067	XN-WF-439 R2	8011120622*	71-3 P	17733
NUREG/CR-1753	8011190081	NUREG	PNL-3339	YAEC-1227	8011090325*	50-29 P	
NUREG/CR-1758	8011190183	NUREG	SA101580-455LJ				
NUREG/CR-1761	8011240101	NUREG	ORNL/NUREG/TH-3				

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7812190004	7812190001	78/12/14	50-70 P
7812190013	7812190001	78/12/14	50-70 P
7812190020	7812190001	78/12/14	50-70 P
7812190026	7812190001	78/12/14	50-70 P
7910010092	7910010016	79/09/26	FOIA
7910300552	7910300550	79/10/17	50-255 P
7912190487	7912190466	79/12/14	50-255 P
7912190496	7912190466	79/12/14	50-255 P
8003130581	8003130577	80/03/03	50-255 P
8003130585	8003130577	80/03/03	50-255 P
8003130587	8003130577	80/03/03	50-255 P
8003130590	8003130577	80/03/03	50-255 P
8003130592	8003130577	80/03/03	50-255 P
8004070401	8004070383	80/02/27	70-364
8005130284	8005130126	80/04/10	FOIA
8005270692	8005270337	80/05/16	FOIA
8007280369	8007280363	80/07/21	PT9
8008130627	8008130621	80/08/09	50-333 Q
8009100228	8009100225	80/08/21	SECY
8009190587	8009190299	80/09/04	FOIA
8009190630	8009190299	80/09/04	50-219 Q
8009290380	8009290378	80/09/24	50-352 B
8009290382	8009290378	80/09/24	50-352 B
8009290477	8009290474	80/09/12	SECY
8009290528	8009290520	80/09/12	SECY
8010020311	8010020309	80/09/16	50-364 A
8010020745	8010020739	80/09/04	40-8304
8010160491	8010160487	80/10/09	50-338 F
8010160493	8010160487	80/10/09	50-338 F
8010160498	8010160487	80/10/09	50-338 F
8010160501	8010160487	80/10/09	50-338 F
8010160502	8010160487	80/10/09	50-338 F
8010160505	8010160487	80/10/09	50-338 F
8010220053	8010220042	80/09/29	71-9010
8010220071	8010220042	80/09/29	71-9010
8010220282	8010220274	80/09/03	10CFR
8010270115	8010270112	80/09/25	70-1092
8010270468	8010270462	80/10/17	50-528 T
8010290010	8010290005	80/10/22	50-220 P
8010290014	8010290005	80/10/22	COMMISSION
8010290019	8010290005	80/10/22	COMMISSION
8010290028	8010290005	80/10/22	50-277 P
8010290377	8010290375	80/10/15	40-8727
8010290381	8010290379	80/10/17	40-4492
8010310162	8010310152	80/10/07	71-9086
8011030017	8011030009	80/10/10	70-8
8011030022	8011030009	80/10/10	70-8
8011030024	8011030009	80/10/10	70-8
8011030047	8011030045	80/09/18	70-25
8011030070	8011030069	80/10/02	71-398

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8011030075	8011030071	77/08/29	SECY
8011030078	8011030071	77/08/29	SECY
8011030088	8011030084	80/09/18	50-440 Q
8011030089	8011030082	80/10/02	71-399
8011030093	8011030084	80/09/18	50-440 Q
8011030097	8011030077	80/10/09	50-368 P
8011030102	8011030096	80/10/14	50-275 H
8011030103	8011030077	80/10/09	50-368 P
8011030105	8011030098	80/09/17	50-329 Q
8011030107	8011030077	80/10/09	50-368 P
8011030111	8011030098	80/09/17	50-329 Q
8011030114	8011030109	80/10/02	PR
8011030115	8011030110	80/09/17	CONTRACT
8011030124	8011030119	80/10/23	XPORTRIC
8011030126	8011030122	80/10/03	XPORTRIC
8011030128	8011030120	80/09/26	50-373 Q
8011030138	8011030132	80/10/20	50-358 Q
8011030140	8011030127	80/10/29	FOIA
8011030151	8011030147	80/10/15	MISC
8011030159	8011030152	80/10/28	50-302 P
8011030177	8011030172	80/10/15	50-271 P
8011030190	8011030184	80/10/17	50-374 S
8011030191	8011030193	80/10/15	TOPREP
8011030207	8011030201	80/10/24	71-6568
8011030209	8011030200	80/10/20	50-334 P
8011030216	8011030195	80/10/28	FOIA
8011030218	8011030200	80/10/20	50-334 P
8011030220	8011030213	80/10/24	71-9037
8011030223	8011030200	80/10/20	50-334 P
8011030225	8011030195	80/10/28	FOIA
8011030232	8011030226	80/10/27	71-248
8011030233	8011030227	80/07/29	FOIA
8011030238	8011030231	80/10/06	50-261 F
8011030240	8011030231	80/10/06	50-261 P
8011030247	8011030227	80/07/29	FOIA
8011030255	8011030248	80/10/21	50-358 Q
8011030263	8011030250	80/10/22	FOIA
8011030267	8011030260	80/10/17	50-321 Q
8011030270	8011030250	80/10/22	FOIA
8011030273	8011030250	80/10/22	FOIA
8011030275	8011030272	80/10/15	70-143
8011030280	8011030276	80/10/14	50-344 Q
8011030311	8011030302	80/09/26	50-335 P
8011030414	8011030410	80/10/14	50-324 S
8011030418	8011030413	80/10/24	50-324 S
8011030423	8011030417	80/10/28	50-261 S
8011030425	8011030421	80/10/27	50-324 S
8011030433	8011030432	80/10/27	50-280 S
8011030438	8011030436	80/10/17	CONTRACT
8011030443	8011030440	80/10/16	CONTRACT

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8011030445	8011030441	80/10/24	50-245	S	8011040214	8011040208	80/10/27	50-312	P
8011030445	8011030440	80/10/28	50-270	S	8011040215	8011040197	80/10/30	50-237	P
8011030471	8011030467	80/10/30	50-282	G	8011040216	8011040182	80/10/31	50-286	P
8011030481	8011030477	80/10/29	50-220	P	8011040219	8011040212	80/10/31	50-361	A
8011030484	8011030479	80/10/28	50-334	S	8011040232	8011040226	80/06/04	TOPREP	
8011030485	8011030477	80/10/29	50-220	P	8011040233	8011040225	80/10/31	50-387	F
8011030491	8011030487	80/10/24	50-269	S	8011040240	8011040237	80/10/31	50-244	P
8011030509	8011030499	80/10/31	50-271	S	8011040249	8011040245	80/10/31	50-313	P
8011030521	8011030513	80/10/24	TOPREP		8011040293	8011040250	80/10/09	40-8681	
8011030524	8011030516	80/10/24	50-338	S	8011040285	8011040279	80/10/31	50-344	P
8011030530	8011030513	80/10/24	TOPREP		8011040290	8011040279	80/10/31	50-344	P
8011030536	8011030529	80/10/31	50-286	P	8011040300	8011040297	80/10/02	50-346	Q
8011030539	8011030533	80/10/31	50-255	P	8011040302	8011040299	80/10/17	50-413	Q
8011030540	8011030534	80/10/24	50-327	G	8011040304	8011040299	80/10/17	50-413	Q
8011030544	8011030531	80/10/31	50-454	K	8011040306	8011040299	80/10/17	50-413	Q
8011030549	8011030543	80/10/22	50-29	P	8011040309	8011040305	80/10/02	50-546	Q
8011030550	8011030545	80/10/28	50-155	P	8011040310	8011040299	80/10/17	50-413	Q
8011030557	8011030552	80/10/21	50-443	O	8011040319	8011040313	80/09/23	50-324	Q
8011030561	8011030556	80/10/30	50-335	P	8011040323	8011040317	80/10/20	50-416	H
8011030567	8011030560	80/10/29	50-271	S	8011040326	8011040317	80/10/20	50-416	H
8011030571	8011030564	80/10/02	40-8743		8011040330	8011040325	80/10/22	50-280	Q
8011030573	8011030568	80/10/29	50-155	P	8011040337	8011040325	80/10/22	50-280	Q
8011030575	8011030565	80/10/28	50-272	S	8011040340	8011040325	80/10/22	50-280	Q
8011030580	8011030569	80/10/29	50-344	P	8011040345	8011040325	80/10/22	50-280	Q
8011030587	8011030569	80/10/29	50-344	P	8011040357	8011040352	80/09/26	50-261	Q
8011030593	8011030591	80/10/31	50-358	A	8011040363	8011040320	80/10/31	50-213	P
8011030603	8011030597	80/10/30	50-263	S	8011040366	8011040320	80/10/31	50-213	P
8011030605	8011030594	80/10/22	50-237	S	8011040373	8011040370	80/10/31	50-295	Q
8011030610	8011030599	80/10/22	50-29	P	8011040377	8011040376	80/10/29	50-334	R
8011030622	8011030615	80/10/28	50-312	S	8011040381	8011040378	80/10/28	50-271	S
8011030624	8011030618	80/10/14	50-324	S	8011040387	8011040385	80/10/28	50-271	S
8011030635	8011030628	80/10/27	50-289	T	8011040393	8011040389	80/10/28	50-327	S
8011030640	8011030632	80/10/22	50-237	S	8011040403	8011040400	80/10/30	40-1162	
8011030646	8011030658	80/10/14	40-8781		8011040414	8011040412	80/10/29	50-289	T
8011030684	8011030678	80/10/31	50-341	K	8011040418	8011040413	80/10/28	50-313	P
8011030686	8011030683	80/09/23	50-546	S	8011040427	8011040423	80/10/31	50-336	Q
8011030691	8011030685	80/10/29	50-247	S	8011040431	8011040423	80/10/31	50-336	Q
8011030700	8011030692	80/10/09	50-245	P	8011040432	8011040423	80/10/29	50-219	B
8011030703	8011030692	80/10/09	50-245	P	8011040434	8011040424	80/10/29	50-259	S
8011030708	8011030692	80/10/09	50-245	P	8011040441	8011040435	80/10/29	50-289	T
8011030753	8011030747	80/09/26	50-395	Q	8011040444	8011040439	80/10/31	50-245	F
8011040014	8011040012	80/10/29	50-281	P	8011040445	8011040436	80/10/30	50-320	S
8011040029	8011040027	80/08/25	71-9132		8011040446	8011040440	80/10/31	50-373	A
8011040036	8011040030	80/10/21	70-1201		8011040447	8011040437	80/10/27	50-206	S
8011040039	8011040030	80/10/21	70-1201		8011040450	8011040439	80/10/31	50-245	P
8011040044	8011040030	80/10/21	70-1201		8011040451	8011040433	80/10/30	50-272	B
8011040051	8011040030	80/10/21	70-1201		8011040453	8011040443	80/10/28	50-327	S
8011040060	8011040054	80/09/23	50-390	Q	8011040457	8011040449	80/10/29	50-320	S
8011040068	8011040064	80/10/20	50-413	Q	8011040461	8011040458	80/10/30	50-320	P
8011040073	8011040064	80/10/20	50-413	Q	8011040462	8011040454	80/10/29	50-324	B
8011040075	8011030070	80/10/20	50-320	H	8011040466	8011040459	80/10/31	50-244	B
8011040085	8011040080	80/10/20	QA999		8011040468	8011040460	80/10/24	50-219	R
8011040087	8011040080	80/10/20	QA999		8011040472	8011040463	80/10/28	50-336	S
8011040091	8011040080	80/10/20	QA999		8011040473	8011040467	80/10/31	50-289	T
8011040096	8011040080	80/10/20	QA999		8011040480	8011040467	80/10/31	50-289	T
8011040103	8011040099	80/08/21	QA999		8011040484	8011040471	80/10/27	50-260	S
8011040110	8011040105	80/10/20	QA999		8011040488	8011040467	80/10/31	50-289	T
8011040113	8011040105	80/10/20	QA999		8011040489	8011040483	80/10/20	50-128	P
8011040118	8011040105	80/10/20	QA999		8011040491	8011040467	80/10/31	50-289	T
8011040125	8011040105	80/10/20	QA999		8011040492	8011040487	80/10/29	50-333	S
8011040131	8011040105	80/10/20	QA999		8011040494	8011040483	80/10/20	50-128	P
8011040132	8011040126	80/10/31	50-387	A	8011040499	8011040482	80/10/29	50-302	B
8011040135	8011040105	80/10/20	QA999		8011040500	8011040467	80/10/31	50-289	T
8011040136	8011040126	80/10/31	50-387	A	8011040505	8011040478	80/10/31	50-269	S
8011040138	8011040105	80/10/20	QA999		8011040508	8011040467	80/10/31	50-289	T
8011040142	8011040126	80/10/31	50-387	A	8011040512	8011040474	80/10/23	50-249	S
8011040148	8011040105	80/10/20	QA999		8011040517	8011040506	80/10/31	50-280	F
8011040149	8011040146	80/10/30	50-269	P	8011040521	8011040470	80/10/27	50-293	G
8011040156	8011040153	80/09/10	QA999		8011040526	8011040520	80/10/31	50-206	P
8011040174	8011040170	80/10/17	CONTRACT		8011040527	8011040506	80/10/31	50-280	F
8011040178	8011040173	80/10/31	50-498	A	8011040534	8011040529	80/10/28	50-259	R
8011040183	8011040173	80/10/31	50-498	A	8011040536	8011040528	80/10/28	50-309	R
8011040184	8011040180	80/09/30	50-295	Q	8011040537	8011040531	80/09/26	50-302	G
8011040186	8011040182	80/10/31	50-286	P	8011040547	8011040542	80/10/30	50-289	T
8011040188	8011040173	80/10/31	50-498	A	8011040548	8011040541	80/09/23	50-395	G
8011040194	8011040191	80/10/29	50-440	Q	8011040558	8011040553	80/09/23	50-390	Q
8011040199	8011040196	80/10/31	50-155	P	8011040567	8011040560	80/10/29	70-2313	
8011040203	8011040197	80/10/30	50-237	P	8011040568	8011040565	80/09/22	50-348	Q
8011040207	8011040197	80/10/30	50-237	P	8011040575	8011040573	80/10/24	50-327	S
8011040210	8011040182	80/10/31	50-286	P	8011040576	8011040571	80/10/31	50-281	S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

363

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B011040578	B011040560	80/10/29	70-2313
B011040580	B011040572	80/10/30	50-339 S
B011040586	B011040571	80/10/31	50-281 S
B011040588	B011040583	80/10/30	50-339 S
B011040592	B011040571	80/10/31	50-281 S
B011040602	B011040594	80/10/30	50-280 S
B011040604	B011040599	80/10/28	50-327 S
B011040631	B011040626	80/10/27	50-320 T
B011040665	B011040660	80/09/26	50-382 Q
B011040674	B011040668	80/09/26	50-445 Q
B011040691	B011040688	80/10/24	50-271 F
B011050005	B011050002	80/09/23	70-2909
B011050006	B011050004	80/10/23	50-344 P
B011050008	B011050004	80/10/23	50-344 P
B011050009	B011050004	80/10/23	50-344 F
B011050010	B011050002	80/09/23	70-2909
B011050012	B011050004	80/09/23	50-344 F
B011050016	B011050002	80/09/23	70-2909
B011050017	B011050002	80/09/23	70-2909
B011050021	B011050019	80/10/24	50-289 Q
B011050028	B011050025	80/10/28	10CFR
B011050034	B011050030	80/10/23	10CFR
B011050044	B011050042	80/10/27	50-409 Q
B011050062	B011050046	80/10/23	50-296 U
B011050068	B011050046	80/10/23	50-296 U
B011050110	B011050104	80/10/28	50-454 Q
B011050119	B011050078	80/09/29	50-354 S
B011050123	B011050118	80/10/29	50-454 Q
B011050137	B011050135	80/10/02	50-305 Q
B011050142	B011050135	80/10/02	50-305 Q
B011050153	B011050147	80/10/28	50-282 Q
B011050184	B011050178	80/10/03	40-8084
B011050212	B011050208	80/10/07	50-269 P
B011050219	B011050063	80/09/24	50-423 S
B011050227	B011050222	80/10/29	50-302 Q
B011050231	B011050222	80/10/29	50-302 Q
B011050235	B011050222	80/10/29	50-302 Q
B011050241	B011050222	80/10/29	50-302 Q
B011050257	B011050247	80/10/28	50-261 Q
B011050261	B011050247	80/10/28	50-261 Q
B011050264	B011050247	80/10/28	50-261 Q
B011050268	B011050247	80/10/28	50-261 Q
B011050278	B011050273	80/09/29	50-348 Q
B011050286	B011050281	80/09/30	50-364 Q
B011050292	B011050290	80/09/30	50-364 Q
B011050294	B011050275	80/10/24	50-341 A
B011050300	B011050297	80/09/30	50-261 Q
B011050305	B011050299	80/10/30	50-293 S
B011050325	B011050320	80/10/31	50-29 P
B011050331	B011050328	80/11/02	50-317 P
B011050340	B011050337	80/09/16	50-285 Q
B011050347	B011050342	80/10/15	50-344 Q
B011050353	B011050350	80/10/17	50-206 Q
B011050360	B011050356	80/10/15	50-528 Q
B011050371	B011050366	80/10/27	50-364 Q
B011050375	B011050366	80/10/27	50-364 Q
B011050377	B011050366	80/10/27	50-364 Q
B011050381	B011050366	80/10/27	50-364 Q
B011050386	B011050383	80/09/02	50-298 Q
B011050394	B011050391	80/10/06	50-303 Q
B011050402	B011050400	80/10/02	50-344 Q
B011050403	B011050404	80/10/21	50-393 A
B011050411	B011050410	80/10/31	70-1308
B011050418	B011050417	80/10/31	50-320 P
B011050420	B011050417	80/10/31	50-320 P
B011050428	B011050423	80/10/28	50-219 P
B011050430	B011050427	80/10/15	50-295 P
B011050434	B011050432	80/11/03	50-445 Q
B011050445	B011050443	80/09/30	TOPREP
B011050449	B011050443	80/09/30	TOPREP
B011050452	B011050443	80/09/30	TOPREP
B011050455	B011050453	80/10/31	50-286 Q
B011050473	B011050467	80/10/28	50-230 Q
B011050476	B011050468	80/10/21	XPORTLIC
B011050477	B011050467	80/10/28	50-250 Q
B011050481	B011050467	80/10/28	50-250 Q
B011050485	B011050480	80/09/25	50-219 P
B011050487	B011050480	80/09/25	50-219 P
B011050496	B011050467	80/10/28	50-250 Q
B011050498	B011050492	80/09/25	50-409 P

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B011050502	B011050492	80/09/25	50-409 P
B011050503	B011050499	80/10/30	50-235 P
B011050508	B011050501	80/10/24	50-321 Q
B011050510	B011050506	80/11/04	50-317 P
B011050512	B011050501	80/10/24	50-321 Q
B011050513	B011050507	80/09/08	50-327 Q
B011050515	B011050506	80/11/04	50-317 P
B011050516	B011050501	80/10/24	50-321 Q
B011050519	B011050501	80/10/24	50-321 Q
B011050521	B011050517	80/09/04	70-133
B011050529	B011050525	80/09/29	50-354 Q
B011050533	B011050531	80/10/20	50-311 H
B011050559	B011050536	80/10/29	50-321 Q
B011050564	B011050536	80/10/29	50-321 Q
B011050569	B011050536	80/10/29	50-321 Q
B011050574	B011050536	80/10/29	50-321 Q
B011050580	B011050575	80/10/31	50-320 T
B011050592	B011050590	80/10/30	10CFR
B011050603	B011050599	80/10/30	50-230 P
B011050605	B011050599	80/10/30	50-230 P
B011050609	B011050599	80/10/30	50-230 P
B011050615	B011050611	80/10/30	50-348 P
B011050617	B011050611	80/10/30	50-348 P
B011050618	B011050611	80/10/30	50-348 P
B011060040	B011060035	80/10/03	MISC
B011060075	B011060071	80/10/21	50-266 F
B011060081	B011060079	80/10/01	50-29 F
B011060095	B011060093	80/09/24	50-298 Q
B011060101	B011060093	80/09/24	50-298 Q
B011060104	B011060098	80/09/22	50-289 H
B011060110	B011060093	80/09/24	50-298 Q
B011060119	B011060114	80/10/21	50-336 F
B011060122	B011060080	80/10/29	50-3 R
B011060126	B011060118	80/10/27	50-361 Q
B011060128	B011060117	80/10/28	50-269 Q
B011060130	B011060124	80/09/19	50-213 Q
B011060131	B011060118	80/10/27	50-361 Q
B011060133	B011060113	80/08/30	50-440 Q
B011060135	B011060118	80/10/27	50-361 Q
B011060136	B011060117	80/10/28	50-269 Q
B011060137	B011060080	80/10/29	50-289 R
B011060139	B011060124	80/09/19	50-213 Q
B011060141	B011060117	80/10/28	50-269 Q
B011060144	B011060118	80/10/27	50-361 Q
B011060145	B011060143	80/10/23	50-344 P
B011060146	B011060080	80/10/29	50-289 R
B011060149	B011060117	80/10/28	50-269 Q
B011060157	B011060153	80/10/28	50-364 Q
B011060160	B011060153	80/10/28	50-364 Q
B011060163	B011060153	80/10/28	50-364 Q
B011060168	B011060153	80/10/28	50-364 Q
B011060204	B011060197	80/10/06	71-9019
B011060206	B011060200	80/09/22	50-289 H
B011060207	B011060202	80/09/03	50-373 Q
B011060213	B011060208	80/10/20	50-320 H
B011060218	B011060212	80/09/19	50-306 Q
B011060222	B011060214	80/10/06	50-315 P
B011060225	B011060216	80/10/27	50-333 Q
B011060232	B011060214	80/10/06	50-315 P
B011060239	B011060231	80/10/23	QA999
B011060240	B011060233	80/10/14	71-397
B011060241	B011060214	80/10/06	50-315 P
B011060245	B011060231	80/10/23	QA999
B011060247	B011060231	80/10/23	QA999
B011060249	B011060237	80/10/20	50-320 H
B011060251	B011060242	80/09/18	50-440 Q
B011060252	B011060231	80/10/23	QA999
B011060262	B011060254	80/10/23	QA999
B011060265	B011060254	80/10/23	QA999
B011060269	B011060254	80/10/23	QA999
B011060270	B011060263	80/09/29	50-321 Q
B011060274	B011060271	80/09/16	50-264 Q
B011060278	B011060266	80/10/23	QA999
B011060279	B011060273	80/10/23	XPORTLIC
B011060286	B011060281	80/09/17	50-409 Q
B011060289	B011060287	80/09/15	QA999
B011060292	B011060284	80/10/03	50-329 Q
B011060293	B011060291	80/09/16	50-329 Q
B011060296	B011060294	80/10/16	CONTRACT
B011060297	B011060293	80/10/17	QA999

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8011060301	8011060293	80/10/17	QA999	8011070204	8011070182	80/11/04	50-237 T
8011060306	8011060302	80/10/10	40-8743	8011070209	8011070182	80/11/04	50-237 T
8011060307	8011060293	80/10/17	QA999	8011070211	8011070205	80/10/14	50-70 Q
8011060311	8011060305	80/10/02	50-456 Q	8011070214	8011070182	80/11/04	50-237 T
8011060317	8011060310	80/11/04	50-339 P	8011070218	8011070215	80/10/16	50-187 Q
8011060318	8011060313	80/09/18	QA999	8011070219	8011070182	80/11/04	50-237 T
8011060321	8011060314	80/09/12	QA999	8011070223	8011070215	80/10/16	50-187 Q
8011060329	8011060322	80/10/24	50-302 P	8011070225	8011070182	80/11/04	50-237 T
8011060332	8011060326	80/09/12	QA999	8011070282	8011070277	80/10/29	50-321 P
8011060334	8011060332	80/10/24	50-302 P	8011070291	8011070288	80/10/31	50-320 P
8011060349	8011060345	80/10/02	XPORTLIC	8011070329	8011070325	80/10/31	50-298 Q
8011060359	8011060353	80/09/19	SECY	8011070336	8011070332	80/10/31	50-317 B
8011060360	8011060355	80/10/06	XPORTLIC	8011070342	8011070340	80/11/03	50-338 B
8011060362	8011060354	80/10/17	71-6698	8011070346	8011070344	80/11/03	50-338 B
8011060371	8011060366	80/10/09	70-734	8011070350	8011070338	80/10/06	71-6698
8011060375	8011060367	80/10/14	50-285 P	8011070355	8011070338	80/10/06	71-6698
8011060376	8011060370	80/10/17	70-143	8011070358	8011070356	80/10/31	50-320 P
8011060378	8011060372	80/11/03	50-155 Q	8011070362	8011070359	80/10/15	MISC
8011060379	8011060367	80/10/14	50-285 P	8011070371	8011070370	80/10/24	50-298 Q
8011060383	8011060367	80/10/14	50-285 P	8011070372	8011070370	80/10/24	50-298 Q
8011060384	8011060372	80/11/03	50-155 Q	8011070374	8011070373	80/11/04	50-348 B
8011060392	8011060387	80/10/17	QA999	8011070376	8011070373	80/11/04	50-348 B
8011060397	8011060394	80/10/28	50-289 T	8011070377	8011070376	80/10/31	50-339 B
8011060402	8011060396	80/10/02	XPORTLIC	8011070379	8011070378	80/11/03	50-295 B
8011060404	8011060394	80/10/28	50-289 T	8011070381	8011070380	80/10/30	50-220 B
8011060447	8011060441	80/11/04	50-244 P	8011070383	8011070382	80/10/31	50-249 B
8011060447	8011060441	80/11/04	50-244 P	8011070385	8011070384	80/10/24	50-220 Q
8011060453	8011060452	80/10/30	70-1308	8011070388	8011070384	80/10/24	50-220 Q
8011060469	8011060467	80/11/03	50-498 H	8011070394	8011070391	80/10/24	50-333 Q
8011060479	8011060478	80/11/03	State Prog	8011070397	8011070391	80/10/24	50-333 Q
8011060481	8011060476	80/10/31	50-346 B	8011070410	8011070405	80/11/04	50-318 B
8011060484	8011060483	80/10/31	50-293 B	8011070417	8011070416	80/11/07	50-337 B
8011060488	8011060486	80/10/31	50-306 B	8011070419	8011070411	80/10/31	50-313 P
8011060490	8011060489	80/10/31	50-317 B	8011070420	8011070415	80/10/31	50-344 B
8011060496	8011060494	80/10/31	50-306 B	8011070426	8011070422	80/11/04	50-289 B
8011060501	8011060490	80/11/03	50-333 B	8011070434	8011070430	80/10/30	50-338 B
8011060504	8011060502	80/10/30	50-249 P	8011070435	8011070432	80/10/31	70-143
8011060506	8011060503	80/11/03	50-333 B	8011070445	8011070440	80/10/31	40-279
8011060521	8011060519	80/10/20	50-320 B	8011070446	8011070439	80/11/03	50-249 P
8011060572	8011060569	80/10/30	50-286 P	8011070467	8011070462	80/10/08	50-335 P
8011060577	8011060569	80/10/30	50-286 P	8011070469	8011070465	80/10/31	50-410 A
8011060582	8011060569	80/10/30	50-286 P	8011070474	8011070466	80/10/24	50-331 Q
8011060613	8011060607	80/10/07	70-1113	8011070478	8011070472	80/09/11	50-336 P
8011060617	8011060611	80/10/20	50-320 H	8011070480	8011070466	80/10/24	50-331 Q
8011060620	8011060607	80/10/07	70-1113	8011070489	8011070484	80/10/15	70-1100
8011060624	8011060621	80/10/21	50-329 A	8011070493	8011070486	80/10/24	50-263 Q
8011060631	8011060628	80/09/19	50-409 Q	8011070494	8011070484	80/10/15	70-1100
8011060640	8011060621	80/10/21	50-329 A	8011070497	8011070486	80/10/24	50-263 Q
8011060643	8011060621	80/10/21	50-329 A	8011070499	8011070484	80/10/15	70-1100
8011060647	8011060621	80/10/21	50-329 A	8011070502	8011070496	80/10/31	50-344 B
8011060651	8011060621	80/10/21	50-329 A	8011070503	8011070484	80/10/15	70-1100
8011060654	8011060621	80/10/21	50-329 A	8011070508	8011070504	80/10/24	50-335 Q
8011060657	8011060621	80/10/21	50-329 A	8011070512	8011070504	80/10/24	50-335 Q
8011060662	8011060621	80/10/21	50-329 A	8011070517	8011070513	80/11/03	50-339 B
8011060666	8011060621	80/10/21	50-329 A	8011070523	8011070516	80/10/24	50-299 Q
8011060671	8011060621	80/10/21	50-329 A	8011070526	8011070521	80/10/31	50-344 B
8011060676	8011060670	80/09/26	50-313 Q	8011070531	8011070516	80/10/24	50-257 Q
8011060682	8011060670	80/09/26	50-313 Q	8011070532	8011070528	80/09/15	70-398
8011060699	8011060694	80/10/27	50-116 Q	8011070537	8011070534	80/09/19	70-135
8011060709	8011060704	80/10/21	50-320 H	8011070546	8011070541	80/10/09	70-135
8011060797	8011060793	80/10/20	50-237 Q	8011070552	8011070541	80/10/09	70-135
8011060806	8011060803	80/09/29	50-335 Q	8011070556	8011070545	80/10/31	FOIA
8011060809	8011060800	80/10/16	50-375 Q	8011070558	8011070541	80/10/09	70-135
8011070040	8011070038	80/09/19	50-282 Q	8011070561	8011070545	80/10/31	40-8364
8011070041	8011070033	80/10/28	10CFR	8011070566	8011070545	80/10/31	FOIA
8011070047	8011070033	80/10/28	10CFR	8011070568	8011070545	80/10/31	FOIA
8011070071	8011070033	80/10/28	10CFR	8011070570	8011070562	80/10/24	50-266 Q
8011070077	8011070033	80/10/28	10CFR	8011070572	8011070545	80/10/31	FOIA
8011070078	8011070033	80/10/28	10CFR	8011070573	8011070545	80/10/24	50-271 Q
8011070085	8011070033	80/10/28	10CFR	8011070575	8011070545	80/10/31	FOIA
8011070120	8011070113	80/10/29	XPORTLIC	8011070576	8011070562	80/10/24	50-266 Q
8011070130	8011070126	80/10/28	50-277 F	8011070578	8011070567	80/10/24	50-271 Q
8011070135	8011070092	80/10/10	REVIEW QRP	8011070579	8011070545	80/10/31	40-8364
8011070136	8011070125	80/10/28	50-277 F	8011070582	8011070545	80/10/31	FOIA
8011070142	8011070092	80/10/10	REVIEW QRP	8011070584	8011070545	80/10/31	FOIA
8011070143	8011070125	80/10/28	50-277 F	8011070585	8011070581	80/10/24	50-293 Q
8011070169	8011070163	80/11/06	50-367 Q	8011070588	8011070581	80/10/24	50-293 Q
8011070173	8011070168	80/10/20	50-320 H	8011070590	8011070545	80/10/31	40-8364
8011070190	8011070182	80/11/04	50-237 T	8011070591	8011070587	80/10/16	50-94 Q
8011070199	8011070182	80/11/04	50-237 T	8011070596	8011070545	80/10/31	FOIA

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8011070204	8011070182	80/11/04	50-237 T
8011070209	8011070182	80/11/04	50-237 T
8011070211	8011070205	80/10/14	50-70 Q
8011070214	8011070182	80/11/04	50-237 T
8011070218	8011070215	80/10/16	50-187 Q
8011070219	8011070182	80/11/04	50-237 T
8011070223	8011070215	80/10/16	50-187 Q
8011070225	8011070182	80/11/04	50-237 T
8011070282	8011070277	80/10/29	50-321 P
8011070291	8011070288	80/10/31	50-320 P
8011070329	8011070325	80/10/31	50-298 Q
8011070336	8011070332	80/10/31	50-317 B
8011070342	8011070340	80/11/03	50-338 B
8011070346	8011070344	80/11/03	50-338 B
8011070350	8011070338	80/10/06	71-6698
8011070355	8011070338	80/10/06	71-6698
8011070358	8011070356	80/10/31	50-320 P
8011070362	8011070359	80/10/15	MISC
8011070371	8011070370	80/10/24	50-298 Q
8011070372	8011070370	80/10/24	50-298 Q
8011070374	8011070373	80/11/04	50-348 B
8011070376	8011070373	80/11/04	50-348 B
8011070377	8011070376	80/10/31	50-339 B
8011070379	8011070378	80/11/03	50-295 B
8011070381	8011070380	80/10/30	50-220 B
8011070383	8011070382	80/10/31	50-249 B
8011070385	8011070384	80/10/24	50-220 Q
8011070388	8011070384	80/10/24	50-220 Q
8011070394	8011070391	80/10/24	50-333 Q
8011070397	8011070391	80/10/24	50-333 Q
8011070410	8011070405	80/11/04	50-318 B
8011070417	8011070416	80/11/07	50-337 B
8011070419	8011070411	80/10/31	50-313 P
8011070420	8011070415	80/10/31	50-344 B
8011070426	8011070422	80/11/04	50-289 B
8011070434	8011070430	80/10/30	50-338 B
8011070435	8011070432	80/10/31	50-339 B
8011070445	8011070440	80/10/31	40-149 Q
8011070446	8011070439	80/11/03	50-269 P
8011070467	8011070462	80/10/08	50-335 P
8011070469	8011070465	80/10/31	50-410 A
8011070474	8011070466	80/10/24	50-331 Q
8011070478	8011070472	80/09/11	50-336 P
8011070480	8011070466	80/10/24	50-331 Q
8011070489	8011070484	80/10/15	70-1100 Q
8011070493	8011070486	80/10/24	50-263 Q
8011070494	8011070484	80/10/15	70-1100 Q
8011070497	8011070486	80/10/24	50-263 Q
8011070499	8011070484	80/10/15	70-1100 Q
8011070502	8011070496	80/10/31	50-344 B
8011070505	8011070484	80/10/15	70-1100 Q
8011070508	8011070504	80/10/24	50-335 Q
8011070512	8011070504	80/10/24	50-335 Q
8011070517	8011070513	80/11/03	50-339 B
8011070523	8011070516	80/10/24	50-299 Q
8011070526	8011070521	80/10/31	50-344 B
8011070531	8011070516	80/10/24	50-299 Q
8011070532	8011070528	80/09/15	70-399 B
8011070537	8011070534	80/09/19	70-135 B
8011070546	8011070541	80/10/09	70-135 B
8011070552	8011070541	80/10/09	70-135 B
8011070554	8011070545	80/10/31	FOIA
8011070558	8011070541	80/10/09	70-135 B
8011070561	8011070545	80/10/31	40-8364 FOIA
8011070566	8011070545	80/10/31	FOIA
8011070568	8011070545	80/10/31	FOIA
8011070570	8011070562	80/10/24	50-266 Q
8011070572	8011070545	80/10/31	FOIA
8011070573	8011070569	80/10/24	50-271 Q
8011070575	8011070545	80/10/31	FOIA
8011070576	8011070562	80/10/24	50-266 Q
8011070578	8011070569	80/10/24	50-271 Q
8011070579	8011070545	80/10/31	40-8364 FOIA
8011070582	8011070545	80/10/31	FOIA
8011070584	8011070545	80/10/31	FOIA
8011070585	8011070581	80/10/24	50-293 Q
8011070588	8011070581	80/10/24	50-293 Q
8011070590	8011070581	80/10/31	40-8364 FOIA
8011070591	8011070587	80/10/16	50-94 Q
8011070596	8011070545	80/10/31	FOIA

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

365

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8011070400	8011070545	80/10/31	FOIA	8011100437	8011100389	80/10/09	70-1143
8011070401	8011070595	80/10/24	50-336 Q	8011100440	8011100397	80/10/09	70-1143
8011070404	8011070595	80/10/24	50-336 Q	8011100445	8011100462	80/10/30	50-324 B
8011070405	8011070597	80/10/24	50-317 Q	8011100467	8011100464	80/11/07	50-337 P
8011070406	8011070545	80/10/31	FOIA	8011100473	8011100469	80/10/28	50-325 B
8011070410	8011070545	80/10/31	FOIA	8011100480	8011100475	80/10/30	50-335 B
8011070411	8011070597	80/10/24	50-317 Q	8011100482	8011100475	80/11/05	50-29 B
8011070425	8011070621	80/10/06	71-371	8011100487	8011100483	80/10/31	50-266 B
8011100004	8011100001	80/10/17	50-72 P	8011100488	8011100484	80/10/30	50-346 B
8011100011	8011100008	80/10/23	50-344 Q	8011100491	8011100490	80/10/31	50-335 P
8011100035	8011100031	80/10/30	CONTRACT	8011100498	8011100494	80/11/03	50-339 B
8011100037	8011110034	80/10/02	50-341 Q	8011100505	8011100501	80/11/04	50-281 B
8011100041	8011100033	80/11/04	FOIA	8011100510	8011100493	80/10/24	50-320 H
8011100043	8011100039	80/10/17	50-358 Q	8011100528	8011100523	80/11/06	50-320 B
8011100044	8011100040	80/10/31	50-247 P	8011100531	8011100521	80/09/29	50-289 Q
8011100046	8011100040	80/10/31	50-247 P	8011100533	8011100515	80/09/24	50-155 F
8011100051	8011100040	80/10/31	50-247 P	8011100539	8011100515	80/09/24	50-155 F
8011100054	8011100047	80/10/17	50-546 Q	8011100578	8011100374	80/10/27	50-367 U
8011100062	8011100055	80/10/14	50-309 F	8011100621	8011100618	80/10/31	50-320 U
8011100067	8011100061	80/10/16	50-275 Q	8011100624	8011100618	80/10/31	50-320 U
8011100069	8011100065	80/09/29	50-288 Q	8011100629	8011100627	80/11/07	50-255 Q
8011100076	8011100070	80/10/07	50-312 Q	8011100631	8011100630	80/11/04	50-237 T
8011100077	8011100056	80/11/03	FOIA	8011100634	8011100630	80/11/04	50-237 T
8011100082	8011100074	80/11/04	FOIA	8011100635	8011100630	80/11/04	50-237 T
8011100085	8011100056	80/11/03	FOIA	8011100638	8011100630	80/11/04	50-237 T
8011100086	8011100074	80/11/04	FOIA	8011100640	8011100630	80/11/04	50-237 T
8011100087	8011100083	80/05/19	50-10 P	8011100642	8011100630	80/11/04	50-237 T
8011100091	8011100083	80/05/19	50-10 P	8011100646	8011100630	80/11/04	50-237 T
8011100094	8011100056	80/11/03	FOIA	8011100650	8011100630	80/11/04	50-237 T
8011100096	8011100074	80/11/04	70-1237	8011100652	8011100630	80/11/04	50-237 T
8011100098	8011100089	80/09/19	40-8549	8011100656	8011100630	80/11/04	50-237 T
8011100106	8011100102	80/09/19	50-445 Q	8011100661	8011100630	80/11/04	50-237 T
8011100111	8011100104	80/09/19	50-259 Q	8011100667	8011100630	80/11/04	50-237 T
8011100112	8011100074	80/11/04	FOIA	8011110010	8011110006	80/10/27	70-162
8011100116	8011100102	80/09/19	50-445 Q	8011110014	8011110007	80/11/04	50-338 Q
8011100118	8011100109	80/09/19	50-498 Q	8011110022	8011110012	80/10/24	50-249 Q
8011100123	8011100074	80/11/04	FOIA	8011110023	8011110019	80/11/03	50-315 Q
8011100139	8011100135	80/10/10	71-9070	8011110029	8011110012	80/10/24	50-249 Q
8011100150	8011100145	80/10/21	71-248	8011110034	8011110027	80/10/17	50-10 Q
8011100157	8011100109	80/09/19	50-498 Q	8011110035	8011110012	80/10/24	50-249 Q
8011100186	8011100172	80/09/15	50-498 Q	8011110041	8011110012	80/10/24	50-249 Q
8011100225	8011100218	80/10/31	27-39	8011110050	8011110012	80/10/24	50-249 Q
8011100226	8011100215	80/09/19	RES	8011110054	8011110047	80/10/24	50-247 Q
8011100232	8011100215	80/09/19	RES	8011110058	8011110012	80/10/24	50-249 Q
8011100238	8011100234	80/10/24	50-320 H	8011110065	8011110047	80/10/24	50-247 Q
8011100249	8011100245	80/10/17	71-121	8011110077	8011110068	80/10/24	50-338 Q
8011100255	8011100247	80/10/24	50-320 H	8011110083	8011110068	80/10/24	50-338 Q
8011100261	8011100252	80/11/04	50-395 Q	8011110085	8011110078	80/10/24	50-348 Q
8011100273	8011100263	80/11/05	50-275 Q	8011110091	8011110078	80/10/24	50-348 Q
8011100276	8011100269	80/09/17	50-289 Q	8011110098	8011110021	80/08/25	0A999
8011100280	8011100275	80/10/03	50-334 P	8011110099	8011110088	80/10/24	50-334 Q
8011100292	8011100282	80/09/17	50-289 Q	8011110106	8011110088	80/10/24	50-334 Q
8011100298	8011100291	80/09/17	50-289 Q	8011110112	8011110100	80/10/24	50-286 Q
8011100306	8011100299	80/10/28	50-344 P	8011110120	8011110100	80/10/24	50-286 Q
8011100311	8011100303	80/09/17	50-199 Q	8011110155	8011110139	80/10/24	50-269 Q
8011100315	8011100299	80/10/28	50-344 P	8011110171	8011110139	80/10/24	50-269 Q
8011100332	8011100321	80/09/16	50-352 Q	8011110193	8011110184	80/10/31	50-254 R
8011100334	8011100324	80/09/16	50-271 Q	8011110203	8011110197	80/11/07	50-346 R
8011100348	8011100329	80/09/23	70-820	8011110214	8011110209	80/11/07	50-295 R
8011100350	8011100340	80/09/29	50-271 Q	8011110221	8011110212	80/10/27	XPORTLIC
8011100355	8011100344	80/09/26	50-443 Q	8011110226	8011110222	80/11/04	50-312 R
8011100369	8011100360	80/10/09	50-244 Q	8011110233	8011110230	80/11/04	50-302 P
8011100373	8011100363	80/09/29	50-387 Q	8011110236	8011110228	80/10/23	50-313 Q
8011100376	8011100371	80/11/05	50-395 A	8011110240	8011110235	80/11/06	50-263 Q
8011100379	8011100375	80/09/26	50-213 Q	8011110242	8011110239	80/11/04	50-327 P
8011100382	8011100377	80/10/31	50-313 P	8011110245	8011110235	80/11/06	50-263 Q
8011100387	8011100359	80/10/09	70-1143	8011110252	8011110235	80/11/06	50-263 Q
8011100388	8011100381	80/09/16	50-333 Q	8011110259	8011110247	80/11/05	50-346 B
8011100391	8011100386	80/11/04	50-261 B	8011110267	8011110257	80/11/03	50-219 B
8011100395	8011100392	80/10/24	XPORTLIC	8011110272	8011110263	80/11/07	50-346 B
8011100406	8011100400	80/10/29	50-254 B	8011110273	8011110261	80/11/06	50-313 B
8011100407	8011100401	80/10/31	50-295 B	8011110287	8011110277	80/11/07	50-368 B
8011100416	8011100410	80/10/31	50-295 B	8011110288	8011110281	80/11/04	50-289 T
8011100434	8011100433	80/11/03	50-339 B	8011110289	8011110280	80/11/04	50-368 B
8011100439	8011100436	80/10/23	50-265 B	8011110300	8011110295	80/11/04	50-368 B
8011100444	8011100440	80/11/03	50-368 B	8011110302	8011110293	80/11/05	50-346 B
8011100449	8011100447	80/10/31	50-368 B	8011110303	8011110290	80/11/06	50-302 D
8011100453	8011100452	80/11/05	50-318 B	8011110313	8011110306	80/11/06	50-271 B
8011100455	8011100454	80/10/27	50-293 B	8011110317	8011110308	80/10/30	50-346 B
8011100456	8011100359	80/10/09	70-1143	8011110322	8011110316	80/11/05	50-346 B

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
801110328	801110321	80/11/05	50-302 S	8011120426	8011120422	80/11/03	50-272 Q
801110337	801110327	80/10/24	50-368 Q	8011120428	8011120421	80/10/31	50-327 S
801110340	801110319	80/11/07	FOIA	8011120429	8011120425	80/11/03	50-344 S
801110341	801110331	80/11/07	50-306 S	8011120430	8011120432	80/10/31	50-327 S
801110347	801110327	80/10/24	50-368 Q	8011120440	8011120433	80/11/05	50-339 S
801110393	801110388	80/11/03	50-289 Q	8011120447	8011120442	80/10/29	50-334 S
801110399	801110390	80/09/19	50-244 Q	8011120452	8011120445	80/11/04	50-366 S
801110404	801110390	80/09/19	50-244 Q	8011120457	8011120448	80/11/06	50-260 S
801110409	801110402	80/10/27	50-267 Q	8011120460	8011120450	80/11/03	50-324 S
801110412	801110390	80/09/19	50-244 Q	8011120462	8011120455	80/10/31	50-327 S
801110424	801110402	80/10/27	50-267 Q	8011120464	8011120456	80/10/31	50-312 P
801110426	801110418	80/10/24	50-344 Q	8011120475	8011120468	80/11/03	50-327 S
801110434	801110418	80/10/24	50-344 Q	8011120476	8011120469	80/11/04	50-285 S
801110439	801110431	80/10/24	50-315 Q	8011120487	8011120483	80/11/06	50-333 R
801110445	801110431	80/10/24	50-315 Q	8011120488	8011120481	80/10/31	50-327 S
801110448	801110442	80/10/24	50-309 Q	8011120490	8011120484	80/11/05	50-302 S
801110451	801110431	80/10/24	50-315 Q	8011120503	8011120495	80/11/05	50-339 S
801110453	801110450	80/11/04	50-213 P	8011120512	8011120508	80/10/27	50-335 P
801110455	801110442	80/10/24	50-309 Q	8011120513	8011120505	80/11/07	50-289 P
801110457	801110431	80/10/24	50-315 Q	8011120517	8011120507	80/11/04	50-259 S
801110464	801110459	80/10/24	50-312 Q	8011120518	8011120505	80/11/07	50-289 P
801110467	801110461	80/09/04	TOPREF	8011120519	8011120499	80/11/04	50-366 S
801110470	801110459	80/10/24	50-312 Q	8011120526	8011120520	80/11/03	50-293 S
801110480	801110474	80/10/24	50-346 Q	8011120529	8011120523	80/11/05	50-267 S
801110484	801110474	80/10/24	50-346 Q	8011120538	8011120533	80/11/06	50-263 R
801110492	801110490	80/11/07	50-333 P	8011120539	8011120532	80/11/06	50-271 P
801110493	801110488	80/10/24	50-261 Q	8011120549	8011120543	80/11/07	50-333 S
801110498	801110488	80/10/24	50-261 Q	8011120557	8011120542	80/11/03	50-409 F
801110501	801110497	80/10/24	50-280 Q	8011120559	8011120553	80/11/03	50-320 H
801110506	801110500	80/10/24	50-235 Q	8011120560	8011120552	80/10/29	50-237 P
801110507	801110497	80/10/24	50-280 Q	8011120564	8011120542	80/11/03	50-409 F
801110508	801110503	80/11/06	50-313 F	8011120565	8011120561	80/10/27	State Prog
801110513	801110500	80/10/24	50-235 Q	8011120568	8011120556	80/11/07	50-333 S
801110515	801110497	80/10/24	50-280 Q	8011120571	8011120569	80/10/23	50-124 P
801110527	801110522	80/10/24	50-250 Q	8011120573	8011120569	80/10/23	50-124 P
801110532	801110522	80/10/24	50-250 Q	8011120576	8011120572	80/11/05	50-259 S
801110539	801110522	80/10/24	50-250 Q	8011120585	8011120580	80/11/07	50-296 S
801110535	801110549	80/10/24	50-324 Q	8011120595	8011120589	80/11/05	50-296 S
801110538	801110548	80/10/24	50-324 Q	8011120608	8011120604	80/11/06	50-270 S
801110539	801110548	80/10/24	50-324 Q	8011120614	8011120611	80/11/03	50-364 P
801110561	801110548	80/10/24	50-324 Q	8011120619	8011120609	80/11/07	50-255 R
801110568	801110564	80/11/06	50-330 T	8011120620	8011120614	80/11/05	50-73 P
801110570	801110565	80/10/24	50-277 Q	8011120622	8011120618	80/10/10	71-3
801110576	801110565	80/10/24	50-277 Q	8011120624	8011120616	80/11/05	50-73 P
801110579	801110565	80/10/24	50-277 Q	8011120644	8011120640	80/10/29	CONTRACT
801110580	801110573	80/10/24	50-295 Q	8011120651	8011120648	80/10/22	71-371
801110582	801110565	80/10/24	50-277 Q	8011120654	8011120648	80/10/22	71-371
801110584	801110578	80/10/27	COMMISSION	8011120661	8011120657	80/10/20	71-382
801110585	801110573	80/10/24	50-295 Q	8011120681	8011120677	80/10/29	CONTRACT
801110586	801110583	80/10/29	State Prog	8011120686	8011120685	80/09/29	50-266 Q
801110591	801110573	80/10/24	50-295 Q	8011120689	8011120685	80/09/29	50-266 Q
801110602	801110595	80/10/24	State Prog	8011130006	8011130001	80/10/30	50-320 P
801110606	801110600	80/10/24	50-321 Q	8011130013	8011130010	80/10/28	70-1966
801110607	801110595	80/10/24	State Prog	8011130028	8011130022	80/10/22	50-261 P
801110614	801110600	80/10/24	50-321 Q	8011130030	8011130022	80/10/22	50-261 P
801110631	801110625	80/10/24	50-213 Q	8011130033	8011130022	80/10/22	50-261 P
801110638	801110625	80/10/24	50-213 Q	8011130050	8011130043	80/09/03	50-289 Q
801110650	801110646	80/10/16	40-8502	8011130056	8011130049	80/11/03	50-320 T
801110668	801110661	80/10/24	50-155 Q	8011130060	8011130054	80/09/24	50-311 Q
801110676	801110661	80/10/24	50-155 Q	8011130066	8011130061	80/09/24	50-286 Q
801110679	801110669	80/10/24	50-245 Q	8011130082	8011130074	80/10/24	ORG
801110687	801110669	80/10/24	50-245 Q	8011130084	8011130076	80/09/22	50-354 Q
801110754	801110745	80/10/28	TOPREF	8011130085	8011130081	80/11/05	71-382
8011120018	8011120011	80/10/14	70-2304	8011130099	8011130090	80/10/02	50-54 Q
8011120021	8011120017	80/10/28	50-320 H	8011130105	8011130090	80/10/02	50-54 Q
8011120022	8011120011	80/10/14	70-2304	8011130109	8011130090	80/10/02	50-54 Q
8011120027	8011120011	80/10/14	70-2304	8011130113	8011130090	80/10/02	50-54 Q
8011120044	8011120038	80/10/28	50-320 Q	8011130136	8011130130	80/09/15	50-289 Q
8011120064	8011120062	80/10/30	50-320 T	8011130152	8011130143	80/09/15	50-220 Q
8011120065	8011120061	80/10/29	27-39	8011130165	8011130159	80/09/16	50-247 Q
8011120087	8011120082	80/11/07	50-369 Q	8011130179	8011130172	80/10/29	50-400 Q
8011120089	8011120082	80/11/07	50-369 Q	8011130181	8011130177	80/10/08	70-2116
8011120092	8011120082	80/11/07	50-369 Q	8011130184	8011130177	80/10/08	70-2116
8011120100	8011120095	80/11/05	50-275 Q	8011130186	8011130182	80/11/07	50-358 K
8011120113	8011120108	80/10/20	COMMISSION	8011130187	8011130172	80/10/29	50-400 Q
8011120337	8011120335	80/11/04	50-244 P	8011130190	8011130177	80/10/08	70-2116
8011120344	8011120339	80/11/07	50-269 S	8011130196	8011130172	80/10/29	50-400 Q
8011120354	8011120351	80/10/29	50-334 S	8011130201	8011130172	80/10/29	50-400 Q
8011120401	8011120399	80/11/06	50-244 Q	8011130203	8011130199	80/11/07	50-269 P
8011120410	8011120407	80/10/29	50-295 P	8011130204	8011130194	80/10/30	NUREG

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

387

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8011130205	8011130197	80/10/31	50-313 P
8011130207	8011130172	80/10/29	50-400 Q
8011130211	8011130194	80/10/30	NUREG
8011130215	8011130172	80/10/29	50-400 Q
8011130223	8011130172	80/10/29	50-400 Q
8011130230	8011130222	80/11/05	50-324 P
8011130241	8011130232	80/10/30	50-327 Q
8011130249	8011130232	80/10/30	50-327 Q
8011130250	8011130232	80/10/30	50-327 Q
8011130256	8011130232	80/10/30	50-327 Q
8011130325	8011130319	80/11/10	50-395 D
8011130329	8011130321	80/09/16	70-364
8011130348	8011130341	80/09/16	70-371
8011130350	8011130334	80/11/06	50-387 Q
8011130361	8011130334	80/11/06	50-387 Q
8011130369	8011130356	80/10/03	50-250 Q
8011130375	8011130334	80/11/06	50-387 Q
8011130387	8011130377	80/10/27	70-143
8011130392	8011130377	80/10/27	70-143
8011130398	8011130377	80/10/27	70-143
8011130405	8011130377	80/10/27	70-143
8011140004	8011140003	80/10/31	50-142 J
8011140008	8011140003	80/11/03	50-237 S
8011140009	8011140006	80/11/10	50-280 S
8011140013	8011140010	80/11/07	50-324 S
8011140017	8011140012	80/11/07	50-281 S
8011140019	8011140014	80/10/29	50-254 S
8011140020	8011140018	80/11/07	50-298 R
8011140024	8011140022	80/11/07	50-305 R
8011140029	8011140027	80/11/06	50-206 R
8011140033	8011140028	80/11/05	50-368 S
8011140036	8011140032	80/11/05	50-368 S
8011140041	8011140034	80/11/10	50-295 S
8011140044	8011140039	80/11/07	50-325 S
8011140047	8011140042	80/11/05	50-329 Q
8011140050	8011140043	80/11/07	50-302 S
8011140052	8011140046	80/11/11	50-29 S
8011140069	8011140062	80/11/07	50-367 Q
8011140074	8011140090	80/11/05	50-261 P
8011140076	8011140091	80/11/07	50-348 K
8011140078	8011140091	80/11/07	50-348 K
8011140129	8011140121	80/11/07	50-30 W
8011140171	8011140159	80/10/24	50-272 Q
8011140178	8011140159	80/10/24	50-272 Q
8011140197	8011140187	80/10/31	50-313 P
8011140267	8011140264	80/10/28	50-321 P
8011140270	8011140264	80/10/28	50-321 P
8011140276	8011140264	80/10/28	50-321 P
8011140315	8011140312	80/10/31	State Prog
8011140316	8011140313	80/09/30	50-160 Q
8011140336	8011140332	80/11/05	50-220 R
8011140343	8011140340	80/11/07	50-267 R
8011140356	8011140349	80/11/07	50-213 P
8011140374	8011140372	80/11/10	50-269 S
8011140380	8011140378	80/11/06	50-366 S
8011140382	8011140381	80/11/10	50-260 S
8011140384	8011140383	80/11/07	50-368 S
8011140386	8011140385	80/11/07	50-368 S
8011140388	8011140387	80/11/12	50-280 R
8011140390	8011140389	80/11/12	50-29 R
8011140392	8011140391	80/11/10	50-261 R
8011140397	8011140394	80/11/10	50-324 R
8011140401	8011140399	80/11/10	50-267 S
8011140411	8011140406	80/11/10	50-267 S
8011140416	8011140414	80/11/06	50-313 R
8011140424	8011140420	80/10/31	50-313 F
8011140432	8011140426	80/11/07	50-346 S
8011140434	8011140428	80/11/06	50-438 A
8011140438	8011140428	80/11/06	50-438 A
8011140450	8011140442	80/11/10	50-324 S
8011140457	8011140452	80/11/10	50-255 S
8011140460	8011140456	80/11/11	50-317 S
8011140471	8011140466	80/11/07	50-367 Q
8011140474	8011140466	80/11/07	50-367 Q
8011140476	8011140466	80/11/07	50-367 Q
8011140479	8011140466	80/11/07	50-367 Q
8011140482	8011140466	80/11/07	50-367 Q
8011140485	8011140466	80/11/07	50-367 Q
8011140489	8011140466	80/11/07	50-367 Q
8011140490	8011140466	80/11/07	50-367 Q

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8011140474	8011140466	80/11/07	50-367 Q
8011140477	8011140466	80/11/07	50-367 Q
8011140500	8011140466	80/11/07	50-367 Q
8011140505	8011140466	80/11/07	50-367 Q
8011140507	8011140501	80/11/07	50-395 H
8011140508	8011140466	80/11/07	50-367 Q
8011140512	8011140466	80/11/07	50-367 Q
8011140517	8011140466	80/11/07	50-367 Q
8011140526	8011140466	80/11/07	50-367 Q
8011140530	8011140466	80/11/07	50-367 Q
8011140538	8011140466	80/11/07	50-367 Q
8011140545	8011140522	80/11/06	50-338 Q
8011140546	8011140466	80/11/07	50-367 Q
8011140569	8011140466	80/11/07	50-367 Q
8011140574	8011140466	80/11/07	50-367 Q
8011140586	8011140577	80/10/28	CONTRACT
8011140626	8011140617	80/09/18	50-244 F
8011140638	8011140630	80/10/24	50-302 Q
8011140647	8011140630	80/10/24	50-302 Q
8011140668	8011140656	80/10/29	SECY
8011140677	8011140674	80/09/19	40-8412
8011140679	8011140656	80/10/23	SECY
8011140681	8011140678	80/10/23	50-320 P
8011140682	8011140674	80/09/19	40-8412
8011140684	8011140656	80/10/29	SECY
8011140686	8011140674	80/09/19	40-8412
8011140687	8011140678	80/10/23	50-320 P
8011140688	8011140674	80/09/19	40-8412
8011140690	8011140656	80/10/29	SECY
8011140692	8011140683	80/10/24	50-282 Q
8011140693	8011140674	80/09/19	40-8412
8011140695	8011140683	80/10/24	50-282 Q
8011170048	8011170045	80/10/31	50-320 H
8011170066	8011170056	80/10/01	50-302 Q
8011170090	8011170086	80/10/27	XPORTRIC
8011170107	8011170101	80/09/25	0A999
8011170109	8011170098	80/10/30	50-311 Q
8011170113	8011170105	80/10/31	CONTRACT
8011170114	8011170098	80/10/30	50-311 Q
8011170124	8011170116	80/08/25	0A999
8011170137	8011170127	80/11/03	MIBC
8011170140	8011170129	80/10/23	CONTRACT
8011170200	8011170196	80/11/13	50-244 P
8011170204	8011170198	80/09/16	50-483 Q
8011170205	8011170196	80/11/13	50-244 P
8011170211	8011170209	80/11/10	50-373 A
8011170212	8011170198	80/09/16	50-483 Q
8011170221	8011170198	80/09/16	50-483 Q
8011170223	8011170172	76/08/11	50-259 Q
8011170227	8011170198	80/09/16	50-483 Q
8011170232	8011170198	80/09/16	50-483 Q
8011170234	8011170172	76/08/11	50-259 Q
8011170238	8011170172	76/08/11	50-259 Q
8011170239	8011170256	80/11/06	50-397 Q
8011170263	8011170256	80/11/06	50-397 Q
8011170266	8011170259	80/10/10	70-882
8011170272	8011170214	80/11/07	50-367 Q
8011170275	8011170259	80/10/10	70-882
8011170278	8011170259	80/10/10	70-882
8011170284	8011170259	80/10/10	70-882
8011170288	8011170259	80/10/10	70-882
8011170294	8011170287	80/10/24	50-305 Q
8011170297	8011170259	80/10/10	70-882
8011170302	8011170287	80/10/24	50-305 Q
8011170305	8011170259	80/10/10	70-882
8011170309	8011170259	80/10/10	70-882
8011170314	8011170259	80/10/10	70-882
8011170322	8011170259	80/10/10	70-882
8011170343	8011170340	80/10/27	50-367 A
8011170345	8011170340	80/10/27	50-367 A
8011170364	8011170360	80/11/03	CONTRACT
8011170374	8011170369	80/11/03	0A999
8011170378	8011170369	80/11/03	0A999
8011170382	8011170369	80/11/03	0A999
8011170384	8011170373	80/10/24	50-313 Q
8011170388	8011170369	80/11/03	0A999
8011170394	8011170373	80/10/24	50-313 Q
8011170399	8011170391	80/10/03	50-335 Q
8011170413	8011170410	80/10/23	50-320 P
8011170414	8011170407	80/11/12	50-338 S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8011170415	8011170404	80/03/04	40-1162	8011170727	8011170720	80/10/09	50-482 Q
8011170418	8011170410	80/10/23	50-320 P	8011170738	8011170734	80/10/03	50-456 Q
8011170419	8011170410	80/10/23	50-320 P	8011170742	8011170734	80/10/03	50-456 Q
8011170421	8011170410	80/10/23	50-320 P	8011170766	8011170763	80/07/18	GA999
8011170422	8011170410	80/10/23	50-320 P	8011170771	8011170763	80/07/18	GA999
8011170424	8011170404	80/03/04	40-1162	8011170777	8011170772	80/08/13	CONTRACT
8011170428	8011170410	80/10/23	50-320 P	8011170781	8011170772	80/08/13	CONTRACT
8011170429	8011170420	80/11/10	50-293 S	8011170793	8011170787	80/10/07	CONTRACT
8011170433	8011170410	80/10/23	50-320 P	8011170799	8011170587	80/10/20	COMMISSION
8011170434	8011170410	80/10/23	50-320 P	8011170803	8011170587	80/10/20	COMMISSION
8011170436	8011170410	80/10/23	50-320 P	8011170804	8011170587	80/10/20	COMMISSION
8011170437	8011170426	80/10/23	COMMISSION	8011170806	8011170587	80/10/20	COMMISSION
8011170442	8011170410	80/10/23	50-320 P	8011170808	8011170800	80/10/31	50-247 P
8011170444	8011170432	80/11/13	50-261 S	8011170809	8011170587	80/10/20	COMMISSION
8011170445	8011170410	80/10/23	50-320 P	8011170811	8011170587	80/10/20	COMMISSION
8011170451	8011170446	80/11/10	50-272 R	8011170813	8011170587	80/10/20	COMMISSION
8011170458	8011170450	80/11/10	50-338 S	8011170815	8011170587	80/10/20	COMMISSION
8011170460	8011170456	80/10/27	50-293 S	8011170818	8011170587	80/10/20	COMMISSION
8011170461	8011170457	80/11/10	50-338 S	8011170819	8011170587	80/10/20	COMMISSION
8011170476	8011170466	80/11/07	50-368 S	8011170822	8011170587	80/10/20	COMMISSION
8011170478	8011170469	80/11/10	50-339 S	8011170824	8011170587	80/10/20	COMMISSION
8011170487	8011170480	80/11/11	50-368 S	8011170826	8011170821	80/10/27	50-277 P
8011170489	8011170484	80/11/10	50-313 S	8011170827	8011170587	80/10/20	COMMISSION
8011170492	8011170490	80/11/10	50-266 R	8011170830	8011170587	80/10/20	COMMISSION
8011170500	8011170496	80/11/10	50-271 S	8011170832	8011170587	80/10/20	COMMISSION
8011170503	8011170502	80/11/10	50-407 R	8011170834	8011170587	80/10/20	COMMISSION
8011170505	8011170472	80/11/07	50-369 Q	8011170836	8011170587	80/10/20	COMMISSION
8011170510	8011170508	80/11/11	50-282 R	8011170838	8011170587	80/10/20	COMMISSION
8011170524	8011170514	80/10/31	50-275 H	8011170840	8011170833	80/10/28	GA999
8011170530	8011170528	80/10/24	State Prog	8011170841	8011170587	80/10/20	COMMISSION
8011170534	8011170528	80/10/24	State Prog	8011170845	8011170833	80/10/28	GA999
8011170541	8011170537	80/10/06	50-440 Q	8011170847	8011170587	80/10/20	COMMISSION
8011170544	8011170537	80/10/06	50-440 Q	8011170848	8011170842	80/10/28	GA999
8011170549	8011170548	80/11/10	PROJ	8011170850	8011170833	80/10/28	GA999
8011170552	8011170548	80/11/10	PROJ	8011170852	8011170833	80/10/28	GA999
8011170553	8011170551	80/11/10	50-346 P	8011170856	8011170833	80/08/03	GA999
8011170556	8011170548	80/11/10	PROJ	8011170858	8011170833	80/10/28	GA999
8011170561	8011170548	80/11/10	PROJ	8011170861	8011170833	80/08/03	GA999
8011170563	8011170562	80/10/29	50-413 Q	8011170866	8011170862	80/10/28	GA999
8011170568	8011170562	80/10/29	50-413 Q	8011170872	8011170862	80/10/28	GA999
8011170571	8011170566	80/10/10	50-322 Q	8011170875	8011170862	80/10/28	GA999
8011170578	8011170574	80/09/30	50-275 Q	8011170879	8011170862	80/10/28	GA999
8011170584	8011170582	80/10/31	71-121	8011170888	8011170883	80/10/31	71-5939
8011170588	8011170587	80/10/20	COMMISSION	8011170898	8011170895	80/10/24	40-8743
8011170590	8011170566	80/10/10	50-322 Q	8011170906	8011170902	80/11/10	50-461 Q
8011170591	8011170587	80/10/20	COMMISSION	8011170918	8011170907	80/11/06	70-143
8011170592	8011170587	80/10/20	COMMISSION	8011170928	8011170907	80/11/06	70-143
8011170594	8011170587	80/10/20	COMMISSION	8011170935	8011170907	80/11/06	70-143
8011170595	8011170566	80/10/10	50-322 Q	8011170937	8011170932	80/10/21	50-219 Q
8011170596	8011170587	80/10/20	COMMISSION	8011170939	8011170932	80/10/21	50-219 Q
8011170598	8011170587	80/10/20	COMMISSION	8011170941	8011170932	80/10/21	50-219 Q
8011170600	8011170587	80/10/20	COMMISSION	8011170943	8011170907	80/11/06	FOIA
8011170601	8011170597	80/10/17	50-344 Q	8011170945	8011170942	80/10/09	50-456 Q
8011170602	8011170587	80/10/20	COMMISSION	8011170946	8011170932	80/10/21	50-219 Q
8011170603	8011170566	80/10/10	50-322 Q	8011170947	8011170942	80/10/09	50-456 Q
8011170604	8011170587	80/10/20	COMMISSION	8011170948	8011170907	80/11/06	FOIA
8011170606	8011170587	80/10/20	COMMISSION	8011180013	8011180010	80/11/03	71-9091
8011170607	8011170587	80/10/20	COMMISSION	8011180020	8011180016	80/11/06	50-320 H
8011170608	8011170587	80/10/20	COMMISSION	8011180024	8011180017	80/10/24	50-367 Q
8011170614	8011170587	80/10/20	COMMISSION	8011180030	8011180017	80/10/24	50-367 Q
8011170616	8011170587	80/10/20	COMMISSION	8011180066	8011180062	80/11/03	CONTRACT
8011170620	8011170587	80/10/20	COMMISSION	8011180081	8011180077	80/10/31	50-320 H
8011170621	8011170587	80/10/20	COMMISSION	8011180083	8011180076	80/11/14	50-237 T
8011170623	8011170587	80/10/20	COMMISSION	8011180092	8011180087	80/11/03	50-289 H
8011170627	8011170587	80/10/20	COMMISSION	8011180104	8011180099	80/10/02	50-409 Q
8011170630	8011170587	80/10/20	COMMISSION	8011180114	8011180099	80/10/02	50-409 Q
8011170632	8011170587	80/10/20	COMMISSION	8011180119	8011180112	80/10/30	50-289 H
8011170634	8011170622	80/09/17	50-332 Q	8011180126	8011180122	80/11/17	50-395 K
8011170636	8011170587	80/10/20	COMMISSION	8011180135	8011180131	80/11/14	50-329 A
8011170639	8011170587	80/10/20	COMMISSION	8011180163	8011180128	80/10/31	50-247 H
8011170642	8011170587	80/10/20	COMMISSION	8011180165	8011180139	80/11/12	FOIA
8011170646	8011170587	80/10/20	COMMISSION	8011180171	8011180139	80/11/12	FOIA
8011170648	8011170587	80/10/20	COMMISSION	8011180173	8011180168	80/11/04	70-267
8011170652	8011170587	80/10/20	COMMISSION	8011180176	8011180170	80/10/31	50-247 H
8011170654	8011170587	80/10/20	COMMISSION	8011180180	8011180177	80/11/03	50-320 H
8011170657	8011170587	80/10/20	COMMISSION	8011180182	8011180168	80/11/04	70-267
8011170658	8011170587	80/10/20	COMMISSION	8011180185	8011180168	80/11/04	70-267
8011170662	8011170587	80/10/20	COMMISSION	8011180192	8011180168	80/11/04	70-267
8011170664	8011170587	80/10/20	COMMISSION	8011180203	8011180196	80/10/28	CONTRACT
8011170701	8011170695	80/10/28	PR	8011180210	8011180199	80/11/13	FOIA

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

369

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8011180229	8011180224	80/11/10	50-289 T	8011180645	8011180636	80/11/11	50-219 S
8011180243	8011180513	80/11/06	50-313 P	8011180647	8011180643	80/11/12	50-285 R
8011180262	8011180238	80/11/11	TOPREP	8011180648	8011180640	80/11/10	50-327 S
8011180274	8011180269	80/10/29	COMMISSION	8011180650	8011180638	80/11/07	50-293 S
8011180277	8011180269	80/10/29	COMMISSION	8011180657	8011180641	80/11/12	50-316 R
8011180279	8011180267	80/11/14	50-356 Q	8011180660	8011180631	80/11/14	50-286 R
8011180282	8011180269	80/10/29	COMMISSION	8011180662	8011180654	80/11/14	50-318 S
8011180285	8011180269	80/10/29	COMMISSION	8011180663	8011180653	80/11/14	50-271 S
8011180289	8011180269	80/10/29	COMMISSION	8011180664	8011180656	80/11/14	50-247 S
8011180293	8011180269	80/10/29	COMMISSION	8011180667	8011180659	80/11/14	50-267 S
8011180301	8011180269	80/10/29	COMMISSION	8011180673	8011180665	80/11/12	50-277 R
8011180319	8011180303	80/10/13	State Prog	8011180676	8011180669	80/11/11	50-313 S
8011180320	8011180313	80/11/03	QA999	8011180677	8011180671	80/11/10	50-344 S
8011180327	8011180313	80/11/03	QA999	8011180678	8011180670	80/11/12	50-305 S
8011180332	8011180313	80/11/03	QA999	8011180679	8011180672	80/11/14	50-247 S
8011180333	8011180303	80/10/13	DRG	8011180689	8011180680	80/11/12	50-306 S
8011180338	8011180335	80/11/07	50-295 P	8011180690	8011180683	80/11/14	50-3 R
8011180340	8011180313	80/11/03	QA999	8011180691	8011180682	80/11/12	50-327 S
8011180342	8011180335	80/11/07	50-295 P	8011180693	8011180687	80/11/05	50-339 S
8011180343	8011180335	80/11/07	50-295 P	8011180697	8011180685	80/11/14	50-255 S
8011180346	8011180335	80/11/07	50-295 P	8011180701	8011180694	80/11/13	50-259 S
8011180361	8011180356	80/11/10	50-261 P	8011180703	8011180696	80/11/13	50-231 S
8011180365	8011180356	80/11/10	50-261 P	8011180706	8011180698	80/11/07	50-266 S
8011180371	8011180362	80/11/12	50-271 P	8011180708	8011180702	80/11/13	50-331 S
8011180384	8011180377	80/11/13	50-324 P	8011180710	8011180700	80/11/05	50-339 S
8011180386	8011180379	80/09/29	50-483 Q	8011180712	8011180704	80/11/12	50-270 S
8011180391	8011180379	80/09/29	50-483 Q	8011180719	8011180707	80/11/10	50-327 S
8011180394	8011180381	80/11/12	50-344 P	8011180721	8011180713	80/11/10	50-324 S
8011180396	8011180392	80/11/12	50-269 P	8011180722	8011180711	80/11/13	50-287 S
8011180402	8011180381	80/11/12	50-344 P	8011180723	8011180716	80/11/07	50-295 S
8011180409	8011180400	80/10/09	50-373 Q	8011180724	8011180715	80/11/14	50-255 S
8011180415	8011180407	80/11/05	71-400	8011180725	8011180718	80/11/12	50-324 S
8011180420	8011180417	80/11/14	50-368 R	8011180735	8011180730	80/11/14	50-255 S
8011180429	8011180423	80/11/05	71-395	8011180748	8011180743	80/11/14	50-255 S
8011180434	8011180427	80/11/10	50-293 R	8011180752	8011180747	80/11/05	50-320 H
8011180442	8011180433	80/11/07	50-286 P	8011180770	8011180762	80/11/04	71-24
8011180443	8011180439	80/10/09	50-272 Q	8011180772	8011180768	80/10/07	71-18
8011180449	8011180433	80/11/07	50-286 Q	8011180784	8011180781	80/11/06	XPORTRLIC
8011180450	8011180439	80/10/09	50-272 Q	8011180797	8011180793	80/10/08	50-341 Q
8011180452	8011180435	80/11/17	50-285 P	8011180803	8011180800	80/10/21	50-272 Q
8011180453	8011180447	80/11/12	50-10 R	8011180808	8011180800	80/10/21	50-272 Q
8011180460	8011180455	80/09/19	50-29 Q	8011180811	8011180800	80/10/21	50-272 Q
8011180461	8011180435	80/11/17	50-285 P	8011180814	8011180800	80/10/21	50-272 Q
8011180462	8011180457	80/11/14	50-247 R	8011180829	8011180826	80/10/24	COMMISSION
8011180467	8011180465	80/11/10	50-213 R	8011180841	8011180825	80/10/06	CONTRACT
8011180472	8011180466	80/09/16	50-354 Q	8011180846	8011180845	80/11/06	71-6273
8011180476	8011180473	80/11/13	50-334 R	8011180851	8011180849	80/10/08	50-255 Q
8011180477	8011180469	80/11/13	50-327 P	8011180853	8011180849	80/10/08	50-255 Q
8011180500	8011180496	80/11/10	50-348 S	8011180860	8011180856	80/10/06	50-373 Q
8011180509	8011180507	80/11/10	50-368 S	8011180866	8011180864	80/10/10	XPORTRLIC
8011180524	8011180522	80/10/28	50-320 H	8011190033	8011190028	80/11/14	50-409 Q
8011180528	8011180526	80/11/03	50-320 H	8011190035	8011190025	80/10/14	40-8027
8011180530	8011180527	80/11/13	50-327 V	8011190036	8011190028	80/11/14	50-409 Q
8011180540	8011180537	80/11/11	40-8602	8011190041	8011190028	80/11/14	50-409 Q
8011180543	8011180537	80/11/11	40-8602	8011190045	8011190038	80/09/15	FR
8011180564	8011180554	80/11/05	50-339 S	8011190050	8011190046	80/11/18	50-461 Q
8011180571	8011180568	80/11/12	50-327 R	8011190055	8011190046	80/11/18	50-461 Q
8011180579	8011180576	80/11/05	50-133 R	8011190118	8011190106	80/11/13	50-443 Q
8011180584	8011180578	80/11/11	50-271 R	8011190122	8011190117	80/11/12	50-390 R
8011180587	8011180583	80/11/10	50-311 R	8011190143	8011190138	80/11/05	50-320 H
8011180589	8011180581	80/11/13	50-302 S	8011190145	8011190135	80/11/15	27-39
8011180592	8011180582	80/11/13	50-269 R	8011190151	8011190146	80/11/03	50-321 P
8011180593	8011180585	80/11/13	50-269 S	8011190152	8011190144	80/11/14	50-409 Q
8011180594	8011180588	80/11/10	50-259 R	8011190159	8011190135	80/11/15	27-39
8011180596	8011180590	80/11/10	50-244 R	8011190162	8011190157	80/11/05	50-289 H
8011180604	8011180599	80/11/08	50-230 R	8011190163	8011190156	80/11/14	50-348 Q
8011180607	8011180600	80/11/12	50-237 S	8011190172	8011190165	80/11/05	50-320 H
8011180609	8011180601	80/11/13	50-281 S	8011190193	8011190189	80/11/05	50-320 H
8011180610	8011180602	80/11/05	50-346 S	8011190203	8011190195	80/10/17	50-277 Q
8011180613	8011180595	80/11/03	50-265 S	8011190222	8011190218	80/11/07	50-295 P
8011180614	8011180608	80/11/10	50-302 R	8011190234	8011190214	80/10/31	50-289 P
8011180618	8011180601	80/11/13	50-281 S	8011190239	8011190214	80/10/31	50-289 P
8011180619	8011180611	80/11/13	50-331 S	8011190240	8011190195	80/10/17	50-277 Q
8011180625	8011180615	80/11/12	50-315 R	8011190243	8011190214	80/10/31	50-289 P
8011180627	8011180621	80/11/05	50-272 R	8011190244	8011190195	80/10/17	50-277 Q
8011180628	8011180617	80/11/06	50-245 S	8011190254	8011190195	80/10/17	50-277 Q
8011180631	8011180623	80/11/13	50-331 S	8011190255	8011190250	80/10/16	50-146 Q
8011180633	8011180624	80/11/12	50-327 S	8011190263	8011190250	80/10/16	50-146 Q
8011180635	8011180629	80/11/12	50-245 R	8011190273	8011190270	80/11/15	50-289 R
8011180644	8011180634	80/11/12	50-327 S	8011190285	8011190279	80/11/10	50-289 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8011190287	8011190282	80/11/14	50-280	P	8011200107	8011200042	80/10/30	50-249	Q
8011190289	8011190283	80/10/09	50-282	Q	8011200114	8011200110	80/10/10	50-245	Q
8011190292	8011190279	80/11/10	50-289	Q	8011200116	8011200110	80/10/10	50-245	Q
8011190293	8011190290	80/11/10	50-321	R	8011200117	8011200105	80/10/29	50-460	Q
8011190307	8011190286	80/10/10	50-352	Q	8011200122	8011200110	80/10/10	50-245	Q
8011190308	8011190303	80/11/17	50-498	K	8011200126	8011200110	80/10/10	50-245	Q
8011190319	8011190286	80/10/10	50-352	Q	8011200129	8011200105	80/10/29	50-460	Q
8011190323	8011190317	80/11/13	50-333	P	8011200130	8011200110	80/10/10	50-245	Q
8011190324	8011190286	80/10/10	50-352	Q	8011200131	8011200120	80/10/08	50-219	Q
8011190329	8011190286	80/10/10	50-352	Q	8011200134	8011200110	80/10/10	50-245	Q
8011190342	8011190334	80/11/06	50-320	P	8011200135	8011200105	80/10/29	50-460	Q
8011190348	8011190334	80/11/06	50-320	P	8011200151	8011200141	80/10/16	50-213	Q
8011190353	8011190334	80/11/06	50-320	P	8011200153	8011200150	80/10/08	50-341	Q
8011190369	8011190351	80/11/06	50-320	H	8011200159	8011200156	80/10/24	50-328	A
8011190378	8011190371	80/11/18	50-443	A	8011200160	8011200150	80/10/08	50-341	Q
8011190383	8011190371	80/11/18	50-443	A	8011200165	8011200156	80/10/24	50-328	A
8011190396	8011190371	80/11/18	50-443	A	8011200174	8011200188	80/11/10	CONTRACT	
8011190400	8011190392	80/11/11	50-321	S	8011200206	8011200200	80/10/07	50-461	Q
8011190411	8011190407	80/11/13	50-293	S	8011200207	8011200199	80/11/18	50-361	A
8011190412	8011190403	80/11/11	50-321	S	8011200214	8011200200	80/10/07	50-461	Q
8011190421	8011190416	80/11/17	50-318	S	8011200224	8011200220	80/11/10	50-339	P
8011190422	8011190417	80/11/11	50-321	S	8011200249	8011200242	80/11/12	50-287	A
8011190439	8011190437	80/11/15	50-286	S	8011200254	8011200248	80/11/17	50-461	K
8011190444	8011190442	80/11/14	50-293	S	8011200258	8011200255	80/10/24	50-335	P
8011190446	8011190445	80/11/03	50-329	Q	8011200261	8011200257	80/09/29	50-846	A
8011190451	8011190449	80/10/09	50-460	Q	8011200264	8011200257	80/09/29	50-846	A
8011190453	8011190449	80/10/09	50-460	Q	8011200274	8011200268	80/11/17	50-244	P
8011190455	8011190449	80/10/09	50-460	Q	8011200277	8011200268	80/11/17	50-244	P
8011190472	8011190447	80/11/03	50-440	Q	8011200279	8011200275	80/11/12	50-395	A
8011190483	8011190479	80/11/03	50-461	Q	8011200288	8011200281	80/11/13	50-346	B
8011190496	8011190490	80/10/14	50-150	Q	8011200290	8011200287	80/10/08	50-329	Q
8011190505	8011190501	80/10/28	40-2061		8011200294	8011200287	80/10/08	50-329	Q
8011190509	8011190504	80/10/16	NUREG		8011200296	8011200291	80/11/14	50-272	B
8011190518	8011190515	80/10/08	50-10	Q	8011200300	8011200298	80/11/17	50-338	R
8011190526	8011190515	80/10/08	50-10	Q	8011200309	8011200302	80/11/14	50-331	R
8011190528	8011190522	80/10/28	40-2061		8011200341	8011200340	80/11/13	50-443	Q
8011190602	8011190595	80/10/21	50-245	Q	8011200343	8011200342	80/10/24	70-1092	
8011190613	8011190607	80/10/31	70-371		8011200355	8011200354	80/11/05	50-327	P
8011190619	8011190609	80/10/16	50-29	Q	8011200366	8011200362	80/11/05	XPORTLIC	
8011190624	8011190609	80/10/16	50-29	Q	8011200369	8011200361	78/01/25	SECY	
8011190632	8011190609	80/10/16	50-29	Q	8011200372	8011200361	78/01/25	SECY	
8011190647	8011190639	80/11/04	50-409	Q	8011200373	8011200370	80/11/06	XPORTLIC	
8011190648	8011190643	80/10/20	50-275	H	8011200379	8011200376	80/11/03	50-280	Q
8011190664	8011190659	80/10/16	50-289	H	8011200382	8011200376	80/11/03	50-280	Q
8011190684	8011190678	80/10/16	50-320	H	8011200386	8011200376	80/11/03	50-280	Q
8011190690	8011190678	80/10/16	50-320	H	8011200388	8011200383	78/05/30	SECY	
8011190742	8011190733	80/10/30	50-358	S	8011200390	8011200376	80/11/03	50-280	Q
8011190751	8011190746	80/11/18	50-443	Q	8011200391	8011200383	78/05/30	SECY	
8011190755	8011190707	80/10/31	70-2913		8011200395	8011200383	78/05/30	SECY	
8011190772	8011190768	80/11/07	71-6386		8011200401	8011200400	80/11/06	50-388	H
8011200004	8011200002	80/10/03	50-331	Q	8011200402	8011200383	78/05/30	SECY	
8011200007	8011200002	80/10/03	50-331	Q	8011200411	8011200405	80/11/03	50-438	Q
8011200012	8011200009	80/11/03	50-10	Q	8011200417	8011200405	80/11/03	50-438	Q
8011200022	8011200017	80/11/03	50-409	Q	8011200422	8011200405	80/11/03	50-438	Q
8011200028	8011200023	80/10/28	50-344	P	8011200425	8011200405	80/11/03	50-438	Q
8011200033	8011200023	80/10/28	50-344	P	8011200427	8011200405	80/11/03	50-438	Q
8011200034	8011200029	80/09/15	50-482	Q	8011200430	8011200405	80/11/03	50-438	Q
8011200040	8011200036	80/09/17	50-373	Q	8011200442	8011200436	80/11/03	50-348	Q
8011200043	8011200039	80/11/07	50-339	Q	8011200446	8011200438	80/11/05	50-416	Q
8011200046	8011200043	80/10/15	50-334	Q	8011200449	8011200436	80/11/03	50-348	Q
8011200048	8011200039	80/11/07	50-339	Q	8011200451	8011200438	80/11/05	50-416	Q
8011200049	8011200043	80/10/15	50-334	Q	8011200452	8011200445	80/10/10	10CFR	
8011200053	8011200043	80/10/15	50-334	Q	8011200455	8011200436	80/11/03	50-348	Q
8011200056	8011200043	80/10/15	50-334	Q	8011200456	8011200438	80/11/05	50-416	Q
8011200057	8011200055	80/11/05	50-368	F	8011200460	8011200438	80/11/05	50-416	Q
8011200066	8011200062	80/10/30	50-249	Q	8011200461	8011200457	80/10/06	10CFR	
8011200067	8011200065	80/11/05	50-289	F	8011200463	8011200436	80/11/03	50-348	Q
8011200071	8011200062	80/10/30	50-249	Q	8011200469	8011200464	80/10/31	50-302	Q
8011200076	8011200074	80/10/16	50-434	Q	8011200470	8011200465	80/10/08	REQD	
8011200078	8011200062	80/10/30	50-249	Q	8011200481	8011200477	80/11/12	70-1113	
8011200081	8011200062	80/10/30	50-249	Q	8011200485	8011200477	80/11/12	70-1113	
8011200084	8011200084	80/08/07	10CFR		8011200489	8011200477	80/11/12	70-1113	
8011200085	8011200074	80/10/16	50-434	Q	8011200497	8011200494	80/04/02	50-335	Q
8011200087	8011200062	80/10/30	50-249	Q	8011200515	8011200510	80/11/06	70-143	
8011200094	8011200062	80/10/30	50-249	Q	8011200519	8011200510	80/11/06	70-143	
8011200099	8011200091	80/11/04	50-344	P	8011200534	8011200529	80/10/14	70-27	
8011200096	8011200063	80/10/09	50-498	Q	8011200542	8011200518	80/10/22	50-289	Q
8011200099	8011200062	80/10/30	50-249	Q	8011200544	8011200539	80/11/06	50-10	Q
8011200102	8011200098	80/10/08	50-458	Q	8011200550	8011200548	80/10/15	50-546	Q
8011200104	8011200100	80/09/25	50-336	Q	8011200553	8011200548	80/10/15	50-546	Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

371

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
80112100554	80112100548	80/10/15	50-546 Q
8011210013	8011210006	80/11/10	CONTRACT
8011210037	8011210027	80/11/04	CONTRACT
8011210073	8011210066	80/11/05	MISC
8011210078	8011210068	80/11/07	50-327 Q
8011210083	8011210068	80/11/07	50-327 Q
8011210087	8011210068	80/11/07	50-327 Q
8011210093	8011210068	80/11/07	50-327 Q
8011210104	8011210072	80/11/10	CONTRACT
8011210111	8011210101	80/10/21	XPORTLIC
8011210128	8011210121	80/10/14	PR
8011210129	8011210125	80/11/04	50-369 Q
8011210131	8011210126	80/11/05	50-73 P
8011210134	8011210124	80/11/03	50-390 Q
8011210137	8011210125	80/11/04	50-369 Q
8011210141	8011210121	80/10/14	PR
8011210144	8011210124	80/11/03	50-390 Q
8011210145	8011210139	80/10/08	50-424 Q
8011210149	8011210142	80/10/16	50-266 Q
8011210150	8011210147	80/11/10	XPORTLIC
8011210157	8011210148	80/11/14	50-361 K
8011210158	8011210153	80/10/29	50-370 Q
8011210161	8011210124	80/11/03	50-390 Q
8011210166	8011210153	80/10/29	50-370 Q
8011210169	8011210124	80/11/03	50-390 Q
8011210173	8011210124	80/11/03	50-390 Q
8011210174	8011210164	80/10/17	50-305 Q
8011210186	8011210124	80/11/03	50-390 Q
8011210190	8011210183	80/10/15	50-263 Q
8011210191	8011210185	80/11/10	10CFR
8011210206	8011210202	80/11/18	50-325 F
8011210208	8011210185	80/11/10	10CFR
8011210209	8011210195	80/11/03	50-390 Q
8011210219	8011210195	80/11/03	50-390 Q
8011210226	8011210195	80/11/03	50-390 Q
8011210232	8011210229	80/10/29	27-47
8011210235	8011210229	80/10/29	27-47
8011210238	8011210195	80/11/03	50-390 Q
8011210242	8011210234	80/10/31	COMMISBION
8011210245	8011210239	80/11/05	50-234 F
8011210275	8011210265	80/10/01	40-8702
8011210276	8011210271	80/11/18	50-327 P
8011210285	8011210279	80/11/19	50-395 Q
8011210297	8011210280	80/09/30	70-135
8011210336	8011210326	80/10/24	50-309 Q
8011210355	8011210343	80/11/05	50-289 Q
8011210356	8011210326	80/10/24	50-309 Q
8011210363	8011210326	80/10/24	50-309 Q
8011210368	8011210361	80/11/10	50-348 Q
8011210370	8011210364	80/11/18	50-364 P
8011210373	8011210326	80/10/24	50-309 Q
8011210374	8011210367	80/10/27	50-387 Q
8011210378	8011210343	80/11/05	50-289 Q
8011210379	8011210367	80/10/27	50-387 Q
8011210381	8011210377	80/11/14	50-348 R
8011210386	8011210367	80/10/27	50-387 Q
8011210390	8011210387	80/11/14	50-364 R
8011210395	8011210367	80/10/27	50-387 Q
8011210400	8011210396	80/11/13	50-336 R
8011210402	8011210393	80/10/02	50-289 Q
8011210415	8011210405	80/10/15	50-327 Q
8011210424	8011210419	80/10/21	50-305 Q
8011210431	8011210429	80/10/06	50-261 Q
8011210447	8011210444	80/11/12	50-440 Q
8011210450	8011210449	80/11/14	50-263 S
8011210452	8011210451	80/11/17	50-324 S
8011210454	8011210453	80/11/14	50-369 S
8011210456	8011210455	80/11/14	50-336 S
8011210458	8011210457	80/11/14	50-260 S
8011210460	8011210459	80/11/12	50-324 Q
8011210462	8011210459	80/11/12	50-324 Q
8011210464	8011210459	80/11/12	50-324 Q
8011210466	8011210465	80/11/14	50-395 A
8011210467	8011210465	80/11/14	50-395 A
8011210468	8011210465	80/11/14	50-395 A
8011210469	8011210465	80/11/14	50-395 A
8011210472	8011210470	80/11/12	50-325 S
8011210474	8011210471	80/10/27	50-254 Q
8011210475	8011210473	80/11/17	50-270 S
8011210478	8011210477	80/10/31	50-267 S

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8011210485	8011210480	80/11/10	50-259 S
8011210486	8011210483	80/11/19	50-358 I
8011210491	8011210488	80/11/07	50-298 S
8011210493	8011210489	80/11/14	50-336 S
8011210497	8011210492	80/11/14	50-327 S
8011210499	8011210495	80/10/31	50-298 S
8011210500	8011210498	80/11/17	50-369 A
8011210506	8011210504	80/11/17	50-348 S
8011210512	8011210504	80/11/17	50-348 S
8011210515	8011210507	80/11/06	50-245 S
8011210521	8011210516	80/11/14	50-293 S
8011210522	8011210510	80/11/17	50-280 S
8011210524	8011210519	80/11/17	50-312 F
8011210534	8011210526	80/11/17	50-317 S
8011210535	8011210510	80/11/17	50-260 S
8011210548	8011210537	80/11/12	50-259 S
8011210550	8011210510	80/11/17	50-280 S
8011210551	8011210543	80/11/13	50-249 S
8011210552	8011210541	80/10/31	50-267 S
8011210565	8011210562	80/11/14	50-344 P
8011210570	8011210564	80/11/03	50-298 S
8011210571	8011210566	80/11/20	50-367 A
8011210574	8011210565	80/11/14	50-327 S
8011210581	8011210575	80/10/31	50-267 S
8011210588	8011210585	80/11/07	50-348 P
8011210590	8011210584	80/11/17	50-368 S
8011210596	8011210586	80/11/12	50-296 S
8011210605	8011210595	80/11/13	50-368 S
8011210606	8011210598	80/11/14	50-296 S
8011210608	8011210601	80/11/12	50-259 S
8011210618	8011210613	80/11/03	40-2053
8011210624	8011210621	80/10/21	50-445 Q
8011210626	8011210609	80/11/17	50-313 S
8011210627	8011210623	80/10/30	50-293 Q
8011210630	8011210623	80/10/30	50-293 Q
8011210631	8011210621	80/10/21	50-445 Q
8011210632	8011210628	80/11/14	50-262 S
8011210637	8011210623	80/10/30	50-293 Q
8011210641	8011210623	80/10/30	50-293 Q
8011210663	8011210647	80/11/10	50-395 Q
8011210668	8011210647	80/11/10	50-395 Q
8011210673	8011210647	80/11/10	50-395 Q
8011210675	8011210652	80/11/10	50-397 A
8011210680	8011210647	80/11/10	50-395 Q
8011210694	8011210687	80/10/03	10CFR
8011210699	8011210689	80/10/22	40-8702
8011210715	8011210708	80/10/02	50-286 Q
8011210717	8011210711	80/10/24	50-213 Q
8011210718	8011210714	80/10/08	50-267 Q
8011210724	8011210711	80/10/24	50-213 Q
8011210725	8011210714	80/10/08	50-267 Q
8011210726	8011210721	80/11/12	50-275 H
8011210729	8011210711	80/10/24	50-213 Q
8011210732	8011210730	80/11/12	50-305 Q
8011210735	8011210731	80/11/12	50-275 H
8011210736	8011210711	80/10/24	50-213 Q
8011210738	8011210730	80/11/12	50-305 Q
8011210739	8011210722	80/11/03	50-271 P
8011210749	8011210722	80/11/03	50-271 P
8011210754	8011210741	80/11/13	50-546 A
8011210756	8011210722	80/11/03	50-271 P
8011210759	8011210741	80/11/13	50-346 A
8011210760	8011210751	80/09/24	50-445 Q
8011210763	8011210753	80/11/12	50-498 Q
8011210769	8011210767	80/11/13	50-456 Q
8011240007	8011240003	80/10/24	50-244 Q
8011240011	8011240003	80/10/24	50-244 Q
8011240020	8011240014	80/10/24	50-219 Q
8011240025	8011240014	80/10/24	50-219 Q
8011240032	8011240028	80/10/24	50-206 Q
8011240034	8011240028	80/10/24	50-206 Q
8011240042	8011240037	80/10/24	50-237 Q
8011240045	8011240037	80/10/24	50-237 Q
8011240059	8011240051	80/10/24	50-29 Q
8011240063	8011240051	80/10/24	50-29 Q
8011240076	8011240070	80/10/24	50-409 Q
8011240079	8011240074	80/10/16	50-295 Q
8011240081	8011240070	80/10/24	50-409 Q
8011240084	8011240074	80/10/16	50-295 Q
8011240094	8011240090	80/10/15	50-254 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8011240098	8011240090	80/10/15	50-254 Q	8011250311	8011250307	80/11/18	50-317 P
8011240108	8011240103	80/10/15	50-346 Q	8011250315	8011250307	80/11/18	50-317 P
8011240113	8011240103	80/10/15	50-346 Q	8011250317	8011250307	80/11/18	50-317 P
8011240158	8011240151	80/11/07	50-289 P	8011250320	8011250313	80/11/20	50-336 B
8011240174	8011240169	80/11/17	50-312 P	8011250327	8011250323	80/11/21	50-454 Q
8011240192	8011240188	80/11/07	TOPREP	8011250331	8011250326	80/11/20	50-445 A
8011240280	8011240278	80/11/18	50-373 K	8011250333	8011250323	80/11/21	50-454 Q
8011240289	8011240288	80/11/18	50-287 B	8011250334	8011250325	80/11/18	50-249 B
8011240296	8011240291	80/11/17	50-320 B	8011250337	8011250330	80/11/14	50-295 B
8011240301	8011240298	80/11/14	50-334 B	8011250341	8011250328	80/11/20	50-348 B
8011240310	8011240305	80/11/18	50-348 B	8011250343	8011250338	80/11/20	50-295 B
8011240317	8011240315	80/11/17	50-320 P	8011250344	8011250340	80/09/22	50-155 P
8011240318	8011240314	80/11/17	50-312 B	8011250347	8011250328	80/11/20	50-348 B
8011240320	8011240305	80/11/18	50-382 K	8011250350	8011250345	80/11/21	50-259 B
8011240324	8011240319	80/11/13	50-317 R	8011250352	8011250348	80/11/13	50-254 B
8011240326	8011240306	80/11/18	50-382 K	8011250356	8011250353	80/11/21	50-333 B
8011240328	8011240323	80/11/19	50-339 B	8011250363	8011250360	80/11/19	50-318 B
8011240337	8011240332	80/11/14	50-327 B	8011250364	8011250361	80/11/18	50-338 B
8011240345	8011240343	80/11/19	50-339 B	8011250368	8011250322	80/11/18	50-249 B
8011240352	8011240349	80/11/19	50-339 B	8011250371	8011250367	80/11/17	50-265 B
8011240362	8011240356	80/11/17	50-312 B	8011250372	8011250366	80/11/20	50-280 B
8011240364	8011240147	80/11/24	50-348 F	8011250375	8011250318	80/11/14	50-304 B
8011240370	8011240361	80/11/06	50-245 P	8011250379	8011250374	80/11/19	50-324 B
8011240372	8011240368	80/11/17	50-312 B	8011250380	8011250316	80/11/19	50-313 B
8011240375	8011240147	80/11/24	50-348 F	8011250384	8011250376	80/11/20	50-260 B
8011240380	8011240378	80/11/20	50-373 K	8011250385	8011250377	80/11/20	50-245 B
8011240381	8011240374	80/11/13	50-254 P	8011250386	8011250382	80/11/19	50-324 B
8011240383	8011240379	80/11/19	50-339 B	8011250389	8011250314	80/11/19	50-155 B
8011240384	8011240147	80/11/24	50-348 F	8011250390	8011250387	80/11/21	50-327 B
8011240386	8011240374	80/11/13	50-254 P	8011250391	8011250388	80/11/19	50-245 B
8011240391	8011240387	80/11/18	50-338 B	8011250403	8011250395	80/11/17	50-327 B
8011240393	8011240374	80/11/13	50-254 P	8011250404	8011250396	80/11/19	50-277 B
8011240394	8011240147	80/11/24	50-348 F	8011250408	8011250400	80/11/19	50-155 B
8011240402	8011240398	80/11/19	50-338 B	8011250417	8011250414	80/11/17	50-324 B
8011240412	8011240406	80/11/12	50-271 B	8011250419	8011250409	80/11/17	50-296 B
8011240416	8011240411	80/11/04	XPORTLTC	8011250426	8011250422	80/11/17	50-324 B
8011240477	8011240147	80/11/24	50-348 F	8011250442	8011250436	80/11/24	50-260 B
8011240478	8011240472	80/11/14	50-247 T	8011250444	8011250433	80/11/15	50-213 R
8011240482	8011240147	80/11/24	50-348 F	8011250446	8011250431	80/11/17	50-324 B
8011240485	8011240147	80/11/24	50-348 F	8011250455	8011250449	80/11/24	50-327 B
8011240486	8011240472	80/11/14	50-247 T	8011250464	8011250451	80/11/19	50-344 B
8011240488	8011240147	80/11/24	50-348 F	8011250470	8011250461	80/11/19	50-334 B
8011240495	8011240147	80/11/24	50-348 F	8011250471	8011250460	80/11/12	50-361 A
8011240497	8011240147	80/11/24	50-348 F	8011250474	8011250465	80/11/07	50-285 B
8011240507	8011240147	80/11/24	50-348 F	8011250477	8011250469	80/11/21	50-313 B
8011240508	8011240147	80/11/24	50-348 F	8011250482	8011250460	80/11/12	50-361 A
8011240515	8011240147	80/11/24	50-348 F	8011250485	8011250478	80/11/19	50-325 B
8011240519	8011240147	80/11/24	50-348 F	8011250490	8011250486	80/11/19	50-324 B
8011240524	8011240501	80/11/20	50-247 T	8011250494	8011250460	80/11/12	50-361 A
8011240526	8011240147	80/11/24	50-348 F	8011250497	8011250489	80/11/20	50-324 B
8011240528	8011240147	80/11/24	50-348 F	8011250503	8011250460	80/11/12	50-361 A
8011240532	8011240501	80/11/20	50-247 T	8011250506	8011250480	80/11/21	50-270 B
8011240542	8011240147	80/11/24	50-348 F	8011250508	8011250505	80/10/23	TOPREP
8011240548	8011240501	80/11/20	50-247 T	8011250510	8011250500	80/11/18	50-219 B
8011240555	8011240147	80/11/24	50-348 F	8011250520	8011250513	80/11/17	50-334 B
8011240562	8011240147	80/11/24	50-348 F	8011250522	8011250515	80/11/19	50-387 R
8011240567	8011240147	80/11/24	50-348 F	8011250531	8011250515	80/11/19	50-387 R
8011240575	8011240147	80/11/24	50-348 F	8011250534	8011250524	80/11/19	50-219 B
8011250027	8011250021	80/11/18	50-556 Q	8011250539	8011250529	80/11/12	50-237 B
8011250033	8011250031	80/11/19	50-471 Q	8011250547	8011250540	80/11/17	50-320 B
8011250053	8011250049	80/10/23	50-440 Q	8011250553	8011250545	80/11/12	50-265 B
8011250062	8011250057	80/10/21	50-546 Q	8011250557	8011250549	80/11/14	50-361 A
8011250072	8011250067	80/10/20	50-440 Q	8011250568	8011250558	80/11/17	50-249 B
8011250114	8011250110	80/08/29	70-882	8011250565	8011250642	80/11/07	50-321 F
8011250121	8011250110	80/08/29	70-882	8011250564	8011250559	80/11/17	71-3
8011250132	8011250126	80/10/10	50-482 Q	8011250675	8011250663	80/10/02	50-317 Q
8011250144	8011250136	80/10/06	50-373 Q	8011250680	8011250673	80/10/31	CONTRACT
8011250214	8011250210	80/11/18	50-219 R	8011250692	8011250688	80/10/01	50-309 Q
8011250238	8011250237	80/10/29	50-311 Q	8011250697	8011250696	80/11/20	50-272 P
8011250252	8011250246	80/10/09	TOPREP	8011250698	8011250696	80/11/20	50-272 P
8011250264	8011250262	80/11/19	50-320 R	8011250702	8011250699	80/11/10	CONTRACT
8011250270	8011250267	80/11/03	50-416 A	8011260003	8011260001	7/10/21	CONTRACT
8011250283	8011250281	80/10/10	50-461 Q	8011260009	8011260004	80/11/12	PR
8011250286	8011250281	80/10/10	50-461 Q	8011260023	8011260020	80/11/20	50-320 Q
8011250292	8011250246	80/10/09	TOPREP	8011260027	8011260020	80/11/20	50-320 Q
8011250294	8011250246	80/10/09	TOPREP	8011260031	8011260020	80/11/20	50-320 Q
8011250299	8011250308	80/11/10	50-277 P	8011260034	8011260020	80/11/20	50-320 Q
8011250300	8011250296	80/11/20	50-272 P	8011260035	8011260028	80/10/27	70-182
8011250302	8011250296	80/11/20	50-272 P	8011260037	8011260028	80/10/27	70-182
8011250306	8011250296	80/11/20	50-272 P	8011260040	8011260028	80/10/27	70-182

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

373

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8011260041	8011260038	80/11/14	50-483 A		8011260290	8011260213	80/11/24	50-295 F	
8011260051	8011260048	80/11/13	50-298 G		8011260296	8011260213	80/11/24	50-295 F	
8011260057	8011260063	80/11/20	50-219 F		8011260301	8011260213	80/11/24	50-295 F	
8011260058	8011260066	80/10/24	70-261		8011260321	8011260318	80/11/06	50-395 D	
8011260069	8011260064	80/10/01	50-320 G		8011260322	8011260316	80/11/14	50-389 A	
8011260076	8011260073	80/10/22	50-267 G		8011260325	8011260316	80/11/14	50-389 A	
8011260079	8011260073	80/10/22	50-267 G		8011260328	8011260316	80/11/14	50-389 A	
8011260081	8011260073	80/10/22	50-267 G		8011260339	8011260335	80/09/12	50-440 G	
8011260087	8011260083	80/11/21	50-329 A		8011260340	8011260334	80/11/14	71-9070	
8011260102	8011260101	80/11/06	50-293 G		8011260348	8011260335	80/09/12	50-440 G	
8011260106	8011260105	80/10/21	50-298 G		8011260352	8011260346	80/10/10	50-395 G	
8011260126	8011260123	80/10/02	40-672		8011260357	8011260354	80/09/12	50-440 G	
8011260129	8011260123	80/10/02	40-672		8011260362	8011260356	80/10/10	50-250 G	
8011260136	8011260131	80/11/13	CONTRACT		8011260364	8011260384	80/09/12	50-440 G	
8011260160	8011260158	80/10/24	XPCORTLIC		8011260375	8011260367	80/10/15	50-409 G	
8011260161	8011260148	80/11/24	50-327 P		8011260378	8011260372	80/09/23	50-546 G	
8011260168	8011260167	80/11/24	50-387 G		8011260387	8011260380	80/10/07	50-321 G	
8011260170	8011260167	80/11/24	50-387 G		8011260396	8011260392	80/10/09	50-416 G	
8011260172	8011260165	80/11/12	PR		8011260407	8011260399	80/10/09	70-443	
8011260174	8011260173	80/11/14	50-313 P		8011260414	8011260413	80/11/12	50-382 G	
8011260176	8011260173	80/11/14	50-313 P		8011260421	8011260418	80/10/09	50-566 G	
8011260178	8011260173	80/11/14	50-313 P		8011260424	8011260416	80/11/10	50-546 G	
8011260180	8011260179	80/11/20	50-339 G		8011260427	8011260422	80/10/09	50-424 G	
8011260182	8011260181	80/11/21	50-306 G		8011260428	8011260423	80/10/01	50-354 G	
8011260184	8011260183	80/11/20	50-318 G		8011260429	8011260416	80/11/10	50-546 G	
8011260186	8011260185	80/11/20	50-334 G		8011260433	8011260431	80/10/27	50-277 G	
8011260197	8011260195	80/10/17	50-498 G		8011260439	8011260431	80/10/27	50-277 G	
8011260198	8011260194	80/11/20	50-395 A		8011260441	8011260431	80/10/27	50-277 G	
8011260200	8011260194	80/11/20	50-395 A		8011260446	8011260431	80/10/27	50-277 G	
8011260201	8011260199	80/11/13	50-321 P		8011280011	8011280009	80/11/25	50-361 A	
8011260202	8011260199	80/11/13	50-321 P		8011280023	8011280021	80/11/21	50-409 G	
8011260204	8011260196	80/11/20	50-395 A		8011280027	8011280025	80/11/25	TOPREP	
8011260205	8011260199	80/11/13	50-321 P		8011280029	8011280028	80/11/10	50-331 G	
8011260207	8011260196	80/11/20	50-395 A		8011280035	8011280032	80/10/17	50-267 G	
8011260210	8011260209	80/11/19	50-358 A		8011280048	8011280047	80/11/26	50-337 G	
8011260224	8011260213	80/11/24	50-295 F		8011280052	8011280049	80/11/21	50-368 G	
8011260225	8011260213	80/11/24	50-295 F		8011280058	8011280055	80/11/21	50-272 G	
8011260228	8011260213	80/11/24	50-295 F		8011280062	8011280060	80/11/18	50-321 G	
8011260231	8011260213	80/11/24	50-295 F		8011280066	8011280063	80/11/24	50-282 P	
8011260234	8011260213	80/11/24	50-295 F		8011280067	8011280064	80/11/26	50-416 K	
8011260237	8011260213	80/11/24	50-295 F		8011280068	8011280063	80/11/24	50-282 P	
8011260241	8011260213	80/11/24	50-295 F		8011280069	8011280064	80/11/26	50-416 K	
8011260243	8011260213	80/11/24	50-295 F		8011280070	8011280064	80/11/26	50-416 K	
8011260245	8011260213	80/11/24	50-295 F		8011280072	8011280064	80/11/26	50-416 K	
8011260247	8011260213	80/11/24	50-295 F		8011280073	8011280071	80/11/24	50-361 A	
8011260249	8011260213	80/11/24	50-295 F		8011280074	8011280064	80/11/26	50-416 K	
8011260251	8011260248	80/11/17	50-339 P		8011280076	8011280064	80/11/26	50-416 K	
8011260253	8011260213	80/11/24	50-295 F		8011280077	8011280075	80/11/24	50-334 P	
8011260255	8011260248	80/11/17	50-339 P		8011280076	8011280071	80/10/01	50-220 G	
8011260257	8011260248	80/11/17	50-339 P		8011280076	8011280071	80/11/10	50-266 G	
8011260259	8011260213	80/11/24	50-295 F		8011280202	8011280199	80/11/18	50-186 G	
8011260262	8011260213	80/11/24	50-295 F		8011280206	8011280204	80/11/18	50-454 G	
8011260268	8011260213	80/11/24	50-295 F		8011280212	8011280208	80/10/17	50-498 G	
8011260273	8011260213	80/11/24	50-295 F		8011280224	8011280221	80/10/23	50-254 G	
8011260275	8011260271	80/10/21	50-234 G		8011280229	8011280226	80/11/06	50-327 G	
8011260276	8011260213	80/11/24	50-295 F		8011280230	8011280226	80/11/06	50-327 G	
8011260278	8011260213	80/11/24	50-295 F		8011280237	8011280235	80/10/28	50-440 G	
8011260280	8011260272	80/11/14	50-313 G		8011280240	8011280238	80/11/12	50-369 G	
8011260283	8011260271	80/10/21	50-234 G		8011280242	8011280238	80/11/12	50-369 G	
8011260284	8011260213	80/11/24	50-295 F						

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Application for construction permit.
2. General Information submitted with construction permit application.
3. Amendments and changes to items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses.
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit.
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license.
13. General Information submitted with operating license application.
14. Amendments and changes to items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR).
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
17. Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

3. Transmittal and acknowledgement letters.
4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal and acknowledgement letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal register notices citing the availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
2. Supplements to the DES and FES.
3. Correspondence relating to the DES and FES.
4. Comments from other federal, state and local government agencies.
5. Transmittal and acknowledgement letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Federal register notice citing availability of items 1 and 2.
9. Site visits to obtain information for DES or FES.
10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
2. Supplements to SER.
3. Correspondence relating to SER.
4. Federal register notices citing availability of items 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1. Fire Hazard Protection Plan and surveys.
2. Plant evacuation correspondence.
3. Safeguards Contingency Plans.
4. Review of Health Physics Program.
5. Correspondence relating to aforementioned plans.
6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
2. Federal register notices regarding hearings.
3. Requests to make appearances at hearings.
4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
6. Correspondence to and from intervenors.
7. Board orders and decisions.
8. Petitions for Commission action.
9. Legal filings and Commission orders and decisions resulting from item 8.



H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Change of address notifications.
2. Changes in structure of organization.
3. Changes in service lists.
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

1. Limited Work Authorizations (LWA) and amendments.
2. Correspondence pertaining to work performed under LWA's.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
2. Correspondence where the primary topic of discussion is antitrust matters.
3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
2. Correspondence from ACRS.
3. Announcement of ACRS meetings.
4. Transmittal and acknowledgement letters.
5. ACRS reports.
6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
7. Minutes at ACRS Subcommittee Meetings.

P. OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes and related correspondence.
2. Technical specifications and changes.

3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
4. Federal register notices citing availability of items 1 and 2.
5. Correspondence regarding the Final Safety Analysis Report (FSAR).
6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
8. Information on the Standard Review Plan (STP).
9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
11. Owner's group meeting announcements and reports.
12. Quality assurance information.
13. Environmental matters (technical).
14. Emergency core cooling system documents.
15. Radioactive waste information.
16. Correspondence regarding expansion of spent fuel storage pool.
17. Start-up test reports.
18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1. Inspection reports.
2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Pre-service and in-service inspections and procedures.
7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

1. Monthly, semiannual, or annual operating reports (other than financial).
2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Periodic personnel exposure reports.
4. Operational Logbooks:
 - Logbooks on Environmental Data
 - Logbooks on Radiological Data
 - Operations Log on Plant Systems Core
 - Plant Status Summary Sheets.
5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
2. Potential or possible reportable deficiency reports and related correspondence.
3. Personnel exposure reports.
4. Construction deficiency reports submitted under 10 CFR 50.55e.
5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
6. Environmental Technical Specifications violation reports and Environmental Event reports.
7. Part 21 Reports of defects and noncompliance.
8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
2. Testimony and statements submitted to ASLB and ASLAB.
3. Commission meeting transcripts.
4. NRC staff briefings to the Commission.
5. Statements and written testimony submitted at Commission meeting or hearings.
6. Transcripts of utility briefs to NRC staff.
7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
2. Preparatory and backup documents for item 1.
3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators.
2. NRC examination results.
3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

1. Application for authority to voluntarily surrender license.
2. Application to dismantle the facility and dispose of component parts.
3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
4. Documents relating to disposal of radioactive material and decontamination of the site.
5. Other correspondence relating to above items.
6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR — Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS — Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION — NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT -- NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
2. Solicitations (RFP or IFB) issued by the NRC.
3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
4. Contractual documents and contract modifications, if any.

DISCLOSURE -- Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA -- Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year--numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS -- Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

3. Meeting notifications and minutes.
4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E – Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC – Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG – NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG – Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR – Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM – Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.

3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ – Projects–Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.
2. Notices of deviations.
3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES – Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP – NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY – Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
3. State Legislative Reports.
4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP – Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT – Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 (7 77)		U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		1. REPORT NUMBER <i>(Assigned by DDC)</i> NUREG-0540 Vol 2, No 11	
4. TITLE AND SUBTITLE <i>(Add Volume No., if appropriate)</i> Title List of Documents Made Publicly Available November 1 - 30, 1980				2. (Leave blank)	
7. AUTHOR(S)				3. RECIPIENT'S ACCESSION NO.	
9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS <i>(Include Zip Code)</i> Division of Technical Information and Document Control U.S. Nuclear Regulatory Commission Washington, D.C. 20555				5. DATE REPORT COMPLETED MONTH December YEAR 1980	
12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS <i>(Include Zip Code)</i> Division of Technical Information and Document Control U.S. Nuclear Regulatory Commission Washington, D.C. 20555				DATE REPORT ISSUED MONTH February YEAR 1981	
13. TYPE OF REPORT Monthly				6. (Leave blank)	
				8. (Leave blank)	
				10. PROJECT/TASK/WORK UNIT NO.	
15. SUPPLEMENTARY NOTES				11. CONTRACT NO.	
16. ABSTRACT <i>(200 words or less)</i> This document is a monthly publication containing descriptions of information received and generated by the US NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The docketed information includes information formerly issued through the U.S. Department of Energy's Technical Information Center under the title <i>Power Reactor Docket Information (PRDI)</i> . This document replaces PRDI, which will no longer be prepared. This document contains the following indexes: Personal Author Index, Corporate Source Index, and Report Number Index.				14. (Leave blank)	
17. KEY WORDS AND DOCUMENT ANALYSIS				17a DESCRIPTORS	
17b IDENTIFIERS/OPEN-ENDED TERMS					
18. AVAILABILITY STATEMENT Unlimited				19. SECURITY CLASS <i>(This report)</i> Unclassified	
				21 NO. OF PAGES	
				20. SECURITY CLASS <i>(This page)</i> Unclassified	
				22. PRICE \$	